

322358

Description	Created	Closed	Notes	Type
ECU fault	21/04/22	21/04/22		Breakdown
Trace and rectify air leak	16/06/22	17/06/22	5,050 hrs	Breakdown
250hr Service and Inspection	4/07/22	7/09/22	5,266 hrs	Service
no start	14/09/22	27/09/22	5,371 hrs	Breakdown
500hr Service and Inspection	15/09/22	31/10/22	5,517 hrs	Service
250hr Service and Inspection	8/11/22	18/01/23	5,769 hrs	Service
2000hr Service and Inspection	14/02/23	12/04/23	6,010 hrs	Service
Park brake fault	8/03/23	8/06/23	5,958 hrs	Breakdown
250hr Service and Inspection	20/04/23	2/06/23	6,240 hrs	Service
Centre diff DUO seal leaking	29/05/23	8/06/23	6,278 hrs	Breakdown
hyd hose u/s	8/06/23	5/07/23	6,298 hrs	Breakdown
500hr Service and Inspection	20/06/23	9/08/23	6,515 hrs	Service
replace uhf aerial	30/06/23	3/05/24		Breakdown
250hr Service and Inspection	11/08/23	6/09/23	6,746 hrs	Service
ECU Faults	3/10/23	1/12/23	5,990 hrs	Breakdown
Check Pos 6 tyre fault	20/10/23	19/04/24	4,659 hrs	Damage: Accident/Incident
1000hr Service and Inspection	24/10/23	1/12/23	6,990 hrs	Service
250hr Service and Inspection	19/12/23	15/02/24	7,271 hrs	Service
500hr Service and Inspection	3/01/24	3/05/24	7,511 hrs	Service
Check Leaking Cooling Header Tank	25/01/24	19/02/24	7,275 hrs	Breakdown
check ECU Fault	20/02/24	29/02/24	7,309 hrs	Breakdown
Pos 2 Tyre Damage	1/03/24	28/06/24	7,354 hrs	Damage: Accident/Incident
Repairs - Washer pump & rear view mirror	14/03/24	1/05/24	7,511 hrs	General Repair
Check ECU Faults	15/04/24	27/06/24	7,451 hrs	Breakdown
250hr Service and Inspection	23/05/24	24/06/24	7,771 hrs	Service
2000hr Service and Inspection	17/06/24	13/08/24	8,002 hrs	Service
Replace Worn Rear Diff Uni Joints	9/07/24	18/07/24	7,870 hrs	Breakdown
Replace Artic hoses	5/08/24	13/08/24	8,002 hrs	General Repair
250hr Service and Inspection	3/09/24	30/09/24	8,240 hrs	Service
Replace Grille locks	23/09/24	27/09/24	8,240 hrs	General Repair
Trace and rectify blown hose under trans	23/09/24	25/09/24	8,228 hrs	Breakdown
ECU Comms Fault Again	14/10/24	29/10/24	8,291 hrs	Breakdown
Replace failed water pump	29/10/24	1/11/24	8,363 hrs	Breakdown
500hr Service and Inspection	5/11/24	2/12/24	8,505 hrs	Service
Replace Cracked dash panels and rockers	27/11/24	19/12/24	5,753 hrs	General Repair
250hr Service and Inspection	29/01/25	13/02/25	8,745 hrs	Service
Repairs from service 26496	12/02/25	24/02/25	8,745 hrs	General Repair
Replace failed exhaust pipe	12/02/25	19/02/25	8,745 hrs	General Repair
Replace failed batteries	24/02/25	6/03/25	8,774 hrs	Breakdown
Perform software update	7/03/25	18/03/25	8,811 hrs	General Repair
Replace failed UHF handpiece	3/04/25	4/04/25	8,856 hrs	General Repair
Tranny low trans pressure fault	11/04/25	24/04/25	8,869 Hrs	Breakdown
Replace Cab switches as required	24/05/25	30/05/25	8,908 Hrs	General Repair
POS 4 flat tyre	4/06/25	4/06/25	8,908 Hrs	Breakdown
1000hr Service and Inspection	17/06/25	24/06/25	8,996 Hrs	Service
POS 6 tyre sidewall split	27/06/25	4/07/25	9,020Hrs	Breakdown
250hr Service and Inspection	10/07/25	21/08/25	9,237 Hrs	Service
Repairs from service	17/08/25	19/09/25	9,345 Hrs	General Repair
500hr Service and Inspection	9/09/25	17/10/25	9,506 Hrs	Service
Cab repairs	16/09/25	22/09/25	9,348 Hrs	General Repair
Replace LH top step	23/09/25	1/10/25	9,409 Hrs	General Repair
POS 6 tyre change	1/10/25	1/10/25	9,418 Hrs	General Repair
Cracked header tank	8/10/25	13/10/25	9,466 Hrs	Breakdown
replace lift cylinder hoses found during service	19/10/25	12/11/25	9,666 Hrs	General Repair
Replace seat air valve	25/10/25	7/11/25	9,581 Hrs	Breakdown
250hr Service and Inspection	28/10/25	3/12/25	9,730 Hrs	Service
Replace air tank	14/11/25	19/11/25	9,676 Hrs	Breakdown
A/C Compressor Failure	23/11/25	26/11/25	9,694 Hrs	Breakdown
POS 3 Tyre sidewall damage	9/12/25	12/01/26	9,778 Hrs	Damage: Accident/Incident
Defect repairs	13/01/26	18/02/26	9,889Hrs	General Repair
Repair leak in tyre	3/02/26	25/05/26	9,834 Hrs	General Repair
2000hr Service and Inspection	10/02/26	28/07/26		Service
Repairs from offhire	14/02/26	19/02/26	9,889 Hrs	General Repair