CLOSE TO OUR CUSTOMERS

Original

WIRTGEN Australia Pty Ltd · PO Box 279 · Guildford WA 6935

Kee Surfacing Pty Ltd 36 Murray Road NORTH WELSHPOOL WA 6106 WIRTGEN Australia Pty Ltd

Lot 2, Great Eastern Highway \cdot South Guildford WA 6055

Telephone switchboard +61 8 6279 2200

Contact person Matthew Schofield
Department Customer Support
Telephone +61492019942

Fax

Email matthew.schofield@wirtgen-group.com

www.wirtgen-group.com/australia

Tax Invoice

Invoice no. / Date 1900111667 / 27.03.2024

Page 1 / 3

Customer no. 4104342 Order no./date 203401446 / 28.02.2024 Delivery note 704793601 / 08.03.2024

Your reference 40064

CRM Doc. no. 904216147

Shipping address Wirtgen Australia Pty Ltd

Lot 2, Great Eastern Highway (Access via Ivy Street) SOUTH GUILDFORD WA 6055

Your ABN 68148877347

Reference object 0911.0467 Super 1303-2 AB 340 TV

Vehicle ID K237 Machine hours 5741

Payment terms Full payment (30) days from end of month

Delivery Terms EXW Ex Works Incoterms 2020

Delivery condition Service Collection - Less than 2 Hours

Attended site. Investigate parkbreak fault.

Trying to move the machine, folded back and noticed the park rake would not release.

Investigated the foot park brake. Dismantled the protective cover to find the potentiometer, visual inspection looked okay tested and noticed no voltage.

Inspected the faults present in the machine and noticed within looking at the schematics. There was a common fuse controlling the senses.

Opened up the housing where the electrical board was and noticed fuse 14 was blown. Isolated and replaced fuse. Turn the machine onto test and noticed more faults present and the fuse 14 had blown again

Trace short circuit in wiring loom.

Removed melted supply and earth cables and replaced with new, started to replace panels and require a new fuse holder to continue

Machine had smoldered a lot of its harness due to a dead short, towed machine to wash bay and washed all dry powder residue off, removed right wheel and most panels to asses damage, found the main earth cables and power/earth supply to electrical box had all melted significantly. disconnected all supplies and spent hours testing for dead short disconnecting individual plugs on affected circuits. Found the main harness to machine control from electrical box had been impaled by part of the machine chassis, upon inspection found that 30% of the wires within this harness were melted together, striped back conduit and splice repaired all effected cabless, tested machine and ran without any faults.

Diagnose fault with brake accumulator not building pressure.

CLOSE TO OUR CUSTOMERS

Original

Tax Invoice

Invoice no. / Date 1900111667 / 27.03.2024 Page 2 / 3

Oring on valve had torn. Replace orings and install valve and carry out testing. Final check $\boldsymbol{\cdot}$

Item	Product	Quantity	UoM	List Price	Discount	Unit Price	Net Amount
	812 Travel Time	1.000	Н			169.00 AUD	169.00 AUD
	811 Working Time	12.000	Н			169.00 AUD	2,028.00 AUD
20	817 Mileage	20.000	KM	1.80	100.00- %	0.00 AUD	0.00 AUD
40	817 Mileage	20.000	KM	1.80	100.00- %	0.00 AUD	0.00 AUD
70	2513591 2 PC BATT TERM H/D 10MM BOLT NEG					14.12 AUD	28.24 AUD
80	2513593 2 PC BATT TERM H/D 10MM BOLT POS					14.12 AUD	28.24 AUD
100	813 Working Time 8/0		PC			169.00 AUD	1,014.00 AUD
110	813 Working Time 7/0		PC			169.00 AUD	1,690.00 AUD
120	813 Working Time 12,		PC hrs			1,436.50 AUD	1,436.50 AUD
130	813 Working Time 13,		PC			169.00 AUD	1,183.00 AUD
140	813 Working Time 14,		PC			169.00 AUD	1,521.00 AUD
150	818 Service Callout	1	PC			129.00 AUD	129.00 AUD
160	813 Sundry Items	1	PC			48.00 AUD	48.00 AUD
	Total net amount			0.374.00	NID.		9,274.98 AUD
	Taxable GST 10%			9,274.98 <i>f</i> 10.0 %	AUD		927.50 AUD
	Tota	l amount				_	10,202.48 AUD

Any agreement shall be governed and construed in accordance with Australian law. The General Terms and Conditions of Sales of Wirtgen Australia Pty Ltd. shall apply in addition to any agreement. These are available at

CLOSE TO OUR CUSTOMERS

Original

Tax Invoice

Invoice no. / Date 1900111667 / 27.03.2024 Page 3 / 3

http://www.wirtgen-group.com/australia/en or can be sent on request.