



TAX INVOICE IE4687 (REPRINT)

RQ0405

Date: 23/02/2022

Rego: Y80080

Page 1 of 3

Charge to: 5669

Customer: 5669

ABN: 89 007 376 883

Phone
Contact:

Mobile

Order No:	STEVE 08/02	Next Service Date:	00/00/0000	Next Service Kms:	0
Service Adviser:	PS	Odometer reading:	993,743	Warranty Expiry Date:	00/00/0000
VIN	6HJVWAU0SE33366	Engine No.		Delivery Date:	00/00/0000
Stock Number	VT420F	Model	VAWDREY-VB53	Engine Hours:	0.00

Product	Description	Quantity	Price Excl.
REPACK TRAILER BEARINGS			
<p>Released the park brakes with workshop air pressure and lifted up each axle to turn the wheels to a position that we can crack the hub caps with, unplugged the park brakes then lowered each axle.</p> <p>Released Park brake and backed off brakes, jacked each axle up and lowered onto stands, opened up both rear of trailer curtains and slid two gates on either side up to give more room to work.</p> <p>Removed 6x hubcaps, took all locking springs out of axles, unscrewed all hub nuts and removed all hubs as one set.</p> <p>Removed all outer circlips, hub nuts, outer wheel bearings, removed seal runners and O rings, removed dust seals, removed inner circlip and removed hub seals and removed inner wheel bearings and tagged inner and outer bearings so they go back onto the same hub.</p> <p>Cleaned all bearings in the hot wash, cleaned all hub seals and circlips and hub nuts, cleaned stub axles and hubs, pulled bearings out of the hot wash after 1 hour, brake cleaned them and blew them out with air, inspected all bearings, stub axles, hubs and tested the tension for the hub nuts 4/6 failed and need replacing, inspected seals.</p> <p>Repacked all hubs & fitted bearings & seals to the hubs.</p> <p>Fitted hubs to axles and tensioned wheels nuts.</p> <p>Adjusted all brakes.</p> <p>Lowered trailer on to ground.</p>			
04L	LABOUR REPACK TRAILER BEARINGS		1,965.75

	BPW ECO-LI GREASE 20KG	1	420.08
	S/CARRIER ECO PLUS 10/12 TONNE	6	138.96
	HUB SEAL-BPW ECO PLUS	6	235.02
	O-RING 100X3 S/CAR 7470 7620T	6	8.10
	SEAL-DUST BPW ECO PLUS HUB CAP	6	32.34

Continued ...

HUB SLEEVE ECO PLUS 10T	6	31.74
WASHER-STD HUB ECO BEAMH91	6	49.08
WEDGE LOCKING AXNUT ECO PLUS	6	13.92
RING LOCKING FOR WEDGE	6	5.46
NUT & WASHER KIT	4	170.56
	Sub Total:	3,071.01

CARRY OUT TURNTABLE INSPECTION & ADJUSTMENT

Cleaned off old grease from the turn table.
 Checked adjustment found all ok.
 Removed old auto greaser & fitted new on to the turntable .

REPLACE GREASE CANISTER ALSO

72L	LABOUR ACCESSORY FITMENT	131.05

	GREASE CANISTER	1 933.70
	COURIER FRIEGHT CHARGE	1 10.00

	Sub Total:	1,074.75

CARRY OUT BRAKE PERFORMANCE TEST REPORT

34L	Carried brake performance test.	

	Sub Total:	43.04

Parts: \$2,048.96 Labour: \$2,139.84 Others: \$0.00 Sub Total: \$ 4,188.80

Total GST: \$ 418.89

Payment by EFT: BSB: 034-081 Account #: 132587

Reference: IE4687

Please advise details of deposit by

email hallam@hallamtruck.com.au

INVOICE TOTAL \$ 4,607.69

For terms and conditions see last page