



TAX INVOICE IE4484 (REPRINT)

RQ0471

Date: 18/01/2022

Rego: 0295S7

Page 1 of 2

Charge to: **5669**

Customer: **SKIPT001**

ABN: **89 007 376 883**

Phone
Contact:

Mobile

Order No:	Next Service Date:	00/00/0000	Next Service Kms:	0
Service Adviser:	Odometer reading:	673,429	Warranty Expiry Date:	00/00/0000
VIN	Engine No.		Delivery Date:	00/00/0000
Stock Number	Model	TRAILER VAWDREY	Engine Hours:	0.00

***** RECOMMENDATIONS *****

``A`` TRAILER

Product	Description	Quantity	Price Excl.
RETENTION ALL R/H WHEEL BEARINGS			
	Re-tension all R/H wheel bearings		
	Remove hub caps and locknut retainer.		
	Re-tension wheel nut and refit hub caps.		
32L	LABOUR RETENTION ALL R/H WHEEL BEARINGS		262.10

		Sub Total:	262.10

Parts: \$0.00	Labour: \$262.10	Others: \$0.00	Sub Total: \$ 262.10
			Total GST: \$ 26.21
Payment by EFT: BSB: 034-081 Account #: 132587 Reference: IE4484 Please advise details of deposit by email hallam@hallamtruck.com.au			

INVOICE TOTAL \$ 288.31

For terms and conditions see last page



TAX INVOICE IE5267 (REPRINT)

RQ1084

Date: 28/05/2022

Rego: 0295S7

Page 1 of 4

Charge to: **5669**

Customer: **SKIPT001**

ABN: **89 007 376 883**

Phone
Contact:

Mobile

Order No:	Next Service Date:	00/00/0000	Next Service Kms:	0
Service Adviser:	Odometer reading:	0	Warranty Expiry Date:	00/00/0000
VIN	Engine No.		Delivery Date:	00/00/0000
Stock Number	Model	TRAILER VAWDREY	Engine Hours:	0.00

***** RECOMMENDATIONS *****

``A`` TRAILER

Product	Description	Quantity	Price Excl.
TRAILER WHEEL BEARING REPACK			
	Raised axles and placed on stands.		
	Removed hub caps and bearing hardware.		
	Removed hub.		
	Disassembled hubs and bearings.		
	Washed parts and hot washed bearings and hardware.		
	Cleaned out hubs and drums.		
	Cleaned stub axles.		
	Inspected bearings, all ok.		
	Packed bearings.		
	Fitted new hub seals.		
	Assembled bearings and hardware.		
	Fitted hubs and set bearing preload.		
	Fitted lock tabs and fitted and tensioned hub caps.		
	Wiped rims clean.		
	Adjusted brakes and		
	removed stands.		
04L	LABOUR TRAILER WHEEL BEARING REPACK		1,307.25

SUPP	SUNDY SHOP SUPPLIES	1	19.30
ENVIRO	ENVIRONMENTAL TREATMENT SUPPLY	1	19.80
	BPW ECO-LI GREASE 20KG	1	420.08
	SEAL-DUST H91/H10 ECO HUB	6	54.72
	SEAL-ECO H91/10/R10	6	84.54
	O-RING 100X3 S/CAR 7470 7620T	6	8.10
		Sub Total:	1,913.79

CHECK TRAILING ARM BUSHES

Inspected all spring eye bushes and suspension bushes, all ok.

04L	LABOUR CHECK TRAILING ARM BUSHES	72.63
		Sub Total:
		72.63

Continued ...

CHECK RIDE HEIGHT VALVES

Removed the ride height control valve rod from the mounting pin on the axle.
 Moved the rod up and down and measured the movement between where it would raise and lower the airbag pressure.
 Found 3-4mm movement at the valve.
 Found the rubber end piece to be worn and needing replacement.
 Ordered a new height control valve from parts department.
 Removed old unit from the trailer, swapped all fittings from the old unit onto the new one.
 Adjusted the rods to the same lengths as the old unit.
 Installed the new unit into the trailer and re-connected the airlines.
 Applied air to the trailer and tested for air leaks, all ok.

04L

LABOUR CHECK RIDE HEIGHT VALVES		435.75

VALVE-HCV-BPW BASIC	1	150.83
LINKAGE	1	23.00
		Sub Total: 609.58

CHECK TYRE PRESSURES & CONDITION

Inspected and adjusted tyre pressures on trailer to 100PSI.

****TYRE REPORT****

1ST AXLE LH INNER 6MM OUTER 9MM
 1ST AXLE RH INNER 8MM OUTER 8MM
 2ND AXLE LH BOTH 7MM TYRES HAS UNEVEN WEAR ON INNER AND OUTER EDGES.
 2ND AXLE RH INNER 10MM OUTER 11MM BOTH TYRES HAVE UNEVEN WEAR ON INNER AND OUTER EDGES AND ARE SCALLOPING.
 3RD AXLE LH INNER 7MM OUTER 6MM
 3RD AXLE RH INNER 6MM OUTER 6MM
 ALL MEASUREMENTS FROM WEAR INDICATOR ON TYRES.

36L

LABOUR CHECK TYRE PRESSURES & CONDITION	145.25

	Sub Total: 145.25

CHECK TRAILER KING PINS AND TURNTABLE

Check condition of kingpin, all ok.
 Checked tension of mounting bolts, all ok.
 Checked over turntable condition and feet bushes, Adjusted turntable within spec.

04L

LABOUR CHECK TRAILER KING PINS AND TURNTABLE	108.94

	Sub Total: 108.94

CHECK TRAILER GATES FOR CRACKS & DAMAGE

Inspected internal gates on trailer for cracks in the welds and damage.
 Found a couple small cracks and some broken horizontal straps that required welding back together.
 Found one section of strap to be snapped off and missing, had a sharp edge where the snap occurred.
 Grounded edge down smooth.
 Removed the damaged 3 gates.
 Cleaned broken surfaces and welded back together.

Measured out a strap to fit, cut and welded in place.

04L	LABOUR CHECK TRAILER GATES FOR CRACKS & DAMAGE	225.38

	Sub Total:	225.38

Parts: \$741.27	Labour: \$2,295.19	Others: \$39.10	Sub Total: \$ 3,075.57
Payment by EFT: BSB: 034-081 Account #: 132587			Total GST: \$ 307.56
Reference: IE5267			
Please advise details of deposit by			
email hallam@hallamtruck.com.au			

INVOICE TOTAL \$ 3,383.13

For terms and conditions see last page