

Work Order History - R86

AssetCode	Registration	Work OrderCode	Work Order Date	Service Code	RM Categor	
R86	040SFO	25198	03/13/2020	GEN	TRACKER FITTED AND LOGGED 13.03.2020 ESN # 4661295244	39
R86	040SFO	25198	03/13/2020	GEN		
R86	040SFO	26299	04/16/2020	CUMAE5	SERVICE COMPLETED.	1
					FILTERS NEEDED LF9039 + FF1003 + AIR FILTER. FILTER TREAT ISSUE STILL THERE - NEEDS FURTHER INVESTIGATION. NEED DRAG LINK FROM SECOND STEERING BOX TO SECOND STEER AXLE. NEEDS WIPER BLADES REPLACED. ADJSUTED CLUTCH.	
R86	040SFO	26299	04/16/2020	CUMAE5		0
R86	040SFO	26299	04/16/2020	CUMAE5		0
R86	040SFO	26299	04/16/2020	CUMAE5		16
R86	040SFO	26382	04/17/2020	GEN	COMPLETED BY BRIDGESTONE 17.04.2020 INVOICE # 98370154	15
R86	040SFO	26382	04/17/2020	GEN		15
R86	040SFO	27608	06/05/2020	ROTDRI	DRIVE TYRE ROTATION COMPLETED.	15
R86	040SFO	27608	06/05/2020	ROTDRI	COMPLETED BY BRIDGESTONE - DAVE 05.06.2020	
R86	040SFO	27607	06/05/2020	STEROT	STEER TYRE ROTATION COMPLETED.	15
R86	040SFO	27607	06/05/2020	STEROT	COMPLETED BY BRIDGESTONE - DAVE 05.06.2020	
R86	040SFO	27621	06/06/2020	CUMAE5	SERVICE COMPLETED BY BILLY 06.06.2020	1
					HAS A CRACKED BACK WINDOW, SMALL CRACK IN DRIVERSIDE WINDOW IN CORNER AFTER TREAT LIGHT STILL ON - NO LAPTOP DRAG LINK ARM NEEDS CHANGING, POSSIBLE LOOK AT GREASE ON C & D FOR STEER CAPS	
R86	040SFO	27621	06/06/2020	CUMAE5	CHANGED WIPER BLADES AS REQUIRED, CHANGED AIR FILTER AS REQUIRED	0
R86	040SFO	27621	06/06/2020	CUMAE5		6
R86	040SFO	27621	06/06/2020	CUMAE5		40
R86	040SFO	27621	06/06/2020	CUMAE5		6
R86	040SFO	27621	06/06/2020	CUMAE5		6
R86	040SFO	27621	06/06/2020	CUMAE5		6
R86	040SFO	27621	06/06/2020	CUMAE5		13
R86	040SFO	27621	06/06/2020	CUMAE5		16
R86	040SFO	27621	06/06/2020	DEFECT	Reported Defect :- Defect Code : 00004146 Defect Reference : WO 26299 Date : 16/04/2020 Description of Defect : FILTERS NEEDED LF9039 + FF1003 + AIR FILTER.	1
R86	040SFO	27621	06/06/2020	DEFECT	DEFECT CLEARED BY BILLY 06.06.2020 Reported Defect :- Defect Code : 00004149 Defect Reference : WO 26299 Date : 16/04/2020 Description of Defect : NEEDS WIPER BLADES REPLACED.	
R86	040SFO	27621	06/06/2020	DEFECT	DEFECT CLEARED BY BILLY 06.06.2020 STEER TYRE ROTATION COMPLETED.	
R86	040SFO	29604	08/12/2020	STEROT	COMPLETED BY BRIDGESTONE - 12.08.2020 - DAVE.	
R86	040SFO	29683	08/19/2020	ROTDRI	DRIVE TYRE ROTATION COMPLETED.	15
R86	040SFO	29683	08/19/2020	ROTDRI	COMPLETED BY BRIDGESTONE -	15
R86	040SFO	29683	08/19/2020	TYRDRI		
R86	040SFO	30031	08/31/2020	CUMA		1

R86	040SFO	30031	08/31/2020 CUMA	SERVICE COMPLETED BY SEAN & BEN 31/08/2020	16
R86	040SFO	30031	08/31/2020 CUMA	ADBLUE LEAKING FROM EXHAUST GASKET BEFORE MUFFLER	0
R86	040SFO	32850	12/03/2020 CUMAE5		1
R86	040SFO	32850	12/03/2020 CUMAE5	SERVICE COMPLETED.	
R86	040SFO	32850	12/03/2020 CUMBE5	SERVICE COMPLETED BEN/MICK	0
				REPLACED DRAG LINK END ON SECOND STEER AXEL	
R86	040SFO	32850	12/03/2020 CUMBE5	COMPLETED B SERVICE	0
R86	040SFO	32850	12/03/2020 CUMBE5		16
R86	040SFO	32850	12/03/2020 CUMBE5		13
R86	040SFO	32980	12/10/2020 GEN		39
R86	040SFO	32980	12/10/2020 GEN		39
R86	040SFO	32980	12/10/2020 GEN		39
R86	040SFO	32980	12/10/2020 GEN		39
R86	040SFO	32980	12/10/2020 GEN		39
R86	040SFO	32980	12/10/2020 GEN		39
R86	040SFO	32980	12/10/2020 GEN		39
R86	040SFO	32980	12/10/2020 GEN		39
R86	040SFO	32980	12/10/2020 GEN		39
R86	040SFO	36291	03/29/2021 RIGIDA	SERVICE COMPLETED BY KEIRAN AND MICK	0
				REPALCED EXHASUT GASKET AFTER INJECTOR CHECK FOR ADBLUE NEXT SERVICE	
				FITTED 5L GREEN SPARE COOLANT BOTTLE TOPPED UP 5L OF OIL	
R86	040SFO	36291	03/29/2021 RIGIDA		0
R86	040SFO	36291	03/29/2021 RIGIDA		16
R86	040SFO	36291	03/29/2021 RIGIDA		40
R86	040SFO	36291	03/29/2021 RIGIDA		11
R86	040SFO	37994	05/29/2021 CUMAE5		1
R86	040SFO	37994	05/29/2021 CUMAE5	SERVICE COMPLETED.	
R86	040SFO	37994	05/29/2021 CUMBE5	SERVICE COMPLETED BY KEIRAN	0
R86	040SFO	37994	05/29/2021 CUMBE5		16
R86	040SFO	37994	05/29/2021 CUMBE5		40
R86	040SFO	37994	05/29/2021 CUMBE5		6
R86	040SFO	37994	05/29/2021 CUMBE5		6
R86	040SFO	37994	05/29/2021 CUMBE5		6
R86	040SFO	38617	06/11/2021 GEN		39
R86	040SFO	38617	06/11/2021 GEN		39
R86	040SFO	38614	06/11/2021 TYRES		15
R86	040SFO	38614	06/11/2021 TYRES		15
				Reported Defect :- Defect Code : 00006660 Defect Reference : 08851 Date : 02/07/2021 Description of Defect : DRIVER SEAT NEEDS REPAIR CLUTCH BRAKE & CLUTCH ADJUSTMENT TREATMENT LIGHT TO BE FIXED STEER TYRES NEED ROTATION	
R86	040SFO	39496	07/07/2021 DEFECT	DEFECT CLEARED BY MICK 09.07.2021 Reported Defect :- Defect Code : 00004860 Defect Reference : WO 30031 Date : 31/08/2020 Description of Defect :	
R86	040SFO	39496	07/07/2021 DEFECT	ADBLUE LEAKING FROM EXHAUST GASKET BEFORE MUFFLER	

R86	040SFO	39496	07/07/2021 DEFECT	CHECK FOR ADBLUE NEXT SERVICE	
R86	040SFO	39496	07/07/2021 GEN		0

R86	040SFO	39496	07/07/2021	GEN	TO BROWN AND HURLEY	
R86	040SFO	39496	07/07/2021	GEN		16
R86	040SFO	39496	07/07/2021	GEN		2
R86	040SFO	39496	07/07/2021	GEN		14
R86	040SFO	39468	07/08/2021	CUMCES		1

R86	040SFO	39468	07/08/2021 CUMCE5	* AFTER TREAT LIGHT STILL ON	
R86	040SFO	39468	07/08/2021 CUMCE5		0
R86	040SFO	39468	07/08/2021 CUMCE5		0
R86	040SFO	39468	07/08/2021 CUMCE5		0
R86	040SFO	39468	07/08/2021 CUMCE5		16
R86	040SFO	39468	07/08/2021 CUMCE5		6
R86	040SFO	39468	07/08/2021 CUMCE5		6
R86	040SFO	39468	07/08/2021 CUMCE5		40
R86	040SFO	39468	07/08/2021 CUMCE5		40
R86	040SFO	39468	07/08/2021 CUMCE5		12
R86	040SFO	39468	07/08/2021 CUMCE5		6
R86	040SFO	39468	07/08/2021 EXOINS		0

[illegible]

[illegible]

R86	040SFO	44015	12/03/2021 GEN		16
R86	040SFO	44015	12/03/2021 GEN		14
R86	040SFO	44293	12/15/2021 TYRES		39
R86	040SFO	44293	12/15/2021 TYRES		39
R86	040SFO	44525	01/06/2022 CUMAE5		1
R86	040SFO	44525	01/06/2022 CUMAE5	SERVICE COMPLETED.	
R86	040SFO	44525	01/06/2022 CUMBE5		1
				SERVICE COMPLETED MICK AND KEIRAN	
				- REPLACED WARNING BUZZER IN DASH	
				- PER DEFECT SHOCK RUBBERS HAVE BEEN DONE. FRONT WINDOW HAS BEEN REPLACED AFTER TREAT	
				ISSUE WAS RESOLVED.	
R86	040SFO	44525	01/06/2022 CUMBE5	* AFTER TREAT LIGHT CAME ON CODE 319	
R86	040SFO	44525	01/06/2022 CUMBE5		0
R86	040SFO	44525	01/06/2022 CUMBE5		0
R86	040SFO	44525	01/06/2022 CUMBE5		16
R86	040SFO	44525	01/06/2022 CUMBE5		6
R86	040SFO	44525	01/06/2022 CUMBE5		6
R86	040SFO	44525	01/06/2022 CUMBE5		6
R86	040SFO	44525	01/06/2022 CUMBE5		6
R86	040SFO	44525	01/06/2022 CUMBE5		40
R86	040SFO	44525	01/06/2022 CUMBE5		11
				Reported Defect :-	
				Defect Code : 00006644	
				Defect Reference : WO39468	
				Date : 08/07/2021	
				Description of Defect :	
R86	040SFO	44525	01/06/2022 DEFECT	* FRONT AND REAR WINDOW CRACKED	
R86	040SFO	44682	01/17/2022 TYRES		15
R86	040SFO	44682	01/17/2022 TYRES		15
R86	040SFO	44813	01/18/2022 GEN		0
				REPAIR COMPLETED BY IAN AND KEIRAN	
R86	040SFO	44813	01/18/2022 GEN	REMOVE AND REPLACE BLOWN AIR BAG @ POS 7 (FRONT OF AXLE)	
R86	040SFO	44813	01/18/2022 GEN		0
R86	040SFO	44813	01/18/2022 GEN		16
R86	040SFO	44813	01/18/2022 GEN		11
R86	040SFO	44813	01/18/2022 GEN		11
R86	040SFO	44873	01/24/2022 GEN		39
R86	040SFO	44888	01/24/2022 GEN		39
R86	040SFO	44873	01/24/2022 GEN		39
R86	040SFO	44888	01/24/2022 GEN		39
R86	040SFO	44887	01/27/2022 GEN		39
R86	040SFO	44913	01/27/2022 GEN		39
R86	040SFO	44887	01/27/2022 GEN		39
R86	040SFO	44913	01/27/2022 GEN		39
R86	040SFO	44887	01/27/2022 GEN		39
R86	040SFO	44887	01/27/2022 GEN		39
R86	040SFO	44887	01/27/2022 GEN		39
R86	040SFO	44887	01/27/2022 GEN		39
R86	040SFO	44887	01/27/2022 GEN		39
R86	040SFO	44887	01/27/2022 GEN		39
R86	040SFO	44887	01/27/2022 GEN		39
R86	040SFO	44887	01/27/2022 GEN		39
R86	040SFO	44887	01/27/2022 GEN		39
R86	040SFO	44887	01/27/2022 GEN		39
R86	040SFO	44923	01/28/2022 GEN		39
R86	040SFO	44923	01/28/2022 GEN		39
R86	040SFO	44923	01/28/2022 GEN		39
R86	040SFO	44923	01/28/2022 GEN		39
R86	040SFO	44923	01/28/2022 GEN		39
R86	040SFO	44923	01/28/2022 GEN		39
R86	040SFO	44923	01/28/2022 GEN		39
R86	040SFO	44923	01/28/2022 GEN		39
R86	040SFO	47455	05/06/2022 GEN		39
R86	040SFO	47455	05/06/2022 GEN		39
R86	040SFO	47455	05/06/2022 GEN		39
R86	040SFO	47455	05/06/2022 GEN		39
R86	040SFO	47455	05/06/2022 GEN		39
R86	040SFO	47455	05/06/2022 GEN		39
R86	040SFO	47470	05/09/2022 GEN		0
R86	040SFO	47470	05/09/2022 GEN	REPAIR COMPLETED BY IAN AND TYLER	
R86	040SFO	47470	05/09/2022 GEN		0
R86	040SFO	47470	05/09/2022 GEN		16
R86	040SFO	47470	05/09/2022 GEN		11
R86	040SFO	47470	05/09/2022 GEN		11

R86	040SFO	47553	05/12/2022 GEN	REPAIR COMPLETED BY BEN AND IAN	0
				REPLACED FUEL SENDER - IAN	
				REPLACED WIPER BLADES - BEN	
				TIGHTENED COOLANT FILTER - IAN	
				REPAIR LATCH FOR GLOVE BOX LID	
R86	040SFO	47553	05/12/2022 GEN		
R86	040SFO	47553	05/12/2022 GEN		0
R86	040SFO	47553	05/12/2022 GEN		16
R86	040SFO	47575	05/13/2022 TYRES		15
R86	040SFO	47575	05/13/2022 TYRES		15
R86	040SFO	47575	05/13/2022 TYRES		15
R86	040SFO	47575	05/13/2022 TYRES		15
R86	040SFO	47599	05/16/2022 GEN		0
				REPAIR COMPLETED BY IAN AND KEIRAN	
R86	040SFO	47599	05/16/2022 GEN	CHECK CLUTCH OPERATION AND ADJUST EXCESS FREE TRAVEL AT QUADRANT	
R86	040SFO	47599	05/16/2022 GEN		0
R86	040SFO	47599	05/16/2022 GEN		16
R86	040SFO	47952	05/30/2022 TYRES		15
R86	040SFO	47952	05/30/2022 TYRES		15
R86	040SFO	47952	05/30/2022 TYRES		15
R86	040SFO	47952	05/30/2022 TYRES		15
R86	040SFO	47952	05/30/2022 TYRES		15
R86	040SFO	47952	05/30/2022 TYRES		15
R86	040SFO	47952	05/30/2022 TYRES		15
R86	040SFO	47952	05/30/2022 TYRES		15
R86	040SFO	51096	09/30/2022 GEN		39
R86	040SFO	51422	09/30/2022 GEN		39
R86	040SFO	51096	09/30/2022 GEN		39
				REPAIR COMPLETED BY VAWDREY	
				INV# Q24742	
R86	040SFO	51422	09/30/2022 GEN		39
R86	040SFO	51096	09/30/2022 GEN		39
R86	040SFO	51422	09/30/2022 GEN		39
R86	040SFO	51096	09/30/2022 GEN		39
				REPAIR COMPLETED BY BVR 30.09.2022	
				TRAVEL TO SITE AND INSPECT UNIT - MOUNT BATTERY BOX AND FIT BATTERY. RUN HARNESS CLAMPS	
				ALONG CHASSIS - FIT FUEL PUMP - RUN FUEL HOSES	
R86	040SFO	51096	09/30/2022 GEN		39
R86	040SFO	51096	09/30/2022 GEN		39
R86	040SFO	51096	09/30/2022 GEN		39
R86	040SFO	51096	09/30/2022 GEN		39
R86	040SFO	51421	10/13/2022 FVGEN		39
R86	040SFO	51421	10/13/2022 FVGEN		39
R86	040SFO	51421	10/13/2022 FVGEN		39
R86	040SFO	51421	10/13/2022 FVGEN		39
R86	040SFO	51421	10/13/2022 FVGEN		39
R86	040SFO	51421	10/13/2022 FVGEN		39
R86	040SFO	51421	10/13/2022 FVGEN		39
				SERVICE COMPLETED BY BVR 13.10.2022	
				4.10.2022 TRAVEL TO SITE AND INSPECT UNIT - EXTENDED BATTERY CABLES AND FIT NEW BATTERY	
				TERMINALS AS REQUIRED. RAN INCAB HARNESS INTO CAB	
				5.10.2022 TRAVEL TO SITE AND INSPECT UNIT - RUN CAPPING DOWN FRONT WALLS - RUN 2A WIRE	
				TO BATTERY - COMPLETE COVERING CABLES IN SPLIT TUBING - FIT HMI IN DASH	
R86	040SFO	51421	10/13/2022 FVGEN		39
R86	040SFO	51421	10/13/2022 FVGEN		39
R86	040SFO	51421	10/13/2022 FVGEN		39
R86	040SFO	51421	10/13/2022 FVGEN		39
R86	040SFO	51421	10/13/2022 FVGEN		39
R86	040SFO	51421	10/13/2022 FVGEN		39
R86	040SFO	51421	10/13/2022 FVGEN		39
R86	040SFO	51380	10/14/2022 CUMAES		0

[illegible]

INSPECTION COMPLETED BY SCOTT P - AEM MAREEBA 30.11.2022
Check over driver reported issue with horn. Replace blown fuse. No shorts found. Check horn and interior light - OK.

[illegible]

[illegible]

[illegible]

R86	040SFO	60756	10/10/2023 TYRES		15
R86	040SFO	60758	10/10/2023 TYRES		15
R86	040SFO	60760	10/10/2023 TYRES		15
R86	040SFO	60756	10/10/2023 TYRES		39
R86	040SFO	60758	10/10/2023 TYRES		15
R86	040SFO	60760	10/10/2023 TYRES		15
R86	040SFO	60756	10/10/2023 TYRES		15
R86	040SFO	60758	10/10/2023 TYRES		15
R86	040SFO	60760	10/10/2023 TYRES		15
R86	040SFO	60756	10/10/2023 TYRES		15
R86	040SFO	60758	10/10/2023 TYRES		15
R86	040SFO	60760	10/10/2023 TYRES		15
R86	040SFO	60756	10/10/2023 TYRES		39
R86	040SFO	60758	10/10/2023 TYRES		39
R86	040SFO	60760	10/10/2023 TYRES		15
R86	040SFO	60756	10/10/2023 TYRES		15
R86	040SFO	60758	10/10/2023 TYRES		15
R86	040SFO	60760	10/10/2023 TYRES		15
R86	040SFO	60756	10/10/2023 TYRES		15
R86	040SFO	60758	10/10/2023 TYRES		15
R86	040SFO	60758	10/10/2023 TYRES		15
R86	040SFO	60758	10/10/2023 TYRES		39
R86	040SFO	61206	10/23/2023 GEN		15
R86	040SFO	61206	10/23/2023 GEN		15
R86	040SFO	61206	10/23/2023 GEN		15
R86	040SFO	61206	10/23/2023 GEN		15
R86	040SFO	61206	10/23/2023 GEN		15
R86	040SFO	61206	10/23/2023 GEN		15
R86	040SFO	61999	11/16/2023 GEN		39
R86	040SFO	61999	11/16/2023 GEN		16
R86	040SFO	61999	11/16/2023 GEN		16
R86	040SFO	61999	11/16/2023 GEN		39
R86	040SFO	61999	11/16/2023 GEN		39
R86	040SFO	61999	11/16/2023 GEN		39
R86	040SFO	61999	11/16/2023 GEN		39
R86	040SFO	61999	11/16/2023 GEN		39
R86	040SFO	61999	11/16/2023 GEN		16
R86	040SFO	61999	11/16/2023 GEN		16
R86	040SFO	61999	11/16/2023 GEN		39
R86	040SFO	61936	11/17/2023 CUMAE5		1
R86	040SFO	61936	11/17/2023 CUMAE5	SERVICE COMPLETED.	
R86	040SFO	61936	11/17/2023 CUMBE5		1
SERVICE COMPLETED BY RED'S TRUCK & TRAILER ON 08/11/2023. INVOICE NO. 29712					
R86	040SFO	61936	11/17/2023 CUMBE5	CARRIED OUT B SERVICE	
R86	040SFO	61936	11/17/2023 CUMBE5		1
R86	040SFO	61936	11/17/2023 CUMBE5		16
R86	040SFO	61936	11/17/2023 CUMBE5		16
R86	040SFO	61936	11/17/2023 CUMBE5		6
R86	040SFO	61936	11/17/2023 CUMBE5		6
R86	040SFO	61936	11/17/2023 CUMBE5		6
R86	040SFO	61936	11/17/2023 CUMBE5		16
R86	040SFO	61936	11/17/2023 CUMBE5		40
R86	040SFO	61936	11/17/2023 CUMBE5		1
R86	040SFO	61936	11/17/2023 CUMBE5		16
R86	040SFO	61936	11/17/2023 CUMBE5		16
R86	040SFO	61936	11/17/2023 CUMBE5		6
R86	040SFO	61936	11/17/2023 CUMBE5		6
R86	040SFO	61936	11/17/2023 CUMBE5		6
R86	040SFO	61936	11/17/2023 CUMBE5		16
R86	040SFO	61936	11/17/2023 CUMBE5		40
R86	040SFO	62151	11/24/2023 GEN		15
R86	040SFO	62151	11/24/2023 GEN		15
R86	040SFO	62151	11/24/2023 GEN		15
R86	040SFO	62151	11/24/2023 GEN		15
R86	040SFO	62151	11/24/2023 GEN		15
R86	040SFO	62151	11/24/2023 GEN		15
R86	040SFO	62151	11/24/2023 GEN		15
R86	040SFO	62151	11/24/2023 GEN		15
R86	040SFO	62151	11/24/2023 GEN		15
R86	040SFO	62688	12/08/2023 CUMAE5		39

[illegible]

R86	040SFO	65209	02/19/2024	GEN		3
R86	040SFO	65209	02/19/2024	GEN		13
R86	040SFO	65209	02/19/2024	GEN		13
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		17
R86	040SFO	65209	02/19/2024	GEN		17
R86	040SFO	65209	02/19/2024	GEN		13
R86	040SFO	65209	02/19/2024	GEN		13
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		14
R86	040SFO	65209	02/19/2024	GEN		14
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		1
R86	040SFO	65209	02/19/2024	GEN		6
R86	040SFO	65209	02/19/2024	GEN		6
R86	040SFO	65209	02/19/2024	GEN		6
R86	040SFO	65209	02/19/2024	GEN		6
R86	040SFO	65209	02/19/2024	GEN		6
R86	040SFO	65209	02/19/2024	GEN		6
R86	040SFO	65209	02/19/2024	GEN		40
R86	040SFO	65209	02/19/2024	GEN		40
R86	040SFO	65209	02/19/2024	GEN		40
R86	040SFO	65209	02/19/2024	GEN		40
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		13
R86	040SFO	65209	02/19/2024	GEN		3
R86	040SFO	65209	02/19/2024	GEN		13
R86	040SFO	65209	02/19/2024	GEN		13
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		17
R86	040SFO	65209	02/19/2024	GEN		17
R86	040SFO	65209	02/19/2024	GEN		13
R86	040SFO	65209	02/19/2024	GEN		13
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		14
R86	040SFO	65209	02/19/2024	GEN		14
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65209	02/19/2024	GEN		16
R86	040SFO	65492	03/10/2024	DEFECT		1
R86	040SFO	65492	03/10/2024	DEFECT		
R86	040SFO	65492	03/10/2024	DEFECT	DEFECT CLEARED.	
R86	040SFO	65492	03/10/2024	RIGVANB		0

R86	040SFO	67701	05/23/2024	FVGEN	Service completed by FNQ Transport 23/05/2024 - Check squealing noise found broken fan shaft, housing rebuilt second hand one and fitted re-tensioned belts and test run, ok at time of testing	
R86	040SFO	67701	05/23/2024	FVGEN		39
R86	040SFO	67701	05/23/2024	FVGEN		39
R86	040SFO	67701	05/23/2024	FVGEN		39
R86	040SFO	67701	05/23/2024	FVGEN		39
R86	040SFO	68464	06/18/2024	GEN		1
R86	040SFO	68464	06/18/2024	GEN		16
R86	040SFO	68464	06/18/2024	GEN		6

				'A' SERVICE COMPLETED BY AEM MAREEBA ON 22/11/2024.	
				DEFECT:	
				SUMP LEAKING	
				DUMP PIPE FLANGE WORN OUT AND NOT SEALING ON 'V' BAND CLAMP	
				KING PINS	
				WIPER MOTOR STRIPPED	
R86	040SFO	73948	11/22/2024 CUMAE5	F/E LAST INSPECTED: FEB 2024	
R86	040SFO	73819	12/01/2024 FVGEN		39
R86	040SFO	73819	12/01/2024 FVGEN		39
R86	040SFO	73819	12/01/2024 FVGEN		39
				Service completed by FNQ Transport 01/12/2024 - Job. No.D111 - Called to check alternator fault check and found alternator belt damaged - damage caused from birds nest in unit - cleaned out - fit new belt test, ok at time of testing	
R86	040SFO	73819	12/01/2024 FVGEN		39
R86	040SFO	73819	12/01/2024 FVGEN		39
R86	040SFO	73819	12/01/2024 FVGEN		39
R86	040SFO	73949	12/03/2024 CUMAE5		1
R86	040SFO	73949	12/03/2024 CUMAE5	SERVICE COMPLETED.	
				'B' SERVICE COMPLETED BY AEM MAREEBA ON 03/12/2024.	
				F/E LAST INSPECTED FEB 2024	
				DUMP PIPE LEAKING OFF TURBO - REQUIRES REPLACEMENT	
				KING PIN MOVEMENT	
R86	040SFO	73949	12/03/2024 CUMBES	REPLACED TOP RIGHT CLEARANCE LIGHT	
R86	040SFO	73949	12/03/2024 DEFECT		1
R86	040SFO	73949	12/03/2024 DEFECT		
R86	040SFO	73949	12/03/2024 DEFECT	DEFECT CLEARED.	
R86	040SFO	74072	12/04/2024 FVGEN		39
R86	040SFO	74072	12/04/2024 FVGEN		39
R86	040SFO	74072	12/04/2024 FVGEN		39
R86	040SFO	74072	12/04/2024 FVGEN		39
R86	040SFO	74072	12/04/2024 FVGEN		39
				Service completed by FNQ Transport 04/12/2024 - Job No. D117	
				Carried out service to refrigeration unit - Changed engine oil and all filters, checked all levels and belts - Washed condenser and evaporator - Could not carry out good calibration due to the rear door seals needing replacement and evaporator is blocked with dirt and will need a good hot wash	
R86	040SFO	74072	12/04/2024 FVGEN		39
R86	040SFO	74072	12/04/2024 FVGEN		39
R86	040SFO	74072	12/04/2024 FVGEN		39
R86	040SFO	74072	12/04/2024 FVGEN		39
R86	040SFO	74072	12/04/2024 FVGEN		39
R86	040SFO	75203	01/20/2025 TYRES		15
R86	040SFO	75203	01/20/2025 TYRES		15
R86	040SFO	75203	01/20/2025 TYRES		15
R86	040SFO	75203	01/20/2025 TYRES		15
R86	040SFO	75487	01/23/2025 DEFECT		1
R86	040SFO	75487	01/23/2025 DEFECT	DEFECT CLEARED.	
				REPAIR COMPLETED BY AEM MAREEBA ON 23/01/2025.	
				CHECK OVER DRIVER REPORTED FAULTS WITH VEHICLE. LIAISE WITH MICK AT BRISBANE WORKSHOP.	
				NOTED:	
				* FRONT SUSPENSION REQUIRES REPLACEMENT	
				* AIRCON FAN UNSERVICEABLE AND SYSTEM LOW ON REFRIGERANT	
				* BODY CROSS MEMBER REQUIRES REPAIRS (TO BE COMPLETED BY ENGINEERING FIRM)	
				* REAR FLOOR DAMAGED	
				* A SERVICE DUE	
R86	040SFO	75487	01/23/2025 GEN		
R86	040SFO	75487	01/23/2025 GEN		16
R86	040SFO	75487	01/23/2025 GEN		39
R86	040SFO	75487	01/23/2025 GEN		39

				A SERVICE COMPLETED BY AEM MAREEBA ON 19/02/2025 INVOICE NO. 00012770	
				Complete A, C & D service as per document provided by Exodas Pty Ltd. Replace aircon fan assembly as required. Connect gauges and check pressures. Add oil, dye and aircon refrigerant. Check pressures and temp - OK. Replace belt for thermoking water pump as required. Degrease engine. Wash down. Road test. Supply 2 light globes as requested	
R86	040SFO	76142	02/19/2025 CUMAE5	FIRE EXT EXP: LAST CHECKED FEB 2024 C SERVICE COMPLETED BY AEM MAREEBA ON 19/02/2025. INVOICE NO. 00012770	
				Complete A, C & D service as per document provided by Exodas Pty Ltd. Replace aircon fan assembly as required. Connect gauges and check pressures. Add oil, dye and aircon refrigerant. Check pressures and temp - OK. Replace belt for thermoking water pump as required. Degrease engine. Wash down. Road test. Supply 2 light globes as requested.	
R86	040SFO	76143	02/19/2025 CUMCE5	FIRE EXT EXP: LAST CHECKED FEB 2024	
R86	040SFO	76142	02/19/2025 DEFECT		1
R86	040SFO	76143	02/19/2025 DEFECT		1
R86	040SFO	76144	02/19/2025 DEFECT		1
R86	040SFO	76142	02/19/2025 DEFECT	DEFECT CLEARED.	
R86	040SFO	76143	02/19/2025 DEFECT	DEFECT CLEARED.	
R86	040SFO	76144	02/19/2025 DEFECT	DEFECT CLEARED. Reported Defect :- Defect Code : 00013616 Defect Reference : R86 Date : 23/01/2025 Description of Defect : A-SERVICE DUE Reported Defect :- Defect Code : 00013613 Defect Reference : R86 Date : 23/01/2025 Description of Defect : AIRCON FAN UNSERVICEABLE AND SYSTEM LOW ON REFRIGERANT VEHICLE DID NOT PASS ANNUAL ROADWORTHY INSPECTION ATTEMPT # 1	
R86	040SFO	76142	02/19/2025 DEFECT		
				INSPECTION COMPLETED BY AEM MAREEBA ON 19/02/2025	
				Complete A, C & D service as per document provided by Exodas Pty Ltd. Replace aircon fan assembly as required. Connect gauges and check pressures. Add oil, dye and aircon refrigerant. Check pressures and temp - OK. Replace belt for thermoking water pump as required. Degrease engine. Wash down. Road test. Supply 2 light globes as requested.	
R86	040SFO	76144	02/19/2025 EXOINS	DEFECTS AS PER FAULT REPORT. 00013086, 00013087, 00013615, 00013614, 00013612	
R86	040SFO	76144	02/19/2025 EXOINS		1
R86	040SFO	76144	02/19/2025 EXOINS		6
R86	040SFO	76144	02/19/2025 EXOINS		6
R86	040SFO	76144	02/19/2025 EXOINS		6
R86	040SFO	76144	02/19/2025 EXOINS		6
R86	040SFO	76144	02/19/2025 EXOINS		6
R86	040SFO	76144	02/19/2025 EXOINS		6
R86	040SFO	76144	02/19/2025 EXOINS		6
R86	040SFO	76144	02/19/2025 EXOINS		40
R86	040SFO	76144	02/19/2025 EXOINS		40
R86	040SFO	76144	02/19/2025 EXOINS		40
R86	040SFO	76144	02/19/2025 EXOINS		16
R86	040SFO	76144	02/19/2025 EXOINS		16
R86	040SFO	76144	02/19/2025 EXOINS		13
R86	040SFO	76144	02/19/2025 EXOINS		16
R86	040SFO	76144	02/19/2025 EXOINS		16
R86	040SFO	76144	02/19/2025 EXOINS		3

[illegible]

R86	040SFO	78178	05/23/2025 GEN		39
R86	040SFO	78178	05/23/2025 GEN		39
R86	040SFO	78178	05/23/2025 GEN		39
R86	040SFO	78178	05/23/2025 GEN		39
R86	040SFO	78178	05/23/2025 GEN		39
R86	040SFO	78178	05/23/2025 GEN		39
R86	040SFO	78485	06/06/2025 CUMAE5		0
A SERVICE COMPLETED BY AEMSC 06.06.2025 INV # 00012365					
FIRE EXT EXP:					
Complete A service as per document provided by Exodas Pty Ltd. Top up engine oil. Replace blown RH tail light bulb as required. Grease suspension. Road test. Omitted in error from invoice 12770 20/02/2025: Check over issue with belt. Source, remove and replace drive belt as required. Check over - OK.					
R86	040SFO	78485	06/06/2025 CUMAE5		16
R86	040SFO	78485	06/06/2025 CUMAE5		1
R86	040SFO	78485	06/06/2025 DEFECT		
R86	040SFO	78485	06/06/2025 DEFECT	DEFECT CLEARED.	
R86	040SFO	80873	09/10/2025 GEN		39
REPAIR COMPLETED BY HARTWIGS MECHANICAL 10/09/2025					
INVOICE #4277					
CHECKED AND ADJUSTED CLUTCH AS REQUESTED BY CUSTOMER CLUTCH ENGAGES AT TOP OF PEDAL, WORN OUT AND NEEDS REPLACING					
R86	040SFO	80873	09/10/2025 GEN		39
R86	040SFO	80873	09/10/2025 GEN		39
R86	040SFO	80998	09/18/2025 GEN		
REPAIR COMPLETED BY ROWE AUTO ELECTRICAL 18/9/2025					
INVOICE #00035600					
REMOVE TELETRAC NAVMAN					
R86	040SFO	80998	09/18/2025 GEN		39
R86	040SFO	80998	09/18/2025 GEN		15
R86	040SFO	81055	09/23/2025 TYRES		15
R86	040SFO	81055	09/23/2025 TYRES		15
R86	040SFO	81055	09/23/2025 TYRES		15