

TAX INVOICE

BJC HEAVY HAULAGE

Invoice Date
28 Aug 2025

Invoice Number
INV-3290

Reference
XB25KJ

ABN
92 202 366 253

Timbo's Auto
6 Troy Drive
Goondiwindi QLD 4390
Phone: 0482519533

Description	Quantity	Unit Price	GST	Amount AUD
LABOUR Check start on peter built. Check voltages. Diagnosed isolation switch turned off. Turn on isolation switch. Crank no fire. Checked all fuses-ok Check codes. INSITE Computer no communication with ecm. Check for damaged wiring. Pin out harness-ok Diagnosed faulty ecm. Order parts. Removed replaced ecm. Flash ecm. Test drive truck-ok Tidy ecm wiring and harness Removed isolation switch from truck. Make new earth leads to suit. Fit leads Check ice pack. Diagnosed faulty start relay. Removed replaced relays. Diagnosed bad connection on fuel pump and starter motor. Repair connections. Check operation-ok	7.00	130.00	10%	910.00

KM 613529

PARTS RECON ECM (EPR)	1.00	7,292.66	10%	7,292.66
PARTS ECM CORE RETURN	0.00	1,300.00		0.00
PARTS ECM FLASH FILE F/N N11500 620HP 2050 FT LBS	1.00	1,600.00	10%	1,600.00

Description	Quantity	Unit Price	GST	Amount AUD
MINI RELAY 12V 40amp N/O 5 PIN RESISTOR TYPE	3.00	14.00	10%	42.00
00 B&S BATTERY CABLE BLACK	2.00	33.00	10%	66.00
CABLE LUG 70mm x 10mm	4.00	3.50	10%	14.00
CONSUMABLES	1.00	30.00	10%	30.00
FREIGHT	1.00	30.00	10%	30.00
			Subtotal	9,984.66
			TOTAL GST 10%	998.47
			TOTAL AUD	10,983.13

Due Date: 28 Aug 2025

Please make payment to:

Account Name: Tim Forster

BSB: 014583

ACC: 641798411

-X-----

PAYMENT ADVICE

Customer	BJC HEAVY HAULAGE
Invoice Number	INV-3290
Amount Due	10,983.13
Due Date	28 Aug 2025
Amount Enclosed	

To: Timbo's Auto
6 Troy Drive
Goondiwindi QLD 4390
Phone: 0482519533

Enter the amount you are paying above



All Time Diesel Pty Ltd
9 Wills Road
PO Box 793
Emerald, QLD 4720

Phone (07) 4911 1020 **Mob** 0400 262 233
Email admin@alltimediesel.com.au
A.B.N. 32 617 075 751

BJC Heavy Haulage
14087 Gore Hwy
Goondiwindi, QLD
(04) 1971 1360

Registration XB25KJ
Make/Model Peterbilt
Odometer
Colour White
VIN 1NPXGGG50D219740
Build Date 04/2014

Item	Description	Quantity	Unit Price	GST	Total
LABOUR					
LABOUR TECH	Lab	4.00	\$130.00	\$52.00	\$572.00
Labour Total					\$572.00
PARTS					
CT300L	Radiator Hose Clamp 2.5" Hose	2.00	\$23.79	\$4.76	\$52.34
70.250	Silicone Radiator Hose 63mm 2.5" ID Per CENTREMETRE	20.00	\$0.84	\$1.68	\$18.48
NPN03	Supply Battery Only	1.00	\$247.56	\$24.76	\$272.32
Parts Total					\$343.14
CONSUMABLES					
NPN02	Workshop Consumables Used	1.00	\$21.00	\$2.10	\$23.10
Consumables Total					\$23.10
					Subtotal \$852.94
					GST \$85.30
					Total \$938.24

Payment Terms: **14DAYS** **Balance Due** **\$938.24**

Invoice Notes

Investigate coolant leak for possible water pump failure, found water pump to be ok. Coolant leak coming from top radiator hose. Drained coolant, removed old and fit new top radiator hose housing with new clamps. Refill radiator with reclaimed coolant. Wash all coolant residual off side of engine. Pressure test cooling system to verify repairs.

Remove and test batteries, 1 x battery boiled and remaining batteries in ordinary state. Tried to source 4 new batteries but only 1 battery available in town. Replaced faulty battery, cleaned up all connections. Returned vehicle to service.

Please ensure payment is made within our Trading Terms.
All Time Diesel Pty Ltd BSB: 064 704 Account #: 1039 7721



Vehicle History Summary

BJC Heavy
Haulage

Fleet #	P7
Registration	XB25KJ
Make	PETERBILT
Model	389
VIN / Chassis #	1NPXGGGG50D219740
Build Date	2013

Date	Reading / Units	Type / Repairer Notes	Repairer
08/02/2026		Alternator, Battery R-169	
08/10/2025	632,388 kms	B - 250Hrs S-626 405 hrs	Internal Workshop
09/09/2025	621,512 kms	B - 250Hrs S-625 162 hrs	Internal Workshop
		Please note inbetween last service and this one ecm short circuited it self due to wiring issue and was replaced with another so old old hours plus the old hours plus these hours old hours were not up loaded into ecm from the out side company Old old hours 7498 Old hours 3707 New hours 168 Hours all up 11373 hrs on engine	
28/07/2025	3,707 hrs	B - 250Hrs S-624	Internal Workshop
23/06/2025	588,173 kms	B - 250Hrs S-623 3,365 hrs	Internal Workshop
25/05/2025	3,058 hrs	B - 250Hrs S-622	Internal Workshop
		Note the hours on truck are different compared to older readerings due to ecm being changed so hours must be added to old hours Old hour hours 7489 New hours 3058	
14/04/2025	2,685 hrs	B - 250Hrs S-621	Internal Workshop
13/03/2025	547,856 kms	B - 250Hrs S-600 2,396 hrs	Internal Workshop
13/02/2025	532,732 kms	B - 250Hrs S-597 2,090 hrs	Internal Workshop
16/01/2025	522,625 kms	turntable R-161 1,897 hrs	Internal Workshop
		replace turntable with new one and bolt and touqe to spec	
18/12/2024	514,032 kms	C - 365Day S-579 1,686 hrs	Internal Workshop
17/09/2024		Lights R-154 rubbed wire fixed wire	Internal Workshop
10/09/2024	480,914 kms	B - 250Hrs S-541 7,489 hrs	Internal Workshop
26/08/2024	475,157 kms	Drum Bearings R-145 628 hrs	Internal Workshop
		pull apart and clean and replace damaged wheel seal and repac bearing and put back together	
20/08/2024	471,677 kms	Suspension R-143 554 hrs	Internal Workshop
		undo u bolts and replace shock/bump stop	

Date	Reading / Units	Type / Repairer Notes	Repairer
05/08/2024	465,157 kms 407 hrs	Chassis R-138 fixed leaking air fittings two ride hight control valves are leaking soricing parts	Internal Workshop
05/08/2024	465,157 kms 407 hrs	Suspension R-141 replaced drive shocks and cab shocks	Internal Workshop
05/08/2024	465,157 kms 407 hrs	B - 250Hrs S-529	Internal Workshop
04/07/2024	446,100 kms 5,700 hrs	B - 250Hrs S-506	Internal Workshop
04/07/2024	446,100 kms 5,700 hrs	Driveline R-111	Internal Workshop
03/07/2024	446,100 kms 5,700 hrs	Engine R-107	Internal Workshop
22/05/2024		Lights R-116	
23/04/2024	8,893 kms	Power Steering R-136	Vic Baker
22/04/2024	42,937 kms 5,265 hrs	Driveline R-133	Toowoomba Heavy Diesel
19/04/2024	430,217 kms 5,291 hrs	B - 250Hrs S-484 ice pac serviced at 797.8 hrs	Internal Workshop
08/04/2024	425,012 kms 5,187 hrs	Suspension R-97	Internal Workshop
14/03/2024	415,750 kms 5,028 hrs	Driveline R-86	Internal Workshop
14/03/2024	41,570 kms 5,028 hrs	Chassis R-87	Internal Workshop
11/03/2024	415,588 kms 5,018 hrs	B - 250Hrs S-473	Internal Workshop
05/02/2024	403,103 kms 4,749 hrs	C - 365Day S-456	Internal Workshop
14/12/2023		Driveline R-43	Internal Workshop
11/12/2023		Steering R-74	Tony Briskey
28/11/2023	388,382 kms 4,487 hrs	Driveline R-42	Internal Workshop
24/11/2023	388,381 kms 4,487 hrs	B - 250Hrs S-147	Internal Workshop
02/11/2023	377,269 kms 4,316 hrs	Driveline R-64	Marters Mechanical
02/11/2023	377,269 kms 4,316 hrs	Alternator R-64	Marters Mechanical

Date	Reading / Units	Type / Repairer Notes	Repairer
02/11/2023	377,269 kms 4,316 hrs	Engine R-64 carried out hot set to motor	Marters Mechanical
01/11/2023	4,083 hrs	A - 150Hrs S-145	Internal Workshop
19/10/2023	367,959 kms 4,176 hrs	B - 250Hrs S-137	Internal Workshop
11/09/2023	352,270 kms 3,933 hrs	B - 250Hrs S-119	Internal Workshop
04/09/2023		Cab R-54	DDH
23/08/2023	344,760 kms 37,796 hrs	Engine R-33	Internal Workshop
15/08/2023	344,760 kms 3,779 hrs	A - 150Hrs S-111	Internal Workshop
10/08/2023	3,715 hrs	A - 150Hrs S-105	Internal Workshop
24/07/2023	333,333 kms 3,520 hrs	B - 250Hrs S-94 gaskets ordered for gearbox oil leak	Internal Workshop
30/06/2023		Lights R-27	Internal Workshop
27/06/2023		Driveline R-25	
19/06/2023	317,747 kms 3,321 hrs	B - 250Hrs S-74	Internal Workshop
15/05/2023	3,040 hrs	B - 250Hrs S-68	Internal Workshop
01/05/2023	292,548 kms 2,500 hrs	Cab R-20 Replace faulty air bag	Internal Workshop
28/04/2023	289,910 kms 2,685 hrs	Engine R-17 Replace water pump	Internal Workshop
28/04/2023	289,913 kms 2,785 hrs	Engine R-18 REMOVE AND REPLACE BEARINGS IN IDLERS	Internal Workshop
28/04/2023	289,910 kms 2,685 hrs	Driveline R-16 replace drive shaft unis	Internal Workshop
28/04/2023	289,913 kms 2,785 hrs	Steering R-18 REMOVE AND REPLACE WHEEL SEAL	Internal Workshop
27/04/2023	289,910 kms 2,685 hrs	Cab R-16 Replace leaking cab air bag	Internal Workshop
15/04/2023	289,910 kms 2,685 hrs	B - 20k S-58	Internal Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
21/02/2023	263,935 kms 2,168 hrs	Driveline R-15 Replace both unis i	Internal Workshop
21/02/2023	263,935 kms 2,168 hrs	A - 10k S-52	Internal Workshop
08/12/2022	269,167 kms 2,359 hrs	Suspension R-5	Internal Workshop
02/11/2022	263,935 kms 2,168 hrs	C - 80k S-27	

Signed:

Name:

Date:



PITTSWORTH FLEET MAINTENANCE

TAX INVOICE

Tax Invoice Number: PFM1453

Date: 15/12/2025

Due Date: 22/12/2025

Payment Term: End of Month

20 Cypress Street
Pittsworth Queensland 4356
ABN: 58 657 489 220
Licence: ARCTick RTL: AU56443
Tel: (07) 45892412
Email: accounts@pittfm.com.au
Website: www.pittfm.com.au

BILL TO:

BJC HEAVY HAULAGE PTY LTD
14087 Gore Highway
Kindon Queensland 4390
ABN: 34615480870
Mobile: 0419711360
Email: accounts@bjchaulage.com.au

FOR:

XB25KJ - Air Leaks

Make	Model/Year	Body Type	Reg No.	Odometer	Color
Peter Built	389AT/2013		XB25KJ	642,079 Kms	

Description	Qty.	Unit Price	GST	Amount
Labour- Workshop Pittsworth Fleet Maintenance	12.0	\$160.00	\$192.00	\$1,920.00
Freight	1.0	\$18.00	\$1.80	\$18.00
Torque Rod Female with Bush	2.0	\$332.33	\$66.47	\$664.66
Torque Rod Male with Bush	2.0	\$376.29	\$75.26	\$752.58
MACK/ ETC ARDST airbag	2.0	\$257.40	\$51.48	\$514.80
Freight	1.0	\$14.50	\$1.45	\$14.50
1/2x3/8 Male Elb A/B Quick-Fit	2.0	\$15.68	\$3.14	\$31.36
1/2x3/8 Male Airbrake Quick Fit	2.0	\$10.17	\$2.03	\$20.33
Tapered Roll Bearing	1.0	\$250.51	\$25.05	\$250.51
Tapered Roll Bearing	1.0	\$157.63	\$15.76	\$157.63
Cr Scotseals	1.0	\$68.80	\$6.88	\$68.80

28/11/2025
-Replace d/s steering wheel bearings and seal
-Replace rear engine mounts
-Run new air line to valve on drive to increase airline flow
-Replace top torque rod bushes on top of diffs
-Diagnose a/c fault trucks requires new blower motor
-Source parts

Subtotal	\$4,413.17
GST	\$441.32
Total	\$4,854.49
Paid	\$0.00
Balance Due	\$4,854.49

Our Banking details are Acct Name: Pittsworth Fleet Maintenance Pty Ltd | BSB: 084-961 | Acct Number: 98 095 7712
Please remember to note the INVOICE number on your EFT remittance.

PAYMENTS ARE STRICTLY DUE ON RECEIPT OR UNLESS STATED ABOVE FOR ACCOUNT CONTRACTS ONLY

Please note: a reasonable surcharge will be applied for all late payments on all invoices after several contact attempts. Condition of Sale subject to our Terms of Sales which can be requested at any time. Parts remain the property of Pittsworth Fleet Maintenance Pty Ltd until this invoice is paid in full. Warranty: is limited to PFM Approval. Consent must be obtained from PFM before commencement of any works. Failing to do so may result in your warranty claim being denied. No warranty on unpaid invoices. Warranty period is 12 months from installation/repair. All parts are as per manufacturer's warranty. **Conditions Apply