

Make	Heil
Model	
VIN / Chassis	6V9TABB3S9T014015
Build Date	2009

Number	Date	Km	Hours	Fuel Usage	Type	Repairer Notes	Repairer
R-2329					0 AIR LEAK, API valve	Replaced	Internal
O-749	2026-05-22	0	0		0 Internal Tanker wash	Internal Wash AM	Third Party
S-1020	2025-10-13	0	0		0 C - C Service	C Service completed	Third Party
R-1852	2025-10-13				0 Hand rail	Fault fixed- cost included in cost for service	Third Party
S-829	2025-05-01	0	0		0 B - B Service	Puncture repairs completed only so far.	Internal
T-501	2025-04-30				0 RUNOUT	Runout -1st axle RHS Inner. Puncture repair- 2nd axle LHS outer.	Internal
T-491	2025-04-04	0	0		0 Puncture		Internal
R-1555	2025-01-06				0 Air leaks	Replaced	Internal
S-626	2024-10-30	0	0		0 B - B Service	Carry out Trailer B service as per service sheet. Repairs carried out: - Missing 2x grease nipples on 3rd axle S-cams. Fit new grease nipples as required. -Tension loose RHS 1st axle shock absorber (top) bolt.	Third Party
T-333	2024-10-22	0	0		0 Puncture		Internal
T-335	2024-10-22	0	0		0 Puncture		Internal
S-477	2024-07-22	0	0		0 B - B Service	b service true up tyres air leaks hand rail air rams leaking	Internal
R-1260	2024-06-24	0	0		0 King Pin, Ring Feder	Fit new Ring Feder	Internal
S-382	2024-05-16	0	0		0 C - C Service		Third Party
R-1176	2024-01-31	0	0		0 Trailer plug		Internal
S-235	2024-01-16	0	0		0 C - C Service	cleaned and repacked all wheel bearings. Used 6kg of BPW grease. replaced left hand middle and rear wheel bearings. resealed both handrail seals. need to replace all grease nipples in slack adjusters and cam shaft tubes.	Internal
S-78	2023-10-25	1	0		0 B - B Service		Internal
S-133	2023-10-10	1			0 B - B Service		Third Party
R-871	2023-09-29	0	0		0 AIR LEAK	Collect parts from Liquip Drive to workshop Replace leaking top seal	Internal

						Fixed air leaks Greased Checked bearings Checked king pin	
S-112	2023-09-19	1			A - A Service		Internal
R-860	2023-09-19	3	0	0	Jost Legs	Replaced handle	Internal
R-647	2023-07-28	0	0	0	Air bags	Replace all 6 air bags	Internal
R-651	2023-07-28	0	0	0	Shock Absor	Replace all 6 shocks	Internal
R-650	2023-07-28	0	0	0	Lights	Replace light assembly	Internal
R-649	2023-07-28	0	0	0	Tanker	Replace all 5 internal valve solenoids	Internal
R-648	2023-07-28	0	0	0	Marker Plates	Replace marker plates	Internal
R-652	2023-07-28	0	0	0	AIR LEAK	Reseal relay valve RH side between 1st and 2nd axles Tighten all booster clamps Replace air regulator	Internal
R-657	2023-07-21	0	0	0	Footvalve	AIR RAM ASSY FOR FOOTVALVE SLV FILTER/REG LUBE (NO GAUGE) EXCEL72 QUIKCLAMP WALLBKT NECK MOUNT BRACKET	Third Party
R-184	2023-03-31		0	0	SLP	SLP PASS 164210	Third Party