



Plant & Vehicle Maintenance & Repairs

Asset Number: CO213		Registration Number: SV3954	Serial Number: CAT0930KHRHN02880
Make: Caterpillar		Model: 930K Loader	Date of Manufacture 2015
Date	Hrs/Kms	Work Conducted	Responsible Person
09/29/2015	250	250 hrs service. Change eng oil and filters.	TG/GC
11/12/2015	437	Repalce O ring at relief valve.	TG/GC
11/28/2015	508	Change cutting edges.	TG/GC
02/09/2016	702	Repair LH indicator wiring at switch.	TG/GC
03/17/2016	833	750 hrs service.	TG/GC
05/04/2016	990	Repair fork slipper.	TG/GC
05/10/2016	1002	Free up and lubricate quick hitch shafts.	TG/GC
05/17/2016	1020	1000 hrs service.	TG/GC
06/24/2016	1098	Change diff oils as per SOS, re-sample at 1223 hrs.	TG/GC
06/25/2016	1098	Change rear diff oil as per SOS, re-sample at 1348 hrs.	TG/GC
08/03/2016	n/a	Bucket sent to Wilkinsons Engineering to replace heel plates.	TG/GC
08/25/2016		Wilkinson repaired bucket, removed & replaced wear strip & heel plates on ext floor, removed & replaced bolt on Wilkinson	
09/14/2016	1292	250 Hrs Service, Remove Cover plates & lubricate rear drive shaft	TG
09/22/2016	1310	Replace engine inner air filter. Replace 2 air con filters.	GC
10/06/2016	1351	Sample front and rear diffs at half interval as per SOS report.	TG/GC
12/03/2016	1483	500 hrs service.	TG/GC
01/12/2017	1536	Free up and lubricate quick hitch rods.	GC
01/17/2017	1550	Hastings - inspect air con operation (faulty compressor).	GC
01/18/2017	1550	Remove panels ready for Hastings. Hastings replaced compressor, recharged air con. system and test.	GC
01/19/2017	1551	No L/H indicator, remove indicated switch, repair broken wire.	GC
02/06/2017		Hastings callout to repair faulty A/C compressor caused by low refrigerant & leaking compressor	TG
02/14/2017		Puncture repairs 20.5R25 - refer Arno Invoice 158507	GC
07/20/2017		Replace bucket edges and bolts an dnuts. Replace arm rest	TG GC
07/24/2017	1805	Service and repair hyd oil leak suction ??	TG
08/09/2017		Checked all good - transmission oil not in sight glass	MM
09/18/2017		Part fitted by Ellis Mobile, new pressure switch. Air con OK	Ellis Auto
01/15/2018		Quick hitch fixed	
01/24/2018		Cutting edge and heel plates worn - done	MM
03/07/2018	2687	Complete 500hr service	BO MM
06/28/2018	3056	3000hr service, wash and clean, repair indicator wiring	GC TG

Plant & Vehicle Maintenance & Repairs

Asset Number: CO213		Registration Number: SV3954	Serial Number: CAT0930KHRHN02880
Make: Caterpillar		Model: 930K Loader	Date of Manufacture 2015
07/05/2018		Replace fittings on loader auxillary pipes, remove jack from hose spooling, linish pump piston and rod, reseal and assemble, test OK. Hosepower invoice W26220	GC TG
10/18/2018	3266	250 hr service, replaced air filters, changed cutting edges	TG SS
11/21/2018	3366	Diagnose temp issue, has broken a/c line	MM
11/28/2018	3374	Replace dishcharge hose and drier for a/c	Ellis Auto
12/17/2018		Front RH tyre slow leak - Done	TG
04/23/2019	3573	500hr service, change engine oil and fuel filterrs, replace air filters and cab filters	TG SS
06/04/2019	3633	Repair air hose supply to seat	TG
07/16/2019	3702	2 batteries recived and changed out	GC
08/06/2019	3745	250 hour service, changed engine oil, filters, fuel filters, inspect seat leak, ordered parts	TG
08/29/2019	3782	Remove and replace seat adjust valve	TG
08/29/2019	3782	Remove and manufacture new rear window, and refit - Windscreens Territory	TG
01/10/2020	3967	Checked Quick hitch intermittent operation, replaced switch, tested. OK.	TG
01/23/2020	3995	4000 hr service, changed engine oil, transmission oil, front and rear diff oils, replaced hose on oil cooler return line	TG SS
06/23/2020	4236	Lubricate door latch. OK	TG
07/28/2020	4264	250 hr service complete, change engine oil and filter, replaced air filters	TG
07/28/2020	4264	Cut off old wear plate under bucket and replace, 500 Bisalog	TG SS
08/29/2020	4269	Ordered new parts from HD. ETA Mon 31/8	TG SS
09/02/2020	4267	Replaced cutting edges and bolts.	TG SS
10/08/2020		Resealed both steering cylinders and bucket tilt cylinder	SS TG
10/16/2020	4407	Repaired/replaced locking pin knob	SS
12/10/2020	4606	500 hr service completed.	TG SS
03/06/2021	4836	250 hr service complete, oil & fileter change, blow out all filters, grease.	SS
23/06/2021		4 x Mich 20.5R25 XHA2 L3 Tyres - Refer Inv NT Tyres 76273-	NTT
04/27/2021	5010	1000 hr service done, fuel filters, engine & air filters, cab AC filters, oil samples done	TG SS
07/20/2021	1285	Replaced blown hydraulic hose on articulation to pump	SS
08/05/2021	5234	250 hr service, sample engine oil, change oil, filters, blow out all A/C and air filters, grease machine	SS
08/31/2021	5300	Replaced broken ignition switch wirth new switch, slight mods needed to wiring - completed all good	SS
10/20/2021	5353	High exhaust pressure code issues - refer to attached Hastings service journal	TG/Hastings
11/09/2021	5420	Replaced 4 x sun damaged hydraulic hoses for crowd cylinder and remote hydraulics	
11/12/2021		Fit new fork tyres	Glen Abbot
11/30/2021	5461	Leaking steering cylinder, replaced seals & reassembled	TG
21/06/2022	5778	JN#3134 - 250hr Sve, changed engine oil, oil filters, replaced AC filters, blown out & air filters blown out, Greasec	SS

Plant & Vehicle Maintenance & Repairs

Asset Number: CO213		Registration Number: SV3954	Serial Number: CAT0930KHRHN02880
Make: Caterpillar		Model: 930K Loader	Date of Manufacture 2015
07/05/2022	5798	JN#3137 - Leaking cylinder - Removed RH light cylinder, Hosepower re-sealed, refitted tested OK	SS
07/07/2022		Re Seal lift Cylinder - refer Hosepower Inv IN045879 attached	HP
07/21/2022	5848	JN#3147 - Changed out cutting edges.	TG SS
28/07/2022	5848	JN#3133 - Replaced front windscreen & wiper arms, old arms stripped in spline on arms	TG/SS
10/07/2022	5984	JN#3204 - Fault, leaking oil. Replaced 2x pilot hydraulic hoses.	SS TG
10/11/2022		JN#3100 - Repaired wiper arms, replaced washer bottle.	SS TG
11/04/2022	6005	JN#3253 - Completed 6000hrs Sve, changed engine oil, filters, air filters, trans oil, hydraulic oil, diff oils, checked valve & adjusted	SS
11/14/2022		Refer to att bridgestone Inv 90191359 - straight air/Liq valve, O rings, 0020 Service	Bridgestone Mining
11/22/2022		Replaced leaking hydraulic pipe on front valve block. Was leaking oil from manufactured weld.	SS
01/25/2023		Checked operation of wiper washer jet. Not working, found loose plug on washer motor tank	SS
02/08/2023	6083	Replaced fuel filters and drain water from fuel tank. Replaced startor isolator	SS
05/30/2023	6182	Bleed off water from fuel water separator	TG
08/08/2023	6254	Wash down and inspect cylinder oil leaks, remove LH steering cylinder, strip down and re-seal, and re-fit	Workshop
08/09/2023	6254	Hosepower re-seal FLH cylinder	Hosepower
08/09/2023	6254	250 hr service complete, change oil, filters	Workshop
08/10/2023	6254	Re-fit LH lift cylinder, wash down	Workshop
09/11/2023		Touch up paint	Serg
09/12/2023		Ongoing touch up repairs to loader. Touch up paint and remove, replace reflective tape	Workshop
09/15/2023		Refit guards	Workshop
09/27/2023		Charged batteries	
10/16/2023	6284	Fitted new batteries from Hastings refer Att Hastings Inv 2016120334	Workshop
11/14/2023	6322	Removed seat, replaced hose from air switch to airbag	Workshop
01/25/2024	6370	Remove and clean rubber moulding off joy stick	Workshop
02/29/2024	6382	Pick up new battery isolator, travel to site, remove & replace isolator, tested ok, Job number OBS-416 complete.	Workshop
05/07/2024		Replaced E Stop	Workshop
06/21/2024	6470	OBS-1474 Replaced Radio Bracket.	Workshop
07/04/2024	6496	Top up diff oil. Inspect leak at rear diff. Seems to be leaking from pinion seal.	Workshop
09/06/2024	6508	Replaced horn button,	Workshop
		Bad oil leak from centre of machine. Found to be hose from under cab to front valve body. Removed hose and took into Hosepower, had new hose made up. Refitted on site. Lost 30L Hydraulic oil, topped oil back up. Job complete at 6536 hrs.	Serg
07/18/2024	6536	Refer att Hosepower Inv 90389	
07/18/2024	6536	UHF radio bracket replaced by Serg.	Serg
09/12/2024	6580	500 hr service complete, change oil, filters	Workshop

Plant & Vehicle Maintenance & Repairs

Asset Number: CO213		Registration Number: SV3954	Serial Number: CAT0930KHRHN02880
Make: Caterpillar		Model: 930K Loader	Date of Manufacture 2015
09/13/2024	6580	Leak at rear brake hose, ordered hose. Wash down & bring into workshop, removed belly plate & found oil leaking from rear brake hose, replaced hose & tested ok. Job complete, 13/9/24 @ 6580hrs.	Workshop
09/19/2024	6580	Remove and re-seal steering cylinders with Halite seals from Hosepower, re-assemble and test. OK	Workshop
09/27/2024	6585	Removed crowd cylinder & drop off to hosepower for cylinder leakage test, reported cylinder bypassing internally, pick up cylinder & seal kit from Hastings Deering, disassemble cylinder & replaced seals, re-assemble, install & tested ok, wash down loader.	Workshop
09/23/2024		Active Fault # 492-5 3rd function rearward solenoid, broken wire in front frame harness refer att TPS Inv 1973	TPS
10/10/2024	6599	Inspect park brake, need to drop belly plates to adjust	Workshop
10/21/2024	6613	Prep for wiring harness removal	
10/22/2024		Remove wiring harness	Workshop
10/24/2024	6613	Hastings inspect brackets and location of install	Workshop
10/28/2024	6613	Mount brackets, install harness	Workshop
10/29/2024	6613	Install wiring harness and fasten in place, tested. OK.	Workshop
10/30/2024	6613	Completed wiring harness job	Workshop
10/31/2024	6613	Mobilise back to DVO	Workshop
03/04/2025	6685	Straighten out right side step and repair broken mudguard	Workshop
03/28/2025		Repair LH side steps, straighten in press	Workshop
04/07/2025	6685	Fit RH auxilliary hose, remove blown.	Workshop