

Plant & Vehicle Maintenance & Repairs

Asset Number: CO072		Serial Number: WKX00501		«
Make: Caterpillar		Model: 315 Excavator		Year of Manufacture: 2020
Date	Hr/Kms	Work Conducted	Responsible Person	
03/25/2021	21	Mobilised to C020 Larrakeyah site	TG	
06/08/2021	282	250 hr service, sampled all required fluids, replaced engine oil, filter, blew out all filters, greased.	SS	
06/10/2021	280	Fitted new cutting edges, part # 4T-0367, 10X4F-3635 bolts, 10X4K-0367 nuts.	TG	
09/02/2021	505	500 hr service completed. Sampled engine oil, replaced engine oil, 3 x oil filters, replaced fuelfilter, blew out air	SS	
19/10/2021	738	After treatment fault - Hastings to fit new dosing pump & clear codes - Refer Hastings Service Journal attached	TG/Hastings	
10/22/2021		315 Troubleshoot DPF Issues - refer to Att Hastings Invoice 40100386031 for travel only under warranty	Hastings	
11/02/2021	778	In progress - Repair bucket, straighten out roof gutter and remove sunvisor, parts ordered.	TG	
11/08/2021	789	250 hr service done. Changed engine oil and filters, blow out a/c and air filters.	TG	
11/09/2021	789	Repair and replace damaged brackets and catches for sun roof and visor	TG	
01/24/2022	984	1000 hr service Changed engine oil and filters, blow out a/c and air filters, grease. Oil samples	SS	
03/15/2022	n/a	Replaced bucket teeth.	SS	
20/04/2022	1164	Oil leaking from quickhitch - re tensioned hose	SS	
05/17/2022	1255	250hr service carried out. Replaced engine oil/filter blew out air filters & cab filters, greased machine. Oil sampled.	SS	
06/03/2022	1303	Replaced flashing beacon	SS	
08/30/2022		JN#3153 - Supply & instal starting system as per attached Hastings Inv 40100446190	Hastings	
08/30/2022	1497	JN#3152 - Dropped to Hastings for warranty on slew gear box - Refer attached Warranty Job Card 43100655468.	Hastings	
09/05/2022	1521	JN#3154 - Fault, Cutting edge worn. Rotate cutting edge.	SS	
20/08/2022	1588	JN#3127 - Re tension hoses, counterweight scratches	SS TG	
09/09/2022	1588	JN#3141 - Completed 500hr service. Changed eng oil & filters. Air filter & fuel filters.	SS TG	
07/10/2022	1588	JN#2974 - Re-Fit guard over quicklift locking pin & re weld	TG	
03/10/2022	1588	JN#3185 - Fitted new grease line	SS TG	
02/02/2023		System communication fault between engine ecm & adblue quality sensor - Ref Hastings Inv 40100477500	Hastings	
03/09/2023	1668	Changed bucket teeth	TG, SS	
03/09/2023	1668	Fitted new adblue sender manifold unit	Dylan, TPS	
9/03/2023	1666	JN#3337 - Faulty DEF sensor -Dylan from TPS plug in ET, diagnose faulty auxillary line, relit soleroid, ordered parts and replaced soleroid Refer Inv 0839	Dylan, TPS	
9/03/2023	1666	Failed coil on variable relief refer to TPS Inv 0829	TPS	
6/04/2023	1779	JN#3356 - 250 hr service, changed engine oil and filter, blew out all air filters and grease	SS, TG	
30/05/2023	1839	Removed side panels and drop off to Beta Pave to be painted by Andrew	SS, TG	
31/10/2023	1983	Refilled Adblue	SS	
22/11/2023	1997	2000 hr service, changed final drive oils, A/C cab filters, engine oil and filters, air filter, fuel filter	Workshop	

[illegible]

