

Plant & Vehicle Maintenance & Repairs

et Number: CO281		Registration Number: CC10AQ		Serial Number: JAANLS85HB7100019	
Make: Isuzu		Model: NPR622 Tray Truck		Year of Manufacture: 2011	
Date	Kms	Work Conducted		Responsible Person	
01/14/2016		Refer to Airpower Invoice DUCS53057		Airpower	
02/16/2016		Refer to Airpower Invoice 162552		Airpower	
02/19/2016		Refer to Airpower Invoice DUCS53506		Airpower	
02/26/2016	36086	Change LH steer tyre.		TG/GC	
07/01/2016		Identify IVMS tracker IMEI # 358683060268997		TG/GC	
07/15/2016	39105	Top up engine oil, run engine, check for abnormal noise, test drive, all ok.		TG/GC	
07/19/2016	39217	Fit spare wheel to inside rear.		GC	
10/13/2016	40523	45,000 km service. Airpower			
10/14/2016		Refer to Airpower Invoice DUCS55232			
10/25/2016	40645	Replace rear shockers. Restock all spill kits at car park.		TG/GC	
07/26/2017	43692	Remove tyres, arnos tyres replace 4 x drive tyres. Arnos tyres replace tyre		TG	
		1 x 265x65x17 Dunlop 8020			
07/27/2017	43691	Replace tyres, refit		TG SS	
10/11/2017		Done - beacon not working		MM	
10/18/2017		Remove steer tyres, fit new tyres		SS	
12/20/2017		Dropped vehicle at Airpower for repairs		BO TG	
01/09/2018		Airpower invoice DUCS58287 for A/C repair.		MM	
02/16/2018	48295	Fix engine light		Ellis	
02/19/2018	48310	Diagnosing fault with a/c		SS	
02/21/2018		Ellis invoice 1420 - fix fault with DPF system		Ellis	
02/26/2018	48509	A/C evaporator has hole in it. Ellis invoice 1436 to fit new.		Ellis	
04/21/2018	49962	Travel to EAC yard, sort out spare tyre, remove 2 x front tyre, replace 1 head light globe		BO	
04/23/2018		Arnos invoice 168208 - 2 new 205/85R16 tyres			
06/19/2018	51555	50000km service, replace coolant, repair a/c hose and regas		SS GC	
07/10/2018		Fit, balance new 205/85R16 tyre. Arno's invoice 170065			
07/19/2018	52188	Replaced headlight, spare tyre fitted		SS	
08/27/2018	53585	Replace faulty isolator switch		GC	
08/17/2018		Repairs to IVMS and beacon		SS	
09/24/2018	54100	Repair brake lights		SS	
06/26/2019	58363	60,000km service carried out, changed oil and oil filter,primary and secondary fuel filter. Repaired leaking induction hose to throttle body. Replaced window regulator in passenger front door. Air con system cleaned, evaporator and fan cleaned.		SS	
10/23/2019	59917	Replace 4 rear drive tyres dunlop SPLT50s, check window washers fault, found disconnected wiring.		TG	
03/26/2020		Replace batteries, clean out battery box and paint with corrosion protector		TG	
11/18/2020	15182	Premobilisation inspection completed for C020.		TG	

Plant & Vehicle Maintenance & Repairs

et Number: CO281	Registration Number: CC10AQ	Serial Number: JAANLS85HB7100019
Make: Isuzu	Model: NPR622 Tray Truck	Year of Manufacture: 2011
12/06/2021	62782 Replaced batteries refer attached Inv	TG
01/18/2022	62945 Service & front end repairs, changed engine oil, change fuel & air filters, replaced upper & lower control arm bushes & front CV shafts.	TG/SS/GC
05/13/2022	64093km Removed DPF, washed out, reassemble, CJD reset computer, test systems. OK	TG, CJD
05/23/2022	Radio wasn't working. Fitted new radio	SS
06/28/2022	64407 JN#2844 - Spare key cut & programmed at Toplock	SS
11/04/2022	65752 JN#3254 - replaced 2 Way radios	GA
11/21/2022	66 Replace front brake pads, replaced 2 way radio	SS
01/12/2023	3294 Supply & fit Front windscreen & front mould to suit - refer att WT Inv 1133	WT
03/29/2023	66279km Remove rocker cover, replace camshaft, injector and rocker cover seals.	SS
08/04/2023	Service air compressor	Workshop
12/08/2023	New drop sides and paint. (Dropsides from Falcon Engineering).	Workshop
12/11/2023	68222 Remove driver side front tyre and replace with new spare	
12/18/2023	68222 Drop to NT Tyre, fit new tyre Toyo 205/85R16 - refer att Inv 88454	NT Tyres
12/20/2023	68324 Collect tyre from NT Tyres, fit onto LH front. Now has 2 new steer tyres. Put old tyre under back in spare carrier	NT Tyres
01/22/2024	Pressure wash and prep for paint at Betapave yard	Serg
01/29/2024	Ordered EAC and plant number stickers from Ben Designs	Workshop
02/08/2024	68401 Travelled to BetaPave & refit tray back onto truck, drove back to Nebo Rd, removed rear wheels & painted. dropped off 1 x rear tyre to NT Tyre for puncture repair	TG/SS
02/09/2024	68401 Fit new bolts to tray & bolt tray back to chassis, solder rear taillight wiring back together & shrink wrap. Start on overhead lighters re wiring. Pick up puncture & refit	Workshop
02/12/2024	68401 Finished off re-connect wiring, weld tray to body mount	SS
02/20/2024	68401 Remove park lights from bullbar, strip old light assy & re-use lense as the clear lenses are now obsolete, bolt in new lights & connect wiring, working well	Workshop
02/29/2024	68401 OBS-372 - Found not charging, replaced alternator, tested ok, dash lights not on now.	Workshop
02/29/2024	68401 Replaced Beacon	Workshop
02/29/2024	68401 Removed & replace AM-FM Radio	Workshop
06/18/2024	69430km OBS-1469 Inspected & found A/C belt needs adjusting, adjusted belt & tested ok	
08/16/2024	69670 70000km service done. Changed engine oil and filter, fuel filters, blow out air filters	Workshop
09/25/2024	70343 Replaced u/s batteries 2 x Century NS70L MF refer att NTT Inv 92016	Workshop
09/25/2024	70343 Change power supply from radios to accessories circuit so not constantly on.	Workshop
01/24/2025	Truck overheated on way to Inpex. Investigating	Workshop
02/01/2025	Charged batteries, run up and check temperature found not circulating.	Workshop
02/13/2025	Repair & Paint cab white, tray & chssis black out - refer to Att Inv 2317 AB	AB
02/04/2025	70820 Replaced thermostat, found radiator not circulating. Investigate	Workshop

Plant & Vehicle Maintenance & Repairs

et Number: CO281	Registration Number: CC10AQ	Serial Number: JAANLS85HB7100019
Make: Isuzu	Model: NPR622 Tray Truck	Year of Manufacture: 2011
02/12/2025	70820	Put scan tool on to measure injector parameters, 0.5 and 0.2 milliamps comp need to get specs to compare Workshop
02/14/2025	70820	Pur G scan on truck and tested parameters, -2.3 to 0, need to do injector cutout when cold. Workshop
02/20/2025	70820	Remove glow plugs for compression test. Workshop
02/21/2025	70820	Compression test, need Schroeder valve extension, reading around 280PSI on all. Workshop
02/24/2025	70820	Make up compression test fittings Workshop
02/27/2025	70820	Compression test - #1-320 PSI, #2-400 PSI, #3-360 PSI, #4-360 PSI. Remove injectors, send to MTQ engine services for injector test Workshop
03/13/2025	70820	Re-install injectors, change injector trim file numbers in computer to new injector numbers, bleed system and test run. Of Workshop
03/17/2025	70820	Test drive, temp guage reading low. After shutdown, ignition on and temp guage normal reading, test run again, stayed same. Need to monitor Workshop
03/18/2025	70820	Test drive, temp guage at half, then went to red, stopped and idle down, shut down, restarted and put heater on, no change, shut down again, temp guage stayed on. Isolated truck, guage still stuck on at half, restarted, stayed on half. Suspect temp guage. Workshop
03/19/2025	70820	Swap out instrument cluster from CO260 to CO281, test drive and monitor temp readings, all OK, will continue monitoring Workshop
04/03/2025	70820	Fit new speedo cluster, old speedo reading 70820km Workshop
05/28/2025	70,891	Top up AC, may have possibly leaked in evaporator losing gas SS