



## Plant & Vehicle Maintenance & Repairs

<b>Asset Number:</b> CO277		<b>Registration Number:</b> CC01GF	<b>Serial Number:</b> JAANPR75LF7100358
<b>Make:</b> Isuzu		<b>Model:</b> NRP 65-190 Tray Truck	<b>Year of Manufacture:</b> 2015
Date	Hr / Kms	Work Conducted	Responsible Person
03/15/2016		Replace RH headlight globe.	TG/GC
05/25/2016		5000 kms service. Airpower.	
10/20/2016		Drop off to Air Power 15,000 km service. Headlight wiring repairs.	TG
01/17/2018		UHF fixed	TG
01/20/2018		Fit new light globe to LH head light	
02/27/2018	21928	Repaired reverse beeper, flashing light	BO MM
03/16/2018	22398	10,000 km service completed, washed out radiator, after cooler and condensor, cleaned out cabin a/c and blocked off outside	BO GC
03/29/2018	116704	Replace fire extinguisher,	BO
07/11/2018	27351	Replaced RH Headlight globe and clean a/c filters	GC SS
11/01/2018	30816	30000km service, replace LH rear tail light blinker and reverse light lenses. Clean out a/c evaporator, clean cab and wash down	TG SS
08/06/2019	35597	Change engine oil fuel and air filters, CJD - warning light fault, remove and replace LHF electronic stability sensor, remove and replace ABS sensor harness. Replaced stop light switch, replaced batteries.	CJD / TG
08/17/2020	39719	Remove drive motor and replace bearing. Re-assemble	SS
08/17/2020	39719	Replaced windscreen	Territory Windscreens
08/25/2020	40193	Incorrect radio setting	TG
09/01/2020	40193	40,000km service	SS
11/24/2020		Removed and blew out A/C filters	SS
06/11/2021		Cleaned up and got working after possum stuck in fan belts.	TG
01/06/2022		<a href="#">Strip &amp; Tint 2 x Doors ref Inv 22915</a>	WT
01/28/2022	47052	Engine light is on. Checked engine light with Serg, Scan tool.	
05/06/2022	48159km	Isolate, delete engine light, has not come back on	SS
10/11/2022		JN#3121 - Cleared fault lights, did not re-occur.	SS
10/31/2022	50000km	50,000km service, change oil filters	SS
10/31/2022		<a href="#">Strip &amp; tint Windscreen - refer att WT Inv 792</a>	WT
11/22/2022		<a href="#">Replaced Battery Isuzu NS70L refer att CJD Inv 002530514</a>	CJD / TG
11/28/2022		<a href="#">Replace 1 x Mich 205/75R17.5 Tyre refer att NTT inv 83919</a>	NTT
12/31/2022		Repair wiring for beacon. Window tint replaced.	TG
02/28/2023	52,603	Fit 2 new steer tyres, repair RH rear brake & tail light, Fit 1 x tyre from steers onto spares rack	TG/SS
03/01/2023	52,622	Fit 2 new mine spec heights above cab	TG/SS
07/17/2023	57744km	Refer att CJD Inv 6474871 - JN# - 3416 - collect from CJD again, test drive to Toyota in city, engine light came back on, delJS	
10/10/2023		<a href="#">Fit 1 x Max 205 Tyre refer att NTT Inv 87473</a>	NTT

10/25/2023	59260km	Replace aircon and fan belts	Workshop
10/25/2023	59,297	<a href="#">Supply &amp; fit rear window refer - Windscreen T inv 2821</a>	WT
10/30/2023		<a href="#">Supply &amp; fit front windscreen refer - Windscreen T Inv 2860</a>	WT
12/06/2023		<a href="#">New drop sides &amp; paint ref att Inv 11597 Falcon Engineering</a>	Workshop
12/19/2023	59,550	Serg and Andrew (Betapave) Completed painting	Betapave
02/06/2024	60,385	60,000km Service changed engine oil, fuel filters, adjusted AC belts, grease, check lights & wash down	Workshop
08/13/2024	62532	Remove two way radio, fit 24-12V transformer and new radio	Workshop
08/13/2024	62532	Remove AC blower fan and clean	Workshop
11/11/2024		<a href="#">Fit new rear right passenger window. Windscreen Territory fit new tint ref Att Inv 5037</a>	Windscreen Terr
03/31/2025		Replace LH headlight globe	Workshop
06/02/2025	3549	DS Window has faulty regulator assy have order new one from CJD	SS
06/13/2025	68077	Refit new power window mechanism to drivers door and test.	SS