

## Plant & Vehicle Maintenance & Repairs

<b>Asset Number:</b> CO227		<b>Registration Number:</b> CD28ZZ	Serial Number: JALFVZ34PG7000832
<b>Make:</b> Isuzu		<b>Model:</b> FVZ 260-300	<b>Year of Manufacture</b> 2018
Date	Hr/Kms	Work Conducted	Responsible PersonColum
08/10/2018		MVR Rego, compliance check for 2 new tippers	TG SS
09/04/2018	16	Fit cab air line and blower	TG
12/06/2018	117	100hr service, fix pin on tail gate, repair oil leak at diverter valve	TG SS
09/18/2019	248	250 hr service, replace rear mud flap, wash and clean	TG
01/08/2020	261	Check engine warning light on, DPF system fault, do manual DPF burnoff, shut down, isolate, restart fault still present. take to CJD to remove fault code. CJD removed 1 x code for ECU inactive too long. Test. OK.	TG
04/16/2020		New hinges placed on rear mudguard	TH
04/30/2020	407	Inspect damage to hydraulic tank, tank has dent but safe to operate	TG
09/04/2020	6751	Lubricated rod & pin on booster	SS
09/12/2020		Reconnect cut wiring on IVMS and disconnect fuse ready for switching	SS
09/29/2020	505 hrs	Completed 500 hr service. All filters replaced. Found back brakes to be noisy left hand side rim. Drum full of	SS
11/12/2020		Replaced faulty air brake valve at rear of chassis that are common failure	TG
12/01/2020		Changed out flat drive tyre, fit spare, drop to NT tyres for repair.	TG
03/05/2021	750 hrs	250 hr service Engine oil change, grease, blow out filters etc	SS
04/09/2021	9064km	Fit new 2 way UHF radio to truck in-dash style	SS
05/27/2021		Replaced tipper valve on body truck 227	SS
06/02/2021	9420km	tightened hydraulic fitting on PTO pressure line (PTO pressure line leaking)	SS
08/25/2021	1063	1000 hr service -changed eng and diff oils, trans oil and filters	TG
10/04/2021	1160	Adjust tipper relief valve pressure	TG
11/05/2021	1261	250 hr service done. Changed engine oil and filter, adjust a/c belt.	TG
02/10/2022	1428	Replaced both headlight globes	TG
04/12/2022	1573	250hr servicing carried out. Engine oil & filler, air filters. Grease truck cleaned out A/C evaporator and blower	SS
05/19/2022	1703	Replaced 2 off headlight bulbs	SS
09/06/2022	2004	JN#3126 - Completed 2000hr service, replaced eng oil & filters, fuel filters, air filt	SS
09/08/2022		<a href="#">Replace 1 x DC 11R22.5 Drive Tyre &amp; 1 x MIC 295/80R22.5 XMZ2 refer attached NT Tyre Inv 82866</a>	NTT
10/03/2022	2082	JN#3190 - Replaced FLH mud flap.	SS
10/06/2022	2115	JN#3202 - Fault, Damaged tarp cover. Removed tarp bows, straightened, re-fit & replaced rail slides, adjsuted, tested ok.	TG SS
10/11/2022		JN#3074 - Replaced spare tyre	SS
10/14/2022	2102	JN#3180 - Replaced wiper blades.	SS
10/14/2022	2102	JN#3156 - Retensioned bolts.	SS
10/14/2022	2102	JN#3120 - Replaced FRH hub seal.	SS
10/24/2022	2121	JN#3229 - Replaced 3 x tarp sliders,Weld up rope rails & cracks in bins, replace drive tyre	WG
07/11/2022	2250	JN#3247 - Remove retractable tarp cover for Leachate Shoal Bay	SS/WG

## Plant & Vehicle Maintenance & Repairs

<b>Asset Number:</b> CO227		<b>Registration Number:</b> CD28ZZ	Serial Number: JALFVZ34PG7000832
<b>Make:</b> Isuzu		<b>Model:</b> FVZ 260-300	<b>Year of Manufacture</b> 2018
11/04/2022		Re-seal leaking hub. Wash down dust and asphalt stains	SS
11/18/2022	2255	Changed tyre and tighten fitting at diverter valve	SS
12/12/2022		Flat tyre. Tyre changed by Brooke and others	Brooke
01/10/2023		Inspected chunk in tyre. Still serviceable.	TG
01/24/2023	2313	Replaced split air hose from air tank to regulator	SS
02/21/2023	2404	Completed 500hr service, replaced eng oil & filters, changed drive tyre and replaced onto spare rack	TG, SS
02/27/2023	2404	Fixed auto headlights not coming on	SS
02/27/2023	2426	<a href="#">Replaced 2 x Drive tyres - refer NTT Inv 84742</a>	NTT
03/08/2023	2448	Fixed drivers side headlight	SS
04/20/2023		<a href="#">Replace 8 x drive tyres - Refer att NT Tyre Inv 85264</a>	NTT
05/03/2023	2628	CJD plugged in computer, found no active faults and light gone out (engine light fault)	CJD
05/18/2023	28458km	Refit retractable tarp	TG, SS
07/17/2023	2771	Complete 250 hr service, change oil, filter	TG, SS
07/18/2023	2771	JN# - 3420 - Heat, straighten out hinge, weld up top pivot mounting to raise tailgate to correct level, straighten and weld up tailgate rope rails	TG, SS, JS
09/18/2023	2845	Leak between spacer plate on air actuator side of valve causing air to leak at tipper valve inside cabin. Rebuilt	Workshop
10/17/2023	2857	Full grease over	Workshop
12/18/2023	2906	Drop to NT Tyre service	NT Tyres
02/20/2024	2942	Tarp motor seized, Parts ordered- disassemble tarp retractor, remove & replace gearbox, remove drive motor from	Workshop
02/29/2024	2952	Found air leak above transmission, air line has split due to heat from engine, cut out damaged section and fit	Workshop
03/21/2024	3023	3000 hr service complete.	Workshop
03/22/2024		<a href="#">1 x YOK 295/80R22.5 Refer Inv 89515 att</a>	NTT
03/20/2024		<a href="#">Repairs to Drivers Seat - Valve quick release &amp; height adj, refer att ISRI Unv 10139</a>	ISRI
03/26/2024		Spare tyre has been fitted to spare rack, Job complete, 26/3/24.	Workshop
04/11/2024		Completed by NT testing, 11/4/24, job complete.	NT Testing
07/23/2024		Jump start	Serg
07/24/2024		Took battery out but truck starting ok, so put batteries in container.	Serg
08/07/2024	3214	250 hr service complete. Change oil, filters, blow out air cleaners, grease, wash down, hose radiators and AC condenser, replaced batteries.	Workshop
09/13/2024	3244	Repair air leak, replaced section of hose from cab down RH side of chassis rail, heat damaged from exhaust	Workshop
09/17/2024	3244	Move air line harness from RH side to LH chassis rail to get away from heat.	Workshop
01/10/2025	3290	Tipper valve airline split, replace hose section with 2 x joiners	Workshop
01/13/2025	3295	Inspect tailgate lock not engaging properly, removed booster and inspected, all OK, adjusted yolk out further to assist locking, re-installed and test OK	Workshop

