

Plant & Vehicle Maintenance & Repairs

Asset Number: CO077 Registration Number: CD57HH Serial Number: MROKA3CD101222967

1ake: Toyota	Hr. I Wass	Model: Hilux Year of Manufacture:	2019 Responsil
Date	Hr / Kms	Work Conducted	Person
14/05/2019	10.000	Health check / 1,000km comp service at Toyota	75.1
07/16/2019	10,000	6Mth/10,000 km service by Bridge Toyota	JN
10/02/2019	20033	20,000 km service Bridge Toyota refer attached Inv JC2462000	Bridge
4/02/2020	30325	18Mth/30,000 km service, as per proforma inv JC14124616	Bridge
22/04/2020	39054	Test battery, found fault, replaced battery- refer to attached Inv PI23050956	TG
22/04/2020	39054	Rotated tyres	TG
11/05/2020	40721	24Mth/40,000 km Service Bridge Toyota - Refer attached Inv JC14129120	Bridge
12/08/2020	50368	30Mth/50,000 km Service Bridge Toyota - Refer attached Inv JC14133974	Bridge
11/11/2020	61,283	36Mth/60,000 km Service Bridge Toyota - Refer attached Inv JC14138551	Bridge
15/01/2021		4 x YOK 265/65R17 Tyres, fitted & disposed - Refer NT Tyre Inv 73520 attached	NTT
15/01/2021		Wheel Allignment - refer attached diagram from NT Tyres	NTT
26/02/2021	72,184	70,000 km Service Bridge Toyota - Refer attached Inv JC14144154	Bridge
		Repaired fault on UHF radio by re-wiring (wasn't working)	
11/03/2021	73,597	Safety recall ref # 20SMD-105 - Replace IMV Brake Booster Assy - refer attached Inv JC14144915	Bridge
8/06/2021	82,687	80,000km service- refer attached JC14149311	Bridge
9/09/2021	90,591	Complete 90,000km Service, changed engine oil & filters, fuel filter, air filter & AC filter	TG/GC
5/01/2022	100,837	Completed 100,000km Service	TG
13/06/2022	109646km	Dead battery. Replaced battery.	ВО
1/03/2022		Repaired fault on UHF radio by re-wiring (wasn't working)	GC
30/03/2022		Replaced brake pedal cover.	SS
6/07/2022	110,327	JN#3005 - Dropped to Bridge toyota, could not fault	SS
28/07/2022	110,889	JN#3125 - Completed 110,000km Sve, changed engine oil, oil filter with genuine parts, changed fuel filter,	GC
21/11/2022	114628	Remove front right tyre, NT tyres puncture repairs and refit.	NT tyres,
30/11/2022	115,300	Replaced RH indicator and brake lights on light bar.	SS
29/05/2023		Timing chain inspection with Bridge Toyota refer Inv JC14187530	Bridge
31/05/2023		Timing Chain rattle repairs to be done 3rd - 7th July under warranty see below	Bridge
5/06/2023	120500	120000 service- changed engine oil and filter, rotate tyres	SS, TO
10/07/2023	121,669	Timing chain & associated parts under warranty refer to att Inv JC14187530/JC14185320 Toyota	Bridge
12/07/2023	121,810km	Remove and replace alternator (noisy), replaced with CO078 alternator, noise not present after changeover	Worksho
23/10/2023	125,221	Repair puncture front L/H tyre	Worksho
23/02/2024		1 x Non stock SH Tyre, rotate 4 x 4 tyres & disposal refer att Inv 89154	NTT
11/03/2024	130976	Removed handpeice & fitted new communications cable. tested radio operation ok. Job completed,	
14/03/2024	130467	Completed 130,000km service, changed engine oil & fuel filters grease, inspected lights & tire pressures.	Worksho
		OBS-498 Inspect brake pedal pulsation, removed wheels & brake calipers & measured DTV with dial gauge &	
14/03/2024	130467	found to be out of spec, replaced brake rotors & brake pads & re-assembled & tested ok, Job completed 13/3/24	
		@ 131034 km`s	Worksho
15/07/2024		Install Century DIN65LH MF AGM Battery - Refer Att Inv NTT Inv 91023	NT Tyre
16/07/2024	143262	Replace start battery as had complaints re having to jump start.	Serg
31/07/2024		140000km service complete. Changed engin oil and filter, replaced cab a/c filter, topped up fluids, greased	
, ,	144878	tailshafts, test drive. OK	Serg
29/08/2024	147980	Lubricate switch controller and vent selector disk cam and re-assemble	Worksh
14/10/2024		150k service - Changed engine oil , filter, fuel filter, greased, top up coolant, washer bottle, blow out air filter,	
<u> </u>	151492	check tyres	Worksh
7/11/2024	152275	NT tyres fit 4 x 265165R17 112H GO15 ref att NT tyre Inv 92647	NT Tyre
04/16/2025	157521	Replaced front windscreen on insurance	Windscree
05/19/2025	148,000	Noise coming from under bonnet, replaced alternator & fitted new engine belt	Serg

Click For Equipment List

Click For Maintenance Open Jobs

Click For Machine Hours

Click For Last Service Interval

EASTARM CIVII	Plant & Vehicle Maintenance & Repairs					
Asset Number: CO077	Registration Number: CD57HH	Serial Number: MROKA3CD101222967	<u>«</u>			
Make: Toyota	Model: Hilux	Year of Manufacture:	2019			

Click For Equipment List

Click For Maintenance Open Jobs

Click For Machine Hours

EASTARM civil	Plant & Vehicle Maintenance & Repairs				
Asset Number: CO077	Registration Number: CD57HH	Serial Number: MROKA3CD101222967		<u>«</u>	
Make: Toyota	Model: Hilux	Year of Manufacture:	2019		

Click For Equipment List

Click For Maintenance Open Jobs

Click For Machine Hours