



Plant & Vehicle Maintenance & Repairs

Asset Number: CO075		Registration Number: CD57HB	Serial Number: MROKA3CDX01225026	«
Make: Toyota		Model: Hilux	Year of Manufacture:	2019
Date	Hr / Kms	Work Conducted		Responsible Person
13/05/2019	1000	Health check / 1,000km comp service Bridge Toyota refer attached Inv JC14110059		Toyota
09/25/2019	11974	6Mth/10,000 km service at Bridge Toyota refer attached Inv JC14117755		Toyota
25/09/2019	11974	Windscreens Territory remove and replace windscreen Refer attached Inv 18199		Windscreen T
22/05/2020	18575	Remove rear left tyre, puncture repair and re-fit		TG
19/06/2020	20200	12Mth/20,000km Service refer to Bridge Inv JC14131109		BT
22/01/2021	30,771	18Mth/30,000 km Sve refer to Bridge Inv JC14142182		Bridge
9/02/2021	30,771	Recalled - IMV Brake Booster refer TUFAN-0018-2020 Replaced brake booster assy		Bridge
15/05/2021	37,360	Checked tyre wear; decision to have tyres changed before next wet.		SS
26/06/2021		Replace Battery - Refer Att Inv 4150590857		Repco/SS
8/05/2021	41,147	24Mth/40,000km Refer attached Bridge Inv		Bridge
30/09/2021	44,873	Fit 4 x Yokohama 265/65R17 Tyres, wheel balance & alignment refer attached NT Tyre Inv 78032		TG/NTT
17/02/2022	51761	50,000km service completed by Bridge Toyota Inv JC14162563 and License plate recall inspected & replaced		Bridge
21/07/2022	61689	60,000km service completed by Bridge Toyota, recommended to have pollen filter replaced		Bridge
10/02/2023	71275	70,000km service completed. Changed engine oil and filter, fuel filter and A/C filter		TG
31/07/2023	79768	80,000km service. Changed engine oil and filters, rear diff, transfer and gearbox oils, replaced engine oil filter,		Workshop
20/02/2024	88288	Replaced rear left taillight globe & front right headlight globe		Workshop
13/03/2024	89610	Fit new wiper blades		
15/03/2024	90000	Complete 90,000km service, changed engine oil & filter, fuel filter, air filter, grease, check & top up all fluids,		
24/06/2024		Replaced battery Century DIN65 KHX MF UHP see att NTT Inv 90748		Workshop
19/07/2024	94000	2 way radio handpiece replaced. Transmitting button was not working.		Serg
23/07/2024	94626	Replaced both headlight bulbs		Serg
13/08/2024	95570	FR inner guard rubbing on tyre, refit with body panel clips		Workshop
9/12/2024	101,300	Changed engine, fuel, air filters, grease etc.		Workshop
12/02/2025	103,122	Rotate tyres		Workshop

- Click For [Equipment List](#)
- Click For [Maintenance Open Jobs](#)
- Click For [Machine Hours](#)
- Click For [Last Service Interval](#)