

Plant & Vehicle Maintenance & Repairs

Asset Number: C0257		Serial Number: CAT0CS76ACYX00965	
Make: Caterpillar		Model: CS76XT	Year of Manufacture: 2012
Date	Hr / Kms	Work Conducted	Responsible Person
10/05/2015		Remove padfoot shells and set up for flat drum	TG/GC
04/20/2016		Refer to Hastings Deering Invoice AP300038194	Hastings
08/12/2016		Hastings. Fit new vibration on/off switch. (Yard).	TG
09/02/2016	2513	Check A/C fault.	TG
09/20/2016	2529	Remove seat assembly	GC
09/21/2016	2529	Fit adjuster kit to seat base. Assemble and fit to roller.	GC
01/23/2017		Refer to Hastings Deering Invoice 5000505611 & 5000506101	Hastings
01/24/2017	2532	Check park brake fault. Check engine wont start fault.	TG/GC
01/25/2017		Replace park brake switch assembly. Fault find electrical fault at fuel prime pump.	
01/25/2017		Prime system and start engine. Fault with cracked fuel sedimentor bowl.	
01/25/2017		Ordered. Test. All ok.	TG/GC
02/10/2017		Service. Oil change. Remove interior mats, etc. Repair steering console mounts. Pressure cleaner. Repair	
02/10/2017			TG/GC
02/08/2017		1 x Fuel sedimenter bowl refer invoice # 2010329227 Hastings	Hastings
02/14/2017		2 x Blades A refer Hastings invoice # 2010340155	TG
02/16/2017		Purchase 1 x Stop Tail Indicator Lens - refer Ashdown Inv 7180027732	TG
01/16/2018	2572	Replace 2 x batteries	GC
03/07/2018	2591	Complete 500hr service	
03/08/2018		Replaced fire extinguishers	BO
04/12/2018	2614	Replaced LHR tail ight globe, cleaned contacts, removed blown hose and replaced	BO SS TG
02/07/2020	2630	Removed pad foot shells	TG
04/28/2020	2639	Inspect coolant leak, found leaking housing on back of water pump, replaced O rings. Tested OK, top up coolant 6L	TG SS
06/19/2020	2642	Remove steering line and perform cylinder bypass test, found RH cylinder to be bypassing oil, remove cylinder, fit seal kit, reassemble and test. OK	TG SS
09/17/2020		Fit padfoot shells and scrapers. Remove old number plates and brackets.	
09/30/2020	2656	Repaired drivers seat - fit new springs, adjusted lever	SS
09/26/2020		Replaced steering tilt strutt	TG
09/30/2020	2656	Checked and aircon working fine	SS
12/06/2021	2659	Remove pad foot shells & set up with smooth drum scrapers	TG
02/15/2022	2680	Oil leak - Replaced case drain hose vib motor	TG/GC

Plant & Vehicle Maintenance & Repairs

Asset Number: C0257		Serial Number: CAT0CS76ACYX00965	
Make: Caterpillar		Model: CS76XT	Year of Manufacture: 2012
03/23/2022	2710	Fault, blown steering cylinder seats, remove & re seal left side steering cylinder, re-install & test ok, top up oil 40ltrs	TG
03/09/2022	2701	Fault, blown steering cylinder seals, remedy, removal cylinder, re-sealed at re-assembled. Right side cylinder	TG
05/10/2022	2729	Replaced 4 x gas struts on engine/bonnet cover.	SS/TG
05/10/2022	2729	Radio bracket has been fixed	TG/GC
10/28/2022	2809	Replaced batteries	TG/NTT
10/31/2022	2809	JN#3248 - Completed 250hr Service	TG
11/10/2022	2809	JN#3249 - Fitted Sheep pad shells	TG
11/10/2022	2809	JN#3250 - Fitted new rims & tyres - refer Bridgestone Mining Inv 90190828	BSM/TG
11/14/2022		Replaced 1kg ABE Extinguisher	Tony Rowland
11/24/2022	2812	Replaced shell bolts as padfoot shells were loose	TG/SS
12/12/2022	2809	Remove cooling pack, replaced fan motor hoses, re-install cooling pack, repair cracks in radiator tank	TG, SS
02/16/2023	2896	Remove cooler pack and replace radiator, removed exhaust and tested for leaks. OK. Adjusted valves and replaced	SS, TG
06/14/2023		Finish off fitting padfoot shells	SS, TG
06/19/2023		Replace bolts in padfoot shells and use conelock nuts, was	
07/04/2023	2926	Tighten shells	SS
09/01/2023	2930	Repair LH rear work light, inspect washer bottle algae, replace wiper blades, remove padfoot shells	Workshop
09/07/2023	2930	Painting complete	Betapave
09/13/2023	2930	Refit hoses at Betapave yard	Betapave
09/14/2023		Take white float to Betapave yard to pick up drum roller with Glen and Jordan, refitted bonnet, organise decals with Ben Design and transport machine back to Nebo	Workshop
09/18/2023	2932	Fit bonnet rubber to base of bonnet	Workshop
09/26/2023	?	Ben Designs fitted new decals	Ben Designs
04/29/2024	2934	Found beacon has water inside, beacon US, replaced beacon & rewired, tested ok	Workshop
11/07/2024	2980	Resealed rear window.	Workshop
01/06/2025		1000 hr service, changed engine oil and filter, fuel filters, hydraulic filters, sampled oils, changed final drive oils. Ryan wanted loader for DVO at Port, so differential and drum oils still to be done.	Workshop
01/06/2025		Edgy delivered to Port	Edgy
03/20/2025		Changed drum support oil and eccentric oil, refill diff TDT050	
03/28/2025	3008	Refit belly plates	Workshop
03/10/2025		Supply & fit RH side window refer att Inv 5685 Windscreens Territory	WT

