

Plant & Vehicle Maintenance & Repairs

| Asset Number: CO211 | | Registration Number: SV3932 | Serial Number: CAT0432FELNR01202 |
|----------------------------|--------|--|---|
| Make: Caterpillar | | Model: 432F Backhoe | Date of Manufacture: 2014 |
| Date | Hr/Kms | Work Conducted | Responsible person |
| 11/10/2015 | | Fit tap to heater circuit. | TG/GC |
| 12/01/2015 | 326 | Replaced drier. Regas and test. (Hastings). | Hastings |
| 04/11/2016 | 500 | 500 hrs service. | TG/GC |
| 08/10/2016 | 627 | Fit new air filters. | TG |
| 01/17/2017 | 687 | Replace quick connect coupling on backhoe and mate on rock breaker. | GC |
| 02/11/2017 | 695 | Remove floor mats and interior. Clean out cab and interior. | TG/GC |
| 09/12/2017 | 714 | JKC inspection, grease and check | TG |
| 02/20/2018 | 824 | 250hr service | BO |
| 02/19/2018 | | Inspect hydraulic oil leak, found hose split | BO |
| 02/20/2018 | 824 | Service 250hr, strip hammer assembly | BO SS |
| 02/21/2018 | 824 | Removed and replaced door stoppers, and hydraulic hose | BO |
| 04/06/2018 | | Fit new retaining pins to bucket teeth | BO |
| 07/19/2018 | 872 | Replaced LH rear tail light globe | GC TH |
| 07/31/2018 | 892 | Repair leaking wiper bottle | SS TG |
| 12/17/2018 | 959 | 1000 hour service | TG |
| 01/21/2019 | 1001 | Check engine valve lock adjustment, replace 1 x grease nipple LH bucket crowd linkage | TG SS |
| 06/09/2020 | 1040 | Rotate cutting edge on batter bucket | TG |
| 07/16/2020 | 1047 | Check operation of boom travel locks, found no problems. | TG |
| 07/17/2020 | 1047 | Re-seal 4 bucket cylinders, replace quick couplers (male and female) on auxillary lines at backhoe stick | TG |
| 12/01/2020 | 1068 | Replaced batteries | TG |
| 25/10/2021 | 1138 | Stabilizer legs missing rubber pads, replaced pads | TG |
| 01/31/2022 | 1175 | Sealed around window glass | TG |
| 03/03/2022 | 1214 | Bucket lift arm on left side leaking bad - Remove cylinder pre-seal, re-fit lift cylinder LHS | TG |
| 04/26/2022 | 1298 | Check gas frp, backhoe on AC found a little low - topped up | SS |
| 05/14/2022 | 1358 | 250hr service replaced engine oil/ filter, blew out air filter, a/c bad filters, greased machine, oil sampled. | SS |
| 05/14/2022 | 1358 | Ordered and replaced broken RH rear tail light. Assembly & tail light guard | SS |
| 06/26/2022 | | Boom cylinder was leaking. Hosepower resealed cylinder, refitted | SS/GC |
| 06/24/2022 | 1447 | JN#3090 - Replaced back window & refitted wiper Assy | SS |
| 08/02/2022 | | JN#3172 - LH lift & crowd cylinders leaking. Removed & re-sealed cylinders, re-installed. | SS TG |
| 10/10/2022 | 1494 | JN#2947 - Removed quick hitch hyd cylinder, disassemble & clean up piston & cylinder, re-assemble, tested | TG |
| 10/11/2022 | 1494 | JN#3211 - Completed 500hr service, replaced engine oil & filters, fuel filter, air filter & cab a/c filters. | TG |
| 10/11/2022 | 1494 | JN#3111 - Replaced receiver drier & a/c discharge hose, re-gas to spec at 2kg. Tested ok. | SS |

Plant & Vehicle Maintenance & Repairs

| | | | | |
|----------------------------|------|--|---|---|
| Asset Number: CO211 | | Registration Number: SV3932 | Serial Number: CAT0432FELNR01202 | « |
| Make: Caterpillar | | Model: 432F Backhoe | Date of Manufacture: 2014 | |
| 11/14/2022 | 1537 | JN#3264 - Braze up broken filter elbow on transmission, replaced & fill with coastroll off road 30 | TG/SS | |
| 11/20/2022 | 1543 | Replaced seat adjuster, air switch, top up trans oil | TG | |
| 03/09/2023 | 1583 | Replace 2 x Tyres refer NTT Inv 84863 attached | NTT | |
| 03/14/2023 | 1583 | Re-seal joints at sides of windscreens of grommets for lights wiring etc (Tez diary) | | |
| 04/18/2023 | 1584 | Re-seal and re-assemble cylinder, refit cylinder and replace associated hydraulic hoses | SS, TG | |
| 04/20/2023 | 1584 | Finish refit cylinder and replace hoses on LHS, start make up spanner for slew cylinders | SS, TG | |
| 04/21/2023 | 1584 | Make up spanner to undo slew cylinder cap nuts | TG | |
| 04/26/2023 | 1584 | Pick up cylinders from Hosepower after reseal, 28/4- refit cylinder rods, bleed and connect to backhoe, tested. | O SS | |
| 04/26/2023 | 1584 | Hosepower 2 x Rod Re Sealed refer att Inv INO62771 | Hosepower | |
| 06/28/2023 | | Touched up paint and repainted bonnet | BetaPave | |
| 11/17/2023 | | Remove hydraulic return hoses inspect and replace with new hoses | workshop | |
| 11/20/2023 | | Finish install return hoses, wash down and test, found leaking high press hose, ordered parts | workshop | |
| 11/22/2023 | 1642 | Check for leaks and wash down replace floor plates and floor mats, replace under dash plastic panels and steering | workshop | |
| 03/28/2024 | 1711 | Windscreens Territory re-tinted right rear window 1711 hrs, Job complete, 28/4/24, refer att WT Inv 3740 | WT | |
| 06/03/2024 | | Reseal 2 x Cylinders - refer Hosepower Inv INO87433 | HP | |
| 07/05/2024 | 1783 | Complete. Sample engine oil, drain, refill engine oil, replaced oil filter, blow out all air filters, engine, A/C etc. Grease machine. | | |
| 08/08/2024 | | Went to Middle Arm Pit to jump start. | workshop | |
| 08/19/2024 | 1793 | Flat batteries, purchase new batteries from Hastings - refer att Inv 2016936565 | workshop | |