

Asset Number: CO212		Registration Number: SV3953		Serial Number: CATCS56BCM4M00204		«
Make: Caterpillar		Model: CS56B Roller		Year of Manufacture:		2015
Date	Hr/Kms	Work Conducted				Responsible person
10/08/2015		Repair reverse lights				GC
04/23/2016	581	500 hrs service				TG
06/15/2016	611	Remove seat. Dismantle. Inspect broken winder ass. Ready to order new parts.				GC
06/16/2016	611	Repair winder height adjuster on seat, assemble seat and fit to machine.				GC
08/12/2016		Hastings. Check vibration frequency settings. Upload software for variable vib frequency.				TG
09/19/2016	685	Remove seat dismantle, fit new adjuster ass				GC
09/20/2016	685	Assemble seat & refit to roller				GC
01/13/2017	718	Replace both inner and outer air filters.				GC
01/17/2017	721	Hastings - inspect engine air fault on screen (faulty air sensor)				GC
01/20/2017	721	Hastings - replaced air vaccum switch (warranty)				GC
02/06/2017		Hastings call out to repair active fault refer invoice # 40100030579				GC
11/02/2017		a/c fault, no power to a/c, clutch needs pressure test and switch replaced				TG
01/17/2018		Ellis Autos replace pressure switch (A/C fault). Invoice 1336				Ellis
05/15/2018		Fit new padfoot shells with new bolts and nuts				TH
05/16/2018		Replace hoses on drum roller. Hoses in drum drive motors. 2 x RH, 2 x LH				SS TH GC
<i>Note machine was replaced around this time, back to first 250 hr service</i>						
06/27/2018	263	Initial 250 hr service, wash down and clean				GC TH
05/23/2019	339	Check charging fault, found no charge, faulty alternato, replaced alternator and test charge, all OK				TG
02/21/2020	448	Replace O ring on pump valve body				TG
05/19/2020	505	500 hr service, change fuel and oil filters and air filters				TG
05/19/2020	505	Final Drive Right oil sample. Result A				HD
09/28/2020	529	Replace rear view mirror				
01/04/2022	713	Fire extinguisher from inside cab missing. Was replaced as per TR email to FB on 22/6/22				SS
06/13/2022	879	250 hr service, changed oil & filter, replaced LH mirror bracket				BO
09/05/2022	944	JN#3157 - Replaced both start batteries. Refer to att NTT Inv 67797				SS/NTT
02/11/2022		JN#3201 - Disassemble & replace speaker, reassemble tested OK				SS
02/01/2023	1105	Replaced broken bonnet strut mounts, drained fuel filter sedimeter bowls				TG, SS
02/01/2023	1107	1000hr service, changed drum support oil, engine oil and filter, fuel filters, diff and final drive oils..				workshop
08/30/2023	1212	Fixed bonnett lock				workshop
09/01/2023	1213	Replaced wiper blades				Jordon
12/21/2023		Washed down by Edgie				Steven Edge

