

## Plant & Vehicle Maintenance & Repairs

**Asset Number:** CO245 **Registration Number:** N/A

**Make:** Fintec

| Date       | Hr / Kms | Work Conducted   | Responsible Person |
|------------|----------|--|--------------------|
| 02/04/2017 | 1907     | Check operation. Run and test. Free up conveyor rollers. Remove old screens.   | TG                 |
| 02/07/2017 | 1907     | Continue screen removal and wash down.   | TG                 |
| 02/07/2017 | 1907     | Order parts for screen plant from Precision Screens - Brisbane.  | TG/GC              |
| 02/08/2017 | 1907     | Clean up screen mounts, grind off ruse and build up, refit screens.  | TG/GC              |
| 02/09/2017 | 1907     | Change engine oil, oil filter, fuel filters and air filters. Replace screen mats.  | TG/GC              |
| 02/14/2017 |          | Purchase 1 x Back up Audio Alarm - Refer Ashdown Inv 7180027515  | TG                 |
| 02/09/2017 |          | 1 x Pkt AAA Energiser Batteries - Refer Dimet Inv SI138083   | TG                 |
| 02/09/2017 |          | Fuel Filter Cartridge,Air Filter Element,Air Filter Safety - refer Hitachi Inv IP600186104   | TG                 |
| 02/09/2017 |          | Adaptors, sockets, grease lines - Refer Hosepower Inv 23887  | TG                 |
| 02/21/2017 |          | Reseal Charlyn Motor strip motor & clean up - refer Hosepower Inv W23901   | TG                 |
| 02/08/2017 |          | 1 x Set Vee Belt refer invoice # 2010329251  | TG                 |
| 02/09/2017 |          | 1 x Element Assembly & 1 x Air Filter refer invoice # 2010331983 Hastings  | TG                 |
| 02/14/2017 |          | Nuts, Bolts & Washers - refer NTF Inv 400432   | TG                 |
| 02/14/2017 |          | 1 x Cable Assembly refer invoice 2010339128 Hastings   | TG/GC              |
| 02/16/2017 |          | 1 x Switch Assembly - R refer invoice # 2010344661 Hastings  | TG                 |
| 09/18/2018 |          | Change screens, run and test, replace battery, Replace e-stop switch, pre hire service   | SS                 |
| 09/24/2018 | 1999     | 2000hr service, replace product conveyor, drive drum bearing - drive side  | SS                 |
| 11/01/2018 | 2065     | Call out to Sage Constructions gravel pits. Remove and replace main product conveyor RH tail drum bearing,   | TG                 |
| 09/23/2019 | 2304     | Check over and test run screen plant, adjust fan belts. Test E-stops, clean out dirt from right rear stabiliser leg. Wash down load for transport to Humpty Doo Dump | TG SS              |
| 12/17/2019 | 2393     | Check Battery voltage, check power to starter solenoid OK, remove starter motor, disassemble free up stuck   | TG SS              |
| 12/06/2019 |          | Remove piano wire screens 5mm  | TG SS              |
| 01/07/2020 | 2431     | Inspect broken grease line, get hose fittings from Hosepower, repair and test. OK  | TG SS              |
| 07/07/2020 | 2464     | Remove radiator hose and replace with universal hose from CBC  | TG SS              |

|            |      |   |                     |
|------------|------|---|---------------------|
| 07/08/2020 | 2476 | <a href="#">Remove guards and remove tension bolts from tail drum, fully back off adjustment. Fenner Dunlop replaced belt and spliced. Next day, re-tension belt and track belt under load, adjust final tails belt scraper and feed conveyor belt scraper.</a> | TG SS, Fenner       |
| 07/29/2020 |      | <a href="#">Fenner Dunlop drive to Middle Arm &amp; change out belt &amp; cold splice Refer Attached Fenner Inv FD327088</a>  | TG/Fenner           |
| 08/06/2020 |      | <a href="#">Fenner Dunlop prep belt, splice drive to Hamuara Rd &amp; change out Refer Fenner Inv Q11788</a>  | TG/Fenner           |
| 07/28/2020 | 2519 | Heat up and straighten grizzly pivot rod, refit to screen plan  | TG SS               |
| 08/17/2020 | 2519 | Removed guards, undo mount bolts and slide conveyor assembly out to allow access for belt splicers  |                     |
| 08/17/2020 | 2519 | Remove drive motor and replace bearing, re-assemble (collapsed head drum bearing on tail conveyor)  | TG                  |
| 11/23/2020 | 2528 | Refit feeder convertor, track belts, refit all guards, adjust skirts.   | TG SS               |
| 12/01/2021 |      | Replaced spare key & put on Nebo Rd board   | TG                  |
| 03/10/2023 | n/a  | Pick up bracket from Wilkinsons and paint. (from Tez diary)   | TG                  |
| 03/10/2023 | n/a  | Fit new tail drum drive, mount bracket for motor and scraper  | TG SS               |
| 03/15/2023 | 2537 | 250 hr service - changed engine oil and filter, changed fuel filters, changed air filters (from Tez diary)  | TG SS               |
| 03/16/2023 | 2537 | Set up to remove LH track adjuster (from Tez diary)   | TG SS               |
| 03/17/2023 | 2537 | Remove mounts from track adjuster, still has no room to remove heat up master link and remove pin to split tracks   | TG SS               |
| 03/21/2023 | 2537 | Reseal track adjuster and reassemble, replace 2 x hydraulic hoses, tail belt tilt and raise hoses, replace 2 x drive motor hoses  | TG SS               |
| 09/12/2023 | 2537 | Replaced conveyer rollers as pairs on side conveyers, 6 rollers from OPS  | Workshop, Ty, Jutty |
| 09/13/2023 | 2537 | Replaced 2 hoses on vibrator motor  | Workshop            |
| 09/19/2023 | 2537 | Quad float- check for air leaks on float over pit in workshop. Replaced half a dozen hose clamps over trailer, replaced air leaking relay valve at rear of trailer. Remove 2nd axle left hand outer tyre to replace at tyre shop with second hand tyre          | Workshop            |
| 09/13/2023 | 2540 | Make pin on conveyor bracket  | Workshop            |
| 10/06/2023 | 2541 | <a href="#">Fenner Dunlop cut/shortened belt. Adjusted tension. May need future tensioning when belt goes to work/operation</a>   | Fenner Dunlop       |