

FE17-1

TT #9 2025 Service Records

Date:	Description:	Hours:	Km:	Next Service:	Reported By:
Feb 22/25	Changed oil (on add) Greased Topped up fluids Filter cover missing (out of service) ordered a new one Inner fender broken, rotted out obsolete made new one Changed upper coolant line from compressor to thermostat housing Changed oil pressure sensor & line to bottom of compressor Bad oil leak somewhere, will monitor	23194	732629	Grease 23319 Oil 23444	Dean
July 21/25	Velocity/ First Truck Centre- shock absorbers, exhaust pipe, muffler insulators, clutch				
July 22/25	Velocity/ First Truck Centre- brake drums				
July 23/25	Kal-Tire- CVIP, rear spring end bushings, u-bolt rod, brake shoes, replaced both front drive axle retainers, hardware in front drive upper torque arm, toe set/ rear drive axles				
July 27/25	Ready unit for CVIP Remove all wheels, measure shoes & drums Replace #3 drums Tighten loose bolts crossmember front diff Replace rear shocks Tighten loose #2 RH shock Repair air leak behind air filter Replace fan hub blade Replace lights as needed Replace RH lower exhaust bushings Replace RH air cooler mounts	23333	736205		
Aug 19/25	Velocity/ First Truck Centre- water pump				
Aug 28/25	Replaced water pump Installed new water filter & replaed hose- was blown Installed new bearing to all idler pulleys Installed new thermostat	23361	737158		Dean
Sept 15/25	T&E Pumps- input shaft, idler shaft, bushings, seals, insert ball bearings, wearplate, oil				

Sept 22/25

Change oil & service
Check fluids
Check lights
Check air system for leaks
Test dayco
Curt change thermostat

23385

737919

Grease 23510
Oil 23635

TT #9 2024 Service Records

Date:	Description:	Hours:	Km:	Next Service:	Reported By:
Jan 26/24	Change oil & service Check fluids Check lights Check air system for leaks Check dayco Tighten loose chock bolts Clean cab filter	22385	703274	Grease 22510 Oil 22635	Dean
Jan 29/24	Coronation Industrial- cab heater, fan				
June 21/24	Change oil & service Check fluids Check lights Check air system for leaks Clean cab filter Change air & fuel filters	22690	712516	Grease 22815 Oil 22940	Travis
Aug 6/24	Hayworth Mechanical- 2 tires				
Aug 7/24	Ready for CVIP Remove all wheels, measure shoes & drums Replace #2 axle drums Replace 2 inner drive axle rims Replace RH front signal light Repair #2 LH shock mount Tighten #2 RH shock bolt Grease unit	22855	719165		
Sept 11/24	Change oil & service Check fluids Check lights Check air system for leaks	22940	722600	Grease 23065 Oil 23190	Sergii

TT #9 2023 Service Records

Date:	Description:	Hours:	Km:	Next Service:	Reported By:
Jan 11/23	Fort Garry Industries- steel wheel				
Feb 24/23	Changed oil Greased Topped up fluids Checked belts & pulleys Changed 2 battery & lockout Replace steer axle wheel seals Tested shut down Passenger side front steer wheel seal leaking Topped up driver side front wheel hub Good oil leak by engine, filter will have to wash & monitor Checked lights, 1 cab clearance light out Changed air filter	21599	678463	Grease 21724 Oil 21849	Travis
Mar 16/23	Fort Garry Industries- starter				
Mar 20/23	Replaced starter from Ft. Gary	21670	680599		
June 2/23	O'Brien Collision Center- fender, step, mudflap				
June 12/23	Hayworth Mechanical- 8 tires				
June 14/23	Change oil & service Check fluids Check lights Check air system for leaks Change air filter *Needs T&E seals*	21880	687348	Grease 22005 Oil 22130	Steve
June 15/23	T&E Pumps- pump				
July 11/23	RJames Western Star- switch blower				
July 14/23	Velocity/ First Truck Centre- air springs, shock absorbers				
Aug 10/23	Ready for CVIP Remove all wheels, measure shoes & drums Replace all shocks	22080	692697		

Replace 3 air bags
Grease unit
Replace air dryer
Fix lights as necessary
Repair air leaks as necessary

Aug 26/23 Veteran Colony- alum bumper

Sept 29/23	Change oil & service	22130	693826	Grease 22255	Mike
	Check fluids			Oil 22380	
	Check lights				
	Check air system for leaks				
	Check dayco function				

Nov 24/23	Pre service grease job & check over	22253	698490		Dean
	Changed air & fuel filters				
	Checked shut down				
	Checked lights				
	PTO indicator light not working				
	Checked for air, water & oil leaks				
	Oil leak on passenger side. *will need to address*				
	Fixed up air lines & electrical that were rubbing, protected them.				

TT #9 2022 Service Records

Date:	Description:	Hours:	Km:	Next Service:	Reported By:
Jan 10/22	RJames Western Star- dash control valve, spring brake valve, steering arm				
Feb 7/22	Ready for Cvip Remove all wheels measure shoes and drums Replace power steering box Replace Draglink Replace dash valve Tighten shock bolts Grease unit	21010	659063		
May 30/22	TNT Tank & Traller Repair- pad for float ball				
May 31/22	Tank inspection done to put back into crude hauling took to TNT Lloyd to get pad welded into tank Installed new valve stainless steel and acutaor Changed AC system Replaced air filters. June(1/22) Oil press sensor leaking Topped up oil 1 gal Worked on window switch driver door	21041	660369		
July 15/22	Check over for CVIP Got roof lights working Clean pass window pisser Replace driver window switch Check fluids Oil change and service	21070	661291	Grease 21295 Oil 21320	
Oct 3/22	Greatwest Kenworth- seat				
Dec 12/22	Changed oil & service Checked lights Check fluid levels Check air system for leaks Test dayco function Tighten #2 RH shock bolt Tighten loose cross member front diff. Change cab filter	21325	669513	Grease 21450 Oil 21575	Dean

TT #9 2021 Service Records

Date:	Description:	Hours:	Km:	Next Service:	Reported By:
June 21/21	Changed oil Greased Topped up fluids Changed fuel filters Baldwin BF1362,(Baldwin BF7587 replaced with Donaldson P551311) Checked belts and pullies Checked front. hubs Tested shut down Checked lights Changed air filter. Fleet guard AF25139M Changed out. oil line Fixed door panel and grill	20555	646896	Grease 20680 Oil 20805	
June 30/21	Velocity/ First Truck Centre- fuel sensor, alternator, accumulator, seals				
July 1/21	Replace alternator and A/C compressor High and low pressure switch Change out inline filter on high press side Change out accumulator receiver dryer)				
July 2/21	RJames Western Star- reg assy, harness, switch				
Aug 11/21	Grease unit , check over Top up fluids Replace RL outer signal light Check air system for leaks	20722	651707		Merv
Sept 17/21	Installed new batteries (3) cleaned up connections innterstate	20777	652573		Travis
Oct 22/21	Changed oil Topped up fluids Checked lights Checked. Belts and pullies Checked front hubs Power steering gear box leaking Resivoir very low, topped up will monitor Tested shut down	20826	654291	Grease 20951 Oil 21076	Pat

TT #9 2020 Service Records

Date:	Description:	Hours:	Km:	Next Service:	Reported By:
Dec 20/20	FTG Enterprises- CVIP				