

Work Order History Listing

Search: 303205

W/O ...	Asset No	Asset Description	Description
 20075	303205-FEL1469	JOHN DEERE 844K II	Isolator switch n/w. Stealth fixing 7.6.26. Completed by Stealth
 20068	303205-FEL1469	JOHN DEERE 844K II	Not starting. Stealth fixing 15.6.26. Completed by Stealth.
 19866	303205-FEL1469	JOHN DEERE 844K II	Decon loader. Installed back top bonnet and installed air cleaner housing & air hose line. Installed muffler exhaust connected to turbo. Installed all side door cover assy & potentiometer switch assy together with wiring harness. Removed uhf radio a ...
 19354	303205-FEL1469	JOHN DEERE 844K II	machine needs injectors, not to be repaired, to be decommissioned and disposed of. Assisted and helped Brandt tech. Removing top bonnet all side covers, air cleaner hose connectors & exhaust muffler & pipe assy. 19304hrs
 17417	303205-FEL1469	JOHN DEERE 844K II	Replace turbo actuator. Refit turbo actuator and fitted linkages, water pipes, top up coolant and run up check operation all ok. 19307hrs
 16852	303205-FEL1469	JOHN DEERE 844K II	Scales n/w. Checked and inspected scale n/w. Checked all wiring cable and all plug connections all good. Checked pressure sensors also good. Checked scale potentiometer manually n/w. Recommend electrician for further investigations. Removed and rep ...
 15341	303205-FEL1469	JOHN DEERE 844K II	Scales n/w. PB 14.10.25 Stealth fixing. Completed by Stealth.
 15304	303205-FEL1469	JOHN DEERE 844K II	Ride height control issue. Assisted RDO tech found out some wiring harness open circuit. repaired wiring cables. Adjusted joystick @ righthand side. Run and tested at stockpile yard all good. 19270hrs
 15286	303205-FEL1469	JOHN DEERE 844K II	PM1 - Victoria Plant Pool - John Deere 844K II Carry out PM1 Service. E stop n/w Found out wiring harness has open circuit. remove and replaced wiring harness. need to remove all lower covers at cab to have access. Calibrate trans & check why brakes ...
 15025	303205-FEL1469	JOHN DEERE 844K II	Hydraulic oil leak. Attended machine hydraulic oil leak found out hyd hose line leak connecting fitting blown Oring seal. need to be replaced. Removed bottom cab fenders r/h/s & l/h/s and front middle. Removed air duck bottom l/h/s & r/h/s to have a ...
 14697	303205-FEL1469	JOHN DEERE 844K II	Ride control issues. Checked and inspected ride control issues. Run and tested to sales yard stockpiles. found out ride control suspension accumulator malfunctions. Recommend RDO tech to check and re-gas accumulators. Assisted and helped John deere ...
 14508	303205-FEL1469	JOHN DEERE 844K II	Hyd oil leak @ front control valve and emergency steering pump. Cleaned and located hydraulic leak at emergency steering connection fittings x2 (x1 big & x1 small.) Removed both hoses & fitting removed and replaced o ring seals. then installed back ...
 14444	303205-FEL1469	JOHN DEERE 844K II	Repair steps / Arm rest bracket. Repair steps / Fit fab bracket / fit.
 14295	303205-FEL1469	JOHN DEERE 844K II	Replace x3 thermostats, header tank, both hoses, radiator cap & Flush coolant system. Drained coolant and removed hose line at tank. Removed and replaced reservoir tank assy. Removed all related parts @ thermostat housing and removed thermostat hou...
 13868	303205-FEL1469	JOHN DEERE 844K II	R/H joystick broken. Pick up parts at RDO. Removed r/h console cover. removed arm rest assy. removed all plug connected at r/h/s joystick. Removed mounting bracket of joystick assy. and removed joystick assy. Installed joystick assy and installed al ...
13365	303205-FEL1469	JOHN DEERE 844K II	brakes not pulling up on machine. Wades to check machine to be decommissioned 20-5-26 closed out this wo
 13305	303205-FEL1469	JOHN DEERE 844K II	Not starting. Unit not starting jump + load onto float. Charge rate ok.
 13254	303205-FEL1469	JOHN DEERE 844K II	Missing l/h/f mudflaps & front engine oil small weep found on mex:13246 Washed the whole machine specially engine bay & trans bay. Engine oil leak at rocker arm cover and front part of engine and also found out exhaust @ turbo connection is leaking. ...
 13246	303205-FEL1469	JOHN DEERE 844K II	Check over. Checked all oil level as per required engine. trans. diff, front & rear, checked coolant level. Topped up hydraulic oil as per required level and auto grease tank. Refilled water at wiper washer. Run & tested all good. Washed/ cleaned th ...
 13066	303205-FEL1469	JOHN DEERE 844K II	Replace Hyd pumps due to failures / leaking into transmission. RDO completed repairs to estops, check Transmisson issues, clean all wiring and solenoids. tested all ok. replace RHF hub seal, replace rear washer jet, LH door latch, replace orings on ...
 12987	303205-FEL1469	JOHN DEERE 844K II	Scales n/w. Assist Smart tech repair scale n/w. Run & tested all good.
12957	303205-FEL1469	JOHN DEERE 844K II	Scales not working smart tech to inspect 29/5/25 repaired 29/5 broken wires in loom
 12934	303205-FEL1469	JOHN DEERE 844K II	Not starting. Attended machine @ jobsite not starting found out batteries are weak 14v only. Jump started with power pack and performed rapid charging until goes 24v. Started machine all good. 19064hrs
 12734	303205-FEL1469	JOHN DEERE 844K II	Replacement of hyd pumps due to leaking. replacement of hyd hoses. completed by RDO 10/5/25
 12061	303205-FEL1469	JOHN DEERE 844K II	Scales n/w Wash down + inspect pressure switch/ transducer circuit. Confirm harness continuity. John deere fixing issue.
 11839	303205-FEL1469	JOHN DEERE 844K II	Fix scales n/w. Stealth fixing 19.3.25. inv 97296 Grab machine 2 jobsite and brought to workshop for Stealth elec fixing scales n/w. Run & tested machine then calibrated all good. 19047hrs
 11367	303205-FEL1469	JOHN DEERE 844K II	Leaking Oil noticed RDO to inspect Assisted RDO tech removing l/h f/h hoses, cleaned and refitted. tested all ok. Run the machine and back @ machine again finding then took too out. 18034hrs

 11839	303205-FEL1469	JOHN DEERE 844K II	Fix scales n/w. Stealth fixing 19.3.25. inv 97296 Grab machine 2 jobsite and brought to workshop for Stealth elec fixing scales n/w. Run & tested machine then calibrated all good. 19047hrs
 11367	303205-FEL1469	JOHN DEERE 844K II	Leaking tilt cylinder RDO to inspect Assited RDO tech removing l/h tilt ram assy. repaired and refitted, tested all ok. Run the machine and park @ machine repair parking then lock tag out. 19034hrs
 11323	303205-FEL1469	JOHN DEERE 844K II	Not starting. Completed by Stealth. inv. 96583
 11217	303205-FEL1469	JOHN DEERE 844K II	Jump start. jump start loader. Loader had flat Tyre. BP Tyres fixing Tyre issue.
 10969	303205-FEL1469	JOHN DEERE 844K II	Oil leak. Checked and inspected machine. oil leak found out emergency steering pump hyd connection fitting leaking. Washed the machine and tighten fitting. refilled hyd oil as per required. Tested all good. 19007hrs
 10717	303205-FEL1469	JOHN DEERE 844K II	Oil leak. Checked and inspected oil leak found out slightly leaking @ main hydraulic pump and slightly leaking @ front of engine. Washed & cleaned machine. Topped up hydraulic oil & engine oil as per required. Run & tested suspected leaking 2 front ...
 8193	303205-FEL1469	JOHN DEERE 844K II	Leak from Transmisson area. checked system, low on Hyd fluid, Transmisson overflowing out filler pipe. Appears that one of the Hyd pumps seals has failed and filling Transmisson with Hyd fluid. Remove bucket Float to RDO. repairs completed 13/11/24, ...
 7934	303205-FEL1469	JOHN DEERE 844K II	PM3 - Victoria Plant Pool - John Deere 844K II RDO to complete during Transmisson repairs completed 4/10 RDO
 7888	303205-FEL1469	JOHN DEERE 844K II	Grease Unit & Check lights. Found grease around front most fitting on grease unit looked like pressure relief. Traced hose to pins that were dry replaced 1 grease fitting. Manually pump grease through block and lines for bucket tilt + pins. Check li ...
7879	303205-FEL1469	JOHN DEERE 844K II	grease line not connected - to be checked checked found front grease line broken, replaced olive and reconnected all ok, checked system, found blockages in auto grease block and line, removed and cleared, manually greased through line all ok.
 7640	303205-FEL1469	JOHN DEERE 844K II	bucket pin coming out. Pulled out broken pin lock bolts. Installed back bucket pin and put new lock pin bolt r/h/s 18877hrs
 7517	303205-FEL1469	JOHN DEERE 844K II	repairs to RR side spot light broken off, dust in cabin to be checked. grease front drive shaft yokes etc after being replaced. Stealth replacing r/h/r side spotlight. done by Stealth. inv. 00093404 Removed & replaced door seal lower door seal l/h & ...
 7370	303205-FEL1469	JOHN DEERE 844K II	Drive shaft failure. Check drive shaft, shaft between transmission and park brake has failed, appears yoke securing nut on park brake assembly has come off and caused yoke and drive shaft to release, damaging the shaft splines and locking nut thread ...
 7328	303205-FEL1469	JOHN DEERE 844K II	Hydraulic leak. Checked & located hydraulic leak. found out busted hyd hose line from trans control valve. Call Reddy fix for hyd hose. Assisted Reddy fix remove & replace hyd hose then refilled hyd oil. washed the machine. 18780hrs
 5651	303205-FEL1469	JOHN DEERE 844K II	Bucket noisy please grease. Checked and inspected auto greaser found out its empty. Cleaned up reservoir tank and refilled with grease. Tested auto grease one supply grease not functioning. Greased all grease nipple @ bucket manually one by one. 186 ...
 5527	303205-FEL1469	JOHN DEERE 844K II	PM1 - Victoria Plant Pool - John Deere 844K II & Repairs. Conducted PM1 Service as per service sheet list. 18780hrs
5492	303205-FEL1469	JOHN DEERE 844K II	Assessment on brake system after incident on face RDO to conduct 29/5 PO 100110 Replacement of brake accumulator unit 31/5 RDO to complete, accumulator not in the country, ordered and awaiting arrival 3/6. fitted 30/9 due repairs at RDOP.
 5461	303205-FEL1469	JOHN DEERE 844K II	Accelerator pedal issues & Replace fire extinguishers. Assist RDO inspection of brake. Checked and cleaned the lubricated accelerator pedal and tested all good. Removed and Replaced fire extinguisher 9kg & 1kg. 18649hrs
 5060	303205-FEL1469	JOHN DEERE 844K II	Check brakes & Check for oil leaks (Due to incident on tip face.) Checked all oil level engine, Hydraulic and Trans all good as per required. Checked all hydraulic lines for leaks all good. Checked brake hyd pipelines all good. Tested machine operat ...
 5028	303205-FEL1469	JOHN DEERE 844K II	Hydraulic oil leak. Checked and located hydraulic oil leaks. Pilot hyd hose busted x2. Call Reddy fix and Fabricated hose. Removed and replaced hyd hoses x2 then tested. Refilled hyd oil as per required and washed the machine. 18630hrs
4761	303205-FEL1469	JOHN DEERE 844K II	fire extinguisher testing
 4670	303205-FEL1469	JOHN DEERE 844K II	R/h hub seal leaking. Cleaned Tyre rim and hub. Removed hub cover and Replaced O-ring seal and installed back. Refilled diff oil as per required level. Remove breather and clean. Pick up new seal for r/h/s front cap for hub. 18540hrs
 4006	303205-FEL1469	JOHN DEERE 844K II	r/h/f hub leaking & Slipping gears. Removed hub cover, Removed and Replaced hub cover Oring then installed back hub cover. Assisted RDO tech. Installed back l/h/s wall cover. Washed machine & transmission and all related parts.
 3990	303205-FEL1469	JOHN DEERE 844K II	Transmisson slipping. Checked and Tested transmission manual shifting gear 1-4 all good. Tested auto shifting gear 1-4 all good. Tested auto shifting gear kick down 1-2-1 all good. Advised Jay to operate with load and monitor. 18491hrs
 3865	303205-FEL1469	JOHN DEERE 844K II	Coolant leak fix coolant leak.
 3828	303205-FEL1469	JOHN DEERE 844K II	hydraulic leak & Battery box repair. Install lid. Inspect hydraulic leak and organize for repair. Diagnose oil leak found broken hose.