

205-5

C.R. Mechanics Ltd.
Box 267
Picture Butte AB T0K 1V0

INVOICE

BILL TO

Sub Terrain Excavating
Box 95
Iron Springs AB T0K 1G0

INVOICE # 16870
DATE 04/20/2026
DUE DATE 05/20/2026
TERMS Net 30

DESCRIPTION	AMOUNT
2005 TROJAN QUAD TRAILER S/N2T9GAFEW25E008692	
WENT TO SHOP AND MEASURED UP THE DRUMS AND BRAKES AND CHECKED THE S CAMS FOR MOVEMENT. SHOWED DON THINGS THAT HAS TO BE DONE TO PASS THE CVIP	100.00
GOT TRAILER INTO THE SHOP AND CHECKED FOR CRACKS IN FRAME AND CHECKED SUSPENSION AND FOUND SOME ISSUES WITH THE BRAKES. FOUND THE BRAKE POT ROD ON THE PASSENGER SIDE REAR AXLE THE ROD IS TOO SHORT AND THE SLACK ADJUSTER IS HITTING THE AXLE. REMOVE BRAKE POT AND CUT THE ROD AND INSTALL AND READJUST. REMOVE THE TIRES AND HAD TO REPLACE SOME OF THE TIRES AS THEY DIDNT PASS. REPLACED 4 AIR BAGS THAT WE TOLD DON TO REPLACE AS THE BOTTOM OF THE BAGS HAVE CORDS SHOWING. HAD TO TOUCH THEM ALL OFF AS THEY WERE ALL SEIZED. HAD TO REPLACE ONE SHOCK ON THE FRONT RIGHT AXLE AND HAD TO CUT OFF. ABS LIGHT WAS ON ALL THE TIME. THERE WAS AN LED LIGHT ON IT TO MAKE IT SEEM LIKE ITS WORKING. DIAGNOSE THE ISSUE AND CHECKED ALL WIRING AND THE CODES WERE SENSOR Y1 IS NO GOOD, ABS MODULE IS NOT KICKING THE LIGHT ON. WE HAD A EXTRA ONE HERE SO WE INSTALLED IT AND IT ALL WORKED. INSTALL NEW ABS MODULE AND TEST NOW ALL WORKS. REPLACE ONE MUDFLAP. REPLACE ALL THE LIGHTS THAT DID NOT WORK. PIVOT PINS ON THE BACK OF THE TRAILER NEED TO BE REPAIRED BEFORE WE CAN PUT A STICKER ON THIS TRAILER. JUSTIN IS GOING TO GET HORIZON TO GET IT DONE AND WILL BRING BACK.	3,800.00
G3003 LED LIGHTS	57.32
67010 PIGTAIL	10.78
WAB1008506010 ABS ECU	936.88
MEREAS8050 AIR BAG	883.84
HENS20002 SHOCK	83.89
78333 ABS LIGHT	12.24
11980 MUD FLAP	32.40
198233 11R24.5 TIRES	2,230.00
3/4 FINE THREAD NUTS	14.64
TOTAL FREIGHT	105.75
SHOP SUPPLIES	120.00

Thank You for your Business

SUBTOTAL

8,987.74

We are set up as a creditor at most banks or e-transfers to crmech8@gmail.com
2% per month interest charged on all accounts over 30 days
GST# 829438365



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is “sold as is” no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture