

504-1



Lethbridge  
1001 41 ST. NORTH  
LETHBRIDGE, AB T1H 6J3  
P: (403) 327-7611

BODYSHOP  
6533 79th AVE SE  
CALGARY, AB T2C 4S6  
P: (825) 257-5782

SERVICE ORDER: R103007025  
ESTIMATE: E103002955  
Tag Number:  
License Plate Number:

DATE INVOICE	SALES TYPE	ADVISOR	TERMS	PO #				
	SRET	3332	CASH					
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODOMETER
2000	SPARTAN MOTORS	MOTORHOME	4VZBN2390YC035517		498			82678

#### Sold Operations

#### JOB #1 MILEAGE PLEASE OBTAIN CURRENT MILEAGE & ENGINE HOURS FOR UNIT

COMPLAINT PLEASE OBTAIN CURRENT MILEAGE & ENGINE HOURS FOR UNIT  
CAUSE  
CORRECTION

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
-----	------	-------------	------------	------------

Prepay: Parts: Labor: Misc: Sublet:

#### JOB #2 PMOIL ENGINE OIL AND OIL/FUEL FILTERS SERVICE (OIL TYPE     )

COMPLAINT ENGINE OIL AND OIL/FUEL FILTERS SERVICE (OIL TYPE     )  
CAUSE MAINTENANCE  
CORRECTION 3330.  
BRING UNIT IN. IDENTIFY OIL FILTER NUMBERS TO ENSURE WE HAVE THEM. DRAIN OIL. REMOVE OIL FILTER. INSTALL NEW OIL FILTER. REINSTALL OIL PLUG. FILL SYSTEM WITH OIL AND TOP UP WHEN NECESSARY. COMPLETE COMPLIMENTARY PM INSPECTION. REMOVE FUEL FILTER. INSTALL NEW FUEL FILTER. RUN UNIT TO PRIME FILTERS. GREASE UNIT. CLEAN ALL RESIDUAL. FILL OUT PM PAPERWORK.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1.30	LABOR PMOIL	ENGINE OIL AND OIL/FUEL FILTERS SERVICE (OIL TYP		149.99
1.00	103D/FG WF2051	FILTER *D	26.58	26.58
1.00	8L	GOVERNMENT EHCI CHARGE 8L	0.55	0.55
1.00	103D/FG LF14009NN	FILTER, OIL FILTER COMBO SP *D	101.40	101.40
1.00	8P	GOVERNMENT EHC CHARGE 8P	1.25	1.25
1.00	103X/15-204	WW -40C TURBO POWER	4.99	4.99
1.00	103X/33352	FILTER	19.58	19.58
22.00	103D/ESO 105816	OIL, M-DELVAC 1300S 15W40, *D	5.05	111.10
22.00	OIL	GOVERNMENT FEE OIL	0.06	1.32
1.00	8L	GOVERNMENT EHCI CHARGE 8L	0.55	0.55

Prepay: \$0.00 Parts: \$263.65 Labor: \$149.99 Misc: \$3.67 Sublet: \$0.00 \$417.31



SERVICE ORDER: R103007025

ESTIMATE: E103002955

**Sold Operations (Cont.)**

**JOB #7 234**

**POWER STEERING PUMP REPAIR OR REPLACE**

COMPLAINT  
CAUSE  
CORRECTION

REPLACE POWER STEERING PUMP (PARTS WARRANTY)  
LEAKING

3326

- PULLED LINES OFF PUMP
- DRAINED THE POWER STEERING FLUID
- PULLED THE POWER STEERING PUMP
- CLEANED AEA WIIERE PUMP GOES TO AIR COMPRESSER
- PUT NEW GASKET AND PUMP ON AND TORQUED TO SPEC
- PUT POWER STEERING LINES ON
- REFILLED THE POWER STEERING FUID
- WASHED AREA OFF TO VERIFY THERE ARE NO FLUID LEAKS
- STARTED UNIT AND RAN TO OPERATING TEMP
- WHEN UNIT IS RUNNING THERE ARE NO LEAKS
- WHEN SHUT DOWN UNIT FOUND THAT LEAKING IN THE SAME SPOT ON THE PUMP AS THE OLD ONE

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1.50	LABOR 234	REPLACE POWER STEERING PUMP (PARTS WARRANTY		239.92
Prepay: \$0.00 Parts: \$0.00 Labor: \$239.92 Misc: \$0.00 Sublet: \$0.00				\$239.92

**JOB #8 146**

**STEERING SYSTEM REPAIRS**

COMPLAINT  
CAUSE

REMOVE POWER STEERING PUMP; RE-ORING PUMP, REINSTALL  
WHEN POWER STEERING PUMP WAS MADE IN THE FACTORY THE RUBBER SEALS IN THE PUMP WERE  
CRUSHED AND NOT INSTALLED PROPERLY

CORRECTION

3326

- DRAINED ALL THE POWER STEERING FLUID
- CUT THE ZIP TIES HOLDING THE POWER STEERING LINES
- PULLED THE POWER STEERING LINES OFF THE PUMP
- PULLED THE NEW POWER STEERING PUMP
- PULLED THE PUMP APART AND FOUND THE RUBBER ORING SEALS WERE PINCHED FROM BRAND NEW
- RESEALED THE PUMP AND VERIFED WHEN PUT BACK TOGETHER THE SEALS DID NOT GET CRUSHED
- PULLED THE OLD GASKET OFF THE PUMP AND INSTALLED NEW GASKET
- CLEANED AREA WHERE THE PUMP MOUNTS THE THE ENGINE
- PULLED THE POWER STEERING RESOVOR COVER OFF
- INSTALLED THE NEW POWER STEERING PUMP AND TORQUED TO SPEC
- INSTALLED THE POWER STEERING LINE BACK ONTO THE PUMP AND TORQUED TO SPEC

\*\*\* NO CHARGE TO CUSTOMER \*\*\*

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
0.00	LABOR 146	REMOVE POWER STEERING PUMP; RE-ORING PUMP, R		0.00
Prepay: \$0.00 Parts: \$0.00 Labor: \$0.00 Misc: \$0.00 Sublet: \$0.00				\$0.00



SERVICE ORDER: R103007025  
ESTIMATE: E103002955

**Sold Operations (Cont.)**

**JOB #9 146**

**STEERING SYSTEM REPAIRS**

COMPLAINT  
CAUSE  
CORRECTION

REMOVE RESERVOIR, CHECK/CHANGE FILTER  
NEW POWER STEERING PUMP INSTALLED  
3326  
- PULLED THE POWER STEERING FILTERS OUT  
- INSTALLED THE 3 NEW FILTERS  
- PUT THE POWER STEERING RESERVOIR BACK ON AND TORQUED TO SPEC  
- FILLED THE POWER STEERING FLUID  
- TOPPED UP FLUID  
- RAN UNIT TO VERIFY THERE ARE NO LEAKS

(NO CHARGE LABOR)

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
3.00	103D/DN P550781	HYDRAULIC FILTER CARTRIDGE *D	29.68	89.04
0.00	LABOR 146	REMOVE RESERVOIR, CHECK/CHANGE FILTER		0.00
1.00	103D/ESO 124706	UNIVIS N-C 32 19L PAIL *D	162.91	162.91

Prepay: \$0.00 Parts: \$251.95 Labor: \$0.00 Misc: \$0.00 Sublet: \$0.00 \$251.95

**Sold Operations Totals** Prepay: \$0.00 Parts: \$2,172.05 Labor: \$1,269.63 Misc: \$204.87 Sublet: \$0.00 **\$3,646.55**

**Authorization of Repairs & Warranty**

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees' permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. The dealership is not responsible for damages from freezing due to lack of antifreeze.

I agree that any warranty coverage noted on this statement of account is based solely on New West Truck Centres estimate of warranty coverage and that I remain responsible for any portion of the charges incurred which is shown as being covered by warranty if the warranty coverage is not accepted by the manufacturer and I agree that such rejected amount should be charged to my account and that I will promptly pay such amount.

PRINTED NAME

SIGNATURE

**Pre-Work Disclaimer**

I agree to receive New West Truck Centres newsletter containing news, updates and promotions regarding New West Truck Centres products. You can withdraw your consent at any time. Please refer to our Privacy Policy or contact us for more details.

X

**Emissions Disclaimer**

I agree this vehicle emissions system has not been defeated, modified or deleted. New West Truck Centres assumes no responsibility for damage to any aftermarket or modified component as a result of our diagnostics or repairs.

Do you authorize New West Truck Centres to undertake any no charge outstanding recalls, field service modifications or campaigns recommended by the manufacturer to the chassis or engine

X

	ESTIMATED	BILLED
LABOR		\$1,269.63
PARTS		\$2,172.05
MISC		\$204.87
SUBLET		\$0.00
DEPOSIT		\$0.00
SUBTOTAL		\$3,646.55
SHOP SUPPLIES		\$120.61
MISC SUPPLIES		\$0.00
TAX		\$188.36
TOTAL		\$3,955.52

Please Remit Payment To:  
New West Freightliner Inc.  
5925 79 Ave SE  
Calgary, AB T2C 5K3  
GST#: 100731173