



Southern Tire Mart

INVOICE #**6100155704**

PHOENIX-BUCKEYE #610
SOUTHERN TIRE MART
4820 WEST BUCKEYE RD
PHOENIX, AZ 85043

PAGE: 1

602/269-2509

CUSTOMER: RITCHIE BROS AUCTIONEERS
0519592 5410 W LOWER BUCKEYE RD
PHOENIX AZ 85043

SHIP TO: WORKED ON @ STM610

EMAIL: lrickey@rbauction.com

PO NUMBER: LANCE

SALESMAN: 11994
INVOICE DATE: 08/17/26

VEHICLE: 2023 ESCALADE 1GYS4PKL7PR166822
LICENSE: 7MA 3G7 AZ MILEAGE: 78118
DUE: 09/10/26

PRODUCT	MECHANIC	QUANTITY	PRICE	F.E.T.	EXTENSION
SHOP SUPPLIES 240		1	12.50		12.50
COMPLAINT-CUSTOMER REQUESTED PM SERVICES AND BRAKES					
PM SERVICES 190	26764	0.50	155.00		77.50
OIL FILTER 200MP		1	6.50		6.50
OIL 5W-30 200MP		8	9.89		79.12
AIR FILTER BALPA 10417 200MP		1	24.12		24.12
R&R FRONT BRAKES/ROTRS AND REAR 190	26764	2.25	155.00		348.75
FRONT BRAKES KIT PSG SG 9139M 200MP		1	51.00		51.00
REAR BRAKES AKE ACT 2174 200MP		1	98.00		98.00
*** UPON DISASSEMBLY TECH FOUND FRONT ROTORS DAMAGED AND NEED TO BE REPLACED***					
FRONT ROTORS- 48882458 200MP		2	63.00		126.00

PLEASE REMIT To:

Dept. 143
P.O. Box 1000
Memphis, TN 38148-0143

PRINTED NAME/CUSTOMER SIGNATURE

IMPORTANT: CUSTOMER SHOULD RE-CHECK TORQUE ON LUG NUTS ON WHEELS SERVICED
AFTER 25 TO 100 MILES OF OPERATION



INVOICE #

6100155704

PHOENIX-BUCKEYE #610

PAGE: 2

CUSTOMER: RITCHIE BROS AUCTIONEERS

SHIP TO: WORKED ON @ STM610

PRODUCT	MECHANIC	QUANTITY	PRICE	F.E.T.	EXTENSION
MNT/DSMNT TIRE CHANGE LT TRK 121	25187	4.00	25.00		100.00
BALANCE TIRE, LIGHT TRUCK 133	25187	4.00	18.00		72.00
275/50R22 DUELER AT ASCENT XL B015423		4	320.00		1280.00
ARIZONA NEW TIRE FEE 802		4	4.73		18.92
FEE, TIRE DISPOSAL, LIGHT TRUCK 209		4	4.00		16.00
TAXABLE TIRE RELATED MATERIALS TTRM	61000		3.60		3.60
MERCHANDISE:					1680.84
LABOR:					598.25
OTHER:					34.92
SALES TAX:					154.41
INVOICE TOTAL:					2468.42
ON ACCOUNT A/R					2468.42

Pulled by: _____ Scanned by: _____ Delivered by: _____
THANK YOU FOR YOUR BUSINESS!!

PLEASE REMIT To:
Dept. 143
P.O. Box 1000
Memphis, TN 38148-0143

PRINTED NAME/CUSTOMER SIGNATURE

IMPORTANT: CUSTOMER SHOULD RE-CHECK TORQUE ON LUG NUTS ON WHEELS SERVICED
AFTER 25 TO 100 MILES OF OPERATION