

E05-1

Can Doo Excavating Services Ltd.



EQUIPMENT INFORMATION

S/O # _____

UNIT # 31

EQUIPMENT DESCRIPTION 94 International

Date of Maintenance	Who performed Maintenance	Maintenance Complete	Hours/Mileage recorded
June 19/24	Cypress comm.	Microphone.	
Nov 29/24	Garth Brian kole	change oil/filter change fuel filters Clean Air Cleaner Change passenger side fuel tank Strap	961495
Dec 17/24	Garth, kole, Brian	Replace rad Hoses	961495
March 6 2025		mudflaps	
June 11/25		oval sealed lamp red	
10/16/25	Summit	Alternator	
Oct 21/25	Kirks	flat repair	
FEB 27/26	Kole Garth	Change oil and filter change fuel filters and grease clean air cleaner change Mudflaps and check lights	967229

E05-1

Can Doo Excavating Services Ltd.

37L



EQUIPMENT INFORMATION

VIN/SN # 2HGFHERRARCO88354

UNIT # 31

EQUIPMENT DESCRIPTION 1994 International Truck

Date of Maintenance	Who performed Maintenance	Maintenance Complete	Hours/Mileage recorded										
Dec 10, 2018	Western Diesel	<table border="1"> <tr> <td>6384-175</td> <td>HOSE SILICONE 1.75</td> </tr> <tr> <td>6384-100</td> <td>HOSE SILICONE 1"</td> </tr> <tr> <td>9216</td> <td>CLAMP SILICON LINER</td> </tr> <tr> <td>9228</td> <td>CLAMP SILICON LINER</td> </tr> <tr> <td>23515635</td> <td>TURBO SER 60 A101601N</td> </tr> </table>	6384-175	HOSE SILICONE 1.75	6384-100	HOSE SILICONE 1"	9216	CLAMP SILICON LINER	9228	CLAMP SILICON LINER	23515635	TURBO SER 60 A101601N	
6384-175	HOSE SILICONE 1.75												
6384-100	HOSE SILICONE 1"												
9216	CLAMP SILICON LINER												
9228	CLAMP SILICON LINER												
23515635	TURBO SER 60 A101601N												
JULY 16/19	SCOTT	GREASE BLOW OUT AIR FILTER STRAIGHTEN OUT BUMPER	930780										
Sept 16/19	GARTH	Change oil and fuel filters Check Rear ends and Trans Change Air Cleaner Grease	933325										
NOV 21 2020	Perry	tighten Belts, tighten clamps. Blew out HVAC, inspect clutch, @ end of ady.											
Dec 3/20	GF	Service	941927										
Dec 17/22	GF	Service											
MAR 27/23	GF	Change oil and fuel filters Change Coolant filter Change Air Cleaner Fix window Dr	954776										
FEB 2/24	GF	Change Temp Gauge change Pinion seal	22500										

May 14/24 Dynamic Safety

Can Doo Excavating Services Ltd.



EQUIPMENT INFORMATION

UNIT # 31
EQUIPMENT DESCRIPTION

1994 International Truck
S/N: 2H5FHERR2RC088354

Date of Maintenance	Who performed Maintenance	Maintenance Complete	Hours/Mileage recorded																
JUNE 18/18	SCOTT BISHOP	GREASE TRUCK	922254																
JULY 17/18	SCOTT GARTH	Change Air Valves in cab Change 1 Brake Pot Clean Air filter Change mud flaps																	
JULY 31, 2018	Fairland Supply.	-1' 4 1/2" Hose -1' 3/8" Air brake tube -1 H60-6 Comp Sleeve																	
MARCH 8/19	SCOTT	Fix ALL LIGHTS, PUT HOSE ON THROW OUT BEARING , GREASE WASH TRUCK FOR INSPECTION	855836																
AUGUST 16, 2018	Action Auto	WIH 40745 Air filter																	
AUGUST 27, 2018	Speedy Glass	Domestic Windshield																	
SEPT 11, 2018	X-Calibre	Unit#31 Repair cracks, cut out old pin and add new bushings and pin assembly. 4 bushings were added and stoppers were installed. Box had to be lifted to access the pins.																	
SEPT 14, 2018	Summit Motors	Flap																	
NOV 23, 2018	Action Auto	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 50%;">Description</th> <th style="width: 50%;">Description</th> </tr> </thead> <tbody> <tr> <td>WIH- 51970</td> <td>OIL FILTER</td> </tr> <tr> <td>EHC - \$1.00</td> <td>Environmental Handling Charge</td> </tr> <tr> <td>WIH- 33118</td> <td>FUEL FILTER</td> </tr> <tr> <td>EHC - \$0.50</td> <td>Environmental Handling Charge</td> </tr> <tr> <td>WIH- 33120</td> <td>FUEL FILTER</td> </tr> <tr> <td>EHC - \$0.50</td> <td>Environmental Handling Charge</td> </tr> <tr> <td></td> <td>Goods and Services Tax</td> </tr> </tbody> </table>	Description	Description	WIH- 51970	OIL FILTER	EHC - \$1.00	Environmental Handling Charge	WIH- 33118	FUEL FILTER	EHC - \$0.50	Environmental Handling Charge	WIH- 33120	FUEL FILTER	EHC - \$0.50	Environmental Handling Charge		Goods and Services Tax	
Description	Description																		
WIH- 51970	OIL FILTER																		
EHC - \$1.00	Environmental Handling Charge																		
WIH- 33118	FUEL FILTER																		
EHC - \$0.50	Environmental Handling Charge																		
WIH- 33120	FUEL FILTER																		
EHC - \$0.50	Environmental Handling Charge																		
	Goods and Services Tax																		

Can Doo Excavating Services Ltd.



EQUIPMENT INFORMATION

UNIT # 31

EQUIPMENT DESCRIPTION

1994 International Truck

S/N: 2HSFHERB2RC088354

Date of Maintenance	Who performed Maintenance	Maintenance Complete	Hours/Mileage recorded
March 16 2018	Summit Motors	- Fanblade - 9 Blade / 5 inch P11 - Drive, 9.5 inch fan clutch rebu.	
"	Action (Scott) Auto	- Oil filter - Grease fix hood + light on front	918532
March 28 2018	Kirby Bergen	- Clean + inspect + rumage through parts for unit 31 - engine rebuild	
		- Thoroughly clean engine that was open since last July	
		- Rebuild engine with part ordered and purchased before job	
		- Had to swap parts over from old Cyl head to new, new injectors, piston liners, bearings	
		- Remove + rebuild fan clutch week later.	
	Perry Macphee	- Thoroughly clean + inspect engine parts, order + replace what extra that was needed.	
		- Rebuild #31 engine - R+R engine fan clutch + fan week later.	
May 29 2018	Hat Truck Repair	<p>1. REPAIR AIR DRYER</p> <p>CHECKED FOR AIR LEAK AND FOUND AIR DRYER LEAKING REMOVED AND REPLACED AIR DRYER CHECKED FOR LEAKS -OK</p> <p>TDA/R955065225 AIR DRYER NP</p>	

Can Doo Excavating Services Ltd.



EQUIPMENT INFORMATION

UNIT # 31

EQUIPMENT DESCRIPTION 1994 International Truck

SIN: 2HSFHERR2RC088354

Date of Maintenance	Who performed Maintenance	Maintenance Complete	Hours/Mileage recorded
March 1 2018	Western Diesel Wholesale	BOLT HD 60 SER STAT 190F SERIES 60 CAM BRG SER 60	
		CUSTOMER FREIGHT INCOMING CLAMP 5" GSKT ACC DR 60 SER INSULATOR/BOLT 0/P CLAMP HD LRG SPRING GSKT DECIV OIL P/U	
March 5 2018	Summit Motors	- 2 5 inch galvanized flex tube / foot	
"	Action Auto	- Water Filter	
March 8 2018	Minute Muffler and Brakes	-(N) Elbow -(N) H.P. Flared Adapter -Welding	
"	Hydraco Industries	- Push pull cable	
March 10 2018	Action Auto	- 50/50 HD D. Ext life 4L - oil filter	
March 16 2018	Co-op	- D-MO CC-4 15W40 (2/10L) - Enviro Charg 10 - oil (40L)	

Can Doo Excavating Services Ltd.



EQUIPMENT INFORMATION

UNIT # 31

EQUIPMENT DESCRIPTION

1994 International Truck

SIN - 2H5FHERR2RC088354

Date of Maintenance	Who performed Maintenance	Maintenance Complete	Hours/Mileage recorded
Mar. 3/17	Action Parts	Fuel Filter	
" "	Garth	change oil + filters	913263
July 10/17	Skky Industrial	<p>R & R both rear u-joint Replaced steering brake shoes Replace steering box input seal Add fluid and test to operating temperature R & R both front Drive axle brake drum Cut out stretched suspension bolts and replaced Installed roof light Passenger Side Had to drill and tap new light mounting holes Disassemble interior head liner to get access Tested</p> <p>Parts Cab Marker Kit Freight Charges Clamp Half Round U-Joint Shoe Kit Seal Kit Lamp Nut Drum</p>	915694
Aug 11/17	Skky Industrial	<p>1-R/R Steering axle brake drums 2 centrifuse front drum</p>	916599
Jan 25, 2018	Action Auto Parts (Garth)	- 2OLT solvent (x2)	
Jan 26, 2018	Action Auto Parts	- Pads 6x9 Maroon, 002-006 Plastigage, 001-003 Plastigage, assorted packaged clips	
Jan 26, 2018	Action Auto Parts	- 320 Erit shop Roll	
Feb 20, 2018	Summit motors	- 2 Insulatr (part # 479237c1)	
Feb 22, 2018	Bolt supply House	<p>- 2 5/8 x 4 NC GR5 C/S ZINC - 4 5/8 Flat washer 2 bag - 2 5/8 - 11 NC Nylon locknut Bag</p>	

Can Doo Excavating Services Ltd.



EQUIPMENT INFORMATION

UNIT # 31

EQUIPMENT DESCRIPTION 1994 International Truck

SN: 2HSFHERR2RC088354

Date of Maintenance	Who performed Maintenance	Maintenance Complete	Hours/Mileage recorded
Feb 10/16	Summit Motors	1-Belt	
Feb 10/16	RD/Garth	rebuild rear shock mounts	909190
May 12/16	alpha-Wide	2x6-16 # 2+BTR KO SPR	
May 12/16	Action Parts	lens for 46793	
June 2/16	MG Mechanical	Safety Inspection	910263 km
June 9/16	Farmland Supply	1- 5/8" x 6'-5" heater hose 2-P10SS Clamps	
Aug 18/16	MG Mechanical	Transmission 17" Valeo Clutch	910992 km.
Sept 16/16	Kirks Tire	Flad repair	
Sept 30/16	Action Parts	2 1/2" Rnd. SL Mark w/ ref	
Dec 31/16	Johnny's Diesel	end yoke, transmission output yoke nut wash, shaft yoke, u joint assembly	912901 km

Can Doo Excavating Services Ltd.



EQUIPMENT INFORMATION

UNIT # 31

EQUIPMENT DESCRIPTION

1994 International Truck

SIN 2HSFHERR2RC088354

Date of Maintenance	Who performed Maintenance	Maintenance Complete	Hours/Mileage recorded
Sept 10/15	Garth	Grease wind - check diff weld grease nipple on box pin	906668
Nov 30/15	Jarmland Supply	Tip, 1/4" mini ball valve	
Feb 8/16	Action Parts	oil filter, air filter fuel filter	
Feb 8/16	RD/Garth	change oil + filters, change fuel filter, air filter, grease + check DIFFS	909190
Feb 8/16	Co-op	15-40 oil	
Feb 9/16	Action Parts	JB weld	
Feb 9/16	Summit Motors	5in Galvanized flex tube 1ft	
Feb 9/16	RD/Garth	- fix exhaust pipe under cab - change fan belt	909190
Feb 10/16	Action Parts	Electrical tape, silicone rubber adhesive, grommet (2 1/2") 2 1/2" End. sl. mark wire	

Can Doo Excavating Services Ltd.



EQUIPMENT INFORMATION

UNIT # 31
EQUIPMENT DESCRIPTION

1994 International Truck

SN 2HSFHERR2RC088354

Date of Maintenance	Who performed Maintenance	Maintenance Complete	Hours/Mileage recorded
Oct 20/14	Action Auto Parts	Stop-tail - turn lamp. Red	
Nov. 18/14	Action Auto Parts	Hose clamps - 4. GL 1 3/4 x 3/8" Red Hose	
Nov. 18/14	Med. Had Co-op	Prestone W/D Diesel Antifreeze	
Dec 9/14	Summit Motors	- 2 - Flextube clamp - 1 - clamp	
Dec 9/14	Larry/Peter	Grease unit top off all oil levels	
June 5/15	Pro Brake & Suspension	BEN-5007132 - Maxi pot	
June 12/15	Hydraco Industries	Air KN68230 - Valve 12V Solenoid Pilot	
June 19/15	MS Mechanical	Safety Inspection	904013 km
June 19/15	MS Mechanical	Stop tail - LED. BAC - 2.5" Round Marker Red LED Brake check B200 - Wiring supplies - air brake connector nylon 3/8 x 3/8 - air brake coupler 1/2 hose 10 x 3/8 - air brake Brake pot	904013 km

Can Doo Excavating Services Ltd.



EQUIPMENT INFORMATION

UNIT # 31

EQUIPMENT DESCRIPTION 1994 International Truck

SIN 2HSFHERR2RC 088354

Date of Maintenance	Who performed Maintenance	Maintenance Completed
June 5/14	Great West Kenworth	Clamp exhaust - EC50PLB
June 6/14	Had Truck Repair	CVIP Inspection OD: 893,018 km
June 10/14	Pro Brakes Suspension	RBT-E-XK 6554709E1 Eaton W/tabs
July 4/14	MG Mechanical	Turbocharger, core-turbo, mounting nuts, gaskets, hose, exhaust studs
Aug 18/14	Action Auto Parts	Stop-tail-turn lamp - Red
Sept 3/14 897425 km	Garth F Larry H.	Oil change, oil filters, Fuel filters Coolant filter, New air filter grease, check all diff & travel joints
Sept 3/14	Summit Motors	2 - LF 3333 filters
Sept 3/14	Action Auto	Oil filter - 2 - W1H 51971MP Oil filter - 1 - W1R 51970 Fuel filter - 2 - W1H 33118 Fuel filter - 2 - W1H 33120 Water filter - 1 - W1H 24071 Air filter - W1H 46745.

Sept 3/14

MN Co-op

D-MO Gold 15/40 20ltr.

Can Doo Excavating Services Ltd.



EQUIPMENT INFORMATION

UNIT # 31

EQUIPMENT DESCRIPTION 1994 International Truck

SN 2H5FHERR2 RC088354

Date of Maintenance	Who performed Maintenance	Maintenance Completed
July 12/13	MN Co-op	Hours Diesel Fuel Cond.
July 20/13	Action Parts	2. WTI-51971mp oil filters
Aug 1/13	Alta Wide	New Boards 2x12-14'
Sept 3/13	Kirks Tire	Flat repair
Oct 5/13	Kirks Tire	B11R 22.5 OTD → 4 tire change over.
May 29/13	Summit Motors	Fuel Cap
June 4/14	Pro Brake + Suspension	Diaphragm type 30, three wire pigtail clear oval bluelight, licence plate lamp
June 4/14	Speedy Glesco	Windshield
June 5/14	Summit Motors	Horn

Records hrs + kms

Can Doo Excavating Services Ltd.



EQUIPMENT INFORMATION

UNIT # 31
EQUIPMENT DESCRIPTION

1994 International Truck

S/N 2H5FAERRJRC088354

Date of Maintenance	Who performed Maintenance	Maintenance Completed
Apr 15/12	Marcel	inspection
June 8/12	Allstar Radiator Tom	1-71R2700 - Thermostat Check A/c system
June 12/12	X-calibre Curtis	cut welds + remove hitch from rear - new mounts top bottom + installed on rear
June 4/12	Pinnacle	2-AMS65409 - Absorber 47425 Belt 3565416C1 Belt
June 6/12	Action Tom	Poly Cog Belt
July 6/12	Pinnacle	641R12401 Spring
Dec 19 /12	Action Parts	8" Convex Mirror
Apr 12 /13	Allstar Radiator	Repair RAD - remove Frame. Clean + pressure test. Radiator repaired hole in tank - painted
11	Co-op BRIAN KAUMRING	842C Topring Cplr 1/4 F NPT Topring PLUG 1/4" m npt Serviced - Tom Klop

Plate
FCA 539

Can Doo Excavating Services Ltd.



EQUIPMENT INFORMATION

UNIT # 31

EQUIPMENT DESCRIPTION 1994 International Truck

S/N 2H5FHERR2RC088354

Date of Maintenance	Who performed Maintenance	Maintenance Completed
July 18/11	Marcel	Trouble shoot electrical for tailgate and disassemble console + repair wiring
Sept 16/11	Action Parts	Halogen Leaf Beam
Nov 9/11	A+B Steel Ron Hammel	5" Flex Nose
Jan 4/12	Alta Wide - Tom	2x6-16' #2 BTL KD Spr.
Jan 5/12	Farmland - Tom	DB Brass Bulk head, brass elbow Teflon Tape, 3/8" hose splic
Jan 5/12	Bolt Supply - Tom	hex nut, Mal wash 5/16 x 2 1/2 NC GR5 C15 ZINC
Jan 5/12	Farmland - Tom	1-GAS-Gold band 4' 3/8 Air Brake hose - 7-1490-6 Slaves
Jan 5/12	Kirks / Tom	tierod - NSPAL R-R L.S. Tie rod w/ake CR960-189
Jan 30/12	Dunlop	2-BW/N10a685 AD-a Air D
Jan 31/12	Shop / Tom	Replace Air Dyer + tank brace
Feb 1/12	Action / Jeff	Oil Filter Fuel Filter Air Filter Water Filter



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is "sold as is" no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture