



Vehicle Service Records (VSR Explorer)

Repair history D-203786

Registration nr: 1EWU297 **Chassis nr:** D-203786 **VIN nr:** YV5RP80G0GD203786
Market type: FH16A84T **Country:** AUS **Delivery date:** 2016-10-27

PC	Type	Code	Description (Original)	#
2023-08-14 - Mileage: 720446 - Order nr: 2240056				
	*	SHIFT	DAY - 14/08 - 15/08.	
		LO-210	DIAGNOSE HARD STARTING	3
			- FAULT CODE P02D300 INJECTOR NO. 4.	
		LO-262	CONNECTING PIPE REPLACEMENT	1
			- PREVENTATIVE - CUSTOMER REQUEST.	
		VO-85013343	EXCH UNIT INJECTOR	1
		LO-211	INJECTOR TUBE REPLACEMENT	8
		VO-21344774	FLANGE SCREW	6
		VO-20736230	D16C R/C GKT	1
		VO-276948	D12 INJ/SEAL KIT	5
		VO-21351717	INJECTOR SLEEVE	6
		AU2-AMP24078863	VOLVO VCS-2 COOLANT 5L	1
		VO-20852765	GASKET	4
		VO-21420336	CONNECTING PIPE	1
		VO-20799996	SEALING RING	1
		VO-21423788	SEALING RING	1
			NEW UNIT SN: 23614223.	
			Connect laptop and read fault codes - injector No. 4 code	

PC	Type	Code	Description (Original)	#
	🔧		logged. Carry out compression test - all cylinders over	
	🔧		95%. Remove the rocker cover. Check valve heights - OK.	
	🔧		Carry out cylinder balance test and reset - cylinder 4 out	
	🔧		of spec. Remove the rocker shaft. Inspect injector No. 4	
	🔧		- found the lower o'ring broken and pitting on the groove.	
	🔧		- INCLUDING NEW INJECTOR NO. 4.	
	🔧		Drain coolant. Remove the injectors. Replace the injector	
	🔧		tubes with new. Reassemble in reverse order with new parts	
	🔧		as required, including new No. 4 injector. Carry out top	
	🔧		set adjustment. Refit the rocker cover. Connect laptop,	
	🔧		clear fault codes and set new injector trim code.	
	🔧		Replace the connecting pipe and seals with new. Fill and	
	🔧		top up coolant. Start and run the engine. Check over - OK.	
🔍 2023-06-14 - Mileage: 711184 - Order nr: 2238473				
🔧	*	SHIFT	DAY	
🔧	🔧	LO-250	ENGINE BRAKE NOT WORKING ON STAGE 3	2.75
	🔧		INVESTIGATE, REPORT ON CAUSE WITH P&A AND RECTIFY	
🔧	🔧	VO-1677370	VEB SEAL	2
🔧	🔧	VO-20526428	VEB SEAL	1
	🔧		NOTE: THERE HAS BEEN A FEW REPAIRS CARRIED OUT ON ENGINE	
	🔧		BRAKE FROM US AND O' BRIEN'S AUTO	
	🔧		Connected lap top. Download and read DTCs. Found faults	
	🔧		logged for EBS CAN communication. Removed rocker cover.	
	🔧		Test VEB valve. Valve clicks. Removed and replaced VEB	
	🔧		seals. Refit rocker cover and secure. Tested exhaust	

PC	Type	Code	Description (Original)	#
	🔧		brake. Found air leak from rubber pipe. Removed and	
	🔧		replaced pipe. Cleared DTCs. Road test. Found working	
	🔧		well on stage 3.	
🔍 2023-03-23 - Mileage: 703668 - Order nr: 2236203				
🔧	*	SHIFT	DAY	
🔧	🔧	LO-255	REPLACE TURBO	3
	🔧		CUSTOMER REQUEST AS BOLTS ARE MISSING IN BACK HOUSING &	
🔧	🔧	LO-761	REPLACE CAB SHOCKS	3
	🔧		Customer request as leaking.	
🔧	🔧	LO-560	INSPECT COMPRESSOR & IF RECOMMEND	3.5
	🔧		REPLACING, REPLACE IT AS PREVENTATIVE MAINTENANCE.	
🔧	🔧	VO-85000622	EXCH TURBO	1
🔧	🔧	VO-23111320	SHOCK ABSORBER	2
🔧	🔧	VO-85013941	EXCH COMPRESSOR	1
🔧	🔧	VO-20784537	GASKET	1
🔧	🔧	VO-993811	FLANGE SCREW	4
🔧	🔧	VO-22206133	GASKET	1
🔧	🔧	VO-8148729	CONNECTOR	1
🔧	🔧	VO-470993	TRBO RETURN GSK	1
🔧	🔧	VO-469601	TURBO DRAIN SEAL	1
🔧	🔧	VO-21940615	SEALING RING	1
🔧	🔧	VO-20573472	SPACER SLEEVE	4
🔧	🔧	VO-467310	EXHAUST CLAMP	1
🔧	🔧	VO-994441	M8*50 FLANGE SCREW	1
🔧	🔧	VO-990950	M8 FLANGE LOCK NUT	1















































PC	Type	Code	Description (Original)	#
		VO-1629499	CLAMP	1
		VO-990941	FLANGE NUT	1
		VO-994195	FLANGE SCREW	1
		VO-992065	O-RING	1
		VO-471708	SEALING RING	1
		VO-23690622	APM DRYER FILTER KIT	1
		VO-977639	12*12 VIPS	2
		VO-992247	SWIVEL	1
		VO-977237	COMP/FEED HOSE	1
			LEAKING.	
			Removed and replace Turbo using ne gaskets, o-rings and	
			seals to spec. Road tested. Checked over. All OK.	
			Removed and replaced cab shocks as requested. Checked	
			over. All OK.	
			CUSTOMER REQUEST	
			Inspected compressor. Found compressor leaking. Removed	
			and replaced compressor using new fittings as required.	
			Removed ait drier. Strip, clean and rekit. Calibrated	
			and tested. All OK.	
			*** POSSIBLE POLICY CLAIM ***	
			NEW SERIAL# TH222870397	
			NEW SERIAL# 4122 2 412 704027	
	2023-03-15 - Mileage: 702337 - Order nr: 9721167			
		INFO	DETAILS	
			KM:702337	

PC	Type	Code	Description (Original)	#
		LO-260	COOLANT LEAK	1
			FUEL BURN:509601	
			ENG HRS:14774	
			DRIVER ADVISED THAT THERE WAS A PUDDLE OF COOLANT UNDER	
			THE TRUCK THIS MORNING.	
			CHECK OVER FOR OBVIOUS COOLANT LEAKS. PRESSURE TESTED	
			COOLING SYSTEM. FOUND TAIL TAIL ON WATER PUMP IS WET.	
			NOTICED TWO HOSES ON RHS HAVE DEEP CHAFF MARKS IN HOSES.	
			DRIVER TOOK TRUCK WITHOUT ANY REPAIRS BEING CARRIED OUT.	
		91	CONSUMABLES	
2022-12-07 - Mileage: 673795 - Order nr: 2233701				
		SHIFT	DAY	
		LO-560	BRAKE MALFUNCTION WARNING EXCESS AIR	2
			CONSUMPTION. BUILDS AIR TO MAX THEN SOUNDS LIKE IT	
		VO-23690622	APM DRYER FILTER KIT	1
		VO-21583806	KIT	1
			DISCHARGES FROM BOTTOM OF AIR DRYER. DROPS UNTIL	
			COMPRESSOR CUTS IN AGAIN AN REPEATS.	
			CUSTOMER HAS REQUESTED THAT IF THE AIR DRYER IS THE	
			PROBLEM QUOTE A NEW UNIT AS WELL AS PRICE TO RE-KIT THE	
			OLD ONE.	
			Checked purge valve for leaks. No leaks noted. Connected	
			lap top. Download and read DTCs. Found APM filter fully	
			consumed. Removed filter. Found excess carbon build up.	
			Carried out P & A to re kit air drier and replace filter	

PC	Type	Code	Description (Original)	#
	🔧		and spool valve. All OK. Strip clean and re kit air	
	🔧		drier. Fit new filter and spool valve. Calibrated and	
	🔧		tested. All OK.	
🔍 W 2022-07-30 - Mileage: 647582 - Order nr: 2230570				
🔧	*	SHIFT	DAY	
	🔧		CONTACT EMAIL : manager@derekmco.com.au	
🔧	🔧	LO-214	Carry out Valve Adjustment/Top set	3.5
	🔧		as due/requested	
🔧	🔧	LO-262	FAN LOCKED IN/COMING IN A LOT MORE	4
	🔧		THEN NORMAL. CHECK FAN OPERATION	
🔧	🔧	VO-85023556	EXCH FAN	1
🔧	🔧	VO-20592783	CLAMP	2
🔧	🔧	VO-3979639	PRE HEAT GSK	2
🔧	🔧	VO-953053	FAN STUD	4
🔧	🔧	VO-990950	M8 FLANGE LOCK NUT	4
🔧	🔧	VO-993977	HOSE CLAMP	2
🔧	🔧	VO-25371156	7 PIN FEMALE CONNECTOR	1
🔧	🔧	VO-984945	CABLE TERMINAL	5
🔧	🔧	VO-970771	CABLE SEAL	2
🔧	🔧	VO-20734499	ANTI-TAMPER SEALIN	5
🔧	🔧	VO-22889891	ACTUATOR SERVICE KIT	1
🔧	🔧	LO-250	EXHAUST BRAKE ACTUATOR NOT THERE	2
🔧	🔧	VO-2637500	Fan belt idler pulley, replace	0.5
🔧	🔧	VO-21753149	IDLER PULLEY	1
	🔧		*** POSSIBLE POLICY CLAIM ***	

PC	Type	Code	Description (Original)	#
		OTH-QNC20	NYLON CONDUIT 16.6mm ID	1
		MK-160AX568F	SILICON HOSE	2
		VO-975269	HOSE CLAMP	4
		VO-983014	CABLE TERMINAL	5
			Removed intakes etc. Removed rocker cover. Carried out	
			top set to spec. Record all measurements. Refit rocker	
			cover. Refit intakes etc. Road tested. Checked over.	
			All OK.	
			Connected lap top. Download and read DTCs. Found engine	
			fan faults logged. Tested fan. Found fan speed sensor	
			faulting. Carried out P & A to replace engine fan. All	
			OK. Disassembled and removed fan. Found pins on engine	
			harness for fan had lost tension. Removed and replaced	
			pins on plug. Fit new fan and secure. Refit and secure	
			all removed items. Cleared codes. Tested fan operation.	
			All OK.	
			Found exhaust brake solenoid missing. Fit new exhaust	
			brake solenoid. Fit new silicone hose and double clamp at	
			both ends. Fit conduit and tape up. Tested operation.	
			All OK.	
		263	FANS,FAN SHROUDS AND COUPLINGS	
			Inspected fan belt idler. Found bearing noisy and notchy.	
			Removed and replaced idler pulley.	
			Note: Part claimed to Parts Warranty.	
			NEW SERIAL# GT8803-03 080322 136	

PC	Type	Code	Description (Original)	#
	📄		*** POSSIBLE POLICY CLAIM ***	
	📄		NEW SERIAL# 11-03-22 000630	
🔍 2022-05-05 - Mileage: 0 - Order nr: 2228919				
🟢	*	CARD	NOT REQUIRED	
🔍 2022-04-06 - Mileage: 0 - Order nr: 2228228				
🟢	*	CARD	NOT REQUIRED	
🔍 2022-01-21 - Mileage: 591133 - Order nr: 2227001				
🟢	*	SHIFT	DAY	
🟢	🔧	LO-5000	AIR LEAK ON TRUCK BRAKE SYSTEM	3
	📄		CUSTOMER STATES THAT WHEN YOU BUILD UP AIR AND THEN APPLY	
🟢	🔧	LO-2100	OIL LEAK OVER BELL HOUSING	1
	📄		DIGNOSE AND REPORT - CUSTOMER HAS LEFT THE OIL ON THE BELL	
🟢	🔧	VO-991972	NIPPLE	2
🟢	🔧	VO-992249	ELBOW NIPPLE	1
🟢	🔧	VO-980834	PLASTIC PIPE 16MM	1
🟢	🔧	VO-992018	SWIVEL	1
🟢	🔧	VO-991972	NIPPLE	1
🟢	🔧	VO-992249	ELBOW NIPPLE	1
🟢	🔧	VO-23239988	BALL BEARING	1
🟢	🔧	VO-20483426	SEALING RING	1
🟢	🔧	VO-85022454	EXCH CLUTCH CYLINDER	1
🟢	🔧	VO-85022366	EXCH CLUTCH	1
🟢	🔧	VO-23020379	DISC	1
🟢	🔧	LO-2100	R&R GEARBOX INPUT SEAL LEAK	14
	📄		NEW CLUTCH AND CYLINDER	

PC	Type	Code	Description (Original)	#
		VO-20483426	SEALING RING	1
		VO-3192614	PISTON SEAL	2
		VO-20497205	GASKET	1
		VO-995906	HEXAGON SCREW	4
		VO-984050	HEXAGON NUT	4
		VO-20992763	AIR HOSE	1
		AU2-AMP22567321	VOLVO VCS COOLANT 5LT	1
		VO-85108352	CRANKSHAFT SEAL	1
		20	SUBLET - Machine Flywheel	
		VO-953104	STUD 12*75	1
		VO-990952	M12 FL LOCK NUT	1
		AU2-WUR5580000036	10MM JOINER	1
		MK-FT1162X12M	BRASS PUSH-CONNECT	1
		VO-20593252	PLUG FLYWHEEL HOUSING	1
		VO-961968	PROTECTING PLUG	1
		LO-451	DEFECT - REMOVE AND REFIT BOTH SHAFTS	2.25
		VO-995906	HEXAGON SCREW	16
		VO-984050	HEXAGON NUT	16
		VO-23469625	SPIDER	2
		VO-23686080	SPIDER KIT	2
			SEND OUT FOR UNI JOINT REPLACEMENTS	
		60	SUBLET - FIT SUPPLIED UNI'S TO MAIN	
			AND JACKSHAFT, ALSO BALANCE SHAFT	
			Checked system. Found air leaking when brake pedal is	
			applied. Traced leak to 16mm airline from front steer	

PC	Type	Code	Description (Original)	#
	🔧		valve to second steer. Removed and replaced entire	
	🔧		section of airline using new fittings as required. Re	
	🔧		tested. All OK.	
	🔧		Inspected oil leak out of bell housing flywheel hole.	
	🔧		Found oil is most likely from a failed rear main seal.	
	🔧		Gearbox will need to be removed for further investigation.	
	🔧		Drained coolant. Removed drive shaft. Found dust covers	
	🔧		on uni joints split. Also removed jackshaft. Shafts to	
	🔧		be sent out to have uni joints replaced.	
	🔧		Disassembled and removed gearbox. Inspected. Found oil	
	🔧		leaking from rear main seal. Also noticed oil leaking	
	🔧		from gearbox input seal and clutch brake seal. Inspected	
	🔧		clutch and clutch cylinder. Found worn and require	
	🔧		replacement. All OK. Removed flywheel. Sent for	
	🔧		machining. Found bungs missing from flywheel housing.	
	🔧		Fit new bungs as required. Removed and replaced rear main	
	🔧		seal. Clean housing. Fit flywheel to spec. Removed and	
	🔧		replaced gearbox input seal and clutch brake seal.	
	🔧		Removed and replaced clutch and clutch cylinder to spec.	
	🔧		Reassembled gearbox and secure. Fit and secure repaired	
	🔧		drive shafts using new nuts and bolts to spec. Fill	
	🔧		coolant. Connected lap top. Calibrated gearbox. Cleared	
	🔧		codes. Washed down and road tested. Checked over. All	
	🔧		OK.	
	🔧		THE FOOT BRAKE THE TRUCK STARTS DUMBING AIR.	




























PC	Type	Code	Description (Original)	#
	📄		HOUSING AND NOT WASHED IT SO WE CAN LOOK FOR IT .	
🔍 2021-10-19 - Mileage: 562313 - Order nr: 2224777				
🟢	*	CARD	NOT REQUIRED	
🔍 2021-09-22 - Mileage: 558255 - Order nr: 2224338				
🟢	*	SHIFT	BREAKDOWN	
🟢	🔧	LO-510	INSPECT & ADVISE FAULT CODES	2
	📄		C101201 - WHEEL SPEED SENSOR	
🟢	🔧	LO-194	TRAVELLING TIME	0.75
	📄		40 BRANT RD KELMSCOTT	
	📄		Load Ute. Travel to site. Checked wiring at sensor. All	
🟢	🔧	LO-363	WIPER WARNING LIGHT ON	0.5
	📄		Checked wiring and connections. Found fault is with	
	📄		wiper fluid sensor. Advise Customer accordingly.	
	📄		C109C16 - WINDSCREEN WASHER LEVEL SENSOR.	
🟢	📄	VO-994225	HOUSING	1
🟢	📄	VO-22225554	MODULATOR	1
🟢	*	561	EBS Fault	
	📄		Customer reports truck is faulting.	
	📄		Connected lap top. Download and read codes. Carried out	
🟢	🔧	LO-561	EBS Modulator Fault	2.5
	📄		Checked codes. Found code logged for air modulator.	
	📄		OK. Tested resistance. 1.2k ohm. All OK. Tap in	
	📄		sensor. Update EBS. Road tested. All OK.	
	📄		GD. Found fault is coming from the trailer attached to	
	📄		truck. Advise Customer accordingly.	

PC	Type	Code	Description (Original)	#
			Carried out fault tracing. Found front modulator was	
			bypassing park brake air, causing the second wheels to	
			lock up. Carried out P & A. All OK. Removed and	
			replaced modulator. Checked over. All OK.	
			ALXILLARY BRAKE STILL IN NUTRAL/ DISABLE - ON DASH	
			CUSTOMER REPORTED BRAKES LOCKED UP. TRAILER BRAKES ARE	
			WORKING.	
			NEW SERIAL# 20454 00336 K093192	
2021-09-08 - Mileage: 555985 - Order nr: 2223958				
	*	SHIFT	DAY	
		VO-3741100	Harness, lining wear sensor, repair, rea	2.5
			INSPECT & ADVISE, RECTIFY	
		VO-23740253	SENSOR	1
		MK-NARV56308	CABLE TIE 1=25 PK	1
		VO-980464	STRIP CLAMP - CABLE TIE	25
			Connected lap top. Download and read DTCs. Found faults	
			For first steer LHS lining wear sensor - signal below	
			minimum. Checked wiring and connections. All OK. Fault	
			is in sensor. Carried out P & A to replace. All OK.	
			Removed and replaced sensor. Carried out brake pad wear	
			test. All OK. Cleared codes. Disconnected lap top.	
2021-07-23 - Mileage: 553223 - Order nr: 2222715				
	*	SHIFT	DAY	
		LO-850	REPLACE FRONT ROLLER BLIND	1
		VO-84431057	ROLLER BLIND	1

PC	Type	Code	Description (Original)	#
	🔧		Removed and replaced roller blind as requested by	
	🔧		Customer. All OK.	
🔍 2021-07-20 - Mileage: 552663 - Order nr: 2222498				
🟢	*	DEREK	OFFSITE - 20/07/2021.	
🟢	🔧	VO-2141300	Valves and unit injectors, adjust	3.5
	🔧		Carried out top set adjustment as per specifications.	
🔍 2021-06-16 - Mileage: 544831 - Order nr: 2221731				
🟢	*	DEREK	DAY	
🟢	🔧	LO-284	PLUG IN LAPTOP ADVISE	1.5
🟢	🔧	VO-85139619	PRESSURE SENSOR	1
🟢	🔧	VO-21582423	PLUG KIT	1
🟢	🔧	OTH-KT34AHD	34MM HEAT SHRINK	0.1
🟢	🔧	VO-21296868	SENSOR	1
	🔧		WHY ENGINE MALFUNCTION COMES ON DASH EVERY TIME KEY IS	
🟢	🔧	LO-386	SENDERS FOR INDICATOR/WARNING SYSTEM	0.5
	🔧		Connected lap top. Download and read DTCs. Found fault	
	🔧		for back pressure sensor. Tilt cab. Checked wiring and	
	🔧		connections. All OK. Pressure sensor failed internally.	
	🔧		Removed and replaced pressure sensor. Fit new plug. Seal	
	🔧		with heat shrink. Secure harness. Cleared codes. Check	
	🔧		over. All OK.	
	🔧		TURNOFF - NO FAULT CODES PRESENT	
	🔧		Found #4 brake lining sensor giving incorrect reading.	
	🔧		Found sensor had failed internally. Removed and replaced	
	🔧		sensor. Secure harness. Cleared codes. Check sensor.	

PC	Type	Code	Description (Original)	#
	📄		All OK.	
🔍 2021-04-30 - Mileage: 0 - Order nr: 2220552				
📄	*	510	Customer informed no trailer brakes,	
	📄		message comes up on dash - Truck brake failure, put Aux	
	📄		brake stalk in neutral and exhaust brake inop as well.	
	📄		Below faults supplied	
	📄		C107287	
	📄		C108707	
	📄		C108E62	
	📄		P107B86	
	📄		Investigate report and rectify.	
📄	*	CARD	NOT REQUIRED	
🔍 2020-11-30 - Mileage: 471653 - Order nr: 8601707				
📄	📄	VO-85000622	EXCH TURBOCHARGER	1
	📄		PRICE CHANGE REQUIRED FROM ORIGINAL INVOICE 7053447	
🔍 2020-11-30 - Mileage: 471653 - Order nr: 7053638				
📄	📄	VO-85000622	EXCH TURBOCHARGER	1
	📄		h160532537	
	📄		old	
	📄		H200433060	
	📄		PRICE ADJUSTMENT REQUIRED FROM ORIGINAL BOOKING 7053447	
🔍 2020-11-12 - Mileage: 471653 - Order nr: 7053447				
📄	*	INFO	DETAILS	
	📄		KM:471653	
📄	📄	LO-250	Rectify sudden loss of power	4.6

PC	Type	Code	Description (Original)	#
Ⓟ	■	VO-85000622	EXCH TURBOCHARGER	1
Ⓟ	■	VO-20573472	SPACER SLEEVE	4
Ⓟ	■	VO-20784537	GASKET	1
Ⓟ	■	VO-21940615	SEALING RING	1
Ⓟ	■	VO-22206133	GASKET	1
Ⓟ	■	VO-420643	TURBO GSK	1
Ⓟ	■	VO-469601	TURBO O'RING	1
Ⓟ	■	VO-8148729	CONNECTOR	1
Ⓟ	■	AU2-WUR0890117	BRKCLNR-(UNI-RAPID	1
Ⓟ	■	VO-21312237	CHARGE AIR HOSE	1
Ⓟ	■	VO-21716424	AIR FILTER	1
Ⓟ	■	VO-20411816	AIR FILTER	1
Ⓟ	■	VO-21312239	CHARGE AIR HOSE	1
Ⓟ	■	VO-1161929	JOINTING PASTE	1
Ⓟ	■	VO-994441	FLANGE SCREW	1
Ⓟ	■	VO-990950	FLANGE LOCK NUT	1
Ⓟ	⚙	VO-1921200	Transfer time to breakdown site and back	4.5
	📄		to repairing dealer. Breakdown, call-out service	
Ⓟ	*	92	TRAVEL 370KM Ö Å1.50 CTS PER KM	
Ⓟ	*	BREAKDOWN	BREAKDOWN	
	📄		DESTINATION:MIDDLETON RD	
Ⓟ	■	VO-21940610	SEALING RING	1
	📄		Collected parts/ tools and travelled to breakdwon location	
	📄		near Northcliffe.	
	📄		Checked over and found turbo failed - only just happened	

PC	Type	Code	Description (Original)	#
			and seized up in inlet side, impella still intact.	
			Truck in unsafe position to repair.	
			Assisted driver in removing trailer and limped truck to	
			safe area to carry out repair.	
			Removed and replaced turbo with new.	
			Fitted new lower boost hose and small hose off turbo.	
			Removed and replaced outer air filter with new due to	
			being dirty.	
			Torqued all to spec and advised driver to retorque once he	
			returned to workshop.	
			Started and checked - all ok.	
			Followed driver for a few kms to confirm no issues - all ok.	
			Returned to TCWA Bunbury.	
			FUEL BURN:336933	
			ENG HRS:9361	
			IDLE HRS:1932	
			PTO HRS:530	
			CONTACT PERSON :	
			PHONE NUMBER :	
			CALL OUT TIME 12:30	
			DATE 12/11/20	
		91	CONSUMABLES	
		2020-08-27 - Mileage: 445643 - Order nr: 2214494		
			S1426 TECU, SW UPDATE. FH/FM (4)	
		VO-4301400	TECU, sw, update. Only campaign	0.4

PC	Type	Code	Description (Original)	#
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
	*	DEREK	D KEW	
			Derek Murray	
		VO-2141300	Valves and unit injectors, adjust	3.5
2020-06-20 - Mileage: 428454 - Order nr: 2212976				
	*	SHIFT	DAY	
		LO-260	Customer informed header tank is	3
			black and they have taken a sample - its black.	
		LO-263	Customer informed Fan stuck	1.5
			on - Investigate, report & rectify	
		VO-85003294	EXCH THERMO FAN	1
		AU2-CAL8394800	VOLVO VCS COOLANT	2
		AU2-CAL85108913	VOLVO VCS COOLANT 5 LITRE	1
		VO-970771	CABLE SEAL	7
		VO-990950	M8 FLANGE LOCK NUT	4
		CU-CC2610	RESTORE CLEANER (3.785L)	1
		VO-984757	FLANGE SCREW	1
			Travel to Customer's yard. Inspected. Found header tank	
			coolant dirty. Drained coolant. Fill with restore. Test	
			drive up hill to flush. Drained coolant. Drop gearbox	
			pipe and side cover hoses. Drain completely and refill	
			with water. Drive up hill again to flush. Repeat drain	
			and drive once more. Drain system. Fill with fresh	
			coolant. Pack up and travel home.	
			Fan stuck in the on position.	






























PC	Type	Code	Description (Original)	#
			Connected lap top. Download and read DTCs. Found: -	
			P052612: Fan Speed Sensor Circuit, Circuit Short To	
			Battery Inactive 255.	
			Inspect connections. All OK. Inspect harness. All OK.	
			Tested fan operation. Found fan intermittently faulting.	
			Disassembled and remove fan. Fit new fan and secure.	
			Refit and secure all removed parts. Cleared codes.	
			Carried out fan function test. All OK. Checked on test	
			drive. All OK.	
		LO-194	TRAVELLING TIME	0.75
			Might require a flush - Investigate and report	
			NOTE: Truck recently had major repairs done to truck	
			*** POSSIBLE POLICY CLAIM ***	
			*** POSSIBLE POLICY CLAIM ***	
	2020-03-12 - Mileage: 392644 - Order nr: 2210558			
		DEREK	DAY	
		LO-260	TRUCK LEAKING COOLANT FROM BEHIND TURBO	10
		VO-1161963	RUBBER GREASE	2
		VO-1547252	SEALING RING	2
		VO-22206133	GASKET	1
		VO-420643	TURBO DRAIN GASKET	1
		OTH-440381	S/BRITE DISC	5
		VO-469601	TURBO DRAIN SEAL	1
		VO-984733	M8*15 FL BOLT	2
		VO-21423788	SEALING RING	1

PC	Type	Code	Description (Original)	#
		VO-8131154	SEALING RING	1
		VO-20938686	CONNECTOR	1
		VO-8148729	CONNECTOR	1
		VO-21339891	HOSE,COOLANT	1
		VO-22718181	KIT-EXH MANIFOLD	1
		VO-21302234	GASKET	1
		VO-21503575	SEALING RING	1
		VO-21940610	SEALING RING	1
		VO-20938964	SEAL	1
		VO-21695684	SEALING RING	2
		VO-21242536	HOSE	1
		VO-22821826	EXPANSION TANK	1
		VO-21389923	PIPE	1
		VO-984993	HOSE CLAMP	1
		VO-22560373	HOSE	1
		VO-993977	HOSE CLAMP	1
		VO-21133832	HOSE	1
		VO-995680	HOSE CLAMP	1
		VO-993977	HOSE CLAMP	1
		VO-21245628	PIPE	1
		VO-21949994	PIPE	1
		VO-21903113	HOSE	1
		VO-21903114	HOSE	1
		VO-984993	HOSE CLAMP	2
		VO-984993	HOSE CLAMP	2

PC	Type	Code	Description (Original)	#
		VO-20805110	CONNECTOR	1
		VO-85021957	EXCH RADIATOR	1
		VO-21539900	GASKET KIT	1
		VO-20520607	SEALING RING KIT	6
		VO-990215	HOSE CLAMP	6
		VO-22338433	PIPE	1
		VO-21339891	HOSE,COOLANT	3
		VO-21052612	CONNECTOR	2
		VO-20940702	CONNECTOR	1
		VO-21052612	CONNECTOR	1
		VO-21843360	SEALING	2
		VO-21420336	CONNECTING PIPE	1
		VO-21849890	HOSE	1
		VO-21052612	CONNECTOR	1
		VO-20722710	HOSE CLAMP	2
		VO-21380391	CONNECTOR	1
		VO-21351717	INJECTOR SLEEVE	6
		VO-21780371	SEALING RING	1
		VO-20734156	SEALING STRIP	1
		AU2-CAL8394800	VOLVO VCS COOLANT	2
		AU2-CAL85108913	VOLVO VCS COOLANT 5 LITRE	1
		CU-CC2638	RESTORE PLUS	1
		LO-213	REPLACE LINER O RINGS	40
			INCLUDING	
		LO-261	REPLACE RADIATOR	9

PC	Type	Code	Description (Original)	#
	🔧		INCLUDING	
	🔧		-REMOVE CYLINDER HEAD	
	🔧		-SUMP, OIL PUMP, STIFFENING PLATE	
	🔧		-PISTONS & LINERS	
	🔧		-REPLACING PIPE BETWEEN CYLINDER HEAD A COOLANT PUMP	
🔧	🔧	LO-237	REPLACE INJECTOR TUBES	4
	🔧		LABOUR QUOTED TO DO WHILE CYLINDER HEAD OFF	
🔧	🔧	LO-260	REPLACE COOLANT HOSES	4
	🔧		INCLUDING	
	🔧		-GEARBOX COOLER HOSES Ö GEARBOX	
	🔧		-O RINGS ON PIPES INTO CYLINDER BLOCK	
	🔧		-COOLANT HOSES & O RINGS OUT OF CLINDER HEAD & BLOCK	
	🔧		-HEATER FITTING, CLAMPS & HOSES OUT OF CYLINDER BLOCK	
	🔧		-AIR COMPRESSOR COOLANT HOSES & CLAMPS	
	🔧		-FLUSH COOLING SYSTEM WITH RESTORE	
	🔧		-FILL WITH NEW COOLANT	
	🔧		-EXPANSION TANK	
	🔧		-ALL HOSES OUT OF EXPANSION TANK	
	🔧		-TOP & BOTTOM RAD HOSES	
	🔧		-TRANS COOLER LINES WHILE RAD OUT	
	🔧		-COOLANT PUMP WHILE RAD OUT	
	🔧		-HEATER HOSES, UNDER THE ENGINE & INTO THE CAB WHILE RAD	
	🔧		OUT	
🔧	🔧	VO-21103569	SEALING RING	1
🔧	🔧	VO-980464	STRIP CLAMP - CABLE TIE	25

PC	Type	Code	Description (Original)	#
		VO-948211	CABLE TIE	25
		VO-1161963	RUBBER GREASE	2
		VO-21924631	HOSE	1
		VO-1161277	LINER SEALANT	1
		VO-85103205	GREEN PAINT	1
		OTH-440381	S/BRITE DISC	3
		VO-20578851	D16C2 MAIN BRG SHELL	6
		VO-20578853	D16C2 MAIN BRG SHELL	1
		VO-21948268	THRUST WASHER KIT	1
		LO-216	BEARING ROLL	3.5
			Carry out bearing roll on vehicle as bearings have	
		VO-20586602	BIG-END BEARING KI	6
		VO-20563945	INTAKE MANIFOLD SEAL	1
		VO-955982	O-RING	6
		VO-20915849	HOSE CLAMP	6
		AU2-WUR0890117	BRKCLNR-(UNI-RAPID	3
		VO-994447	FLANGE SCREW	6
		VO-21015266	SCREW	6
		VO-944126	O-RING INJ HARNESS	1
		VO-20852765	GASKET	4
		VO-20775507	HEX. SOCKET SCREW	12
		VO-21344774	FLANGE SCREW	6
		VO-8192804	SCREW	8
		VO-983472	D12 LOOM TIE	8
		VO-1677370	VEB SEAL	2

PC	Type	Code	Description (Original)	#
		VO-8131393	CAGE	3
		VO-21099402	HOSE CLAMP	1
		VO-21707133	OIL FILTER	2
		VO-21707132	BYPASS OIL FILTER	1
			Inspect entire cooling system. Found coolant leaking from	
			side cover. Found seals breaking up and leaking.	
			Recommend replacing every coolant hose/o ring due to the	
			previous contamination.	
			Quote up parts	
			Includes time spent for call out	
			Removed injector tubes. Clean ports. Fit new injector	
			tubes to spec.	
			Drained coolant. Removed all hoses and pipes. Removed	
			Replace all coolant hoses. Secure with new clamps. Fit	
			Drained oil. Removed sump. Stiffing plate, oil pump and	
			Removed intake and exhaust assemblies. Removed rocker	
			header tank. Removed radiator assembly. Split	
			intercooler from radiator. Fit intercooler to new	
			radiator. Remove water pump. Flush	
			housing. Fit new seal. Remove heater hoses. Wash out	
			system. Reassemble and secure. Reassemble radiator	
			assembly into engine bay. Checked over. All	
			OK.	
			new header tank. Resecure all pipes and lines. Removed	
			and replaced compressor cooling lines. Removed and	

PC	Type	Code	Description (Original)	#
	Ⓜ		replaced gearbox oil cooler lines. Fill with	
	Ⓜ		fresh water. Drain water from cooling system. Fill with	
	Ⓜ		fresh water. Road test to flush system. Drain water.	
	Ⓜ		Fill with coolant flush. Road tested to flush. Drained	
	Ⓜ		system. Remove, clean and refit header tank. Refill with	
	Ⓜ		water. Road test to flush. Drain water. Fill with fresh	
	Ⓜ		coolant. Pressure tested. All OK. Ran engine. Checked	
	Ⓜ		over for leaks. All OK. Test drive and checked over.	
	Ⓜ		All OK.	
	Ⓜ		cover. Removed rocker gear, injectors and cam gear.	
	Ⓜ		Unbolt and lift out head and place on bench. Removed side	
	Ⓜ		cover. Inspect block. All OK. Removed pistons and	
	Ⓜ		liners. Clean all parts. Install new liner seals.	
	Ⓜ		Reinstall cylinder liners to spec. Install pistons to	
	Ⓜ		spec. Fit main coolant line from water pump to head.	
	Ⓜ		Refit cylinder head using new gasket to spec. Reassembled	
	Ⓜ		rocker gear, injectors etc. Torque to spec. Carry out	
	Ⓜ		top set to spec. Cleaned exhaust manifold. Paint	
	Ⓜ		surface. Refit exhaust manifold using new gaskets. Fit	
	Ⓜ		turbo using new base gasket. Fit cam gear with new bolts.	
	Ⓜ		Torque to spec. Set backlash to spec. Torque idler gear	
	Ⓜ		bolts. Refit top timing cover using new gasket. Refit	
	Ⓜ		rocker cover using new gasket. Refit intake manifold	
	Ⓜ		assemblies using new gaskets. Paint. Fit thermostat.	
	Ⓜ		Clean injectors. Fit new o-rings and washers.	

PC	Type	Code	Description (Original)	#
	🔍		2080	
	🔍		*** POSSIBLE POLICY CLAIM ***	
	🔍		excessive scoring	
🟢	*	94	WASTE DISPOSAL	
🟢	*	91	CONSUMABLES	
	🔍		oil lines. Carried out bearing roll to spec. Fit rings	
	🔍		and rods to pistons. Install to engine. Torque to spec.	
	🔍		Reassembled oil pump and oil lines. Refit stiffing plate.	
	🔍		Clean and refit sump to spec.	
🔍 2020-02-25 - Mileage: 385916 - Order nr: 2210107				
🟢	*	DEREK	DAY	
🟢	🔍	LO-260	COOLANT LEAKED DOWN RHS ENGINE	7
	🔍		- SOMETHING LIKE DIESEL IN THE HEADER TANK & O-RING ON CAP	
🟢	🔍	VO-21884469	FILLER CAP	1
🟢	🔍	AU2-CAL8394800	VOLVO VCS COOLANT	2
🟢	🔍	AU2-CAL85108913	VOLVO VCS COOLANT 5 LITRE	1
🟢	🔍	CU-CC2638	RESTORE PLUS	1
🟢	🔍	LO-194	TRAVELLING TIME	0.75
	🔍		Load Ute. Travel to site. Inspected. Found coolant	
	🔍		contaminated and has destroyed seal on header tank cap and	
	🔍		thermostat seal. Advised Customer accordingly. OK to	
	🔍		flush system and replace coolant. Drained coolant. Flush	
	🔍		out with restore. Test drive a couple of times to fully	
	🔍		flush. All OK. Removed and replaced thermostat seal and	
	🔍		cap. Fill with fresh coolant. Checked over. All OK.	

PC	Type	Code	Description (Original)	#
	🔧		Pack up and travel back to workshop.	
	🔧		Brant rd Kelmscott.	
	🔧		SWOLLEN - COOLANT HAS BEEN FLUSHED AND CAP REPLACED.	
🔍 2019-11-27 - Mileage: 361186 - Order nr: 2207998				
🟢	*	DEREK	KEW SHIFT: VOLVO WAITING	
🟢	🔧	LO-560	ABS FAULT ON DASH	2
	🔧		C100F01 POS 3 - FRNT RHS DRIVE - INSPECT AND QUOTE	
🟢	🔧	VO-6781769	SPLICE-RED(22-18)	2
🟢	🔧	VO-980464	STRIP CLAMP - CABLE TIE	15
	🔧		Connected lap top. Download and read DTCs. Found fault	
	🔧		with wheel sensor 3. Jacked up second steer axle.	
	🔧		Carried out wheel speed sensor test. Test failed.	
	🔧		Checked sensor resistance. All OK. Spin wheel and check	
	🔧		AC output. All OK. Checked continuity on harness from	
	🔧		EBS module and sensor. Found fault. Inspected	
	🔧		harness. Found broken wire. Wire corded through.	
	🔧		Repaired as required. Re tested. All OK. Test drive.	
	🔧		All OK. No further codes noted. Cleared codes.	
🔍 2019-11-25 - Mileage: 359842 - Order nr: 2207932				
🟢	*	DEREK	D KEW SHIFT:	
🟢	🔧	LO-214DERE	Valve adjustment fixed price package	3.5
🟢	🔧	VO-20736230	D16C R/C GKT	1
	🔧		Derek Murray	
	🔧		Removed intakes etc. Removed rocker cover. Carried out	
	🔧		top set to spec. Record all measurements. Refit rocker	















































PC	Type	Code	Description (Original)	#
			cover using new gasket and secure. Refit intakes etc.	
			Checked over. All OK.	
2019-10-30 - Mileage: 353124 - Order nr: 2207282				
	*	DEREK	D KEW SHIFT:	
	*	1706800	36 Months ECU download and oil sample.	
			Only valid for Australian market	
		VO-23448457	OIL SAMPLING KITX1	4
		LO-194	TRAVELLING TIME	0.75
			Brant rd Kelmscott	
			PLEASE FILL OUT THE COUPON	
			Melinda booked off site 36 month samples & downloads for	
			a date when the vehicle was outside its 36 month period	
			from delivery date - VGA advised would not pay claim.	
2019-08-16 - Mileage: 331142 - Order nr: 2204731				
	*	DEREK	D KEW SHIFT:	
		VO-2221300	Oil filter housing, replace	1.2
		VO-21497512	GASKET	1
		VO-22114765	OIL FILTER HOUSING	1
		LO-192	TRAVEL TIME	0.75
		VO-21940610	SEALING RING	1
		VO-21707133	OIL FILTER	2
		VO-21707132	BYPASS OIL FILTER	1
		VO-1820200	Localised wash for fault tracing	0.3
2019-06-30 - Mileage: 315803 - Order nr: 2204215				
	*	DEREK	D KEW SHIFT:	












































PC	Type	Code	Description (Original)	#
		LO-263	BELTS & TENSIONERS	1
			- REPLACE	
		VO-85003294	EXCH THERMO FAN	1
		VO-21503575	SEALING RING	1
		VO-8131154	SEALING RING	1
		VO-3979639	PRE HEAT GSK	2
		AU2-CAL85108913	VOLVO VCS COOLANT 5 LITRE	1
		VO-953053	FAN STUD	4
		VO-990950	M8 FLANGE LOCK NUT	4
		VO-22031832	FAN HUB	1
		VO-21454379	BELT TENSIONER	1
		VO-21631484	BELT TENSIONER	1
		VO-21753149	IDLER PULLEY	1
		VO-2630000	Fan, fan shroud and clutch. Secondary op	0.4
		VO-2630600	Thermostat fan, replace	2.9
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2632500	Engine cooling fan, test	0.2
			operation number	
			Inspected belts and tensioners. Found belt tensioners and	
			idler Puller noisy and notchy. Removed belts. Removed and	
			replaced idler and tensioners. Refit belts. Top up	
			coolant to spec. Ran engine. Checked over. All OK.	
			NEW SERIALÄ 6911	
			OLD SERIALÄ 3003201600168	
2019-06-25 - Mileage: 315002 - Order nr: 2204102				


















































PC	Type	Code	Description (Original)	#
	*	SHIFT	SHIFT : DAY CALL OUT	
			ENG HRS 5795 FUEL BURN 221573:	
		VO-2221300	Oil filter housing, replace	1.2
	*	92	TRAVEL	
	*	194	TRAVELLING TIME	
		VO-21497512	GASKET	1
		VO-21707133	OIL FILTER	2
		VO-21707132	BYPASS OIL FILTER	1
		VO-984734	M8*20 FL BOLT	2
		VO-20704747	WASHER LOCK-3/8:	2
		VO-20704998	WASHER	2
	*	170	CHANGE ENGINE OIL - AS NEW FILTERS	
	*	93	42 Ltrs Engine Oil	
	*	94	WASTE DISPOSAL	
			CONTACT PERSON :DAVID HAND	
			PHONE NUMBER :0419 944 955	
			Travel out to Customers yard to collect truck. Travelled	
			CHECK AND INSPECT OIL LEAKING SUSPECT	
			OIL LEAK COMING FROM OIL FILTER HOUSING	
		VO-1820200	Localised wash for fault tracing	0.3
			back to workshop. Washed down oil from engine. Test	
			drive. Checked for cause of oil leak. Found oil leaking	
			from oil filter housing gasket. Drained oil. Removed	
			filters. Removed oil filter housing. Cleaned. Removed	
			housing. Refit housing using new gasket. Fit new oil	

PC	Type	Code	Description (Original)	#
	📄		filters. Fill with fresh oil. Checked over. All OK.	
	📄		Take truck back to Customer's yard. Travelled back top	
	📄		workshop.	
	📄		Replaced missing bolts on boost pipe bracket.	
	📄		MAIN YARD : 40 BRANT ROAD, KELMSCOTT	
	📄		Travel out to Customers yard to collect truck. Travelled	
	📄		back to workshop. Return truck back to Customer's yard.	
	📄		Travelled back top workshop.	
🔍 2019-05-10 - Mileage: 300608 - Order nr: 2202792				
📄	*	DEREK	D KEW SHIFT: ENG HRS 5948	
	📄		BURN 210459	
📄	📄	VO-1706700	30 Months ECU download and oil sample. O	0.9
📄	📄	VO-8394887	OIL TEST KIT	4
🔍 2019-02-19 - Mileage: 269703 - Order nr: 2200949				
📄	📄	VO-3092340	SEALANT (GREY)	1
📄	📄	LO-194	TRAVEL TO SITE	0.75
	📄		Derek Murray	
📄	📄	VO-2141300	Valves and unit injectors, adjust	3.5
📄	*	92	TRAVEL 48 KM Ö Å1.50 CTS PER KM	
	📄		BRANT ROAD, KELMSCOTT	
	📄		Travelled out to site. Carried out valve adjustment as per	
	📄		REPAIR CARRIED OUT 19.02.19.	
	📄		specifications. Used sealant to seal back of rocker cover	
	📄		gasket as required. Travelled back to workshop.	
🔍 2018-10-09 - Mileage: 223440 - Order nr: 2198026				

PC	Type	Code	Description (Original)	#
		LO-371	INJECTOR HARNESS O'RING - RESEAL	2.12
		VO-2531400	Control cylinder exhaust brake, replace	0.6
		LO-645	POWER STEERING OIL LEAKS - RECTIFY	1.5
		VO-983472	D12 LOOM TIE	10
		VO-990211	FERRULE	4
		VO-984810	FITTING NUT	4
		VO-22889891	ACTUATOR SERVICE KIT	1
		VO-85122800	1L DEXRON3 ATF	3
		VO-1790600	Diagnostic with Tech Tool/GD. Connect-di	0.5
			Connect-disconnect of diagnostic tool included.	
		VO-2534000	Warm hold function, test	0.2
		VO-2533600	Engine brake function, test	0.4
			Inspect and found oil leaking from the injector harness.	
			Remove both power steering pipes, cut off nuts and clean	
		VO-20741911	O-RING	1
			Remove the cover, found the plug secure and leak from the	
			o'ring. R&R the injector harness o'ring with new. Refit	
			the cover. Wash down. Road test. No further leaks found.	
			pipes. Fit new nut and ferrule as required. Refit both	
			pipes. Fill with ATF. Wash down. Road test. All OK.	
		2018-09-25 - Mileage: 217621 - Order nr: 2197721		
			Campaigned De-Actioned - review Order job details	
		VO-1790600	Diagnostic with Tech Tool/GD. Connect-di	0.5
		VO-4132000	Clutch cylinder, replace. Gearbox remove	0.3
		VO-85013166	EXCH CYLINDER	1






































PC	Type	Code	Description (Original)	#
		VO-20992763	AIR HOSE	1
		VO-20483426	SEALING RING	1
		VO-20722721	AIR INLET	1
		VO-20860677	SEALING RING	1
		AU2-CAL85108913	VOLVO VCS COOLANT 5 LITRE	1
		VO-22901068	BOLT,PROPSHAFT	4
		VO-990971	NUT,PROPSHAFT	4
		VO-1706600	24 Months ECU download and oil sample. O	0.9
		VO-8100500	24 Months cab inspection	0.4
		VO-1774600	Annual service	2.6
		VO-983472	D12 LOOM TIE	5
		VO-8394887	OIL TEST KIT	4
		LO-263	FAN BELT TENSIONER & IDLER PULLEY	1
		VO-21631484	BELT TENSIONER	1
		VO-21753149	IDLER PULLEY	1
		VO-975197	M8*20 10.9 FL BOLT	1
			NEW UNIT SN: 666482000262 0618.	
			OLD UNIT SN: T154248.	
			No campaigns active in laptop when connected.	
			Connect-disconnect of diagnostic tool included.	
		VO-4317000	Gearbox, remove	1
		VO-4317200	Gearbox, install	1.6
		LO-481	Power take-off, remove	0.4
		LO-481	Power take-off, install	0.6
		VO-4007000	Clutch, gearbox, pulling position, calib	0.2

PC	Type	Code	Description (Original)	#
		VO-4136100	Air hose, replace. CVU/CCA	0.4
		LO-262	BOLT MISSING FROM THE HEADER TANK	0.1
			- FIT NEW.	
			- REPLACE.	
		VO-4313100	Sealing ring input shaft, replace. Gearb	0.3
			Gearbox removed.	
		VO-4001000	Clutch cylinder, test	0.2
		VO-4008300	PWM valves, clutch, test	0.2
		VO-4118200	PWM valves clutch, activation, test	0.2
			R&R the fan belt tensioner & idler pulley with new.	
			Fit new bolt and secure the header tank.	
  2018-05-05 - Mileage: 175876 - Order nr: 2193720				
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-8711300	CCM, SW Updating. Campaign only	0.2
		VO-2580000	Emissions after-treatment. Secondary ope	1
		OTH-AAB122ML-1/2PP-10	100 MESH FILTER 1/2" 122ML	1
		OTH-ADBLUE FILTER BRA	ADBLUE PICKUP FILTER BRACKET	1
		OTH-NOR-W3-10	STAINLESS STEEL HOSE CLAMP	2
		OTH-NYP60608	NYLON ELBOW	2
		VO-20744595	CONNECTOR	1
		VO-21032572	CLAMP,UREA HOSE	2
		VO-21429181	HOSE (urea)	1
		VO-3985511	CLAMP	1
		VO-984724	M6*12 FL BOLT	2

















































PC	Type	Code	Description (Original)	#
		VO-2520000	Silencer and exhaust pipe. Secondary ope	1.5
		VO-21969162	PIPE	1
		VO-991091	NIPPLE	1
		VO-21516229	FILTER	1
		VO-21954674	STRAINER	1
			CCM, SW UPDATE. FH/FM (4)	
		VO-2534000	Warm hold function, test	0.2
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2563000	Air filter housing, remove	0.1
		VO-2565100	Air filter housing, install	0.4
		VO-5617000	Compressor, remove	0.6
		VO-5617200	Compressor, install	0.7
		OTH-AB15	ADBLUE 15L	4
		VO-2585800	AdBlue tank, clean. Urea tank removed	0.5
		VO-2500600	Inlet and exhaust systems, check	0.2
		VO-2580400	AdBlue tank, remove	0.8
		VO-2580500	AdBlue tank, install	0.7
		VO-2584800	Strainer, replace. Pump unit	0.2
		VO-2582200	Filter, AdBlue, replace	0.2
		VO-2584600	SCR system, test	0.5
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		10	ADBLUE 15L x4	
		10	NYLON ELBOW x2	
		10	STAINLESS STEEL HOSE CLAMP x2	
		10	ADBLUE PICKUP FILTER BRACKET	










































PC	Type	Code	Description (Original)	#
	*	10	100 MESH FILTER 1/2" 122ML	
			AUTHORITY NUMBER: 200429611.	
W 2018-03-29 - Mileage: 160610 - Order nr: 2192881				
		VO-1706500	18 Months ECU download and oil sample. O	0.9
			Only valid for Australian market	
	*	92	TRAVEL 44 KM Ö Å1.10CTS PER KM	
			40 Brant Road Kelmscott	
		LO-192	TRAVEL TIME	1
		VO-8394887	OIL TEST KIT	4
W 2018-02-19 - Mileage: 149285 - Order nr: 2191741				
			AIRBAG MODULE, REPLACE. FH/FM (4)	
		VO-8842000	Airbag module, replace	0.3
		VO-22900843	ççAIRBAG MODULE, RAVEN	1
	*	92	TRAVEL 22 KM Ö Å1.10CTS PER KM	
			Travel to 40 BRANT ROAD, KELMSCOTT	
		LO-192	TRAVEL TIME	0.5
		LO-2140	CARRY OUT TOP SET RE-TENSION INJECTOR	3
			YOKES ON D13 & D16 ONLY	
		VO-20775507	HEX. SOCKET SCREW	12
		VO-20736230	D16C R/C GKT	1
			Carry out top set. Replace VEB bolts and rocker cover	
			gasket with new, Road test - all ok.	
			TAKE MEASUREMENTS BEFORE AND AFTER	
W 2017-09-15 - Mileage: 93632 - Order nr: 2187748				
	*	DEREK	D KEW SHIFT: WEEKEND	
































PC	Type	Code	Description (Original)	#
	📄		ENG HRS: 1674. FUEL BURN: 65114.	
🔧	🔧	VO-1774600	Annual service. Chassis lubrication and	2.6
🔧	🔧	VO-8100300	12 Months cab inspection	0.4
🔧	🔧	VO-1706400	12 Months ECU download and oil sample. O	0.9
🔧	🔧	VO-2580700	Pump unit, replace	0.8
📄	*	262	CUSTOMER REPORTS SQUEALING NOISE	
🔧	🔧	LO-810	RATTLING NOISE FROM BEHIND THE GRILLE	0.25
🔧	🔧	LO-810	LOOSE CHASSIS BOLT UNDER THE BATTERY/	0.1
	📄		FUSE BOX. CHECK AND REPORT.	
	📄		CHECK AND REPORT.	
🔧	🔧	VO-8394887	OIL TEST KIT	4
🔧	🔧	VO-2850800	Exhaust back pressure sensor, replace	0.2
📄	🔧	OTH-AB15	ADBLUE 15L	4
🔧	🔧	VO-22851845	PUMP UNIT	1
🔧	🔧	VO-22406383	KIT	1
🔧	🔧	VO-85139619	PRESSURE SENSOR	1
🔧	🔧	VO-21582423	PLUG KIT	1
🔧	🔧	VO-20915849	HOSE CLAMP	2
	📄		CONTACT PERSON: DAVID HAND	
	📄		CONTACT NUMBER: 0419 944 955	
	📄		oil changes included only in some models.	
	📄		NEW UNIT SN: 17-07-22 33301.	
🔧	🔧	VO-1701000	Connect-disconnect of diagnostic tool	0.2
🔧	🔧	VO-1701200	Fault codes, reading	0.2
🔧	🔧	VO-2584600	SCR system, test	0.5

PC	Type	Code	Description (Original)	#
		VO-2580300	AdBlue tank, replace	1.3
		VO-2585800	AdBlue tank, clean. Urea tank removed	0.5
		VO-2580000	Emissions after-treatment. Secondary ope	0.2
		VO-2582800	Combined tank unit, replace. AdBlue tank	0.2
			(includes filter, replace)	
		VO-1790600	Diagnostic with Tech Tool/GD. Connect-di	0.5
			Connect-disconnect of diagnostic tool included.	
		VO-1701200	Fault codes, reading	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-3711700	Connector, replace (1-8 cables)	0.3
		VO-1703700	Sensor and parameter values, monitoring	0.2
			AT IDLE. CHECK AND REPORT.	
			Check and found the centre section of the grille rattling.	
			Adjust the grille slightly. No longer rattling.	
			Tighten up 1x loose chassis bolt on the LHS side.	
		LO-260	HOSE CLAMP FOR SIDE COVER HOSE MISSING	0.25
			Fit new hose (coolant) clamps on the side cover.	
		LO-252	EXHAUST FLEX CLAMP RUBS ON ADBLUE HOSE	0.1
			Relocate the exhaust flex clamp so no longer rubbing.	
			Check the fan belt, tensioners and alternator belt - OK.	
			Monitor on road test - no squealing noise heard.	
	*	10	ADBLUE 15 LTS x4	
	*	91	CONSUMABLES	
		2017-07-25 - Mileage: 82369 - Order nr: 2186332		
	*	DEREK	D KEW SHIFT: DAY	

PC	Type	Code	Description (Original)	#
			CONTACT PERSON: DAVID HAND	
		VO-8400000	Outside trim parts, glass, sealing mould	0.5
		VO-3950800	Antenna, replace	1.2
		VO-22472979	ANTENNA	1
			CONTACT NUMBER: 0419 944 955	
		VO-8821100	Sun visor, replace	0.4
2017-04-28 - Mileage: 0 - Order nr: 2184241				
	*	1000	card not required	
2017-03-15 - Mileage: 44662 - Order nr: 2183135				
	*	DEREK	D KEW SHIFT:	
			CONTACT PERSON: DAVID HAND	
		VO-2530000	Exhaust brake, exhaust pressure governor	0.3
		VO-21887528	ACTUATOR SERVICE K	1
		MK-HS006	HOSECLAMP 11/22	1
			CONTACT NUMBER: 0419 944 955	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-2500600	Inlet and exhaust systems, check	0.2
		VO-2531400	Control cylinder exhaust brake, replace	0.6
		VO-2534000	Warm hold function, test	0.2
	*	10	HOSE CLAMP 11/22	
2017-03-04 - Mileage: 53368 - Order nr: 2183201				
	*	DEREK	D KEW SHIFT:	
			CONTACT PERSON: DAVID HAND	
		VO-2520000	Silencer and exhaust pipe. Secondary ope	1.5

PC	Type	Code	Description (Original)	#
		VO-21969162	PIPE	1
		VO-3816800	Instrument complete, replace	0.5
		VO-22222032	INSTRUMENT CLUSTER	1
		VO-1706300	6 Months ECU download and oil sample. On	0.9
		VO-2800800	EMS and ACM, sw , update. Only campaign	0.4
		VO-8394887	OIL TEST KIT	4
		VO-991091	NIPPLE	1
		VO-992081	HOSE CLAMP	2
		VO-471708	SEALING RING	1
		VO-992065	O-RING	1
		VO-980881	CABLE TIE	1
			CONTACT NUMBER: 0419 944 955	
			S0221 EMS and ACM, SW update. EU4/5. FH/FM (4)	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2534000	Warm hold function, test	0.2
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2563000	Air filter housing, remove	0.1
		VO-2565100	Air filter housing, install	0.4
		VO-5617000	Compressor, remove	0.6
		VO-5617200	Compressor, install	0.7
		VO-1709200	Replace control unit, programming	0.1
		VO-3710200	Electric wires and connections, check	0.4
		VO-3811700	Instrument, check	0.4
		2017-03-03 - Mileage: 41899 - Order nr: 2182878		
		DEREK	D KEW SHIFT:	




























PC	Type	Code	Description (Original)	#
			CONTACT PERSON: DAVID HAND	
		VO-2141300	Valves and unit injectors, adjust	1.7
		LO-3540800	Interior Lights, Cable Harness, Install	0.5
		VO-2502100	ACM, sw, update. only campaign	0.4
		VO-22935545	WIRES	7
		VO-23003426	FAN RING	1
		VO-990950	M8 FLANGE LOCK NUT	4
		VO-995680	HOSE CLAMP	1
		VO-993977	HOSE CLAMP	1
		VO-976162	SCREW	3
			CONTACT NUMBER: 0419 944 955	
		VO-2373200	Yoke, injector, check. Valve cover remov	0.4
			C3628 Cab, interior lights, cable harness, install. FH (4)	
			S0127 Fan ring, check/adjust. FH/FM (4)	
			AUTHORITY NUMBER: 200417344.	
		VO-2631800	Fan ring, replace	1.4
  2017-01-04 - Mileage: 24634 - Order nr: 2181320				
		SHIFT	SHIFT :DAY	
			CONTACT PERSON : DAVID	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
			S3609 TECU, SW update. AMT-F. FH/FM (4)	
			S3652 ACM, SW update. FH/FM (4)	
			CONTACT NUMBER : 0419 944 955	
		VO-2549400	ACM, SW, update. only campaign	0.2

PC	Type	Code	Description (Original)	#
		VO-4301400	TECU, sw, update. Only campaign	0.4
 2016-11-25 - Mileage: 10379 - Order nr: 2180395				
	*	SHIFT	SHIFT : DAY	
			ENG HRS: 187. FUEL BURN: 6903.	
		VO-1721000	Warranty service. After 4 weeks or maxim	1.9
		VO-FK18B	FILTER KIT	1
		VO-20779040	G/BOX OIL FILTER KIT	1
		OTH-85131754L	GEAR OIL SYNTH 1 LITER SHC50	17
		VO-949329	COPPER WASHER	4
		OTH-CAL85136280L	SYNTH DIFF OIL(97312)PER LITRE	40
			After 4 weeks or maximum 10 000 km.	
	*	94	WASTE DISPOSAL	
	*	93	42 LTS ENGINE OIL	
 2016-10-25 - Mileage: 39 - Order nr: 8724082				
			RE-RUN HYDRAULIC HOSES ON BOTH DEREK MURRAY TRUCKS	
	*	850	RE-RUN HYDRAULIC HOSES	
	*	80	SUBLET - RE-RUN HYDRAULIC HOSES	
 2016-10-17 - Mileage: 39 - Order nr: 8722442				
			Balistic Phone - TF100 inc High Gain A 1500.00	
	*	284	S&F BALLISTIC TF100 PHONE	
	*	20	SUBLET - S&F TF100 BALLISTIC PHONE	
			0812320kt	
 2016-10-17 - Mileage: 39 - Order nr: 8722432				
			7790NT04 Wheel Nut Indicators 8X4 161.00	
			SUPPLY AND FIT WHEEL NUT INDICATORS 8X4	

PC	Type	Code	Description (Original)	#
		LO-7790NT0	S&F WHEEL NUT INDICATORS 8X4	0.75
	*	91	CONSUMABLES	
		OTH-DTLRY33	WHEEL INDICATORS LONG REACH	80
2016-10-14 - Mileage: 39 - Order nr: 8722428				
			Evap Air Con Mochila Delta 4000.00	
	*	850	S&F EVAP AIR CONDITIONER MOCHILA	
	*	80	S&F EVAP AIR CONDITIONER MODCHILA	
			0812315kt	
2016-10-13 - Mileage: 39 - Order nr: 8723933				
			60100 C/O WHEEL ALIGNMENT CHECK MACK/VOLVO 280.00	
	*	6010000	Wheel alignment	
	*	60	SUBLET - C/O WHEEL ALIGNMENT	
			0812778kt	
			part no: 21607575	
			cc reference: 200411787	
2016-10-13 - Mileage: 39 - Order nr: 8722451				
			9016NT01 S&F MUDFLAPS TO FRONT BULLBAR - VOLVO 317.42	

			THIS WAS NOT DONE	
2016-10-12 - Mileage: 39 - Order nr: 8723896				
			890 CHANGE TURN TABLE PLATE AND FEET 500.00	
		LO-890	CHANGE TURN TABLE PLATE AND FEET	4
		UNK-CS54581	BASE PLATE AND FOOT ASSEMBLY	1
2016-10-10 - Mileage: 1 - Order nr: 8722448				
			1111NT01 PRE DELIVERY INSPECTION 735.00	

PC	Type	Code	Description (Original)	#
		LO-1111NT0	PRE - DELIVERY INSPECTION VOLVO	7
2016-10-06 - Mileage: 39 - Order nr: 8722444				
			S & F clearance lights 404.00	
		LO-353	S&F CLEARANCE LIGHTS TO REAR	3
		OTH-DT2-2	2 CIRC DEUTSCH	1
		91	CONSUMABLES	
2016-10-05 - Mileage: 39 - Order nr: 8723869				
			93 FUEL 07/10/2016 243.94	
		93	FUEL	
			07/10/2016	
			200.11 litres	
2016-09-27 - Mileage: 39 - Order nr: 8722440				
			6 " Exhaust Stack Return old one to Dave (AKA driver)350.00	
		LO-250	S&F 6" EXHAUST STACK	1
		OTH-CRSP6560	EXHAUST STACK CURVED REDUCED	1
		OTH-FBC600C	EXHAUST CLAMP 6" CHROME	1
		91	CONSUMABLES	
2016-09-20 - Mileage: 39 - Order nr: 8723501				
		VO-2520000	Silencer and exhaust pipe. Secondary ope	1
		VO-8842300	MID 232 SID 1 Driver air bag ignition lo	0.6
		VO-3110000	Battery, energy storage system. Secondar	1
		VO-2586200	SCR catalytic muffler, replace	1.3
		VO-8100000	Body and cab framework, general	0.5
			Power Divider Cylinder Option	
		VO-3660000	Automatic monitoring and control. Second	2






































PC	Type	Code	Description (Original)	#
			Fit camera bracket 82809782 to RH & 82809776 to LH	
			Argus case 1-3632963331	
			Apply Silastic to hole in plastic cover at rear cab channel	
			Fit a longer cable with a straight lug, not 90 degrees	
			Fit full length cover to the driver's side air bag	
			Argus case 1-4293139157	
		VO-3110000	Battery, energy storage system. Secondar	0.25
			Fit label to battery area	
		VO-3730000	Cable system, front. Secondary operation	3
			Reposition directly under the connectors & run under chassis	
			Power Divider autofunction	
			D16G Vertical muffler Welding	
			Cab mudguard with storage locker, without air kit	
			Cab mudguard without storage locker without air kit	
			Cab mudguard without storage locker with air kit	
			Cab mudguard with storage locker with air kit	
			Drivers mirror blows in	
			FE Transmission Cover	
			Dust entering cab	
			Check for all outstanding campaigns	
			Battery earth cable can break at chassis	
			Trans coolant hoses coming off at engine block	
			Relay & trailer valves relocate	
			Jackshaft univeral joints can fail on Tri-Drive	
			Dust getting into side mount 90L adblue tank	















































PC	Type	Code	Description (Original)	#
	🔍		Cab rear air bags leak due ot heat	
	🔍		Oil residue can get into diff breather hoses	
	🔍		Steering pipes can come off under steering box	
	🔍		Door seals adrift	
	🔍		Starter Motor failing prematurely	
	🔍		Battery label advising how to jump start trucks	
	🔍		Check parameters for suspension	
	🔍		Check the parameters in VDA+ suspension	
	🔍		FE Side bin lift overheat front wheel bearings	
	🔍		EBA wiring getting squashed under load	
	🔍		*****	
📌	🔍	VO-82809782	BRACKET	1
📌	🔍	VO-82809776	BRACKET	1
📌	🔍	VO-984733	FLANGE SCREW	10
📌	🔍	OTH-F114	AIR BAG COVER	1
📌	🔍	OTH-57141	LUG 70-10	1
📌	*	30	LUG 70-10	
	🔍		Argus case 1-5939500866	
	🔍		part no: 21556424	
	🔍		- R&R and weld muffler as per AS 25 209/PSI 5101	
	🔍		part no: 21395509	
	🔍		part no: 22287351	
	🔍		Argus case 1-4020601431	
	🔍		cc referene: 200411898	
📌	*	91	CONSUMABLES	

PC	Type	Code	Description (Original)	#
2016-09-20 - Mileage: 39 - Order nr: 8722441				
	☒		Short Tail Suzi Coils in Lieu of Long 100.00	
📄	🕒	LO-890	S&F SHORT SUZI COILS	0.57
📄	📏	MK-ABC78020	SUZI COIL	1
📄	*	91	CONSUMABLES	
2016-09-19 - Mileage: 22 - Order nr: 8722445				
	☒		9116NT01 Walk Plate Alloy Checker to Front of T 866.00	
📄	🕒	LO-9116NT0	S&F ALLOY CHECKER PLATE TO CHASSIS	2.5
📄	*	91	CONSUMABLES	
📄	📏	OTH-61104	36MM SURAF0AM	4
📄	📏	OTH-E3L1BP9R	COMP LATCH	2
📄	📏	OTH-E3K9R	COMP/KEY 9MM ROUND	1
📄	📏	OTH-KPCHSSISPLT	CHASSIS PLATE 2200X820	1
2016-09-15 - Mileage: 1 - Order nr: 8722450				
	☒		3520NT02 WIRE UP BULLBAR INDICATORS_FH4 534.40	
📄	🕒	LO-3520NT0	WIRE UP BULLBAR INDICATORS_FH4/FM	4.5
📄	📏	OTH-QNC12	NYLON CONDUIT 12MM	0.5
📄	📏	OTH-12M16	ADAPT BODY KIT	1
📄	📏	OTH-5823TW	TWIN CORE CABLE	15
📄	📏	VO-948211	STRIP CLAMP	30
📄	📏	OTH-56707	CONV TUBE 7MM	10
📄	*	91	CONSUMABLES	
📄	📏	OTH-FHO-N54412	FUSE HOLDER MINI IN LINE BLADE	2
2016-09-13 - Mileage: 39 - Order nr: 8722433				
	☒		2340NT02 Powder Coat Two Fuel Tanks 1630.00	

PC	Type	Code	Description (Original)	#
	🔍		Tanks same as Bull Bar Powercoating 1.00	
	🔍		POWDER COAT COLOUR SLIVER GLOW PEARL	
	🔍		R & R TANKS & POWDERCOATING	
📌	🔍	LO-2340NT0	R&R POWDERCOAT TWO FUEL TANKS	6
	🔍		R & R TANKS & POWDERCOATING	
📌	*	SKY1	POWDER COAT FUEL TANK SUBLET POWDER COAT	
	🔍		FUEL TANK	
	🔍		0812316kt	
	🔍		SUBLET POWDER COAT FUEL TANK	
🔍 2016-09-12 - Mileage: 22 - Order nr: 8722431				
	🔍		8310NT04 Weather Shields FH 350.00	
📌	🔍	LO-8310NT0	S&F WEATHERSHIELDS_FH4	1
📌	🔍	VO-84165756	WIND DEFLECTOR KIT	1
📌	*	91	CONSUMABLES	
🔍 2016-09-12 - Mileage: 22 - Order nr: 8722430				
	🔍		3930NT03 UHF Electraphone TX4500WS Remote Mount 930.00	
📌	🔍	LO-3930NT0	S&F GME TX4500W UHF RADIO SUIT_FH4	3
📌	🔍	MK-9771-TX4500WS	UHF RADIO WIRELESS GME	1
📌	🔍	OTH-COM-LEM6P	HAND MICROPHONE EXTENSION LEAD	1
📌	🔍	VO-21138398	HOUSING	1
📌	🔍	VO-20798809	CABLE TERMINAL	2
📌	*	91	CONSUMABLES	
📌	🔍	VO-948211	STRIP CLAMP	30
🔍 2016-09-12 - Mileage: 22 - Order nr: 8722429				
	🔍		8500NT04 Cab Gun Blower 80.00	

PC	Type	Code	Description (Original)	#
		LO-8500NT0	S&F CAB GUN BLOWER	0.5
		MK-9732-BG12	DUST BLOWER	1
		91	CONSUMABLES	
2016-09-12 - Mileage: 1 - Order nr: 8722446				
			8550NT04 Dash mat - Volvo FH/FM 158.00	
		LO-8550NT0	S&F DASH MAT_FH4	0.3
		OTH-DAMAT-FH4	DASH MAT VOLVO FH(4)	1
2016-09-12 - Mileage: 1 - Order nr: 8722436				
			Spotlights 2 x Lightforce HID - CANCELLED 0.00	
			Substitute Lightforce LED ilo HID	
			Delete Orange Spotlight covers 1.00	
			S&F 2 X LIGHTFORCE LED SPOTLIGHTS	
		LO-350	S&F 2 X LIGHTFORCE LED SPOTLIGHTS	4
		OTH-CBLED215S	LED SPOT LIGHT 215MM 108W SNGL	1
		OTH-CBLED215SD	LED DRIVE LIGHT 215MM 108W SGL	1
		OTH-5823TW	TWIN CORE CABLE	20
		OTH-56707	CONV TUBE 7MM	10
		VO-21244697	RELAY	1
		VO-25392050	RELAY RETAINER	1
		VO-979002	TERMINAL	5
		VO-990060	CABLE TERMINAL	1
		91	CONSUMABLES	
2016-09-10 - Mileage: 39 - Order nr: 8723500				
		VO-3520000	Lighting, front. Secondary operation num	4
			- Carry out glueing procedure as per GB	


















































PC	Type	Code	Description (Original)	#
	*	30	SUBLET - SUPPLY OF GLUE	
		VO-8300000	Doors and lids, general	0.25
			- Glue in 4 rubber stops	
			argus case 1-3597953021	
			Drivers door rubber stops	
			Bunk hinge mod	
			Headlight panels	
			Argus case 1-2756213791	
			part no: 21874457	
			cc reference: 200410638	
	*	91	CONSUMABLES	
	2016-09-10 - Mileage: 22 - Order nr: 8722438			
			3111NT01 Light VisionX LED Mirror Mounted Loadi 970.00	
		LO-3111NT0	S&F LED VISION X MIRROR LIGHTS	5
	*	91	CONSUMABLES	
		OTH-5823TW	TWIN CORE CABLE	10
		OTH-56707	CONV TUBE 7MM	10
		VO-948211	STRIP CLAMP	30
		OTH-WL-10WRS	LED 10W MIRROR LIGHTS ROUND	2
		VO-979002	TERMINAL	5
		VO-990060	CABLE TERMINAL	1
		VO-21244697	RELAY	1
		VO-25392050	RELAY RETAINER	1
		VO-978304	CABLE TERMINAL	1
		OTH-22207188A	SWITCH COVER	1













































PC	Type	Code	Description (Original)	#
 2016-09-10 - Mileage: 22 - Order nr: 8722437				
			9019NT04 Yard Hitch with Single Air Line to Rea 1290.00	
		LO-9019NT0	S&F YARD HITCH SINGLE AIR LINE_FH4	4.5
		91	CONSUMABLES	
		VO-945884	NUT,M16	4
		VO-980464	STRIP CLAMP	100
		OTH-38B	3/8 BSP SOCKET	1
		OTH-ABF215	COUPLING 3/8F	1
		VO-984834	FLANGE SCREW	4
		VO-994693	NIPPLE	1
		OTH-VB010	BALL VALVE 3/8 BLUE HANDLE	1
		OTH-MZ16HTW	WASHER 16mm HIGH/T ZINC	4
		MK-FT3325X6	BRASS PIPE	1
		OTH-YHBP1	YARD HITCH BACK PLATE SINGLE	1
		VO-980833	12MM AIR LINE	15
		VO-991083	SWIVEL	1
		VO-991075	NIPPLE	2
		VO-991980	T NIPPLE	1
		VO-984853	FLANGE SCREW	4
		VO-992328	FLANGE NUT	4
		AU2-9703- ROCKINGER805	NON-AUTOMATIC TRAI	1
		VO-20428158	CABLE TIE	2
 2016-09-09 - Mileage: 22 - Order nr: 8722449				
			1021NT02 UNLOAD SINGLE NEW TRUCK WITH AIR KIT 577.50	
		LO-1021NT0	UNLOAD SINGLE NEW TRUCK WITH AIR KIT	2.5

PC	Type	Code	Description (Original)	#
		LO-891AK	FIT AIR KIT ALL VOLVOS	3
2016-09-07 - Mileage: 1 - Order nr: 8723568				
			93 FUEL 09/09/2016 119.92	
	*	93	FUEL	
			09/09/2016	
			100.02 litres	
2016-09-07 - Mileage: 1 - Order nr: 8722435				
			9012NT01 Seat Covers Volvo Cloth 655.00	
		LO-9012NT0	S&F VOLVO CLOTH SEAT COVERS (NEW)	0.6
		VO-21579059	SEAT COVER	1
		VO-21579627	SEAT COVER	1
	*	91	CONSUMABLES	
2016-08-19 - Mileage: 22 - Order nr: 8722439				
			Teflon Wear Plate , Predrilled Ö 100mm 1.00	
		LO-9002NT0	S&F KHITCH FIXED TURNTABLE 3.5" TEFLON	4
		OTH-MZ1655G8B	BOLT 16X55 ZINC PLATE 8.8	12
		OTH-MZ16HTW	WASHER 16mm HIGH/T ZINC	24
		OTH-MZ16NYL	NYLOC NUT 16mm ZINC PLATED	12
	*	91	CONSUMABLES	
	*	900KH8	SUPPLY KHITCH FIXED 3.5" TEFLON TURNTABL	
			0812319kt	
			9002NT08 S&F KHITCH FIXED TURNTABLE 3.5" TEFLON 2749.65	
			Turntable height to be 1275mm approx	
			mount 200mm nehind centre of 1st drive	
			Pre drill for T/T movement to 100mm back & forward	

PC	Type	Code	Description (Original)	#
	📄		serial number for turntable: MK-18130	
🔍 2016-08-02 - Mileage: 39 - Order nr: 8722447				
	📄		1212NT01 C/O PITS, REGO & LICENCE 1000.00	
	📄		PITS, REGO & LICENCE	
📌	📄	LO-1212NT0	C/O PITS, REGO & LICENCE	4
	📄		PITS, REGO & LICENCE	
📌	📄	OTH-85113349L	ADBLUE PER LITRE	60
📌	📄	80	SUBLET - VEHICLE MODIFICATION INSPECTION	
	📄		0812750kt	
🔍 2016-07-28 - Mileage: 39 - Order nr: 8722443				
	📄		Water Tank & Tool Box to 2nd Steer Axl 1000.00	
📌	📄	LO-891	S&F WATER TANK & TOOL BOX TO 2ND STEER	10
📌	📄	OTH-RJ23	VOIR 23LTR	1
📌	📄	VO-984729	FLANGE SCREW	4
📌	📄	VO-990949	FLANGE LOCK NUT	4
📌	📄	VO-994847	WASHER 6MM	4
📌	📄	VO-984863	FLANGE SCREW	6
📌	📄	OTH-TB029	TOOL BOX 600X400X500	1
📌	📄	VO-984736	FLANGE SCREW	4
📌	📄	VO-990950	FLANGE LOCK NUT	4
	📄		*****	
	📄		OVER ESTIMATE.	
	📄		TOOLBOX PACK IS Å1000.00	
	📄		WATER TANK PACK IS Å600.00	
	📄		TOTAL Å1600.00	

PC	Type	Code	Description (Original)	#
	🔒		*****	
📌	*	91	CONSUMABLES	
🔍 2016-07-27 - Mileage: 39 - Order nr: 8722434				
	🔒		9111NT02 Hydraulics Semi Tipper "I" shift with 12375.00	
	🔒		HYD HOSES TO BE 3 METERS LONG 2 X FEMA 1.00	
📌	🔒	LO-890	S&F HYDRAULIC SEMI TIPPER "I" SHIFT WITH	51
	🔒		DIVERTER VAVLE	
📌	*	80	SUBLET - C/O HYDRAULIC HOSE UP	
📌	*	80	SUBLET - SUPPLY HYDRAULIC PARTS	
	🔒		0812317kt	
	🔒		0812318kt	
📌	🔒	VO-984735	FLANGE SCREW	40
📌	🔒	VO-984741	FLANGE SCREW	14
📌	🔒	VO-994930	SIX POINT SOCKET S	8
📌	🔒	VO-990861	FLANGE SCREW	60
📌	🔒	OTH-TP2	BRACKET VOLVO REAR DOUBLE AIR	1
📌	🔒	OTH-03193202	1/2"BSP BLACK SOCKET	2
📌	*	80	SUBLET - SUPPLY STEEL	
	🔒		ACDC order CS-53064kt	
📌	🔒	OTH-R-TRAIN-BLACK	ROADTRAIN Å COVER BLACK	1
📌	🔒	UNK-CS53101	PAINT	1
	🔒		REF INV: 316212 - GLOBAL	
📌	🔒	VO-1629141	CONTROL STICKER	1
📌	🔒	VO-1629142	SUPPLY STICKER	1
📌	🔒	MK-ABCABF198	COUPLING, MALE 1/2	1

PC	Type	Code	Description (Original)	#
		MK-ABCABF201	ADAPTOR, MALE 3/8	1
		OTH-Z1868X4X4ZZ	CHECK VALVE	1
		OTH-230808	3/8"BSP*1/2"BSP ADAPTOR	2
		VO-980464	STRIP CLAMP	100
		VO-1629141	CONTROL STICKER	1
		VO-1629142	SUPPLY STICKER	1
		VO-8039588	WARNING	1
		VO-994862	WASHER 10MM	8
		VO-994848	WASHER	4
		VO-984744	FLANGE SCREW	3
		VO-990950	FLANGE LOCK NUT	3
		VO-969324	VIP M12-9	1
		VO-976445	VIPS 8-9	1
		VO-976958	ELBOW NIPPLE	1
		MK-ABCABT6	TUBE NYLON 3/8: BL	3
		OTH-AL14X100MX4	4 CORE 1/4" RED/BK/BL/WHT	10
		VO-994441	FLANGE SCREW	2
		VO-990950	FLANGE LOCK NUT	2
		OTH-5873TC	3MM 7 CORE CABLE	4
		OTH-QNC16	NYLON CONDUIT	3
		MK-NARV56614	HEATSHRINK 1=1.2M	1
		VO-948211	STRIP CLAMP	30
		VO-980464	STRIP CLAMP	50
		VO-969324	VIP M12-9	1
		VO-976958	ELBOW NIPPLE	1

PC	Type	Code	Description (Original)	#
		VO-976445	VIPS 8-9	1
		MK-ABCABT6	TUBE NYLON 3/8: BL	2
		OTH-AL14X100MX4	4 CORE 1/4" RED/BK/BL/WHT	4
		VO-984740	FLANGE SCREW	2
		VO-990950	FLANGE LOCK NUT	2
		VO-990060	CABLE TERMINAL	2
		VO-20375162	CABLE TERMINAL	3
		VO-978304	CABLE TERMINAL	2
		OTH-31095610	1/4X1/8 BSP MALE ELBOW	4
		VO-21500715	SWITCH AUX 3	1
		VO-21500718	SWITCH AUX4	1
		OTH-22207188A	SWITCH COVER	3
		VO-21244697	RELAY	3
		VO-25392050	RELAY RETAINER	3
		VO-984849	HOUSING	2
		VO-3944972	HOUSING	1
		VO-979002	TERMINAL	12
		VO-990060	CABLE TERMINAL	1
		VO-978304	CABLE TERMINAL	1
		VO-984847	CABLE TERMINAL	8
		VO-3963046	CABLE TERMINAL	4
		91	CONSUMABLES	