













































Vehicle Service Records (VSR Explorer)






































Repair history D-203778

Registration nr: 1EWU298 **Chassis nr:** D-203778 **VIN nr:** YV5RP80G1GD203778
Market type: FH16A84T **Country:** AUS **Delivery date:** 2016-10-27


































PC	Type	Code	Description (Original)	#
2023-11-22 - Mileage: 838192 - Order nr: 2242773				
	*	SHIFT	EVENING	
	🔧	LO-214	CARRY OUT TOPSET	3.5
	📄		Removed intakes etc. Removed rocker cover. Carried out	
	📄		top set to spec. Record all measurements. Refit rocker	
	📄		cover. Refit intakes etc. Road tested. Checked over.	
	📄		All OK.	
2023-10-03 - Mileage: 0 - Order nr: 2241448				
	*	CARD	NOT REQUIRED	
2023-06-12 - Mileage: 805583 - Order nr: 2238315				
	*	SHIFT	EVENING - 12/06/2023.	
	🔧	LO-818	CAB TILT HOSE REPLACEMENT	3.15
	📄		- HOSE FAILED/BLOWN.	
	🔧	VO-22562965	HOSE KIT	1
	📄		Block off the blown hose and tilt the cab for access.	
	📄		Replace failed hose, pump to rear cab lock. Wash off oil	
	📄		leakage around the the cab hoses and pump area. All OK.	
2023-05-09 - Mileage: 797874 - Order nr: 2237512				
	*	SHIFT	DAY - 09/05/2023.	

PC	Type	Code	Description (Original)	#
		LO-250	REPORTS BOOST LEAKS / DOWN ON POWER	1.5
			Connect laptop and read fault codes. Road test and monitor	
			sensor values - confirm low and boost and hear leak.	
			Remove inlet air pipes from turbo. Carry out boost test -	
			hosing out from turbo clamp. Remove turbo cam housing.	
			Inspect and found o'ring split. Source o'ring and fit.	
			Reassemble. No further boost leaks. Road test and monitor	
			sensor values again - no boosting to 195 KPA. All OK.	
  2023-03-27 - Mileage: 787281 - Order nr: 2236411				
		LO-211	REPLACE CYLINDER HEAD WITH NEW	5.45
			DONE	
		VO-24121331	CYL HEAD 16L	0.5
		VO-1161963	RUBBER GREASE	1
		VO-1547252	SEALING RING	2
		VO-1677370	VEB SEAL	2
		VO-20526428	VEB SEAL	1
		VO-20563945	INTAKE MANIFOLD SEAL	0.5
		VO-20736230	D16C R/C GKT	0.5
		VO-20784537	GASKET	1
		VO-20799996	SEALING RING	1
		VO-20815558	SEALING STRIP	1
		VO-20852765	GASKET	4
		VO-21015266	SCREW	6
		VO-21185132	SEALING	2
		VO-21344774	FLANGE SCREW	6

PC	Type	Code	Description (Original)	#
		VO-21352841	GASKET	3
		VO-21420336	CONNECTING PIPE	1
		VO-21423788	SEALING RING	1
		VO-21503575	SEALING RING	1
		VO-21575727	HEAD GASKET	0.5
		VO-21940615	SEALING RING	1
		VO-22206133	GASKET	1
		VO-276948	D12 INJ/SEAL KIT	3
		VO-3092340	SEALANT (GREY)	1
		VO-3979639	PRE HEAT GSK	2
		VO-420643	TURBO DRAIN GASKET	1
		VO-469601	TURBO DRAIN SEAL	1
		VO-471708	SEALING RING	1
		VO-8131154	SEALING RING	1
		VO-8131393	CAGE	6
		VO-8148729	CONNECTOR	1
		VO-8192804	SCREW	8
		VO-944126	O-RING INJ HARNESS	1
		VO-983472	D12 LOOM TIE	8
		VO-990950	M8 FLANGE LOCK NUT	1
		VO-993811	FLANGE SCREW	4
		VO-994447	FLANGE SCREW	6
		VO-20592783	CLAMP	1
		VO-984732	M8*12 FL BOLT	1
		VO-984733	M8*15 FL BOLT	1

PC	Type	Code	Description (Original)	#
		AU2-AMP24078864	VO VCS-2 COOLANT 20L, PER L	20
		LO-250	INVESTIGAGE LACK OF BOOST - FOUND ON	2.5
		VO-2110000	Cylinder head. Secondary operation numbe	5.45
		LO-211	CARRY OUT DIAGNOSIS ON ENGINE RUNNING	9.5
			ROUGH, LOSS OF POWER	
		VO-24121331	CYL HEAD 16L	0.5
		VO-20563945	INTAKE MANIFOLD SEAL	0.5
		VO-20736230	D16C R/C GKT	0.5
		VO-21575727	HEAD GASKET	0.5
		VO-21352841	GASKET	3
		VO-276948	D12 INJ/SEAL KIT	3
			ROAD TEST AFTER CYLINDER HEAD REPLACED	
			Connected laptop, checked error codes. Removed, inspected	
			& cleaned boost pressure sensor. Refit & road tested -	
			still lacking boost/power.	
			Fit pressure testing equipment to vehicle, tested & found	
			intercooler leaking.	
			Advised Neil who said he would rectify himself.	
		94	WASTE DISPOSAL	
		91	CONSUMABLES	
			Brought vehicle in to workshop, performed diagnostics.	
			Connected Tech Tool. Downloaded error codes & performed	
			compression test - low on cylinders 2 & 4.	
			Removed rocker cover, inspected valves - found stem seal	
			damage on no. 1 exhaust valve.	

PC	Type	Code	Description (Original)	#
	🔧		Removed rocker shaft & injectors individually, fit testing	
	🔧		tool & pressurised each cylinder - found leaking in to	
	🔧		intake manifold from cylinder 2.	
	🔧		Drained cooling system, removed all attachments from cyl	
	🔧		head. Removed head & placed on bench. Carried out further	
	🔧		inspection & confirmed no. 2 & 4 valves not seating.	
	🔧		Cleaned block, installed new gasket. Cleaned & transfered	
	🔧		all required parts over to new cyl head.	
	🔧		Fit & torqued head to spec. Fit & torqued rocker shaft,	
	🔧		completed valve adjustment & recorded all measurements.	
	🔧		Refit all remaining attachments, covers etc. & filled	
	🔧		cooling system.	
	🔧		Washed engine, ran up & road tested vehicle - all ok.	
	🔧		- ROAD TEST TO CONFIRM ISSUE	
	🔧		- CONNECT LAPTOP, DOWNLOAD ERROR CODES	
	🔧		- PERFORM COMPRESSION TEST	
	🔧		- REMOVE ROCKER COVER, VISUALLY INSPECT, MEASURE ALL	
	🔧		VALVES.	
	🔧		- REMOVE ALL ATTACHMENTS FROM CYLINDER HEAD, RMEOVE HEAD	
	🔧		AND PLACE ON BENCH FOR FULL INSPECTION.	
	🔧		NEW SERIAL#230442215	
🔍 2023-02-21 - Mileage: 779514 - Order nr: 2235446				
🟢	*	SHIFT	DAY	
🟡	*	360	INSPECT & ADVISE DIFF LOCK & POWER	
	🔧		DIVIDER NOT WORKING. SOLINOID NOT WORKING.	

PC	Type	Code	Description (Original)	#
	*	430	CHANGE EBS STATIC ROLLOVER SET TOO LOW	
			WHEN GOING AROUND A ROUND ABOUT, TRUCK SLAMS ON BRAKES	
			Connected lap top. Download and read DTCs. No related	
			codes logged. Removed tread plate for access to	
			solenoids. Test feeds. Found both have earth but no power	
			feed. Test switch. All OK. Unbolt rear modulator to	
			access RCIOM. Pin our wiring. All OK and was able to	
			power up from module and would operate. RCIOM not powering	
			up solenoids. Checked parameters. No parameters. Update	
			all modules to test software. Still will not function.	
			Raise Argus as possible software in RCIOM at fault (module	
			was replaced last visit). Run accessory kit as advised in	
			Argus reply. Re tested power divider and diff lock. Now	
			operational. Refit RCIOM. Re secure wiring. Refit rear	
			modulator and tread plate. Cleared DTCs. Road tested and	
			re test operation. All OK.	
 2022-12-22 - Mileage: 771558 - Order nr: 2234079				
		LO-451	JACKSHAFT FAILURE	6
		LO-451	JACKSHAFT - REPLACE	20
		VO-22244623	PROPELLER SHAFT	1
		VO-995906	HEXAGON SCREW	8
		VO-984050	M14 HEX NUT	8
		VO-85104619	BEARING	2
		VO-1673393	NUT RT2610HV	1
		VO-20801083	THRU/SHAFT FLANGE 2370A	1

PC	Type	Code	Description (Original)	#
B	■	VO-20366534	NUT	1
B	■	VO-22058737	AIR SPRING	1
B	⚙	LO-370	CHASSIS HARNESS & WIRING REPAIRS	5.5
B	■	VO-21546699	WIRES	1
B	■	VO-22225554	MODULATOR	1
B	■	VO-980833	PLASTIC PIPE 12MM	4
B	■	VO-22160659	BRACKET	1
B	■	VO-991084	SWIVEL FITTING	1
B	■	VO-992021	X-NIPPLE	1
B	■	VO-991075	NIPPLE	8
B	■	VO-991968	SWIVEL FITTING	1
B	■	VO-21999965	COVER	1
B	■	VO-23637085	WHEEL SPEED SENSOR	1
B	■	VO-23637090	WHEEL SPEED SENSOR	1
B	■	VO-23637089	WHEEL SPEED SENSOR	1
B	■	VO-23740261	SENSOR	1
B	■	VO-23740262	SENSOR	1
B	■	OTH-F	FREIGHT	1.5
	⊞		- INCLUDING TIME TO REPLACE DAMAGED COMPONENTS.	
B	■	VO-23224803	WIRES	1
B	■	VO-991084	SWIVEL FITTING	3
B	■	VO-992247	SWIVEL	1
B	■	VO-991073	NIPPLE	1
B	■	VO-993859	ELBOW NIPPLE	2
B	■	VO-991984	SWIVEL RING	1































PC	Type	Code	Description (Original)	#
Ⓟ	■	VO-991972	NIPPLE	1
Ⓟ	■	VO-992026	ELBOW NIPPLE	1
Ⓟ	■	VO-992025	ELBOW NIPPLE	1
Ⓟ	■	VO-991980	T NIPPLE	1
Ⓟ	■	VO-992023	TEST NIPPLE	1
Ⓟ	■	VO-992271	NIPPLE	1
Ⓟ	■	VO-992026	ELBOW NIPPLE	1
Ⓟ	■	VO-991073	NIPPLE	1
Ⓟ	■	VO-994000	ELBOW NIPPLE	1
Ⓟ	■	VO-21445337	MANIFOLD	1
Ⓟ	■	OTH-F	FREIGHT	1.5
Ⓟ	■	VO-23637084	WHEEL SPEED SENSOR	1
Ⓟ	■	VO-980834	PLASTIC PIPE 16MM	2
Ⓟ	■	VO-980832	PLASTIC PIPE 8MM	8
Ⓟ	■	VO-992021	X-NIPPLE	1
Ⓟ	■	VO-991075	NIPPLE	1
Ⓟ	■	VO-991074	NIPPLE	1
Ⓟ	■	VO-991083	SWIVEL	1
Ⓟ	■	VO-992304	PIPE RETAINER 12mm	3
Ⓟ	■	VO-21556424	WIRES	1
Ⓟ	■	OTH-F	FREIGHT	2
Ⓟ	■	VO-22771641	CONTROL UNIT	1
Ⓟ	■	VO-22771636	CONTROL UNIT	1
Ⓟ	■	VO-20706811	COMPANION FLANGE	1
Ⓟ	■	OTH-F	FREIGHT	5

PC	Type	Code	Description (Original)	#
Ⓟ	■	VO-6781769	SPLICE-RED(22-18)	10
Ⓟ	■	MK-FT1162X12M	BRASS PUSH-CONNECT	1
Ⓟ	■	VO-991981	T NIPPLE	1
Ⓟ	■	VO-993363	HOUSING	1
Ⓟ	■	AU2-AMP23068346	VO ENG OIL VDS4.5 BULK PER LT	6
Ⓟ	■	AU2-AMP23068346	VO ENG OIL VDS4.5 BULK PER LT	3.4
Ⓟ	Ⓞ	LO-311	BATTERIES - REPLACE	1
Ⓟ	■	AU2-23446985	BATTERY N200	2
	📄		SN:1645149	
	📄		SN:16251182	
Ⓟ	Ⓞ	LO-560	ABS VALVE & AIRLINE REPAIRS	3
	📄		- NOTE: ADDITIONAL TIME TAKEN AS RUN NEW LENGTHS OF	
Ⓟ	Ⓞ	LO-284	RCIOM & CCIOM - REPLACE	5
	📄		AIRLINES INSTEAD OF USING JOINERS AS PER CUSTOMER REQUEST.	
	📄		Replace both failed batteries with new.	
	📄		Remove the turntable, part of the jackshaft and output	
	📄		shaft yoke. Inspect for further damage on the shaft and	
	📄		axle housing - OK. Truck will require both output shaft	
	📄		and input shaft of rear most diff yokes. New jackshaft,	
	📄		output shaft overhaul, 1x rear air bag, RCIOM harness, 3x	
	📄		ABS sensors, 2x rear brake wear sensors, rear modulator,	
	📄		multiple airlines fittings, brackets and joiners etc.	
	📄		Remove all drive wheels. Replace 2x wear sensors on 1st	
	📄		drive and 4x ABS sensors on all drive axles. Cable tie in	
	📄		place. Refit wheels and torque specs. Replace RH rear 1st	

PC	Type	Code	Description (Original)	#
	🔧		drive air bag with new. Replace 1st drive output shaft	
	🔧		bearings and seal including new companion flange. Install	
	🔧		new jackshaft and torque fasteners. Refit the fifth wheel	
	🔧		and catwalk. Connect laptop and program modules. Start	
	🔧		truck and check for leaks – all OK. Re-seat air bags and	
	🔧		calibrate level sensors. Top up coolant and engine oil.	
	🔧		Road test and check over – all OK.	
	🔧		Replace 3x harnesses with new.	
	🔧		Replace RCIOM and CCIOM together are pair.	
	🔧		- RCIOM plug retainers damaged.	
	🔧		Repair and re-route all wiring as required.	
	🔧		Replace the rear modulator with new. Replace all required	
	🔧		fittings and connect airlines. Replace signal hose to the	
	🔧		distribution manifold. Replace the rear air tank module	
	🔧		hoses. Replace the manifold. Build up air - no leaks found.	
🔍 2022-11-21 - Mileage: 760552 - Order nr: 2233189				
🟢	*	SHIFT	EVENING - 21/11/2022.	
🟢	🔧	VO-2141300	Valves and unit injectors, adjust	3.5
	🔧		Carried out top set adjustment as per specifications.	
🔍 2022-09-14 - Mileage: 740989 - Order nr: 2231915				
🟢	*	SHIFT	DAY - 14/09/2022.	
🟢	🔧	LO-840	ROOF HATCH, CRACKED/LEAKING - REPLACE	4
🟢	🔧	VO-78578078	ROOF HATCH	1
🟢	🔧	VO-85142067	MOUNTING KIT	1
🟢	🔧	VO-82080988	SUPPORT	2

PC	Type	Code	Description (Original)	#
	🔧		Remove inner panneling for access. Remove old roof hatch.	
	🔧		Clean the mating surfaces. Apply primer and sealant. Fit	
	🔧		up new roof hatch. Reassemble in reverse. All OK.	
📅 2022-07-12 - Mileage: 713947 - Order nr: 2230551				
🟢	*	SHIFT	BREAKDOWN	
🟢	*	92	TRAVEL 80 KM @ \$2.00 CTS PER KM	
	🔧		Travel to Brookton HWY	
🟢	🕒	LO-194	TRAVELLING TIME	1.25
🟢	🕒	LO-510	Brake fault on dash -	2
	🔧		Investigate, report and rectify	
🟢	🔧	VO-992303	PIPE RETAINER 8mm	2
🟢	🔧	VO-22085772	MODULATOR	1
	🔧		Load Ute. Travel to breakdown. Checked for cause of	
	🔧		brake fault on dash. Traced fault to foot brake valve.	
	🔧		Removed and replaced valve. Test operation. All OK. Pack	
	🔧		up and returned to workshop.	
	🔧		SERIAL# 22065 00292	
📅 2022-07-08 - Mileage: 0 - Order nr: 2230358				
🟢	*	CARD	NOT REQUIRED	
📅 2022-07-05 - Mileage: 0 - Order nr: 2230429				
🟢	*	CARD	NOT REQUIRED	
📅 2022-05-05 - Mileage: 685771 - Order nr: 7724221				
	🔧		ECM KMS: FUEL USED: ENG HRS:	
	🔧		IDLE HRS: PTO HRS:	
	🔧		-----	

PC	Type	Code	Description (Original)	#
	🔧		CONTACT : NEIL 0419 944 955	
	🔧		-----	
	🔧		ASSESS PULLING POWER REDUCED ON DASH - ADBLUE PUMP	
	🔧		REPLACED 2 DAYS AGO AT FORRESTFIELD	
🟢	🟡	LO-258	ASSESS PULLING POWER REDUCED	1
	🔧		CONNECTED LAPTOP	
	🔧		READ AND PRINT DTCS	
	🔧		ADBLUE FAULTS	
	🔧		RAN SCR TEST	
	🔧		ADBLUE PUMP PRESSURE AT 5KPA	
	🔧		CHECKED EXTERNAL ADBLUE FILTER AND INLET FILTER	
	🔧		CLEANED BUT OKAY	
	🔧		INSPECTED HOSES	
	🔧		FOUND HOSE FROM EXTERNAL FITTING TO PUMP INLET LOOSE AND	
	🔧		NOT SECURE AND PINCHED	
	🔧		REROUTE AND SECURE HOSES	
	🔧		RAN PRESSURE TEST - 500KPA - ALL OKAY	
🟢	*	91	CONSUMABLES	
🔍 2022-05-03 - Mileage: 686381 - Order nr: 2228918				
🟢	*	SHIFT	DAY	
🟢	🟡	VO-2580000	Emissions after-treatment. Secondary ope	3
	🔧		P22FB00 NOx SENSOR 1 BANK 1	
🟢	🟡	LO-263	FAN ERROR P048013	1
	🔧		FAN STUCK ON.	
🟢	🔧	VO-22851845	PUMP UNIT	1











































PC	Type	Code	Description (Original)	#
		VO-21032572	CLAMP,UREA HOSE	2
			P116300 NOx EXCEEDENCE NON ERASABLE.	
			Checked DTCs. Carried out pressure test. Found at 3.5	
			KPA (spec 500 KPA). Removed and replaced pump. Re	
			tested. Found pump only at 5 KPA. Bypass tank filter	
			and re tested. Test still failed. Checked lines for	
			blockages. AI OK. Run water straight into pump.	
			Pressure now at 500 KPA. Re connect to tank. Pump	
			failed. Caried out further checks. Found hoses at	
			injector had been disconnected. Refit hoses. Test with	
			old pump. Test with new pump. All OK. Carried out P & A	
			to replace pump. All OK. Fit and secure new pump.	
			Checked over. All OK.	
			Checked DTCs. No related codes logged. Test drive.	
			Found fan engaging and dis engaging correctly. Re checked	
			DTCs. Still no codes. Carried out fan clutch engagement	
			test. Clutch operates normally. Checked over wiring and	
			connections. All OK. No faults found.	
			NEW SERIAL# 21/6/22 40601	
	2022-02-01 - Mileage: 670242 - Order nr: 2227006			
		1000	card not required	
	2022-01-19 - Mileage: 670265 - Order nr: 2226938			
		SHIFT	EVENING - 19/01/2022.	
		LO-257	CRANKCASE VENTILATION GASKET - REPLACE	2.5
		VO-20532891	CCV GASKET	1

PC	Type	Code	Description (Original)	#
		VO-21976104	O-RING	1
			- LEAKING OIL.	
			Inspect and found oil leaking from the CCV housing gasket	
			and base gasket. Remove the CCV. Clean the sealing	
			surfaces. Fit new housing gasket and base gasket. Refit	
			the CCV. Wash down leakage. Road test and check over - OK.	
2021-12-09 - Mileage: 658733 - Order nr: 2226062				
		SHIFT	DAY	
		LO-214DERE	Valve adjustment fixed price package	3.5
		LO-285	Check for fan fault codes	0.75
			Derek Murray	
			Removed intakes etc. Removed rocker cover. Carried out	
			top set to spec. Record all measurements. Refit rocker	
			cover. Refit intakes etc. Road tested. Checked over.	
			All OK.	
			Connected lap top. Download, read and print DTCs.	
			Disconnected lap top.	
2021-11-27 - Mileage: 0 - Order nr: 2225466				
		CARD	NOT REQUIRED	
2021-10-18 - Mileage: 628305 - Order nr: 4511497				
		DEREK	DAY - 04/10/2021.	
		260	COOLANT HOSE - REPLACE	
		VO-21339891	HOSE,COOLANT	0.8
		VO-984993	HOSE CLAMP	4
			- BETWEEN HEAD AND BOTTOM RADIATOR.	

PC	Type	Code	Description (Original)	#
	📄		CREDIT OF HOSE CLAMPS AND COOLANT HOSE INCORRECTLY	
	📄		CHARGED ON ORIGINAL INVOICE 2224591.	
	📄		APOLOGIES FOR ANY INCONVENIENCE CAUSED.	
🔍	2021-10-18 - Mileage: 0 - Order nr: 2224906			
	📄		CARD NOT REQUIRED.	
🔍	📄	2021-10-04 - Mileage: 628305 - Order nr: 2224591		
📄	*	DEREK	DAY - 04/10/2021.	
📄	🔧	VO-2632300	Fan hub, replace	1.8
📄	🕒	LO-194	TRAVELLING TIME	0.75
📄	🔧	VO-22031832	FAN HUB	1
📄	🔧	VO-990950	M8 FLANGE LOCK NUT	4
📄	🔧	VO-21847501	V-RIBBED BELT LG1413mm	1
📄	🔧	VO-21753149	IDLER PULLEY	1
📄	🔧	VO-23669027	BELT TENSIONER	1
📄	🔧	VO-21190817	V-RIBBED BELT	1
📄	🔧	VO-984755	M10*40 FL BOLT	2
📄	🔧	VO-21631484	BELT TENSIONER	1
	📄		Brant rd Kelmscott.	
📄	🔧	LO-260	COOLANT HOSE - REPLACE	1
📄	🔧	VO-21339891	HOSE,COOLANT	1
📄	🔧	VO-984993	HOSE CLAMP	4
📄	*	263	FAN & ALTERNATOR BELT TENSIONERS	
	📄		- NO ADDITIONAL LABOUR CHARGE.	
	📄		Replace the fan belt and alternator belt tensioners.	
	📄		- BETWEEN HEAD AND BOTTOM RADIATOR.	

PC	Type	Code	Description (Original)	#
	🔧		Drain coolant. Replace the coolant hose and clamps with	
	🔧		new. Refill coolant. Check over - no further leaks found.	
🔍 2021-09-03 - Mileage: 617864 - Order nr: 2223898				
🔧	*	SHIFT	DAY	
🔧	🕒	LO-194	TRAVELLING TIME	0.75
🔧	🕒	LO-260	Coolant leak - Suspect Water	3.25
	🔧		pump?	
🔧	🔧	VO-85021450	EXCH PUMP UNIT	1
🔧	🔧	VO-21103569	SEALING RING	1
	🔧		Load Ute. Travel to site. Drained coolant. Removed and	
	🔧		replaced coolant pump. and secure. Fill coolant. Checked	
	🔧		over. All OK. Pack up and returned to workshop.	
	🔧		Investigate, report and rectify	
🔍 2020-10-09 - Mileage: 537931 - Order nr: 2215650				
	🔧		S1426 TECU, SW UPDATE. FH/FM (4)	
🔧	🕒	VO-4301400	TECU, sw, update. Only campaign	0.4
🔧	🕒	VO-1701000	Connect-disconnect of diagnostic tool	0.2
🔧	*	SHIFT	DAY	
🔧	🕒	LO-210	ENGINE IS CHOOFING - DRIVER REPORTED	22
	🔧		THAT HE COULDN'T FEEL A MISFIRE	
	🔧		48 MONTHS OLD.	
🔧	🔧	VO-85022268	EXH CYL HEAD 16L	0.7
🔧	🔧	VO-1161963	RUBBER GREASE	1
🔧	🔧	VO-1547252	SEALING RING	1
🔧	🔧	VO-1677370	VEB SEAL	2











































PC	Type	Code	Description (Original)	#
Ⓟ	■	VO-20526428	VEB SEAL	2
Ⓟ	■	VO-20563945	INTAKE MANIFOLD SEAL	1
Ⓟ	■	VO-20736230	D16C R/C GKT	1
Ⓟ	■	VO-20799996	SEALING RING	1
Ⓟ	■	VO-20815558	SEALING STRIP	1
Ⓟ	■	VO-20852765	GASKET	4
Ⓟ	■	VO-21015266	SCREW	6
Ⓟ	■	VO-21185132	SEALING	2
Ⓟ	■	VO-21344774	FLANGE SCREW	6
Ⓟ	■	VO-21352841	GASKET	6
Ⓟ	■	VO-21423788	SEALING RING	1
Ⓟ	■	VO-21503575	SEALING RING	1
Ⓟ	■	VO-21575727	HEAD GASKET	1
Ⓟ	■	VO-21801388	YOKE	6
Ⓟ	■	VO-21940615	SEALING RING	1
Ⓟ	■	VO-22206133	GASKET	1
Ⓟ	■	VO-276948	D12 INJ/SEAL KIT	6
Ⓟ	■	VO-3092340	SEALANT (GREY)	1
Ⓟ	■	VO-3979639	PRE HEAT GSK	2
Ⓟ	■	VO-420643	TURBO DRAIN GASKET	1
Ⓟ	■	VO-469601	TURBO DRAIN SEAL	1
Ⓟ	■	VO-470993	TRBO RETURN GSK	1
Ⓟ	■	VO-8131154	SEALING RING	1
Ⓟ	■	VO-8192804	SCREW	8
Ⓟ	■	VO-85103205	GREEN PAINT	1







































PC	Type	Code	Description (Original)	#
		VO-944126	O-RING INJ HARNESS	1
		VO-983472	D12 LOOM TIE	8
		VO-993811	FLANGE SCREW	4
		VO-994447	FLANGE SCREW	6
		VO-8131393	CAGE	10
		AU2-CAL85108913	VOLVO VCS COOLANT 5 LITRE	1
		OTH-40124	SUPERGLUE 25ML	1
			Serial number 170511316.	
		VO-994441	M8*50 FLANGE SCREW	1
		VO-990950	M8 FLANGE LOCK NUT	1
		VO-994195	FLANGE SCREW	1
		VO-990941	FLANGE NUT	1
		VO-21531072	TEMPERATURE SENSOR	1
		VO-84431057	ROLLER BLIND	1
		LO-880	INTERNAL SUNVISOR - REPLACE	1.5
		LO-560	DEFECT - INSPECT BRAKE FAULT	0.5
			- FOUND 2ND STEER BRAKE PADS VARIANCE BETWEEN LEFT AND	
		VO-85022268	EXH CYL HEAD 16L	0.3
		2110000	Cylinder head. Secondary operation	
			number	
			ser 170511316	
			Connected lap top. Download and read DTCs. Carried out	
			GD. Carried out compression test. Found compression low	
			on Ä4 & Ä5. Checked valve heights and clearances. All	
			OK. Drained coolant. Removed intake and exhaust manifold	

PC	Type	Code	Description (Original)	#
	🔧		assemblies. Strip and clean. Removed rocker gear.	
	🔧		Inspected. Ä4 & Ä5 exhaust valve stem seals? split.	
	🔧		Removed head. Strip and clean. Build new head. Refit	
	🔧		injectors using new O-rings. Refit rocker gear. Carried	
	🔧		out top set to spec. Refit intakes and exhaust manifold	
	🔧		assemblies using new gaskets, o-rings and seals as	
	🔧		required. Refit intake and exhaust pipework and secure.	
	🔧		Fill coolant. Bled fuel system. Run engine. Washed down	
	🔧		and reset cylinder balance. Cleared DTCs. Download	
	🔧		latest software. Program ECU. Checked over. All OK.	
	🔧		Road tested. Found coolant temp fluctuating severely.	
	🔧		Inspected sensor. Found coolant leaking from sensor.	
	🔧		Removed and replaced sensor. Test drove. Found temp	
	🔧		still slightly fluctuating. Bled cooling system and top	
	🔧		up. Road tested. All OK. Temp now steady.	
	🔧		Note: Cylinder head has been supported with 30% VGA	
	🔧		Goodwill assistance.	
	🔧		Checked codes. Found code active for wear sensor.	
	🔧		Carried out brake pads wear test. Found reading 30 %	
	🔧		difference. Checked manual indicators. Confirmed 30%	
	🔧		difference. Advised Customer accordingly.	
	🔧		Carried out P & A to replace. All OK. Removed interior	
	🔧		panels and bolts for visor. Removed and replaced visor.	
	🔧		Checked operation. All OK. Refit and secure panels.	
	🔧		BUT THERE WAS DEFINATLEY AN AUDIBLE	
































PC	Type	Code	Description (Original)	#
	📄		CHOOOFING NOISE. INSPECT AND ADVISE.	
	📄		QUOTE REPAIR.	
	📄		RIGHT. INSPECTED AND FOUND NEW BRAKE PADS ONLY FITTED TO	
	📄		ONE SIDE.	
	📄		*** POSSIBLE POLICY CLAIM ***	
	📄		*** POSSIBLE POLICY CLAIM ***	
📄 2020-09-30 - Mileage: 533123 - Order nr: 2215419				
📄	*	SHIFT	DAY	
📄	🕒	LO-194	TRAVELLING TIME	0.75
📄	🕒	LO-258	AD BLUE INJECTOR FITTING LEAKING	3.5
	📄		REFER PLANNER FOR PHOTOS	
📄	📄	VO-20744599	CONNECTOR,SAE 5/16	1
📄	📄	VO-20748166	CONNECTOR,SAE 3/8	1
📄	📄	VO-21032572	CLAMP,UREA HOSE	2
📄	*	773	SUPPLY 6X STEER AXLE WHEEL STUDS	
	📄		CUSTOMER REQUEST	
📄	📄	VO-20515514	FRONT METRIC WHEEL STUD	6
	📄		MAIN YARD : 40 BRANT ROAD, KELMSCOTT (USUALLY FOR ALL	
	📄		Load Ute. Travel to site. Inspect. Found signs of	
	📄		Adblue leak from fitting on the injector. Caried out	
	📄		pressure test. Confirm leak. Found hose loose. Cut off	
	📄		old fittings. Crimp on new fittings and secure. Re	
	📄		tested. All OK. Pack up and travel back to workshop.	
	📄		CALL OUTS)	
📄 2020-08-31 - Mileage: 0 - Order nr: 2214487				


















































PC	Type	Code	Description (Original)	#
	*	CARD	NOT REQUIRED	
2020-08-22 - Mileage: 513320 - Order nr: 2214519				
		LO-465	CLEAN METAL FROM THE DIFF HOUSING	1
		VO-3092340	SEALANT (GREY)	1
		VO-995906	HEXAGON SCREW	8
		VO-984050	HEXAGON NUT	8
		VO-3199066	REAR 1/2 SHAFT SEAL	2
		VO-1068253	U/J SPIDER KIT (60MM CAP)	2
		LO-451	MAIN SHAFT UNI JOINTS - REPLACE	3
		AU2-CAL85136279	SYNTH REAR AXLE OIL 20L(97312)	1
		VO-992017	SWIVEL	2
		VO-984735	M8*25 FL BOLT	8
		VO-948211	CABLE TIE	10
		VO-20428158	CABLE TIE	6
		OTH-NYP60608	NYLON ELBOW	1
		VO-4653100	Differential carrier, first rear axle, o	10.9
		VO-1522345	DIFF GEAR NEEDL	184
		VO-1524058	ROLLER BEARING	1
		VO-1524881	RT NEEDLE BEARING	1
		VO-1524887	THRUST WASHER RT	4
		VO-181632	BEARING EV87	1
		VO-20438702	RTS2370 PINION NUT	1
		VO-20508274	KIT RTS2370A - FRO	1
		VO-20545485	DIFF LOCK DIAPHRAGM	1
		VO-20551283	BEARING	1

PC	Type	Code	Description (Original)	#
		VO-20568621	THRUST WASHER	1
		VO-20582548	ROLLER BEARING	1
		VO-20582549	ROLLER BEARING	1
		VO-20907634	DEFLECTOR	1
		VO-21448461	LIP SEAL	1
		VO-21793022	THRUST WASHER KIT	1
		VO-8171089	RTS2370 HEMISPHERE BOLT	12
		VO-8171090	SPLIT PIN RTS2370	1
		VO-8171338	DIFF INPUT NUT	1
		VO-184622	ROLLER BEARING	1
		VO-8171107	GASKET	1
		VO-6790354	O-RING	1
			Included Operations:	
			46530 Differential carrier, first rear axle, remove	
			46574 Differential carrier, first rear axle, overhaul	
			46525 Differential carrier, first rear axle, install	
		VO-1820200	Localised wash for fault tracing	0.3
			- FOUND BADLY CORRODED.	
			Replace the main shaft uni joints with new.	
			Shaft removed from the vehicle for diff repairs.	
		2020-06-18 - Mileage: 478553 - Order nr: 2212907		
		SHIFT	DAY	
		LO-192	TRAVEL TIME	2.75
		92	TRAVEL 186 KM Ö Å1.50 CTS PER KM	
			TRUCK IS OUTSIDE THE DWELLINGUP CEMETRY, DRIVERS NAME IS	






































PC	Type	Code	Description (Original)	#
		VO-2630600	Thermostat fan, replace	2.9
		LO-560	SMALL AIR LINE OFF COMPRESSOR KEEPS	0.4
			COMING OF NOT MUCH OTHER INFO PROVIDED	
		VO-21753149	IDLER PULLEY	1
		VO-990950	M8 FLANGE LOCK NUT	4
		VO-953053	FAN STUD	4
		VO-22031832	FAN HUB	1
		VO-21884469	FILLER CAP	1
		AU2-CAL85108913	VOLVO VCS COOLANT 5 LITRE	2
		VO-992024	ELBOW NIPPLE	1
		VO-85003294	EXCH THERMO FAN	1
		VO-21847501	V-RIBBED BELT LG1413mm	1
			*** POSSIBLE POLICY CLAIM ***	
			TROY 0407577049 -	
		VO-2605300	Fan hub, replace. Fan removed	0.5
			Inspected fan hub. Found fan hub worn. Removed and	
			replaced fan hub. Checked over. All OK.	
			Air leak from signal line to compressor. Found fitting	
			broken. Removed and replaced failed fitting. Tested.	
			All OK.	
		VO-2341300	Filler cap, replace	0.1
			Found coolant cap had been removed when coolant was hot.	
			Found seal rubber seal missing from cap and coolant had	
			blown out. Top up coolant to spec. Fit new cap and	
			secure. Checked over. All OK.	










































PC	Type	Code	Description (Original)	#
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2632500	Electrically controlled engine cooling f	0.2
			fan, check	
		VO-3710200	Electric wires and connections, check	0.4
		VO-3720200	Fuse, electrical center, replace	0.1
2020-04-08 - Mileage: 447236 - Order nr: 2211262				
	*	92	TRAVEL KM Ö Å1.50 CTS PER KM	
			40 BRANT ROAD, KELMSCOTT.	
		LO-194	TRAVELLING TIME	0.75
		LO-491	GEARBOX RADIATOR - REPLACE	3.25
		VO-23653292	RADIATOR	1
		VO-21959962	HOSE	1
		VO-21959469	HOSE	1
		AU2-CAL85108913	VOLVO VCS COOLANT 5 LITRE	1
		VO-990215	HOSE CLAMP	4
		VO-20722710	HOSE CLAMP	4
			- PIN HOLE IN OIL COOLER, RADIATOR.	
			Organise parts and load the ute. Travel to customers yard.	
			Inspect and found the cooler leaking. Remove the bullbar,	
			front grill, steps, brackets and crossmember for access.	
			Drain coolant. Remove the cooler. Fit new hoses and clamps	
			to new cooler and install. Reassemble in reverse order.	
			Time taken to align the bullbar. Fill coolant. All OK.	
2019-11-04 - Mileage: 413406 - Order nr: 2207278				
	*	DEREK	D KEW SHIFT:	

PC	Type	Code	Description (Original)	#
	*	1706800	36 Months ECU download and oil sample.	
			Only valid for Australian market	
		VO-23448457	OIL SAMPLING KITX1	4
			PLEASE FILL OUT THE COUPON	
			Melinda booked off site 36 month samples & downloads for	
			a date when the vehicle was outside its 36 month period	
			from delivery date - VGA advised would not pay claim.	
 2019-09-23 - Mileage: 405175 - Order nr: 2206349				
	*	DEREK	D KEW SHIFT:	
		LO-194	TRAVELLING TIME	0.75
		VO-20736230	D16C R/C GKT	1
			Derek Murray	
		VO-2141300	Valves and unit injectors, adjust	3.5
			needs to be price adjusted to Å111.00 as per notes	
			Removed intakes etc. Removed rocker cover. Found rocker	
			gasket had perished. Carried out top set to spec. Record	
			all measurements. Refit rocker cover using new gasket and	
			secure. Refit intakes etc. Washed down and road tested.	
			All OK.	
			no km	
	*	211	GASKET	
 W 2019-05-10 - Mileage: 362847 - Order nr: 2202793				
	*	DEREK	D KEW SHIFT:	
		VO-1706700	30 Months ECU download and oil sample. O	0.9
		VO-8394887	OIL TEST KIT	4




































PC	Type	Code	Description (Original)	#
			Hours and Fuel Burn not showing on dash.	
  2019-01-17 - Mileage: 323823 - Order nr: 2200278				
		LO-211	Balance of time for VST	0.4
		92	TRAVEL 47 KM Ö Å1.50 CTS PER KM	
		LO-194	TRAVELLING TIME	0.75
		80	SUBLET - TOW TRUCK	
		VO-2112600	Cylinder head, replace	11.9
		OTH-9115	INSULATING TAPE	1
		VO-21575727	GASKET	1
		VO-994447	FLANGE SCREW	6
		VO-20563945	INTAKE MANIFOLD SEAL	1
		VO-3979639	PRE HEAT GSK	2
		VO-20741911	O-RING	1
		VO-983472	D12 LOOM TIE	7
		VO-8131393	CAGE	6
		VO-20815558	SEALING STRIP	1
		VO-21503575	SEALING RING	1
		VO-8131154	SEALING RING	1
		VO-21423788	SEALING RING	1
		VO-1547252	SEALING RING	1
		VO-21352841	GASKET	6
		VO-20784537	GASKET	1
		VO-85000622	EXCH TURBO	1
		VO-22718181	KIT	1
		VO-22206133	GASKET	1

PC	Type	Code	Description (Original)	#
		VO-8148729	CONNECTOR	1
		VO-8192804	SCREW	8
		VO-276948	D12 INJ/SEAL KIT	6
		VO-21312239	CHARGE AIR HOSE	1
		AU2-CAL85108913	VOLVO VCS COOLANT 5 LITRE	1
		VO-1677370	VEB SEAL	2
		VO-20526428	VEB SEAL	1
		VO-21780371	SEALING RING	2
		VO-1543578	F16 SEAL (OIL P	2
		VO-20734156	SEALING STRIP	1
		VO-21254035	CYLINDER LINER KIT D16G	1
		VO-955982	O-RING	1
		VO-984816	M12*40 FL BOLT	13
		VO-20586602	BIG-END BEARING KI	1
		VO-949656	O-RING 19MM ID	1
		VO-1161277	LINER SEALANT	1
		VO-469601	TURBO DRAIN SEAL	1
		VO-21940615	SEALING RING	1
		VO-85000888	EXCH CYLINDER HEAD	1
		VO-21344774	FLANGE SCREW	6
		VO-85103205	GREEN PAINT	1
		OTH-40124	SUPERGLUE 25ML	1
		VO-20775507	HEX. SOCKET SCREW	12
		VO-470993	TRBO RETURN GSK	1
		VO-85000622	EXCH TURBO	1

PC	Type	Code	Description (Original)	#
		LO-2550	TURBO & MANIFOLD GASKETS - REPLACE	10
		VO-21352841	GASKET	6
		VO-20784537	GASKET	1
		VO-22206133	GASKET	1
		VO-470993	TRBO RETURN GSK	1
		VO-20938964	SEAL	1
			NEW SERIALÄ 151930347	
			OLD SERIALÄ 162240608	
			*12.3 hours.	
			NEW UNIT SN: H180435305.	
			OLD UNIT SN: H180437915.	
		VO-1820200	Localised wash for fault tracing	0.3
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2100600	Cylinder Compression, test	0.2
		VO-2141700	Valve guide wear, check. all	0.4
			*REWORK ON TECH 2052. RMS ENTERED BY BRIAN/KG.	
			Brant rd Kelmscott.	
			FROM: Derek Murray Transport.	
			TO: TCWA Kewdale.	
		VO-2652200	Charge air hose, replace	0.3
		VO-2135700	Piston and liner, replace (one). Cylinde	1.6
			Cylinder head and sump removed.	
		VO-2170800	Oil sump, install	0.6
		VO-2170600	Oil sump, remove	0.3
		VO-2500600	Inlet and exhaust systems, check	0.2

PC	Type	Code	Description (Original)	#
		VO-2131500	Cylinder Liner height, check (one). Cyli	0.3
			Cylinder head removed.	
		10	OTHER COSTS =	
			SUPERGLUE 25ML.	
			INSULATING TAPE.	
		VO-2840700	Sensor values, check	0.2
		VO-2161100	Connecting rod bearings, replace (all).	1.3
			Oil sump removed.	
			NEW UNIT SN: H180437915.	
			OLD UNIT SN: H160535149.	
			AUTHORITY NUMBER: 200437244.	
		2018-10-23 - Mileage: 280631 - Order nr: 2198382		
		92	TRAVEL 47 KM Ö Å1.50 CTS PER KM	
			BRANT RD, KELMSCOTT.	
		VO-2630600	Thermostat fan, replace	1.5
		VO-85003294	EXCH THERMO FAN	1
		VO-990950	M8 FLANGE LOCK NUT	4
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-2632500	Engine cooling fan, test	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-2500500	Response, test drive	0.4
		LO-194	TRAVELLING TIME	0.75
		LO-263	ENGINE FAN FAULTS	0.5
			Charging Parts Dept. 0.5 hour for excess time spent waiting	

PC	Type	Code	Description (Original)	#
			for parts to be picked. ATTN: LEE PURCELL.	
2018-10-08 - Mileage: 275226 - Order nr: 2197988				
	*	SHIFT	SHIFT :DAY	
			ENG HRS: 5036 FUEL BURN: 193126	
		VO-1706600	24 Months ECU download and oil sample. O	0.9
			Only valid for Australian market	
		VO-1774600	Annual service	2.6
			NO OIL CHANGE - WARRANTY CHECKS ONLY	
		VO-8100500	24 Months cab inspection	0.4
		LO-214DERE	Valve adjustment fixed price package	4
		VO-8394887	OIL TEST KIT	4
		LO-350	LHF fog light inop - If globe	0.5
			replace, if not inform customer further diagnoses required	
		LO-210	Engine harness leaking LHS of	0.5
			head	
		VO-2637500	Fan belt idler pulley, replace	0.5
			as noisy - Found on defect list	
		VO-4132000	Clutch cylinder, replace. Gearbox remove	0.3
		LO-560	Air leak under turntable from brake	0.88
		LO-5000	LHF brake pad - out of range -	2
			CONTACT PERSON :DAVID	
			PHONE NUMBER :0419 944 955	
			NOTE: PLEASE PRINT TECH TOOL REPORT AND	
			ATTACH TO JOB CARD.	
		VO-21753149	IDLER PULLEY	1












































PC	Type	Code	Description (Original)	#
		VO-944126	O-RING INJ HARNESS	1
		VO-983472	D12 LOOM TIE	7
		VO-990037	H7 GLOBE L/L	1
		VO-21296863	SENSOR	1
		VO-85013166	EXCH CYLINDER	1
		VO-20992763	AIR HOSE	1
		VO-983472	D12 LOOM TIE	2
			S/N:666482000262	
		VO-990073	CABLE TIE	1
		VO-22901068	BOLT,PROPSHAFT	4
		VO-990971	NUT,PROPSHAFT	4
			Removed intakes etc. Removed rocker cover. Carried out	
			top set to spec. Record all measurements. Refit rocker	
			cover and secure. Refit intakes etc. Washed down and	
			road tested. All OK.	
			Derek Murray	
			Rocker cover was already removed for top set. Found oil	
			Found fan belt idler noisy. Removed and replaced idler.	
			Checked over. All OK.	
			Checked for cause of air leak. Found air leaking from	
			under turntable. Found 3 x airlines not securely seated.	
			Removed, cleaned and refitted securely. Tested. All OK.	
			No further leaks noted.	
			Found LHF fog light in-op. Traced cause to blown globe.	
			Removed and replaced globe. Tested. All OK.	

PC	Type	Code	Description (Original)	#
			Checked for cause of LHF brake lining out of range.	
			Removed LH & RH front sensors. Found LH notchy. Lube and	
			refit both sensors. Found fault still present. Removed	
			and replaced LH sensor. Fault now cleared. Deleted	
			codes. Checked over. All OK.	
	*	210	OIL LEAKS	
			Checked for cause of engine oil leaks. Washed down engine.	
			Road tested. Found oil leaking from flywheel	
			housing/timing plate. Take photos.	
			removed	
		VO-4317000	Gearbox, remove	1
		VO-4317200	Gearbox, install	1.6
		LO-481	POWER TAKE-OFF (GEARBOX)	0.8
			48108 = 0.8 R & R PTO	
			leaking from engine harness. Found o-ring had failed.	
			Removed harness. Removed o-ring. Clean harness.	
			Reassembled using new o-ring and secure. Checked over.	
			All OK.	
			- Found on defect list	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-4112600	Clutch wear, check. VCADS Pro operation	0.2
			Re secured loose fittings. Tested. All OK.	
	*	91	CONSUMABLES	
	2018-10-02 - Mileage: 274307 - Order nr: 6042579			
			ECM KLS: FUEL: ENG HRS	

PC	Type	Code	Description (Original)	#
	📄		IDLE: PTO	
	📄		REPAIR CARRIED OUTBUSH ON P/S LEAK AT BOTTON OF STG BOX	
	📄		CUSTOMER WANTS TO CONFIRM THAT IT IHAS BEEN REPAIRED	
	📄		CORRECTLY	
📌	📌	LO-640	STEERING - GENERAL	1.5
📌	*	94	WASTE DISPOSAL	
📌	📌	LO-870	AIR CONDITIONING - GENERAL	0.5
📌	📌	VO-21190817	V-RIBBED BELT	1
📌	📌	VO-21177272	SOCKET	1
📌	📌	VO-990211	FERRULE	2
📌	📌	VO-984810	FITTING NUT	2
📌	📌	VO-21665525	SERVO PIPE	1
	📄		connect laptop and run conversion kit for new air con	
	📄		parts fitted.	
📌 2018-10-02 - Mileage: 273511 - Order nr: 4419381				
📌	*	INFO	DETAILS	
	📄		KM:273,511km's	
📌	*	BREAKDOWN	BREAKDOWN	
	📄		OFFSITE WORK	
📌	*	645	STEERING PIPE FAILURE	
📌	*	60	SUBLET: SEIVYS MECHANICAL	
	📄		GW71058MK	
	📄		DESTINATION:MT MAGNET	
	📄		AFTER HOURS: NO	
	📄		CALL OUT TIME 4:30PM	

PC	Type	Code	Description (Original)	#
	📅		DATE 01/10/18	
	📅		CONTACT ON SITE IS:TROY 0407 963 200	
	📅		CONTACT OFF SITE IS:DAVID HAND 0419 944 955	
🔍 2018-08-14 - Mileage: 255306 - Order nr: 2196613				
🟢	🕒	LO-810	SUN ROOF GLASS - REPLACE	4
🟢	🔧	VMR-22225554A	MODULATOR	1
🟢	🔧	VO-21325001	GLASS ! ROOF HATCH FH4	1
🟢	🕒	LO-560	BRAKE MODULATOR - REPLACE	1.5
🟢	🔧	VO-990962	FLANGE LOCK NUT - M16	12
🟢	🔧	VO-984834	M16*50 FL BOLT	12
	📅		NOTE: 6 MONTHS WARRANTY COVERAGE ONLY.	
	📅		Strip down the truck interior as required. Remove broken	
	📅		roof hatch hinges. Install new roof glass. Reassemble in	
	📅		reverse order. Wipe down glass.	
	📅		Remove the turntable for access. R&R the modulator with	
	📅		new. Refit the turntable with new nuts and bolts. Clear	
	📅		fault codes. Active fault for LHS front brake lining	
	📅		sensor, carry out test and trace to faulty sensor. Also	
	📅		notice air leak from the clutch cylinder. Advise customer.	
🟢	*	91	CONSUMABLES	
🔍 📄 2018-07-25 - Mileage: 242375 - Order nr: 2196052				
🟢	*	92	TRAVEL 48 KM Ö Å1.10CTS PER KM	
	📅		Travel to 40 Brant Road, Kelmscott. Return.	
🟢	🕒	LO-194	TRAVELLING TIME	1
🟡	🕒	VO-2631800	Fan ring, replace	2.8

PC	Type	Code	Description (Original)	#
		VO-23003426	FAN RING	1
		VO-3979639	PRE HEAT GSK	2
		VO-993975	HOSE CLAMP	1
		VO-984734	M8*20 FL BOLT	2
2018-06-28 - Mileage: 229014 - Order nr: 2195323				
		VO-2850800	Exhaust back pressure sensor, replace	0.2
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1705400	Accessory kit, programming	0.1
		VO-85139619	PRESSURE SENSOR	1
		VO-21582423	PLUG KIT	1
		OTH-VBPMKIT	VOLVO BACK PRESSURE KIT	1
		VO-946834	CLAMP 11.1mm	1
		VO-965544	BRACKET LP48	1
		VO-990950	M8 FLANGE LOCK NUT	1
		VO-984735	M8*25 FL BOLT	1
		VO-984751	FLANGE SCREW	1
		VO-22889891	ACTUATOR SERVICE KIT	1
		VO-3710200	Electric wires and connections, check	0.4
		VO-3711700	Connector, replace (1-8 cables)	0.3
		VO-1703700	Sensor and parameter values, monitoring	0.2
		VO-2840000	Control system, fuel supply. Secondary o	1.5
		VO-2531400	Control cylinder exhaust brake, replace	0.6
		VO-1790600	Diagnostic with Tech Tool/GD. Connect-di	0.5
			Connect-disconnect of diagnostic tool included.	
		VO-2534000	Warm hold function, test	0.2







































PC	Type	Code	Description (Original)	#
			I-ROLL SW UPDATE. FH/FM (4)	
		10	VOLVO BACK PRESSURE KIT	
 2018-05-19 - Mileage: 209721 - Order nr: 2193721				
			AIRBAG MODULE, REPLACE. FH/FM (4)	
		VO-8842000	Airbag module, replace	0.3
			CCM, SW UPDATE. FH/FM (4)	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-8711300	CCM, SW Updating. Campaign only	0.2
		DEREK	D KEW SHIFT:	
			ENG HRS 3936 FUEL BURN 145901:	
		VO-22900843	φφAIRBAG MODULE, RAVEN	1
		VO-2580000	Emissions after-treatment. Secondary ope	1
		OTH-AAB122ML-1/2PP-10	100 MESH FILTER 1/2" 122ML	1
		OTH-AB15	ADBLUE 15L	4
		OTH-ADBLUE FILTER BRA	ADBLUE PICKUP FILTER BRACKET	1
		OTH-NOR-W3-10	STAINLESS STEEL HOSE CLAMP	2
		OTH-NYP60608	NYLON ELBOW	2
		VO-20744595	CONNECTOR	1
		VO-21032572	CLAMP,UREA HOSE	2
		VO-21429181	HOSE (urea)	1
		VO-3985511	CLAMP	1
		VO-984724	M6*12 FL BOLT	2
		VO-20428158	CABLE TIE	10
		LO-593	INVESTIGATE BRAKE MALFUNCTION ON DASH	3.5








































PC	Type	Code	Description (Original)	#
	📄		Park brake malfunction on dash	
	📄		CONTACT PERSON:DAVID HAND	
	📄		CONTACT NO :0419 944 955	
	📄		EMAIL PRO-FORMA TO DAVID HAND (derekmcö	
	📄		bigpond.net.au) FOR PO.	
	📄		Checked for cause of brake malfunction.	
	📄		Found external Adblue filter mod required.	
	📄		Drained Adblue. Removed tank. Removed pick up. Cut off	
	📄		heating coil and removed filter sock. Refitted pick up.	
	📄		Re fitted tank and filled with Adblue. Fit external	
	📄		filter. Pressure test system. All OK. Washed down and	
	📄		test drive. All OK.	
🔧	🔧	VO-2500600	Inlet and exhaust systems, check	0.2
🔧	🔧	VO-2580400	AdBlue tank, remove	0.8
🔧	🔧	VO-2585800	AdBlue tank, clean. Urea tank removed	0.5
🔧	🔧	VO-2580500	AdBlue tank, install	0.7
🔧	🔧	VO-2584600	SCR system, test	0.5
🔧	🔧	VO-1701000	Connect-disconnect of diagnostic tool	0.2
🔧	*	10	SUBLET V (SERVICE/MNTCE)	
	📄		10 =	
	📄		Found C101721 Lining wear sensor fault logged.	
	📄		Removed and replaced sensor. Found fault still apparent.	
	📄		Carried out brake pads test. Found out of range lining	
	📄		wear sensor 1. Carried out speed sensor test. Front left	
	📄		in-op. Inspected modulator. Found plugs missing the	






































PC	Type	Code	Description (Original)	#
	🔧		cover and debris in plugs. Cleaned and ordered parts.	
	🔧		100 Mesh Filter Å37.27	
	🔧		60 Ltrs Adblue Å68.00	
	🔧		Adblue pick up filter bracket Å9.99	
	🔧		Stainless steel hose clamp x 2 Å3.82	
	🔧		Nylon elbow x 2 Å8.76	
🟢	*	91	CONSUMABLES	
🔍 W 2018-03-29 - Mileage: 189071 - Order nr: 2192882				
🟡	🕒	VO-1706500	18 Months ECU download and oil sample. O	0.9
	🔧		Only valid for Australian market	
🟢	🕒	VO-2141300	Valves and unit injectors, adjust	3.5
🟡	🔧	VO-8394887	OIL TEST KIT	4
	🔧		Removed intakes etc. Removed rocker cover. Carried out	
	🔧		top set to spec. Record all measurements. Refit rocker	
	🔧		cover and secure. Refit intakes etc. Washed down and	
	🔧		road tested. All OK.	
	🔧		Note: Work carried out at Customer's yard.	
🔍 W 2017-11-22 - Mileage: 144753 - Order nr: 2189609				
🟢	*	DEREK	D KEW SHIFT: CALL OUT	
	🔧		ENG HRS 2622 FUEL BURN 98648	
🟡	🕒	VO-1701000	Connect-disconnect of diagnostic tool	0.2
🟡	*	92	TRAVEL 48 KM Ö Å1.10CTS PER KM	
🟡	🕒	LO-194	TRAVELLING TIME	0.6
	🔧		KELMSCOTT YARD	
🟡	🔧	VO-22643809	BRACKET	1






















PC	Type	Code	Description (Original)	#
		VO-22811869	PIPE SET	1
		VO-21582423	PLUG KIT	1
		VO-22889891	ACTUATOR SERVICE KIT	1
			CONTACT PERSON:DAVID HAND	
			CONTACT NO :0419 944 955	
		VO-2531400	Control cylinder exhaust brake, replace	0.6
		VO-2534000	Warm hold function, test	0.2
		VO-1701200	Fault codes, reading	0.2
		2584600	SCR system, test	
		VO-2850800	Exhaust back pressure sensor, replace	0.2
		VO-3710200	Electric wires and connections, check	0.4
			Checked for cause of Adblue fault codes. Checked system	
			pressure. All OK. Carried out dosage test. All OK.	
			Deleted codes. Customer drove truck. No further codes	
			noted. Driver to monitor.	
		VO-3711700	Connector, replace (1-8 cables)	0.3
		2017-09-09 - Mileage: 111543 - Order nr: 2187566		
		DEREK	D KEW SHIFT: VOLVO WEEKEND	
			ENG HRS: 2041. FUEL BURN: 77395.	
		VO-1706400	12 Months ECU download and oil sample. O	0.9
			Only valid for Australian market	
		VO-8100300	12 Months cab inspection	0.4
		VO-1774600	Annual service. Chassis lubrication and	2.6
		VO-2141300	Valves and unit injectors, adjust	4.02
		VO-8394887	OIL TEST KIT	4

PC	Type	Code	Description (Original)	#
	📅		VO/8394887 WAS FITTED BY BRANCH 1	
	📅		.- ON REPAIR ORDER 2183570 - DATE 2017-04-10 MILEAGE - 56108	
🔧	🔧	VO-2631300	Fan belt tensioner, replace	0.5
🔧	🔧	VO-21631484	BELT TENSIONER	1
🔧	🔧	VO-2850800	Exhaust back pressure sensor, replace	0.2
🔧	🔧	VO-85139619	PRESSURE SENSOR	1
🔧	🔧	VO-21582423	PLUG KIT	1
🔧	🔧	VO-3711700	Connector, replace (1-8 cables)	0.3
	📅		Carried out top set adjustment as req.	
🔧	*	91	CONSUMABLES	
🔍 🔧 2017-04-08 - Mileage: 56108 - Order nr: 2183570				
🔧	*	SHIFT	SHIFT :WEEKEND	
	📅		CONTACT PERSON : DAVID	
🔧	🔧	VO-1706300	6 Months ECU download and oil sample. On	0.9
🔧	🔧	VO-2800800	EMS and ACM, sw , update. Only campaign	0.4
🔧	🔧	VO-2502100	ACM, sw, update. only campaign	0.5
🔧	🔧	LO-263	ENGINE FAN FUNCTION CHECK	1.5
🔧	🔧	LO-284	SET IDLE SHUT DOWN FOR 5 MINS	0.35
🔧	🔧	VO-8560000	Drivers resting compartment	1
🔧	🔧	VO-8394887	OIL TEST KIT	4
🔧	🔧	VO-82328296	HINGE	1
🔧	🔧	VO-82379452	HINGE	1
🔧	🔧	VO-82378986	HINGE FITTING	1
🔧	🔧	VO-82328298	HINGE FITTING	1
🔧	🔧	VO-969405	SCREW	4

PC	Type	Code	Description (Original)	#
		VO-990939	FLANGE NUT	4
			CONTACT NUMBER : 0419 944 955	
			S0221 EMS and ACM, SW update. EU4/5. FH/FM (4)	
			S0127 Fan ring, check/adjust. FH/FM (4)	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
			Connect laptop and read fault codes - none related. Carry	
			out road test to get engine to temp. Carry out fan function	
			test - all OK. Unable to fault.	
			Set idle shut down for 5 MINS as requested. All OK.	
  2017-02-08 - Mileage: 39034 - Order nr: 2182275				
		DEREK	D KEW SHIFT: Day	
			CONTACT PERSON: DAVID HAND	
		LO-3540800	Cab interior lights, harness, install	0.5
		VO-2141300	Valves and unit injectors, adjust	1.7
		LO-560	APM FAULT CODES REPORTED	2.72
		VO-22935545	WIRES	8
		VO-20775507	HEX. SOCKET SCREW	12
			CONTACT NUMBER: 0419 944 955	
			C3628 Cab, interior lights, cable harness, install. FH (4)	
		VO-2373200	Yoke, injector, check. Valve cover remov	0.4
		601	WHEEL ALIGNMENT	
			- ADJUST INTER AXLE AS REQUIRED.	
  2017-01-04 - Mileage: 26088 - Order nr: 2181318				
		SHIFT	SHIFT :DAY	
			CONTACT PERSON : DAVID	

PC	Type	Code	Description (Original)	#
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-22223804	KIT	1
		LO-560	AIR DRIER FILTER, EXPIRED - REPLACE	1
			S3652 ACM, SW update. FH/FM (4)	
			CONTACT NUMBER : 0419 944 955	
		VO-2549400	ACM, SW, update. only campaign	0.2
			Connect laptop and read fault codes - air drier filter	
			expired. Check accessory kit - current. R&R air drier	
			filter with new. Carry out filter calibration/reset.	
 2016-11-21 - Mileage: 9563 - Order nr: 2180327				
		SHIFT	SHIFT : VOLVO DAY	
			CONTACT PERSON : DAVID HAND	
		VO-1721000	Warranty service. After 4 weeks or maxim	1.9
			After 4 weeks or maximum 10 000 km.	
		93	ENGINE OIL & GREASE	
			FULL SYNTHETIC IN DIFFS AND GEARBOX.	
		94	WASTE DISPOSAL	
		VO-4301400	TECU, sw, update. Only campaign	0.4
		VO-FK18B	FILTER KIT	1
		OTH-85131754L	GEAR OIL SYNTH 1 LITER SHC50	16
		VO-20779040	G/BOX OIL FILTER KIT	1
		OTH-CAL85136280L	SYNTH DIFF OIL(97312)PER LITRE	40
		VO-20593252	PLUG FLYWHEEL HOUSING	1
			CONTACT NUMBER : 0419 944 955	
			S3609 TECU, SW update. AMT-F. FH/FM (4)	





























PC	Type	Code	Description (Original)	#
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
 2016-11-11 - Mileage: 5170 - Order nr: 2180113				
	*	DEREK	D KEW SHIFT: Night Breakdown	
			CONTACT PERSON: DAVID HAND	
	*	92	TRAVEL 350 KM Ö Å0.98CTS PER KM	
			Travel to Wongan Hills.	
		LO-194	TRAVELLING TIME	4.4
		VO-2373400	Unit injector, replace (one)	2.8
		VO-85013343	UNIT INJECTOR, EXC	1
		VO-21801388	YOKE	1
		VO-21344774	FLANGE SCREW	1
			CONTACT NUMBER: 0419 944 955	
			Driver: Kevin 0407 963 200	
			NEW UNIT SN: 23408629.	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-2361500	Injector function	0.2
		VO-2302200	Fuel supply pressure, check. Oscilloscop	0.5
 2016-10-30 - Mileage: 1 - Order nr: 2179784				
			KEWDALE MERCHANDISE 149.16	
		OTH-VTSKELJKT2XL	SKELETON BLACK JACKET 2XL	1
 2016-10-21 - Mileage: 33 - Order nr: 8724067				
			60100 C/O WHEEL ALIGNMENT CHECK MACK/VOLVO 280.00	
	*	6010000	Wheel alignment	

PC	Type	Code	Description (Original)	#
	*	60	SUBLET - C/O WHEEL ALIGNMENT	
			0812769kt	
			part no: 21607575	
			cc reference: 200411749	
🔍 2016-10-21 - Mileage: 33 - Order nr: 8500626				
			60100 C/O WHEEL ALIGNMENT CHECK MACK/VOLVO 280.00	
	*	6010000	Wheel alignment	
	*	60	SUBLET - C/O WHEEL ALIGNMENT	
			0812769kt	
🔍 2016-10-18 - Mileage: 33 - Order nr: 8723990				
			Evap Air Con Mochila Delta 4000.00	
	*	850	S&F EVAP AIR CON MOCHILA	
	*	80	SUBLET - S&F EVAP AIR CON MOCHILA	
			0812304kt	
			*****	
			Credit done - reference: 8500616	
			original job card 8722393	
🔍 2016-10-17 - Mileage: 33 - Order nr: 8722407				
			Balistic Phone - TF100 inc High Gain A 1500.00	
	*	810	S&F BALLISTIC PHONE TF100	
			INCLUDING HIGH GAIN AERIAL	
	*	80	SUBLET - S&F TF100 BALLISTIC PHONE	
			0812309kt	
🔍 2016-10-17 - Mileage: 33 - Order nr: 8722397				
			7790NT04 Wheel Nut Indicators 8X4 161.00	


































PC	Type	Code	Description (Original)	#
		LO-770	S&F WHEEL NUT INDICATORS	0.75
		OTH-DTLRY33	WHEEL INDICATORS LONG REACH	40
		91	CONSUMABLES	
2016-10-17 - Mileage: 1 - Order nr: 8722416				
			9016NT01 S&F MUDFLAPS TO FRONT BULLBAR - VOLVO 317.42	















































			NOT REQUIRED TO BE DONE	
2016-10-17 - Mileage: 1 - Order nr: 8722393				
			Evap Air Con Mochila Delta 4000.00	
		850	S&F EVAP AIR CON MOCHILA	
		80	SUBLET - S&F EVAP AIR CON MOCHILA	
			0812304kt	
2016-10-17 - Mileage: 1 - Order nr: 8500616				
			Evap Air Con Mochila Delta 4000.00	
		850	S&F EVAP AIR CON MOCHILA	
		80	SUBLET - S&F EVAP AIR CON MOCHILA	
			0812304kt	
2016-10-12 - Mileage: 33 - Order nr: 8723895				
			890 CHANGE TURN TABLE PLATE AND FEET 500.00	
		LO-890	CHANGE TURN TABLE PLATE AND FEET	4
		UNK-CS54581	BASE PLATE AND FOOT ASSEMBLY	1
2016-10-12 - Mileage: 1 - Order nr: 8722400				
			9012NT01 Seat Covers Volvo Cloth 655.00	
		LO-9012NT0	S&F VOLVO CLOTH SEAT COVERS	1
		VO-20797177	FH L/H SEAT COVER	1








































PC	Type	Code	Description (Original)	#
		VO-20797175	FH R/H SEAT COVER	1
		91	CONSUMABLES	
2016-10-10 - Mileage: 33 - Order nr: 8722413				
			1111NT01 PRE DELIVERY INSPECTION 735.00	
		LO-1111NT0	PRE - DELIVERY INSPECTION VOLVO	7
2016-10-10 - Mileage: 33 - Order nr: 8722411				
			8550NT04 Dash mat - Volvo FH/FM 158.00	
		LO-8550NT0	S&F DASH MAT_FH4	0.3
		OTH-DAMAT-FH4	DASH MAT VOLVO FH(4)	1
2016-10-07 - Mileage: 1 - Order nr: 8722405				
			6 " Exhaust Stack Return old one to Dave 350.00	
		LO-890	S&F 6" EXHAUST STACK	1.7
		OTH-CRSP6560	EXHAUST STACK CURVED REDUCED	1
		OTH-FBC600C	EXHAUST CLAMP 6" CHROME	1
		91	CONSUMABLES	
2016-10-06 - Mileage: 1 - Order nr: 8722409				
			S & F clearance lights 404.00	
		LO-353	S&F CLEARANCE LIGHTS TO REAR	3
		91	CONSUMABLES	
2016-09-20 - Mileage: 33 - Order nr: 8723505				
		LO-252	D16G VERTICAL MUFFLER WELDING	1
			- R&R and weld muffler as per AS 25 209/PSI 5101	
		VO-8842300	MID 232 SID 1 Driver air bag ignition lo	0.6
		VO-3110000	Battery, energy storage system. Secondar	1
		VO-2586200	SCR catalytic muffler, replace	1.3










































PC	Type	Code	Description (Original)	#
		VO-8100000	Body and cab framework, general	0.5
			Power Divider Cylinder Option	
			part no: 21395509	
		VO-3660000	Automatic monitoring and control. Second	2
			Fit camera bracket 82809782 to RH & 82809776 to LH	
			Argus case 1-3632963331	
			Apply Silastic to hole in plastic cover at rear cab channel	
			Fit a longer cable with a straight lug, not 90 degrees	
			Fit full length cover to the driver's side air bag	
			Argus case 1-4293139157	
		VO-3730000	Cable system, front. Secondary operation	3
			Reposition directly under the connectors & run under chassis	
			Power Divider autofunction	
			D16G Vertical muffler Welding	
			Cab mudguard with storage locker, without air kit	
			Cab mudguard without storage locker without air kit	
			Cab mudguard without storage locker with air kit	
			Cab mudguard with storage locker with air kit	
			Drivers mirror blows in	
			FE Transmission Cover	
			Dust entering cab	
			Check for all outstanding campaigns	
			Battery earth cable can break at chassis	
			Trans coolant hoses coming off at engine block	
			Relay & trailer valves relocate	

PC	Type	Code	Description (Original)	#
	🔍		Jackshaft univeral joints can fail on Tri-Drive	
	🔍		Dust getting into side mount 90L adblue tank	
	🔍		Cab rear air bags leak due ot heat	
	🔍		Oil residue can get into diff breather hoses	
	🔍		Steering pipes can come off under steering box	
	🔍		Door seals adrift	
	🔍		Starter Motor failing prematurely	
	🔍		Battery label advising how to jump start trucks	
	🔍		Check parameters for suspension	
	🔍		Check the parameters in VDA+ suspension	
	🔍		FE Side bin lift overheat front wheel bearings	
	🔍		EBA wiring getting squashed under load	
	🔍		*****	
📌	🔍	VO-82809782	BRACKET	1
📌	🔍	VO-82809776	BRACKET	1
📌	🔍	VO-984733	FLANGE SCREW	10
📌	🔍	OTH-F114	AIR BAG COVER	1
📌	🔍	OTH-57141	LUG 70-10	1
📌	🔍	OTH-D258B	H/D HEAT SHRINK	1
📌	🔍	30	LUG AND HEATSHRINK	
	🔍		Argus case 1-5939500866	
	🔍		part no: 21558237	
	🔍		part no: 22287351	
	🔍		Argus case 1-4020601431	
	🔍		cc reference: 200411572	

PC	Type	Code	Description (Original)	#
	*	91	CONSUMABLES	
 2016-09-20 - Mileage: 22 - Order nr: 8722410				
			9116NT01 Walk Plate Alloy Checker to Front of T 866.00	
		LO-9116NT0	S&F ALLOY CHECKER PLATE TO CHASSIS	2.5
	*	91	CONSUMABLES	
		OTH-61104	36MM SURAF0AM	4
		OTH-E3L1BP9R	COMP LATCH	2
		OTH-E3K9R	COMP/KEY 9MM ROUND	1
		OTH-KPCHSSISPLT	CHASSIS PLATE 2200X820	1
 2016-09-14 - Mileage: 33 - Order nr: 8722398				
			2340NT02 Powder Coat Two Fuel Tanks 1630.00	
			Tanks same as Bull Bar Powercoating 1.00	
			colour Sliver Glow Pearl	
			R & R TANKS & POWDERCOATING	
		LO-2340NT0	R&R POWDERCOAT TWO FUEL TANKS	6
			R & R TANKS & POWDERCOATING	
	*	SKY1	POWDER COAT FUEL TANK SUBLET POWDER COAT	
			FUEL TANK	
			0812305kt	
			SUBLET POWDER COAT FUEL TANK	
 2016-09-14 - Mileage: 22 - Order nr: 8722402				
			9019NT04 Yard Hitch with Single Air Line to Rea 1290.00	
		LO-9019NT0	S&F YARD HITCH SINGLE AIR LINE_FH4	4.5
	*	91	CONSUMABLES	
		VO-945884	NUT,M16	4

PC	Type	Code	Description (Original)	#
		VO-980464	STRIP CLAMP	100
		OTH-38B	3/8 BSP SOCKET	1
		OTH-ABF215	COUPLING 3/8F	1
		VO-984834	FLANGE SCREW	4
		VO-994693	NIPPLE	1
		OTH-VB010	BALL VALVE 3/8 BLUE HANDLE	1
		OTH-MZ16HTW	WASHER 16mm HIGH/T ZINC	4
		MK-FT3325X6	BRASS PIPE	1
		OTH-YHBP1	YARD HITCH BACK PLATE SINGLE	1
		VO-980833	12MM AIR LINE	15
		VO-991083	SWIVEL	1
		VO-991075	NIPPLE	2
		VO-991980	T NIPPLE	1
		VO-984853	FLANGE SCREW	4
		VO-992328	FLANGE NUT	4
		AU2-9703-ROCKINGER805	NON-AUTOMATIC TRAI	1
		VO-20428158	CABLE TIE	2
 2016-09-14 - Mileage: 22 - Order nr: 8722396				
			8310NT04 Weather Shields FH 350.00	
		LO-8310NT0	S&F WEATHERSHIELDS_FH4	1
		VO-84165756	WIND DEFLECTOR KIT	1
		91	CONSUMABLES	
 2016-09-14 - Mileage: 22 - Order nr: 8722394				
			8500NT04 Cab Gun Blower 80.00	
		LO-8500NT0	S&F CAB GUN BLOWER	0.5

PC	Type	Code	Description (Original)	#
		MK-9732-BG12	DUST BLOWER	1
		91	CONSUMABLES	
 2016-09-07 - Mileage: 33 - Order nr: 8722415				
			3520NT02 WIRE UP BULLBAR INDICATORS_FH4 534.40	
		LO-3520NT0	WIRE UP BULLBAR INDICATORS_FH4/FM	4.5
		OTH-QNC12	NYLON CONDUIT 12MM	0.5
		OTH-12M16	ADAPT BODY KIT	1
		OTH-5823TW	TWIN CORE CABLE	15
		VO-948211	STRIP CLAMP	30
		OTH-56707	CONV TUBE 7MM	10
		91	CONSUMABLES	
		OTH-FHO-N54412	FUSE HOLDER MINI IN LINE BLADE	2
  2016-09-06 - Mileage: 33 - Order nr: 8723504				
		VO-3520000	Lighting, front. Secondary operation num	4
			- Carry out glueing procedure as per GB	
		30	SUBLET - SUPPLY OF GLUE	
		VO-8300000	Doors and lids, general	0.25
			- Glue in 4 rubber stops	
			argus case 1-3597953021	
			Drivers door rubber stops	
			Bunk hinge mod	
			Headlight panels	
			Argus case 1-2756213791	
			part no: 21874457	
			cc reference: 200410648	

PC	Type	Code	Description (Original)	#
	*	91	CONSUMABLES	
 2016-09-06 - Mileage: 22 - Order nr: 8722414				
			1021NT02 UNLOAD SINGLE NEW TRUCK WITH AIR KIT 577.50	
		LO-1021NT0	UNLOAD SINGLE NEW TRUCK WITH AIR KIT	2.5
		LO-891AK	FIT AIR KIT ALL VOLVOS	3
 2016-09-06 - Mileage: 22 - Order nr: 8722403				
			3111NT01 Light VisionX LED Mirror Mounted Loadi 970.00	
		LO-3111NT0	S&F LED VISION X MIRROR LIGHTS	5
	*	91	CONSUMABLES	
		OTH-5823TW	TWIN CORE CABLE	10
		OTH-56707	CONV TUBE 7MM	10
		VO-948211	STRIP CLAMP	30
		OTH-WL-10WRS	LED 10W MIRROR LIGHTS ROUND	2
		VO-979002	TERMINAL	5
		VO-990060	CABLE TERMINAL	1
		VO-21244697	RELAY	1
		VO-25392050	RELAY RETAINER	1
		VO-978304	CABLE TERMINAL	1
		OTH-22207188A	SWITCH COVER	1
 2016-09-06 - Mileage: 22 - Order nr: 8722395				
			3930NT03 UHF Electraphone TX4500WS Remote Mount 930.00	
		LO-3930NT0	S&F GME TX4500W UHF RADIO SUIT_FH4	3
		MK-9771-TX4500WS	UHF RADIO WIRELESS GME	1
		OTH-COM-LEM6P	HAND MICROPHONE EXTENSION LEAD	1
		VO-21138398	HOUSING	1

PC	Type	Code	Description (Original)	#
		VO-20798809	CABLE TERMINAL	2
		91	CONSUMABLES	
		VO-948211	STRIP CLAMP	30
2016-09-06 - Mileage: 1 - Order nr: 8722401				
			Spotlights 2 x Lightforce HID-CANCELLED 1841.00	
			Delete Orange Spotlight covers 1.00	
			Substitute Lightforce LED ilo HID	
			S&F SPOTLIGHTS 2X LIGHTFORCE LED	
		LO-350	S&F SPOTLIGHTS 2X LIGHTFORCE LED	4
		OTH-CBLED215S	LED SPOT LIGHT 215MM 108W SNGL	1
		OTH-CBLED215SD	LED DRIVE LIGHT 215MM 108W SGL	1
		OTH-5823TW	TWIN CORE CABLE	20
		OTH-56707	CONV TUBE 7MM	10
		VO-21244697	RELAY	1
		VO-25392050	RELAY RETAINER	1
		VO-979002	TERMINAL	5
		VO-990060	CABLE TERMINAL	1
		VO-3985620	ADAPTER	1
		OTH-DT2-2	2 CIRC DEUTSCH	2
		91	CONSUMABLES	
2016-08-26 - Mileage: 33 - Order nr: 8723910				
			60100 C/O WHEEL ALIGNMENT CHECK MACK/VOLVO 280.00	
		6010000	Wheel alignment	
		60	SUBLET - C/O WHEEL ALIGNMENT	
			0812769kt	




PC	Type	Code	Description (Original)	#
2016-08-25 - Mileage: 33 - Order nr: 8723873				
	📅		93 FUEL 07/10/2016 146.40	
📌	*	93	FUEL	
	📅		07/10/2016	
	📅		120.10 litres	
2016-08-19 - Mileage: 22 - Order nr: 8722404				
	📅		9002NT08 S&F KHITCH FIXED TURNTABLE 3.5" TEFLON 2749.65	
📌	🔧	LO-9002NT0	S&F KHITCH FIXED TURNTABLE 3.5" TEFLON	4
📌	🔧	OTH-MZ1655G8B	BOLT 16X55 ZINC PLATE 8.8	12
📌	🔧	OTH-MZ16HTW	WASHER 16mm HIGH/T ZINC	24
📌	🔧	OTH-MZ16NYL	NYLOC NUT 16mm ZINC PLATED	12
📌	*	91	CONSUMABLES	
📌	*	900KH8	SUPPLY KHITCH FIXED 3.5" TEFLON TURNTABL	
	📅		0812308kt	
	📅		Teflon Wear Plate , Predrilled Ö100mm 1.00Turntable	
	📅		height to be 1275mm approx mounted 200mm behind centre of 1s	
	📅		t drive	
	📅		Pre drill for T/T movement to 100mm back an forward	
	📅		serial number for turntable: MK3-18132	
2016-08-02 - Mileage: 33 - Order nr: 8722412				
	📅		1212NT01 C/O PITS, REGO & LICENCE 1000.00	
	📅		PITS, REGO & LICENCE	
📌	🔧	LO-1212NT0	C/O PITS, REGO & LICENCE	4
	📅		PITS, REGO & LICENCE	
📌	🔧	OTH-85113349L	ADBLUE PER LITRE	60

PC	Type	Code	Description (Original)	#
	*	80	SUBLET - VEHICLE MODIFICATION INSPECTION	
			0812749kt	
🔍 2016-07-28 - Mileage: 33 - Order nr: 8722408				
			Water Tank & Tool Box to 2nd Steer Axle 1000.00	
		LO-891	S&F WATER TANK & TOOLBOX TO 2ND STEER AX	10.1
		OTH-RJ23	VOIR 23LTR	1
		OTH-TB029	TOOL BOX 600X400X500	1
		VO-990950	FLANGE LOCK NUT	12
		VO-984738	FLANGE SCREW	4
		VO-984736	FLANGE SCREW	4
		VO-984735	FLANGE SCREW	4

			OVER ESTIMATE	
			TOOLBOX PACK IS Å1000.00	
			WATER TANK PACK IS Å400.00	
			TOTAL Å1600.00	

	*	91	CONSUMABLES	
🔍 2016-07-27 - Mileage: 33 - Order nr: 8722406				
			Short Tail Suzi Coils in Lieu of Long 100.00	
		LO-860	S&F SHORT SUZI COILS,	0.51
		MK-ABC78020	SUZI COIL	1
	*	91	CONSUMABLES	
🔍 2016-07-27 - Mileage: 33 - Order nr: 8722399				
			9111NT02 Hydraulics Semi Tipper "I" shift with 12375.00	

PC	Type	Code	Description (Original)	#
	📄		HYD HOSES TO BE 3 METERS LONG 2 X FEMA 1.00	
📌	🔧	LO-890	S&F SEMI TIPPER "I" SHIFT WITH DIVERTER	50.5
	📄		HYDRAULICS.	
📌	*	80	SUBLET - SUPPLY HYDRAULIC PARTS	
📌	*	80	SUBLET - C/O HYDRAULIC HOSE UP	
	📄		0812306kt	
	📄		0812307kt	
📌	🔧	VO-990861	FLANGE SCREW	23
📌	🔧	VO-984756	FLANGE SCREW	12
📌	🔧	VO-984757	FLANGE SCREW	8
📌	🔧	VO-994459	FLANGE SCREW	4
📌	🔧	VO-984834	FLANGE SCREW	15
📌	🔧	OTH-TP2	BRACKET VOLVO REAR DOUBLE AIR	1
📌	🔧	OTH-03193202	1/2"BSP BLACK SOCKET	2
📌	*	80	SUBLET - SUPPLY STEEL	
	📄		ACDC order CS-53064kt	
📌	🔧	OTH-R-TRAIN-BLACK	ROADTRAIN Å COVER BLACK	1
📌	🔧	UNK-CS53101	PAINT	1
	📄		REF INV: 316212 - GLOBAL	
📌	🔧	VO-1629141	CONTROL STICKER	1
📌	🔧	VO-1629142	SUPPLY STICKER	1
📌	🔧	MK-ABCABF198	COUPLING, MALE 1/2	1
📌	🔧	MK-ABCABF201	ADAPTOR, MALE 3/8	1
📌	🔧	OTH-VB010	BALL VALVE 3/8 BLUE HANDLE	2
📌	🔧	VO-948211	STRIP CLAMP	30

PC	Type	Code	Description (Original)	#
		OTH-QNC16	NYLON CONDUIT	5
		VO-3963412	7 PIN MALE PLUG	1
		VO-3963409	CABLE TERMINAL	4
		OTH-15324974	BLUE WIRING GROMET	4
		VO-3985620	ADAPTER	1
		VO-21500715	SWITCH AUX 3	1
		VO-21500718	SWITCH AUX4	1
		OTH-22207188A	SWITCH COVER	3
		VO-20375162	CABLE TERMINAL	4
		VO-21244697	RELAY	3
		VO-25392050	RELAY RETAINER	3
		VO-979002	TERMINAL	15
		VO-990060	CABLE TERMINAL	1
		VO-978304	CABLE TERMINAL	2
		OTH-5873TC	3MM 7 CORE CABLE	6
		OTH-5823TW	TWIN CORE CABLE	2
		VO-20707815	COVER	1
		VO-84531138	MIRROR	1
		VO-984735	FLANGE SCREW	8
		VO-990950	FLANGE LOCK NUT	8
		VO-984855	FLANGE SCREW	2
		VO-984862	FLANGE SCREW	2
		VO-984864	FLANGE SCREW M14 X 110	1
		VO-992328	FLANGE NUT	6
		OTH-230808	3/8"BSP*1/2"BSP ADAPTOR	2

PC	Type	Code	Description (Original)	#
		VO-980833	12MM AIR LINE	4
		VO-1629141	CONTROL STICKER	1
		VO-1629142	SUPPLY STICKER	1
		VO-8039588	WARNING	1
		OTH-5874TC	4mm 7CORE CABLE	1
		OTH-CAB-6-100TS	CABLE 6MM TWIN	1
		OTH-QNC16	NYLON CONDUIT	1
		OTH-DT2-2	2 CIRC DEUTSCH	2
		VO-25371156	CONNECTOR	2
		VO-3963412	7 PIN MALE PLUG	2
		OTH-15324974	BLUE WIRING GROMET	14
		VO-984945	CABLE TERMINAL	14
		VO-3963409	CABLE TERMINAL	14
		VO-984744	FLANGE SCREW	3
		VO-990950	FLANGE LOCK NUT	3
		VO-984815	FLANGE SCREW	2
		VO-990942	FLANGE NUT	2
		OTH-31095610	1/4X1/8 BSP MALE ELBOW	3
		91	CONSUMABLES	