

REPAIR ORDER

A02-46
SEP

P.O. Box 338
Medicine Hat, Alberta
T1A 7G1

Phone: (403) 526-4873
Fax: (403) 528-2515

DATE October 14th 2023

DRIVER Kyle Deatch

No. **11218**

UNIT # 163

Hours 13709.9

KM's _____

(Above to be completed fully by Drivers)

EXPLANATION: ① Coolant leak above exhaust.

Inventory Parts

Cost

② Drivers side high beam out.

MECHANIC'S COMMENTS: _____

Direct Parts

Cost

① Dunlop changed trans. cooling line

② repaired wire on KB. drive side high beam

Total

Total

DATE REPAIRED: October 20/23

MECHANIC'S INITIALS: [Signature]

HOURS: _____

KM's: _____

DATE ROAD TESTED: _____

DRIVER: _____

DRIVER:

REPAIR ORDER

P.O. Box 338
Medicine Hat, Alberta
T1A 7G1

Phone: (403) 526-4873
Fax: (403) 528-2515

DATE Feb 18/23 DRIVER Darryl No. **3701**

UNIT # 163 Hours 13149 KM's 627484
(Above to be completed fully by Drivers)

EXPLANATION:

Inventory Parts

Cost

① Major air leak under cab
when you use hand brake

② Right hand windshield
took a good rock.

③ Reverse lights in skirt
don't work very well with truck
unning

④ Backup alarm is very quiet

Total

MECHANIC'S COMMENTS:

Direct Parts

Cost

① repaired air leak under cab
(air line rubbed through under)

② Elmer and Harold's Replaced Windshield

③ changed reverse light switch
and fixed problem with

④ reverse lights and backup
alarm

Total

DATE REPAIRED: March 7/23

MECHANIC'S INITIALS: [Signature]

HOURS: _____

KM's: _____

DATE ROAD TESTED: _____

DRIVER: _____



Phone: (403) 526-4873
Fax: (403) 528-2515

DATE Feb 17/25 DRIVER Buck No. **3700**

UNIT # 140 Hours 13054 KM's 383720
(Above to be completed fully by Drivers)

EXPLANATION:

Inventory Parts

Cost

~~Alcohol~~ Alcohol sniffer corroded through - leaking air

MECHANIC'S COMMENTS:

Direct Parts

Cost

Installed new Alcohol siffer

Total

DATE REPAIRED: March 1/23 MECHANIC'S INITIALS: DD

HOURS:

KM's: _____

DATE ROAD TESTED: _____ DRIVER: _____

REPAIR ORDER

P.O. Box 338
Medicine Hat, Alberta
T1A 7G1

Phone: (403) 526-4873
Fax: (403) 528-2515

DATE Jan 8/2023

DRIVER Don

No. **3689**

UNIT # 163

Hours 13022

KM's 625629

(Above to be completed fully by Drivers)

EXPLANATION:

Inventory Parts

Cost

① Winch brake with not hold a load

② Back up Lights only worked for about 2 min.

③ The A/C Fans on The roof ran with The Key on

Total

MECHANIC'S COMMENTS:

Direct Parts

Cost

① installed new brake parts Feb 23
DJ & DK

② backup lights switch changed on top of transmission Feb 23/23

③ A/C Fans repaired at Dunlop

Total

DATE REPAIRED: _____

MECHANIC'S INITIALS: DJ

HOURS: _____

KM's: 626000

DATE ROAD TESTED: _____

DRIVER: _____



Phone: (403) 526-4873
Fax: (403) 528-2515

DATE Feb 19/23 DRIVER Dean B No. **3698**

UNIT # 155 Hours 14906.4 KM's 702482
(Above to be completed fully by Drivers)

EXPLANATION: _____ Inventory Parts Cost

① Winch is Seeping down
not able to hold stuff

MECHANIC'S COMMENTS: _____	Direct Parts _____	Cost _____
----------------------------	--------------------	------------

① installed new brake disks and spring bearing in wheel

DATE REPAIRED: March 16/23 MECHANIC'S INITIALS: DP

HOURS:

DATE ROAD TESTED: _____ DRIVER: Leah B

KM's: _____

REPAIR ORDER

P.O. Box 338
Medicine Hat, Alberta
T1A 7G1

Phone: (403) 526-4873
Fax: (403) 528-2515

DATE 26/12/2022

DRIVER Don

No. **3682**

UNIT # 163

Hours 13009

KM's 625209

(Above to be completed fully by Drivers)

EXPLANATION:

	Inventory Parts	Cost
① windshield wiper motor		
② The A.B.S.		
③ Needs a clutch set and The is very hit the clutch brake		
④ mud flaps need To be rebuilt.		
⑤ webasto		
	Total	
MECHANIC'S COMMENTS:	Direct Parts	Cost
① } all repairs done at Dunlop		
② } Westernstar		
③ }		
④ rebuilt by Excubus Welding		
⑤ repaired at Dunlop Westernstar		
	Total	

DATE REPAIRED: January 2023

MECHANIC'S INITIALS: [Signature]

HOURS: _____

KM'S: _____

DATE ROAD TESTED: _____

DRIVER: _____

REPAIR ORDER

P.O. Box 338
Medicine Hat, Alberta
T1A 7G1

Phone: (403) 526-4873
Fax: (403) 528-2515

DATE Sept 20 / 2022 DRIVER Don No. **2931**

UNIT # 163 Hours 12522 KM's 602614
(Above to be completed fully by Drivers)

EXPLANATION:

Inventory Parts

Cost

① need to repair step
on The Drivers side

② Look at The ABS

Total

MECHANIC'S COMMENTS:

Direct Parts

Cost

① welded up aluminum
Step Sept 24/22

Total

DATE REPAIRED: _____ MECHANIC'S INITIALS: _____

HOURS: _____

KM's: _____

DATE ROAD TESTED: _____ DRIVER: _____