



Phone: (403) 526-4873
Fax: (403) 528-2515

DATE OCT 11/2022 DRIVER Matt Volk No. **2937**

UNIT # 162 Hours 12183 KM's 552430
(Above to be completed fully by Drivers)

EXPLANATION:	Inventory Parts	Cost
Starter is hanging up		
have to smack with hammer		
to start		

Fuel Sender not working (No fuel gauge)		
--	--	--

MECHANIC'S COMMENTS: _____	Direct Parts _____	Cost _____
----------------------------	--------------------	------------

① starter replaced at Peterbilt		
------------------------------------	--	--

② Fuel gage checked at Peterbuilt		
--------------------------------------	--	--

DATE REPAIRED: October 2022 MECHANIC'S INITIALS: af

HOURS:

KM's: _____

DATE ROAD TESTED: _____ DRIVER: _____

DRIVER: _____



Phone: (403) 526-4873
Fax: (403) 528-2515

(Above to be completed fully by Drivers)

EXPLANATION:	Inventory Parts	Cost
(U) Tensioner Pulley came apart and wrecked belt		
	Total	

MECHANIC'S COMMENTS:	Direct Parts	Cost
Installed new bearings and new belt		
	Total	

DRIVER: _____