



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

T01-22
Nov

Ship To:

Branch CAMROSE			*REPRINT*		
Date 03/17/26	Time 22:20:08 (B)	Page 01			
Account No	Phone No	Inv No W30657			
Ship Via	Purchase Order				
Tax ID No					
		Salesperson 137			

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C019330	X9 1000 COMBINE	744	1H0X910XJN0820740	08/01/24	
	X9 1000	524	RG6136U004039 HX404	07/31/26	1250 X

GST# 895703353

SEGMENT# 1 C 188 10-900-010 02/11/26 02/12/26

BRI INSPECTION

14.83 HRS

Repair:

Ran unit up and checked over. Made a list of service and repairs.

ADDITIONAL DESCRIPTION:

*O/S LABOR-CAMROSE MACHINE AND WELDING- MACHINE

YOLK-INV#21-24932*

-Has comp powergard \$1,000 deductible until July 31 2026.

-Make sure to go through field ready checklist.

AXE86003	Bearing With Ho	1-	247.51	247.51-
	Bearing With Housing			

PARTS 247.51-

LABOR 2595.25

16001000

SEGMENT TOTAL==> 2347.74

SEGMENT# 2 C 196 NA 02/17/26 02/17/26

SERVICE

7.50 HRS

Update engine controller software. 2.0 hrs. Done

Change final drive oil. 2.0 hrs. - JB

Change tank breather filters. .5 hrs. Done

Change chopper 2 speed gear case oil. 1.0 hrs. Done

Tighten up lower rad hose. .5 hrs. Done

Top up low coolant level. .5 hrs. Done

Blow out cooling package. 1.0 hrs. Done

EF4662	RECYC FEE OIL	2	.55	1.10
--------	---------------	---	-----	------

EF4665	RECYC FEE OIL	1	.48	.48
--------	---------------	---	-----	-----

CONTINUED ON PAGE 02

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St
Camrose, AB T4V 3W9
Phone: 780-672-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To:

Invoice To:

Branch CAMROSE		
Date 03/17/26	Time 22:20:08 (B)	Page 02
Account No	Phone No	Inv No W30657
Ship Via		Purchase Order
Tax ID No		
		Salesperson 137

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C019330	X9 1000 COMBINE	744	1H0X910XJN0820740	08/01/24	
	X9 1000	524	RG6136U004039 HX404	07/31/26	1250 X
EF4666		RECYC FEE OIL	1	2.40	2.40
H216169		FUEL TANK VENT	2	32.93	65.86
TY22462		CLAMP.NO 4	1	1.48	1.48
TY26575		COOL GARD P 4L	2	27.03	54.06
TY26816		80W90 G/L 18.9L	1 O	221.33	221.33
TY6354		HY-Gard 3.78L	1	31.34	31.34
			PARTS		378.05
			LABOR		1312.50
10102001	16001000		SEGMENT TOTAL==>		1690.55

SEGMENT# 3 C 188 NA 02/17/26 02/17/26
LEFT HAND SIDE 3.00 HRS

Repair:

Loosened off the unloading auger drive belt and removed.
Loosened off front end drive belt and removed belt.
Loosened off the rotor belt tension, removed the belt and replaced. Set the drive rotor sheeve cap and tensioned the belt, reinstalled the other belts and tensioned to specification.

ADDITIONAL DESCRIPTION:

Replace rotor drive belt. 3 hrs.

HXE107859	ROTOR DRIVE	1	1455.07	1455.07
			PARTS	1455.07
			LABOR	525.00
10102001	16001000		SEGMENT TOTAL==>	1980.07

SEGMENT# 4 C 188 NA 02/17/26 02/17/26
RIGHT HAND SIDE 7.00 HRS

Repair:

Checked front right concave actuator for no movement.

CONTINUED ON PAGE 03

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4483

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To:

Branch CAMROSE		
Date 03/17/26	Time 22:20:08 (B)	Page 03
Account No	Phone No	Inv No W30657
Ship Via		Purchase Order
Tax ID No		
		Salesperson 137

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C019330	X9 1000 COMBINE	744	1H0X910XJN0820740	08/01/24	
	X9 1000	524	RG6136U004039 HX404	07/31/26	1250 X

Removed

build up around the front of the concave. performed concave calibration. Operation was corrected.

ADDITIONAL DESCRIPTION:

Replace key on lower clean grain sprocket. 1.5hrs. -

Removed bearing, disconnected chain, move sprocket and took out old key. Cut new key, re-installed bearing and chain. - JB

Replace tensioner arm bushings - has play. 2.0hrs. -Removed pulley, removed seals and bushings. Installed new bushings and seals, re-installed pulley. - JB

Clean activation camera lens. - Wiped down camera lens with glass cleaner. - JB .5hrs.

Check front concave for binding, code for no movement.

3.0hrs.

AA5607R	SEAL.9600	2	9.82	19.64
---------	-----------	---	------	-------

AXE86003	Bearing With Ho	1	247.51	247.51
----------	-----------------	---	--------	--------

Bearing With Housing

H171061	BUSHING	2	15.41	30.82
---------	---------	---	-------	-------

PARTS 297.97

LABOR 1225.00

10102001	16001000	SEGMENT TOTAL==>	1522.97
----------	----------	------------------	---------

SEGMENT# 5 C 188 NA 02/17/26 02/17/26

PLATFORM

3.50 HRS

Repair:

Replaced the table auger height bushings that were missing.

Adjusted the auger to the correct height. Removed the rear stripper channels and replaced with new channels. The

stripper plates were bent and twisted as well replaced the

CONTINUED ON PAGE 04

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To:

Branch CAMROSE		
Date 03/17/26	Time 22:20:08 (B)	Page 04
Account No	Phone No	Inv No W30657
Ship Via		Purchase Order
Tax ID No		
		Salesperson 137

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C019330	X9 1000 COMBINE	744	1H0X910XJN0820740	08/01/24	
	X9 1000	524	RG6136U004039 HX404	07/31/26	1250 X

plates with new ones. Adjusted the stripper plates to the
auger. Adjusted the table auger drive chain tension.

ADDITIONAL DESCRIPTION:

Adjust table auger drive chain tension. .5hrs.
Replace missing auger height bushings, adjust height.
1.0hrs.
Replace bent rear stripper brackets bent and twisted.
2.0hrs.

AH231461	FINGER/HOLDOWN	1	32.91	32.91
HXE120389	Sleeve	4 N	42.05	168.20
HXE157112	Plate	2 N	102.59	205.18
HXE165772	Stripper	2 N	579.00	1158.00
	PARTS			1564.29
	LABOR			612.50
10102001	16001000	SEGMENT TOTAL==>		2176.79

SEGMENT# 6 C 188 NA 02/17/26 02/17/26
RUN AND CHECK 2.00 HRS

Repair:

Ran unit up and checked operation, operation was normal.

	LABOR	350.00
16001000	SEGMENT TOTAL==>	350.00

***** WORK ORDER TOTALS *****

	INTERNAL	CUSTOMER
PARTS	3447.87	
LABOR	6620.25	
O/S LABOR & MAT	42.00	
CONTINUED ON PAGE 05		

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To:

Invoice To:

Branch CAMROSE		
Date 03/17/26	Time 22:20:08 (B)	Page 05
Account No	Phone No	Inv No W30657
Ship Via		Purchase Order
Tax ID No		
		Salesperson 137

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C019330	X9 1000 COMBINE	744	1H0X910XJN0820740	08/01/24	
	X9 1000	524	RG6136U004039	HX404 07/31/26	1250 X
			SERV ACCESORIES		100.00
			INTERNAL TOTAL		10210.12

1-877-913-3373

WWW.BRILTD.COM

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



CAMROSE:
4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

KILLAM:
5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

PROVOST:
P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

WAINWRIGHT:
1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To:

Invoice To:

Branch		
CAMROSE		*REPRINT* CNYYYY
Date	Time	Page
02/03/26	14:38:30 (O)	01
Account No	Phone No	Inv No
		P25187
Ship Via		Purchase Order
Tax ID No		
		Salesperson
		1

PARTS INVOICE

ORDER#: 220976

GST# 895703353

***** BATTLE RIVER IMPLEMENTS LTD STORE HOURS *****
***** OPEN WEEKLY 8:00-5:00 CLOSED ON SATURDAYS *****
***** AFTER HOURS CALL 1-877-913-3373 *****

Part#	Description	Bin	ORD	ISS	SHP	B/O	UTTTT	Price	Amount
X9-225	X9 .225 CONCAVE CS		6	6		RETAIL		1085.00	
					6			899.99	5399.94
X9-435	X9 .435 CONCAVE CS		6	6		RETAIL		1085.00	
					6			899.99	5399.94
FRT	FREIGHT	ANG	12	12	12			15.00	180.00

STK#: C019330 ACC#: 16001000PER VINCE EDWARDS TOTAL INTERNAL 10979.88

Your total savings today was \$2220.12

WWW.BRI.LTD.COM

RETURN POLICY: All returns are subject to Battle River Implements' return policy. All items must be in sellable condition and in original, unopened packaging. Electrical components, opened kits, and items under \$20.00 or listed as non-returnable by John Deere on JDPoint are non-returnable. However, parts under \$20.00 and Deere-listed non-returnable may be accepted within 30 days via daily return with a 25% restocking fee. Stocked parts returned within 10 days are not subject to a restocking fee; between 10 days and 1 year, a 25% fee applies; after 1 year, the fee is 25%. Special-order parts returned within 30 days (if returnable through Deere) are subject to a 25% restocking fee; after 30 days, the fee is also 25%. Returns from other dealers incur a 35% restocking fee.

X

Signature