

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

TO1-24
NOV

Ship To:

Invoice To:

Branch		CAMROSE		*REPRINT*	
Date		Time		Page	
01/15/25		22:20:06 (B)		01	
Account No		Phone No		Inv No	
				W29029	
Ship Via			Purchase Order		
Tax ID No					
				Salesperson	
				137	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016693	S790 STS COMBINE	1E	1H0S790STKT805180	05/01/20	
	S790S	1105E			

GST# 895703353

SEGMENT# 1 C 10 10-900-010 12/11/24 11/27/24
BRI INSPECTION 11.40 HRS
-O/S LABOR & MAT, ABC FIRE SAFETY, PRESSURE GAUGE FOR FIRE
EXT, INVOICE3 015732

	LABOR	1995.00
16001000	SEGMENT TOTAL==>	1995.00

[illegible]

- CHANGE ENGINE OIL AND FILTER (1.0) - JB
- CHANGE CAB FILTERS AND CLEAN OUT HOUSING (0.5) - JB
- CHANGE ENGINE OUTER AIR FILTER (0.5) - JB
- CHANGE DEBRIS FILTER AND CLEAN OUT HOUSING (0.5) - JB
- CHANGE REVERSER OIL (1.0) - KS
- CHANGE PRIMARY COUNTER SHAFT GEAR CASE OIL TO SYNTHETIC (1.0) - KS
- CHANGE DESICCANT CARTRIDGES FOR ACTIVE VISION CAMERAS (1.0) - JB
- CHANGE FUEL AND DEF TANK VENT FILTERS (0.5) - JB
- CHANGE FUEL FILTERS (1.0) - JB
- INSTALL 1 SOFTWARE PACKET (0.5) - KS
- TOP UP COOLANT (0.5) - JB
- TOP UP MEG (0.5) - KS
- CLEAN SEDIMENT BOWL (0.5) - JB

AXE42066	FILTER AIR DEBR	1	208.93	208.93
	DEBRIS MANAGEMENT OUTER			
DZ112918	FILTER FUEL	1	212.86	212.86
	CONTINUED ON PAGE 02			

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To:

Branch CAMROSE		
Date 01/15/25	Time 22:20:06 (B)	Page 02
Account No	Phone No	Inv No W29029
Ship Via		Purchase Order
Tax ID No		
		Salesperson 137

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016693	S790 STS COMBINE S790S	1E	1H0S790STKT805180 1105E	05/01/20	
DZ130550		Filter Element	1	209.51	209.51
EF4662		RECYC FEE OIL	2	.50	1.00
EF4663		RECYC FEE OIL	4	1.00	4.00
EF4664		RECYC FEE OIL	6	.10	.60
EF4665		RECYC FEE OIL	2	.40	.80
EF4666		RECYC FEE OIL	2	2.00	4.00
HXE11090		FILTER AIR	1	416.65	416.65
H216169		FUEL TANK VENT	2	36.87	73.74
KXE10744		Desiccant	2	314.53	629.06
L214634		FILTER CAB AIR	1	45.21	45.21
RE284091		FILTER CAB AIR	1	109.84	109.84
RE572785		FILTER ENG OIL	1	136.64	136.64
TY22062		HY-GARD 10L	1	83.11	83.11
TY26372		80W140GL SYN 1L	2	43.62	87.24
TY26408		HD460 GL SYN	4	58.58	234.32
TY26576		COOL GARD 9.46L	1	60.89	60.89
TY26673		15W40 PLUS 3.8	2	37.14	74.28
	Plus-50 II Oil	15W40 CK4/SN			
TY26679		15W40 PLUS 18.9	2	159.28	318.56
	Plus-50 II Oil	15W40 CJ4/SN			
TY6341		GREASE	1	11.34	11.34
	SD POLYUREA GREASE, 14OZ:	397G			
11M7032		COTTER PIN	1	1.44	1.44
		PARTS			2924.02
		LABOR			1575.00
	16001000	SEGMENT TOTAL==>			4499.02

SEGMENT# 3 C 10 NA 12/20/24 12/20/24
615P PLATFORM 2.00 HRS
-REPLACE 1 BROKEN TABLE AUGER FINGER ASSEMBLY (1.0) - JB
CONTINUED ON PAGE 03

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To:

Branch CAMROSE		
Date 01/15/25	Time 22:20:06 (B)	Page 03
Account No	Phone No	Inv No W29029
Ship Via		Purchase Order
Tax ID No		
		Salesperson 137

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016693	S790 STS COMBINE	1E	1H0S790STKT805180	05/01/20	
	S790S	1105E			
	-ADJUST TABLE AUGER DRIVE CHAIN TENSION (0.5) - JB				
	-ADJUST TABLE AUGER SPACING (0.5) - JB				
AH231461	FINGER/HOLDOWN	1	33.32	33.32	
H169913	SPRING LOC	1	2.44	2.44	
	Spring Locking Pin				
H169914	FINGER/615P	1	20.57	20.57	
H172459	914P/RETAINER	1	5.06	5.06	
11M7081	COTTER PIN	2	.56	1.12	
28316	SPRING PIN	1	4.00	4.00	
	Spring Locking Pin				
			PARTS	66.51	
			LABOR	350.00	
16001000			SEGMENT TOTAL==>	416.51	

SEGMENT# 4 C 10 NA 12/20/24 12/20/24
FEEDER HOUSE 12.00 HRS

CORRECTION:

- began removal of connector latch cable
- removed clamps and end bolt
- removed old line
- began re installing new line, got it fed and attached the pin and then attached at the coupler
- adjusted cable as needed and then put clamps back on
- put cable latch on the front and the operated the cable and it worked perfectly
- tightened jam nuts
- Removed the front isolator from the feeder house. Cleaned up debris build up and installed the new isolator.
- Removed the upper feeder house door, straightened the door and reinstalled.

CONTINUED ON PAGE 04

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-872-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To:

Branch CAMROSE		
Date 01/15/25	Time 22:20:06 (B)	Page 04
Account No	Phone No	Inv No W29029
Ship Via		Purchase Order
Tax ID No		
		Salesperson 137

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016693	S790 STS COMBINE	1E	1H0S790STKT805180	05/01/20	
	S790S	1105E			

ADDITIONAL DESCRIPTION:

-STRAIGHTEN TOP DOOR (2.0) - KS
-REPLACE BENT STONE TRAP DOOR (1.5) - KS
-REPLACE TORN FORE/AFT ISOLATOR (2.0) - DA
-REPLACE CONNECTOR LINK IN FEEDER CHAIN DRIVE
CHAIN (0.5) - KS

--Remove 1/2 link and adjust tension
-REPLACE FEEDER CHAIN DRIVE CHAIN BRACKET (1.5) - KS
--Replace 2 standard carriage bolts with factory metric
-REPLACE BACK SHAFT BEARING (1.5) - KS
-REPLACE 1 MULTI COUPLER SHEAR PIN (0.5) - KS
-REPLACE LATCH CABLE AND CLEAN OUT LINKAGE (2.5) - CB

AH212083	Push Pull Cable	2 N	482.42	964.84
AXE16328	Bracket	1	914.36	914.36
AXE63441	Bracket	1	738.33	738.33
AXE68018	Bearing With Ho	1	391.08	391.08
	Bearing With Housing			
HXE84785	Isolator	1	143.57	143.57
L215374	BOLT 12MMX35MM	2	6.03	12.06

BOLT 12MMX35MM 10.9

SW60HCOUS	CHAIN LINK CON	1	8.39	8.39
11M7030	COTTER PIN	2	1.44	2.88
14M7264	LOCK NUT	1	.74	.74
14M7299	NUT FLG 12MM	2	3.98	7.96
19M9326	HEX SOCK 4MX30M	1	3.02	3.02

PARTS 3187.23

LABOR 2100.00

16001000

SEGMENT TOTAL==> 5287.23

SEGMENT# 5 C 10 NA 12/20/24 12/20/24

CONTINUED ON PAGE 05

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To:

Branch CAMROSE		
Date 01/15/25	Time 22:20:06 (B)	Page 05
Account No	Phone No	Inv No W29029
Ship Via		Purchase Order
Tax ID No		
		Salesperson 137

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016693	S790 STS COMBINE	1E	1H0S790STKT805180	05/01/20	
	S790S	1105E			

RT SEPARATOR

7.00 HRS

CORRECTION:

Removed the shielding around the re thresher chain. Lowered the tailings elevator out of the housing. Loosened off and removed the upper shaft and sprocket. Replaced the shaft and sprocket, installed with new shaft key and bearings. Pulled the elevator chain back into the elevator housing. Connected the chain and tensioned to specification. Replaced the re thresher drive chain, reinstalled the shielding around the drive chain.

ADDITIONAL DESCRIPTION:

-REPLACE RE THRESHER DRIVE CHAIN (1.0) - DA
-REPLACE CLEAN GRAIN ELEVATOR LOWER SPROCKET KEY (1.5) - KS
--Replace 2 cotter pins for connector link
-REPLACE TAILINGS ELEVATOR UPPER AND LOWER SPROCKET KEYS (4.0) - DA
--Replace upper shaft, sprocket, keys and 2 bearings
-INSTALL FINAL DRIVE BREATHER (0.5) - CB

AXE23392	Bearing With Ho			5.64-
	Bearing With Housing			
AXE54619	Roller Chain	1	288.09	288.09
AZ10045	ECCENTRIC	3	14.64	43.92
	Eccentric Locking Collar			
HXE11401	Shaft	1	490.10	490.10
H150269	SHAFT KEY	1	19.92	19.92
H164796	SPROCKET TOP	1	67.68	67.68
	CLEAN GRAIN ELEVATOR TOP SPROCKET			
JD10384	BRG/ELV/TAIL/98	3 S	72.42	217.26
JD5801	PRESSURE RELIEF	1	3.83	3.83
	Pressure Relief Fitting			

CONTINUED ON PAGE 06

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4483

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To:

Invoice To:

Branch CAMROSE		
Date 01/15/25	Time 22:20:06 (B)	Page 06
Account No	Phone No	Inv No W29029
Ship Via		Purchase Order
Tax ID No		
		Salesperson 137

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016693	S790 STS COMBINE S790S	1E	1H0S790STKT805180	05/01/20	
11M7080			1105E		
15H514			COTTER PIN	2	1.00
15H602			PIPE BUSHING	1	19.11
26M4228			1/2"90 ST ELBOW	1	35.31
			SHAFT KEY	1	10.96
			PARTS		1191.54
			LABOR		1225.00
	16001000		SEGMENT TOTAL==>		2416.54

SEGMENT# 6 C 10 NA 12/20/24 12/20/24
LT SEPARATOR 6.50 HRS

COMPLAINT:

-O/S LABOR * MAT, SCHNELL & BARRIE LTD, HYDRAULIC HOSE,
INVOICE# 24401D

CORRECTION:

- unloading auger chain was previously removed
- reinstalled new chain and tensioned to spec
- removed final drive fill plug and replaced it with a breather
- pipe doped and oriented the breather accordingly

ADDITIONAL DESCRIPTION:

- READJUST CONCAVE POSITION SENSORS AND RE-CALIBRATE (1.5) - KS
- REPLACE MISSING LINK FOR CAB LADDER SAFETY CHAIN (0.5) - KS
- REPLACE UNLOADING AUGER DRIVE CHAIN (1.0) - CB
- REPLACE HYDRAULIC PUMP PRESSURE LINE (3.0) - KS
- Replace o-ring
- Have Schnell & Barrie build new hose
- INSTALL FINAL DRIVE BREATHER (0.5) - CB

AXE20532 Clip 1 19.45 19.45
CONTINUED ON PAGE 07

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St
Camrose, AB T4V 3W9
Phone: 780-872-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1801 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To:

Invoice To:

Branch CAMROSE		
Date 01/15/25	Time 22:20:06 (B)	Page 07
Account No	Phone No	Inv No W29029
Ship Via		Purchase Order
Tax ID No		
		Salesperson 137

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016693	S790 STS COMBINE	1E	1H0S790STKT805180	05/01/20	
	S790S	1105E			
	Track Chain W/O Shoes				
AXE79735	Roller Chain	1	N	430.67	430.67
JD5801	PRESSURE RELIEF	1		3.83	3.83
	Pressure Relief Fitting				
T78313	O-RING	1		9.86	9.86
15H514	PIPE BUSHING	1		19.11	19.11
15H602	1/2"90 ST ELBOW	1		35.31	35.31
				PARTS	518.23
				LABOR	1137.50
	16001000		SEGMENT TOTAL==>		1655.73

SEGMENT# 7 C 10 NA 12/20/24 12/20/24
ENGINE COMPARTMENT 3.50 HRS

CORRECTION:

Remove bolts through bracket and remove bracket, install new bracket and bolts and tighten bolts, loosen off jackshaft belt and remove belt, install new belt around pulleys.

ADDITIONAL DESCRIPTION:

- REPLACE ROTARY SCREEN ENGINE TO JACK SHAFT BELT (2.5) - BS
- REPLACE ENGINE ACCESSORY MOUNT BRACKET (1.0) - BS
- Replace hardware

HXE130611	V-Belt	1	97.97	97.97
HXE149943	Bracket	1	114.67	114.67
KK54762	M8 Lock Nut	2	.77	1.54
19M7866	8-20 MET	2	2.53	5.06
19M7868	8X30 FLANGE	2	2.67	5.34
			PARTS	224.58
			LABOR	612.50
	16001000		SEGMENT TOTAL==>	837.08

CONTINUED ON PAGE 08

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T6W 1L2
Phone: 780-842-2171

Ship To:

Branch CAMROSE		
Date 01/15/25	Time 22:20:06 (B)	Page 08
Account No	Phone No	Inv No W29029
Ship Via		Purchase Order
Tax ID No		
		Salesperson 137

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016693	S790 STS COMBINE	1E	1H0S790STKT805180	05/01/20	
	S790S	1105E			

SEGMENT# 8 C 10 NA 12/20/24 12/20/24

SHOE 5.50 HRS

-REPLACE 2 BADLY BENT LOUVERS ON CHAFFER (4.0) - JB

-- Removed chaffer, located broken louvers and replaced them.

-REPLACE BROKEN PRE-CLEANER ACTUATOR (1.5) - JB

-- While I had chaffer out replaced pre-cleaner actuator.

AXE42167	Louver	1	111.36	111.36
----------	--------	---	--------	--------

H156801	ACTUATOR	1 N	68.98	68.98
---------	----------	-----	-------	-------

PARTS 180.34

LABOR 962.50

16001000

SEGMENT TOTAL==> 1142.84

SEGMENT# 9 C 10 NA 12/20/24 12/20/24

MISC 16.00 HRS

CORRECTION:

Removed the grain tank unloading auger loop, straightened the loop and reinstalled.

ADDITIONAL DESCRIPTION:

-REMOVE SUICIDE KNOB FROM STEERING WHEEL (0.5) - KS

-CHECK SPREADER KEYS AND HUBS (6.0) - CB

--Replace 2 keys, 1 hub bearing and 1 wag bearing

--Replace LT spreader hub + (1.5) - CB

-FLIP STRAW CHOPPER STATIONARY KNIVES (1.5) - KS

-STRAIGHTEN GRAIN TANK LOADING AUGER HOOP (1.5) - DA

-REPAIR DENT IN UNLOADING AUGER TUBE (3.5) - KS

-CLEAN OUT SPREADER LT SHROUD, JAMMED (1.5) - CB

--Recalibrate shrouds

AH224093	Wheel	1	71.71	71.71
----------	-------	---	-------	-------

CONTINUED ON PAGE 09

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To:

Branch CAMROSE		
Date 01/15/25	Time 22:20:06 (B)	Page 09
Account No	Phone No	Inv No W29029
Ship Via		Purchase Order
Tax ID No		
		Salesperson 137

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016693	S790 STS COMBINE S790S		1E 1H0S790STKT805180 1105E	05/01/20	
AXE23329			Disk	1	1432.99
HXE25673			Spacer	1 N	13.27
HXE96444			Ball Bearing	2	61.74
JD10384			BRG/ELV/TAIL/98	S	1.56-
JD39102			BALL BEARI	1	33.09
T77858			FF-12 O-RING	2	3.25
49M7061			Shaft Key	2	1.98
			PARTS		1683.44
			LABOR		2800.00
	16001000		SEGMENT TOTAL==>		4483.44

SEGMENT#10 C 10	NA	12/20/24 01/06/25	
RUN AND CHECK			2.00 HRS
RUN AND CHECK			
Pre-inspection			
-Remove panels and shields			
-Record and clear codes			
-Run and check operation			
Post-inspection and repairs			
-Run and check repairs - OK			
-Check operation - ECU and unloading auger problems			
-Reinstall panels and shields			
		LABOR	350.00
	16001000	SEGMENT TOTAL==>	350.00

SEGMENT#11 C 10	NA	12/20/24 01/06/25
Engine runs rough during final run up		
-CHECK INJECTOR CODES AND ENGINE SHUTTING DOWN - KS		
--Run diagnostics for ECU codes		
---Check harnesses and connectors - seem OK		

CONTINUED ON PAGE 10

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____



4717 38th St.
Camrose, AB T4V 3W9
Phone: 780-672-4463

5907 51st Ave
Killam, AB T0B 2L0
Phone: 780-385-3993

P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

1601 - 23 Street
Wainwright, AB T9W 1L2
Phone: 780-842-2171

Ship To:

Invoice To:

Branch CAMROSE		
Date 01/15/25	Time 22:20:06 (B)	Page 10
Account No	Phone No	Inv No W29029
Ship Via		Purchase Order
Tax ID No		
		Salesperson 137

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C016693	S790 STS COMBINE	1E	1H0S790STKT805180	05/01/20	
	S790S	1105E			
--Use donor ECU and check operation - OK					
--Do service regen - OK					
--Replace ECU and reprogram					
CRDZ115244	Engine Controll	1-	283.00	283.00-	
DZ115244	Engine Controll	1	2719.28	2719.28	
Engine Controller					
PARTS 2436.28					
LABOR 353.50					
16001000	SEGMENT TOTAL==>				2789.78

1-877-913-3373

***** WORK ORDER TOTALS *****
INTERNAL CUSTOMER

PARTS	12412.17
LABOR	13461.00
O/S LABOR & MAT	327.01
SERV ACCESORIES	100.00
INTERNAL TOTAL	26300.18

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

Signature: _____