

Number	Type	Date Open	Date Closed	Fault	Repairer / Notes	Cost / Invoice
S-7681	A - 3 Week	03/11/2026	03/11/2026		Internal Workshop - Night Shift	\$0.00
S-7599	B - 1 Year	02/09/2026	02/09/2026		Internal Workshop - Night Shift	\$0.00
R-9060	Tarp cable	01/22/2026	01/16/2026		Internal Workshop - Night Shift REAPLACED BOTH TARP CABLES. REPLACED MISSING MUDFLAP.	\$0.00
S-7523	A - 3 Week	12/15/2025	12/15/2025		Internal Workshop - Night Shift	\$0.00
S-7461	A - 3 Week	11/14/2025	11/14/2025		Internal Workshop - Night Shift	\$0.00
S-7409	A - 3 Week	10/27/2025	10/27/2025		Internal Workshop - Night Shift	\$0.00
O-2	Registration		10/15/2025		Internal Workshop - Night Shift ADJUSTED BRAKES ON 2ND AXLE. ADDED ONE MORE CLICK ON SLACK ADJUSTER. CLEARED DEFECT. COI ATTACHED.	\$0.00
R-8931	Machinery Defects	10/13/2025	10/13/2025		Internal Workshop - Night Shift REPLACED MISSING REFLECTORS	\$0.00
S-7340	A - 3 Week	10/07/2025	10/07/2025		Internal Workshop - Night Shift RE-PACKED ALL WHEEL BEARINGS.	\$0.00
R-8302	Wheel Bearing Repack	01/30/2025	10/01/2025		Internal Workshop - Night Shift REPLACED 4TH AXLE RHS AIR BAG	\$0.00
R-8796	air bag	08/05/2025	09/15/2025		Internal Workshop - Night Shift	\$0.00
S-7297	A - 3 Week	09/15/2025	09/15/2025		Internal Workshop - Night Shift	\$0.00
S-7250	A - 3 Week	08/28/2025	08/28/2025		Internal Workshop - Night Shift	\$0.00
R-8813	Mud Flaps	08/20/2025	08/18/2025		Internal Workshop - Night Shift REPALCED ALL MUDFLAPS ON DOLLY AND REAR OFF TRAILER.	\$0.00
S-7138	A - 3 Week	07/21/2025	08/05/2025		Internal Workshop - Night Shift	\$0.00
R-8793	Mud Flaps	08/05/2025	08/04/2025		REPLACED LHS REAR MUDFLAP. COMPLETED BY RYAN.	\$0.00
R-8790	Tarp cable	08/05/2025	08/04/2025		REPLACED BOTH TARP CABLES.	\$0.00
S-7105	A - 3 Week	07/08/2025	07/08/2025		Internal Workshop - Night Shift REPLACED BOTH TARP CABLES.	\$0.00
S-6988	A - 3 Week	06/02/2025	06/02/2025		Internal Workshop - Night Shift R&R 2ND AXLE LHS SLACK ADJUSTER.	\$0.00
S-6923	A - 3 Week	04/28/2025	04/29/2025		SERVICE COMPLETED BY TYSON E.	\$0.00
S-6883	A - 3 Week	03/31/2025	04/01/2025		Internal Workshop - Night Shift SERVICE COMPLETED BY TYSON E.	\$0.00
R-8341	light	02/19/2025	02/17/2025		Internal Workshop - Night Shift FOUND DAMAGED WIRING AND CUT AND REPLACED.	\$0.00
S-6808	A - 3 Week	02/12/2025	02/12/2025		Internal Workshop - Night Shift SERVICE COMPLETED BY IZAAK H.	\$0.00
S-6763	C - 2 Year	01/23/2025	01/24/2025		Internal Workshop - Night Shift SERVICE COMPLETED BY IZZAK H.	\$0.00
R-8286	Tarp gearbox	01/23/2025	01/09/2025		Internal Workshop - Night Shift REPLACED GEARBOX AND MOTOR.	\$0.00
R-8235	Annual Cracks Inspection	12/23/2024	12/23/2024		Internal Workshop - Fabrication Inspected by Damien. Front dolly crossmember cracked and 1st to 4th axles. Repairs completed. Notes attached.	\$0.00
S-6718	A - 3 Week	12/13/2024	12/16/2024		Internal Workshop - Night Shift SERVICE COMPLETED BY IZAAK H. Defect notice #D103372203 issued for: 1. Service brake imbalance 3nd axle passenger side. Repaired on R#8172 Self clearing. COI attached.	\$0.00
I-59	Machinery Inspection	12/09/2024	12/09/2024		COI attached.	\$0.00
R-8172	Machinery Defects	12/03/2024	12/05/2024		Internal Workshop - Night Shift BRAKES OUT OFF ADJUSTMENT. ADJUST ALL. Internal Workshop - Night Shift SERVICE COMPLETED BY IZAAK H. BRETT REPAIRED ALL CRACKS ON AXLE TRAILING ARM WELDS. BRETT REPAIRED CRACKS ON FIRST AXLE X MEMBER. BRETT STRAIGHTNED 1ST AND 2ND AXLE LHS BENT S-CAM TUBES.	\$0.00
S-6653	A - 3 Week	11/13/2024	11/13/2024			\$0.00

S-6626	A - 3 Week	10/29/2024	10/30/2024	Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.	\$0.00
R-7668	Brake Reline	07/08/2024	10/11/2024		REPLACED 2ND AXLE BRAKE DRUMS AND SHOES.	\$0.00
S-6585	A - 3 Week	10/14/2024	10/11/2024	Internal Workshop - Field Service	SERVICE COMPLETED BY IZAAK H.	\$0.00
S-6578	A - 3 Week	10/04/2024	10/11/2024	Internal Workshop - Night Shift	SERVICE COMPLETED BY IZAAK H.	\$0.00
R-7977	Air line	09/24/2024	09/23/2024	Internal Workshop - Night Shift	REMOVE AND REPLACE ALL AIRLINES FROM TRAILER TO TRUCK. RE- WIRE ABS LINE. FIX ANDERSON PLUG LEADS. FIX LIGHT PLUG WIRING.	\$0.00
S-6525	A - 3 Week	09/10/2024	09/11/2024	Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.	\$0.00
R-7913	Clamps	09/11/2024	09/10/2024	Internal Workshop - Night Shift	REMOVED AND REPLACED CLAMP.	\$0.00
S-6452	A - 3 Week	08/01/2024	08/16/2024	Internal Workshop - Night Shift	SERVICE COMPLETED BY TYSON E.	\$0.00
R-7665	Brake booster	07/08/2024	07/09/2024	Internal Workshop - Night Shift	REPLACED 2ND AXLE LHS BRAKE BOOSTER SUPPLIED BY MAXI PARTS. SERVICE COMPLETED BY TYSON E. 2ND AXLE LHS BOOSTER FAULTY -TYPE 30 SINGLE CHAMBER.	\$0.00
S-6345	B - 1 Year	07/02/2024	07/04/2024		2ND AXLE BRAKES DUE SOON	\$0.00
S-6255	A - 3 Week	05/24/2024	06/03/2024	Internal Workshop - Night Shift	A Service completed by Tyson E.	\$0.00
S-6197	A - 3 Week	04/16/2024	04/16/2024	Internal Workshop - Night Shift		\$0.00
R-7487	Tyre repairs	04/15/2024	04/15/2024	Internal Workshop - Night Shift	Repaired 2nd axle outer LHS.	\$0.00
R-6988	Mud Guard	01/12/2024	02/15/2024	Internal Workshop - Night Shift	Fitted ally checker plate guards behind 4th axle	\$0.00
R-6984	Mudguards	01/12/2024	02/15/2024	Internal Workshop - Night Shift	Removed all plastic guards on 3rd and 4th axle and fitted mudflap brackets in front of 3rd axle.	\$0.00
S-6048	A - 3 Week	02/07/2024	02/15/2024		Remove and repair 3rd axle inner LHS and RHS 2nd axle in puncture repairs.	\$0.00
S-6016	A - 3 Week	01/19/2024	01/19/2024			\$0.00
R-7164	Welding Repair	01/09/2024	01/09/2024	Internal Workshop - Fabrication	Cut top mud guard brackets off over axles 1 and 2 on trailer.	\$0.00
R-7005	Welding Repairs	01/12/2024	01/09/2024	Internal Workshop - Fabrication	Crack in trail arm to axle - 3rd axle passenger side front. - Grind out weld - Reweld - Blend and clean No visible cracks in crossmembers Inspected all axles with no visible signs of cracking except noted above.	\$0.00
S-5961	A - 3 Week	12/07/2023	12/07/2023			\$0.00
S-5902	A - 3 Week	11/03/2023	11/03/2023		Trailing arm bushes are getting bad.	\$0.00
R-6591	clearance light	09/13/2023	10/13/2023	Internal Workshop - Night Shift	Front left clearance light not working - Amber LED. This has been done.	\$0.00
S-5860	A - 3 Week	10/13/2023	10/13/2023			\$0.00
I-11	Machinery Inspection	09/21/2023	09/21/2023		Self clearing defect notice issued as attached on 19/9. Defects cleared and COI issued 21/9. P/S FRONT CLEARANCE LIGHT INOP DRAWBAR BUSHES EXCESSIVE PLAY CRACKS IN CROSS MEMBER 1ST AXLE AREA MARKED WITH CHALK R&R Drawbar bushes and bolts Weld 1st	\$0.00
R-6583	Machinery Defects	09/20/2023	09/20/2023		crossmember and paint R&R front left clearance light. Faults fixed. Front left clearance light not working - nil stock. Amber LED. - JC	\$0.00
S-5790	A - 3 Week	09/08/2023	09/13/2023		Needs tyres 3rd axle RH side.	\$0.00
R-6604	Tarp	09/01/2023	09/01/2023		Reposition tarp bows, adjust tarp bow ends, replace both left and right tarp cables. Replace RH rear mudflap. Tarp opens and closes as it should.	\$0.00
S-5769	A - 3 Week	08/29/2023	08/29/2023			\$0.00

				Internal Workshop Flat tyre LHS 2nd axle outer (dolly). Remove tyre - repair puncture. Refit tyre and test for leaks - OK.	
T-135	Dolly Tyre	08/15/2023	08/15/2023		\$0.00
S-5704	A - 3 Week	07/27/2023	08/02/2023		\$0.00
S-5647	A - 3 Week	07/11/2023	07/11/2023		\$0.00
T-120	Trailer Tyres	06/23/2023	06/22/2023	Bridgestone Wacol New tyres for 4th axle. Invoice attached.	\$0.00
S-5601	A - 3 Week	06/21/2023	06/21/2023	Trailing arm bushes all worn need replacing - JC Cracks in trailing arms at hangers 3rd and 4th axle.	\$0.00
R-6257	EBS	05/31/2023	05/31/2023	Internal Workshop - Night Shift EBS valve under dolly leaking out of exhaust. 13/9 checked by Tyson - very minor leak. Monitor. 13/10/23 - This is getting worse. Jarrod. Replaced EBS valve on 31/5/23 supplied by Shepherds. Broke bolt RH rear body pivot mount Rear body pivot not taking grease - cleared and greased LH tarp cable replaced	\$0.00
S-5540	A - 3 Week	05/31/2023	05/31/2023	EBS valve under dolly leaking out of exhaust - JC created.	\$0.00
S-5489	A - 3 Week	05/10/2023	05/10/2023	Puncture repair 2nd axle RH outer - Tyson	\$0.00
T-116	Trailer Tyres	04/26/2023	04/26/2023	Bridgestone Wacol Replaced 4th axle tyres x4	\$0.00
S-5442	A - 3 Week	04/19/2023	04/19/2023	Internal Workshop - Night Shift Completed by Tyson.	\$0.00
R-6124	Ride height, Tyre	04/11/2023	04/11/2023	Internal Workshop - Night Shift Garth - check and test dolly ride height; all working okay. Adjust ride height and re-check; all okay. Remove and replace RH outer tyre with other run out, refit; all okay. Internal Workshop - Night Shift Completed by Tyson and Ryan. Replaced 2nd axle slack adjusters and adjust brakes.	\$0.00
S-5383	A - 3 Week	03/27/2023	03/29/2023	R&R LH tarp cable (Ryan).	\$0.00
S-5319	A - 3 Week	02/24/2023	02/24/2023	Internal Workshop - Night Shift Completed by Tyson. Repaired puncture tyre.	\$0.00
S-5245	B - 1 Year	02/01/2023	02/01/2023	Internal Workshop - Night Shift Garth - EBS valve leaking air.	\$0.00
R-5637	Wheel Bearing Repack	01/03/2023	01/09/2023	Internal Workshop - Night Shift Tyson - remove bearings, remove all wheels and hubs, clean out all bearings and inspect, R&R LH 4th axle bearings and seal, R&R 1st axle bearings, grease bearings and hubs, fit wheels and tension hub to spec, adjusted brakes. Internal Workshop C Service created from previous wheel bearing repack This is to bring the service schedule into alignment	\$0.00
S-5316	C - 2 Year	02/24/2023	01/09/2023	See recent wheel bearing repack service sheet for information	\$0.00
R-5826	Cracks	01/05/2023	01/05/2023	Internal Workshop - Fabrication Danny. 1. Cracks at bolts around back of ball-race underside rear. Removed bolt from back of ball-race and prep and repair crack. 2. 1st cross member. Repair welds on underside of 1st cross member. 3. Cracks at all axle saddles. Clean paint off all axle saddles welds and inspect for cracks. Blend all welds to prevent cracking.	\$0.00
R-5472	Tyre	11/24/2022	12/21/2022	2nd axle rhs outside needs run out put on Tyson inspected and no further work required. Suspect Garry worked on this prior and did not complete a repair card.	\$0.00
S-5197	A - 3 Week	12/21/2022	12/21/2022	Internal Workshop - Night Shift Completed by Tyson.	\$0.00

S-5140	A - 3 Week	12/05/2022	06/12/2022	21	Internal Workshop - Night Shift Completed by Izaak. RH tarp cable replaced. RH rear mud guard fixed.	\$0.00
R-5581	Indicators, Lights	11/21/2022		11/21/2022	Internal Workshop - Night Shift Wires rubbed through on trailer lights at drawbar. Reverse come on with indicator. Tyson: repaired EBS wiring. Repaired tarp wires. Repaired 7 core trailer light wires.	\$0.00
S-5079	A - 3 Week	11/10/2022	15/11/2022	26	Internal Workshop - Night Shift Completed by Izaak. 3rd axle RHS inner tyre removed, fixed puncture and refit, tensioned wheels nuts.	\$0.00
R-5407	Brake Re-line	10/25/2022		10/25/2022	Garth - Brake reline on 1st and 3rd axle, replacing shoes and drums with new. Refit and torqued. Adjusted brakes; all okay.	\$0.00
R-5405	Mud Flaps, Mud Guard, Tai	10/25/2022		10/25/2022	Internal Workshop - Night Shift Garry - Repositioned mud guards at rear. Re-secured mud flaps. Tightened tarp cables.	\$0.00
S-5014	A - 3 Week	10/21/2022	20/10/2022	21	Internal Workshop - Night Shift Completed by Garth.	\$0.00
S-4962	A - 3 Week	09/30/2022	30/09/2022	21	Izaak.	\$0.00
R-5203	Floor	09/20/2022		09/20/2022	Shepherd's replaced floor.	\$0.00
S-4878	A - 3 Week	09/08/2022	09/09/2022	21	Tyson - tightened RH tarp cable.	\$0.00
T-52	Puncture Repair	09/08/2022		09/06/2022	Internal Workshop 2nd axle RHS outside puncture repair. Damaged. Inspect Mud Flaps and Guards are all attached. Left side rear guard broken and mud flap	\$0.00
R-5070	Mud Flaps	08/30/2022		09/01/2022	5261 missing. Izaak - Reattach mud flap to guard. Garth - Checked lights on truck - all okay. Checked lights on trailer; found no park/brake lights. Found electrical plug faulty; replaced with new and repaired wiring where it has rubbed through from the	\$0.00
R-5128	Lights, Mudflap	08/30/2022		08/30/2022	ground. Fit missing mud flap to LH rear.	\$0.00
R-4630	Axle re-line	06/28/2022		08/19/2022	Re-line 3rd & 4th axle next service. Tyson - replaced 4th axle. 3rd axle still good. Tyson - R&R 4th axle shoes and drums.	\$0.00
S-4807	A - 3 Week	08/19/2022	19/08/2022	23	Tighten loose hose clamp 3rd axle.	\$0.00
S-4727	A - 3 Week	07/19/2022	27/07/2022	29	Garth.	\$0.00
R-4553	Gearbox	06/24/2022		06/28/2022	4857 Not Working. Inspect Tarp & tarp cable condition and operation. Gear box gears stripped. Garth - gearbox has been repaired. Garth:	\$0.00
S-4657	A - 3 Week	06/28/2022	28/06/2022	28	Re-line 3rd & 4th axle next service.	\$0.00
S-4582	A - 3 Week	05/31/2022	31/05/2022	20	Replaced brake shoes on 1st axle.	\$0.00
R-4298	Brake lights	05/12/2022		05/12/2022	Repaired broken wires in suzzies lead.	\$0.00
S-4485	A - 3 Week	04/21/2022	11/05/2022	41	1st and 2nd axle brakes next service.	\$0.00
R-4221	Hydraulic hose	04/27/2022		05/10/2022	4485, 4492, Replaced as per repair card 4219 (driver used incorrect unit number on pre-start).	\$0.00
R-4219	Hydraulic hose	04/27/2022		05/10/2022	4484, 4493, Steve Goodhew replaced hose.	\$0.00
R-4320	Tyre	05/09/2022		05/09/2022	Carry out puncture repair. Check second axle brake adjustment next service. 1st cross member cracked.	\$0.00
S-4419	A - 3 Week	03/31/2022	30/03/2022	27	R&R front mud flap. Cracks in cross members.	\$0.00
S-4320	A - 3 Week	03/02/2022	03/03/2022	25	Tightened tarp cables.	\$0.00
S-4301	A - 3 Week	02/17/2022	20/02/2022	14		\$0.00
S-4251	A - 3 Week	02/02/2022	06/02/2022	20		\$0.00

S-2915	A - 3 Week	12/04/2020	15/12/2020	40	internal workshop Spreader chain broken Cracks in trailing arm to axle welds Wiring at draw bare damaged (repaired) Internal workshop Replaced all tarp cables on truck & trailer Auto stop not working on tarp motors - may need to replace pulleys - replaced all tarp motor pulleys with new ones - front pulley on truck seized or was hard to get them off - fault now fixed
R-1693	Tarp cable	11/18/2020	11/18/2020		internal workshop Tightened loose bolts Adjusted brakes evenly
R-1683	Machinery Defects	11/16/2020	11/16/2020		A service done
S-1412	A - 3 Week	11/05/2020	05/11/2020	21	
R-491	Brakes	10/21/2020	10/21/2020		Internal Workshop Trailer not in yard on 21/10/20 Re-lined 1st & 2nd axle dolly brakes 27/10/2020 Internal Workshop A service done
S-610	A - 3 Week	10/15/2020	15/10/2020	23	Dolly brakes will need changing before next service Internal Workshop A service done
S-531	A - 3 Week	09/22/2020	22/09/2020	29	Dolly brakes still ok - to be checked again next service
R-354	Tyres	09/17/2020	09/17/2020		Internal Workshop Replaced 4 x new tyres on 3rd axe with Goodyear trailer tyres from the back shed
R-272	Air line	08/27/2020	08/27/2020		Replaced hose at weight gauge Replaced wind up leg on drawbar - driver collected Service done Replaced LH tarp cable Dolly brakes still ok
S-463	A - 3 Week	08/21/2020	24/08/2020	21	DEFECT: 3rd axle tyres getting low Service done Inspected dolly brakes - still ok - check again next service
S-403	A - 3 Week	08/03/2020	03/08/2020	25	3rd axle tyres worn low A service done
S-330	A - 3 Week	07/09/2020	07/09/2020		Check dolly brakes next service
R-158	Bushes	07/01/2020	07/01/2020		Removed tailgate from trailer - removed old nylon bushes from top hinge mount - cleaned hinge pin & top hinge mount - installed new nylon bushes in top mount - re-installed tailgate with anti seize - check operation of tailgate RECOMMENDATION: to use inox on top hinge mount every service & check door operation a few times to let the inox work it's way down the shaft A service done
S-256	A - 3 Week	06/15/2020	06/16/2020		Rotated 3rd & 4th axle tyres DEFECTS: Cracks at horizontal welds trailing arms to axles - monitor A service done
S-190	A - 3 Week	05/22/2020	05/25/2020		3rd & 4th axle tyres needs rotation DEFECT: cracks as horizontal welds trailing arms to axles - minor
R-1530	Tyres	05/08/2020	05/08/2020		Internal workshop Changed 4 x 2nd axle dolly tyres A service done Replaced LH tarp cable Checked all trailing arm bushes
S-107	A - 3 Week	04/27/2020	04/27/2020		DEFECTS: Cracks at horizontal welds trailing arms to axles

R-1531	Tyre repairs	04/06/2020	04/06/2020	Internal workshop	Repaired puncture - 3rd axle RHS outside tyre
R-1532	Tyres	03/06/2020	03/06/2020	Internal workshop	Repaired puncture 4th axle inside RHS
R-1533	Mudflaps	02/28/2020	02/28/2020	Internal workshop	Replaced broken anti-sail bracket on mudflap behind RHS dolly
R-1534	Slack adjusters	02/11/2020	02/11/2020	Internal workshop	Swapped out Stemco slack adjusters with Bendix
S-1856	A - 3 Week	02/10/2020	10/02/2020	21	Internal workshop A service done, replaced LH tarp cable DEFECTS: cracks at horizontal welds trailing arms to axles - minor, still has Stemco slack adjusters
S-1857	A - 3 Week	02/03/2020	03/02/2020	14	Internal workshop A service done, repaired anti-sail RH 2nd axle on dolly mudflap DEFECT: cracks at horizontal welds trailing arms to axles - minor
S-1855	A - 3 Week	01/20/2020	20/01/2020	39	Internal workshop A service done
S-1854	A - 3 Week	12/12/2019	12/12/2019	21	Internal workshop A service done
S-1853	A - 3 Week	11/21/2019	21/11/2019	17	Internal workshop A service done
R-1535	Pre-machinery check	11/12/2019	11/12/2019	Internal workshop	Pre-machinery checked done only
S-1852	A - 3 Week	11/04/2019	04/11/2019	24	Internal workshop A service done, replaced RHR mudguard & mounts out of Maxiparts stock
S-1851	A - 3 Week	10/11/2019	11/10/2019	22	Internal workshop A service done, disconnected dolly lock DEFECT: LHR mudguards need replacing - none in stock
R-1536	Tyres	10/08/2019	10/08/2019	Internal workshop	Repaired puncture 2nd axle LHS inside tyre
R-1537	Tyres	10/01/2019	10/01/2019	Internal workshop	Inspected flat 2nd axle LHS inside tyre - pretty sure it is extension / air leak rear airbag or booster
R-1538	Tarp cable	09/26/2019	09/26/2019	Internal workshop	Replaced LHS tarp cable
S-1850	A - 3 Week	09/19/2019	19/09/2019	30	Internal workshop A service done
S-1849	A - 3 Week	08/20/2019	20/08/2019	25	Internal workshop A service done, valve extension loose - tightened up & inflate tyre DEFECT: LHS 2nd inside tyre - slight leak, moitor crack in L & R hangers where welded to the chassis
S-1848	A - 3 Week	07/26/2019	26/07/2019	23	Internal workshop A service done DEFECTS: monitor crack in L & R hangers where welded to chassis
S-1847	A - 3 Week	07/03/2019	03/07/2019	20	Internal workshop A service done, cable tied hydraulic line hanging low on dolly DEFECTS: monitor crack in L&R hangers where welded to chassis
S-1846	A - 3 Week	06/13/2019	13/06/2019	22	Internal workshop Carry out G&C (A service) replaced damaged grease nipples at bin hinge DEFECTS: monitor crack in L&R hangers where welded to chassis
S-1845	A - 3 Week	05/22/2019	22/05/2019	26	Internal workshop Carry out G&C (A service) DEFECTS: Crack in L & R hangers where welded to chassis
R-1539	Tarp cable	05/17/2019	05/17/2019	Internal workshop	Repaired LHS tarp cable
R-1540	Mudguards	05/13/2019	05/13/2019	Internal workshop	Repair RHS guard mount bracket - straighten out bent guard bracket RHS 3rd axle - remove both L&R mudflaps catching on tyre
S-1844	A - 3 Week	04/26/2019	26/04/2019	23	Internal workshop Carry out G&C (A service), tightened up leaking hose at 3rd RHS DEFECTS: all tyre pressures low - front axle RHS need extension - NO STOCK, crack in L & R hangers where welded to chassis
S-1843	A - 3 Week	04/03/2019	03/04/2019	30	Internal workshop Carry out G&C (A service)
S-1842	A - 3 Week	03/04/2019	04/03/2019	18	Internal workshop Carry out G&C (A service)
S-1841	A - 3 Week	02/14/2019	14/02/2019	21	Internal workshop Carry out G&C (A Service), pump up tyres to correct pressure
S-1840	A - 3 Week	01/24/2019	24/01/2019	36	Internal workshop Carry out G&C (A Service)
S-1839	A - 3 Week	12/19/2018	19/12/2018	16	Internal workshop Carry out G&C (A Service)

S-1838 A - 3 Week

12/03/2018

12/03/2018

Internal workshop Carry out G&C DEFECTS: Need valve extensions for tyres