

Number	Type	Date Open	Date Closed	Fault	Repairer / Notes	Cost / Invoice
S-7693	A - 3 Week	03/18/2026	03/18/2026		Internal Workshop - Night Shift	\$0.00
R-9092	COI	02/20/2026	02/20/2026		COI ATTACHED	\$0.00
R-9091	Machinery Defects	02/19/2026	02/20/2026		Internal Workshop - Night Shift 1. Axle four failed brake test for an imbalance of 34% passenger side low performance/ REPLACED ALL BRAKE SHOES AND DRUMS DUE TO ONE SHOE BEING CRACKED. 2. Tow eye bush worn / REPLACED TOW EYE BUSH. 3. Axle four shock absorber mounts upper and lower worn with excessive movement / REPLACED SHOCK BUSHES ON 4TH AXLE.	\$0.00
S-7613	A - 3 Week	02/16/2026	02/16/2026		Internal Workshop - Night Shift	\$0.00
S-7581	A - 3 Week	01/23/2026	02/02/2026		Internal Workshop - Night Shift	\$0.00
S-7530	A - 3 Week	12/17/2025	12/17/2025		Internal Workshop - Night Shift	\$0.00
S-7478	A - 3 Week	11/25/2025	11/25/2025		Internal Workshop - Night Shift REPLACED RUBBED THROUGH WIEGHT GUAGE LINE.	\$0.00
S-7439	A - 3 Week	11/05/2025	11/06/2025		Internal Workshop - Night Shift REPLACED MISSING REFLECTORS.	\$0.00
S-7380	A - 3 Week	10/15/2025	10/15/2025		Internal Workshop - Night Shift	\$0.00
S-7315	A - 3 Week	09/24/2025	09/24/2025		Internal Workshop - Night Shift	\$0.00
R-8759	EBS	07/25/2025	09/04/2025		Internal Workshop - Night Shift REPLACED EBS VALVE.	\$0.00
R-8647	Brake Re-line	06/23/2025	09/04/2025		Internal Workshop - Night Shift REPLACED 3RD AND 4TH BRAKES.	\$0.00
S-7263	B - 1 Year	09/02/2025	09/04/2025		Internal Workshop - Night Shift	\$0.00
S-7205	A - 3 Week	08/14/2025	08/15/2025		Internal Workshop - Night Shift REPLACED DOLLY RIDE HEIGHT VALVE.	\$0.00
S-7144	A - 3 Week	07/22/2025	07/23/2025		REPLACED FRAYED TARP CABLE.	\$0.00
R-8648	Air Bag	06/23/2025	07/04/2025		Internal Workshop - Night Shift REPLACED LHS AND RHS 1ST AXLE AIRBAGS.	\$0.00
S-7096	A - 3 Week	07/04/2025	07/04/2025		Internal Workshop - Night Shift	\$0.00
S-7050	A - 3 Week	06/20/2025	06/20/2025		Internal Workshop - Night Shift	\$0.00
R-8358	Bin liner	02/20/2025	05/18/2025	9875	Internal Workshop - Fabrication REPAIRED WELD ON ROCK SHEETING.	\$0.00
S-6932	A - 3 Week	05/02/2025	05/18/2025		Internal Workshop - Night Shift SAY AUTO ELETRICAL @ Crestmead. Inspect, EBS not powering up. Inspect, find damaged EBS and light leads. Replace leads, cover with supplied rubber hose. Fit new plugs, connect and test - OK	\$0.00
R-8488	EBS wiring	04/28/2025	04/09/2025		Internal Workshop - Night Shift SERVICE COMPLETED BY IZAAK H.	\$0.00
S-6843	A - 3 Week	02/26/2025	02/26/2025		Internal Workshop - Night Shift BEARING RE-PACK GOT DONE ON THE 7/10/25	\$0.00
R-7990	Wheel Bearing Repack	10/01/2024	02/07/2025		Internal Workshop - Night Shift SERVICE COMPLETED BY IZAAKH.	\$0.00
S-6751	A - 3 Week	01/20/2025	01/20/2025		Self clearing Defect Notice D103413629 issued for: 1. Passenger side reverse light not working 2. 3rd axle service brake efficiency low 37% Repairs completed by Jarrod on R8233. Defect cleared.	\$0.00
I-65	Machinery Inspection	01/15/2025	01/15/2025		COI attached Internal Workshop - Night Shift REPAIRED WIRING TO STOP LIGHT. ADJUSTED BRAKES TO SPEC.	\$0.00
R-8233	Machinery Defects	01/14/2025	01/14/2025		COMPLETED BY JARROD H. Internal Workshop - Fabrication Inspected by Damien. Front dolly crossmember cracked both sides along with 1st to 4th axles. Repairs completed. Notes attached.	\$0.00
R-8239	Annual Cracks Inspectic	12/27/2024	12/27/2024			\$0.00

S-6704	A - 3 Week	12/06/2024	12/11/2024	Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.	\$0.00
R-7708	Shocker Bushes	07/23/2024	11/14/2024	Internal Workshop - Night Shift	RE-TENSIONED SHOCK BOLTS ALL GOOD NOW.	\$0.00
S-6648	A - 3 Week	11/11/2024	11/14/2024	Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.	\$0.00
S-6564	A - 3 Week	10/01/2024	10/01/2024	Internal Workshop - Night Shift	SERVICE COMPLETED IZAAK H.	\$0.00
R-7914	Airbag	09/11/2024	09/10/2024	Internal Workshop - Night Shift	REPLACED 4TH AXLE AIR BAG LHS	\$0.00
				Internal Workshop - Night Shift	SERVICE COMPLETED BYJARROD H.	
S-6519	C - 2 Year	09/09/2024	09/09/2024		BEARING RE-PACK GOT DONE ON THE 7/1024.	\$0.00
R-7707	Dolly brakes	07/23/2024	08/29/2024	Internal Workshop - Night Shift	REPLACED SHOES AND DRUMS ON 1ST AND 2ND AXLE.	\$0.00
R-7812	Tarp cable	08/28/2024	08/28/2024	Internal Workshop - Night Shift	REPLACED BOTH TARP CABLES.	\$0.00
R-7326	Tarp	03/22/2024	08/28/2024	Internal Workshop - Night Shift	REPLACED COMPLETE ROLLER LHS.	\$0.00
S-6476	A - 3 Week	08/23/2024	08/28/2024	Internal Workshop - Night Shift	SERVICE COMPLETED BY TYSON E.	\$0.00
R-7769	Lights	07/30/2024	07/30/2024	Internal Workshop - Night Shift	Replaced worn part of lead.	\$0.00
				Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.	
					DOLLY BRAKES NEED DOING BEFORE NEXT G/C	
S-6417	A - 3 Week	07/18/2024	07/19/2024		4TH AXLE LOWER SHOCK BUSHES LHS AND RHS U/S.	\$0.00
S-6330	A - 3 Week	06/25/2024	06/26/2024		SERVICE COMPLETED BY JARROD H.	\$0.00
S-6257	A - 3 Week	05/24/2024	05/24/2024			\$0.00
S-6208	A - 3 Week	04/22/2024	05/01/2024			\$0.00
S-6168	A - 3 Week	03/28/2024	03/26/2024			\$0.00
S-6103	A - 3 Week	03/04/2024	03/11/2024			\$0.00
R-7228	Tarp cable	02/27/2024	02/27/2024	Internal Workshop - Night Shift	Replaced LH cable.	\$0.00
S-6090	B - 1 Year	02/26/2024	02/26/2024		Amber clearance light out LH front - replaced.	\$0.00
				Internal Workshop - Fabrication	Cut top mud guard brackets off flush with side of trailer over axles 1 and 2. Front bracket needs to be fully cut off. Complete cutting off of mud guards over 1	
R-6864	Welding Repair	01/04/2024	01/19/2024	7461	and 2 axel of trailer.	\$0.00
				Internal Workshop - Fabrication	Axles, Trailing arm saddles and cross members have had history of cracking on some trailers. A qualified boiler maker is to inspect each axle, each trailing arm saddle and each cross member for cracks. These cracks are to be welded up as per the Axle repair procedure (See Jay for advise). Please record all repairs in detail so they can be saved in the units history. -- No visible cracks on trailing arms to axle. No visible cracks in crossmembers.	\$0.00
R-7112	Welding Repairs	01/12/2024	01/09/2024			\$0.00
R-6991	Mud Guard	01/12/2024	01/05/2024	Internal Workshop - Night Shift	Fitted both checker plate guards on rear apron.	\$0.00
					Tarp roller on headboard 2nd roller cracking at weld.	
S-6030	A - 3 Week	01/25/2024	01/05/2024		Fit alloy guards to rear of trailer.	\$0.00
R-7008	Welding Repair	01/12/2024	01/03/2024	Internal Workshop - Fabrication		\$0.00
				Internal Workshop - Fabrication	Die grind out weld and cracks. Wire buff and clean areas to be	
R-5828	Welding Repair	02/01/2023	01/03/2024	5973	welded. Weld and clean. Straighten guards. Cracks on bin rails - closest to tailgate end.	\$0.00
I-25	Machinery Inspection	12/14/2023	12/14/2023		Passed as per attached.	\$0.00

R-6699	Brake valves	10/13/2023	12/12/2023	Internal Workshop - Night Shift	Brake valve under ball race leaking badly out of the exhaust. Repaired.	\$0.00
					R&R LH rear tarp cable	
					R&R LH Rear tarp roller	
					R&R perished tyre 1st axle RH outer	
S-5973	A - 3 Week	12/12/2023	12/12/2023		R&R mudflap	\$0.00
S-5924	A - 3 Week	11/13/2023	11/15/2023		Rh inner tarp roller bearing mount cracking at weld on bin.	\$0.00
S-5857	A - 3 Week	10/13/2023	10/13/2023		Brake valve under ball race leaking badly out of the exhaust. JC.	\$0.00
S-5797	A - 3 Week	09/08/2023	09/14/2023			\$0.00
				Internal Workshop - Night Shift	R&R 1st axle RH outer tyre with runout.	
T-141	Tyre	09/12/2023	09/12/2023		R&R dolly mudflap.	\$0.00
R-6452	Brakes	07/10/2023	08/23/2023	Internal Workshop	Replaced 4th axle brakes and leaking fitting on booster.	\$0.00
R-6451	Lights	07/10/2023	08/22/2023	Internal Workshop - Night Shift	Replaced bulb.	\$0.00
S-5739	A - 3 Week	08/21/2023	08/22/2023			\$0.00
S-5702	A - 3 Week	07/27/2023	07/31/2023		Puncture repairs 4 axle LH outer	\$0.00
T-130	Dolly Tyre	08/03/2023	07/25/2023		Bridgestone Wacol	\$0.00
					RH tarp cable tightened	
					Air leak 4th axle booster - tightened hose clamps	
S-5636	A - 3 Week	07/10/2023	07/10/2023		Trailing arm bushes worn u/s	\$0.00
S-5597	A - 3 Week	06/20/2023	06/20/2023		R&R LH tarp cable	\$0.00
R-6281	Tyres	06/13/2023	06/13/2023	6519 Internal Workshop - Night Shift	1st axle RHS dolly tyres replaced with runouts.	\$0.00
S-5502	A - 3 Week	05/16/2023	05/22/2023	Internal Workshop - Night Shift		\$0.00
				Internal Workshop	Tested for air leaks. Found leaking air bag on RHR of Trailer. Pick up air bag and fit. Retest for leaks - OK.	\$0.00
R-6214	Air Leak	05/16/2023	05/16/2023	Internal Workshop - Night Shift	Completed by Tyson.	\$0.00
S-5458	A - 3 Week	04/21/2023	04/24/2023			\$0.00
				Internal Workshop - Night Shift	Garth - Replace LH 2nd axle inner tyre with new run out.	\$0.00
				Internal Workshop - Night Shift	Completed by Tyson.	
S-5405	A - 3 Week	04/05/2023	04/05/2023		Pin hole in fitting on 4th axle LHS booster (t piece).	\$0.00
R-6186	Mud Flap	03/27/2023	03/27/2023	Internal Workshop - Night Shift	Garth - Fit mud flap back on rear LHS.	\$0.00
R-6040	Tarp cable	03/23/2023	03/23/2023	Internal Workshop - Night Shift	Garry - Replaced RHS tarp cable.	\$0.00
				Internal Workshop	Foot brake valve on the dolly leaking Replaced leaking ABS / Hill assist valve under dolly.	\$0.00
R-6048	Air valve	03/22/2023	03/22/2023	6223 Internal Workshop - Night Shift	Completed by Garth.	\$0.00
S-5351	A - 3 Week	03/16/2023	03/16/2023			\$0.00
				Internal Workshop - Night Shift	Rear tarp bearing. Garry - replaced both rear bearings.	\$0.00
R-6184	Tarp bearing	03/07/2023	03/07/2023		Bridgestone Wacol Call out to trailer tyre repair on LHS inside and outside 4th axle, and RHS	\$0.00
R-5966	Tyre	02/17/2023	02/17/2023		inside 4th axle. Invoice attached.	\$0.00
				Internal Workshop - Night Shift	Completed by Tyson.	
					R&R faulty tyre 1st axle RH outer.	
S-5286	A - 3 Week	02/15/2023	02/15/2023		Tighten tarp cables.	\$0.00
R-5943	Mud Flaps	02/14/2023	02/14/2023	Internal Workshop - Night Shift	Ryan / Garry - Replaced 3 x mud flaps.	\$0.00

R-5941	Tyre	02/08/2023	02/08/2023	Internal Workshop - Night Shift	Gath - Repair hole on 3rd axle LH outer tyre and re-fit.	\$0.00	
R-5656	Brakes	01/11/2023	01/30/2023	Internal Workshop - Night Shift	Not Working. Other: Major Concerns (Take pics). Back axle not releasing will after 7 minutes Garth - checked and all okay.	\$0.00	
S-5234	B - 1 Year	01/30/2023	01/30/2023	Internal Workshop - Night Shift	Completed by Garth. EBS leaking badly. Brake re-line 2nd axle removing wheels, drums and shoes. Replacing with new. Brakes adjusted.	\$0.00	
S-5181	A - 3 Week	12/15/2022	15/12/2022	22	Repaired puncture LH outer tyre 3rd axle.	\$0.00	
S-5099	A - 3 Week	11/18/2022	23/11/2022	23	Internal Workshop - Night Shift	Completed by Tyson. Internal Workshop - Night Shift	\$0.00
R-5397	Air Lines	11/09/2022	11/09/2022	Internal Workshop - Night Shift	Completed by Izaak. 2nd axle brakes next time in shed.	\$0.00	
S-5039	A - 3 Week	10/31/2022	31/10/2022	19	Internal Workshop - Night Shift	RHS LINES TO TRUCK NEARLY WORN THROUGH/WAY TO LONG Tyson - re-solder EBS lead. R&R load sensor air line. Zip tie back together.	\$0.00
R-5614	Floor	10/18/2022	10/18/2022	Internal Workshop - Night Shift	Completed by Izaak. Rear bin door top left grease nipple shroud is bent; can't grease.	\$0.00	
R-5126	Reverse Lights	09/01/2022	10/12/2022	Shephard Transport Equipment	Shepherd's replaced floor. Invoice attached.	\$0.00	
S-4992	A - 3 Week	10/13/2022	12/10/2022	23	LH reverse light U/S. Completed by Izaak - rewired rear reverse lights due to wires being broken. Completed by Izaak. Replaced trailer plug, rewired rear reverse light due to wires being broken.	\$0.00	
R-5125	Axles	09/01/2022	09/20/2022	Full repack on all axles ASAP (grease). Tyson - been done.	\$0.00		
S-4926	A - 3 Week	09/20/2022	20/09/2022	19	Tyson - mudguard/bracket/flap broken off LHS 3rd axle. Garth - Remove 1st and 2nd hub assembly, rock out bearings, clean out old grease, fit new bearings, pack with new grease, refit. Adjusted brakes.	\$0.00	
R-5129	Bearings, Brake	09/06/2022	09/06/2022	Internal Workshop	C Service created from previous wheel bearing repack This is to bring the service schedule into alignment	\$0.00	
S-5314	C - 2 Year	02/24/2023	09/06/2022	See recent wheel bearing repack service sheet for information	\$0.00		
R-5132	Bearings, Brake	09/05/2022	09/05/2022	Garth - removed 3rd and 4th wheels and hubs, rock out bearings, clean out old grease, fit new bearings, repack with new grease, refit wheels, adjusted brakes. Made new tool to remove hub.	\$0.00		
R-4715	Axle re-line	07/15/2022	09/01/2022	3rd axle reline next service. Garth completed.	\$0.00		
S-4856	A - 3 Week	09/01/2022	01/09/2022	21	Garth - full repack on all axles ASAP (grease) (R-5125). LH reverse light U/S (R-5126). Replaced LH tarp cable due to nearly snapped; all done completed 01/09/22	\$0.00	
R-5050	Guard, Mud Flaps, Pins,	08/23/2022	08/23/2022	Tyson - Tighten tarp cable RHS. Rotate rubber tarp blocks. Heat up rear tailgate pin to free up grease - grease pins. R&R front left dolly guard and brackets. R&R mud flap. Replaced RHS tarp cable. Cleaned blue liner in bin where broken; all good.	\$0.00		
S-4781	A - 3 Week	08/11/2022	11/08/2022	27	Izaak - repair tarp cable & tighten. Position tarp poles correctly and re-secure. Wax up tarp poles etc.	\$0.00	

T-81	Tyre	08/08/2022	08/02/2022	Bridgestone Wacol	Fit 4 x new tyres across 3rd axle.	\$0.00
R-4893	Tyres	07/15/2022	07/15/2022	Bridgestone Wacol	Replace 4 x tyres.	\$0.00
				Garth - EBS leaking at dolly.		
				3rd axle reline next service (R-4715).		
S-4691	A - 3 Week	07/12/2022	15/07/2022	24	Cracks at tailgate (pics sent to Jay).	\$0.00
S-4653	A - 3 Week	06/21/2022	21/06/2022	22	EBS leaking air.	\$0.00
R-4520	Tarp cable, Tarp motor	06/15/2022	06/15/2022		R&R faulty tarp motor. Greased and adjusted cables.	\$0.00
R-4470	Tyre	06/10/2022	06/13/2022		Spin flat spotted tyres 180 degrees on 3rd and 4th axle. Tyson: rotated outer tyres.	\$0.00
R-4460	Guard	06/07/2022	06/07/2022		Paul: removed rubber guards above dolly tyres.	\$0.00
				Paul:		
				Service brake relay valve for front 2 x axles is constantly exhausting air.		
S-4573	A - 3 Week	05/30/2022	30/05/2022	67	One body locator broken and one is bent.	\$0.00
S-4469	A - 3 Week	04/21/2022	21/04/2022	28	Original sheet MIA; Jay recompleted.	\$0.00
				Cracks in axle saddles.		
				Cracks in 1st cross member.		
S-4375	A - 3 Week	03/22/2022	23/03/2022	21	Bin floor rubbing on air tanks.	\$0.00
				Cracks in body RH rear.		
				Cracks in cross member.		
				Brake relay valve leaking.		
S-4314	A - 3 Week	03/02/2022	02/03/2022	38	EBS fault in trailer.	\$0.00
				3rd axle service brake imbalance drivers side low - replace slack adjuster and re-adjust.		
				Underbody chassis cracks near drawbar mounts - weld and repair crack. Tyson: R & R both slack adjusters on 3rd axle. Grind up broken welds and reweld.		\$0.00
R-3914	Defects	02/15/2022	02/15/2022			
				Weld angle for mudguard back on and remove guards 3rd and 4th axle. T-piece air fitting last axle		
				LHS booster has pin hole. Bracket broken 3rd axle (mudguard bracket) replaced and welded. 2 x		
				mudguards and mud flaps replaced. Mud flap front RH corner replaced. Service brake relay valve		
				leaking from exhaust 1st 2nd axle EBS. 4th axle mudguard cracked. 1st axle mudguard cracked.		
R-3835	Pre-machinery inspectic	02/06/2022	02/13/2022		Bottom of the tow eye worn.	\$0.00
R-3863	Tarp	02/08/2022	02/08/2022		Replaced cable. Realigned cable guards.	\$0.00
				Fitted missing flap rear RHS.		
				Straightened tarp.		
S-4197	A - 3 Week	01/23/2022	23/01/2022	43	Needs tyres 1st, 2nd axles low.	\$0.00
S-4132	A - 3 Week	12/09/2021	11/12/2021	26	Replaced shoes and drums 3rd and 4th axles.	\$0.00
				Internal Workshop	Jack.	
S-4014	A - 3 Week	11/02/2021	15/11/2021	29	Fitted tow eye bush.	
R-3597	Tyre	10/31/2021	10/31/2021		Internal Workshop	Fitted missing flap rear LHS
S-3937	A - 3 Week	10/17/2021	17/10/2021	42	Internal Workshop	Jack.
				Internal Workshop	Work done by Jarrod.	
S-3835	A - 3 Week	09/03/2021	06/09/2021	47	Added as reminders: Cracks in trailer tailgate and EBS valve at dolly leaking.	
R-3163	Tarp cable	08/10/2021	07/29/2021		Internal Workshop	Tarped cables shortened by Jarrod.
R-3081	Tarp cable	07/16/2021	07/22/2021		Internal Workshop	Replaced tarp cables

S-3740	A - 3 Week	07/21/2021	21/07/2021	16	Internal Workshop Service done by Jarrod
R-3072	Brake Re-line	07/16/2021	07/16/2021		Replaced tarp cables Replaced o'ring on main hoist Replaced hose fitting hyd mast
S-3671	A - 3 Week	07/05/2021	05/07/2021	24	Internal Workshop Brake re-line of 1st & 2nd axles done - job done by Jarrod
R-2973	Mudguards	06/21/2021	06/21/2021		Internal Workshop Service done by Jarrod Defects: RHR guards missing L:HR guard u/s - suggest removing rear axle guards Dolly brakes need doing
S-3591	A - 3 Week	06/07/2021	11/06/2021	32	Tarp cables need replacing
R-2868	Oil line	05/28/2021	05/28/2021		Fit mudguard back onto trailer LHR - job done by Garth
R-2829	Tarp cable	05/19/2021	05/19/2021		Internal Workshop Service done by Jarrod Defects: Cracks in body rear of bin
R-2815	Air line	05/14/2021	05/14/2021		Dolly brakes low
S-3530	A - 3 Week	05/10/2021	10/05/2021	26	Oil line on trailer replaced - was leaking
R-2759	Tarp cable	04/28/2021	04/28/2021		Internal Workshop Adjusted tarp cables - job done by Jarrod
R-2712	Mudflap	04/15/2021	04/15/2021		Internal Workshop Airline replaced - job done by Jarrod
S-3454	A - 3 Week	04/14/2021	14/04/2021	27	Internal Workshop Service done by Garth
R-2673	Tyres	04/01/2021	04/01/2021		Tightened hydraulic hose on hoist
S-3388	A - 3 Week	03/18/2021	18/03/2021	24	Internal Workshop Replaced tarp cable - repacked idlers with grease - job done by Garth
R-2224	Lights	12/08/2020	02/22/2021		Repaired brake hose on trailer - replaced hose clamps and tidying up leads from front of trailer
S-3346	A - 3 Week	02/19/2021	22/02/2021	12	Internal Workshop Repair RHR mudflap
S-3305	A - 3 Week	02/10/2021	10/02/2021	22	Internal Workshop Service done by Garth
S-3243	A - 3 Week	01/19/2021	19/01/2021	48	Internal Workshop Service done by Garth Tightened first air tank Tightened hydraulic fitting on tipper ram Fitted missing valve extensions

R-2357	Tyre repairs	01/18/2021	01/18/2021	Internal Workshop	Repaired puncture - suggest fitting 4 x new tyres on dolly
R-2341	Tyres	01/04/2021	01/04/2021	Internal Workshop	Fitted runout to RHS 3rd axle
R-2165	Brake Re-line	12/03/2020	12/03/2020		RH indicator on trailer apron missing
S-2657	A - 3 Week	12/01/2020	02/12/2020	28	Internal workshop Service done
R-1956	Tarp cable	11/26/2020	11/26/2020		1st & and axle RH brakes getting low - will need to be done next service
R-1686	Tarp bow	11/18/2020	11/18/2020		Internal Workshop Replaced both tarp cables
S-1355	A - 3 Week	11/04/2020	04/11/2020	21	internal workshop Removed & shift bolts - bolted through head board
R-1206	Tyres	11/03/2020	11/03/2020		Internal Workshop A service done
S-603	A - 3 Week	10/14/2020	14/10/2020	22	Internal Workshop A service done
S-527	A - 3 Week	09/22/2020	22/09/2020	33	Repaired 1st axle RH outer puncture
R-295	Mudflaps	08/31/2020	08/31/2020		Replaced LH 3rd axle mudflap Straightened mudguard bracket Repaired mount on trailer chassis
S-459	A - 3 Week	08/20/2020	20/08/2020	23	Removed mudflaps from front of axle
R-243	Tyres	08/10/2020	08/10/2020		A service done
R-229	Mudguards	08/06/2020	08/06/2020		1st tarp bow bolts missing - drilled & tapped broken bolts out of holes - make bolts to suit
S-391	A - 3 Week	07/28/2020	07/28/2020		Sidewall was damaged - fitted puncture repaired runout
R-145	Brakes	07/08/2020	07/08/2020		Straightened & adjusted 3rd axle mudguard post
S-324	A - 3 Week	07/06/2020	07/06/2020		A service done
R-122	Mudguards	06/24/2020	06/25/2020		Replaced LH tarp cable
S-266	A - 3 Week	06/17/2020	06/18/2020		Replaced brake drums & shoes on 1st & 2nd axle
S-199	A - 3 Week	05/27/2020	05/28/2020		A service done
R-1641	Tyre repairs	03/20/2020	03/20/2020		DEFECTS: monitor minor play 4th axle LH w/bearing
					Crack in crossmember LHF 1st axle
					Dolly brakes low
					2nd axle reline to be done asap
					1st axle suggest reline at same time to keep them even
					Replaced mudguard & refit brackets & mudflap to truck
					Service done
					DEFECT: missing 3rd axle mudguard & bracket
					A service done
					DEFECTS: Body rubbing on dolly guard mounts
					Body rubbing on air tanks
					Dolly guards missing due to damage
					Cracks in crossmember LHF 1st axle
					Minor play 4th axle LH w/bearing - monitor
					Internal workshop Repaired 3rd axle LH inner tyre puncture

R-1642	Tyre repairs	03/19/2020	03/19/2020	Internal workshop	Puncture - removed tyre & repaired with patch - reinstalled & tensioned
R-1644	Tyre repairs	03/17/2020	03/17/2020	Internal workshop	Repaired puncture 2nd axle LHS
R-1643	Tyre repairs	03/17/2020	03/17/2020	Internal workshop	Split sidewall tyre on trailer RHS outside 3rd from back - removed tyre from rim & replace with Dunlop second hand one from stock - refit tyre to truck & tensioned wheel nuts
R-1645	Tarp cable	03/16/2020	03/16/2020	Internal workshop	REQUEST: broken LH tarp cable DEFECTS: removed broken cable & checked cable bulldog clamps - cut 15 metres of new cable - reinstalled new cable to tarp & pulleys - aligned tarp bows so it closes straight - adjusted tarp cable - waxed cable - check operation and adjust cable tension - all ok
R-1646	Tyre repairs	02/25/2020	02/25/2020	Internal workshop	Repaired puncture 3rd axle LH inner
R-1647	Pre-machinery check	02/12/2020	02/12/2020	Internal workshop	Pre-machinery check over, replaced all slack adjusters with Bendix DEFECT: crack in crossmember LHF of 1st axle
R-1648	Tarp cable	11/28/2019	11/28/2019	Internal workshop	Replaced LHS tarp cable
R-1649	Tyre repairs	09/11/2019	09/11/2019	Internal workshop	Repaired 2nd axle RHS inside tyre, repaired 2nd axle LHS outside tyre
R-1650	Tyre repairs	08/27/2019	08/27/2019	Internal workshop	Repaired LHS Dolly 2nd inside tyre, fitted flap LHS rear apron
R-1651	Tyre repairs	07/26/2019	07/26/2019	Internal workshop	Repaired 4th axle LHS inside tyre, fixed up LHR mudflap
R-1652	Check over	02/26/2019	02/26/2019	Internal workshop	Loosened rubber & turned back under the guard on the RHS