

Number	Type	Date Open	Date Closed	Fault	Repairer / Notes	Cost / Invoice
S-7683	A - 3 Week	03/12/2026	03/12/2026		Internal Workshop - Night Shift	\$0.00
R-9111	Tailgate Fin	02/26/2026	02/26/2026	12099	Internal Workshop - Night Shift REPLACED QUICK RELEASE VALVE FOR TAIL GATE BOOSTER. DUE TO POOR AIR FLOW.	\$0.00
S-7624	B - 1 Year	02/18/2026	02/18/2026		Internal Workshop - Night Shift	\$0.00
S-7567	A - 3 Week	01/20/2026	01/20/2026		Internal Workshop - Night Shift	\$0.00
S-7513	A - 3 Week	12/12/2025	12/12/2025		Internal Workshop - Night Shift	\$0.00
R-8848	Brake Relin	09/04/2025	11/13/2025		Internal Workshop - Night Shift REPLACED 2ND AXLE BRAKE DRUMS AND SHOES. REPLACED BOTH SLACK ADJUSTERS ON SAME AXLE.	\$0.00
S-7453	A - 3 Week	11/11/2025	11/13/2025		Internal Workshop - Night Shift	\$0.00
S-7397	A - 3 Week	10/21/2025	10/21/2025		Internal Workshop - Night Shift	\$0.00
S-7330	A - 3 Week	10/01/2025	10/01/2025		Internal Workshop - Night Shift	\$0.00
R-8874	Tailgate rut	09/15/2025	09/08/2025		Internal Workshop - Night Shift REPLACED DAMAGED TAILGATE SEAL.	\$0.00
R-8318	Wheel Bear	02/05/2025	09/05/2025		Internal Workshop - Night Shift RE-PACKED ALL WHEEL BEARINGS AND REPALCED ALL WHEEL SEALS. Internal Workshop - Night Shift REPLACED DAMAGED TARP CABLE. REPAIRED RHS 4TH AXLE GUARD BRACKET.	\$0.00
S-7269	A - 3 Week	09/03/2025	09/03/2025		REPIRED PUNTURE LHS 4TH AXLE OUTER.	\$0.00
S-7199	A - 3 Week	08/12/2025	08/13/2025		Internal Workshop - Night Shift	\$0.00
R-8559	EBS	05/22/2025	07/15/2025		Internal Workshop - Night Shift NIGHT SHIFT SAYING NO LONGER LEAKING.	\$0.00
S-7123	A - 3 Week	07/15/2025	07/15/2025		Internal Workshop - Night Shift REPAIRED LHS FRONT DOLLY GUARD POLL. Internal Workshop - Night Shift REPLACED 2X REAR MUDFLAPS.	\$0.00
S-7047	A - 3 Week	06/18/2025	06/19/2025		REPALCED ALL PLASTIC TARP ENDS.	\$0.00
R-8484	TARP BOW!	04/15/2025	05/16/2025		REPLACED DAMAGED TARP BOWS.	\$0.00
S-6956	A - 3 Week	05/22/2025	05/16/2025			\$0.00
S-6892	A - 3 Week	04/01/2025	04/01/2025		SERVICE COMPLETED BY COREY/TOM/FINAL CHECKED BY RITCHIE.	\$0.00
S-6796	C - 2 Year	02/05/2025	02/05/2025		Internal Workshop - Night Shift SERVICE COMPLETED BY IZAAK H.	\$0.00
R-8207	Tarp	12/11/2024	12/06/2024		Internal Workshop - Night Shift REPLACE PLASTIC TARP ENDS ON 4 BOWS. REPLACE BOTH TARP CABLES. FIT NEW BOLY ON 1ST TARP BOW.	\$0.00
S-6700	A - 3 Week	12/05/2024	12/05/2024		Internal Workshop - Night Shift SERVICE COMPLETED BY TYSON E. Defect Notice # D103367396 issued for: 1. Tow eye bush oversize 2. Axles 1 and 3 brakes do not work Taken to Brown and Hurley Yatala for repair. Invoice attached.	\$0.00
I-57	Machinery	12/03/2024	12/05/2024		Cleared and COI attached.	\$0.00
R-8203	Airbags	12/11/2024	12/03/2024		Internal Workshop - Night Shift REPLACED BOTH AIRBAGS ON 1ST AXLE DOLLY. Internal Workshop - Night Shift REPLACED TRACTOR PROTECTION VALVE ON 1ST AIR TANK AND NOW HAVE BRAKES. REPLACED TOW EYE	\$0.00
R-8170	Machinery	12/03/2024	12/03/2024		BUSH. ALL CLEARED BY BROWN AND HURLEY YATALA.	\$0.00
R-6020	Trailing arr	03/06/2023	11/19/2024		Internal Workshop - Night Shift D&L WHEEL ALIGHMENT REPLACED ALL TRAILING ARM BUSHES AND BOLTS AND DONE WHEEL ALIGHMENT.	\$0.00
S-6646	A - 3 Week	11/08/2024	11/12/2024		Internal Workshop - Night Shift SERVICE COMPLETED BY IZAAK H.	\$0.00
R-8092	Brakes	10/28/2024	10/24/2024		Internal Workshop - Night Shift REPLACED 3RD AND 4T BRAKE DRUMS AND SHOES. REPLACED 3RD AND 4TH AXLE SLACK ADJUSTERS.	\$0.00
S-6590	A - 3 Week	10/14/2024	10/14/2024		Internal Workshop - Fabrication SERVICE COMPLETED BY IZAAK H.	\$0.00
S-6530	A - 3 Week	09/16/2024	09/16/2024		Internal Workshop - Night Shift SERVICE COMPLETED BY JARROD H.	\$0.00
R-7855	Airbag	09/09/2024	09/02/2024		Internal Workshop - Night Shift REPLACED BLOWN AIRBAG ON 4TH AXLE RHS	\$0.00
S-6487	A - 3 Week	08/29/2024	08/29/2024		Internal Workshop - Night Shift SERVICE COMPLETED BY JARROD H. Internal Workshop - Fabrication BOILER MAKERS WELDED A PIECE OFF 100X10MM STRIP ALL THE WAY ACROSS THE BACK AND UP THE	\$0.00
R-7710	Tipper Floo	07/23/2024	08/08/2024	8711	SIDES.	\$0.00

				SERVICE COMPLETED BY TYSON E. REMOVE TARP TENSIONER ON RHS AND FREE UP.	
S-6420	A - 3 Week	07/18/2024	07/18/2024	RE-FIT AND TENSION TARP	\$0.00
S-6340	A - 3 Week	07/01/2024	07/01/2024	SERVICE COMPLETED BY TYSON E. SERVICE COMPLETED BY JARROD H.	\$0.00
S-6319	A - 3 Week	06/20/2024	06/20/2024	TIGHTEN LOOSE SHOCK BOLTS.	\$0.00
S-6240	A - 3 Week	05/15/2024	05/15/2024		\$0.00
S-6175	B - 1 Year	04/04/2024	04/04/2024		\$0.00
S-6130	A - 3 Week	03/14/2024	03/14/2024	Trailing arm bushes noted as worn	\$0.00
R-7243	Tarp	03/04/2024	03/04/2024	Internal Workshop - Night Shift Repair broken wiring.	\$0.00
R-7270	Tarp	02/29/2024	02/29/2024	Internal Workshop - Night Shift All tarp bow ends damaged on tarp bows. Replaced all tarp bow ends and fit two new cables.	\$0.00
R-7199	Airbag	02/27/2024	02/27/2024	Internal Workshop - Night Shift Replaced leaking airbag - 3rd axle LHS.	\$0.00
R-7214	Puncture	02/19/2024	02/19/2024	Internal Workshop - Night Shift Remover and repair puncture No leaks Torqued wheel nuts.	\$0.00
S-6069	A - 3 Week	02/19/2024	02/19/2024		\$0.00
R-7221	Tyre	02/12/2024	02/12/2024	Internal Workshop - Night Shift Remove and repair 1st axle LH inner and outer. Retensioned wheel nuts.	\$0.00
R-6996	Welding Re	01/12/2024	01/31/2024	Internal Workshop - Fabrication	\$0.00
R-6874	Welding Re	01/10/2024	01/10/2024	Internal Workshop - Fabrication Danny inspected the area under the body at the back of the bin chassis and found no visible cracks	\$0.00
R-6698	Dolly brake	10/12/2023	01/08/2024	Internal Workshop - Night Shift Drums and shoes on 1st and 2nd got replaced on 8/1/24	\$0.00
S-5994	A - 3 Week	01/08/2024	01/08/2024	Internal Workshop - Night Shift Checked Dolly brakes as per R6698 Note and they are ok	\$0.00
R-7026	Airbag	12/01/2023	12/01/2023	Internal Workshop Replaced blown air bag on 4th axle LHS.	\$0.00
R-7024	Air Bags, St	11/21/2023	11/21/2023	Internal Workshop - Night Shift R&R both airbags.	\$0.00
S-5931	A - 3 Week	11/16/2023	11/20/2023	Replace 2 x leaking airbags on dolly	\$0.00
R-6678	Lights	10/17/2023	10/17/2023	7131 All reversing lights flash with indicators. Checked junction boxes all connections fine. Wiring under draw bar cleaned up - working good. EBS valve leaking at exhaust - JC	\$0.00
S-5853	A - 3 Week	10/12/2023	10/12/2023	Dolly brakes will need doing in the next 6-8 weeks - JC	\$0.00
I-14	Machinery	10/03/2023	10/03/2023	Self clearing defect notice issued. Cleared as per attached.	\$0.00
R-6632	Machinery	09/27/2023	09/27/2023	3rd axle outer tyre side wall damage replace all damage tyre on 1st and 3rd axle both sides Replaced all damaged tyres by Beaurepairs Wacol. Diagnose break in wiring inside drawbar. Hose out drawbar and run new wiring through drawbar and hook up park lights. Repair wiring at number plate light.	\$0.00
R-6598	Drawbar, Li	08/31/2023	08/31/2023		\$0.00
S-5765	A - 3 Week	08/28/2023	08/28/2023	Refit brake spring to 3rd axle RH side inspect brakes etc. Internal Workshop Flat tyre - 2nd axle on dolly RHS inner. Remove tyre and check condition. Found to be too low on treat to repair puncture. Replaced with a runout tyre - repair two holes in runout tyre before fitting.	\$0.00
T-137	Dolly Tyre	08/17/2023	08/17/2023	Flat tyre - 2nd axle on dolly LHS outer. Remoe, repair puncture, and refit tyre.	\$0.00
S-5715	A - 3 Week	08/04/2023	08/07/2023	1st axle airbag leaking when loaded.	\$0.00
R-6611	EBS wiring	08/04/2023	08/04/2023	Internal Workshop - Night Shift Repair broken EBS wiring a tow eye.	\$0.00
S-5660	A - 3 Week	07/17/2023	07/17/2023		\$0.00
R-5065	Tailgate	08/29/2022	06/26/2023	5252 Fixed by Jarrod Service 5613	\$0.00
S-5613	A - 3 Week	06/26/2023	06/26/2023	Replaxed 3rd axle RH airbag Internal Workshop - Night Shift R&R both tarp cables Remove RH rear tarp roller & retap threads & secure roller bracket Flip bolts on front tarp	\$0.00
R-6310	Tarp	06/15/2023	06/12/2023	bow Secure tarp to pole on LH side.	\$0.00
R-6021	Shock bush	03/06/2023	06/09/2023	Internal Workshop - Night Shift All shockie bushes need replacing. Done - Jarrod 9/6/23	\$0.00

R-5868	EBS	02/16/2023	06/09/2023	6046	Internal Workshop - Night Shift Fixed - Jarrod 9/6/23 Replaced 7 pin plug Bolt missing body prop pivot - replaced Tailgate seal damaged at bottom Tighten all loose shock bolts Weld up broken s-cam mount 4th RH		\$0.00
S-5549	A - 3 Week	06/06/2023	06/09/2023		All trailing arm bushes worn		\$0.00
S-5444	A - 3 Week	04/19/2023	04/19/2023		Internal Workshop - Night Shift Completed by Tyson. Tightened LH tarp cable.		\$0.00
S-5339	A - 3 Week	03/06/2023	03/06/2023		Internal Workshop - Night Shift Completed by Garth. All trailing arm bushes U/S (R-6020). All shockie bushes need replacing (R-6021).		\$0.00
S-5253	A - 3 Week	02/06/2023	02/06/2023		Internal Workshop - Night Shift Completed by Tyson. Secure hyd hose above 1st axle. Tighten RHS tarp cable.		\$0.00
R-5632	Wheel Bear	01/03/2023	01/17/2023		Internal Workshop - Night Shift All wheel bearings need to be removed, cleaned and inspected for wear / damage. Replace damaged wheel bearings as required. Repack all bearings with fresh grease and replace dust deals with new items Refit all hubs and wheels to spec. Note ** Replace worn brake shoes and drums while everything is apart if required ** 16th - Garth - Removed 2nd, 3rd, 4th hub assembly, removed bearings, cleaned and inspected 3rd and 4th, re-packed with grease, re-fit and torqued. 2nd axle knock out bearings and replaced with new, packed with grease, re-fit and torqued. Adjusted brakes. 17th - Garth - Removed 1st axle hub assembly, knock out bearings and replaced with new, packed with grease, refit and torqued. Adjusted brakes.		\$0.00
S-5315	C - 2 Year	02/24/2023	01/17/2023		Internal Workshop C Service created from previous wheel bearing repack This is to bring the service schedule into alignment See recent wheel bearing repack service sheet for information		\$0.00
S-5205	B - 1 Year	01/16/2023	01/16/2023		Internal Workshop - Night Shift Completed by Garth. Straighten RHS dolly bumper. Straightened RHS rear bumper.		\$0.00
R-5630	Tarp cable	12/12/2022	12/12/2022		Cleaned out build up from under grain chute.		\$0.00
S-5143	A - 3 Week	12/06/2022	06/12/2022	33	Internal Workshop - Night Shift Garth replaced LH and RH cable and replaced cable guide at centre on trailer (missing).		\$0.00
S-5058	A - 3 Week	11/03/2022	03/11/2022	25	Internal Workshop - Night Shift Completed by Tyson.		\$0.00
R-5408	Brake	10/25/2022	10/25/2022		Internal Workshop Jay - Replaced spring brake control valve; this was causing brake not to come on.		\$0.00
R-5589	Pre-machir	10/24/2022	10/24/2022		Internal Workshop - Night Shift Garth: 2nd axle brake reline. Adjusted brakes.		\$0.00
R-4865	Shockie bu	07/28/2022	10/09/2022		1st and 2nd axle shockie bushes U/S. Izaak - R&R shocky bushes. Izaak - replaced 1st, 2nd, 3rd axle shocky bushes. Spread all shocky mount apart top and bottom to fit new bushes and shocky back in. Replaced 2nd axle shocky straps.		\$0.00
S-4980	A - 3 Week	10/10/2022	09/10/2022	27	Replaced both tarp cables. Damaged. Check Tyre Pressure (Visual). Flat tyre on drivers side, outside rear axle.		\$0.00
T-51	Flat tyre	09/05/2022	10/09/2022	5291	Izaak - done already at previous service.		\$0.00
R-5204	Body repair	09/27/2022	09/29/2022		internal Izaak - hit back and grind sharp edges off best I could.		\$0.00
R-5066	Hydraulic h	08/29/2022	09/13/2022	5253	Other. Inspect Hydraulic Fittings and hoses (Visual). Leaking a little. Izaak cleaned; all good.		\$0.00
S-4892	A - 3 Week	09/13/2022	13/09/2022	21	Izaak.		\$0.00
R-4866	air bag	07/28/2022	08/23/2022		1st axle RHS air bag leaking 23/08/22 - Jay - this has been done before. Tyson - cracks in axle saddles.		\$0.00
S-4813	A - 3 Week	08/23/2022	23/08/2022	26	Front cross member cracked.		\$0.00
R-4960	Mud Guard	08/11/2022	08/11/2022		Garry - Re-tensioned tarp cable passenger side. Re-aligned rear passenger mud guard. Removed and straighten rear checker plat and refit.		\$0.00

					Garth - 1st and 2nd axle shockie bushes U/S (R-4865). 1st axle RHS air bag leaking (R-4866). Fit missing valve extensions x 1. Adjust tarp cables.	
S-4748	A - 3 Week	07/28/2022	28/07/2022	21	Refit mudguards at rear.	\$0.00
					Garth - all shockie rubbers need replacing.	
S-4677	A - 3 Week	07/06/2022	07/07/2022	15	Repair tarp cable LHS.	\$0.00
R-4122	Slack adjus	03/30/2022	06/22/2022		1st axle brakes out of adjustment; suspect faulty slack adjustor. Garth - welded up s'cam tube.	\$0.00
R-3998	Slack adjus	03/01/2022	06/22/2022		Axle 1 RHS slack adjustor needs replacing. Jay inspected and all good.	\$0.00
					Garth - 1st axle RHS s'cam tube broken - clean and weld, adjust brakes. All shockie brakes U/S. Top centre RHS of tipper bin cracked - pics sent to Jay. Repair 3rd axle outer tyre.	
S-4645	A - 3 Week	06/15/2022	22/06/2022	29	Straighten LH rear guard.	\$0.00
S-4559	A - 3 Week	05/24/2022	24/05/2022	33		\$0.00
S-4483	A - 3 Week	04/21/2022	21/04/2022	21	Axle 1 RHS slack adjuster needs doing still.	\$0.00
R-4169	Slack adjus	04/06/2022	04/06/2022		REPAVED BOTH SLACK ADJUSTERS WITH NEW ONES; ALL OK.	\$0.00
					1st axle brakes out of adjustment; suspect faulty slack adjustor.	
S-4417	A - 3 Week	03/31/2022	30/03/2022	29	Cracks in 1st cross member.	\$0.00
R-3865	Mud Flaps	02/09/2022	03/01/2022	4181	Replaced. Axle 1 RHS slack adjustor needs replacing. Cracks in cross members.	\$0.00
S-4312	A - 3 Week	03/02/2022	01/03/2022	34	Cleaned up wiring at ring feeder.	\$0.00
R-3975	Tarp cable	02/21/2022	02/21/2022		Fit 2 x new tarp cables	\$0.00
R-3877	Drawbar	02/10/2022	02/10/2022	4189	Dent in angle top draw bar. Tail gate lock pin (swing) bent. Danny repaired. LH 2nd axle inner tyre U/S.	\$0.00
S-4207	A - 3 Week	01/26/2022	26/01/2022	16	2nd axle inner LHS puncture repair.	\$0.00
S-4166	A - 3 Week	01/10/2022	10/01/2022	27		\$0.00
S-4142	A - 3 Week	12/14/2021	14/12/2021	22		\$0.00
S-4070	A - 3 Week	11/22/2021	22/11/2021	33	Internal Workshop Internal Workshop Jack. Replaced tow eye bush.	\$0.00
S-3983	A - 3 Week	10/20/2021	20/10/2021	23	Repaired EBS wiring at draw bar.	
R-3193	Tarp	08/16/2021	09/28/2021		Internal Workshop Done by Jack. Replaced tarp adjuster.	\$0.00
S-3881	A - 3 Week	09/28/2021	28/09/2021	49	Internal Workshop Done by Jack.	\$0.00
R-3173	Tarp cable	08/10/2021	08/10/2021		Internal Workshop Replace tarp cables truck and trailer. Jay said this has been done. Internal Workshop RH tarp adjustor needs replacing. 1st axle shock bushes replaced.	\$0.00
S-3778	A - 3 Week	08/10/2021	10/08/2021	26	Draw bar bushes worn.	\$0.00
R-3099	Brakes	07/23/2021	07/27/2021	3270	Internal Workshop Dolly brakes dragging or over working. Job done by Jarrod - checked and readjusted dolly brakes.	
R-3073	Brake Re-li	07/16/2021	07/16/2021		Internal Workshop 1st & 2nd axle brake re-line done by Jarrod	
S-3717	A - 3 Week	07/15/2021	15/07/2021	16	Internal Workshop Service done by Garth	
S-3658	A - 3 Week	06/29/2021	29/06/2021	27	Internal Workshop Service done by Garth Internal Workshop Service done Repaired cracked 3rd axle S-cam tube Replaced LHR red reflector	
S-3583	A - 3 Week	06/02/2021	02/06/2021	35	Defect: Trailing arm bushes showing signs of wear - getting worse	
S-3499	A - 3 Week	04/27/2021	28/04/2021	22	Internal Workshop Service done by Jarrod	
R-2621	Tarp cable	03/22/2021	04/06/2021		Internal Workshop Replaced RHS tarp cable	

					Internal Workshop	Service done by Jarrod		
						DEFECTS: 1st axle shock bushes worn - monitor		
S-3427	A - 3 Week	04/06/2021	06/04/2021	33		Trailing arm bushes showing signs of wear		
R-2611	Mudflap	03/11/2021	03/29/2021	2003	Internal Workshop	Refit mudflap - job done by Jarrod		
					Internal Workshop	Service done by Jarrod		
S-3347	A - 3 Week	02/18/2021	04/03/2021	30		Secured rear mudflap		
S-3275	A - 3 Week	02/02/2021	02/02/2021	81	Internal Workshop	Service done by Laine		
R-1691	Brakes, Shc	11/18/2020	11/18/2020		Internal workshop	Replaced 5 x lower shock bushes Re-lined 1st axle brakes - rectified imbalance		
					Internal Workshop	A service done		
						Pre-machinery check over		
						Tightened RHR guard		
						Tightened LHR guard post		
						Straightened 3rd axle mudguard bracket as it was bent		
S-1634	A - 3 Week	11/13/2020	13/11/2020	17		Straightened mudflap on apron		
R-1224	Tyres	11/05/2020	11/05/2020		Millards	Replaced 16 x Bridgestone 11R22.5 148L R168 Inv 294278 - 05/11/2020		
					Internal Workshop	A service done		
S-913	A - 3 Week	10/27/2020	27/10/2020	21		Fitted 3 x runouts & repaired 2 x punctures		
S-2941	A - 3 Week	10/20/2020	20/10/2020	14	Internal Workshop	Replaced damaged reflectors		
R-411	Mudflaps	10/13/2020	10/13/2020			Replaced 2 x missing mudflaps		
						A service done		
S-565	A - 3 Week	10/06/2020	06/10/2020	33		Replaced RH tarp drive pulley		
R-357	Tyres	09/22/2020	10/02/2020		Internal Workshop	Mick inspected - Tyres wearing inside edges - 1st axle LH inner tyre worst of the 8 - pictures sent to Jay		
					Internal Workshop	Found: replaced 2 x tarp cables on trailer Replaced 1 x tarp cable on truck Tarp motor auto shut off not working - have to stop		
R-381	Tarp cable	09/30/2020	09/30/2020			motor manually - new motor to be ordered		
R-353	Mudflaps	09/18/2020	09/22/2020			Replaced missing mudflap Tarp not closing properly - 3rd bow back falling over - tightened loose tarp cable		
						Loaded 14/9/ - could not get at switch while loaded 15/9/2020 - Checked truck & trailer up & down alarm & visual indicator working for both -		
R-338	Reverse Be	09/15/2020	09/15/2020			could not fault operation Could not get fault to re-occur - replaced body up switch		\$0.00
R-319	Brake Shoe	09/08/2020	09/14/2020		Internal Workshop	Replaced 3rd & 4th axle brakes Replaced LH 4th axle tyres x 2		
					Internal Workshop	A service done		
S-490	A - 3 Week	08/31/2020	03/09/2020	28		DEFECT: 3rd & 4th axle brakes need re-line ASAP		
R-266	Drawbar	08/25/2020	08/25/2020			Unzeised wind up stand on drawbar Repaired body up alarm to be less clicky		
R-245	Slack adjus	08/12/2020	08/13/2020			Replaced 4 x slack adjusters		
						Service done		
						Adjusted RHR mudguard		
S-415	A - 3 Week	08/06/2020	06/08/2020	20		DEFECTS: Stemco slack adjusters on dolly need replacing		
R-205	Lights	07/29/2020	07/30/2020			Repaired rubbed through wiring at dolly apron		
						A service done		
S-359	A - 3 Week	07/17/2020	07/17/2020			3rd & 4th axle reline to be done next service!		
R-164	Mudguards	07/16/2020	07/16/2020			Bent 3rd axle mudguard brackets straight		
R-144	Mudguards	07/08/2020	07/08/2020			Replaced mudguard & mudguard post		
						A service done		
						3rd & 4th axle brakes worn low - check re-line next service		
S-295	A - 3 Week	06/25/2020	29/06/2020	21		4th axle RH mudguard missing - guard post mount missing - needs welding repair		
R-106	Mudguards	06/16/2020	06/17/2020			Replaced damaged mudflap		
R-888	Mudflaps	06/16/2020	06/16/2020		Internal workshop	Re-fit LHR mudflap on back apron - was left in the cab		
S-231	A - 3 Week	06/08/2020	06/08/2020		Internal Workshop	A service done		
						Service done		
S-147	A - 3 Week	05/12/2020	05/12/2020			Replaced RH tarp cable		
R-560	Tyres	05/01/2020	05/01/2020		Internal Workshop	Repaired puncture & re-installed & re-tensioned		

					Internal Workshop A service done Checked all trailing arm bolts Removed backing plates on dolly to remove rock Adjusted all brakes
S-744	A - 3 Week	04/06/2020	06/04/2020	21	DEFECTS: Minor cracks LH tailgate hinge mount, LHR mudguard rubbing through edge - minor
R-559	Mudguards	04/01/2020	04/01/2020		Prep steel & relight guard & rewelded bracket into place NOTE: LH drive tyre has a chunk of rubber out
R-558	Tailgate	03/26/2020	03/26/2020		Internal Workshop Had to heat top pivot pin & clamp the side to pull it across to the post - checked operation of bin fully extended up & let it come down by itself - the tailgate closes by itself
					Internal Workshop A service done Replaced LH tarp cable
S-743	A - 3 Week	03/16/2020	16/03/2020	35	DEFECTS: minor cracks LH tailgate hinge mount LHR mudguard rubbing through edge - minor
R-557	Mudflaps	03/02/2020	03/02/2020		Internal Workshop Straightened rear bar & fitted mudflap
R-556	Brakes	02/18/2020	02/18/2020		Internal Workshop Replaced spring brake park valve on 2nd air tank from the back
					Internal Workshop A service done DEFECTS: minor cracks LH tailgate hinge mount
S-742	A - 3 Week	02/10/2020	10/02/2020	21	LHR mudguard rubbing through edge - minor
R-555	Tyres	02/06/2020	02/06/2020		Internal Workshop Rotated 1st & 2nd axle tyres Internal Workshop A service done
					DEFECTS: minor cracks LH tailgate hinge mount
S-741	A - 3 Week	01/20/2020	20/01/2020	41	LHR mudguard rubbing through edge - minor
					Internal Workshop Service done Tightened 6 x loose shock bolts
					DEFECTS: minor cracks LH tailgate hinge mount
S-740	A - 3 Week	12/10/2019	10/12/2019	43	LHR mudguard rubbing through edge - minor
R-554	Mudflaps, S	11/22/2019	11/22/2019		Removed ALL BWC stickers & replace mudflaps with Holcim ones
R-553	Tyre repairs	11/13/2019	11/13/2019		Internal Workshop Repaired 3rd axle RHS outside tyre
R-552	Machinery	11/06/2019	11/06/2019		Fitted 4 x tyres to 4th axle - rotated others to suite - Fitted 4 x slack adjusters to 3rd & 4th axles - Fit 2 x new boosters to 3rd axle,
R-551	Tarp motor	10/29/2019	10/29/2019		Internal Workshop Replaced cracked tarp motor Internal Workshop A service done Repaired puncture 2nd axle outside tyre RHS
					DEFECTS: monitor cracks in trailing arm
S-739	A - 3 Week	10/28/2019	28/10/2019	20	Tarp motor cracked
R-550	Tarp	10/22/2019	10/22/2019		Internal Workshop Rock was stuck underneath one of the cable carriers causing it to get wedged
S-738	A - 3 Week	10/08/2019	08/10/2019	25	Internal Workshop A service done, fitted 6 x valve extensions, disconnect dolly lock
R-549	Mudflaps	10/02/2019	10/02/2019		Fitted mudflap to LHR
R-548	Tyres	09/13/2019	09/13/2019		Fitted 8 x recaps to Dolly Fitted 2 x runouts to both inside 3rd axles Internal Workshop A service done DEFECTS: monitor cracks in trailing arm
S-737	A - 3 Week	09/13/2019	13/09/2019	29	WORK DONE BY SHEPHARDS: 1st axle trailing arm adjuster bolts were loose - trailer was taken to Shephards to be replaced Internal Workshop A service done Repaired LHR dolly flap & LHR flap
S-736	A - 3 Week	08/15/2019	15/08/2019	29	DEFECTS: Monitor cracks in trailing arm Internal Workshop A service done Fitted runout on 1st axle dolly RHS inside
S-735	A - 3 Week	07/17/2019	17/07/2019	26	DEFECTS: monitor cracks in trailing arm
R-547	Mudflaps	07/10/2019	07/10/2019		Fitted new flap & tightened guard / straightened apron Straightened bin & sanded sharp edges

R-546	Mudguards	07/05/2019	07/05/2019		Sanded off sharp edges & straightened guard & straightened bent light board Internal Workshop A service done
S-734	A - 3 Week	06/21/2019	21/06/2019	21	DEFECTS: monitor cracks in trailing arm Internal Workshop Service done Tightened hoist feet
S-733	A - 3 Week	05/31/2019	31/05/2019	28	Tightened grain door - wasn't staying latched Internal Workshop A service done Regrooved 2 x LHS 1st & 2nd axle inside tyres Replaced tow eye bush Fitted missing valve caps & extensions Monitor hoist feet have slight movement
S-732	A - 3 Week	05/03/2019	03/05/2019	22	Monitor slight bearing movement 1st & 2nd axles
R-545	Tarp motor	04/29/2019	04/29/2019		Repaired damage to ABS & tarp motor wires - cut out damaged section of wire & solder wires together. Insulate wires & cable tie together Internal Workshop A service done Replaced broken grease nipples Replaced 2 x clevis pins at slack adjusters split pins Monitor cracks in trailing arms Monitor hoist feet - slight movement
S-731	A - 3 Week	04/11/2019	11/04/2019	21	Monitor slight bearing movement 1st & 2nd axles
R-544	Tyres	03/22/2019	03/22/2019		Millards Replace tyres on 2nd & 4th axle - Hankook 11R22.5 148/145 TH22 Internal Workshop A service done Fitted missing valve caps & extensions DEFECTS: cracks in trailing arm, 2nd & 4th axle needs tyres, trailing arms have movement,
S-730	A - 3 Week	03/21/2019	21/03/2019	24	monitor slight bearing movement on 1st & 2nd axles
S-729	A - 3 Week	02/25/2019	25/02/2019	31	Internal Workshop Service done Internal Workshop A service done Tyre rotation - not necessary to be done
S-728	A - 3 Week	01/25/2019	25/01/2019	35	DEFECTS: cracks in trailing arm connected to axle Internal Workshop Service done
S-727	A - 3 Week	12/21/2018	21/12/2018	17	Cracked in trailing arms Internal Workshop G&C done Replaced 3rd axle DS inside tyre with spare (tyre flat) DEFECTS: All axles cracking,
S-726	A - 3 Week	12/04/2018	04/12/2018	19	monitor 2nd DS wheel bearing - slight movement
R-543	Machinery	11/16/2018	11/16/2018		Take trailer (#511) to Shephard trailers for crack tests, Take truck to Shephards for them to check oil leak at hoist valve body - they replaced valve Internal Workshop Service done Fitted 3 x clear reflectors dolly & bin, 1 x amber reflectors to dolly, 2 x red reflectors to dolly LH reverse light not working - trace wire back & keep checking for power found plug disconnected at junction - reconnected - tested ok Cut of broken piece of mudguard on LHR dog trailer All slack adjusters undoing - replaced all slack adjusters - WARRANTY JOB
S-725	A - 3 Week	11/15/2018	15/11/2018	22	DEFECTS: All 4 x axles cracked Internal Workshop Found adjustment was way out - slack adjuster have wound off - re-adjusted brakes - needs to go to Shephards for warranty,
R-542	Brakes	11/13/2018	11/13/2018		checked axles - all 4 cracked

R-541	Williams va	11/01/2018	11/01/2018		Removed valve under fittings go to Mack & picked up new valve - left old valve at Mack for warranty - returned to workshop seal & refit fittings - fit new valve & connect air lines - build up with air - checked for leaks - all ok Internal Workshop Service done
S-724	A - 3 Week	10/24/2018	24/10/2018	28	Trailer loaded - couldn't check wheel bearings of lift bin Internal Workshop Service done
S-723	A - 3 Week	09/26/2018	26/09/2018	22	Removed inner bolt on top left inner dolly guard - bolt was wearing into bin rail All 4 x axles starting to crack where trailing arms are welded to axles Internal Workshop Service done
S-722	A - 3 Week	09/04/2018	04/09/2018	21	Cracks starting to appear where trailing arm is welded to axle Internal Workshop Service done
S-721	A - 3 Week	08/14/2018	14/08/2018	28	Bolt from dolly mudguard wearing into bin rail
S-720	A - 3 Week	07/17/2018	17/07/2018	20	Internal Workshop Done A service
S-719	A - 3 Week	06/27/2018	27/06/2018	21	Internal Workshop Service done Internal Workshop Service done Replaced 6 x valve extensions (missing) Tyre rotation on all axles Puncture repair RHS 4th axle inside
S-713	A - 3 Week	06/06/2018	06/06/2018	23	2nd Axle RHS wheel bearings tightened by Shephards Repaired rear mudflap Internal Workshop Service done Lubed tarp cables
S-712	A - 3 Week	05/14/2018	14/05/2018	40	Replaced hose to service brakes on trailer
S-711	A - 3 Week	04/04/2018	04/04/2018	22	Internal Workshop Service done
S-710	A - 3 Week	03/13/2018	13/03/2018	35	Internal Workshop Service done
S-709	A - 3 Week	02/06/2018	06/02/2018	48	Internal Workshop Service done
S-708	A - 3 Week	12/20/2017	12/20/2017		Internal Workshop Service done