

Number	Type	Date Open	Date Closed	Fault	Repairer / Notes	Cost / Invoice
R-6876	Welding Repair	01/10/2024			Internal Workshop - Fabrication Potential Cracking at Rear of Bin Chassis Rails Danny inspected the area under the body at the back of the bin chassis and found Small visible cracks that will need to be welded	\$0.00
S-7685	A - 3 Week	03/12/2026	03/13/2026		Internal Workshop - Night Shift	\$0.00
S-7608	B - 1 Year	02/11/2026	02/11/2026		Internal Workshop - Night Shift	\$0.00
S-7547	A - 3 Week	01/12/2026	01/12/2026		Internal Workshop - Night Shift	\$0.00
S-7465	A - 3 Week	11/18/2025	11/18/2025		Internal Workshop - Night Shift	\$0.00
S-7433	A - 3 Week	11/04/2025	11/04/2025		Internal Workshop - Night Shift	\$0.00
R-8946	Machinery inspection	10/21/2025	10/21/2025		Internal Workshop - Night Shift COI ATTACHED	\$0.00
R-8937	Machinery Defects	10/20/2025	10/20/2025		Internal Workshop - Night Shift BACKED BRAKE OFF ONE CLICK. INSPECTED AXLE ALL OK. CLEARED DEFECT NOTICE ATTACHED.	\$0.00
S-7384	A - 3 Week	10/16/2025	10/16/2025		Internal Workshop - Night Shift	\$0.00
S-7332	A - 3 Week	10/01/2025	09/22/2025		Internal Workshop - Night Shift	\$0.00
S-7287	A - 3 Week	09/10/2025	09/11/2025		Internal Workshop - Night Shift REPAIRED RHS INNER 1ST AXLE TYRE. REPLACED LHS TARP PULLEY.	\$0.00
S-7211	A - 3 Week	08/18/2025	08/18/2025		Internal Workshop - Night Shift REPLACED AIR LINE CLAMPS UNDER DRAWBAR. DONE A PUNTURE REPAIR ON RHS 1ST AXLE.	\$0.00
R-8301	Wheel Bearing Repack	01/30/2025	07/31/2025		Internal Workshop - Night Shift RE-PACKED ALL BEARINGS WITH NEW SEALS.	\$0.00
S-7154	A - 3 Week	07/28/2025	07/31/2025		Internal Workshop - Night Shift	\$0.00
S-7100	A - 3 Week	07/07/2025	07/07/2025		Internal Workshop - Night Shift	\$0.00
S-7033	A - 3 Week	06/16/2025	06/17/2025		Internal Workshop - Night Shift REPLACED ALL PLASTIC TARP ENDS. PUNTURE REPAIR DONE ON 4TH AXLE LHS INNER. REAR MUDFLAPS REPALCED. FRONT OFF REAR AXLE LHS MUDFLAO=P REPLACED. SERVICE COMPLETED BY IZAAK H.	\$0.00
S-6935	A - 3 Week	05/07/2025	05/07/2025		REPLACED ALL 4 AXLES WORTH OFF DRUMS AND SHOES. REPAIRED AIRLEAK AT DOLLY.	\$0.00
S-6838	A - 3 Week	02/20/2025	02/24/2025		Internal Workshop - Night Shift SERVICE COMPLETED BY IZAAK H.	\$0.00

R-8194	Body up alarm	12/05/2024	01/29/2025	Internal Workshop - Night Shift	A GRADE COME TO SITE AND	
				9571	REPAIRED DAMAGE TO WIRING.	\$0.00
S-6773	C - 2 Year	01/23/2025	01/28/2025	Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.	\$0.00
R-8246	Annual Cracks Inspection	01/03/2025	01/03/2025	Internal Workshop - Fabrication	Inspected by Damien. Front dolly crossmember cracked along with 1st to 4th axles. Repairs completed. Notes attached.	\$0.00
S-6720	A - 3 Week	12/13/2024	12/16/2024	Internal Workshop - Night Shift	SERVICE COMPLETED BY IZAAK H.	\$0.00
R-8199	Airbag	12/11/2024	12/03/2024	Internal Workshop - Night Shift	REPLACED 4TH AXLE RHS AIRBAG.	\$0.00
R-8090	Airbags	10/28/2024	11/18/2024	Internal Workshop - Night Shift	REPLACED 3RD AXLE AIRBAG.	\$0.00
S-6650	A - 3 Week	11/13/2024	11/13/2024	Internal Workshop - Night Shift	SERVICE COMPLETED BY IZAAK H.	\$0.00
S-6603	A - 3 Week	10/17/2024	10/25/2024	Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.	\$0.00
S-6556	A - 3 Week	09/27/2024	09/27/2024	Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.	\$0.00
S-6489	A - 3 Week	08/29/2024	08/29/2024	Internal Workshop - Night Shift	SERVICE COMPLETED BY IZAAK H.	\$0.00
S-6445	A - 3 Week	07/30/2024	07/30/2024	Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.	\$0.00
				Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H..	
					TIGHTEN LOOSE TARP CABLES.	
					FIT 3 VALVE EXTENSIONS	
					TIGHTEN LOOSE LOWER SHOCK BOLTS.	
					GRIND SMOOTH ACCIDENT DAMAGE RHS BIN ABOVE 3RD AXLE.	
S-6361	A - 3 Week	07/08/2024	07/08/2024		REPAIR BROKEN LHS 1ST AXLE S-CAM TUBE.	\$0.00
S-6234	A - 3 Week	05/10/2024	05/28/2024		A service completed by Tyson E.	\$0.00
S-6188	A - 3 Week	04/11/2024	04/11/2024			\$0.00
R-7401	Tarp cable	04/02/2024	04/02/2024	Internal Workshop - Night Shift	Check cable Refit cable and tension Check operation and test - OK	\$0.00
S-6146	A - 3 Week	03/21/2024	03/21/2024			\$0.00

R-7316	HYD Hose	03/22/2024	03/15/2024	Internal Workshop - Night Shift Replaced HYD line from the drawbar to the truck	\$0.00
R-7279	Tailgate hinge	03/13/2024	03/13/2024	Internal Workshop - Fabrication Prepped and repaired cracked weld. Done by Danny D.	\$0.00
S-6120	A - 3 Week	03/12/2024	03/12/2024		\$0.00
R-7250	air bag	03/07/2024	03/07/2024	Internal Workshop - Night Shift Replaced 1st axle rhs blown airbag and secure all hoses where zip ties that had to be cut.	\$0.00
S-6085	B - 1 Year	02/22/2024	02/22/2024	Dolly brakes u/s. 1st and 2nd axle - low need doing. JC done. Bridgestone Wacol Replaced all 16 trailer tyres with Bridgestone r 168.	\$0.00
T-155	Trailer Tyres	02/13/2024	02/06/2024	invoice attaced	\$0.00
R-6998	Welding Repairs	01/12/2024	01/31/2024	Internal Workshop - Fabrication Grind out weld and cradck on 3rd axel both passenger and drive sides on front of trail arm to axel. Reweld, blend and clean. No visible signs of cracking on all crossmembers., No visible signs of cracks on axels 1, 2 and 4.	\$0.00
S-6024	A - 3 Week	01/24/2024	01/24/2024	4th axle tyres worn low. Suggest 4x tyres.	\$0.00
R-6834	Valve	12/12/2023	12/12/2023	Internal Workshop - Night Shift R&R Park brake valve.	\$0.00
S-5959	A - 3 Week	12/06/2023	12/06/2023		\$0.00
R-7023	Electrical	12/04/2023	12/04/2023	Internal Workshop - Night Shift	\$0.00
R-7022	Electrical Repair	12/04/2023	12/04/2023	Internal Workshop Trace brake light wiring and found broken wire in drawbar loom. Replaced damaged section of wire and test OK. **Will need new wiring from trailer plug to drawbar	\$0.00
R-7029	Air Leak	11/20/2023	11/20/2023	Internal Workshop - Night Shift Replace leaking EBS valve on front diff. Test system for air leaks - OK. Test operation of brakes - OK.	\$0.00
S-5909	A - 3 Week	11/07/2023	11/07/2023		\$0.00
I-16	Machinery Inspection	10/05/2023	10/13/2023	Self clearing defect notice issued as attached. Cleared as attached.	\$0.00
S-5855	A - 3 Week	10/12/2023	10/12/2023		\$0.00

R-6680	Machinery Defects	10/05/2023	10/05/2023	Internal Workshop - Night Shift weld cross member cracks adjust 1st axle p/s wheel bearing work done buy jarrod	\$0.00
R-6655	Pre Machinery Inspection	10/03/2023	10/03/2023	Internal Workshop - Night Shift Adjust all brakes Tighten loose shock bolts on 3rd and 4th axle.	\$0.00
S-5793	A - 3 Week	09/08/2023	09/14/2023		\$0.00
R-6622	Guard	09/11/2023	09/11/2023	Internal Workshop - Night Shift R&R RH 3rd axle guard mount.	\$0.00
R-6546	Bin up alarm	08/15/2023	09/08/2023	Internal Workshop - Night Shift Bin up alarm not working, needs new switch. Repaired as per Jay Audit 8/9/23	\$0.00
R-6601	Tarp	08/29/2023	08/29/2023	Internal Workshop - Night Shift R&R RH tarp cable Retap tarp pulley mounting bolts and fit larger bolts Tighten LH tarp cable.	\$0.00
S-5729	A - 3 Week	08/04/2023	08/15/2023	Trailer bin up alarm not working, needs new switch - JC.	\$0.00
R-6608	Tarp cable	08/08/2023	08/08/2023	Internal Workshop Check and tighten RH tarp cable Rear pulley mount will need attention. Bolts starting to pull out of wall / top rail.	\$0.00
R-6484	Mudguard	07/27/2023	07/24/2023	Internal Workshop - Fabrication RHS front rubber mudguard bracket cracks repaired.	\$0.00
S-5689	A - 3 Week	07/24/2023	07/24/2023	Mudflap bracket broken RH rear dolly - DONE Crack in X member in front of dolly lock - DONE.	\$0.00
R-6368	Brake Mount	06/15/2023	07/05/2023	1st axle Brake mount broken - cracked on axle. 2nd and 4th axle LH s-cam mount welded cracks	\$0.00
S-5630	A - 3 Week	07/05/2023	07/05/2023		\$0.00
S-5579	A - 3 Week	06/15/2023	06/15/2023	Puncture repair 2nd axle LH inner Tighten loose shocky bolts 1st axle brake mount broken - cracked on axle - JC.	\$0.00
R-6036	Air Bag	03/22/2023	05/24/2023	Internal Workshop - Night Shift 4th axle RHS air bag leaking. Replaced 4th axle RHS - Service 5528.	\$0.00
R-5757	Bushes	01/31/2023	05/24/2023	Internal Workshop - Night Shift 2nd and 3rd axle shocky bushes will need replacing. Tyson - Replaced both shocks on 3rd axle. - Service 5528	\$0.00
S-5528	A - 3 Week	05/24/2023	05/24/2023		\$0.00

				Internal Workshop	Check out ride valves and operation Pump bags all the way up and down a few times to reset - check heights	
R-6218	Air Bags	05/17/2023	05/17/2023		Adjust to correct height 220mm - front 305mm - rear	\$0.00
S-5483	A - 3 Week	05/04/2023	05/04/2023	Internal Workshop - Night Shift	Completed by Tyson.	\$0.00
				Internal Workshop - Night Shift	Ryan - fit new mud flap to rear RHS.	\$0.00
R-6192	Mud Flap	04/19/2023	04/19/2023			\$0.00
S-5436	A - 3 Week	04/17/2023	04/17/2023	Internal Workshop - Night Shift	Completed by Tyson.	\$0.00
				Internal Workshop - Night Shift	Completed by Tyson.	\$0.00
S-5368	A - 3 Week	03/22/2023	03/22/2023		4th axle RHS air bag leaking.	\$0.00
				Internal Workshop - Night Shift	2nd axle brakes due. Garth - replaced brakes with new.	\$0.00
				Internal Workshop - Night Shift	3rd and 4th axle brake re-line due. Garth - R&R axle 3 brake shoes and drums. Remove bearings and hubs and inspect. R&R all bearings and seals. Fit hubs and tension bearings. R&R 4th axle RH inner tyre.	\$0.00
R-5758	Brake Re-line	01/31/2023	02/28/2023	Internal Workshop - Field Service	Completed by Garth.	\$0.00
S-5323	B - 1 Year	02/28/2023	02/28/2023		2nd axle brakes due (job card already live for this).	\$0.00
				Internal Workshop - Night Shift	Completed by Garth.	\$0.00
					2nd and 3rd axle shocky bushes will need replacing (R-5757).	\$0.00
					3rd and 4th axle brake re-line due (R-5758).	\$0.00
S-5240	A - 3 Week	01/31/2023	01/31/2023		LH rear bar on dolly bent.	\$0.00
				Internal Workshop - Night Shift	Garth - 5th January - removed wheels, hubs off first and second axle, clean and inspected bearings; all okay and ready to refit. 6th January - re-pack bearings and hubs, refit and torque to spec. Adjusted brakes.	\$0.00
R-5633	Wheel Bearing Repack	01/03/2023	01/05/2023			\$0.00
				Internal Workshop	C Service created from previous wheel bearing repack	\$0.00
					This is to bring the service schedule into alignment	\$0.00
S-5310	C - 2 Year	02/24/2023	01/05/2023		See recent wheel bearing repack service sheet for information	\$0.00

S-5189	A - 3 Week	12/19/2022	12/19/2022	Internal Workshop - Night Shift Completed by Izaak. Axles 3 - 4 brake re-line with bearings repack (job card 5633 already created for this).	\$0.00
S-5120	A - 3 Week	11/28/2022	28/11/2022 21	Internal Workshop - Night Shift Completed by Tyson.	\$0.00
R-5536	Cross member	11/11/2022	11/11/2022	Internal Workshop - Night Shift Machinery defect: cracks in cross member. Tyson: welded cracks in 1st cross member.	\$0.00
R-5462	Brake drums, Brake Shoe:	11/09/2022	11/09/2022	Internal Workshop - Night Shift Garth Removed wheels, brake drums and shoes on 1st and 2nd axle. Replaced brake shoes and drums with new. Refit wheels and adjusted. Completed by Garth. Tightened up guards.	\$0.00
S-5067	A - 3 Week	11/07/2022	07/11/2022 27	Brake re-line on 3rd, 4th axle next service.	\$0.00
S-4988	A - 3 Week	10/12/2022	11/10/2022 14	Izaak - axle 3 RH mud guard bracket removed, welded up, refit. Izaak - 3rd axle shocky bushes U/S. Tightened RH mud guard mount.	\$0.00
S-4951	A - 3 Week	09/28/2022	28/09/2022 19	*Service was incorrectly created as the truck, U514, hence Jay having to complete the paperwork and the service sheet saying page 5 of 5 (the trailer sheet only has 3 pages). Tyson - drawbar bent. Rear tailgate pivot RHS bent. Damage LHS tailgate etc.	\$0.00
S-4876	A - 3 Week	09/08/2022	09/09/2022 22	Straighten tarp roller LHS.	\$0.00
R-5048	Indicators	08/25/2022	08/25/2022	Tyson - Indicator on trailer. Check over wiring and test for power. R&R blown fuse. Check over truck and trailer for damage	\$0.00
R-4352	air bag	05/23/2022	08/18/2022	1st axle LH airbag leaking. Izaak - replaced. Izaak. Replaced shocky strap 1st axle LHS and 2nd axle RHS.	\$0.00
S-4799	A - 3 Week	08/18/2022	18/08/2022 30	Replaced 1st axle LHS airbag.	\$0.00

R-4916	Brake lights	08/11/2022	08/11/2022		BRAKE LIGHTS NOT WORKING. ALSO RHS REAR GUARD POLE BOLT LOOSE. Tyson: replaced blown fuses. Traced wiring down for trailer stop lights - fault inside cab. Bridge truck brake lights into trailer lights. Repaired broken wiring at toe eye. Fix loose steer mud guard and replace bolts. Repair damage to checker plate at ring feeder. Tighten loos trailer guard.	\$0.00
R-4729	Brake Reline	07/20/2022	07/20/2022		1st axle dolly brakes reline. Izaak - replaced brakes, shoes and drums. Garth - replaced 3rd and 4th axle shockie bushes. 1st axle reline due this week. Replaced tarp cables with new. Fit new mud flaps to RHS rear.	\$0.00
S-4718	A - 3 Week	07/19/2022	19/07/2022	33	Straighten RHS front rear guard.	\$0.00
R-4640	Air Lines	06/28/2022	06/28/2022		Garth - Replace all air lines on draw bar due to accident damage. Repair broken wiring. Re-rap hoses and electrical components.	\$0.00
S-4643	A - 3 Week	06/15/2022	16/06/2022	24	Tyson: R&R rear mud flap. Puncture repair 4th axle LH inner. Garth: weld s'cam tube on 2nd axle LHS. Fit two clear reflectors to front. Replaced brake shoes 2nd axle. 1st axle brakes getting low - next service.	\$0.00
S-4555	A - 3 Week	05/23/2022	23/05/2022	26	1st axle LH airbag leaking.	\$0.00
R-3912	Tyre	02/15/2022	04/27/2022	4220	This has been repaired.	\$0.00
S-4476	A - 3 Week	04/21/2022	27/04/2022	29	2nd axle LH brakes low - reminder for next A service. Brakes wearing uneven.	\$0.00
S-4399	A - 3 Week	03/29/2022	28/03/2022	34	Crack in 1st cross member.	\$0.00
S-4300	A - 3 Week	02/21/2022	22/02/2022	35		\$0.00
R-3616	Wheel Chocks	11/23/2021	01/18/2022	3950	Internal Workshop Replaced.	\$0.00
R-3589	Tailgate	11/16/2021	01/18/2022	3917, 3936,	Internal Workshop Repaired.	\$0.00
S-4168	A - 3 Week	01/10/2022	18/01/2022	43		\$0.00
R-3748	Tarp cable	01/17/2022	01/17/2022	4077	Repaired.	\$0.00
S-4118	A - 3 Week	12/06/2021	06/12/2021	25		\$0.00

S-4046	A - 3 Week	11/10/2021	11/11/2021	24	Internal Workshop Jack. Fitted tow eye bush, tow eye worn underneath. Monitor dolly brakes, getting low. Draw bar bent.
S-3979	A - 3 Week	10/19/2021	18/10/2021	21	Internal Workshop Jack. Internal Workshop Done by Jack. Trailing arms showing signs of movement. 3rd and 4th axle shocky rubbers have movement but look to be replaced already. Straightened and tightened 3rd axle RHS guard. Tensioned both tarp cables.
S-3883	A - 3 Week	09/28/2021	28/09/2021	27	Replaced tow eye bush. Internal Workshop Work done by Jarrod. Repaired broken welds at s-cam tubes.
S-3810	A - 3 Week	09/01/2021	01/09/2021	54	Internal Workshop Service done by Jarrod
S-3709	A - 3 Week	07/09/2021	09/07/2021	22	Internal Workshop Repaired broken wire LHS indicator on dolly Fit 2 x red reflectors Tightened mudguards Replaced all shocky bushes Job done by Garth
R-2970	Electrical, Reflectors	06/23/2021	06/23/2021		
R-2693	Shock bushes	04/13/2021	06/17/2021		Internal Workshop Replaced shock bushes - job done by Garth
S-3623	A - 3 Week	06/17/2021	17/06/2021	49	Internal Workshop Service done by Garth
R-2972	Mudflap	06/15/2021	06/15/2021		Internal Workshop Replaced RHR mudflap - job done by Jarrod
R-2817	Tyres	05/17/2021	05/24/2021		Carroll's Tyres Fit 8 x new tyres to Dolly BRT11225LR168 Internal Workshop Repaired badly damaged wiring at the tow hitch - job done by Garth
R-2780	Electrical	04/29/2021	04/29/2021		Internal Workshop Service done by Garth
S-3501	A - 3 Week	04/29/2021	29/04/2021	21	Internal Workshop Service done by Garth Tightened RHR mudguard & pole Tightened mudflaps Repaired clearance light RHR Front crossmember cracking inside bottom welds All shocky bushes u/s
S-3433	A - 3 Week	04/08/2021	08/04/2021	29	RHS 2nd axle shock strap u/s

R-2510	Brake Re-line	02/22/2021	04/07/2021		Internal Workshop Job done by Jarrod, Re-lined 3rd & 4th axle brakes, Welded 4th axle s-cam tube back in, Tightened loose guard pole Replaced LHR mudflap, Rotated tyres
R-2625	Wheel alignment	03/19/2021	03/19/2021		D & L Laser Alignment Robbie took truck & trailer for wheel alignment
S-3365	A - 3 Week	03/10/2021	10/03/2021	20	Internal Workshop Service done by Jarrod 3rd & 4th axle brakes still need to be relined
S-3329	A - 3 Week	02/18/2021	18/02/2021	22	Internal Workshop Service done by Laine Defects: 3rd, 4th axle reline due next week 1st, 2nd axle shock bushes worn
S-3258	A - 3 Week	01/27/2021	27/01/2021	21	Internal Workshop A service done by Laine Carry out reline on 1st & 2nd axle
S-3211	A - 3 Week	01/04/2021	06/01/2021	55	Internal Workshop Service done Service done
S-1566	A - 3 Week	11/12/2020	12/11/2020	23	Tarp cable was broken
R-1202	Mudflaps	11/09/2020	11/09/2020		Internal Workshop Replaced missing mudflap
S-653	A - 3 Week	10/20/2020	20/10/2020	19	Internal Workshop Service done Defect: Monitor all brakes - getting low Internal Workshop Service done Replaced RHF marker light
S-557	A - 3 Week	10/01/2020	01/10/2020	27	Replaced LHR mudflap Internal Workshop Replaced switch - light still on - found 2 x broken pins in truck socket - replaced socket - isolated wiring at both junction boxes - traced problem to wiring on drawbar - light is off at the moment but may come on again - further repairs might be required
R-317	Switch	09/08/2020	09/08/2020		Service done DEFECTS: LHR mudflap missing RHF marker light need replacing Body up light from trailer on all the time - body up buzzer on all the time - suggest replacing body up switch on trailer
S-495	A - 3 Week	08/31/2020	04/09/2020	25	
S-427	A - 3 Week	08/10/2020	10/08/2020	27	Service done
S-345	A - 3 Week	07/14/2020	07/14/2020		Service done

					Internal Workshop A service done
					Replaced LHF reflector
					Replaced LH tarp cable
					Replaced RHR mudflap
S-284	A - 3 Week	06/23/2020	06/24/2020		Straightened bent tail light apron
					Service done
S-225	A - 3 Week	06/04/2020	06/04/2020		Fitted wheel chocks
R-60	Wheel Chocks	05/25/2020	05/25/2020		Wheel chocks fitted
					A service done
S-159	A - 3 Week	05/18/2020	05/19/2020		LH inner 3rd tyre u/s - replaced with runout
S-852	A - 3 Week	05/04/2020	04/05/2020	13	Internal Workshop A service done
					Internal Workshop A service done
					Tightened loose mudflap on rear
					RHR apron twisted
S-75	A - 3 Week	04/21/2020	04/21/2020		DEFECT: apron on dolly bent
					Internal Workshop A service done
					Tyre rotation on dolly done
					Repaired punctures 1st axle RH inner & 3rd axle RH inner
S-880	A - 3 Week	03/11/2020	11/03/2020	37	DEFECTS: apron on dolly bent
					Internal Workshop A service done
					Straightened 3rd axle RH guard bracket
					DEFECTS: bad tyre scalloping on 3rd axle RHS
S-879	A - 3 Week	02/03/2020	03/02/2020	25	Apron on dolly bent
R-653	Anderson plug	01/30/2020	01/30/2020		Internal Workshop Replaced male light plug
R-652	Mudflaps	01/23/2020	01/23/2020		Replaced LHS rear apron mudflap
S-878	A - 3 Week	01/09/2020	09/01/2020	37	Internal Workshop A service done
					Internal Workshop A service done
					Tightened 3rd axle RH mudguard bracket - was loose
					DEFECTS: RHF amber clearance light out - no stock
S-877	A - 3 Week	12/03/2019	03/12/2019	21	3rd axle LH inner tyre scalloping bad
					Internal Workshop A service done
					Replaced all slack adjusters with Bendix type
S-876	A - 3 Week	11/12/2019	12/11/2019	21	DEFECTS: tyre scalloping on 1st axle & 3rd axle RHS

S-875	A - 3 Week	10/22/2019	22/10/2019	26	Internal Workshop A service done Secured rear mudflaps Tightened 2nd axle upper shock bushes as they were loose DEFECT: Bad tyre scalloping on 1st axle & 3rd axle RHS
S-874	A - 3 Week	09/26/2019	26/09/2019	30	Internal Workshop A service done Inspected noise on dolly and could not fault Replaced missing wheel nut indicators 3rd Axle RHS DEFECTS: Bad tyre scalloping on 1st axle & 3rd axle RHS
S-873	A - 3 Week	08/27/2019	27/08/2019	22	Internal Workshop A service done Fitted runouts to LHS outside 3rd axle Fitted runouts to RHS inside 3rd axle DEFECTS: multiple tyres have irregular wear - might have wheel alignment issue
R-651	Mudflaps	08/15/2019	08/15/2019		Internal Workshop Straightened apron & fitted new flap Tightened guard
S-872	A - 3 Week	08/05/2019	05/08/2019	21	Internal Workshop A service done Fitted multiple valve extensions DEFECTS: possible wheel alignment issue - irregular tyre wear on multiple tyres
R-650	Slack adjusters, Tarp mot	07/16/2019	07/16/2019		Internal Workshop Fitted new slack adjusters - supplied by Shephards both dolly axles (1st & 2nd axles) Fitted new tarp motor Internal Workshop A service done Tightened up and replaced multiple booster hose clamps Shephards repaired ride height on dolly DEFECTS: slack adjusters on dolly to be replaced - waiting for stock from Shephards Monitor tyres 3rd axle DS Multiple tyres have irregular wear - monitor Tarp motor starting to crack
S-871	A - 3 Week	07/15/2019	15/07/2019	21	

S-870	A - 3 Week	06/24/2019	24/06/2019	18	Internal Workshop A service done Straightened out RHR guard DEFECTS: monitor tyres 3rd axle DS Multiple booster hose clamps loose & u/s Height control tab for rod welder on axle wrong spot (Shephards) Dolly ride height to high (Shephards) Dolly has old slack adjusters Internal Workshop A service done Straightened 3rd axle guards both sides Tensioned 3rd axle wheel bearing LHS DEFECTS: all axles cracked Monitor tyres 3rd axle DS Need shocky strap for 1st axle - THIS WILL BE REPLACED WHEN AXLES GET CHANGED
S-869	A - 3 Week	06/06/2019	06/06/2019	34	Trailing arms have movement
R-649	Tyres	05/17/2019	05/17/2019		Internal Workshop Replaced 1 x runout on 2nd axle RHS inside
S-868	A - 3 Week	05/03/2019	03/05/2019	24	Internal Workshop A service done Tightened hoist feet DEFECTS: all axles cracked where spring hanger is welded to axles Monitor 3rd axle DS tyres Internal Workshop Inspect might be wires - checked over plug & whole lead could not find issue - cleaned contacts on plug both sides, ABS light was not on whilst in workshop
R-648	ABS Light	04/12/2019	04/12/2019		
S-867	A - 3 Week	04/09/2019	09/04/2019	21	Internal Workshop G&C (A service) done DEFECTS: axles cracked where spring hanger is welded to axles Trailing arms cracking & showing signs of movement Monitor 3rd axle DS tyres Monitor slight bearing movement 1st & 2nd axle DS & 3rd axle both sides Hoist feet have fair bit of movement Tow eye tongue bent in drawbar

					Internal Workshop A service done Fitted all new valve caps & extensions to missing axles Replaced tow eye bush Fitted new clearance marker front pin DS Tightened loose air tank DEFECTS: monitor trailing arm rubbers (cracking) & showing signs of movement Monitor tyres 3rd axle PS Monitor slight bearing movement 1st&2nd axle DS and 3rd axle both sides Hoist feet have fair bit of movement Tow eye tongue bent in drawbar
S-866	A - 3 Week	03/19/2019	19/03/2019	29	
R-647	Tyres	03/14/2019	03/14/2019		Replaced with run-out Internal Workshop A service done Removed old rego label Straightened LH 3rd guard bracket
S-865	A - 3 Week	02/18/2019	18/02/2019	24	DEFECTS: axles cracked where spring hanger is welded Internal Workshop A Service service Requested tyre rotation but was not done
S-864	A - 3 Week	01/25/2019	25/01/2019	39	DEFECTS: axles cracked where spring hanger is welded
R-646	Tyres	01/08/2019	01/08/2019		Millards 4 x new Hankook TH22 trailer tyres fitted to rear axle & one tyre was rotated forward to 3rd axle
S-863	A - 3 Week	12/17/2018	17/12/2018	17	Internal Workshop Carry out G&C DEFECTS: all axles where spring hanger is welded to axle cracked
R-645	Air line	12/04/2018	12/04/2018		Internal Workshop Replaced lines with new longer hose
S-862	A - 3 Week	11/30/2018	30/11/2018	30	Internal Workshop Service done DEFECTS: axles cracked where spring hanger is welded to axles Both rear axle tyres very low - need replacing asap
R-644	Tyre repairs	10/31/2018	10/31/2018		Internal Workshop Removed & repaired second axle LHS outer flat tyre

S-861	A - 3 Week	10/31/2018	31/10/2018	15	Internal Workshop A service done DEFECTS: Axles cracking around welds where tracking arms connect RH 2nd inner tyre wearing low LHF inner tyre getting low
S-860	A - 3 Week	10/16/2018	16/10/2018	19	Internal Workshop Carry out A service Found bolts for A-Frame on dolly loose - go through & tighten both bolts DEFECTS: all axles cracked where spring hanger is welded to axles
R-643	Tarp cable	10/15/2018	10/15/2018		Internal Workshop Replaced LH tarp cable
S-859	A - 3 Week	09/27/2018	27/09/2018	21	Internal Workshop A service done All 4 x axles cracking where trailing arms weld onto axles
S-858	A - 3 Week	09/06/2018	06/09/2018	28	Internal Workshop A service done
S-857	A - 3 Week	08/09/2018	09/08/2018	17	Internal Workshop A service done
S-856	A - 3 Week	07/23/2018	23/07/2018	19	Internal Workshop A service done Tightened all shockies
S-855	A - 3 Week	07/04/2018	04/07/2018	28	Internal Workshop A service done
S-854	A - 3 Week	06/06/2018	06/06/2018	33	Internal Workshop A service done Replaced 1 x white reflector
S-853	A - 3 Week	05/04/2018	04/05/2018	22	Internal Workshop A service done
S-851	A - 3 Week	04/12/2018	12/04/2018	30	Internal Workshop A service done
S-850	A - 3 Week	03/13/2018	13/03/2018	64	Internal Workshop A service done
S-849	A - 3 Week	01/08/2018	01/08/2018		Internal Workshop A service done