

| Number | Type | Date Open | Date Closed | Fault | Repairer / Notes | Cost / Invoice |
|--------|----------------------|------------|-------------|-------|---|----------------|
| S-7705 | A - 3 Week | 03/24/2026 | 03/23/2026 | | Internal Workshop - Night Shift REPLACED BOTH RIDE HEIGHT VALVES. REPLACED AIR BAG ON 2ND AXLE LHS. | \$0.00 |
| R-9125 | air bag | 03/13/2026 | 02/18/2026 | | Internal Workshop - Night Shift REPLACED 2ND AXLE LHS AIRBAG. | \$0.00 |
| S-7620 | B - 1 Year | 02/18/2026 | 02/17/2026 | | Internal Workshop - Night Shift | \$0.00 |
| S-7562 | A - 3 Week | 01/19/2026 | 01/19/2026 | | Internal Workshop - Night Shift | \$0.00 |
| S-7492 | A - 3 Week | 12/01/2025 | 12/10/2025 | | Internal Workshop - Night Shift | \$0.00 |
| S-7445 | A - 3 Week | 11/07/2025 | 11/10/2025 | | Internal Workshop - Night Shift REPLACED LHS REAR GUARD AND BOTH REAR FLAPS. REPAIRED PUNTURE 1ST AXLE RHS OUTER. | \$0.00 |
| R-8961 | Machinery inspection | 10/28/2025 | 10/28/2025 | | Internal Workshop - Night Shift COI ATTACHED. | \$0.00 |
| R-8960 | Machinery Defects | 10/28/2025 | 10/28/2025 | | Bridgestone Wacol AT MACHINERY INSPECTION THEY FOUND 4TH AXLE P/S OUTER TYRE WORN. BRIDGESTONE WACOL REPLACED ALL 4 TYRES ON 4TH AXLE. DEFECT ALL CLEARED. COI ATTACHED. Internal Workshop - Night Shift REPLACED BOTH SHOCKS 3RD AXLE REPLACED 2ND RHS LEAKING AIR BAG. | \$0.00 |
| R-8643 | Shock bushes | 06/20/2025 | 10/20/2025 | | Internal Workshop - Night Shift | \$0.00 |
| S-7392 | A - 3 Week | 10/20/2025 | 10/20/2025 | | Internal Workshop - Night Shift | \$0.00 |
| S-7304 | A - 3 Week | 09/18/2025 | 09/18/2025 | | Internal Workshop - Night Shift | \$0.00 |
| S-7230 | A - 3 Week | 08/22/2025 | 08/26/2025 | | Internal Workshop - Night Shift | \$0.00 |
| S-7185 | A - 3 Week | 08/07/2025 | 08/07/2025 | | Internal Workshop - Night Shift FITTED NEW GUARD AND BRACKET TO 3RD AXLE LHS. | \$0.00 |
| S-7110 | A - 3 Week | 07/10/2025 | 07/14/2025 | | Internal Workshop - Night Shift REPLACED MULTIPLE GREASE NIPPLES THAT WERNT TAKING GREASE. Internal Workshop - Night Shift PUNTURE REPAIR | \$0.00 |
| S-7020 | A - 3 Week | 06/09/2025 | 06/18/2025 | | 4TH AXLE RHS INNER. | \$0.00 |
| R-8511 | ABS valve | 04/30/2025 | 05/21/2025 | | REPLACED WHOLE REAR EBS VALVE. | \$0.00 |

| | | | | | | |
|--------|--------------------------|------------|------------|---------------------------------|--|--------|
| | | | | Internal Workshop - Night Shift | SAY AUTO REPAIRED | |
| R-8381 | ABS Light | 02/25/2025 | 05/21/2025 | 9908 | WIRING AT DRAW BAR. | \$0.00 |
| S-6954 | A - 3 Week | 05/21/2025 | 05/21/2025 | | Internal Workshop - Night Shift | \$0.00 |
| S-6913 | A - 3 Week | 04/14/2025 | 04/15/2025 | | SERVICE COMPLETED BY TYSON E. | \$0.00 |
| S-6877 | A - 3 Week | 03/25/2025 | 03/25/2025 | | Internal Workshop - Night Shift SERVICE COMPLETED BY TYSON E. | \$0.00 |
| R-8211 | Brake Reline | 12/11/2024 | 03/23/2025 | | Internal Workshop - Night Shift REPLACED 1ST AND 2ND AXLE BRAKE SHOES AND DRUMS. | \$0.00 |
| S-6771 | C - 2 Year | 01/23/2025 | 02/04/2025 | | Internal Workshop - Night Shift SERVICE COMPLETED BY IZAAK H. | \$0.00 |
| R-8245 | Annual Cracks Inspection | 01/02/2025 | 01/02/2025 | | Internal Workshop - Fabrication Inspected by Damien. Front dolly crossmember cracked along with 2nd and 3rd axles. Repairs completed. Notes attached. | \$0.00 |
| S-6706 | A - 3 Week | 12/10/2024 | 12/10/2024 | | Internal Workshop - Night Shift SERVICE COMPLETED BY JARROD H. | \$0.00 |
| I-53 | Machinery Inspection | 11/22/2024 | 11/26/2024 | | Machinery inspection 22/11/24 Self Clearing Defect Notice #D103339434 issued for: 1. Tow Tongue worn thing 2. Third axle service brakes inefficient. Repaired on R#8134 by Shephards. Defect cleared on 26/11/24. | \$0.00 |
| R-8134 | Machinery Defects | 11/18/2024 | 11/22/2024 | | Internal Workshop - Night Shift SHEPARDS REPLACED WHOLE TOW TOUNGE. ADJUSTED 3RD AXLE BRAKES IN SPEC. | \$0.00 |
| S-6655 | A - 3 Week | 11/14/2024 | 11/19/2024 | | Internal Workshop - Night Shift SERVICE COMPLETED BY IZAAK H. | \$0.00 |
| R-8008 | Wheel bearings | 10/08/2024 | 10/28/2024 | | Internal Workshop - Night Shift REPLACED 3RD AND 4TH AXLE BRAKE DRUMS AND SHOES. REPALCED 3RD AXLE RHS WHEEL SEAL. | \$0.00 |
| S-6618 | A - 3 Week | 10/28/2024 | 10/28/2024 | | Internal Workshop - Night Shift SERVICE COMPLETED BY TYSON E. | \$0.00 |

| | | | | | |
|--------|---------------|------------|------------|---|--------|
| S-6572 | A - 3 Week | 10/03/2024 | 10/03/2024 | Internal Workshop - Night Shift SERVICE COMPLETED BY JARROD H. | \$0.00 |
| S-6509 | A - 3 Week | 09/05/2024 | 09/05/2024 | Internal Workshop - Night Shift SERVICE COMPLETED BY JARROD H. REPLACED 4TH AXLE RHS AIRBAG. | \$0.00 |
| R-7824 | Tarp cable | 09/02/2024 | 09/02/2024 | Internal Workshop - Night Shift REPLACED BOTH TARP CABLES WITH CLAMPS. | \$0.00 |
| R-7778 | Brake Reline | 08/19/2024 | 08/15/2024 | Internal Workshop - Night Shift 3RD AXLE RHS HUB SEAL LEAKING. REPLACE BRAKES AT THE SAME TIME. | \$0.00 |
| S-6465 | A - 3 Week | 08/13/2024 | 08/15/2024 | Internal Workshop - Night Shift SERVICE COMPLETED BY TYSON E. | \$0.00 |
| S-6352 | A - 3 Week | 07/02/2024 | 07/02/2024 | SERVICE COMPLETED BY JARROD H. | \$0.00 |
| S-6317 | A - 3 Week | 06/19/2024 | 06/19/2024 | Service completed by Jarrod H. 2nd axle RHS s-cam tube cracked/ welded crack up. | \$0.00 |
| S-6213 | A - 3 Week | 04/24/2024 | 05/09/2024 | | \$0.00 |
| S-6174 | A - 3 Week | 04/04/2024 | 04/04/2024 | Replace both 3rd axle airbags | \$0.00 |
| T-165 | Trailer Tyres | 03/22/2024 | 03/20/2024 | Internal Workshop - Night Shift Moved the 2nd axle to the 1st axle and fitted 4 x Brand New Tyres to the second axle. Checked and tensioned all wheel nuts | \$0.00 |
| R-7293 | Mud Flap | 03/11/2024 | 03/14/2024 | Internal Workshop - Night Shift Replaced two rear 7849 mud flaps | \$0.00 |
| S-6128 | B - 1 Year | 03/14/2024 | 03/14/2024 | Internal Workshop - Night Shift | \$0.00 |
| R-7271 | Tarp motor | 02/29/2024 | 02/29/2024 | Internal Workshop Remove old bent tarp drive bar Cut new drive bar to length Fit new bar to trailer. | \$0.00 |
| R-7126 | Tarp cable | 02/02/2024 | 02/16/2024 | 7577 Internal Workshop - Night Shift Replaced tarp cable. | \$0.00 |
| S-6060 | A - 3 Week | 02/16/2024 | 02/16/2024 | | \$0.00 |
| R-7127 | Mudflaps | 02/02/2024 | 02/06/2024 | 7578 Internal Workshop - Night Shift Replaced mudflap. | \$0.00 |

| | | | | | |
|--------|----------------------|------------|------------|---|--------|
| R-6997 | Welding Repairs | 01/12/2024 | 01/31/2024 | Internal Workshop - Fabrication Grind out weld and crack on trial arm to axel on 3rd axel - front passenger and drivers side on trailer. Reweld, blend and clean. No visible signs of racking on all crossmembers, No visible signs of cracking on axels 1, 2 and 4. | \$0.00 |
| R-6576 | Axles | 08/29/2023 | 01/17/2024 | Internal Workshop - Night Shift R&R leaking hub seal. Tensioned wheel bearings. | \$0.00 |
| R-5889 | Trailing arm bushes | 02/22/2023 | 01/17/2024 | Internal Workshop - Night Shift Checked bushes with bar. Bushes all serviceable. | \$0.00 |
| S-6011 | A - 3 Week | 01/17/2024 | 01/17/2024 | R&R first axle RH airbag - blew up on hoist Repair punctured tyre 1st axle LH inner | \$0.00 |
| R-6875 | Welding Repair | 01/10/2024 | 01/11/2024 | Internal Workshop - Fabrication Crack in bin rails to tailgate welds Grind out weld and cracks Reweld, blend and clean. | \$0.00 |
| S-5941 | A - 3 Week | 11/27/2023 | 11/27/2023 | Driver to check tyres before work every morning. 2 x tyres unroadworthy for long period of time. R&R 3rd axle inner and outer tyres. Complete full reline on 1st and 2nd axle. | \$0.00 |
| R-7035 | Tarp | 11/21/2023 | 11/21/2023 | Internal Workshop - Night Shift R&R bolt tarp cables Replace 3 blades Ziptie rip in RHS tarp. LH & RH tarp cables replaced Tighten loose hoist feet 2nd and 3rd axle s-cam tubes loose -welded Tighten 3rd axle shock bushes 1st axle tyres worn low 3rd axle RH inner tyre worn low | \$0.00 |
| S-5907 | A - 3 Week | 11/07/2023 | 11/07/2023 | | \$0.00 |
| I-18 | Machinery Inspection | 10/13/2023 | 10/13/2023 | | \$0.00 |
| R-6595 | Shockie bushes | 09/13/2023 | 10/09/2023 | 3rd and 4th axle shocky bushes worn - lowers. Bushes are OK. tightened shock bolts. LH tarp cable replaced | \$0.00 |
| S-5844 | A - 3 Week | 10/09/2023 | 10/09/2023 | Tightened loose shock bolts. | \$0.00 |
| R-6646 | Puncture | 10/03/2023 | 10/03/2023 | Internal Workshop - Night Shift R&R tyre with runout (tyre was off bead). | \$0.00 |

| | | | | | |
|--------|----------------|------------|------------|--|--------|
| S-5803 | A - 3 Week | 09/08/2023 | 09/21/2023 | First axle brakes - replaced 2nd axle LH hub seal Cracks in cross member under dolly welded Tighten loose shock bolts 1st, 2nd and 4th axle. | \$0.00 |
| S-5799 | A - 3 Week | 09/08/2023 | 09/12/2023 | 3rd and 4th axle shocky bushes worn - lowers - JC | \$0.00 |
| S-5763 | A - 3 Week | 08/25/2023 | 08/29/2023 | Rh 4th axle seal starting to leak - JC 1st, 2nd and 3rd axle RH s-cam cracked - welded. | \$0.00 |
| R-6615 | Light bar | 07/31/2023 | 07/31/2023 | Internal Workshop Straight rear light bar LHS Tighten up mud guard bracket LHR | \$0.00 |
| R-6114 | Shockie bushes | 04/03/2023 | 07/25/2023 | Internal Workshop - Night Shift 3rd axle shockie bushes need replacing next service. These have been replaced. | \$0.00 |
| S-5691 | A - 3 Week | 07/25/2023 | 07/25/2023 | | \$0.00 |
| S-5625 | A - 3 Week | 06/29/2023 | 06/29/2023 | 2 tyres run flat - repaired 4th axle RH outer tyre R&R 3rd axle RH inner due to being run flat for a period of time. | \$0.00 |
| R-3669 | Drawbar | 12/06/2021 | 06/29/2023 | 3974, 3991 No action required. | \$0.00 |
| R-6133 | Body up alarm | 04/11/2023 | 06/08/2023 | Internal Workshop - Night Shift Body up alarm not working on trailer. Checked in S-5555 by Tyson - 6290 Working. | \$0.00 |
| S-5555 | A - 3 Week | 06/08/2023 | 06/08/2023 | R&R perished tyre 3rd axle RH inner R&R RH tarp cable - Tyson | \$0.00 |
| R-6315 | Tailgate | 06/06/2023 | 06/06/2023 | Internal Workshop - Fabrication Weld up broken top hinge on tailgate Machine up spacer for to hinge Replace bushes in top and bottom hinge Heat top hinge to move tailgate across 5mm Remove rubber around bottom corner of tailgate and knock out corner where damaged Bent back mudguard support & mudflap support back into correct position. Danny & Craig. | \$0.00 |

| | | | | | |
|--------|----------------------|------------|------------|---|--------|
| S-5507 | A - 3 Week | 05/17/2023 | 05/17/2023 | Internal Workshop - Night Shift | \$0.00 |
| R-5884 | Air Leak | 02/22/2023 | 04/26/2023 | Internal Workshop - Night Shift Air leak rear trailer 6074 Tyson - no leak found. | \$0.00 |
| S-5466 | A - 3 Week | 04/26/2023 | 04/26/2023 | Internal Workshop - Night Shift Completed by Tyson. Replaced switch for body up alarm. Stripped wiring under dolly; found break in wires. Also repaired brake light wiring. Found loose terminals in junction box on dolly. Switch still not working; will need more time. | \$0.00 |
| R-6126 | Tailgate, Tarp cable | 04/06/2023 | 04/06/2023 | Internal Workshop - Night Shift Garth - replaced LH tarp cable with new. Adjusted tension on both sides; tested okay. Found tail gate LH top pivot hinge cracking (pics sent to Jay). | \$0.00 |
| S-5400 | A - 3 Week | 04/03/2023 | 04/03/2023 | Internal Workshop - Night Shift Completed by Garth. Weld LH 2nd axle s'cam tube. 3rd axle shockie bushes need replacing next service (R-6114). | \$0.00 |
| S-5352 | A - 3 Week | 03/17/2023 | 03/17/2023 | Internal Workshop - Night Shift Completed by Garth. | \$0.00 |
| S-5301 | A - 3 Week | 02/22/2023 | 02/22/2023 | Internal Workshop - Night Shift Completed by Garth. All trailing arm bushes U/S (R-5889). LH & RH rear axle s'cam tubes broken welds. Clean up and re-weld; tested okay. RH 2nd axle s'cam tube broken. Weld, clean up and re-weld; tested okay. LH 1st axle air bag U/S. Replaced with new; tested okay. | \$0.00 |

| | | | | | | |
|--------|----------------------|------------|------------|------|--|--------|
| R-5847 | Mudflap | 02/07/2023 | 02/09/2023 | 5997 | Internal Workshop - Night Shift Other. Inspect Mud Flaps and Guards are all attached. Missing mudflat RH Rear Ryan - removed and replaced RH rear mud flap. | \$0.00 |
| R-5935 | Brakes | 02/07/2023 | 02/07/2023 | | Internal Workshop - Night Shift Tyson - R&R 4th axle brake shoes and drums. R&R perished tyre 4th axle LHS. Adjusted brakes. Tensioned wheel nuts. | \$0.00 |
| I-3 | Machinery Inspection | 11/22/2021 | 02/02/2023 | | | \$0.00 |
| S-5226 | B - 1 Year | 01/24/2023 | 01/24/2023 | | Internal Workshop - Night Shift Completed by Tyson. R&R faulty tyre 3rd axle RHS inside. | \$0.00 |
| R-5639 | Wheel Bearing Repack | 01/03/2023 | 01/05/2023 | | Internal Workshop - Night Shift 2nd, 3rd and 4th axle bearings need to be removed, cleaned, and inspected for wear / damage. Replace damaged wheel bearings as required. Repack all bearings with fresh grease and replace dust deals with new items Refit all hubs and wheels to spec. Note ** Replace worn brake shoes and drums while everything is apart if required ** Garth - removed wheels and hubs off 2nd, 3rd and 4th axle. Clean and inspect bearings, re-pack with grease. Re-fit hubs and torque to spec. Adjusted brakes. | \$0.00 |
| S-5312 | C - 2 Year | 02/24/2023 | 01/05/2023 | | Internal Workshop C Service created from previous wheel bearing repack This is to bring the service schedule into alignment See recent wheel bearing repack service sheet for information | \$0.00 |
| S-5145 | A - 3 Week | 12/06/2022 | 08/12/2022 | 21 | Internal Workshop - Night Shift Completed by Izaak. | \$0.00 |
| R-5480 | Indicators | 11/28/2022 | 11/28/2022 | | Internal Workshop - Night Shift INDICATOR NOT WORKING Izaak - replaced/fixed all wires. | \$0.00 |

| | | | | | | |
|--------|--------------------------|------------|------------|----|--|--------|
| S-5096 | A - 3 Week | 11/17/2022 | 17/11/2022 | 28 | Internal Workshop - Night Shift Completed by Tyson. | \$0.00 |
| R-5535 | Air Leak | 11/11/2022 | 11/11/2022 | | Internal Workshop - Night Shift Machinery defect: air leak. Tyson: replaced service brake line to LHS maxi due to having hole in it. | \$0.00 |
| R-5540 | Pre-machinery inspection | 11/04/2022 | 11/04/2022 | | Internal Workshop - Night Shift Pre-machinery inspection. Izaak - replaced 3rd and 4th axle shocky bushes. Brake adjustment check over. 3rd axle repair 3 x wheels with punctures. | \$0.00 |
| S-5012 | A - 3 Week | 10/21/2022 | 20/10/2022 | 24 | Internal Workshop - Night Shift Completed by Garth. 2nd axle brake relined - replaced drums and shoes. Replaced tarp cable LHS. | \$0.00 |
| R-5332 | Mud Flap | 10/15/2022 | 10/18/2022 | | Not Working. Inspect Mud Flaps and Guards are all attached. LHR mud flap missing. Garry - replaced rear 5477 left mud flap. | \$0.00 |
| S-4947 | A - 3 Week | 09/27/2022 | 27/09/2022 | 21 | Garth. | \$0.00 |
| S-4868 | A - 3 Week | 09/06/2022 | 06/09/2022 | 21 | Tyson. | \$0.00 |
| R-5080 | Drawbar | 08/31/2022 | 09/01/2022 | | Not Working. Other: Major Concerns (Take pics). Trailer drawbar jack seized Leg needs replacing. Izaak - 5273 replaced with new. | \$0.00 |
| S-4792 | A - 3 Week | 08/16/2022 | 16/08/2022 | 21 | Puncture repair 3rd axle RHS inner (T43). | \$0.00 |
| T-43 | Trailer Tyre | 08/18/2022 | 08/16/2022 | | Puncture repair 3rd axle RHS inner. | \$0.00 |
| R-4141 | Air Leak | 04/06/2022 | 07/26/2022 | | EBS valve is still okay. Will monitor. Jay - this is coming from the EBS valve. Garth - found loose hose clamp; 4423 tightened. | \$0.00 |
| S-4725 | A - 3 Week | 07/19/2022 | 26/07/2022 | 36 | Garth - repair RHS tarp cable. | \$0.00 |

| | | | | | | |
|--------|---------------|------------|------------|------------|--|--------|
| R-4845 | Axles | 07/06/2022 | 07/06/2022 | | Garth - Remove axle hubs, brake boosters, slack adjusters, scams, scam tubes, EBS sensors. Clean hubs and bearings and repack with grease. Fit scam tubes, scams, slack adjusters, brake boosters, and hubs back on. Fit axle back under trailer, bolt on air bags and shockies, fit EBS sensors, new brake shoes and new brake drums, fit wheels, and adjust brakes. Fit wheel indicators back on. | \$0.00 |
| R-4560 | Brake Re-line | 06/28/2022 | 07/06/2022 | | RE-LINE ALL 4 AXLES BRAKES Garth - replaced all brakes. Internal Workshop Tow eye bush needs replacing when re-kit ring feeder. Garth - replaced tow eye bush with new. | \$0.00 |
| R-3727 | Tow eye bush | 01/13/2022 | 06/20/2022 | | | \$0.00 |
| S-4649 | A - 3 Week | 06/15/2022 | 20/06/2022 | 25 | Garth - replaced 1st and 2nd axle shockie bushes. Replaced 2nd axle RHS shockie with new. Brake reline due (Jay has created job card R4560 for this). Replaced 3rd axle front mud flaps. Straighten LH rear mud flaps. Fit missing reflectors with new. Tighten RHS tarp cable. Other. Inspect Tarp & tarp cable condition and operation. RH tarp cable has come loose when open. | \$0.00 |
| R-4399 | Tarp cable | 05/31/2022 | 06/01/2022 | | 4658 Tyson: Tightened cable. | \$0.00 |
| S-4567 | A - 3 Week | 05/26/2022 | 26/05/2022 | 17 | EBS valve leaking. 2nd and 3rd axle brakes low - next service. Cracks in axle saddles. | \$0.00 |
| S-4505 | A - 3 Week | 05/04/2022 | 09/05/2022 | 32 | Tightened tarp cable. | \$0.00 |
| R-3774 | Tyres | 01/24/2022 | 04/07/2022 | | 4097 Replaced with runouts. | \$0.00 |
| R-3683 | Tyre | 12/15/2021 | 04/07/2022 | 4016, 4059 | Repaired. | \$0.00 |

| | | | | | | |
|--------|----------------|------------|------------|------------|--|--------|
| S-4411 | A - 3 Week | 03/31/2022 | 07/04/2022 | 27 | Rear axle 4th tyres low. All brakes getting low. Air leak EBS valve. | \$0.00 |
| R-4156 | Tarp gearbox | 03/17/2022 | 03/17/2022 | | Replaced gearbox and motor. Replaced one roller bearing. | \$0.00 |
| S-4335 | A - 3 Week | 03/09/2022 | 10/03/2022 | 43 | Internal Workshop Cracks in cross member. Cracks in axle saddles 3rd and 4th. | \$0.00 |
| R-3917 | Mudguard poles | 02/11/2022 | 02/11/2022 | | Welded broken tab back on for mudguard pole. | \$0.00 |
| R-3860 | Tyre | 02/07/2022 | 02/08/2022 | 4140, 4149 | Replaced x 2 dolly LHS 2nd axle supplied by Carrols. | \$0.00 |
| R-3691 | Brakes | 12/14/2021 | 02/01/2022 | 4006 | Other. Brakes (incl Maxi brakes). delay in coming on. Jay - brake relay valve has been replaced. 2nd axle LH tyres need replacing. 4th axle LH inner need replacing. Rear axle s-cam tubes need welding - done. Secure apron mud flaps - done. 2nd axle LH shock bushes - done. LH tarp cable - done. | \$0.00 |
| S-4211 | A - 3 Week | 01/26/2022 | 26/01/2022 | 42 | Draw bar bent as a banana. | \$0.00 |
| S-4146 | A - 3 Week | 12/15/2021 | 15/12/2021 | 21 | Tow eye bush needs replacing when re-kit ring feeder. | \$0.00 |
| S-4078 | A - 3 Week | 11/24/2021 | 24/11/2021 | 31 | Internal Workshop Needs tyres 2nd 4th axles LHS. Amber light out front of bin RHS (none in stock). Internal Workshop Jarrod. | \$0.00 |
| S-3994 | A - 3 Week | 10/24/2021 | 24/10/2021 | 28 | Replace tarp cable. | |
| S-3879 | A - 3 Week | 09/27/2021 | 27/09/2021 | 40 | Internal Workshop Done by Jarrod. | |
| R-3019 | Body locator | 07/02/2021 | 08/18/2021 | | Internal Workshop Straightened | |
| R-2942 | Tail light | 06/18/2021 | 08/18/2021 | | Internal Workshop Straightened Internal Workshop Done by Garth. | |
| S-3793 | A - 3 Week | 08/17/2021 | 18/08/2021 | 50 | EBS fault codes 144 12, 003 10 EBS at the rear of trailer leaking air. | |

| | | | | | |
|--------|--------------|------------|------------|------|--|
| S-3656 | A - 3 Week | 06/29/2021 | 29/06/2021 | 27 | Internal Workshop Service done by Jarrod Replaced 1st & 2nd axle shock bushes Defects: RH body locator bent 1st axle RH inner tyre worn heavily inside edge 3rd axle LH inner tyres worn heavily inside edge |
| R-2975 | Tarp cable | 06/23/2021 | 06/24/2021 | 3016 | Internal Workshop Adjusted tarp cables & bows - job done by Jarrod |
| R-2778 | Tyre repairs | 05/05/2021 | 06/21/2021 | | Internal Workshop Can't fault - inspected by Jarrod Garth inspected and repaired puncture |
| R-2820 | Tyres | 05/18/2021 | 06/02/2021 | 2715 | Internal Workshop Internal Workshop Service done by Jarrod Can't find leak on DS rear outside trailer tyre Defects: 1st axle shock bushes worn 3rd & 4th axle EBS valve leaking |
| S-3585 | A - 3 Week | 06/02/2021 | 02/06/2021 | 47 | 1st Axle RH tyres wearing heavily on inside edge Internal Workshop Tarp not retracting property - lubed tarp cable - job done by Garth |
| R-2842 | Tarp | 05/21/2021 | 05/21/2021 | 2785 | Internal Workshop Welded rear mudguard bracket back on - job done by Garth |
| R-2837 | Mudguards | 05/19/2021 | 05/21/2021 | 2753 | Internal Workshop Jay confirmed that we will run tyres until they are illegal |
| R-2792 | Tyres | 05/11/2021 | 05/11/2021 | | Internal Workshop Straightened bent light bar on dolly & rear of trailer - job done by Jarrod |
| R-2721 | Lights | 04/20/2021 | 04/29/2021 | | Internal Workshop Service done by Garth Replaced RHR mudflap |
| S-3463 | A - 3 Week | 04/16/2021 | 16/04/2021 | 23 | Internal Workshop Jarrod inspected the maxi brakes and suggested that the check valve be replaced Jarrod replaced valve on 26/03/2021 |
| R-2629 | Brakes | 03/23/2021 | 03/26/2021 | | Internal Workshop Service done by Jarrod Defects: 1st axle RH tyres wearing heavily on inside edge |
| S-3404 | A - 3 Week | 03/24/2021 | 24/03/2021 | 29 | Drawbar bushes worn Internal Workshop Trailer is booked in at D&L Laser |
| R-2598 | Tyres | 03/17/2021 | 03/17/2021 | 2076 | Alignment on 22/03/2021 |

| | | | | | | |
|--------|------------|------------|------------|----|---|---|
| S-3350 | A - 3 Week | 02/23/2021 | 23/02/2021 | 21 | Internal Workshop | Service done by Jarrod |
| S-3273 | A - 3 Week | 02/02/2021 | 02/02/2021 | 46 | Internal Workshop | Service done by Laine |
| S-3190 | A - 3 Week | 12/18/2020 | 18/12/2020 | 30 | internal workshop | Lock pin missing tailgate and locator damaged |
| R-2329 | Mudflaps | 12/15/2020 | 12/15/2020 | | Internal Workshop | Replaced RHR mudflap |
| R-1903 | Tyres | 11/24/2020 | 11/24/2020 | | internal workshop | Replaced 4 x tyres 2nd axle |
| R-1582 | Tarp | 11/18/2020 | 11/19/2020 | | Replaced 4 x tyres 4th axle | Replaced reflectors |
| S-1971 | A - 3 Week | 11/18/2020 | 18/11/2020 | 27 | Internal workshop | Adjusted tarp cables |
| S-683 | A - 3 Week | 10/22/2020 | 22/10/2020 | 23 | Replaced | tow eye bush |
| S-550 | A - 3 Week | 09/29/2020 | 29/09/2020 | 26 | internal workshop | service done |
| S-494 | A - 3 Week | 08/31/2020 | 03/09/2020 | 27 | | 2nd & 4th axle need tyres |
| S-423 | A - 3 Week | 08/07/2020 | 07/08/2020 | 23 | Adjusted | LH tarp cable |
| S-353 | A - 3 Week | 07/15/2020 | 07/15/2020 | | Internal Workshop | A service done |
| S-282 | A - 3 Week | 06/23/2020 | 06/24/2020 | | Internal Workshop | A service done |
| S-214 | A - 3 Week | 06/02/2020 | 06/02/2020 | | Replaced | 2nd axle LHS with runouts |
| S-134 | A - 3 Week | 05/11/2020 | 11/05/2020 | 46 | Replaced | LH tarp cable |
| S-811 | A - 3 Week | 03/26/2020 | 26/03/2020 | 34 | Internal Workshop | A service done |
| R-608 | Mudflaps | 02/28/2020 | 02/28/2020 | | 2nd axle RH inner tyre swapped for runout | |
| | | | | | A service done | |
| | | | | | Service done | |
| | | | | | Internal Workshop | Service done |
| | | | | | Service done | |
| | | | | | Fitted | wheel chocks |
| | | | | | Tensioned | tarp cables |
| | | | | | Service done | |
| | | | | | Internal Workshop | A service done |
| | | | | | Checked | all trailing arm bolts |
| | | | | | LH tarp cable | u/s |
| | | | | | DEFECTS: | dolly lock plate bent |
| | | | | | Tarp motor | cracked |
| | | | | | Replaced | missing rear mudflaps |

| | | | | | |
|-------|--------------------------|------------|------------|----|--|
| S-810 | A - 3 Week | 02/21/2020 | 21/02/2020 | 22 | Internal Workshop A service done DEFECTS: dolly lock plate bent Tarp motor cracked |
| S-809 | A - 3 Week | 01/30/2020 | 30/01/2020 | 42 | Internal Workshop A service done Replaced RHF clearance light DEFECTS: dolly lock plate bent |
| S-808 | A - 3 Week | 12/19/2019 | 19/12/2019 | 21 | Internal Workshop A service done DEFECTS: dolly lock plate bent Tarp motor cracked |
| R-607 | Tyre repairs | 12/06/2019 | 12/06/2019 | | Internal Workshop Repaired 2nd axle LHS outside Internal Workshop A service done Repaired bolts for mudguards rear of dolly rubbing on body DEFECTS: need full amber clearance light RHF - no stock |
| S-807 | A - 3 Week | 11/28/2019 | 28/11/2019 | 22 | Internal Workshop Checked over that all slack adjusters are travelling evenly Removed ALL BWC stickers & replace mudflaps with Holcim ones |
| R-606 | Machinery pre-inspection | 11/22/2019 | 11/22/2019 | | A service done Secured RH mudflap Tightened loose valve core on 2nd axle LH inner tyre DEFECT: Dolly lock plate bent |
| S-806 | A - 3 Week | 11/06/2019 | 06/11/2019 | 20 | Internal Workshop A service done DEFECTS: dolly lock plate bent Front axle catch straps - almost worn through - 2nd axle LHS hanging by thread |
| S-805 | A - 3 Week | 10/17/2019 | 17/10/2019 | 24 | Bin up alarm zip tied by driver A service done Fitted 4 x shocky straps 1st & 2nd axles |
| S-804 | A - 3 Week | 09/23/2019 | 23/09/2019 | 10 | DEFECTS: dolly lock plate bent |

| | | | | | |
|-------|-----------------|------------|------------|----|---|
| S-803 | A - 3 Week | 09/13/2019 | 13/09/2019 | 25 | Internal Workshop A service done DEFECTS: dolly lock plate bent Front axle catch straps almost worn through 2nd axle LHS hanging by a thread |
| R-605 | Mudflaps | 08/26/2019 | 08/26/2019 | | Internal Workshop Replaced mudflaps on drive & rear of trailer with BWC ones |
| S-802 | A - 3 Week | 08/19/2019 | 19/08/2019 | 27 | Internal Workshop A service done Replaced LHS tarp cable DEFECTS: all 4 axles cracking around saddle welds Monitor spring eye bushes - minor movement - LH 3rd axle excessive RHR bumper bent on dolly |
| R-604 | Tarp motor | 08/02/2019 | 08/02/2019 | | Tarp motor cracked Swapped wires rear of switch |
| R-602 | Slack adjusters | 07/26/2019 | 07/26/2019 | | Shephard Trailers Trailer to Shephard to get slack adjusters done WARRANTY JOB |
| R-603 | Brakes | 07/25/2019 | 07/25/2019 | | Internal Workshop Adjusted brakes |
| S-801 | A - 3 Week | 07/23/2019 | 23/07/2019 | 20 | Internal Workshop A service done REQUEST: tarp button in cab is opposite - swap wires - NOT DONE - JACK TO DO 24/7 Straightened out RHF anti-sail bracket on mudflap Tightened up multiple booster hose clamps DEFECTS: All slack adjusters need replacing ASAP - backing off & some are nearly seized Tarp motor cracked, Centre tailgate finger bent Monitor spring eye bushes All 4 axles cracking around saddle welds RHR bumper bent on dolly |
| R-601 | Tarp cable | 07/19/2019 | 07/19/2019 | | Internal Workshop Aligned tarp bows & re-tensioned cables |

| | | | | | |
|-------|--------------|------------|------------|----|--|
| S-800 | A - 3 Week | 07/03/2019 | 03/07/2019 | 20 | Internal Workshop A service done Fitted 8 x valve extensions |
| R-600 | Tyres | 06/21/2019 | 06/21/2019 | | Internal Workshop Fitted 4 x Hankook to 1st axle Internal Workshop Replaced 2nd, 3rd, 4th axle tyres with Hankook Straightened & welded 3rd axle guard bracket RHS |
| R-599 | Tyres | 06/20/2019 | 06/20/2019 | | Internal Workshop Service done Slack adjusters backing off - Will be replaced by Shephards DEFECTS: all 4 axles around saddle welds cracking Monitor spring eye bushes RHR bumper bent on dolly |
| S-799 | A - 3 Week | 06/13/2019 | 13/06/2019 | 28 | Internal Workshop Service done Fitted 2 x runouts to rear axle both sides insides Fit 1 x runout to 2nd axle LHS inside DEFECTS: all 4 x axles cracking around saddle welds Monitor spring eye bushes RHS rear bumper bent on dolly |
| S-798 | A - 3 Week | 05/16/2019 | 16/05/2019 | 23 | Internal Workshop Repair puncture - tyre 2nd axle LHS outer |
| R-598 | Tyre repairs | 04/23/2019 | 04/23/2019 | | Internal Workshop Service done Changed tyre 2nd axle RHS dolly DEFECTS: all 4 axles cracked Monitor spring eye bushes - minor movement RHS rear bumper bent on dolly |
| S-797 | A - 3 Week | 04/23/2019 | 23/04/2019 | 22 | Drawbar support bent |
| R-597 | Tarp cable | 04/01/2019 | 04/01/2019 | | Internal Workshop Checked wiring & circuit breakers - pushed switch - worked fine both ways |

| | | | | | |
|-------|------------|------------|------------|----|--|
| S-796 | A - 3 Week | 04/01/2019 | 01/04/2019 | 28 | Internal Workshop Service done Fitted missing valve extensions DEFECTS: all 4 axles cracking Monitor LH 1st bearing play Monitor RH 1st, 2nd & 3rd bearing play Internal Workshop Service done |
| S-795 | A - 3 Week | 03/04/2019 | 04/03/2019 | 18 | DEFECTS: all 4 axles cracked Monitor spring eye bushes - minor movement |
| S-794 | A - 3 Week | 02/14/2019 | 14/02/2019 | 24 | Internal Workshop Service was done Pump tyres up to correct pressure Repaired puncture in tyre on LHR outer tyre Re-tensioned both tarp cables Replaced broken RHF clear reflector Tightened RH 3rd & 4th mudguard brackets Cleaned off old grease from rear top & bottom pins |
| R-596 | Tarp cable | 01/23/2019 | 01/23/2019 | | Internal Workshop Replaced tarp cable on LH side Internal Workshop Service done Removed old rego label DEFECTS: Monitor spring eye bushes - minor movement |
| S-793 | A - 3 Week | 01/21/2019 | 21/01/2019 | 35 | All 4 axles cracking around saddle welds |
| S-792 | A - 3 Week | 12/17/2018 | 17/12/2018 | 24 | Internal Workshop Service done DEFECTS: All 4 axles cracking around weld for saddle |
| R-595 | Ringfeder | 12/07/2018 | 12/07/2018 | | Internal Workshop Had to replace tow eye bush Internal Workshop Service done |
| S-791 | A - 3 Week | 11/23/2018 | 23/11/2018 | 11 | Cracks where trailing arms welded to axles |
| S-790 | A - 3 Week | 11/12/2018 | 12/11/2018 | 31 | Internal Workshop Service done Internal Workshop Service done |
| S-789 | A - 3 Week | 10/12/2018 | 12/10/2018 | 21 | Adjusted tarp cable |

| | | | | | | |
|-------|------------|------------|------------|----|---|----------------|
| | | | | | Internal Workshop | Service done |
| | | | | | RHF 3rd axle bung on trailing arm removed & turned around | |
| S-788 | A - 3 Week | 09/21/2018 | 21/09/2018 | 17 | | |
| S-787 | A - 3 Week | 09/04/2018 | 04/09/2018 | 21 | Internal Workshop | Service done |
| | | | | | Internal Workshop | Service done |
| S-786 | A - 3 Week | 08/14/2018 | 14/08/2018 | 27 | Tyres need to be rotated | |
| S-785 | A - 3 Week | 07/18/2018 | 18/07/2018 | 21 | Internal Workshop | Service done |
| S-784 | A - 3 Week | 06/27/2018 | 27/06/2018 | 21 | Internal Workshop | Service done |
| S-783 | A - 3 Week | 06/06/2018 | 06/06/2018 | 22 | Internal Workshop | Service done |
| S-782 | A - 3 Week | 05/15/2018 | 15/05/2018 | 28 | Internal Workshop | Service done |
| S-781 | A - 3 Week | 04/17/2018 | 17/04/2018 | 29 | Internal Workshop | Service done |
| S-780 | A - 3 Week | 03/19/2018 | 19/03/2018 | 33 | Internal Workshop | Service done |
| S-779 | A - 3 Week | 02/14/2018 | 14/02/2018 | 35 | Internal Workshop | Service done |
| S-778 | A - 3 Week | 01/10/2018 | 01/10/2018 | | Internal Workshop | A service done |