



Vehicle History Summary

Fleet #	T02
Registration	02KJP
Make	MACK
Model	TRIDENT
VIN / Chassis #	6FMM12H56GD807991
Build Date	12/2017

Date	Reading / Units	Type / Repairer Notes	Repairer
		Steer Tyres T-679 cancelled as no Invoice recieved matching this Tyre Item #	Ocean Tyres
		New T-721	Ocean Tyres
06/02/2026	1,214,121 kms	New T-817	Ocean Tyres
04/02/2026	1,213,677 kms	B - B Service S-1338 Service complete Brake test complete Replaced front RH shockie Replaced 3rd axle LH and RH shockies Replaced 1 piece of exhaust flex Replaced fuel bowl due to leak Replaced steer axle mudguard brackets rewelded busted drivers step	
07/01/2026	1,205,861 kms	AC blower R-3408 Remove and replace blower motor	
16/12/2025	1,201,486 kms	Brakes, Hydraulics, Ice pack, Lights R-3383 Replaced blown headlights Tightened hydraulic hoses under deck No fault found with trailer brakes Aces repaired icepack	
15/12/2025	1,201,486 kms	icepack R-3399 Replaced lead relay on relay block	
11/12/2025	1,201,486 kms	NHVR Inspection Checklist I-499 Inspection Complete	
11/12/2025	1,201,493 kms	Coolant R-3407 Replaced water pump and thermostat housing	
14/11/2025	1,196,790 kms	AC R-3391 R&R temp sensor	
13/11/2025		Parts O-266	Aces
04/11/2025	1,192,714 kms	Exhaust Brake , Hydralic Tank, Seat R-3375 Replaced Seat Ride height valve Replaced female Tema Replace leaking hydraulic hoses Replaced Exhaust brake switch in cab	
13/10/2025	1,188,573 kms	ABS, Brakes, mudgaurds R-3353 Van aircon seems to get cold Mudguard brackets fixed however still rusted out Step on tank still bent but usable Hydravlic tank wasn't leaking ABS light isnt on however toll trailers make it appear Trailer lights fixed RH steer slack adjuster doesn't seem to be faulty	
13/10/2025	1,188,573 kms	ABS, AC, Exhaust Brake , Hydraulic Tank, mudgaurds, steps, trailer lights R-3363 AC no fault found Mudguard brackets fixed Step on tank slightly bent - Monitor No leak at hydraulic tank ABS light out	
04/09/2025	1,179,648 kms	AC R-3351	

Date	Reading / Units	Type / Repairer Notes	Repairer
02/08/2025	1,176,476 kms	C - C Service S-1281 Brake test and service complete	
04/07/2025		checkover R-3332 complete check over cab cushions are worn tie rod boot busted - steer axle passenger passenger window switch faulty	KJP Workshop - Ethan Sagnol
13/06/2025	1,176,469 kms	exhaust R-3314 R&R exhaust elbow and dpf	KJP workshop - Scott Laburniy
25/04/2025	1,174,833 kms	Engine Tune Up R-3317 Tune up complete	
20/03/2025		New T-775	Ocean Tyres
17/02/2025	1,166,639 kms	B - B Service S-1225	KJP workshop - Mitchell Breen
11/12/2024	1,146,370 kms	NHVR Inspection Checklist I-423 Brake test complete Inspection passed	
01/11/2024	1,135,022 kms	New T-753	Ocean Tyres
30/10/2024	1,131,715 kms	Fan, radiator R-3239 R&R fan, fan hub, fan shroud and belts Radiator test for leaks Intercooler tested for leaks - R&R Chris smith called to remove engine fail safe alarms R&R starter motor	
30/09/2024		Parts O-254 T & R aircon fault R & R new hose	
29/08/2024	1,122,665 kms	B - B Service S-1178 brake test - PASSED	
26/08/2024	112,260 kms	New T-740	Ocean Tyres
28/06/2024		radiator R-3248 remove radiator remove fan hub assembly remove fan and alternator belt tensions dit new tensioner hub and clutch new belts radiator intercooler	
26/06/2024		ABS, ABS/TC, boost, indicator stalk, Waste gate R-3231 WTG Inv 4051986 -\$6562.05 WTG Inv 4052218 - \$751.35	
18/06/2024	1,092,795 kms	Window Regulator R-3228 R&R drivers side window lift mechanism	
31/05/2024		Shaft R-3227 replace input shaft	CC Smith Mechanical Repairs
22/05/2024	107,800 kms	Clutch, Clutch cylinder R-3218 Check transmission light come on and clutch was slipping. Tested clutch cylinder and found to be leaking/failed. Apon removal of gearbox we found clutch and input shaft were also worn. Trans was sent to CC Smith Mechanical for input shaft replacement. Once reassembled Chris Smith reprogrammed transmission. Check trans warning was still present. After cleaning TECU plug and salve solinoid plug and a short drive, warning light went away.	KJP workshop - Judd Porter
22/05/2024	1,078,988 kms	C - C Service S-1142 Brake test complete - PASSED	KJP workshop - Judd Porter, KJP workshop - Ricky Jones
22/05/2024	1,079,000 kms	Exhaust leak, Suspension R-3214 Replaced exhaust pieces	KJP workshop - Scott Laburniy
22/05/2024		New T-714	Ocean Tyres
20/04/2024	1,065,342 kms	B - B Service S-1123	

Date	Reading / Units	Type / Repairer Notes	Repairer
		Brake test complete - PASSED	
18/04/2024	1,055,673 kms	Oil Leak, Spinner filter R-3208 R&R spinner filter	
11/03/2024	1,047,530 kms	Suspension, Torque Rods, Track Rod, Wheel Alignment R-3182 LH 3rd axle hubseal replaced R&R torque rod Wheel Align	KJP Workshop - Jay Sagnol, KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
04/03/2024	1,043,661 kms	Brake problems, Brakes, Hub Seal, Wheel Bearings R-3194 Inspect and look for cause of heating issue removed brakes and drums to inspect Replace faulty brake valce Replace LH and RH brakes and drums Remove hubs and inspect bearings on LH and RH front drive R&R LH front drive slack adjuster	KJP workshop - Scott Laburniy
14/01/2024	1,021,547 kms	B - B Service S-1082 Brake test complete - PASSED	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
08/01/2024	1,017,970 kms	Bonnet Latch, Headlight, icepack , Signs R-3166 1. Ran icepack for 3+ hours - no fault found 2. Fit new studs to bullbar 3. Replaced bonnet latch 4. Installed LED headlights	KJP workshop - Judd Porter
02/01/2024	1,015,420 kms	Booster R-3162 R&R RH front booster	KJP workshop - Mitchell Breen
02/01/2024	1,015,417 kms	Exhaust Brake R-3163 R&R AVU valve and smaller air valve on LH side of block	KJP workshop - Judd Porter, KJP workshop - Mitchell Breen
12/12/2023	1,005,623 kms	NHVR Inspection Checklist I-345 Brake test complete - PASSED	
12/12/2023	1,005,623 kms	Signs, Tyres R-3149 Repair clip on road train sign Test drove - steers ok R&R LH DG book holder	Doug Kretschmer - KJP Haulage, KJP workshop - Mitchell Breen
29/11/2023	992,124 kms	Fault Code R-3124 Travelled to Orica to diagnose. Inspected ABS sensors and wiring - removed backing plates and nothing noticeable found. Truck returned to workshop. Removed wheels and brakes, found hub seal on RHF leaking and interfering with sensor reading - Repaired	Doug Kretschmer - KJP Haulage, KJP workshop - Scott Laburniy
29/11/2023	995,697 kms	Air Leak R-3127 1. Found air leak on RHF chassis rail relay valve - Removed and replaced 2. Removed broken bracket and repaired - Refit	Doug Kretschmer - KJP Haulage, KJP workshop - Scott Laburniy
21/11/2023	991,614 kms	AC R-3116 ACES repaired	Aces
13/11/2023		Replace T-657	Ocean Tyres
01/11/2023	980,435 kms	Brakes, coolant leak, Cracks, Exhaust leak, noisy belts, Windscreen R-3112 replaced step clamps on exhaust flex under cab test A/C system replace A/C thermostat pressurize cooling system look for leaks replace 1st axle LH slack adjuster replace both fan belts repair right hand top tank step	Doug Kretschmer - KJP Haulage, KJP Workshop - Craig Hyde, KJP workshop - Scott Laburniy
30/10/2023	980,435 kms	C - C Service S-1053 fan belt could do with replacing 1st axle slack adjuster is winding off exhaust leak at flex near rear of cab	KJP workshop - Scott Laburniy
17/10/2023	970,597 kms	Headlight R-3090	KJP workshop - Judd Porter, KJP workshop - Mitchell Breen

Date	Reading / Units	Type / Repairer Notes	Repairer
		repair broken headlight insert on bonnet replace headlight	
03/10/2023	961,945 kms	Air Conditioner, Air leak R-3063 1. Airleak fixed 2. Aces inspected AC, still no fault found - wait for issue to progress to diagnose	KJP workshop - Judd Porter
28/09/2023		Seat Belt R-3060 R & R drivers seat belt	Doug Kretschmer - KJP Haulage
15/09/2023	958,717 kms	B - B Service S-1033 degrease and gurney underneath removing Loctite from filter housing threads as best as possible seat belt starting to show signs of wear	KJP workshop - Scott Laburniy
14/09/2023	958,717 kms	Auto Greaser R-2961 Central Queensland Invoice#23232 R & R broken bolt ion muffler cover R & R auto greaser bowl R & R bonnet bushes, fit new pin to LH bonnet wire repair bonnet spring mounts	Doug Kretschmer - KJP Haulage
11/09/2023	958,668 kms	Light R-3050 replaced fuse holder required wiring to driving lights	KJP workshop - Scott Laburniy
11/09/2023	958,666 kms	Dash panel R-3047 tightened up panel, new screws to be sourced refit fridge, check over wiring make sure fridge was getting cold	KJP workshop - Scott Laburniy
31/07/2023		AC R-2965 test A/C replaced both thermostats stripped down and cleaned evaporator	KJP workshop - Scott Laburniy
31/07/2023	937,241 kms	Air leak, window R-2959 Windscreen Wizard inv#9156 1. No fault with drivers window, all trucks has movement 2. Inspected for air leaks, R&R LHF drive airbag 3. Resealed hydraulic solenoid	Doug Kretschmer - KJP Haulage, KJP workshop - Scott Laburniy
31/07/2023	937,241 kms	Exhaust leak R-2995 Realign exhaust pipe off back of turbo	Doug Kretschmer - KJP Haulage
10/07/2023	935,406 kms	Cab Mounts, Exhaust R-2960 R & R exhaust flex and repair pipe flange, cab mounts, air leaks, bonnets mounts, cab shock CC SMITH INV#3406	KJP Workshop - Craig Hyde
04/07/2023		Air Leak , Windscreen R-2943 Refer to - R 2941	
04/07/2023		Exhaust, Windscreen R-2948 Refer to - R 2941	KJP - Internal Workshop
03/07/2023	934,684 kms	Oil Leak R-2949 remove and clean out hub and brake shoe from old oil buff up brake shoes, top up oil and re fit brake and hub replace seal repair ABS fault	KJP Workshop - Craig Hyde
30/06/2023	934,680 kms	Replace T-610	Ocean Tyres
22/06/2023	926,880 kms	Air Dryer, Air Leak , Breakdown R-2933	KJP workshop - Scott Laburniy
12/06/2023		Radiator R-2920 CANCELLED DUPLICATE Gladstone Radiator Services 05.06.23 - Remove top tank & clean out radiator. Replace tank with new one.	Gladstone Radiator Service
10/06/2023	935,406 kms	Exhaust leak, Windscreen R-2941 CQCM INV#18484 R & R manifold	KJP Workshop - Craig Hyde
09/06/2023	919,289 kms	B - B Service S-958 Brake Test - PASSED	KJP workshop - Mark Johnson
29/04/2023	913,244 kms	Alternator, breakdown R-2889 Drive back to work shop & remove alternator from T19 & fit it to T02. Check charge rate & clear fault codes.	KJP workshop - Mitchell Breen

Date	Reading / Units	Type / Repairer Notes	Repairer
28/04/2023	909,775 kms	a/c fan, Air Leaks, Exhaust Brake , radio R-2850 1. Inspect and repair all air leaks 2. Replace broken roof antenna 3. Check fan operation 4. check exhaust brake operation 5. Check batteries 6. Repair Air / Con	KJP workshop - Mark Johnson, KJP workshop - Mitchell Breen
22/04/2023	909,775 kms	Coolant Leak R-2877 Find coolant leak, organise radiator from WTG. Remove radiator, intercooler & fit to new radiator. Fix A.C leak. Vac down & re-gas. Worked as a team to R&R radiator. Gladstone Radiator Services 05.06.23 - Remove top tank & clean out radiator. Replace tank with new one.	KJP workshop - Mark Johnson, KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
01/04/2023		Air Conditioner R-2837 Traced all wiring for heater / air con fan Traced back to a faulty fan, got replacement from ct smith Ice pack not shutting down, replaced shut off solenoid. Cabin fan noisy, plastic fan had exploded, replaced cabin filter.	KJP workshop - Mark Johnson
27/03/2023		New T-559	Ocean Tyres
03/03/2023	894,446 kms	Ride Height , tail shaft R-2818 Tail shaft was damaged badly on way home, had to get yoke cut of and new yoke welded back on. then tail shaft balance Replace Centre bearing Replace and test ride height control valve	KJP workshop - Judd Porter, KJP workshop - Mark Johnson, KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
20/01/2023	881,251 kms	SafetyCampaign R-2727 6FMM12H56GD807991 C0118 - Electrical main switch jumper harness	CC Smith Mechanical Repairs
18/01/2023	882,581 kms	C - C Service S-897 Service truck Brake Test	KJP workshop - Mitchell Breen
15/12/2022	870,040 kms	NHVR Inspection Checklist I-262 Brake test passed	
12/12/2022	867,500 kms	ROTC Pre Check R-2753 Check over for ROTC Inspection Replace wiper blades Replace rotten exhaust elbow and clamps	KJP workshop - Mark Johnson
06/12/2022		Registration O-209	
21/10/2022	853,430 kms	Exhaust Flex R-2715 Remove and replace exhaust flex Replace roof clearance light repair coolant leak Buttlers welded up step Raised drive guards Steer Tyres been replaced front left headlight bulb replaced	KJP workshop - Mitchell Breen
18/10/2022		New T-506	Ocean Tyres
09/09/2022	838,140 kms	B - B Service S-842 Service, repair lights, looks for air leaks, adjust guards & Gurney underneath. Brake test passed.	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
09/09/2022	838,140 kms	Clearance Light R-2665 See service S-842	KJP workshop - Scott Laburniy
17/06/2022	796,156 kms	B - B Service S-793 Brake test passed Grease pot on auto greaser needs replacing (need to order one) Finish off service.	KJP workshop - Mark Johnson, KJP workshop - Mitchell Lancaster
08/06/2022	791,426 kms	Air Dryer R-2545 R&R Air Dryer R&R flexi hose comp to dryer Straightened handle turn table	KJP workshop - Mitchell Lancaster
07/06/2022		Registration O-176	
24/05/2022	800,542 kms	Air leak, drivers seat, Exhaust leak, Shock Bushes, Windscreen R-2569	KJP workshop - Mark Johnson, KJP workshop - Mitchell Lancaster

Date	Reading / Units	Type / Repairer Notes	Repairer
		Changed leaking air fitting ! air dryer R&R williams valve @ wet tank Inspected shockies on drive, found all bushes worn & shockies needed, replacement parts ordered. Replaced 1 x exhaust flex undercab, other one ordered. All drive shockies Front exhaust flex & clamps Fitted drive shocks R&R seat valve, check isolator, had moisture in it.	
12/05/2022	782,084 kms	Air Conditioner, Ice pack R-2460	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
		11.5 -Replaced missing bolts in ice pack, trace ABS wiring, found damaged, repaired wiring & tester, no fault found. Checked out fault with engine fan staying on, found faulty fan hub, ordered replacement. Degreased and hot washed under truck. Spent an hour on phone getting passwords sorted for tech tool. Removed broken U bolt from exhaust bracket, replaced clamp, pulled down ac fan covers and inspected noise coming from motor. 12.5 - R&R engine fan hub, checked with tech tool to make sure working correctly, degreased & washed engine bay.	
12/05/2022	782,084 kms	Windscreen R-2492	KJP workshop - Scott Laburniy
		Only leaked under high pressure wash, no repair required.	
07/04/2022	764,896 kms	New T-428	Ocean Tyres
04/04/2022		Spot Lights R-2432	Aces
		Found earth to relay dropping out, joined relay earth to main switch, tested and all OK.	
01/04/2022		Wheel Alignment R-2428	KJP workshop - Wayne Goodlet
		Completed Wheel Alignment	
31/03/2022	764,049 kms	New T-425	Ocean Tyres
08/03/2022	756,910 kms	C - C Service S-711	KJP workshop - Wayne Goodlet
17/01/2022	744,549 kms	Electrical R-2279	
		Repaired wiring to driving light relay Rewired trailer plug General look over	
07/01/2022	739,016 kms	mudguards R-2270	
04/01/2022	717,649 kms	engine oil, radio speaker R-2218	
		Drain out excess oil after sample was taken Refit cab speaker Sample came back all good, driver error	
22/12/2021	734,166 kms	NHVR Inspection Checklist I-183	
		Inspection, looking over Rockys own. Tidy up cables finding and wrapping rubbing spots wash truck & hook up trailers Brake Test pass	
22/12/2021	732,673 kms	Air Conditioner, Auto Greaser, Engine Mount, Hydraulic Tank R-2204	
		R&R RHS modulator valve, found air bag passing internally QR vavle at front R&R QR1 valve & fittings Found LHS modulator valve needs replacing also Icepack fixed again by Aces Replaced LH modulator valve Reseal grease canistor Clean AC filter R&R cab mounts Find ABS sensor in constock, chase down plug in chasis and compare. Sensor didnt seem right, told not to pull down side to get proper look, patched up wiring on old sensor alarm	
13/12/2021		Registration O-144	
22/11/2021	720,519 kms	Auto Greaser, Ice pack, mudguards R-2222	KJP workshop - Mitchell Lancaster
		1. R&R relay 2. Cleaned up and patched with silicon 3. R&R LHS mudguard 4. Unable to find fault. Monitor 5. same as 4. Front cab mounts need replacing.	
10/11/2021	714,853 kms	turntable R-2212	KJP workshop - Judd Porter
		R&R turntable pads	
09/11/2021	714,493 kms	B - B Service S-616	
		Conducted service Brake test passed Grease pot cracked Tyre pressures checked	
25/10/2021	706,837 kms	drivers seat, Headlights, Suspension R-2171	KJP workshop - Mitchell Lancaster, KJP workshop - Tre Szepanowski, KJP workshop - Wayne Goodlet

Date	Reading / Units	Type / Repairer Notes	Repairer
		Remove and replace torque rod on forward rear axle rear axle torque rod also needs replacing air leaking from trans test port on power steering res - require replacement. 2nd torque rod has been replaced, Air leak fixed. Seat no fault found Replaced faulty head light globe. Tested and replaced rev light with 2nd hand from container Replaced mupflaps and chevron signs Repaired fridge bracket while in truck.	
08/10/2021	699,715 kms	Air Conditioner R-2163	KJP workshop - Judd Porter, KJP workshop - Tre Szepanowski
		Found cab filter blocked, Replaced filter, Wash out condenser to get better air flow.	
30/09/2021	698,080 kms	Air Leak , Cab Shockies, Exhaust Brake , Lights, mudgaurds R-2141	KJP workshop - Judd Porter, KJP workshop - Mitchell Lancaster
		Road tested to fault find. Read DTC's with tech tool 1 - Requires switch replacement - tech tool showing DTC 5 - Faulted on road test, inspected wiring, replaced main power & earth cable & fuse holder for spotlight relay - tested & working 4 - Checked over mudguard mounts & nipped up a few grub screws 3 - Air leak from fitting on top of gear box LHS, fix leak from fittings on side of P/S res bracket 2 - R&R RHS front cab shockie, R&R both front cab rubber springs Removed, repaired & refitted broken bracket for grease insector bank	
24/09/2021	698,042 kms	Ride Height R-2139	KJP workshop - Mitchell Breen
		R & R Ride height control valve, Clean up hydraulic tank, and devcon crack/ leak on tank	
23/09/2021	698,020 kms	Air bag, Wheel Alignment R-2134	KJP workshop - Mitchell Breen, KJP workshop - Wayne Goodlet
		Conducted Wheel alignment Replace leaking air bag	
20/09/2021	698,013 kms	New, Steer Tyres T-351	Ocean Tyres
15/09/2021	697,178 kms	Windscreen R-2107	Windscreen Wizard
		Windscreen Wizard came 15/09/21	
24/08/2021	685,713 kms	New T-343	Ocean Tyres
16/08/2021		Puncture Repair T-340	Ocean Tyres
14/08/2021	678,311 kms	Dipstick, Driveline R-2042	KJP workshop - Mitchell Lancaster, KJP workshop - Scott Laburniy
		R & R center bearing R & R dipstick road tested after reapirs bolt tensions for center bearing and uni to be check @ next service	
10/08/2021		Mud Flap R-2047	KJP workshop - Wayne Goodlet
		R & R LH mudflap	
07/08/2021	674,062 kms	Engine Tune Up R-2117	KJP workshop - Scott Laburniy, KJP workshop - Wayne Goodlet
07/08/2021	674,062 kms	B - B Service S-555	KJP workshop - Wayne Goodlet
		center bearing on tail shaft worn needs new dipstick for engine oil R & R LH 2nd axle inner tyre washed mudflap off under body Brake Test - PASSED engine oil - 38 Trans oil - 10	
28/07/2021	667,818 kms	Coolant Leak R-2021	KJP workshop - Judd Porter
		R & R coolant hose	
21/07/2021	665,499 kms	Air leak, Seat R-2002	KJP workshop - Judd Porter
		NO REPAIR REQUIRED	
18/07/2021	664,592 kms	Breakdown, Low Beam R-1999	KJP workshop - Judd Porter
		Drive to Orica R&R Right hand low beam globe H11 Globe our stock	
09/07/2021	660,875 kms	batteries, Water Pump R-1976	KJP workshop - Mitchell Lancaster
		Load tested all batteries - 3 of 4 failed Remove and replace all 4 batteries Found Coolant leaking from tell tail at water pump Remove and replace water pump and gasket Remove and replace fan belt	
30/06/2021	657,345 kms	Air Conditioner R-1931	Aces, KJP workshop - Wayne Goodlet

Date	Reading / Units	Type / Repairer Notes	Repairer
		Wayne - Remove evaporator and remove and replace TX Valve evaporator Remove and replace receiver drier Recharge A/C ACES: Found leaking behind TX Valve. Found evaporator is leaking. Removed and replaced evaporator. Regas and tested a/c system.	
04/06/2021	647,321 kms	Radiator R-1890	KJP workshop - Judd Porter, KJP workshop - Mitchell Breen
		1/06/21 - Judd - Trace and repair coolant leak Remove and replace radiator (radiator was from stock - was a warranty radiator - no invoice) Gladstone Radiator Services: Intercooler repair	
03/06/2021	647,321 kms	Flex Joint R-1851	KJP workshop - Mitchell Breen
		Remove and replace flex joint	
25/05/2021	642,673 kms	muffler, strap R-1878	KJP workshop - Scott Laburniy
		Remove muffler cover and broken strap. Cut bracket off and weld. Refit repaired bracket.	
23/05/2021	641,496 kms	Air Conditioner, Fan R-1870	KJP workshop - Mitchell Lancaster
		Tested all fuses and relays - all okay Moved wiring around at blower fan and got it working, pushed plug together firm - suspect loose plug Unable to fault further - Fan working	
22/05/2021	643,292 kms	driving lights R-1864	KJP workshop - Mark Johnson
		Trace and find burnt out fuse holder, cut out fuse holder and fit replacement. Repair deck plate	
18/05/2021	634,603 kms	Air Leak , Breakdown R-1858	Mack / Volvo
		Temp fix on invoice 6351892 Repairer went out next day to fit new valve Rural Mechanical Repairs - Replace Pressure protection air bag	
16/05/2021	637,479 kms	C - C Service S-496	KJP workshop - Mitchell Lancaster
		Brake Test - PASSED Replaced wiper blades Topped up coolant Replaced Ice Pack air filter Remove and replace Williams valve at rear of air tank Reformatted dash cam Remove and replace air fitting in williams valve above tank Checked tension on prop shaft uni bolts Hydraulic tank leaking around seam Remove and replace power supply for right hand side high beam globe. Fault with indicators shorting (faulty flasher relay) fitted new flasher relay. Diff Oil - 36Lts Mack Engine Oil - 36Lts	
10/05/2021	633,078 kms	Coolant R-1834	KJP workshop - Scott Laburniy
		Double clamp header tank hose	
22/04/2021	623,696 kms	Driveline R-1816	KJP workshop - Mitchell Lancaster
		Fitted new prop shaft for rear drive Replaced missing diff lock light in dash Degreased hydraulic tank and repaired with metal putty. Greased new tail shaft, rebogged hydraulic tank.	
15/04/2021	620,868 kms	Wheel Alignment R-1787	KJP workshop - Wayne Goodlet
		Complete wheel Alignment	
15/04/2021	623,693 kms	Brake Booster, Exhaust Brake R-1800	KJP workshop - Judd Porter, KJP workshop - Mitchell Breen, KJP workshop - Mitchell Lancaster
		1. Remove and replace right hand rear booster 2. Remove and replace left hand air bag 3. Remove and replace break lines	
12/04/2021	618,370 kms	Air Valve R-1797	KJP workshop - Judd Porter
		Remove and replace air valve left hand side of motor	
26/03/2021	608,085 kms	Exhaust Brake R-1743	KJP workshop - Mark Johnson
		Repaired hose	
26/03/2021	608,085 kms	Light R-1690	KJP workshop - Mark Johnson
		No repair required	
25/03/2021	608,901 kms	Dash cam R-1760	KJP workshop - Mitchell Lancaster
		Traced camera cable to plug, tested camera with new lead, found fault with loose plug, pulled plug apart and tensioned spring, ziptied plug into socket, tested and working. Formatted SD Card	
22/03/2021	606,182 kms	Breakdown R-1742	KJP workshop - Scott Laburniy, KJP workshop - Wayne Goodlet

Date	Reading / Units	Type / Repairer Notes	Repairer
		3rd axle left hand wheel sensor has broken wires - repaired wires Inspected drive wheel bearings and adjusted ROD BIANCHI MOTORS: Connect diagnostic equipment, check for active ABS Faults - None. Check recent ABS wiring repair on LHS of drive axle 2 - okay. Remove wheels, reset ABS sensor and refit wheels. Found loose wheel bearings, remove wheels, reset sensor, fit wheels, clear fault.	
15/03/2021	601,215 kms	exhaust R-1727 Remove strap, clean up and reweld. Replace bolt pin and refit	KJP workshop - Scott Laburniy
11/03/2021	598,999 kms	B - B Service S-469 Brake Test - PASSED Found Coolant Leaking - Pressure test found crecked header tank - Remove and replace header tank Replaced jaw kit - Refitted turntable and adjusted Remove and Replace left hand side roof marker light Degreased rear deck and guards Remove and replace joiner in air line in chassis near starter	KJP workshop - Mitchell Lancaster
10/03/2021	1,598,994 kms	New T-282	Ocean Tyres
18/01/2021	569,996 kms	batteries R-1605 R & R battery and load and test the rest	KJP workshop - Judd Porter
21/12/2020	559,224 kms	Fridge R-1566 Remount motor and bracket to side of fridge	KJP workshop - Scott Laburniy
21/12/2020	559,224 kms	Truck annual Inspection I-97 Brake test - PASSED	
21/12/2020	559,224 kms	B - B Service S-422 Brake Test - PASSED	KJP workshop - Scott Laburniy
21/12/2020	559,224 kms	inspection R-1564 General check over for inspection	KJP workshop - Scott Laburniy
18/12/2020	558,882 kms	driving lights, Ice pack, Steering R-1562 Pulled off icepack cover, blew it out/ cleaned up cleaned relays and plugs checked over wiring for damage including ice pack harness in RH dog box found bolts for cover and refitted pick up from oceans take for test drive to rio tinto to check steering vibrations repair wiring for spotlights	KJP workshop - Scott Laburniy, KJP workshop - Wayne Goodlet
18/12/2020	558,882 kms	New T-241	Ocean Tyres
14/12/2020	556,090 kms	Power Steering R-1544 R & R steering box	KJP workshop - Judd Porter
07/12/2020		Registration O-68	
07/12/2020	552,239 kms	Bolts, Bug Deflector , Diamond Holder, Ice pack, Mud Guard, Spot Lights, Steering R-1524 1. Remove and replace indicator stalk and tested spotlights 2. Inspected and adjusted wheel alignment (Wheel Alignment completed) 3. Straighten diamond holders on bumper 4. Tensioned mudguard bolts 5. Remove and replace bug deflector 6. Replace missing bolts on muffler and ice pack cover 7. Trace and repair brake light faults - clean and secure wiring at rear of truck	KJP workshop - Mitchell Breen, KJP workshop - Wayne Goodlet
21/11/2020	544,442 kms	Accessories, Breakdown Kit R-1500 Set up breakdown kit to keep in the truck	KJP workshop - Scott Laburniy
19/11/2020	544,442 kms	Check Over, driving lights R-1488 Brake Test - PASSED Remove and replace bonnet latch Trace and repair spotlight issue (Judd's timesheet 23/11/20)	KJP workshop - Wayne Goodlet
10/11/2020	540,689 kms	Light R-1432 R & R relay block and fuses	KJP workshop - Judd Porter
10/11/2020	540,689 kms	Exhaust, Mud Guard R-1460 Removed roadside mudguard bracket repair, found bolts and washers to suit and remounted. removed broken muffler straps and modified new ones to suit and installed	KJP workshop - Scott Laburniy

Date	Reading / Units	Type / Repairer Notes	Repairer
26/10/2020	533,102 kms	Wiring Harness R-1404 Remove and replace wiring harness for front diff	KJP workshop - Mark Johnson
26/10/2020	533,102 kms	Air Leak , Bonnet, Bumper, Hydraulic Leak, Sign R-1394 1. Replaced O-ring kit 2. Found split hose that was leaking behind gear box 3. Nothing can be done without removing bumper - No repair required at the moment 4. Removed diamond holder, straightened and refitted	KJP workshop - Mark Johnson
19/10/2020	530,629 kms 8,024 hrs	Thrust Washer R-1428 Remove and replace Thrust Washer on diff Cleaned up surface on the diff Put new O-rings on	CT Smith Mechanical
06/10/2020	522,829 kms	Wheel Alignment R-1365 Complete wheel alignment	KJP workshop - Scott Laburniy
01/10/2020	521,706 kms	New T-198	Ocean Tyres
01/10/2020	521,702 kms	C - C Service S-363 Brake Test - PASSED Engine Oil 36L	KJP workshop - Judd Porter, KJP workshop - Mitchell Lancaster, KJP workshop - Scott Laburniy
29/09/2020	521,702 kms	Shock Absorber R-1327 Remove and replace left hand rear cab shockie	KJP workshop - Mitchell Lancaster
31/08/2020	505,791 kms	Electrical R-1279 R&R light plug	KJP workshop - Wayne Goodlet
27/08/2020	504,894 kms	Windscreen R-1267 Remove and refit half screen	Windscreen Wizard
27/08/2020	504,894 kms	Windscreen R-1269 Double up on jobcards please refer to R-1267	Windscreen Wizard
26/08/2020	504,894 kms	Light R-1243 1. Repaired - refer R-1191 2. found a fault with the seat while fixing light fault - repaired 3. repaired wiring for spot lights 4. replaced broken bolt in crank for mudguards	KJP workshop - Mark Johnson
18/08/2020	497,902 kms	Shock Absorber R-1191 Remove and replace front shockies Remove and replace rear exhaust flex Remove and replace left hand steer booster	KJP workshop - Wayne Goodlet
03/08/2020	493,752 kms	Air, Breakdown R-1239 Remove and replace safety valve	KJP workshop - Mark Johnson
30/06/2020	483,617 kms	Shock Absorber R-1119 R & R cab shockie checked oil and water	KJP workshop - Mark Johnson
24/06/2020	479,390 kms	B - B Service S-320 Mack Ultimate oil 36L Small oil leak from turbo drain Brake test - PASSED	KJP workshop - Wayne Goodlet
18/06/2020	476,314 kms	Engine R-1082 Disconnected both air fittings and plug. Unbolted mounting bolts and secured new replacement valve. Install new wastegate air valve and pipe set. Unbolted air intake pipes including intercooler pipe so turbo was easy to access. Take all oil lines that mount onto the turbo off. Unbolted the clamp that secures the turbo to exit of intake. Unbolted turbo, exhaust manifold bolts and unbolted manifold. Replaced all old seals and gaskets with new ones	CT Smith Mechanical
16/06/2020	476,167 kms	Engine R-1091 Hooked up computer found its the front diff temp sensor, cleaned wiring, cleared code and sensor has been replaced	KJP workshop - Mark Johnson
26/05/2020	465,770 kms	Fan Belt, Lights R-1031 1. Removed both belts to check all idler pulleys, they are all okay, refit belts. 2. Trace and rectify fault to driving lights. Rewire relay block for driving lights	KJP workshop - Mark Johnson
21/05/2020	462,440 kms	Fault Code R-1019	KJP workshop - Wayne Goodlet

Date	Reading / Units	Type / Repairer Notes	Repairer
		Diagnosed fault code to front diff temp sensor. R&R front diff temp sensor and deleted all inactive fault codes.	
14/05/2020	457,855 kms	Bumper, Sign R-1003 1. Fitted road train signs 2. swapped bumper with one on 008KJP	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
20/04/2020	448,320 kms	Exhaust Flex, strap R-960 R & R DPF strap Fix air leaks replace exhaust and flex section	KJP workshop - Judd Porter, KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
01/04/2020	438,561 kms	Lights R-891 Put dash back together after aces have worked on truck wash truck and put grill back together	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
01/04/2020	438,561 kms	Air Conditioner R-905 R & R evaporator vacuum down and clean A/C system with gas	KJP workshop - Mark Johnson
30/03/2020	437,953 kms	B - B Service S-284 1.Brake test - FAILED 2. Brake test - PASSED Refer to repair 901 for the cause and repairs	
27/03/2020	437,953 kms	Brake Booster, Torque Rods R-901 R & R torque rods R& R brake booster Brake test - PASSED	
23/03/2020	436,108 kms	Catalytic Converter R-874 Removed parts from 19KJP to make 02KJP whole repair catalytic straps 19KJP strap has been rectified	KJP workshop - Bill Shanahan, KJP workshop - Scott Laburniy
23/03/2020	435,681 kms	Lights R-880 remove wiring and indicator switch, clean out dust, tighten connector pins on indicator R & R indicator stork	KJP workshop - Bill Shanahan, KJP workshop - Mark Johnson
12/03/2020	429,945 kms	Valves R-848 Remove and replace brake air valve - still was leaking from fitting was after 5pm could get replacement	KJP workshop - Mark Johnson
06/03/2020	428,290 kms	Windscreen Wipers R-842 R & R wiper motor T & R leaked have ordered parts from VCV	KJP workshop - Bill Shanahan, KJP workshop - Judd Porter, KJP workshop - Mark Johnson
01/03/2020	424,470 kms	Air Leaks, Electrical R-819 1. couldn't get headlights to fault 2. no air leaks in dash found 3. remove and replace cruise control switch. tested - fine 4.double check headlight, no fault found will do a kodah on it	KJP workshop - Bill Shanahan, KJP workshop - Judd Porter
24/02/2020	420,905 kms	Repair, Replace T-130	Ocean Tyres
16/01/2020	398,755 kms	ABS, Brake Booster, Suspension R-690 1. fit new ABS sensor 2. fit RH steer shockie 3. remove and replace RH booster 4. remove and replace RH service ABS valve	KJP workshop - Wayne Goodlet
13/01/2020	398,762 kms	C - C Service S-254 conduct C service replaced air filters Brake test - PASSED	
03/01/2020	392,147 kms	muffler, strap R-682 Removing / swapping straps. Putting strap on 05KJP	KJP workshop - Scott Laburniy
11/12/2019	381,359 kms	Power Steering R-642 R & R power steering pump VCV replaced pump under warranty (60% - 40% was our cost)	KJP workshop - Mark Johnson
11/12/2019	381,359 kms	Truck annual Inspection I-28 Brake test - PASSED	
05/12/2019	378,322 kms	Brake Test, General, Lights R-636	KJP workshop - Jason Amos, KJP workshop - Wayne Goodlet

Date	Reading / Units	Type / Repairer Notes	Repairer
		Remove and replace left hand reverse light Inspected reverse alarm to work ROTC Inspection Brake Test - PASSED	
02/12/2019		Registration O-17	
27/11/2019	375,359 kms	Lights R-592	KJP - Internal Workshop, KJP workshop - Bill Shanahan
		Trace and repair rear light a indicator fault. Remove rust from turntable mounts and spray with rust proofer.	
11/11/2019	372,267 kms	Injector R-558	KJP - Internal Workshop
		Clermont Motors - Travel to truck inspect engine - suspect injectors Remove & Replace injector - Program new injector Remove and replace Cylinder head (Warranty work with VCV on invoice number 8530970)	
06/11/2019	361,180 kms	exhaust R-511	KJP workshop - Mark Johnson, KJP workshop - Wayne Goodlet
		Check for exhaust leaks. Remove turbo and exhaust manifold to inspect - clean surfaces - refit Remove hydraulic tank for repair - SUSTAR Fit tank, hoses and fill with oil. Remove and replace steering shaft boot.	
24/10/2019	365,646 kms	Body R-543	Butler Fabrication
		Crack repair on ally tray	
11/10/2019	354,333 kms	Lights R-475	KJP - Internal Workshop, KJP workshop - Wayne Goodlet
		Repaired rubbed wiring to left hand tail light	
08/10/2019	352,403 kms	Air, exhaust R-460	KJP - Internal Workshop
		Further repairs were required to air lines along chassis. Affected by heat from improper exhaust clamp fitment after exhaust manifold repairs (Bill 5/10/19) Remove Hydraulic tank so it can be repaired. Fit new length of air line Clean out tank, fit hydraulic tank, fill with oil	
02/10/2019	349,789 kms	boost leak R-457	KJP workshop - Mark Johnson, KJP workshop - Nathan Hitchcock , KJP workshop - Scott Laburniy
		Trace and repair boost leak Change out boost hose	
27/09/2019	348,611 kms	Electrical, Engine, Warning Triangles R-429	KJP - Internal Workshop
		1 - Heavy duty lead fitted 2 - Fit turbo waste gate control valve. Clean up oil leak at power steering pump and tighten loose fittings 3 - Triangles fitted	
24/09/2019	338,951 kms	Engine R-338	KJP - Internal Workshop
		1 - Fit new exhaust manifold gasket 2. Replaced Starter. 9/9/19 Wheel Alignment completed	
24/09/2019	348,637 kms	New T-20	Ocean Tyres
24/09/2019	348,633 kms	B - B Service S-183	
		Brake Test - PASSED	
14/08/2019	322,873 kms	Air Leaks R-270	
		Checked over truck - no visable leaks found	
06/08/2019	317,713 kms	Exhaust Flex R-268	KJP workshop - Wayne Goodlet
		Remove side cover, removed old flex section - fit new section of flex and refit side cover.	
25/07/2019	311,762 kms	B - B Service S-148	
		Power Steering fluid levels - Pump leaking - tightened fitting Oil level in hubs - Slight leak - tightened bolts Brake Test - PASSED Removed and Replaced Starter motor Solenoid	
17/07/2019	304,867 kms	Mudflap R-209	KJP workshop - Scott Laburniy
		Replaced missing left rear mudflap and chevron Replaced damaged / tearing right rear mudflap	
18/06/2019	293,089 kms	exhaust R-98	KJP workshop - Nathan Hitchcock
		R & R exhaust flex	
14/06/2019	288,689 kms	batteries R-104	KJP workshop - Nathan Hitchcock

Date	Reading / Units	Type / Repairer Notes	Repairer
		R & R battery	
14/06/2019	288,689 kms	batteries R-97 Remove and replace batteries	KJP workshop - Nathan Hitchcock
13/06/2019	288,688 kms	Header Tank R-90 R & R header tank	KJP workshop - Mark Johnson
28/05/2019	277,722 kms	Accessories R-46 Replace driving lights	
22/05/2019	277,722 kms	Air Leak R-142 Remove and Replace desicant filter	
20/05/2019	272,792 kms	Brakes R-9 Brake test - PASSED	KJP workshop - Nathan Hitchcock
17/05/2019	272,792 kms	Lights R-8 T & R wiring back and found a blown fuse	KJP workshop - Mark Johnson, KJP workshop - Nathan Hitchcock , KJP workshop - Scott Laburniy
13/05/2019		brackets, Intercooler, Radiator, sign R-66 remove and replace bumper, intercooler, brackets, sign GLADSTONE RADIATOR SERVICE: Radiator Assembly ADRAD assy. Inc. epoxy repair original radiator & intercooler as spares	
13/05/2019	262,623 kms	Bumper R-29 1. R & R bumper	KJP workshop - Judd Porter
13/05/2019	272,792 kms	C - C Service S-95 Brake test - PASSED	KJP workshop - Judd Porter
07/03/2019	245,889 kms	B - B Service S-13	KJP workshop - Judd Porter
26/02/2019	241,297 kms	New T-41	Ocean Tyres
10/09/2018	152,286 kms	C - C Service S-16	

Signed: _____

Name: _____

Date: _____