



Fleet Number 12  
 Registration Number FAT200  
 Make KENWORTH  
 Model K200 AERODYNE  
 Date of Manufacture Aug-16  
 VIN Number 6F5000000GA456620  
 Accreditation Label No. A040322

DATE	KMS	SERVICE RECORD REPORT	COST OF SERVICE	RUNNING COST	TYRE RECORD	TYRE COST	RUNNING TYRE COST
23/03/18	247,500	SI/SP; RR-C&E-01; Lost orange cover off Rotae Beacon. Fitted with new beacon cover.		\$0.00			\$0.00
26/03/18		SI/SP; RR-C&E-01; Flex Pipe from turbo to exhaust pipe rusted out. Replaced with a new		\$0.00			\$0.00
18/05/18		SI/SP; RR-C&E-01; Centre bar Left to right A-B need wedging up. Light Bar on A left hand		\$0.00			\$0.00
13/06/18	284,593	CHM; Engine Tune up. inv CHM0091	\$591.14	\$591.14			\$0.00
6/07/18	293,909	SP; 'A' Service; All Okay. No Consumables added.		\$0.00	All Ok.		\$0.00
11/07/18	295,619	CHM; Complaint: Engine oil leak. found bolts missing rubber isolators. inv CHM0112	\$428.89	\$1,020.03			\$0.00
4/08/18	303,614	SP; 'A' Service; 4L Engine oil added @ 5.50/L Air leak at first drive booster loose,	\$22.00	\$1,042.03	All Ok. Drive done 102,000km. Steers done 90,000km		\$0.00
17/08/18	308,000	SP; 'B' Service; 46L Engine oil added @ \$5.50 per L	\$264.00	\$1,306.03			\$0.00
8/09/18	315,541	SP; 'A' Service; Tiny weep from RHS rear axle bolts. Found 4 loose mount bolts. All Okay.		\$0.00	2 x New Steers fitted (Old set had done 101,000km) Good years S100's.	\$1,141.80	\$1,141.80
8/09/18		SI; RR-C&E-01; Hub Leak right rear axle. Trailer (B12) Landing foot RHS B trailer. Truck		\$0.00			\$0.00
22/09/18		Diesel Services; (ice pack service) ; Carry out service and minor repairs to icepack. 144hrs.	\$307.98	\$1,614.01			\$0.00
5/10/18	330,685	SP; 'A' Service; 1L Engine oil added. Small weep at seal front diff.	\$5.50	\$1,619.51			\$0.00
27/10/18	344,336	SP; 'A' Service; 3L engine oil added. Faults; Coolant leak @ RHS Engine, Number plate light		\$0.00			\$0.00
14/11/18	355,440	SP; 'B' service; 45L engine oil added. Leaking Front left wheel seal. Removed hub replaced	\$247.50	\$1,867.01	Steers rotated & balanced at Beaurepairs.		\$0.00
15/11/18	355,440	SI/SP; RR-C&E-01; Left hand side front wheel hub leaking out of axle seal. SP; removed		\$0.00			\$0.00
15/11/18	355,400	Beaurepairs; Invoice 6410303750		\$0.00	Beaurepairs; Tyres balanced. Invoice 6410303750. Dated 26.11.18	\$105.82	\$1,247.62
16/11/18		CMV; Seal-Pinion United x 2. Invoice HS0030	\$146.51	\$2,013.52			\$0.00
21/11/18	356,221	SP; PP-C&E-01; pinion & through shaft diff seals leaking. SP & JS; to Replace seals.		\$0.00			\$0.00
21/11/18		CMV; Air Spring AG460 10.5 (part; CS1-1005) Invoice HS0439	\$1,395.99	\$3,409.51			\$0.00
30/11/18	358,990	SP/JS; 'A' Service; No consumables added. General Check over, grease & adjust brakes.		\$0.00			\$0.00
13/12/18	361,458	JS; Tyre rotation		\$0.00	JS; Tyre roatation. 8 x Goodyear G667 (\$570.90 ea) fitted to drive.	\$4,567.20	\$5,814.82
31/12/18	367,074	JS; 'A' Service; No consumables added. LH windsreen cracked. drive brakes getting low.		\$0.00			\$0.00
20/01/19	377,122	JS; 'A' Service; 2L Water Added. 2.5L Engine oil Added (5.50pl.), 1x T4W Globe (No Code	\$13.75	\$3,423.26			\$0.00
1/02/19	383,192	Cummins; Complaint; Wont build up air. Cause; Unloader valve in compressor sticking.	\$3,919.08	\$7,342.34			\$0.00
2/02/19		Bendigo truck centre; Breakdown, remove & replace governor valve. still not working.	\$381.48	\$7,723.82			\$0.00
3/02/19	383,933	SP; 'A' Service; No consumables added. LHS Cab shocker starting to weep.		\$0.00			\$0.00
15/02/19	391,449	Tyre record		\$0.00	JS/SP; 2 x new Goodyear s100's (\$570.90ea) fitted to steer. Comments; 2 x drop in weight I	\$1,141.80	\$6,956.62
18/02/19	392,664	JS; 'A' Service; 4L engine oil added, 12 Litres 46 grade hydro, 1 x H4 globe (no matching		\$0.00			\$0.00
6/03/19	398,991	JS; 'B' Service; Replaced RH Park globe T4W. Faults; Cab shockers leaking. Transmission		\$0.00			\$0.00
29/03/19	411,200	JS; 'A' Service; No consumables added. Cab Shockers leaked out.		\$0.00			\$0.00
24/04/19	423,465	JS; 'A' service; No consumables added. Repairs carried out; Cleaned out adblue system to		\$0.00			\$0.00
6/06/19	424,000	Tyre record		\$0.00	Beaurepairs; Tyres Balanced. remove equal from steer tyres and balance. Inv 6410714350	\$105.82	\$7,062.44
7/06/19	442,000	JS/SI; Fault Repair sheet; Faults found; Hub seat, Re-line, Cab shockers. Repairs made;	\$1,307.77	\$9,031.59			\$0.00
7/06/19	442,000	JS; 'B' Service; Waste gate hose leaking. Replaced Oil & filters (5776 \$59.42 truckline)	\$59.42	\$9,091.01	Front drive tyres rotated side to side		\$0.00
18/07/19	443,731	JS; 'A' Service; No consumables added. Greased & spun turntable bullrace. Adjusted		\$0.00			\$0.00
9/08/19	457,915	JS; 'A' Service; No consumables added. Grease & adjust. Spun ball race.		\$0.00			\$0.00
16/08/19	463,426	JS/SP; 'A' service; No consumables added. General grease & check.		\$0.00			\$0.00
23/08/19	467,310	JS; 'A' Service; No consumables added. Removed drivers side step off of cabin, welded up		\$0.00			\$0.00
5/09/19	473,425	SP; 'A' Service; No consumables added. Tank lights not working LHS. Fixed broken wire on		\$0.00			\$0.00
6/09/19	473,626	Haulmark; Install 'Door Ajar' Park brake alarm. install park brake door alarm. supplied and	\$598.04	\$9,689.05			\$0.00
27/08/19		CHM; Parts supplied: U0011 - Starter motor solenoid \$49.50 Inv 0902	\$49.50	\$9,738.55			\$0.00
17/09/19		SI; RR-C&E-01; Starter Motor Fault; JS; Replaced Starter motor. Repaced 1 x Low charge		\$0.00			\$0.00
18/09/19	480,618	JS; Fault Repair Sheet; Faults found; Starter motor faulty. Battery Box Broken. Repairs	\$563.19	\$10,301.74			\$0.00
18/09/19	480,618	JS; 'B' Service; Replaced 1 x battery. Replaced oil & filters. Replaced Fuel filter.		\$0.00	Steers Due soon.		\$0.00
8/11/19		JS; 'A' Service; No consumables added. Replaced radiator cap (CHM Invoice) Replaced		\$0.00			\$0.00
23/11/19		SP; Fault repair; Fault found; Oil temp fault. Repairs made. Replaced oil temp sensor.		\$0.00			\$0.00
25/11/19	510,888	SI; RR-C&E-01; Idler Pulley on main belt failure (Reported to Sam) New belt and pulley		\$0.00			\$0.00
26/11/19	509,230	JS/SP; 'A' service; 2L water added. Faults found; A/C tensioner needs replacing - Ordered- Cummins; Part only, 1 x 4954905 - sensor temp (coolant) Inv 8395665	\$31.43	\$10,333.17			\$0.00
4/12/19	511,540	SI; RR-C&E-01; Engine oil temp reading high and low. New oil sensor needed. (See fault		\$0.00			\$0.00
5/12/19	511,498	JS; Fault Repair Sheet; Faults found; Icepack fault, stalling. Oil temp high, engine. Repairs		\$0.00			\$0.00
31/12/19	517,714	JS/SP; 'A' Service; Replaced diff oils and filter (no part number or L's). Replaced G/Box oil		\$0.00			\$0.00



























\$0.00  
\$0.00  
\$0.00  
\$0.00

\$0  
\$0  
\$0  
\$0