

Edmonton Main: 18020 - 118 Avenue, Edmonton, Alberta, T5S 2G2

P 780.483.6666 TF: 800.252.7981 F 780.484.2173

Edmonton West: 11603 - 181 St. Edmonton, Alberta, T5S 2K5

P. 780.483.6666 TF 800.252.7981 F: 780.484.2173

Fort McMurray: 340 MacKenzie Boulevard, Fort McMurray, Alberta, T9H 4C4

P. 780.715.3627 TF 866.715.5111 F 780.715.3657

Grande Prairie: 12020 - 101 Avenue, Grande Prairie, Alberta, T8V 8B1

P. 780.539.9991 TF: 888.538.5414 F: 780.539.9902

www.stahlpeterbilt.com

Sold To: FLUIDPRO OILFIELD SERVICES LTD 33095:A

CHAD MCFARLAND 9701-99 STREET CLAIRMONT, AB T8X 5A8

780 778-4380

Ship To:

FLUIDPRO OILFIELD SERVICES

LTD

CHAD MCFARLANE

3764B-30ST

WHITECOURT AR T75 042

MS15993

11-08-23

CUSTOMER INVOICE

2019 KENWORTH / T800B	200//200457	Ol Code Lie	1.46608	Mileage	UnitState
Delivery Missage Delivery Date	3WKDP4EX	8LF969143		277783K	401
03-19-20	10394.0	V15 /	80225185	Transport in	e Serial #

F11550 10-17-23 / 11:07AM 10-18-23 EJM*SLN Tax ID Date:

1 CHECK ENGINE LIGHT

Performed download and found active turbo speed codes logged. Tested speed sensor resistance and its within spec. Tested sensor voltage from ecm and found no 5v. Removed harness from behind the oil filter to inspect - had to cut back the loom and found damaged wiring. Repaired harness and then retested - found no 5v supply. Removed ecm connector and tested voltage at ecm pins 5v found. Checked ecm pin drag - all pins are tight. Customer wanted to replace harness now. Replaced engine harness. Unit had intake nox sensor fault also. Checked voltage and resistance on engine harness all in spec. Replaced intake nox sensor. Unit also had dpf faults logged and black stacks. Removed dpf step assembly and bracket to access dpf. Disassembled dpf and found it breeched but doc is still good. Blew out doc and cleaned all mounting surfaces and assembled new dpf. Had to replace the dpf differential pressure sensor and tubes as all the tubes broke off. Once dpf was together, cleaned the stacks, reset all dpf filters in insite and performed regen on unit. No faults returned. Cleared all codes

> TOTAL LABOR TOTAL PARTS

\$3,168.12 \$8,523.69

Qty	Part Number	Description	List	Unit	Extended	
1 1 3 3 1 1 1 1 10	3687930RXCUM 5484117 N9267001 12110293 CN26250 CN50200 CN41100 5643241CUM 5633757CUM LP34216 2880215CUM 5507314CUM CT03316 CT05512	SENSOR, NI HARNESS, E SENSOR AS CONNECTOR TERMINAL- SEAL-PACK RETAINER- KIT, SPEED KIT, PART CLAMP-V, GASKET, A KIT, PRES TIE-CABLE TIE-CABLE	\$1,407.66 \$2,745.38 \$702.14 \$10.28 \$7.35 \$7.35 \$7.76 \$595.11	\$938.48 \$1,830.48 \$468.48 \$6.90 \$2.45 \$5.20 \$396.79 \$4,357.79 \$64.59 \$28.79 \$402.99	\$938.48 \$1,830.48 \$468.48 \$6.90 \$7.35 \$7.35 \$5.20 \$396.79 \$4,357.79 \$64.59 \$28.79 \$402.99	

2	*****ROAD	SERVIC	E TRAVEL	INFOR	MATION****	* *		
					INFORMATION		ALL	ROAD
	SERVICE WAR							
	START LOCA	TION:		END	LOCATION.			



Sold To:

33095:A

Edmonton Main: 18020 - 118 Avenue, Edmonton, Alberta, T5S 2G2

P; 780.483.6666 TF; 800.252.7981 F; 780.484.2173

Edmonton West: 11603-181 St. Edmonton, Alberta, T5S 2K5

P: 780.483.6666 TF: 800.252.7981 F: 780.464.2173

Fort McMurray: 340 MacKenzle Boulevard, Fort McMurray, Alberta, T9H 4C4

P: 780.715.3627 TF: 866.715.5111 F: 780.715.3657

Grande Prairie: 12020 - 101 Avenue, Grande Prairie, Alberta, TSV 8B1 P: 780.539.9991 TF: 888.538.5414 F: 780.539.9902

www.stahlpeterbilLcom

FLUIDPRO OILFIELD SERVICES LTD CHAD MCFARLAND

9701-99 STREET CLAIRMONT, AB T8X 5A8 780 778-4380

Ship To: FLUIDPRO OILFIELD SERVICES

LTD

CHAD MCFARLANE

3764B-30ST

WHITECOURT, AB T7S 0A2



OUS FORMER HAVOID

			Will your Services and the services	Control Control	/1 1 <u>%.</u>		
2019	KENWORTH / T800B		X8LF969143			9777004	Landon State
	Jely Dale	a managar	The Control of the Co			277783K	401
	03-19-20	10394.0		15 / 80225185		10 (2 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1	ligias a arab
				(AO) OUZZOJOO			/
	tone				n a s	and the second second	S COSTA TENEDO INCORPORA
			F11550	10-17-23 /		10-18-23	C dayou s
		Tax ID Date	Tax ID:		i rioi cuite	10-10-20	EJM*SLN
	START TIME:	_ END TIME:					
	START ODOMETER:	END ODOME	TER:				
	Travel from base to custom	er location	in Whiteco	urt and r	etuna te		
				or c print i	etuin L	Juase	
	TOTAL LAB	∩R			, 4		
	THE TENED MANEET TOUR				\$72	2.15	
		м	TOCELL ANDONE	c cuppie	- 4		
_		Pi	ISCELLANEOU:	2 20bbrie	S \$311	1.22	
	G.S.T REG. NO. 870331	 105 BT0004				··· ;	
	4.5.1 1EG. NO. 5/9331	TOO KIDDOL	5 % OF \$:	12,725.18	= \$6	36.26	
		CUST MECH		4510.91	\$3,890	1.27	
		P&A-TRK R		4610.91		1.69	
		OTHER SUP	P-SRV-CHG'D	611D.91	\$311	22	
		G.S.T. 876	9331105 RT00	302215.1	\$636	.26	
	33095:A	CHARGE		2200.1	\$13,361		
					·	,	
		Terms an	d Conditions:				
Acknowledgment; L for work listed above cally to bind the mene	the undersigned owner or representative, entrowindge the indebtoir s, stimp with the purchase and installation of any necessary parts and a	eas related to the repair materials. I confirm I have	Mercety CorelidateSome is designated for warranty	s; Stabil Paters il line, considerations. If the r	will submit a worse nanufacturer reject	nty claim to the menufacturer for a a the claim or a portion of the clair	ny porton of this repekt t n, the owner shall pay the

the authority to bind the conner.

Payment Terms: Payment for repeirs are due upon receipt of unit unions charged to contorner's account. Payment of account is due in his by the 15° day of the month following the statement date. Unpuid belances will be charged interest of 2% per month companied monthly (26.82% per ensure).

State month companied monthly (26.82% per ensure).

Grange Response Lien: By adming below by on acknowledge and agree that the vehicle described above is subject to a Garage Keepers' Lien in favor of State Pensishtion, for the full dollar amount of repeirs, parts, accessories, materials, and services provided by State Pensishting, as permitted under the Garage Keepers' Lien Act (Alberta), as amended from time to time.

is designated for warmety considerations. If the manufacturer rejects the claim or a portion of the claim, the owner shall pay that person which is rejected in accordance with the Psyment Terms and out above.

Warmenty Limitation: Religious in the requirement bolow, all repair and services carry a 38 day warmenty from the date Stabil Federal's limit or completed the work. The owner must advise Stabil Federal's limit any warmenty claim within 5 days of the fallure date. Central Peris, products, accessories, materials, and other Rems used in completing the typic and service and may be manufactured and supplied by third perion. The quality and workmentally of such terms are smirely contained the control of Stabil Peteral's limit, and Chair Peteral's limit, makes no warmentee, whether expressed, implied, statutory, or otherwise, including any warment of monthembally or of fitness to a particular purpose with respect to such forms.

Responsibility for Vehicle and Contents: Stabil Paterials for, is not responsible for loss or damage to the vehicle, or to procless left in vehicles, in case of fare, that, vandation, or sonderd.

Print Name:	Authorized Signature:	Dale:
Drivers License:		



~

Sold To:

33095:A

Edmonton Main: 18020 - 118 Avenue, Edmonton, Alberta, TSS 2G2

P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Edmonton West: 11603 - 181 St. Edmonton, Alberta, TSS 2K5 P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Fort McMurray: 340 MacKenzie Boulevard, Fort McMurray, Alberta, T9H 4C4 P: 780.715.3627 TF: 866.715.5111 F: 780.715.3657

Grande Prairie: 12020 - 101 Avenue, Grande Prairie, Alberta, T8V 8B1

P: 780.539.9991 TF: 888.538.5414 F: 780.539.9902

www.stahlpeterbilt.com

FLUIDPRO OILFIELD SERVICES LTD CHAD MCFARLAND

9701-99 STREET CLAIRMONT, AB T8X 5A8 780 778-4380

Ship To:

FLUIDPRO OILFIELD SERVICES

LTD

CHAD MCFARLANE

3764B-30ST



USTOMER INVOICE

MATCHANGED WHITECOURT, AB 178 0A2	
2019 KENNODTU JERRO	
	Unitistical
Delivery Mileage Delivery Date, Epiglical State	401
Carlo co	401
Delivery Delive Engine Hours Engine Model / Serial # 147378K 03-19-20 5625.0 X15 / 80225185 Transmission	∉ dode/Seria #
71101 00220100	
	1

the state of the s		
11.00	The second secon	
Mano	TO A STATE OF THE	// lime
*	CE400	
	F5122 05-17-22 / 1	03:43PM 05-18-22 E 144C(4)
	7 ID to	05-18-22 EJM*SLN
1 CUECU HARMAN	Tax to page: Tax ib.	1011 0011

CHECK ENGINE LIGHT ON - DEF PUMP Performed download, opened eds case for 1682, checked for any related faults - none found. Inspected def system for any damage or crystal build up - all ok. Used insite and tried to run def leak test - pump runs but no pressure built. Def tank level is full. Removed the def suction line and blew air through the line - its free and clear. Reconnected to tank and pressured up a bit with air and had def coming out suction line. Performed suction test on def pump and it failed @ 0 inhg. Removed the fitting on inlet to pump - no debris or blockage found. Failed pump detected. Replaced def pump, removed electrical, def line, and coolant line to pump. Mounted new pump and hooked up all plumbing and electrical. Primed pump and performed def leak test again and you can hear the pump prime but not reading on def pressure on insite. Removed dpf step assembly to access the def valve, removed the pressure line and found lots of def in line and flowing. Put gauge in pressure line and measured at 130psi. Def valve is not reading. Replaced def dosing valve and ran leak test after repair - 130psi reading and no def leaks. Tied up all harnesses and lines 15524051 C52387

>> WARRANTY PENDING <<

Qty Part Number Description 1 5578983CUM KIT, 2017 1 5506956RXCUM PUMP, DOSE 2 *****ROAD SERVICE TRAVEL INFORMATION****** TECHNICIAN MUST COMPLETE BELOW INFORMATION FOR ALL ROAD SERVICE WARRANTY REPAIRS START LOCATION:____ _ END LOCATION:_

START TIME: __ END TIME:

START ODOMETER:____ END ODOMETER:

Travel from Whitecourt to Edmonton for parts and return back to Whitecourt.

Starting Mileage: 437939km Ending Mileage: 437374km TOTAL LABOR

\$843.80

3 CHECK REASON FOR BLACK STACKS Carried on diagnostics with eds - no related faults found. Ecm calibration is up to date @ HD10386.09. Failed dpf detected. Removed



33095:A

Edmonton Main: 18020 - 118 Avenue, Edmonton, Alberta, T5S 2G2 P: 780,483,6666 TF: 800,252,7981 F: 780,484,2173

Edmonton West: 11603 - 181 St. Edmonton, Alberta, T55 2K5 P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Fort McMurray: 340 MacKenzie Boulevard, Fort McMurray, Alberta, T9H 4C4 P: 780.715.3627 TF: 866.715.5111 F: 780.715.3657

Grande Prairie: 12020 - 101 Avenue, Grande Prairie, Alberta, T8V 8B1

P: 780.539.9991 TF: 888.538.5414 F: 780.539.9902

www.stahlpeterbilt.com

FLUIDPRO OILFIELD SERVICES LTD

CHAD MCFARLAND 9701-99 STREET CLAIRMONT, AB T8X 5A8 780 778-4380

Ship To: FLUIDPRO OILFIELD SERVICES

LTD

CHAD MCFARLANE 3764B-30ST

<u>Customer invoic</u>

SERVICE INVOICE#

MS13038

DATE

05-26-22

Year Make / Model	WHITECOURT AR 770 And	US OWER INVOICE
2019 KENWORTH / TROOP	WHITECOURT, AB T7S 0A2 VIN 3WKDP4EX8LF969143 Gnging Hours	
Delivery Mileage Delivery Date	3WKDP4EX8LF969143	Mileage Unit/Stock
03-19-20	### ##################################	147378K 401
	5625.0 X15 / 80225185	transmission Model/Serial #
Menio	X15 / 80225185	
	BO N = 1 = 10 = 10 = 10 = 10 = 10 = 10 = 1	

P.O. Number A. Open Date / Time-Service Writer F5122 05-17-22 / 03:43PM

step, mounting bracket to frame for access. Removed temp sensors and differential pressure tubes - had to heat them cause they were seized. Disassembled doc - no face plugging on inlet. Removed sensor brackets on dpf and removed clamps from dpf. Clamps were seized as well had to cut them off. Removed breached dpf. Cleaned all surfaces, pneumatically cleaned doc and inspected for cracks - all ok. Mounted new dpf and cleaned doc with gaskets and clamps - torqued to spec. Reinstalled all sensors in doc and dpf along with the diff pressure tubes. Reinstalled step brackets and step assembly cover. Performed dpf reset and performed regen on unit to make sure no exhaust leaks or further issues. No faults returned. C52387

Qty Part Number >> WARRANTY PENDING << Description 1 5633757 KIT 1 2880215CUM GASKET, A 1 LP34216 CLAMP-V. 6 CT05512 TIE-CABLE

4 CHECK ENGINE LIGHT ON - HEATED LINES

During check engine repairs found the def suction line tip is broken and needs to be replaced as it wont seat properly and found a def leak from the pressure line on the valve - had to replace def line from

NOTE: **** If customer would like to pick up these lines they could submit them to Kenworth for possible parts warranty as unit still has emissions coverage on them****

TOTAL LABOR \$464.09 TOTAL PARTS \$919.07

Oty Part Number Description List Unit Extended 1 M50-6038-5520950 HOSE ASSY \$464.09 \$307.99 \$307.99 1 M50-6039-3233150 HOSE ASSY \$886.56 \$598.48 \$598.48 6 CT03316 TIE-CABLE \$2,70 \$0.45 \$2.70 6 CT05512 TIE-CABLE \$9.90 \$1.65 \$9.90

MISCELLANEOUS SUPPLIES \$104.63



Sold To:

33095:A

Edmonton Main: 18020 - 118 Avenue, Edmonton, Alberta, TSS 2G2

P: 780.483.6566 TF: 800.252.7981 F: 780.484.2173

Edmonton West: 11603 - 181 St. Edmonton, Alberta, TSS 2K5

P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173

Fort McMurray: 340 MacKenzie Boulevard, Fort McMurray, Alberta, T9H 4C4

P: 780.715.3627 TF: 866.715.5111 F: 760.715.3657

Grande Prairie: 12020 - 101 Avenue, Grande Prairie, Alberta, T8V 8B1 P: 780.539.9991 TF: 888.538.5414 F: 780.539.9902

www.stahlpeterbilt.com

FLUIDPRO OILFIELD SERVICES LTD CHAD MCFARLAND

9701-99 STREET CLAIRMONT, AB T8X 5A8

780 778-4380

Ship To: FLUIDPRO OILFIELD SERVICES

LTD

CHAD MCFARLANE

3764B-30ST

WHITECOURT AR TTO ALO



Charles to the Control of the Contro	
CUSTOMER INVO	
CHICAGO COMPONE	
CUO CUMER IN MO	
	200

	1.41	Darwellene)		THILLOUGHT, AB 175 UAZ			
	2019	METO//foligi KENWORTH / TROOP	<u> </u>	License			
			1 3000000000000000000000000000000000000	1443	Mileage	a Unitsise	1
	Delivery Mile	age Delivery Date			1.472704/		Ĺ
- 1	ł		Erigine Hours	Engine Model / Serial#		401	1
•	£	03-19-20	5625.0	VAF	Transmission	Model/Serial #	
			1 020,0	X15 / 80225185			

,	Discourage and the second seco	
1	V runte	CONTRACTOR OF COMPANY OF THE CONTRACTOR OF THE C
	Mono P.O. Attentory F5122	2.01(4.0)
	F5122	05-17-22 / 03:43PM
		05-17-227 03:43PM 05-18-22 EJM*SLN
	Tax ID Date: Tax ID:	LOW CENT
	G.S.T REG. NO. 878331105 PTOOP	

33095:A

5 % OF \$2,331.59 =

\$116.58

CUST MECH LBR-TRK 4510.91 \$1,307.89 P&A-TRK RO-MECH \$919.07 4610.91 OTHER SUPP-SRV-CHG'D 611D.91 \$104.63 G.S.T. 870331105 RT0002215.1 \$116.58 CHARGE 2200.1 \$2,448.17

Terms and Conditions:

Repair Acknowledgment: I, the undersigned owner or representative, authorwiedge the indebtedness related to the repair and service work fisted above, along with the purchase and installation of any necessary parts and materials. I confirm I have the authority to bind the owner.

Payment Terms: Payment for repairs are due upon receipt of unit praiess charged to customer's account. Payment of account is due in hall by the 15° day of the month following the statement date. Unpaid balances will be charged interest of 2% per month compounded monthly of 2.6% per annum.).

Garage Kaupers Liant By spring below you acknowledge and agree that the vehicle described above by scriptct to a Garage Kaupers Liant By spring below you acknowledge and agree that the vehicle described above by scriptct to a Garage Kaupers Liant By start By Bertalitt Inc., for the hall dollar amount of repairs, parts, accessories, materials, and services provided by Stahl Paterbilit Inc., as permitted under the Garage Koepers' Lien Act (Aberta), as amended from time to time.

Warranty Considerations: Stahl Peterbilt inc. will submit a warranty claim to the manufacturer for any portion of this repair that is designated for warranty considerations. If the manufacturer rejects the claim or a portion of the claim, the carrier shall pay that portion which is rejected in accordance with the Payment Terms as load above. Warranty Limitation: Subject to the requirement below, all repair and services carry a 30 day warranty irom the dote Stahl Peterbilt inc. or day warranty claim within 5 days of the failure data. Certain Parts, products, accessories, materials, and other items used in completing the repair and service work may institute and subject by third parties. The quality and workmanship of such items are entirely outside the control of Stahl Peterbilt inc. and Stahl Peterbilt inc. makes no warranties, whether appreciate, implied, statisticy, or otherwise, including any warranty of marchantability or of siness for a particular purpose with respect to such items. Responsibility for Validie and Contents Stahl Peterbilt Inc. is not responsible for loss or damage to the vehicle, or to articles led it vehicles, in cast of fire, theft, vanidation, or accident.

Print Name: Authorized Signature:	Dale:
Drivers License:	. Maid.