

Service Log Report

From: Feb-12-2022 To: Aug-12-2026

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
Mar-26-2025	OH25001	BARNONE	8891			Unit 504 11502 hrs installed new idler
Apr-11-2025		ALBRIGHT REFRIDGERATIO N	83897			unit 504 put on gauges,has gas,good airflow unit 701 put on gauges,has gas,good airflow unit 412 put on gauges has gas cycles well unit 401 put on gauges,has gas,good airflow unit 409 put on gauges,has gas,good airflow
May-01-2025	OH25001	CHARLIE GEERNAERT	12586		2.5	remove cylinder from machine at candle rd
May-02-2025	OH25001	CHARLIE GEERNAERT	12589		4.5	travel to candle rd install lift cylindes
May-03-2025	OH25001	CHARLIE GEERNAERT	12595		1.5	look for hyd oil leak on head check head pressure travel to diba dr
May-05-2025	OH25001	CHARLIE GEERNAERT	12598		3	pick up parts travel to candle rd change aclator cap on head
May-06-2025	OH25001	CHARLIE GEERNAERT	12706		4.5	wait for machine to set out of mud 300 hr service at candle rd switch relays around for head,fix some wiring going to the relays travel to the shop

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
May-08-2025	OH25001	CHARLIE GEERNAERT	12712		4.5	take off g for valve bank took at pressures for auxilery pump for head and valve for head on the machine travel to town to pick up parts at resources and finning
May-12-2025	OH25001	CHARLIE GEERNAERT	12714		8	pick up parts travel to the candle rd look at pressures on head and machine look at and inspect spool valve for heas wait for marlon and phone waratah finning
May-12-2025	OH25001	BARNONE	9124			Unit 504- measure main pump pressure and pilot pressure
May-13-2025	OH25001	CHARLIE GEERNAERT	12718		2.5	travel to the candle rd check pressure on head and wiring blow out rod
May-16-2025	OH25001	CHARLIE GEERNAERT	12752		2.5	travel to candle rd block change solinoid for saw section
May-20-2025	OH25001	CHARLIE GEERNAERT	12755		1.5	change acwator cap at the candle block
May-26-2025	OH25001	CHARLIE GEERNAERT	12775		1.5	change filter cylindes at the candle rd block
May-29-2025	OH25001	CHARLIE GEERNAERT	12616		2	travel to trailer tire block change cap
Jun-03-2025	OH25001	CHARLIE GEERNAERT	12958		4.5	travel to trailer tire block 600hr service tighten top saw motor bolts

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
						travel to shop
Jun-04-2025	OH25001	CHARLIE GEERNAERT	12828		3	travel to trailer tire block change top saw parts
Jun-08-2025	OH25001	CHARLIE GEERNAERT	12838		3	travel to 2.5km change accelerator cap,make and change feed wheel hose
Jun-09-2025	OH25001	CHARLIE GEERNAERT	12845		2	change buttons for feed wheel cylinder at 2.5km central ridge see why feed cylinder sticking closed
Jun-10-2025	OH25001	CHARLIE GEERNAERT	12848		3	adjust pressures for head at 2.5km central ridge change coil for feed cylinder change fitting for measure wheel sensor
Jun-17-2025	OH25001	CHARLIE GEERNAERT	12909		4.5	travel to 2.5 km central ridge bolt up stump pan travel to camp
Jun-19-2025	OH25001	CHARLIE GEERNAERT	12913		2.5	travel to 2.5 km central ridge change measure wheel sprocket change accumulator for head
Jun-20-2025	OH25001	CHARLIE GEERNAERT	12918		3	at to 2.5 km central ridge change accumulator for head change hydraulic hose protecting electrial line going to head go to camp

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
Jun-21-2025	OH25001	CHARLIE GEERNAERT	12919		1	travel to 2.5 km central ridge change accumulator for head tighten tracks
Jun-22-2025	OH25001	CHARLIE GEERNAERT	12924		2	travel to 2.5 km central ridge drill and boom pin keepers bolt hole put new bolts and keeper on
Jun-23-2025	OH25001	CHARLIE GEERNAERT	12878		4.5	travel to 2.5 km central ridge remove top saw assembly weld top saw mount for saw cylinder
Jun-24-2025	OH25001	BARNONE	9357			Unit 504_ 12509hrs, Lower lift cylinders had excessive play
Jun-27-2025	OH25001	BARNONE	9357			unit 504, 1257hrs, capped line for lift cylinder removed pins and cut out lower bushings, pressed in new bushings
Jun-30-2025	OH25001	BARNONE	9414			12605 hrs Unit 504 - Found exhaust end was bent partially close. Bent back open. Cleaned air filter. Completed cylinder cut out test.
Jul-02-2025	OH25001	CHARLIE GEERNAERT	13152		2	travel to 2.5km central ridge change grab arm cylinder
Jul-02-2025	OH25001	BARNONE	9414			unit 504- Trouble shot why measuring wheel would intermittently come down
Jul-04-2025	OH25001	CHARLIE GEERNAERT	13159		3.5	travel to 2.5km central ridge diagnose oil leak coming from fan hub help take hub out with tim

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
						weld pin keeper for lift cylinders
Jul-04-2025	OH25001	BARNONE	9414			Unit 504 Looked at oil leak. Found fan hub was leaking. Found it leaked so hyd oil from actuator pressurized hub and pushed out seal.
Jul-09-2025	OH25001	BARNONE	9447			unit 504- picked up parts and disassembled fan hub, replaced bronze seal retainer
Jul-10-2025	OH25001	CHARLIE GEERNAERT	13174		3	travel to 2.5km central ridge check hub oil for fan wash the engine off with degreases and fire pump
Jul-11-2025	OH25001	CHARLIE GEERNAERT	13051		3.5	travel to 2.5km central ridge check oil level on fan hub weld keeper for lift cylinders pin
Jul-15-2025	OH25001	CHARLIE GEERNAERT	13062		0.5	at 2.5km central ridge check fan hub oil
Jul-17-2025	OH25001	CHARLIE GEERNAERT	13082		5.5	at 2.5km central ridge change and build hose for head 1200hr service
Jul-23-2025	OH25001	CHARLIE GEERNAERT	13095		2.5	remove #20 hose at 2.5km central ridge install #20 hose when frozer got back from town
Jul-25-2025	OH25001	CHARLIE GEERNAERT	13099		5	travel to 2.5km central ridge see what shorting out waratah fuse

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
						change electrical line going from rotax to the head
						change battery on pickup
Jul-28-2025	OH25001	CHARLIE GEERNAERT	13105		2	at rigel pit
						change cab sir filter
						weld grab arm knives
						put bolt in top saw motor shaft
Jul-30-2025	OH25001	CHARLIE GEERNAERT	13109		1.5	travel to rigel pit
						blow out rad
						travel to shop
Jul-31-2025	OH25001	CHARLIE GEERNAERT	13110		2.5	travel to rigel pit
						tighten keeper bolts on head
						put track back on with loader
Aug-04-2025	OH25001	CHARLIE GEERNAERT	12787		1	at rigel pit, change joystick shell
Aug-12-2025	OH25001	CHARLIE GEERNAERT	12865		4.5	see if rails are bad with finning
						take off hand rail to weld it
						install back on machine
						weld top knife chain
						travel to camp
Aug-13-2025	OH25001	CHARLIE GEERNAERT	12866		2	travel to rigel pit
						300hr service machine
Aug-15-2025	OH25001	CHARLIE	12874		5	pick parts at brandt

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
		GEERNAERT				and get oxygen from linde air tavel to rigel pit see why main saw chain not working put top saw nolt in cut off mongled
Aug-16-2025	WC25001	CHARLIE GEERNAERT	13228		2	at rigel pit see whats wrong with main saw oil, order parts
Aug-20-2025	WC25001	CHARLIE GEERNAERT	13239		3	travel to the block near kokwa river change chain oil parts for main saw
Aug-21-2025	WC25001	CHARLIE GEERNAERT	13243		4	travel to block near kokwa river, change o-rings for chain tensioner travel to trailer to organize filters and order parts
Aug-25-2025	WC25001	CHARLIE GEERNAERT			4	at willie rd fix wiring going to attachment filter weld clevis onto machine blow rod out
Aug-26-2025	WC25001	CHARLIE GEERNAERT			6	travel to willie rd see why top saw out wash machine
Aug-27-2025	WC25001	CHARLIE GEERNAERT			504	verify why top saw saying its out order parts
Aug-28-2025	WC25001	CHARLIE GEERNAERT	1		3.5	install top saw proximity sensor at willie rd see why measuring not working

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
Sep-04-2025	OH25001	CHARLIE GEERNAERT	1009	13397	2.5	600hr service at 17km archie way
Sep-08-2025	OH25001	CHARLIE GEERNAERT	1020		1	blow rod out at 17km archie
Sep-09-2025	OH25001	BARNONE	9754	13381		inspected machine and made a list for recommended repairs
Sep-11-2025	OH25001	CHARLIE GEERNAERT	1033	13533	2	travel to 15km archie blow rod out, change two o-rings on head
Sep-12-2025	OH25001	CHARLIE GEERNAERT	1035	13549	4.5	travel to 15km archie wash rod and machine change hyd filter weld fuel nozzel holders
Sep-17-2025	OH25001	CHARLIE GEERNAERT	16056	13600	1.5	travel to 15km archie blow out rod tighten tracks
Sep-25-2025	OH25001	CHARLIE GEERNAERT	15957		2.5	travel to 15km archie way 300hr service travel to shop
Sep-27-2025	OH25001	CHARLIE GEERNAERT	15958	13700	3.5	travel to 15km archie install pin for rod end lift cylinder
Sep-28-2025	OH25001	CHARLIE GEERNAERT	15963	13707	3	at 15km archie check pressures in head

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
						change o-ring for #20 hose going to head travel to he shop and remove slidders off 1002buncher remove master links off old forwarder tracks
Sep-29-2025	OH25001	CHARLIE GEERNAERT	15964	13712	4	pick up parts travel to 10km archie diagnose feed arm and grab arm cylinder bypassing go to trailer change cylinders change grease line for lift cylinder
Oct-01-2025	OH25001	CHARLIE GEERNAERT	20101	13754	1	at 10km archie weld track pin
Oct-03-2025	OH25001	CHARLIE GEERNAERT	20104	13754	4	drop service truck at kaltire travel to 7.5km archie change feed wheel cylinder
Oct-09-2025	OH25001	TIM NEUSTAETER	15987	13820	2	checked why main saw was not oiling add parts list and ordered oiler seals
Oct-14-2025	OH25001	CHARLIE GEERNAERT	20118	13870	5	travel to 15km archie change grab arm cylinder look to see what is leaking by rotate measure two lines on boom make one at the trailer
Oct-14-2025	OH25001	TIM NEUSTAETER	15992	13870	4.5	found oil leaks on machine bent back tool box lid welded cracks on head

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
Oct-15-2025	OH25001	CHARLIE GEERNAERT	20119	13870	4	pick up cylinder travel to 15km archie change hose on top of boom shovel tracks walk machine to road
Oct-16-2025	OH25001	TIM NEUSTAETER	20226	13871	10	disassembled main sa oiler system resealed and replaced seals reassembled
Oct-16-2025	OH25001	CHARLIE GEERNAERT	20051		3.5	travel to 17km Amerada check track pads for loose bolts measure hose to build
Oct-17-2025	OH25001	TIM NEUSTAETER	20227	13871	12	replaced spocket left side removed track links removed idler and cleaned out track from to allow idler to go in
Oct-17-2025	OH25001	CHARLIE GEERNAERT	20053	13872	7	travel to 17km Amerada help Tim take link out and change sprocket change hose on head and hose on carrier travel to shop
Oct-20-2025	OH25001	TIM NEUSTAETER	20228	13872	6.5	replaced right side sprocket remove 1 link from rails
Oct-25-2025	OH25001	TIM NEUSTAETER	20235	13923	8	machine has stuck pulled machine out pulled service truck out of
Oct-27-2025	OH25001	TIM NEUSTAETER	20236	13934	3.5	replaced hyd line in head
Nov-01-2025	OH25001	CHARLIE GEERNAERT	20124	13998	5	travel to 7km pan can 1200hr service

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
Nov-02-2025	OH25001	CHARLIE GEERNAERT	20125		2.5	travel to 7km pan can change bolts and tighten track bolts
Nov-03-2025	OH25001	CHARLIE GEERNAERT	20072	13977	4.5	travel to 7km pancan to change a hydraulic hose walking into the block
Nov-06-2025	OH25001	CHARLIE GEERNAERT	13927	13994	3.5	travel to North fork rd put new Joystick shell on
Nov-07-2025	OH25001	TIM NEUSTAETER	20250	13996	3	trouble shot HYD issue feed wheel RHS delayed
Nov-08-2025	OH25001	TIM NEUSTAETER	20251	13996	3	trouble shot feed wheel issue fend solind valve had restricted passure order solinard installed valve
Nov-11-2025	OH25001	TIM NEUSTAETER	20253	14044	3	welded hand rail trouble shot top saw issue
Nov-12-2025	OH25001	CHARLIE GEERNAERT	13935		1	travel to 4km husky put new plexy glass covering lights on cab
Nov-12-2025	OH25001	TIM NEUSTAETER	20255	14053	5.5	trouble shot top saw malfunction installed measuring wheel guard
Nov-15-2025	OH25001	CHARLIE GEERNAERT	13950		1.5	at 4km husky change top saw return solinoid put pin in grab arm connecting link
Nov-18-2025	OH25001	CHARLIE GEERNAERT	20028	14143	5	at cutbank block take grab arm off

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
						extract bolt for pin keeper make new threads change pin for connecting link
Nov-25-2025	OH25001	CHARLIE GEERNAERT	20033		3.5	travel to pams lane change bar return hose on head
Nov-25-2025	OH25001	TIM NEUSTAETER	20265	11586	2	replaced hyd line in head
Nov-26-2025	OH25001	TIM NEUSTAETER	20268	14190	5	fixed oil leak in head trouble shot no measurement
Nov-27-2025	OH25001	TIM NEUSTAETER	20269	14190	4.5	repaired multiple wires
Nov-30-2025	OH25001	CHARLIE GEERNAERT	20040	14410	2.5	at willie rd loosen tracks check fan hub oil tighten keeper bolt on head
Dec-03-2025	OH25001	CHARLIE GEERNAERT	20505		2.5	travel to end of willie 300hr service see if w can find any broken wire underhead
Dec-06-2025	OH25001	TIM NEUSTAETER	20128	14316	3	replaced hyd line in head
Dec-09-2025	OH25001	TIM NEUSTAETER	20130		3	removed HYD, order new installed gyd line
Dec-10-2025	OH25001	CHARLIE GEERNAERT	20511		1.5	travel to okm willie remove hose of head, travel to town

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
Dec-10-2025	OH25001	TIM NEUSTAETER	20133	14362	1	replaced hyd line
Dec-12-2025	OH25001	CHARLIE GEERNAERT	20513	14700	1.5	travel to 0km willie see where leaking coming from change hose going to head
Dec-13-2025	OH25001	CHARLIE GEERNAERT	20516	1477	2.5	change pilot hose and see what is leaking on head
Dec-14-2025	OH25001	CHARLIE GEERNAERT	20517	14388	2	travel to 0km willie install hose for tilt cyl
Dec-14-2025	OH25001	CHARLIE GEERNAERT	20518		2.5	travel to 0km willie see what's going on with head tighten bolt for head modual
Dec-21-2025		FINNING	6525	14450		REPLACE TRACK RAILS SPROCETS AND ROLLERS
Jan-02-2026	OH25001	CHARLIE GEERNAERT	20577		3	travel to conoco rd see why heat not working blow out heater core with air
Jan-16-2026	OH25001	CHARLIE GEERNAERT	20601		1	at 11.5km hammer change accumulator on head tighten fitting on head
Jan-23-2026	OH25001	TIM NEUSTAETER	20182	14758	3	fixed hyd leak
Jan-26-2026	OH25001	CHARLIE GEERNAERT	20611		4.5	travel to km see where head leaking build hose travel back to put in on
Jan-28-2026	OH25001	CHARLIE GEERNAERT	20613		4	pick up parts travel to 19.5km hammer change #20 hose, tight bolts for top saw motor

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
Jan-29-2026	OH25001	CHARLIE GEERNAERT	20616		4	at 19.km hammer build and change hose for feed wheels
Feb-03-2026		CHARLIE GEERNAERT	20305		1	Unit # 504 - Travel to 20 km Hammer - Righten nut holding head to the stick
Feb-04-2026		CHARLIE GEERNAERT	20306		2.5	Unit # 504 - Travel to 20 km Hammer - 900 hr service, change o-ring on head
Feb-05-2026		TIM NEUSTAETER	20198	14976	1	Unit # 504 - Removed hydraulic line.
Feb-08-2026		CHARLIE GEERNAERT	20308	15010	3.5	Unit # 504 - Travel to 20 km Hammer - Change and make feed wheel hose
Feb-11-2026		CHARLIE GEERNAERT	20314		1.5	Unit # 504 At 20 km Hammer, - Clean saw box, put diameter sensor linkage together - Travel to shop
Feb-13-2026		CHARLIE GEERNAERT	20317		1	Unit # 504 At 20 km Hammer - Change two o-rings on head
Feb-14-2026		CHARLIE GEERNAERT	20319		2	Unit # 504 - Travel to 20 km Hammer - Change spring for feed CYL fitting

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
Feb-15-2026		CHARLIE GEERNAERT	20322		1	Unit # 504 - Change screw on joystick at 20 km Hammer.
Feb-17-2026		CHARLIE GEERNAERT	20327		2.5	Travel to 20 km - change pin for upper connect link
Feb-25-2026		CHARLIE GEERNAERT	20333	15258	4	Pick up posts - travel to 22 km Hammer - change and make feed roller hose
Feb-27-2026		CHARLIE GEERNAERT	20337		4	1200 Hr service at 22 km - travel to camp
Feb-28-2026		CHARLIE GEERNAERT	20339		2	At 22 Km: - Change grab arm cyl - Change hydraulic filters - See why top saw loose bearing - Blew rad out, travel to camp
Mar-02-2026	OH25001	CHARLIE GEERNAERT	20353	15321	2	travel to 22km hammer remove feed motor, install feed motor
Mar-05-2026	OH25001	TIM NEUSTAETER	20175	15372	2	top saw bearing
Mar-09-2026	OH25001	CHARLIE GEERNAERT	20361	15387	4	travel to 13km hammer fix coolant leak on engine
Mar-11-2026	OH25001	TIM NEUSTAETER	20531		3	fixed hyd leaks
Mar-11-2026	OH25001	CHARLIE GEERNAERT	20363	15419	2.5	travel to 13km hammer install hose on head

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
Mar-12-2026	OH25001	CHARLIE GEERNAERT	20365		2	travel to 13km hammer tightem jic fitting on head, add oil
Mar-19-2026	OH25001	TIM NEUSTAETER	20536	15513	4	delimber cylinder replaced joysick repair
Mar-21-2026	OH25001	TIM NEUSTAETER	20539	15555	3	fixed hyd leak
Mar-22-2026		CHARLIE GEERNAERT	20555	15555	3	- Travel to Beaver Rd. - Put base on head - See why measuring not working
Mar-23-2026		CHARLIE GEERNAERT	20557		2.5	- At Beaver Rd. - Change hyd. Hose on head - Clean off proximity sensor for main saw
Mar-24-2026	OH25001	TIM NEUSTAETER	20542		6	replaced hose replaced hyd line helped Charlie with wiring on head
Mar-24-2026		CHARLIE GEERNAERT	20558		5	- Travel to Beaver Rd. - Fix wiring for main saw - Fix proximity sensor under computer - Fix wiring for main computer cable
Mar-26-2026		CHARLIE GEERNAERT	20560		3.5	- Travel to 17 km Amerada - Re-aline top saw motor - Go to Camp
Mar-27-2026		CHARLIE GEERNAERT	20562		3.5	- Travel to 17 km Amerada - Wrap up wiring for computer cable for head - Reroute feed cyl hose so not rubbing on wires - Travel to shop
May-11-2026	OH25001	CHARLIE GEERNAERT	20021		2	case drain test motor for left track at shop

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 504						
May-12-2026	OH25001	CHARLIE GEERNAERT	20023	14622	6	remove track from machine remove track drive assembly install 502's track drive assembly install track onto machine change batteries at yard
May-22-2026	OH25001	CHARLIE GEERNAERT	20620	15734	3.5	pick parts up travel to 16km teddy blow rod out and do a 300hr service
May-23-2026	OH25001	CHARLIE GEERNAERT	20622		3.5	travel to 16km teddy look for hydraulic leak travel to shop
May-25-2026	OH25001	CHARLIE GEERNAERT	20625		2	change hose at 16km teddy
Jun-11-2026	OH25001	CHARLIE GEERNAERT	13987	15806	2	at 16km teddy change feed cyl hose
Jun-14-2026	OH25001	CHARLIE GEERNAERT	13976		2.5	travel to 16km teddy bend hood cover straight plug in plug for grab arms weld hindges on
Jul-28-2026	OH25001	CHARLIE GEERNAERT	20042		2	pick parts up at resource install top saw sprocket, remove all the stuff from the cab
Total Hours:				927		