

Service Log Report

From: Feb-12-2022 To: Aug-12-2026

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 502						
Mar-17-2025	OH25001	BARNONE	8829			unit 502 removed access panel to diameter encoder
Apr-14-2025	OH25001	ALBRIGHT REFRIDGERATIO N	83901			unit 502 install new comp, take off old drier
May-17-2025	OH25001	CLIMB MACHINING	8853			waratah feed cylinder disassembled & inspected
May-22-2025	OH25001	CHARLIE GEERNAERT	12762		1.5	check pressure on head of machine in the yard
Jun-05-2025	OH25001	CHARLIE GEERNAERT	12830		4.5	travel to trailer tire block check pressures on head change shock valves for feed wheel cylinder blow out rad travel to shop
Jun-06-2025	OH25001	CHARLIE GEERNAERT	12833		3	travel to 2.5km central ridge check carrier pressure, cap off feed wheel cyliner to see if these bypassing get hold of waratah
Jun-10-2025	OH25001	CHARLIE GEERNAERT	12847		2	travel to 2.5km central ridge weld door for tool box adjust pressures for head

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 502						
Jun-11-2025	OH25001	CHARLIE GEERNAERT	12855		3.5	at 2.5km central west change wheel cylinder back to shop
Jun-13-2025	OH25001	CHARLIE GEERNAERT	12862		3	at 2.5km central ridge line up pin weld track pin
Jun-16-2025	OH25001	CHARLIE GEERNAERT	12902		5	travel to 2.5 km central ridge change feed wheel cylinder with sized oin adjust head pressure change measure wheel sprocket
Jun-17-2025	OH25001	CHARLIE GEERNAERT	12905		2	put feed wheel hose on machine blow ou rod at 2.5km central ridge
Jun-18-2025	OH25001	CHARLIE GEERNAERT	12910		4	travel to 2.5 km central ridge make and change feed wheel,case drain, and feed cylinder hoses
Jun-20-2025	OH25001	CHARLIE GEERNAERT	12917		7	travel to 2.5 km central ridge change measure wheel wait for parts from town
Jun-21-2025	OH25001	CHARLIE GEERNAERT	12923		1	travel to 2.5 km central ridge adjust measure wheel change grease fitting on beam go to camp

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 502						
Jun-22-2025	OH25001	CHARLIE GEERNAERT	12925		3	travel to 2.5 km central ridge drill and tap keeper bolt hole for feed arm connecting link change pins for connecting link as well travel to 12km pan can
Jun-23-2025	OH25001	CHARLIE GEERNAERT	12879		4	travel to 2.5 km central ridge -change hose to boom travel to town
Jun-24-2025	OH25001	CHARLIE GEERNAERT	12880		3.5	travel to 2.5 km central ridge 1200hr service weld track roller mount structure
Jun-24-2025	OH25001	BARNONE	9357			Unit 502 20298hrs, Replaced feed wheel connecting link bushing
Jun-30-2025	OH25001	BARNONE	9414			unit 502- Looked at why hyd bypass light was on; found filter was dirty and needs to be replaced.
Jul-03-2025	OH25001	CHARLIE GEERNAERT	13156		1.5	travel to 2.5km central ridge change return hydraUlic filter
Jul-09-2025	OH25001	CHARLIE GEERNAERT	13170		3.5	pick up fitting at resource travel to 2.5km central ridge change fitting on head,look at what pilot lines are leaking
Jul-11-2025	OH25001	CHARLIE GEERNAERT	13052		4	clean trailer at laydown yard make and change feed wheel hose at 2.5km central ridge

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 502						
Jul-12-2025	OH25001	CHARLIE GEERNAERT	13055		5	travel to 2.5km centrak ridge walk down the hill to walk machine up the hill weld nuts to the saw box to have something for the guard to bolt to the shop reseal the series three grab arm cylinder
Jul-15-2025	OH25001	CHARLIE GEERNAERT	13061		3	travel to 2.5km central ridge road weld on side door on cab weld track pins 300hr service
Jul-16-2025	OH25001	CHARLIE GEERNAERT	13080		1.5	travel to 2.5km central ridge see bushings and pins worn out on barrel end boom cylinders
Jul-17-2025	OH25001	CHARLIE GEERNAERT	13081		3.5	travel to 2.5km central ridge remove and build hoses for head install hoses on head
Jul-29-2025	OH25001	CHARLIE GEERNAERT	13103		3.5	travel to 2.5km central ridge remove feed wheel motor install feed wheel motor change hydraulic filter
Jul-31-2025	OH25001	CHARLIE GEERNAERT	13111		1.5	at rigel pit change pilot line going to joystick tighten keeper bolts on head

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 502						
Aug-04-2025	OH25001	CHARLIE GEERNAERT	12786		3	travel to rigel pit remove grab arm hoses build hoses at trailer install hoses and jb weld valve section that leaking
Aug-05-2025	OH25001	CHARLIE GEERNAERT	12792		2	at Rigel Pit try to put more JB weld on valve section tighten tracks
Aug-08-2025	OH25001	CHARLIE GEERNAERT	12800		4.5	travel to rigel rd install valve section on head
Aug-11-2025	OH25001	CHARLIE GEERNAERT	12897		4	travel to laydown yard pick up feed motor, travel back to rigel pit install feed motor
Aug-13-2025	OH25001	CHARLIE GEERNAERT	12867		1	change bump shop for head see where chain oil is leaking
Aug-16-2025	WC25001	CHARLIE GEERNAERT	13227		4	see where oil leak remove and make new pilot line at rigel pit install pilot line under valve
Aug-18-2025	WC25001	CHARLIE GEERNAERT	13232		1.5	at rigel pit remove main saw tensioner assembly clean components and put together again back to camp
Aug-19-2025	WC25001	CHARLIE GEERNAERT	13234		1.5	600hr service at rigel pit

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 502						
Aug-25-2025	WC25001	CHARLIE GEERNAERT			2.5	travel to the block near kokwa river to look for engine oil leak look for hydraulic leak
Aug-26-2025	WC25001	CHARLIE GEERNAERT			3	at willie rd look over head verify where engine oil is leaking, order parts
Aug-27-2025	WC25001	CHARLIE GEERNAERT			2	make hose at trailer change hose at willie road
Aug-28-2025	WC25001	CHARLIE GEERNAERT			4.5	wash maching and change gasket on cover on block on engine see what pilot hose leaking going to joystick
Aug-29-2025	WC25001	CHARLIE GEERNAERT	1		3	travel to shop to pick door glass up from Nolan travel to willie rd to help tim with lift cylinder bushings and pins
Sep-04-2025	OH25001	CHARLIE GEERNAERT	1010	21157	2	at 17.5km archie way weld clevis on machine for chains blow rod out
Sep-06-2025	OH25001	CHARLIE GEERNAERT	1015	21179	2	travel to 17km archie way change main saw sprocket
Sep-08-2025	OH25001	CHARLIE GEERNAERT	1018	21213	4	pick up part make and put on #16 hose for head at 17km archie change pilot hose for joystick

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 502						
Sep-09-2025	OH25001	BARNONE	9754	2155		checked over machine to make repair list troubleshoot head fuse blowing repaired wire check checked voltage at head module
Sep-09-2025	OH25001	BARNONE	9724	21082		Pulled pins for lower lift cylinder. Removed bushings. Installed new bushings with new pins.
Sep-10-2025	OH25001	CHARLIE GEERNAERT	1027	21240	4	travel to 17km archie way remove hose going to rotary, wait for hose install hose
Sep-13-2025	OH25001	CHARLIE GEERNAERT	1043	21294	1.5	change o-ring on head #16 at rigel pit
Sep-15-2025	OH25001	CHARLIE GEERNAERT	1054	21339	2.5	travel to rigel pit 900hr service
Sep-16-2025	OH25001	CHARLIE GEERNAERT	16052	21350	2.5	travel to rigel pit km see what is wrong with top saw,order parts
Sep-17-2025	OH25001	CHARLIE GEERNAERT	16059	21370	2	at 2km rigel pit remove hose from around swing motor install measuring arm cylinder install snap ring for top saw
Sep-18-2025	OH25001	CHARLIE GEERNAERT	16063	21370	2	travel to 2km rigel pit install hose near swing motor

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 502						
Sep-21-2025	OH25001	CHARLIE GEERNAERT	16069	21420	3	TRAVEL TO 2km rigel pit change cap on head change bsp washes
Sep-22-2025	OH25001	CHARLIE GEERNAERT	16073		0.5	at 2km rigel pit see why heat not working in COB
Oct-02-2025	OH25001	TIM NEUSTAETER	16018	5670	7	replaced left side idler
Oct-08-2025	OH25001	CHARLIE GEERNAERT	20111		1.5	at 13km archie change #16 hose going to head Grady brought from resource Glue plastics for ignition in cab
Oct-10-2025	OH25001	TIM NEUSTAETER	15989	21621	4	checked oil leak will need seals for main saw tenioner made parts lists and order
Oct-14-2025	OH25001	CHARLIE GEERNAERT	20118	21686	6	at 15km archie weld track pin fix oil leak on head 1200hr service
Oct-15-2025	OH25001	CHARLIE GEERNAERT	20119	21686	1	at 15km archie tighten tracks
Oct-22-2025	OH25001	TIM NEUSTAETER	20230		4	inspected oil leak made parts list and ordered seals main saw swivel seals needto be replace tightened all loose bolts

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 502						
Oct-23-2025	OH25001	CHARLIE GEERNAERT	20061		2	travel to 17km Amerada help Tim with main saw tensioner and motor seals
Oct-23-2025	OH25001	TIM NEUSTAETER	20233	21700	5.5	replaced main saw swivel seals resealed main saw tensioner
Oct-24-2025	OH25001	TIM NEUSTAETER	20234	21700	4.5	welded cracks on head inspected top saw and ordered parts
Oct-28-2025	OH25001	TIM NEUSTAETER	20238	21737	4	installed snap ring and for top saw installed measuring wheel guard
Oct-30-2025	OH25001	CHARLIE GEERNAERT	20067	21740	3	at dobson rd see why machine won't start change inline fuel filter and lift pump
Oct-30-2025	OH25001	TIM NEUSTAETER	20242	21740	3	trouble shot primer pump replaced fuse ordered primer pump
Nov-01-2025	OH25001	CHARLIE GEERNAERT	20122		1.5	at dobson rd weld track pins
Nov-06-2025	OH25001	TIM NEUSTAETER	20247	21835	1	checked top saw function made parts list for repair
Nov-08-2025	OH25001	TIM NEUSTAETER	20251		7.5	removed head removed stick cut out damaged bushings ordered correct parts
Nov-11-2025	OH25001	TIM NEUSTAETER	20254		1.5	replaced heater valve

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 502						
Nov-12-2025	OH25001	CHARLIE GEERNAERT	13936		1	at laydown yard put plexy glass covering lights on cab
Nov-13-2025	OH25001	TIM NEUSTAETER	20256	21864	9	pressed in bushing installed seals and shims assemble stick and attached head
Nov-13-2025	OH25001	CHARLIE GEERNAERT	13941	21721	3.5	at laydown yard help Time put stick and head on machine,
Nov-20-2025	OH25001	CHARLIE GEERNAERT	20030	21929	3.5	travel to 2.5km rat creek add oil to swing motor, change fitting for grease line hand up hard line on stick
Nov-21-2025	OH25001	TIM NEUSTAETER	20262		5.5	removed top saw plate/assemble cut snap ring groove deeper reassembled
Nov-25-2025	OH25001	CHARLIE GEERNAERT	20032	21969	4	travel to 2.5km rat creek straighten foor for hydraulic pump weld broken piece back in knife on head take up broken order parts
Nov-27-2025	OH25001	CHARLIE GEERNAERT	20035		3.5	travel to brandt to get part then to 2.5km rat creek 300hr service
Nov-29-2025	OH25001	CHARLIE GEERNAERT	20038		1.5	travel to 2.5km rat creek change bump stop for head change radio and wire
Nov-29-2025	OH25001	CHARLIE GEERNAERT	20066	21739	2.5	weld top rooler pedistal to track

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 502						
Dec-02-2025	OH25001	CHARLIE GEERNAERT	20503		2.5	at 4km dobson install clamp for hard line on stick install new precleaner install new latch on hydraulic door
Dec-05-2025	OH25001	TIM NEUSTAETER	20126	22090	2	bush fixed, preclean ordered new precleaner
Dec-08-2025	OH25001	CHARLIE GEERNAERT	20507		4	travel to conoco rd change BSP washer on head take plate bolding all hoses together on back of boom, weld it, install it see what is leaking in cab, order pilot hose
Dec-09-2025	OH25001	TIM NEUSTAETER	20130		4	remove hyd line ,ordered new assessed tenioner, spring retainer for recoil has missing, sent parts to town
Dec-09-2025	OH25001	CHARLIE GEERNAERT	20509		6	pick up parts travel to conoco rd install hose on stick try to put track on(tensioner broken)
Jan-02-2026	OH25001	TIM NEUSTAETER	20211		6	installed left track recoil assembly put track back on
Jan-06-2026	OH25001	CHARLIE GEERNAERT	20581		3	travel to 3.5km bredison change pre cleaner for intake see what pilot hose leaking change radio
Jan-07-2026	OH25001	CHARLIE GEERNAERT	20583		2	travel to 3.5km bredison make and change pilot line tighten tracks
Jan-12-2026	OH25001	TIM NEUSTAETER	20221		4.5	trouble shot swing swing gear is damaged will need to remove to asses damages

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 502						
Jan-19-2026	OH25001	TIM NEUSTAETER	20177	22242	4.5	removed head and chained swaing drive for transport drove to bush
Feb-23-2026		CHARLIE GEERNAERT	20331	22245	8	Travel to town - Install head onto stick of machine - Try to fix wiring on crane and service truck
Feb-25-2026		CHARLIE GEERNAERT	20333	22253	6	At 22 km - see what's wrong with rotate - change rotate motor and pins on gear - travel to town
Feb-26-2026		CHARLIE GEERNAERT	20334	22253	8	For head rotote - install ring gear at 22 km Hammer
Feb-27-2026		CHARLIE GEERNAERT	20336	22253	2	Travel to 22 km Hammer - Fix wiring for head in rotate - Change retate hoses around
Mar-02-2026	OH25001	CHARLIE GEERNAERT	20353	22274	2	at 22km hammer remove feed motor remove rotate motor for head
Mar-04-2026	OH25001	CHARLIE GEERNAERT	20357	22272	4.5	at 22km hammer install feed motor, and rotate motor for head
Mar-11-2026	OH25001	CHARLIE GEERNAERT	20364	222354	3	travel to rigel pit change hose, make hose for feed rollers motors
Mar-22-2026		CHARLIE GEERNAERT	20555	22487	1.5	- At Beaver Rd. - 600 Hr Service
May-11-2026	OH25001	CHARLIE GEERNAERT	20021		2.5	remove track from machine at shop

Service Date	Contract	Mechanic Name	Work Order #	Meter/Mileage	Time	Service Description
Unit Number: 502						
May-12-2026	OH25001	CHARLIE GEERNAERT	20023		6	remove track drive assembly install 504's drive assembly install track onto machine
Jun-12-2026	OH25001	CHARLIE GEERNAERT	13994		0.5	install track pad at shop tighten track
Jul-28-2026	OH25001	CHARLIE GEERNAERT	20042		2	install main saw sprocket weld knife cutting edge
Total Hours:				312		