

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2026-03-26		0 8520353		Text		Repair without detail info	
2026-03-25	1307417	8520319	Retail	Other	M	PLEASE FILL IN	
2026-03-25	1307417	8520319		Text		Contact:JIM 0419 657 335	
2026-03-25	1307417	8520319	Retail	Other	192	VEHICLE BROKEN DOWN, TRAVEL TO VEHICLE AT	
2026-03-25	1307417	8520319		Text		22 tile street wacol	
2026-03-25	1307417	8520319	Retail	Other	92	UTE MILEAGE 6 km's @ \$3.30/km.	
2026-03-25	1307417	8520319	Retail	Operation	LO-890	locked keys in truck	3
2026-03-25	1307417	8520319		Text		Broke window glass gaining access into truck, Removed	
2026-03-25	1307417	8520319		Text		Vacuumed up glass and fitted new glass.	
2026-03-25	1307417	8520319		Text		kms:1307417	
2026-03-25	1307417	8520319		Text		hrs:21140	
2026-03-25	1307417	8520319	Retail	Other	91	WORKSHOP CONSUMABLES	
2025-10-24	1264462	8329997	Retail	Other	ACC	***POP***PLEASE FILL IN	
2025-10-24	1264462	8329997	Retail	Operation	VO-1774400	Basic service. Chassis lubrication and o	3
2025-10-24	1264462	8329997		Text		oil changes included only in some models	
2025-10-24	1264462	8329997	Retail	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
2025-10-24	1264462	8329997		Text		area	
2025-10-24	1264462	8329997	Retail	Operation	VO-2331100	Filter, water separator, replace	0.3
2025-10-24	1264462	8329997	Retail	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2025-10-24	1264462	8329997	Retail	Operation	LO-560	secondary air system leaking	1.5
2025-10-24	1264462	8329997		Text		will go down in 1 hr	
2025-10-24	1264462	8329997	Internal	Operation	LO-360	derate issue	1.5
2025-10-24	1264462	8329997		Text		when adblue tank is under 2/3 truck will derate check and	
2025-10-24	1264462	8329997	Retail	Other	97	ENVIRONMENTAL CHARGE	
2025-10-24	1264462	8329997	Retail	Part	VO-85114535	MP8/MP10 FILTER KIT	1
2025-10-24	1264462	8329997	Retail	Part	VO-20579690	DOWDY WASHER	1
2025-10-24	1264462	8329997	Retail	Operation	LO-210	change coolant hoses	5
2025-10-24	1264462	8329997		Text		keep all hoses changed	
2025-10-24	1264462	8329997	Retail	Part	UNK-NPNSUZISI	suzi special \$\$ shorts	2
2025-10-24	1264462	8329997	Retail	Part	MK-9711-9208C	CLIP SET FOR 9208	2
2025-10-24	1264462	8329997		Text		jimmy has these items	
2025-10-24	1264462	8329997		Text		jimmy has these items	
2025-10-24	1264462	8329997	Retail	Operation	LO-563	Right steer brake valve in chassis leak	1.5

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2025-10-24	1264462	8329997	Retail	Part	AU2-CHE23068	VDS 4.5 ENGINE OIL BULK	52
2025-10-24	1264462	8329997	Retail	Operation	LO-222	Oil fill tube leaking oil.	0.5
2025-10-24	1264462	8329997	Retail	Part	VO-21850098	RELAY VALVE	1
2025-10-24	1264462	8329997	Retail	Part	VO-22891920	HOSE	1
2025-10-24	1264462	8329997	Retail	Part	VO-22891932	HOSE	1
2025-10-24	1264462	8329997	Retail	Part	VO-22891922	HOSE	1
2025-10-24	1264462	8329997	Retail	Part	VO-22260634	RUBBER HOSE	1
2025-10-24	1264462	8329997	Retail	Part	VO-21053055	HOSE, COOLANT	1
2025-10-24	1264462	8329997	Retail	Part	VO-21637042	HOSE	1
2025-10-24	1264462	8329997	Retail	Part	VO-21637042	HOSE	1
2025-10-24	1264462	8329997	Retail	Part	VO-21339891	RUBBER HOSE 1/2"	1
2025-10-24	1264462	8329997	Retail	Part	VO-21012932	HOSE SILICON 7/8"	1
2025-10-24	1264462	8329997	Retail	Part	VO-21922388	HOSE CLAMP	6
2025-10-24	1264462	8329997	Retail	Part	VO-994557	HOSE CLAMP 15mm-24mm	6
2025-10-24	1264462	8329997	Retail	Part	VO-20722710	HOSE CLAMP	2
2025-10-24	1264462	8329997	Retail	Part	VO-20883065	OIL FILLER PIPE	1
2025-10-24	1264462	8329997	Retail	Part	VO-21780376	SEALING RING	1
2025-10-24	1264462	8329997	Retail	Part	VO-994557	HOSE CLAMP 15mm-24mm	3
2025-10-24	1264462	8329997	Retail	Part	VO-22525484	HOSE	2
2025-10-24	1264462	8329997	Retail	Part	VO-21380391	CONNECTOR 45 deg	2
2025-10-24	1264462	8329997	Retail	Part	VO-20938685	CONNECTOR 90deg	1
2025-10-24	1264462	8329997	Retail	Part	VO-21380391	CONNECTOR 45 deg	2
2025-10-24	1264462	8329997	Retail	Part	VO-21012932	HOSE SILICON 7/8"	0.5
2025-10-24	1264462	8329997	Retail	Part	VO-21339891	RUBBER HOSE 1/2"	2.5
2025-10-24	1264462	8329997	Retail	Part	AU2-AMP24754	VCS-2 40/60 COOLANT PUMP OUT	5
2025-10-24	1264462	8329997		Text		.	
2025-10-24	1264462	8329997		Text		Contact:jim 0419 657 335 Next Service: CREDIT LIMIT: BALANCE:	
2025-10-24	1264462	8329997		Text		Mileage:1264462 Hrs: 19885 Defect sheet complete Y/N _____	
2025-10-24	1264462	8329997		Text		.	
2025-10-24	1264462	8329997		Text		CONNECTED LAPTOP AND READ DTCS, TRUCK HAS MULTIPLE FA	
2025-10-24	1264462	8329997		Text		FOR AD BLUE PRESSURE LOW. PERFORMED BUILD UP TEST, AD	
2025-10-24	1264462	8329997		Text		BLUE PRESSURE BUILT UP CORRECTLY, CHECKED FOR LEAKS AN	
2025-10-24	1264462	8329997		Text		KINKS IN HOSES, ALL GOOD. REMOVED AD BLUE PICKUP, CHECK	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2025-10-24	1264462	8329997		Text		FOR BLOCKAGES, NO ISSUES, CHECKED OPERATION OF FLOAT L	
2025-10-24	1264462	8329997		Text		SENSOR, ALL GOOD. CHECKED ADBLUE TANK BREATHER FILTER:	
2025-10-24	1264462	8329997		Text		BLOCKAGE, ALL GOOD. NO FAULT FOUND TO CAUSE THIS ISSUE	
2025-10-24	1264462	8329997		Text		report.	
2025-10-24	1264462	8329997		Text		DRAINED COOLANT - CARRIED OUT REPLACEMENT OF ALL HEATI	
2025-10-24	1264462	8329997		Text		HOSE FOR CAB AND BUNK HEATER. REPLACED ALL TRANSMISSIC	
2025-10-24	1264462	8329997		Text		COOLER HOSES, REPLACED HEADER TANK TO THERMOSTAT HOI	
2025-10-24	1264462	8329997		Text		PIPE. REFILLED COOLANT AND BLEED SYSTEM, WASHED TRUCK.	
2025-10-24	1264462	8329997		Text		CHECKED OVER AFTER ROAD TEST ALL GOOD.	
2025-10-24	1264462	8329997		Text		* PLEASE NOTE ONLY HOSE NOT REPLACED WAS HEADER TANK I	
2025-10-24	1264462	8329997		Text		NONE STOCK * ALL HOSES STILL	
2025-10-24	1264462	8329997		Text		IN USEABLE CONDITION HAVE BEEN PUT BETWEEN SEATS IN TRU	
2025-10-24	1264462	8329997		Text		REMOVED AND REPLACED LEAKING RELAY VALVE, BUILT AIR SYS	
2025-10-24	1264462	8329997		Text		AND RE-CHECKED FOR LEAKS ALL OK.	
2025-10-24	1264462	8329997		Text		REMOVED AND REPLACED LEAKING OIL FILLER PIPE.	
2025-10-24	1264462	8329997		Text		CHECKED AND FOUND SOME AIR LINES RUBBING AND LEAKING	
2025-10-24	1264462	8329997		Text		FITTING LEAKING TO ON AIR TANK. REPAIRED AIR LINES AND	
2025-10-24	1264462	8329997		Text		SECURED FROM RUBBING. REMOVED AIR FITTING + CLEANED UF	
2025-10-24	1264462	8329997		Text		THREADS AND RE-INSTALLED. BUILT UP AIR SYSTEM AND	
2025-10-24	1264462	8329997		Text		RE-CHECKED FOR LEAKS ALL OK.	
2025-10-24	1264462	8329997		Text		air leaking at air pressure	
2025-10-24	1264462	8329997		Text		switch at r/h/s of fire wall	
2025-10-24	1264462	8329997		Text		at brake valve area	
2025-10-24	1264462	8329997	Retail	Other	91	WORKSHOP CONSUMABLES	
2025-10-24	1264462	8329997	Warranty	Operation	VO-4390300	Seal, output shaft, replace	1.3
2025-10-24	1264462	8329997	Warranty	Part	VO-976055	O-RING	1
2025-10-24	1264462	8329997	Warranty	Part	VO-8171338	LOCK NUT	1
2025-10-24	1264462	8329997	Warranty	Part	VO-995906	BOLT M14*46 THREAD LOCKER	4
2025-10-24	1264462	8329997	Warranty	Part	VO-984050	NUT M14 FINE THREAD	4
2025-10-24	1264462	8329997	Warranty	Part	VO-20791305	SEALING RING	1
2025-10-24	1264462	8329997		Text		gearbox output seal leaking has been changed before	
2025-10-24	1264462	8329997	Warranty	Operation	VO-1820400	Wash of engine. Including engine encapsu	0.5
2025-10-24	1264462	8329997		Text		encapsulation, all lower hatches, remove-install	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2025-10-24	1264462	8329997	Warranty	Operation	VO-1902000	Road test	0.3
2025-10-24	1264462	8329997		Text		REMOVED DRIVE SHAFT, REMOVED REAR TRANSMISSION OUTPUT	
2025-10-24	1264462	8329997		Text		FLANGE. REMOVED OUTPUT SEAL, INSTALLED NEW SEAL AND FIT	
2025-10-24	1264462	8329997		Text		BACK FLANGE WITH NEW MOUNTING NUT. FITTED BACK DRIVE S	
2025-10-24	1264462	8329997		Text		AND STEAM CLEANED AREA.CHECKED OVER AFTER ROAD TEST.	
2025-09-02	1248632	8328780	Retail	Other	ACC	PPO** PLEASE FILL IN	
2025-09-02	1248632	8328780	Retail	Operation	LO-260	Brakes noisy	6
2025-09-02	1248632	8328780		Text		rhs worse check and report on area	
2025-09-02	1248632	8328780		Text		Remove and replace both belt tensioners,	
2025-09-02	1248632	8328780		Text		idler pulleys and belts.	
2025-09-02	1248632	8328780	Retail	Operation	LO-PSUMMBE	Mack belt/tensioner MP10 \$1199 incl	2.5
2025-09-02	1248632	8328780		Text		Remove and replace both belt tensioners,	
2025-09-02	1248632	8328780		Text		idler pulleys and belts.	
2025-09-02	1248632	8328780	Retail	Part	VO-22950501	BELT TENSIONER	1
2025-09-02	1248632	8328780	Retail	Part	VO-21753149	IDLER PULLEY	1
2025-09-02	1248632	8328780	Retail	Part	VO-23961777	V-RIBBED BELT - 10PK1465	1
2025-09-02	1248632	8328780	Retail	Other	91	WORKSHOP CONSUMABLES	
2025-09-02	1248632	8328780	Retail	Part	VO-984761	BOLT M10*100 FL GR10.9	1
2025-09-02	1248632	8328780	Retail	Part	VO-23961744	V-RIBBED BELT8PK1388	1
2025-09-02	1248632	8328780	Retail	Part	VO-22926887	ADAPTER	1
2025-09-02	1248632	8328780	Retail	Part	VO-984754	BOLT M10*35 FL GR10.9	2
2025-09-02	1248632	8328780	Retail	Part	VO-24201573	BELT TENSIONER	1
2025-09-02	1248632	8328780	Retail	Operation	LO-310	change auto greaser settings to grease	0.5
2025-09-02	1248632	8328780		Text		vehicle less.	
2025-09-02	1248632	8328780		Text		Contact: Jim 0419 657 335 Next Service: CREDIT LIMIT: BALANCE:	
2025-09-02	1248632	8328780		Text		Mileage: 1248632Hrs: 19350Defect sheet complete Y/N _____	
2025-09-02	1248632	8328780	Retail	Operation	LO-260	rectify coolant leak top	1
2025-09-02	1248632	8328780		Text		radiator hose.	
2025-09-02	1248632	8328780	Retail	Part	VO-22891920	HOSE	1
2025-09-02	1248632	8328780	Retail	Part	VO-21922388	HOSE CLAMP	2
2025-09-02	1248632	8328780	Retail	Part	VO-24226156	BRAKE PAD KIT	1
2025-09-02	1248632	8328780	Retail	Part	VO-3092710	BRAKE DISC FLE	1
2025-09-02	1248632	8328780	Retail	Part	VO-1076656	HUB SEAL, UNIT HUB	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2025-09-02	1248632	8328780	Retail	Part	VO-1076335	NUT	1
2025-09-02	1248632	8328780	Retail	Part	VO-22567763	BRAKE HOUSING	1
2025-09-02	1248632	8328780	Retail	Part	VO-24520271	SENSOR	1
2025-09-02	1248632	8328780	Retail	Part	VO-22537018	SENSOR WHEEL	1
2025-09-02	1248632	8328780	Retail	Operation	LO-640	CHECK AND REPORT ON KINGPIN WEAR	0.5
2025-09-02	1248632	8328780	Retail	Operation	LO-250	CHECK AND REPORT ON EXHAUST BRAKE	2.2
2025-09-02	1248632	8328780		Text		FUNCTION. POSSIBLE THAT THE HOSE HAS BLOWN OFF THE	
2025-09-02	1248632	8328780	Retail	Part	MK-NARV56310	CABLE TIE 1=10PC	2
2025-09-02	1248632	8328780	Retail	Part	VO-22823727	EXHAUST BRAKE	1
2025-09-02	1248632	8328780	Retail	Part	VO-85109890	REPAIR KIT	1
2025-09-02	1248632	8328780		Text		Carried out inspection, steer axle all good. Inspected	
2025-09-02	1248632	8328780		Text		Changed auto greaser setting from every 1.5 hours to 6	
2025-09-02	1248632	8328780		Text		currently over greasing vehicle	
2025-09-02	1248632	8328780		Text		hours.	
2025-09-02	1248632	8328780		Text		Carried out inspection found top radiator hose leaking.	
2025-09-02	1248632	8328780		Text		Drained coolant and removed and replaced hose. Refilled	
2025-09-02	1248632	8328780		Text		coolant and preassure tested cooling system. No leaks	
2025-09-02	1248632	8328780		Text		found. Washed down vehicle.	
2025-09-02	1248632	8328780		Text		Jacked up axle and checked kingpins. ALL within	
2025-09-02	1248632	8328780		Text		specification.	
2025-09-02	1248632	8328780		Text		Connected laptop, carried out waste gate actuator and warm	
2025-09-02	1248632	8328780		Text		rear axle found lhs 2nd drive brake pad worn through the	
2025-09-02	1248632	8328780		Text		metal. Removed hub components for axle end found will need	
2025-09-02	1248632	8328780		Text		brake disk, brake pads, caliper, pole wheel and ABS sensor.	
2025-09-02	1248632	8328780		Text		Removed old brake disk from hub. Fitted new disk to hub	
2025-09-02	1248632	8328780		Text		and tentioned bolts. Replaced ABS sensor due to dammage.	
2025-09-02	1248632	8328780		Text		Refitted hub and tentioned to spec. Had to fit new brake	
2025-09-02	1248632	8328780		Text		caliper as excessive damange on the brake caliper.	
2025-09-02	1248632	8328780		Text		tensioned all mounting bolts. Fitted new brake	
2025-09-02	1248632	8328780		Text		pads across axle Refitted wheels and tentioned to	
2025-09-02	1248632	8328780		Text		specificaiton. Carried out road test and checked over	
2025-09-02	1248632	8328780		Text		vehicle no faults found.	
2025-09-02	1248632	8328780		Text		CYLINDER.	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2025-09-02	1248632	8328780		Text		hold tests. Found exhaust brake ram leaking, removed ram,	
2025-09-02	1248632	8328780		Text		found joint in housing worn out, removed and replaced	
2025-09-02	1248632	8328780		Text		exhaust brake housing and ram. Rechecked operation, found	
2025-09-02	1248632	8328780		Text		ok	
2025-09-02	1248632	8328780	Retail	Other	91	WORKSHOP CONSUMABLES	
2025-09-02	1248632	8328780	Warranty	Operation	VO-4390300	Seal, output shaft, replace	1.3
2025-09-02	1248632	8328780	Warranty	Part	VO-20791305	SEALING RING	1
2025-09-02	1248632	8328780	Warranty	Part	VO-8171338	LOCK NUT	1
2025-09-02	1248632	8328780	Warranty	Part	VO-995906	BOLT M14*46 THREAD LOCKER	4
2025-09-02	1248632	8328780	Warranty	Part	VO-984050	NUT M14 FINE THREAD	4
2025-09-02	1248632	8328780		Text		Carried out inspection found gearbox output seal leaking.	
2025-09-02	1248632	8328780		Text		rectify rear transmission seal leaking gearbox just	
2025-09-02	1248632	8328780		Text		replaced by us at last visit.	
2025-09-02	1248632	8328780		Text		should be warranty repair.	
2025-09-02	1248632	8328780		Text		Removed tail shaft. Pressed off flange. Removed seal.	
2025-09-02	1248632	8328780		Text		Pressed in new seal. Refitted flange and tentioned nut to	
2025-09-02	1248632	8328780		Text		specification. Refitted drive shaft and tentioned.	
2025-07-03	1220158	8327108	Retail	Other	ACC	**ppo**PLEASE FILL IN	
2025-07-03	1220158	8327108	Retail	Operation	LO-210	oil leaking at timing plate area	33.2
2025-07-03	1220158	8327108		Text		remove transmission, clutch assembly ,	
2025-07-03	1220158	8327108	Retail	Part	VO-21185132	SEALING	2
2025-07-03	1220158	8327108	Retail	Part	VO-20815558	SEALING STRIP	1
2025-07-03	1220158	8327108	Retail	Part	VO-994447	BOLT M8*25 FL GR8.8 THREAD LOC	25
2025-07-03	1220158	8327108	Retail	Part	VO-943177	OIL COOLER ORIN	1
2025-07-03	1220158	8327108	Retail	Part	VO-21724614	SEALING	2
2025-07-03	1220158	8327108	Retail	Part	VO-20483919	BOLT M10*45 HEX SOCKET GR10.9	6
2025-07-03	1220158	8327108	Retail	Part	VO-984127	O-RING	1
2025-07-03	1220158	8327108	Retail	Part	VO-20736230	SEALING STRIP	1
2025-07-03	1220158	8327108	Retail	Part	VO-20734156	SEALING STRIP	1
2025-07-03	1220158	8327108	Retail	Part	AU2-WUR08901	BRAKE CLEAN	2
2025-07-03	1220158	8327108	Retail	Part	VO-995906	BOLT M14*46 THREAD LOCKER	4
2025-07-03	1220158	8327108	Retail	Part	VO-984050	NUT M14 FINE THREAD	4
2025-07-03	1220158	8327108	Retail	Part	VO-471708	SEAL RING	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2025-07-03	1220158	8327108	Retail	Part	VO-22206111	TIMING GEAR PLATE	1
2025-07-03	1220158	8327108	Retail	Part	VO-22997657	TIMING GEAR COVER	1
2025-07-03	1220158	8327108	Retail	Part	VO-21015266	BOLT M12*50MM	6
2025-07-03	1220158	8327108	Retail	Part	VO-22191895	CRANKSHAFT SEAL	1
2025-07-03	1220158	8327108	Retail	Part	AU2-WUR06732	BROWN LOC 2"	1
2025-07-03	1220158	8327108	Retail	Part	VO-1161963	RUBBER GREASE FETT	1
2025-07-03	1220158	8327108	Retail	Part	MK-NARV56306	CABLE TIE 1=25PC	1
2025-07-03	1220158	8327108	Retail	Part	VO-8192804	BOLT BIG END	8
2025-07-03	1220158	8327108	Retail	Other	430	TRANS FAULTS COMING UP ON DASH	
2025-07-03	1220158	8327108		Text		TRANS NOT WANTING TO PICK UP GEARS	
2025-07-03	1220158	8327108		Text		GOULD HEAR AIR LEAKING ? SHUT DOWN ISOLATED	
2025-07-03	1220158	8327108		Text		VEHICLE RESTART ALL OK	
2025-07-03	1220158	8327108		Text		MID 130 PSID 27 FMI 8	
2025-07-03	1220158	8327108		Text		MID 130 PSID 29 FMI 7	
2025-07-03	1220158	8327108	Retail	Operation	LO-561	AIR LEAKING AT FIRE WALL CHECK & REPORT	2
2025-07-03	1220158	8327108		Text		Contact:JIM 0419 657 335 jim.gatt@yahoo.com.au estimate # 40€	
2025-07-03	1220158	8327108		Text		CREDIT LIMIT: BALANCE: Mileage: 1220158Hrs: 18842Defect she	
2025-07-03	1220158	8327108		Text		Y/N _____	
2025-07-03	1220158	8327108	Retail	Operation	LO-PWINMDR	M Drive Package	8
2025-07-03	1220158	8327108	Retail	Part	VO-85020582	EXCH GBOX ATO3112D	1
2025-07-03	1220158	8327108	Retail	Part	VO-24009664	HOSE KIT	1
2025-07-03	1220158	8327108	Retail	Part	VO-11998	COPPER WASHER	2
2025-07-03	1220158	8327108	Retail	Part	VO-994441	BOLT M8*50 FL	1
2025-07-03	1220158	8327108	Retail	Part	VO-990950	NUT M8 FL LOCKING	1
2025-07-03	1220158	8327108	Retail	Part	VO-994557	HOSE CLAMP 15mm-24mm	2
2025-07-03	1220158	8327108	Retail	Part	VO-20532891	GASKET	1
2025-07-03	1220158	8327108	Retail	Part	VO-992065	O-RING	1
2025-07-03	1220158	8327108	Retail	Part	VO-977030	O-RING	1
2025-07-03	1220158	8327108	Retail	Part	VO-21532261	SEALING RING	1
2025-07-03	1220158	8327108	Retail	Part	MK-NARV56310	CABLE TIE 1=10PC	2
2025-07-03	1220158	8327108	Retail	Part	VO-20499470	RUBBER CUSHION	1
2025-07-03	1220158	8327108	Retail	Part	VO-983762	BOLT M14*25 HEX SOCKET GR10.9	1
2025-07-03	1220158	8327108	Retail	Part	VO-20966752	O-RING	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2025-07-03	1220158	8327108	Retail	Part	VO-994447	BOLT M8*25 FL GR8.8 THREAD LOC	10
2025-07-03	1220158	8327108	Retail	Part	VO-85114535	MP8/MP10 FILTER KIT	1
2025-07-03	1220158	8327108	Retail	Part	VO-20579690	DOWDY WASHER	1
2025-07-03	1220158	8327108	Retail	Part	AU2-CHE85136:	SYNTHETIC GEARBOX BULK	16.5
2025-07-03	1220158	8327108	Retail	Part	VO-21344787	BOLT M10*90 FL	2
2025-07-03	1220158	8327108	Retail	Part	VO-990053	HOUSING	1
2025-07-03	1220158	8327108	Retail	Part	AU2-CHE23068:	VDS 4.5 ENGINE OIL BULK	52
2025-07-03	1220158	8327108	Retail	Part	VO-3082876	PLUG	1
2025-07-03	1220158	8327108	Retail	Part	VO-21850098	RELAY VALVE	1
2025-07-03	1220158	8327108		Text		completed	
2025-07-03	1220158	8327108		Text		.	
2025-07-03	1220158	8327108		Text		.CHECKED AND FOUND THE RELAY VALVE LEAKING	
2025-07-03	1220158	8327108		Text		.DRAIN ALL ENGINE FLUIDS	
2025-07-03	1220158	8327108		Text		.REMOVED AND REPLACED LEAKING RELAY VALVE	
2025-07-03	1220158	8327108		Text		.BUILT AIR SYSTEM AND RE-CHECKED FOR LEAKS ALL OK.	
2025-07-03	1220158	8327108		Text		.CHECKED TRANSMISSION FAULTS AND FOUND INTERNAL ISSUE	
2025-07-03	1220158	8327108		Text		RANGE + EXCESSIVE MOVEMENT IN INPUT SHAFT.	
2025-07-03	1220158	8327108		Text		.CUSTOMER HAS BEEN INFORMED AND APPROVED NEW EXCHAI	
2025-07-03	1220158	8327108		Text		TRANSMISSION.	
2025-07-03	1220158	8327108	Retail	Other	97	ENVIRONMENTAL CHARGE	
2025-07-03	1220158	8327108		Text		.REMOVE ALL COMPONENTS AROUND TRANSMISSION	
2025-07-03	1220158	8327108		Text		.REMOVE TRANSMISSION, CLUCTH & FLYWHEEL	
2025-07-03	1220158	8327108		Text		.REMOVE ALL COMPONENTS AROUND REAR ENGINE HOUSING	
2025-07-03	1220158	8327108		Text		.REMOVE ENGINE SUMP	
2025-07-03	1220158	8327108		Text		.REMOVE REAR ENGINE HOUSING & TIMING GEARS	
2025-07-03	1220158	8327108		Text		.REMOVE TIMING SANDWHICH PLATE	
2025-07-03	1220158	8327108		Text		.CLEAN ALL SURFACES ON REAR ENGINE BLOCK & REAR HOUSIN	
2025-07-03	1220158	8327108		Text		.INSTALL NEW TIMING SANDWHICH PLATE	
2025-07-03	1220158	8327108		Text		.INSTALL BACK ALL TIMING GEARS & CHECK BACKLASH	
2025-07-03	1220158	8327108		Text		.FIT BACK REAR ENGINE HOUSING & ENGINE SUMP	
2025-07-03	1220158	8327108		Text		.FIT BACK ALL COMPONENTS AROUND REAR ENGINE HOUSING	
2025-07-03	1220158	8327108		Text		.REMOVE AND REPLACE R/H REAR ENGINE MOUNT AS SPLIT	
2025-07-03	1220158	8327108		Text		.FIT BACK FLYWHEEL & CLUTCH	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2025-07-03	1220158	8327108		Text		.INSTALL TRANSMISSION & ALL COMPONENTS	
2025-07-03	1220158	8327108		Text		.FILL ALL ENGINE FLUIDS	
2025-07-03	1220158	8327108		Text		.START ENGINE & CHECK OVER	
2025-07-03	1220158	8327108		Text		.STEAM CLEANED ENGINE & ROAD TEST TRUCK	
2025-07-03	1220158	8327108		Text		.CHECK OVER AFTER ROAD TEST ALL OK.	
2025-07-03	1220158	8327108		Text		flywheel housing , sump & rocker cover	
2025-07-03	1220158	8327108		Text		clean all sealing surfacers reassemble	
2025-07-03	1220158	8327108		Text		with parts listed	
2025-07-03	1220158	8327108	Retail	Other	91	WORKSHOP CONSUMABLES	
2025-05-30	1204898	3040253	Retail	Operation	LO-410	CLUTCH	1.25
2025-05-30	1204898	3040253		Text		Please fit clutch solenoid valve as supplied by customer.	
2025-05-30	1204898	3040253	Retail	Other	NOTE	Please Note:	
2025-05-30	1204898	3040253		Text		No fault diagnosis completed by WTG Toowoomba, fitting	
2025-05-30	1204898	3040253		Text		component only as supplied by customer.	
2025-05-30	1204898	3040253		Text		Concern: Clutch solenoid valve	
2025-05-30	1204898	3040253		Text		Cause: Parts supplied.	
2025-05-30	1204898	3040253		Text		Correction: Connected tech tool and inspected fault.	
2025-05-30	1204898	3040253		Text		Removed and replaced PWM vavle as supplied (previous	
2025-05-30	1204898	3040253		Text		diagnosed)	
2025-05-30	1204898	3040253		Text		Calibrate gearbox - all ok.	
2025-05-30	1204898	3040253		Text		Test drove.	
2025-05-30	1204898	3040253		Text		SN - New - 03260143	
2025-05-30	1204898	3040253		Text		Old - 02772353	
2025-05-30	1204898	3040253		Text		(He had a breakdown in Darwin, tech diagnosed component	
2025-05-30	1204898	3040253		Text		fault)	
2025-05-30	1204898	3040253	Retail	Other	91	Workshop Consumables	
2025-05-22	0	3848943	Retail	Operation	LO-920BD	Breakdown	2
2025-05-22	0	3848943	Retail	Other	92	Callout vehicle km charge - \$1.65 per km	
2025-05-22	0	3848943		Text		BP Truck Central	
2025-05-22	0	3848943		Text		Complaint: Breakdown - Stuck in gear	
2025-05-22	0	3848943		Text		Cause: Low Air - Unable to select neutral	
2025-05-22	0	3848943		Text		Complaint: Attend site 21.16	
2025-05-22	0	3848943		Text		Found truck air supply low - Check DTC	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2025-05-22		0 3848943		Text		Air up transmission & confirm truck in neutral	
2025-05-22		0 3848943		Text		Advise customer PWM Valve to be replaced	
2025-05-22		0 3848943	Retail	Other	91	Workshop Consumables	
2025-04-17	1188729	3039497	Retail	Operation	VO-1774600	Annual service. Chassis lubrication and	14
2025-04-17	1188729	3039497		Text		oil changes included only in some models	
2025-04-17	1188729	3039497	Retail	Other	1750400	Lubrication according to actual	
2025-04-17	1188729	3039497		Text		lubrication chart	
2025-04-17	1188729	3039497	Retail	Other	1751500	Oil and filter, engine, change	
2025-04-17	1188729	3039497	Retail	Other	1752300	Gearbox oil and filter, replace. Lube	
2025-04-17	1188729	3039497		Text		area	
2025-04-17	1188729	3039497	Retail	Other	1752700	Final drive oil, change. Lube area	
2025-04-17	1188729	3039497	Retail	Other	2141300	Valves and unit injectors, adjust	
2025-04-17	1188729	3039497		Text		Use ASA sheet.	
2025-04-17	1188729	3039497	Retail	Other	2341400	Filter for fuel tank ventilation,	
2025-04-17	1188729	3039497		Text		replace	
2025-04-17	1188729	3039497	Retail	Other	2562700	Filter insert, air cleaner, replace.	
2025-04-17	1188729	3039497		Text		Only valid for primary filter	
2025-04-17	1188729	3039497	Retail	Other	6403600	Oil and filter, power steering,	
2025-04-17	1188729	3039497		Text		secondary system, replace	
2025-04-17	1188729	3039497	Retail	Other	2562500	Secondary air filter, replace. Air	
2025-04-17	1188729	3039497		Text		filter insert removed	
2025-04-17	1188729	3039497	Retail	Other	5616600	Air drier cassette, replace	
2025-04-17	1188729	3039497	Retail	Other	7714500	Wheel nuts, check tightening (all)	
2025-04-17	1188729	3039497	Retail	Other	8721000	Air filters air conditioning, replace	
2025-04-17	1188729	3039497	Retail	Other	8721400	Air filter air conditioning, replace	
2025-04-17	1188729	3039497		Text		(inside)	
2025-04-17	1188729	3039497	Retail	Other	2582200	Filter, AdBlue, replace	
2025-04-17	1188729	3039497	Retail	Other	3110400	Batteries, charging	
2025-04-17	1188729	3039497	Retail	Other	3111000	Battery cleaning and grease the	
2025-04-17	1188729	3039497		Text		terminals	
2025-04-17	1188729	3039497	Retail	Other	3116800	Battery system, test. Battery tester	
2025-04-17	1188729	3039497	Retail	Other	94	Environmental Levy	
2025-04-17	1188729	3039497	Retail	Other	4362300	Oil sample, check	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2025-04-17	1188729	3039497	Retail	Other	4317700	Gearbox oil sample, take	
2025-04-17	1188729	3039497		Text		Don't change rocker cover gasket on	
2025-04-17	1188729	3039497		Text		Initial valve sets or if Vehicle under	
2025-04-17	1188729	3039497		Text		contract maintenance, as it won't be	
2025-04-17	1188729	3039497		Text		covered unless damaged or split. It is	
2025-04-17	1188729	3039497		Text		mandatory to record before and after	
2025-04-17	1188729	3039497		Text		clearances.	
2025-04-17	1188729	3039497	Retail	Part	VO-85114535	MP8/10 FILTER KIT	1
2025-04-17	1188729	3039497		Text		*** POSSIBLE POLICY CLAIM ***	
2025-04-17	1188729	3039497	Retail	Part	VO-20579690	SUMP PLUG O'RING	1
2025-04-17	1188729	3039497	Retail	Part	MK-57MD42M	***ELEMENT, AIR 'C	2
2025-04-17	1188729	3039497	Retail	Part	VO-85151124	CAB AC FILTER NB	1
2025-04-17	1188729	3039497	Retail	Part	VO-21743197	VENTILATION FILTER	2
2025-04-17	1188729	3039497	Retail	Part	VO-85129688	AIR DRIER FILTER	1
2025-04-17	1188729	3039497		Text		*** POSSIBLE POLICY CLAIM ***	
2025-04-17	1188729	3039497	Retail	Part	MK-5839-87067	FILTER P/STR GRAN	1
2025-04-17	1188729	3039497	Retail	Part	VO-23381558	ADBLUE FILTER NB	1
2025-04-17	1188729	3039497		Text		*** POSSIBLE POLICY CLAIM ***	
2025-04-17	1188729	3039497	Retail	Part	VO-85122800	ATF DEX 3 1 LTR	3
2025-04-17	1188729	3039497	Retail	Part	VO-23448457	SOS VOLVO OIL SAMPLE	3
2025-04-17	1188729	3039497	Retail	Part	OTH-CAL839486	GREASE 100G NLGI 2	3
2025-04-17	1188729	3039497	Retail	Part	VO-22038908	TRANSMISSION FILTER MACK	1
2025-04-17	1188729	3039497	Retail	Part	AU2-CHE23068	ENGINE OIL VDS4.5 15W-40 BULK	48
2025-04-17	1188729	3039497	Retail	Part	VO-24126042	PLAIN WASHER P/STEER RESERVOIR	1
2025-04-17	1188729	3039497	Retail	Part	AU2-CUMQ5926	GASKET 6" OD	1
2025-04-17	1188729	3039497	Retail	Part	AU2-CAL851217	SAE50 TRANS OIL 1 LTR	13.7
2025-04-17	1188729	3039497	Retail	Part	AU2-AMP24078	VOLVO VCS-2 COOLANT BULK	5
2025-04-17	1188729	3039497	Retail	Part	AU2-CAL851217	85W140 GEAR OIL 1 LTR	48
2025-04-17	1188729	3039497	Retail	Part	VO-20736230	MP10 T/COVER GASKET	1
2025-04-17	1188729	3039497		Text		Concern: Annual Service	
2025-04-17	1188729	3039497		Text		Cause: Preventative Maintenance	
2025-04-17	1188729	3039497		Text		Correction: Carried out annual service as per provided	
2025-04-17	1188729	3039497		Text		service swheet. Topped up coolant	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2025-04-17	1188729	3039497		Text		Defects:	
2025-04-17	1188729	3039497		Text		Exhaust Manifold no 5 gasket leaking - major	
2025-04-17	1188729	3039497		Text		Sandwich plated leaking - major	
2025-04-17	1188729	3039497		Text		Air leaks when brake applied, D/S firewall, D/S ABS valve	
2025-04-17	1188729	3039497		Text		Kingpin movement both sides	
2025-04-17	1188729	3039497		Text		Both light bars not working	
2025-04-17	1188729	3039497		Text		Auto greaser over greasing	
2025-04-17	1188729	3039497		Text		Filler tube split	
2025-04-17	1188729	3039497		Text		Exhaust butterfly leaking excessively	
2025-04-17	1188729	3039497	Retail	Other	91	Workshop Consumables	
2025-01-14	1154309	8323407	Retail	Other	ACC	PLEASE FILL IN	
2025-01-14	1154309	8323407		Text		Contact:JIM 0419 657 335	
2025-01-14	1154309	8323407	Internal	Other	360	adblue issue	
2025-01-14	1154309	8323407		Text		has been looked at before see sam for more info	
2025-01-14	1154309	8323407	Internal	Part	VO-20744595	CONNECTOR	1
2025-01-14	1154309	8323407	Internal	Part	VO-20744593	CONNECTOR,SAE 3/8	1
2025-01-14	1154309	8323407	Internal	Part	VO-21032572	CLAMP	2
2025-01-14	1154309	8323407		Text		vehicle derated. isolated and then fault went away	
2025-01-14	1154309	8323407		Text		last ro 8323114	
2025-01-06	1152058	8323114	Warranty	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2025-01-06	1152058	8323114	Warranty	Operation	VO-1701200	Fault codes, reading	0.2
2025-01-06	1152058	8323114	Warranty	Operation	VO-1710000	Road test 17105	0.3
2025-01-06	1152058	8323114	Warranty	Operation	VO-2580700	Pump unit, replace	0.5
2025-01-06	1152058	8323114	Warranty	Operation	VO-2584600	SCR system, test	0.5
2025-01-06	1152058	8323114	Warranty	Operation	VO-3700100	Wiring harness, repair. repair only	0.5
2025-01-06	1152058	8323114	Warranty	Part	VO-24344201	PUMP UNIT	1
2024-12-30	1152058	8323114	Retail	Other	ACC	PLEASE FILL IN	
2024-12-30	1152058	8323114		Text		Contact:JIM 0419 657 335	
2024-12-30	1152058	8323114	Retail	Operation	LO-430	transmission third gear lift off	17
2024-12-30	1152058	8323114		Text		vibration/shudder has had new clutch	
2024-12-30	1152058	8323114	Retail	Part	VO-990001	HOSE CLAMP	1
2024-12-30	1152058	8323114	Retail	Part	VO-22406383	AD BLUE PICK UP FILTER	1
2024-12-30	1152058	8323114	Retail	Part	VO-3944785	COMP AIR FILTER	2

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2024-12-30	1152058	8323114	Retail	Part	VO-990941	NUT M10 FL	1
2024-12-30	1152058	8323114	Retail	Part	AU2-WUR08901	BRAKE CLEAN	3
2024-12-30	1152058	8323114	Retail	Part	VO-1652986	SPIGOT BRG	1
2024-12-30	1152058	8323114	Retail	Part	VO-85022454	CLUTCH CYLINDER, E	1
2024-12-30	1152058	8323114	Retail	Part	VO-22191895	CRANKSHAFT SEAL	1
2024-12-30	1152058	8323114	Retail	Part	VO-995906	BOLT M14*46 THREAD LOCKER	4
2024-12-30	1152058	8323114	Retail	Part	VO-984050	NUT M14 FINE THREAD	4
2024-12-30	1152058	8323114	Retail	Part	AU2-WUR06748	EMERY CLOTH 50MM G240 PER METE	0.5
2024-12-30	1152058	8323114	Retail	Part	AU2-WUR08901	BRAKE CLEAN	1
2024-12-30	1152058	8323114	Retail	Part	VO-961968	PROTECTING PLUG	1
2024-12-30	1152058	8323114	Retail	Part	VO-20593252	PLUG	1
2024-12-30	1152058	8323114	Retail	Part	VO-21339891	RUBBER HOSE 1/2"	0.5
2024-12-30	1152058	8323114	Retail	Part	VO-20722710	HOSE CLAMP	4
2024-12-30	1152058	8323114	Retail	Part	VO-21052612	CONNECTOR	1
2024-12-30	1152058	8323114	Retail	Part	VO-21339891	RUBBER HOSE 1/2"	1
2024-12-30	1152058	8323114	Retail	Part	VO-21380391	CONNECTOR 45 deg	1
2024-12-30	1152058	8323114	Retail	Part	VO-8397707	ELBOW 1/2TU X 1/2TH	1
2024-12-30	1152058	8323114	Retail	Other	97	ENVIRONMENTAL CHARGE	
2024-12-30	1152058	8323114		Text		*** POSSIBLE POLICY CLAIM ***	
2024-12-30	1152058	8323114		Text		*** POSSIBLE POLICY CLAIM ***	
2024-12-30	1152058	8323114		Text		jim.gatt@yahoo.com.au	
2024-12-30	1152058	8323114		Text		CARRIED OUT TESTS AND DIAGNOSTICS AND FOUND INTERNAL F	
2024-12-30	1152058	8323114		Text		servo fitted posable calibration	
2024-12-30	1152058	8323114		Text		check & report	
2024-12-30	1152058	8323114		Text		WITH CLUTCH UNIT. REMOVED COMPONENTS AROUND TRANSM	
2024-12-30	1152058	8323114		Text		REMOVED TRANSMISSION AND FOUND CLUTCH SYSTEM ALL	
2024-12-30	1152058	8323114		Text		CONTAMINATED WITH MUD, STONES AND DEBRIS. REMOVED CL	
2024-12-30	1152058	8323114		Text		AND FLYWHEEL. CLEANED ALL DEBRIS FROM FLYWHEEL HOUSIN	
2024-12-30	1152058	8323114		Text		TRANSMISSION BELL HOUSING, CLEANED CLUTCH PLATE AND	
2024-12-30	1152058	8323114		Text		PRESSURE PLATE. INSTALLED NEW REAR MAIN SEAL AS OLD ONE	
2024-12-30	1152058	8323114		Text		WAS LEAKING, INSTALLED NEW CLUTCH SERVO, INSTALLED NEV	
2024-12-30	1152058	8323114		Text		SPIGOT BEARING. FITTED BACK FLYWHEEL AND OLD CLEANED	
2024-12-30	1152058	8323114		Text		CLUTCH PLEASE + PRESSURE PLATE. FITTED BACK TRANSMISSIO	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2024-12-30	1152058	8323114		Text		AND ALL COMPONENTS. CALIBRATED TRANSMISSION AND CLUT	
2024-12-30	1152058	8323114		Text		ROAD TESTED TRUCK WITH TEST TRAILER AND CHECKED OPERAT	
2024-12-30	1152058	8323114		Text		+ CHECKED FOR ANY VIBRATION ALL OK.	
2024-12-30	1152058	8323114		Text		NOTE: CUSTOMER HAS BEEN INFORMED THAT THEIR WILL BE NO	
2024-12-30	1152058	8323114		Text		WARRANTY ON THIS JOB.	
2024-12-30	1152058	8323114	Retail	Other	91	WORKSHOP CONSUMABLES	
2024-12-30	1152058	8323114	Warranty	Operation	VO-2580700	Pump unit, replace	0.5
2024-12-30	1152058	8323114	Warranty	Part	VO-24344201	PUMP UNIT	1
2024-12-30	1152058	8323114		Text		check engine light on dash	
2024-12-30	1152058	8323114	Warranty	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2024-12-30	1152058	8323114	Warranty	Operation	VO-1701200	Fault codes, reading	0.2
2024-12-30	1152058	8323114	Warranty	Operation	VO-2584600	SCR system, test	0.5
2024-12-30	1152058	8323114		Text		vehicle to derate	
2024-12-30	1152058	8323114	Warranty	Operation	VO-3700100	Wire harness, repair. repair only	0.5
2024-12-30	1152058	8323114	Warranty	Operation	LO-171	Road test 17105	0.3
2024-10-23	1121344	8321530	Retail	Other	ACC	PLEASE FILL IN	
2024-10-23	1121344	8321530		Text		Contact:JIM 0419 657 335	
2024-10-23	1121344	8321530	Retail	Operation	LO-275	WITH CRUSE CONTROL SET	5
2024-10-23	1121344	8321530		Text		VEHICLE TRAVLING AT 100 KMH	
2024-10-23	1121344	8321530	Retail	Part	VO-20791305	SEALING RING	1
2024-10-23	1121344	8321530	Retail	Part	VO-8171338	LOCK NUT	1
2024-10-23	1121344	8321530	Retail	Part	VO-976055	O-RING	1
2024-10-23	1121344	8321530	Retail	Part	VO-995906	BOLT M14*46 THREAD LOCKER	4
2024-10-23	1121344	8321530	Retail	Part	VO-984050	NUT M14 FINE THREAD	4
2024-10-23	1121344	8321530	Retail	Part	VO-20774242	SENSOR WHEEL	1
2024-10-23	1121344	8321530	Retail	Part	VO-FFS	FREIGHT SYDNEY - PINKENBA	1
2024-10-23	1121344	8321530		Text		jim.gatt@yahoo.com.au	
2024-10-23	1121344	8321530		Text		SPEEDO GAUGE READING 100 KMH	
2024-10-23	1121344	8321530		Text		THE DIGITAL READING THE SAME	
2024-10-23	1121344	8321530		Text		VEHICLE SLOWS DOWN GAUGE STILL	
2024-10-23	1121344	8321530		Text		READING 100 THE DIGITAL READING WILL	
2024-10-23	1121344	8321530		Text		DROP TO ABOUT 90/94 THEN PICK BACK UP	
2024-10-23	1121344	8321530		Text		THE DIGITAL WILL READ 108KMH ALONG WITH	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2024-10-23	1121344	8321530		Text		HIS GPS READING 108 KMH	
2024-10-23	1121344	8321530		Text		FAULT FIND SPEEDO FAULTING CHECKING ALL WIRING FOR	
2024-10-23	1121344	8321530		Text		RUB MARKS ALL OK LOAD TEST WIRING ALL OK TEST SPEED SENS	
2024-10-23	1121344	8321530		Text		ALL OK REMOVE SPEED SENSOR LOOKING FOR DAMMAGE TO SE	
2024-10-23	1121344	8321530		Text		NO DAMMAGE USING PICK TRY TO MOVE SPEEDO RING, FINDING	
2024-10-23	1121344	8321530		Text		SPEEDO RING LOOSE ON MAIN SHAFT, DROP TAIL SHAFT REMOV	
2024-10-23	1121344	8321530		Text		YOKE FIT NEW SPEEDO RING REFIT YOKE TENSION NUT FIT TAIL	
2024-10-23	1121344	8321530		Text		SHAFT	
2024-10-23	1121344	8321530		Text		ROAD TEST ALL OK	
2024-10-23	1121344	8321530		Text		*** POSSIBLE POLICY CLAIM ***	
2024-10-23	1121344	8321530	Retail	Other	91	WORKSHOP CONSUMABLES	
2024-08-26	1105461	3035260	Warranty	Operation	VO-2580700	Pump unit, replace	0.5
2024-08-26	1105461	3035260	Warranty	Part	VO-22851853	ADBLUE PUMP UNIT	1
2024-08-26	1105461	3035260		Text		*** POSSIBLE POLICY CLAIM ***	
2024-08-26	1105461	3035260	Warranty	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2024-08-26	1105461	3035260	Warranty	Operation	VO-1701200	Fault codes, reading	0.2
2024-08-26	1105461	3035260	Warranty	Operation	VO-2584600	SCR system, test	0.5
2024-08-26	1105461	3035260	Warranty	Operation	VO-1709700	Take charge	0.3
2024-08-26	1105461	3035260	Warranty	Operation	VO-1902000	Road test	0.3
2024-05-30		0 8318263		Text		Repair without detail info	
2024-03-27	1077758	7524673	Retail	Other	101	Engine Hours -15791HRS	
2024-03-27	1077758	7524673		Text		JIM 0419 657 335	
2024-03-27	1077758	7524673	Retail	Operation	LO-380	DIAGNOSE & REPORT LOSS ALL DRIVE	1.9
2024-03-27	1077758	7524673		Text		LIGHTENING BOLT CAME UP ON DASH, THERE WAS A	
2024-03-27	1077758	7524673		Text		AGE: 48MTHS	
2024-03-27	1077758	7524673	Retail	Part	VO-24157510	CLUTCH	1
2024-03-27	1077758	7524673	Retail	Part	VO-23020399	DISC	1
2024-03-27	1077758	7524673	Retail	Part	VO-22327069	SOLENOID VALVE	1
2024-03-27	1077758	7524673	Retail	Part	VO-20992763	AIR HOSE	1
2024-03-27	1077758	7524673	Retail	Part	VO-20483426	SEALING RING INPUT SHAFT	1
2024-03-27	1077758	7524673	Retail	Part	VO-20860677	SEALING RING	1
2024-03-27	1077758	7524673	Retail	Part	VO-1652986	SPIGOT BALL BEARING	1
2024-03-27	1077758	7524673	Retail	Part	VO-85022454	CLUTCH CYLINDER, REMAN	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2024-03-27	1077758	7524673	Retail	Part	VO-995906	HEXAGON SCREW M14X46	8
2024-03-27	1077758	7524673	Retail	Part	VO-984050	HEXAGON NUT M14 Fine	8
2024-03-27	1077758	7524673	Retail	Operation	LO-410	RECTIFY FAULTY CLUTCH	13.5
2024-03-27	1077758	7524673		Text		ESTIMATE 4219394 APPROVED BY JIM	
2024-03-27	1077758	7524673	Retail	Part	AU2-WUR08901	BRAKE CLEAN 500ML	1
2024-03-27	1077758	7524673	Retail	Part	VO-947281	WASHER	2
2024-03-27	1077758	7524673	Retail	Part	VO-20497205	GASKET	1
2024-03-27	1077758	7524673	Retail	Part	VO-994559	HOSE CLAMP 22-32mm	1
2024-03-27	1077758	7524673	Retail	Part	AU2-WUR08900	LUBRICANT ULTRA 2040 500ML	2
2024-03-27	1077758	7524673	Retail	Part	AU2-AMP24078	VCS-2 COOLANT PUMP OUT DECANT	10
2024-03-27	1077758	7524673		Text		29/03/2024	
2024-03-27	1077758	7524673		Text		SHUDDER IN THE DRIVELINE & LOSS DRIVE	
2024-03-27	1077758	7524673		Text		NEW SR 666482000331	
2024-03-27	1077758	7524673	Retail	Operation	LO-261	REPAIR COOLANT LEAK	1
2024-03-27	1077758	7524673	Retail	Operation	LO-431	Repair oil leak	1
2024-03-27	1077758	7524673		Text		CHECKED AND REPAIRED COOLANT LEAK FROM HEATER HOSE	
2024-03-27	1077758	7524673		Text		HAD TO TOP UP COOLANT.	
2024-03-27	1077758	7524673		Text		ROAD TEST AND CHECKED OVER,	
2024-03-27	1077758	7524673		Text		REMOVED/INSTALLED GEAR BOX,	
2024-03-27	1077758	7524673		Text		Replace input shaft seal &	
2024-03-27	1077758	7524673		Text		brake intermediate shaft seal	
2024-03-27	1077758	7524673		Text		CHECKED ALL COMPONENTS.	
2024-03-27	1077758	7524673		Text		CLUTCH CYLINDER DAMAGED(SIDE HOUSING FELT CAMEOUT,	
2024-03-27	1077758	7524673		Text		POSITION SENSOR BROKE OFF, METAL WENT THROUGH,	
2024-03-27	1077758	7524673		Text		DAMAGING CLUTCH /PRESSURE SPRINGS.	
2024-03-27	1077758	7524673		Text		REMOVED & REPLACED CLUTCH KIT, CYLINDER , PWM VALVE	
2024-03-27	1077758	7524673		Text		(GEAR BOX ON STAND)	
2024-03-27	1077758	7524673		Text		INSTALLED TAIL SHAFT	
2024-03-27	1077758	7524673		Text		CALIBRATED GEAR BOX/CLUTCH	
2024-03-27	1077758	7524673		Text		EXTRA TIME CLEANING GEAR BOX BELL HOUSING	
2024-03-27	1077758	7524673		Text		(FULL OF DUST ALSO NOTICED INPUT SHAFT SEAL LEAKING)	
2024-03-27	1077758	7524673	Retail	Part	AU2-9701-GT35	GRIPTEK SUZI COIL HANDLES	3
2024-03-27	1077758	7524673	Retail	Other	91	WORKSHOP CONSUMABLES	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2024-02-15	1062169	8315577	Retail	Other	M	PLEASE FILL IN	
2024-02-15	1062169	8315577		Text		Contact:JIM 0419 657 335	
2024-02-15	1062169	8315577	Retail	Operation	LO-860	ac cutting out intermitantly	1
2024-02-15	1062169	8315577		Text		switch connector?	
2024-02-15	1062169	8315577	Retail	Operation	LO-260	check and report on derate fault	1.2
2024-02-15	1062169	8315577	Retail	Part	VO-20779144	Harness	1
2024-02-15	1062169	8315577	Retail	Part	VO-25131431	SWITCH, PRESSURE R	1
2024-02-15	1062169	8315577	Retail	Part	VO-22851853	PUMP UNIT	1
2024-02-15	1062169	8315577	Retail	Part	VO-22303391	SENSOR	1
2024-02-15	1062169	8315577		Text		Run up ac system and check operation.	
2024-02-15	1062169	8315577		Text		Connect laptop and check fault codes.	
2024-02-15	1062169	8315577		Text		Found that high pressure switch connector burnt.	
2024-02-15	1062169	8315577		Text		Remove and replace high pressure switch.	
2024-02-15	1062169	8315577		Text		Remove and replace connector.	
2024-02-15	1062169	8315577		Text		Run up system and check operation all ok.	
2024-02-15	1062169	8315577		Text		Found Nox sensor open circuit.	
2024-02-15	1062169	8315577		Text		Check power grounds and data links all ok.	
2024-02-15	1062169	8315577		Text		Remove and replace Nox sensor.	
2024-02-15	1062169	8315577		Text		Also found faults for adblue pump not responding.	
2024-02-15	1062169	8315577		Text		Carry out adblue dosage test will not dose.	
2024-02-15	1062169	8315577		Text		Remove pickup in adblue tank inspect filter all ok.	
2024-02-15	1062169	8315577		Text		Inspect for kink or crushed hoses all ok.	
2024-02-15	1062169	8315577		Text		Remove and replace adblue dosage pump.	
2024-02-15	1062169	8315577		Text		Carry out dosage test all ok.	
2024-02-15	1062169	8315577		Text		Carry out test drive all ok.	
2024-02-15	1062169	8315577	Retail	Other	91	WORKSHOP CONSUMABLES	
2024-01-19	1049707	8314892	Retail	Other	M	PLEASE FILL IN	
2024-01-19	1049707	8314892		Text		Contact:JIM 0419 657 335	
2024-01-19	1049707	8314892	Retail	Operation	LO-250	low power	6.2
2024-01-19	1049707	8314892		Text		Connect techtool read and print DTC list and	
2024-01-19	1049707	8314892	Retail	Other	97	ENVIRONMENTAL CHARGE	
2024-01-19	1049707	8314892	Retail	Part	VO-22406383	AD BLUE PICK UP FILTER	1
2024-01-19	1049707	8314892	Retail	Part	VO-23381558	ADBLUE FILTER	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-12-20	1045657	8313893	Retail	Operation	VO-2141300	Valves and unit injectors, adjust	3
2023-12-20	1045657	8313893		Text		D13A/C and D16E/G-Completing Check List	
2023-12-20	1045657	8313893	Retail	Operation	VO-2582200	Filter, AdBlue, replace	0.3
2023-12-20	1045657	8313893	Retail	Operation	VO-5616600	Air drier cassette, replace	0.4
2023-12-20	1045657	8313893	Retail	Operation	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.6
2023-12-20	1045657	8313893		Text		area MINERAL	
2023-12-20	1045657	8313893	Retail	Operation	VO-1752700	Final drive oil, change. Lube area	0.6
2023-12-20	1045657	8313893		Text		MINERAL	
2023-12-20	1045657	8313893	Retail	Part	VO-85114535	MP8/MP10 FILTER KIT	1
2023-12-20	1045657	8313893		Text		*** POSSIBLE POLICY CLAIM ***	
2023-12-20	1045657	8313893	Retail	Part	VO-20579690	DOWDY WASHER	1
2023-12-20	1045657	8313893	Retail	Part	VO-20736230	SEALING STRIP	1
2023-12-20	1045657	8313893	Retail	Part	VO-23381558	ADBLUE FILTER	1
2023-12-20	1045657	8313893	Retail	Part	VO-21954674	STRAINER ADBLU	1
2023-12-20	1045657	8313893	Retail	Part	VO-85129688	AIR DRIER KIT	1
2023-12-20	1045657	8313893	Retail	Part	VO-22038908	G/BOX FILTER	1
2023-12-20	1045657	8313893	Retail	Operation	LO-170	fill auto greaser	0.1
2023-12-20	1045657	8313893	Retail	Operation	LO-810	l/h/s bonnet strap broken	0.1
2023-12-20	1045657	8313893	Retail	Operation	LO-460	suspension ride valve leaking air	0.7
2023-12-20	1045657	8313893	Retail	Part	VO-23448457	OIL SAMPLING KIT	2
2023-12-20	1045657	8313893	Retail	Part	AU2-AMP23068	VDS 4.5 ENGINE OIL BULK	52
2023-12-20	1045657	8313893	Retail	Part	AU2-CAL851217	TRANS OIL SAE50 BULK	17
2023-12-20	1045657	8313893	Retail	Part	AU2-CAL851217	DIFF OIL 85W140 BULK	33.1
2023-12-20	1045657	8313893	Retail	Operation	LO-810	LH BONNET STRAP SNAPPED	0.2
2023-12-20	1045657	8313893	Retail	Operation	LO-810	FRONT BONNET MOUNTS LOOSE	0.5
2023-12-20	1045657	8313893	Retail	Operation	LO-560	AIR LINE RUBBED THROUGH ON TREADLE	0.9
2023-12-20	1045657	8313893		Text		VALVE	
2023-12-20	1045657	8313893	Retail	Operation	LO-870	A/C RECEIVER DRYER DUE	4
2023-12-20	1045657	8313893		Text		FOT REPLACEMENT	
2023-12-20	1045657	8313893	Retail	Operation	LO-640	POWER STEER RESERVOIR	0.1
2023-12-20	1045657	8313893		Text		LID WEEPING	
2023-12-20	1045657	8313893	Retail	Operation	LO-210	FAN CONNECTOR MISSING LOCKING	0.5
2023-12-20	1045657	8313893		Text		RING AND IS RUBBING ON BELT	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-12-20	1045657	8313893	Retail	Operation	LO-465	FRONT DIFF BEARING COVER	2.4
2023-12-20	1045657	8313893		Text		PLATE LEAKING	
2023-12-20	1045657	8313893	Retail	Operation	LO-450	CENTRE BEARING RUBBER	0.3
2023-12-20	1045657	8313893		Text		NOT SITTING IN CORRECT	
2023-12-20	1045657	8313893	Retail	Operation	LO-560	AIR LEAK FROM GEARBOX	1.2
2023-12-20	1045657	8313893		Text		AIR TANK FITTING	
2023-12-20	1045657	8313893	Retail	Operation	LO-870	SLEEPER AUX HEATER	0.5
2023-12-20	1045657	8313893		Text		COOLANT LINES LEAKING	
2023-12-20	1045657	8313893	Retail	Operation	LO-210	MINOR COOLANT LEAK FROM AIR	0.2
2023-12-20	1045657	8313893		Text		COMPRESSOR FITTING	
2023-12-20	1045657	8313893	Retail	Operation	LO-922	TURN TABLE JAWS ADJUSTMENT	1
2023-12-20	1045657	8313893		Text		REQUIRED	
2023-12-20	1045657	8313893	Retail	Operation	LO-360	POSITIVE BATTERY CABLES	0.5
2023-12-20	1045657	8313893		Text		NOT SECURE OVER REAR	
2023-12-20	1045657	8313893	Retail	Operation	LO-560	AIR LEAK FROM STEER AXLE	1
2023-12-20	1045657	8313893		Text		QR VALVE AIR FITTING	
2023-12-20	1045657	8313893	Retail	Operation	LO-260	P-CLAMP MISSING FROM	0.4
2023-12-20	1045657	8313893		Text		GEARBOX COOLER PIPE	
2023-12-20	1045657	8313893	Retail	Part	VO-25037181	LATCH HOOD-CHROME	1
2023-12-20	1045657	8313893	Retail	Part	MK-NARV56406	CABLE TIE 1=100PK	1
2023-12-20	1045657	8313893	Retail	Part	VO-21169875	QR VALVE	1
2023-12-20	1045657	8313893	Retail	Part	VO-82781567	RECEIVER DRIER	1
2023-12-20	1045657	8313893	Retail	Part	VO-24126042	PLAIN WASHER	1
2023-12-20	1045657	8313893	Retail	Part	VO-85149415	LEVEL VALVE	1
2023-12-20	1045657	8313893	Retail	Part	VO-3963413	LOCK RING	1
2023-12-20	1045657	8313893	Retail	Part	VO-982508	DOWDY WASHER	2
2023-12-20	1045657	8313893	Retail	Part	VO-990177	CLAMP	1
2023-12-20	1045657	8313893	Retail	Part	VO-990950	NUT M8 FL LOCKING	1
2023-12-20	1045657	8313893		Text		carried out rerouted the cables and ziptied out.	
2023-12-20	1045657	8313893	Retail	Part	VO-8397721	CONNECTOR 1/2TU X 1/4TH	1
2023-12-20	1045657	8313893	Retail	Part	VO-25153781	VALVE	1
2023-12-20	1045657	8313893		Text		removed intake piping and rocker cover, carried out valve	
2023-12-20	1045657	8313893		Text		A/c has been drained. reciever dryer ready to remove.	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-12-20	1045657	8313893		Text		carried out replacment of qr valve	
2023-12-20	1045657	8313893		Text		loosend off and rotaited to correct possition	
2023-12-20	1045657	8313893	Retail	Part	VO-20443754	O-RING	2
2023-12-20	1045657	8313893	Retail	Part	MK-NARV56306	CABLE TIE 1=25PC	1
2023-12-20	1045657	8313893		Text		sample front diff oil only	
2023-12-20	1045657	8313893	Retail	Part	VO-20443759	O-RING	1
2023-12-20	1045657	8313893	Retail	Part	VO-20443754	O-RING	1
2023-12-20	1045657	8313893	Retail	Part	VO-85113770	VALVE	1
2023-12-20	1045657	8313893	Retail	Part	VO-85115771	SENSOR	1
2023-12-20	1045657	8313893	Retail	Part	VO-85151124	CAB FILTER	1
2023-12-20	1045657	8313893	Retail	Part	VO-20443754	O-RING	1
2023-12-20	1045657	8313893	Retail	Part	VO-20443759	O-RING	1
2023-12-20	1045657	8313893		Text		Drained front diff oil.	
2023-12-20	1045657	8313893	Retail	Part	VO-8397717	TUBE FITTING	1
2023-12-20	1045657	8313893		Text		sample trans oil	
2023-12-20	1045657	8313893		Text		TENSIONER	
2023-12-20	1045657	8313893		Text		Removed cover and cleaned all mating surfaces and bolt	
2023-12-20	1045657	8313893		Text		threads. Resealed and installed cover. Refilled diff oil	
2023-12-20	1045657	8313893		Text		and Steam cleaned vehicle.	
2023-12-20	1045657	8313893		Text		(AT CLUTCH HOUSING)	
2023-12-20	1045657	8313893		Text		R/R receiver drier and o-rings.	
2023-12-20	1045657	8313893		Text		Vacummed system and monitored for leaks. OK.	
2023-12-20	1045657	8313893		Text		Charged system with 1.49kg of R134a.(Vehicle has AUX	
2023-12-20	1045657	8313893		Text		climate unit). Checked operation of A/C. System is not	
2023-12-20	1045657	8313893		Text		cycling. Pressures only changing with engine fan turning	
2023-12-20	1045657	8313893		Text		on and off and High side getting too high.	
2023-12-20	1045657	8313893		Text		Suspect faulty TX valve.	
2023-12-20	1045657	8313893		Text		Recovered refridgerant. Removed air intake pipe for	
2023-12-20	1045657	8313893		Text		access. R/R TX valve and O-rings on both sides. R/R A/C	
2023-12-20	1045657	8313893		Text		filter and evap temp sensor. Vacuumed down system and	
2023-12-20	1045657	8313893		Text		checked for leaks. OK.	
2023-12-20	1045657	8313893		Text		Charged system with 1.49kg of R134a and carried out	
2023-12-20	1045657	8313893		Text		function check of system. All OK.	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-12-20	1045657	8313893		Text		POSITION.	
2023-12-20	1045657	8313893		Text		OF GEARBOX	
2023-12-20	1045657	8313893		Text		(brakes applied)	
2023-12-20	1045657	8313893		Text		Mack - Ref FST 214 003 07 Engine Valve	
2023-12-20	1045657	8313893		Text		Adjustment MP8 EURO 5 & MP10 -	
2023-12-20	1045657	8313893		Text		Completing Check List	
2023-12-20	1045657	8313893		Text		NOTE: PLEASE CHECK WINDOW OF INITIAL	
2023-12-20	1045657	8313893		Text		VALVE ADJUSTMENT	
2023-12-20	1045657	8313893		Text		set as per impact specifications. refit rockercover and	
2023-12-20	1045657	8313893		Text		intake piping	
2023-12-20	1045657	8313893	Retail	Other	91	WORKSHOP CONSUMABLES	
2023-12-20	1045657	8314403	Internal	Other	870	A/C PIPES MISSING MOUNTING	
2023-12-20	1045657	8314403		Text		BRACKET ON LH SIDE OF	
2023-12-20	1045657	8314403		Text		RADIATOR	
2023-11-08	1021401	8313318	Retail	Other	M	PLEASE FILL IN	
2023-11-08	1021401	8313318		Text		Contact:JIM 0419 657 335	
2023-11-08	1021401	8313318	Internal	Other	360	not getting trailer brake light	
2023-10-09	1009688	3029291	Internal	Operation	LO-MUSEDTR	CUSTOMAIR NOT CHARGING BATTEREIS	7.5
2023-10-09	1009688	3029291	Internal	Part	VO-25154049	INSULATOR	5
2023-10-09	1009688	3029291	Internal	Part	OTH-DXA4122	CA ALTERNATOR 12V 60AMP	1
2023-10-09	1009688	3029291	Internal	Part	OTH-DB-9305	CUSTOMAIR DRIVE BELT 13A0785	1
2023-10-09	1009688	3029291	Internal	Part	OTH-DB-9270	CUSTOMAIR DRIVE BELT 13A0695	1
2023-10-09	1009688	3029291	Internal	Part	OTH-DB-9305	CUSTOMAIR DRIVE BELT 13A0785	1
2023-10-09	1009688	3029291	Internal	Part	OTH-12X3NC8Z	BOLT 1/2 UNC X 3 GR8	3
2023-10-09	1009688	3029291	Internal	Part	OTH-12X2.12NC	BOLT 1/2 UNC X 2-1/2 GR8	4
2023-10-09	1009688	3029291	Internal	Part	OTH-12HTW	WASHER 1/2 GR8	14
2023-10-09	1009688	3029291	Internal	Part	OTH-12NCNYLN	NUT NYLOC 1/2 UNC GR5	7
2023-10-09	1009688	3029291	Internal	Part	OTH-10X40MZPI	M10 X 40 DOME HEAD BOLT	4
2023-10-09	1009688	3029291	Internal	Part	OTH-10MHTW	WASHER M10 X 20 2.0 200HV H/T	8
2023-10-09	1009688	3029291	Internal	Part	OTH-10MNYLN	M10 CL8 NYLOC NUT	4
2023-10-09	1009688	3029291	Internal	Part	OTH-10X50MZPI	M10 X 50 DOME HEAD BOLT	4
2023-10-09	1009688	3029291	Internal	Part	OTH-10MHTW	WASHER M10 X 20 2.0 200HV H/T	8
2023-10-09	1009688	3029291	Internal	Part	OTH-10MNYLN	M10 CL8 NYLOC NUT	4

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-10-09	1009688	3029291	Internal	Part	OTH-10X50MZPI	M10 X 50 DOME HEAD BOLT	4
2023-10-09	1009688	3029291	Internal	Part	OTH-10MHTW	WASHER M10 X 20 2.0 200HV H/T	8
2023-10-09	1009688	3029291	Internal	Part	OTH-10MNYLN	M10 CL8 NYLOC NUT	4
2023-10-09	1009688	3029291	Internal	Part	OTH-ACX1211	BLACK INSULATION TAPE	1
2023-10-09	1009688	3029291	Internal	Part	OTH-NARV5712	CABLE LUG 10MM X 6MM	1
2023-10-09	1009688	3029291	Internal	Part	OTH-NARV5712	CABLE LUG 16MM X 6MM	1
2023-10-09	1009688	3029291	Internal	Part	OTH-PROTECT2	CLOTH HARNESS TAPE	1
2023-09-13	1009688	3027921	Internal	Operation	LO-MUSEDTR	PAINT BONNET - GLOSS WHITE	17.55
2023-09-13	1009688	3027921	Internal	Other	10M	TUFF COATINGS - TANKS & BULLBAR	
2023-09-13	1009688	3027921	Internal	Part	VO-21707766	685 HP MP10 LABEL	2
2023-09-13	1009688	3027921	Internal	Part	OTH-156046.54	WATTYL SUPER ETCH PRIMER	1
2023-09-13	1009688	3027921	Internal	Other	10M	COLOUR STOP - PAINT SUPPLIES	
2023-09-13	1009688	3027921	Internal	Part	MK-5165-475SB	KNOB FOR VOLUME	1
2023-09-13	1009688	3027921	Internal	Part	MK-FAL9094	DECAL LARGE LOGO	1
2023-09-13	1009688	3027921	Internal	Part	MK-NARV56448	CABLE TIE MNTS	1
2023-09-13	1009688	3027921	Internal	Part	MK-5165-475SB	KNOB FOR VOLUME	1
2023-09-13	1009688	3027921	Internal	Other	10M	WTG - DIESEL BY 100LTRS - 12/10/2023	
2023-09-13	1009688	3027921		Text		AS PER QUOTE EXTRA COST FOR POWDERCOAT COLOUR	
2023-08-28	1009780	3027383	Internal	Operation	LO-USED	Used Truck Inspection	2.5
2023-08-28	1009780	3027383		Text		Carry out Mechanical Inspection.	
2023-08-28	1009780	3027383		Text		Carry out Brake Test.	
2023-08-28	1009780	3027383		Text		Complete Engine Oil Sample.	
2023-08-28	1009780	3027383	Internal	Operation	VO-2100400	Compression test, with PC	2
2023-08-28	1009780	3027383		Text		Please send results to Shannan.	
2023-08-28	1009780	3027383	Internal	Operation	LO-223	OIL COOLER	9
2023-08-28	1009780	3027383	Internal	Operation	VO-7734600	Wheel seal, replace (drive axle)	4
2023-08-28	1009780	3027383	Internal	Part	MK-8236-MACK	KIT FA537 STEMCO WHEEL STEER	2
2023-08-28	1009780	3027383	Internal	Part	VO-25087788	LOCK WASHER FRT AXLE	2
2023-08-28	1009780	3027383	Internal	Part	MK-312GB367C	EXCH OIL COOLER	1
2023-08-28	1009780	3027383	Internal	Part	MK-57GC2136C	E6 FILTER KIT	1
2023-08-28	1009780	3027383	Internal	Part	VO-25167470	ROLLER	3
2023-08-28	1009780	3027383	Internal	Part	AU2-CUMQ5926	GASKET 6" OD	1
2023-08-28	1009780	3027383	Internal	Part	VO-20705490	GASKET	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-08-28	1009780	3027383	Internal	Part	AU2-7843-3303	GASKET HUBCAP STEER	2
2023-08-28	1009780	3027383	Internal	Part	VO-20705965	GASKET	2
2023-08-28	1009780	3027383	Internal	Part	AU2-CUM25259	RUBBER GASKET COVE	1
2023-08-28	1009780	3027383	Internal	Part	VO-25623930	OIL SEAL	1
2023-08-28	1009780	3027383	Internal	Part	AU2-7843-3101	AXLE RING	2
2023-08-28	1009780	3027383	Internal	Part	VO-25054217	GASKET	2
2023-08-28	1009780	3027383	Internal	Part	VO-20705993	OIL SEAL	1
2023-08-28	1009780	3027383	Internal	Part	VO-20705760	OIL SEAL	1
2023-08-28	1009780	3027383	Internal	Part	VO-20704810	GASKET	1
2023-08-28	1009780	3027383	Internal	Part	VO-20705967	GASKET	1
2023-08-28	1009780	3027383	Internal	Part	AU2-CUMCC26	RESTORE CLEANER (3	1
2023-08-28	1009780	3027383	Internal	Part	OTH-3418280	RX SUPER	2
2023-08-28	1009780	3027383	Internal	Part	OTH-FREIGHT	FREIGHT & HANDLING CHARGE	25
2023-08-28	1009780	3027383	Internal	Operation	VO-2131100	Cylinder liners and pistons, replace (Al	6.8
2023-08-28	1009780	3027383	Internal	Part	VO-21254035	CYLINDER LINER KIT	1
2023-08-28	1009780	3027383	Internal	Part	VO-994445	FLANGE SCREW	1
2023-08-28	1009780	3027383	Internal	Part	VO-984816	BOLT FLANGE M12 X 40 10.9 SILV	13
2023-08-28	1009780	3027383	Internal	Part	VO-8131198	SCREW CON ROD	4
2023-08-28	1009780	3027383	Internal	Part	VO-20734156	MP10 SUMP GASKET	1
2023-08-28	1009780	3027383	Internal	Part	VO-21780376	SEALING RING	1
2023-08-28	1009780	3027383	Internal	Part	VO-990719	O-RING	1
2023-08-28	1009780	3027383	Internal	Part	OTH-MP8PAINT	RED MACK CYL HD PAINT	1
2023-08-28	1009780	3027383	Internal	Part	VO-21780371	SEALING RING	1
2023-08-28	1009780	3027383	Internal	Part	VO-21006103	BEARING SHELL KIT	6
2023-08-28	1009780	3027383	Internal	Part	VO-21006109	BEARING SHELL KIT	1
2023-08-28	1009780	3027383	Internal	Part	VO-1674454	SPACER PLATE WASHER	1
2023-08-28	1009780	3027383	Internal	Part	VO-984735	BOLT FLANGE M8 X 25 8.8 BLACK	1
2023-08-28	1009780	3027383	Internal	Part	OTH-LOC40125	LOCTITE 401 SUPERBOND 25ML	1
2023-08-28	1009780	3027383	Internal	Part	OTH-615001354	2"3M GREEN BRISTLE DISC	1
2023-08-28	1009780	3027383	Internal	Part	OTH-LOC51825	LOCTITE 518 FLNGE SEALANT 25ML	1
2023-08-28	1009780	3027383	Internal	Part	OTH-KTDT2	DEUTSCH PLUG 2 PIN KIT	1
2023-08-28	1009780	3027383		Text		Concern: Tick in engine	
2023-08-28	1009780	3027383		Text		Cause: Low compression cylinder number 2	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-08-28	1009780	3027383		Text		Correction: Removed intake cross over, removed rocker	
2023-08-28	1009780	3027383		Text		cover, spring tubs, rocker shaft injectors, upper timing	
2023-08-28	1009780	3027383		Text		cover, cam gear, cam shaft, drained coolant, removed	
2023-08-28	1009780	3027383		Text		coolant bleed lines, thermostat housing and top radiator	
2023-08-28	1009780	3027383		Text		hoses, turbo, intake manifold, exhaust manifold, injector	
2023-08-28	1009780	3027383		Text		harness, fuel supply and return, removed head. Cleaned	
2023-08-28	1009780	3027383		Text		block surface and timing plate. Inspected liner heights.	
2023-08-28	1009780	3027383		Text		Applied sealant to sandwich plate, installed head and	
2023-08-28	1009780	3027383		Text		tensioned. Cleaned and installed exhaust manifold with new	
2023-08-28	1009780	3027383		Text		gaskets and bolts, cleaned and installed intake manifold	
2023-08-28	1009780	3027383		Text		with new gasket and bolts. Installed thermostat housing	
2023-08-28	1009780	3027383		Text		with new o-ring. Installed top radiator hose. Installed	
2023-08-28	1009780	3027383		Text		cam shaft and cam gear adjusted backlash to spec. Cleaned	
2023-08-28	1009780	3027383		Text		and installed upper timing cover with new gasket. Cleaned	
2023-08-28	1009780	3027383		Text		and installed injectors with new o-rings and bolts,	
2023-08-28	1009780	3027383		Text		installed rocker shaft, carried out tune up, Installed	
2023-08-28	1009780	3027383		Text		rocker with new gasket. Installed injector harness with	
2023-08-28	1009780	3027383		Text		new o-ring. Installed fuel lines, filled up coolant and	
2023-08-28	1009780	3027383		Text		engine oil. Washed down. Test drove. NEW SN 231520420 OLD	
2023-08-28	1009780	3027383		Text		SN 142732048	
2023-08-28	1009780	3027383		Text		(All). Cylinder heads and oil pan removed	
2023-08-28	1009780	3027383	Internal	Operation	VO-2154400	Camshaft bearings, replace	5.6
2023-08-28	1009780	3027383	Warranty	Operation	VO-2112600	Cylinder head, replace	13.3
2023-08-28	1009780	3027383	Warranty	Part	VO-24121331	CYL HEAD 16L *critical	1
2023-08-28	1009780	3027383	Warranty	Part	VO-1675066	TURBO INTAKE SEAL - BOOST SEAL	2
2023-08-28	1009780	3027383	Warranty	Part	VO-1677370	SEALING RING	2
2023-08-28	1009780	3027383	Warranty	Part	VO-20483919	SCREW TIMING GEAR IDLER	1
2023-08-28	1009780	3027383	Warranty	Part	VO-20526428	SEALING RING	1
2023-08-28	1009780	3027383	Warranty	Part	VO-20852765	GASKET FUEL LINE	4
2023-08-28	1009780	3027383	Warranty	Part	VO-21015266	MP10 ADJ GEAR SCREW	6
2023-08-28	1009780	3027383	Warranty	Part	VO-21344774	BOLT INJECTOR HOLD DOWN	6
2023-08-28	1009780	3027383	Warranty	Part	VO-21344787	MP10 EXH MAN BOLT	24
2023-08-28	1009780	3027383	Warranty	Part	VO-21345129	SCREW HEAD BOLT	38

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-08-28	1009780	3027383	Warranty	Part	VO-21503575	SEAL THERMOSTAT	1
2023-08-28	1009780	3027383	Warranty	Part	VO-21539900	GASKET KIT MP10 / 16LTR	1
2023-08-28	1009780	3027383	Warranty	Part	VO-3092340	SEALANT VOLVO GREY	1
2023-08-28	1009780	3027383	Warranty	Part	VO-3979639	PRE HEATER GASKET	1
2023-08-28	1009780	3027383	Warranty	Part	VO-467310	V CLAMP TURBO 16LTR *NOTES	1
2023-08-28	1009780	3027383	Warranty	Part	VO-469601	TURBO DRAIN SEAL	1
2023-08-28	1009780	3027383	Warranty	Part	VO-471586	SCREW M8	6
2023-08-28	1009780	3027383	Warranty	Part	VO-471708	COMP INLET SEAL	1
2023-08-28	1009780	3027383	Warranty	Part	VO-8073055	O-RING	1
2023-08-28	1009780	3027383	Warranty	Part	VO-8131393	CAGE	6
2023-08-28	1009780	3027383	Warranty	Part	VO-8192804	MP10 CAM BOLT	8
2023-08-28	1009780	3027383	Warranty	Part	VO-983472	SMALL GREY CABLE TIE	6
2023-08-28	1009780	3027383	Warranty	Part	VO-984735	BOLT FLANGE M8 X 25 8.8 BLACK	6
2023-08-28	1009780	3027383	Warranty	Part	VO-984738	FLANGE SCREW M8 X 40MM	2
2023-08-28	1009780	3027383	Warranty	Part	VO-990950	NUT FLANGE M8 X 9.4 GR 8 BLK	1
2023-08-28	1009780	3027383	Warranty	Part	VO-993811	TURBO MOUNT BOLT	4
2023-08-28	1009780	3027383	Warranty	Part	VO-994441	BOLT FLANGE M8 X 50 8.8 BLACK	1
2023-08-28	1009780	3027383	Warranty	Part	VO-994447	BOLT FLANGE M8 X 25 8.8 BLACK	6
2023-08-28	1009780	3027383	Warranty	Part	VO-996457	FLANGE SCREW INLET MANIFOLD	12
2023-08-28	1009780	3027383	Warranty	Part	AU2-WUR05854	NWOVN-SHT-A320-GRE	2
2023-08-28	1009780	3027383	Warranty	Part	VO-21695684	SEALING RING	2
2023-08-28	1009780	3027383	Warranty	Part	VO-20938964	EXHAUST MANIFOLD SLIP SEAL	1
2023-08-28	1009780	3027383	Warranty	Part	VO-976012	O-RING	1
2023-08-28	1009780	3027383	Warranty	Part	VO-949656	O-RING DIPSTICK	1
2023-08-28	1009780	3027383	Warranty	Part	VO-944126	INJECTOR HARNESS O-RING	1
2023-08-28	1009780	3027383	Warranty	Part	VO-21053055	HOSE HEADER TANK BLEED LINE	1
2023-08-28	1009780	3027383	Warranty	Part	VO-983472	SMALL GREY CABLE TIE	4
2023-08-28	1009780	3027383	Warranty	Part	VO-1675066	TURBO INTAKE SEAL - BOOST SEAL	1
2023-08-28	1009780	3027383	Warranty	Part	VO-977237	COMPRESSOR OIL FEED HOSE *NOTE	1
2023-08-28	1009780	3027383	Warranty	Part	VO-993451	NIPPLE	1
2023-08-28	1009780	3027383	Warranty	Part	VO-8082135	ELBOW 90 DEG M12 TH X 1/4 TBE	1
2023-08-28	1009780	3027383		Text		NEW SN:231520420	
2023-08-28	1009780	3027383		Text		OLD SN:142732048	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-08-28	1009780	3027383	Warranty	Operation	VO-1820200	Localised wash for fault tracing	0.3
2023-08-28	1009780	3027383	Warranty	Operation	VO-1902000	Road test	0.3
2023-08-28	0	3027950		Text		Repair without detail info	
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	SWITCH BLANK IN DASH	0.1
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	REPLACE BOTH WINDSCREENS - IF REQUIRED	1
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	FIT NEW DASH MAT	0.5
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	S & F 2 X BLACK SEAT COVERS	1
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	FIT NEW FLOOR MATS	0.5
2023-08-04	0	3027210	Internal	Other	MUSEDTRUCK	REPAIR CUSTOM AIR VENTS	
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	SERVICE CUSTOM AIR	2
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	BUFF CAB	12.07
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	PAINT 1/4 GUARDS, PRE CLEANERS AND WINGS	11.5
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	BRUSH TOUCH	0.87
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	BLACK MACK MUDFLAPS ALL ROUND	2.5
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	REPLACE RHS HEADLIGHT	1
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	REPLACE ROADTRAIN SIGNS	3.8
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	PAINT GRILLES ON BULLBAR	1
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	PAINT DOOR HANDLES	2
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	SECURE CHAIN ON DOLLEY PULL PIN	0.5
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	STRAIGHTEN CUSTOM AIR COVER	2
2023-08-04	0	3027210	Internal	Other	MUSEDTRUCK	SECURE FRONT OF RUBBER DRIVE GUARDS	
2023-08-04	0	3027210	Internal	Other	MUSEDTRUCK	FIT WHEEL CHROME	
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	REPLACE LHS 1/4 GUARD IF NEEDED	1.5
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	SATIN BLACK STONE GUARD	0.5
2023-08-04	0	3027210	Internal	Part	VO-25159354	SWITCH BLANKING PLUG	4
2023-08-04	0	3027210	Internal	Part	VO-85121040	DASH MAT NEW BREED GREY	1
2023-08-04	0	3027210	Internal	Part	VO-23990990	FLOOR MAT SET NEW BREED	1
2023-08-04	0	3027210	Internal	Part	AU2-SHEISR168	ISRI 6860/870 RH/LH SHEEP BLAC	1
2023-08-04	0	3027210	Internal	Part	AU2-CUMLF689	**LUBE FILTER (REP.L	1
2023-08-04	0	3027210	Internal	Part	AU2-CUMFS125	**F/W/SEP (REPS FS12	1
2023-08-04	0	3027210	Internal	Part	AU2-CUMFF149	**FUEL FILTER	1
2023-08-04	0	3027210	Internal	Part	MK-2191-P8226	ICEPACK 2000 AIR FILTER	1
2023-08-04	0	3027210	Internal	Part	OTH-3418278	CASTROL RX SUPER 5L CUSTOMAIR	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-08-04	0	3027210	Internal	Part	MK-9728-2424B	MUDFLAP MACK BLACK 24 X 24	2
2023-08-04	0	3027210	Internal	Part	MK-9728-3024B	MUDFLAP MACK BLACK 30 X 24	2
2023-08-04	0	3027210	Internal	Part	MK-9728-1824B	MACK MUDFLAP BLACK 18 X 24	2
2023-08-04	0	3027210	Internal	Part	VO-24299758	HEADLAMP	1
2023-08-04	0	3027210	Internal	Part	AU2-9719-CIXTC	ROAD TRAIN 2 PCE	1
2023-08-04	0	3027210	Internal	Part	OTH-NCP33U	** 32/33MM SCREW ON NUT COVER	60
2023-08-04	0	3027210	Internal	Part	MK-9711-0011M	MACK STEER HUBCAP W/LOGO	2
2023-08-04	0	3027210	Internal	Part	MK-9711-9208C	CHROME HUBCAP VOLVO AXLE W CLI	4
2023-08-04	0	3027210	Internal	Part	VO-22759114	MUDGUARD	1
2023-08-04	0	3027210	Internal	Part	OTH-FREIGHT	FREIGHT & HANDLING CHARGE	40
2023-08-04	0	3027210	Internal	Other	10M	NOVUS - REPLACE X2 WINDSCREENS - 10/08	
2023-08-04	0	3027210	Internal	Other	10M	K & F TINTING - REMOVE/RETINT RH DOOR	
2023-08-04	0	3027210	Internal	Operation	LO-MUSEDTR	P2 TURNTABLE MODIFICATION	1
2023-08-04	0	3027210	Internal	Part	VO-25171845	WINDSCREEN MOULD / SEAL	1
2023-08-04	0	3027210	Internal	Part	OTH-MODPLATE	MOD PLATE	1
2023-06-20	0	3026024	Internal	Operation	VO-2153000	Sealant, timing gear plate, replace. Gea	13.1
2023-06-20	0	3026024		Text		Gearbox and clutch removed	
2023-06-20	0	3026024	Internal	Operation	VO-4657500	Differential carrier, disassemble-assem	5.2
2023-06-20	0	3026024		Text		Diff leak from pinion, front lower pinion and main gasket.	
2023-06-20	0	3026024	Internal	Operation	VO-2510800	Exhaust manifold, replace	2.7
2023-06-20	0	3026024		Text		Inspect and advise manifold leak.	
2023-06-20	0	3026024	Internal	Part	VO-22438707	TIMING GEAR PLATE	1
2023-06-20	0	3026024	Internal	Part	VO-20532891	ENG BREATHER GSKT	1
2023-06-20	0	3026024	Internal	Part	VO-20734156	MP10 SUMP GASKET	1
2023-06-20	0	3026024	Internal	Part	VO-20736230	MP10 T/COVER GASKET	1
2023-06-20	0	3026024	Internal	Part	VO-20815558	TIMING GR CVR GASKET	1
2023-06-20	0	3026024	Internal	Part	VO-20852765	GASKET FUEL LINE	4
2023-06-20	0	3026024	Internal	Part	VO-21015266	MP10 ADJ GEAR SCREW	1
2023-06-20	0	3026024	Internal	Part	VO-21185132	TIMING COVER SEAL	2
2023-06-20	0	3026024	Internal	Part	VO-21724614	SEALING	2
2023-06-20	0	3026024	Internal	Part	VO-3092340	SEALANT VOLVO GREY	1
2023-06-20	0	3026024	Internal	Part	VO-471708	COMP INLET SEAL	1
2023-06-20	0	3026024	Internal	Part	VO-8192804	MP10 CAM BOLT	8

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-06-20	0	3026024	Internal	Part	VO-943177	O-RING	1
2023-06-20	0	3026024	Internal	Part	VO-949656	O-RING DIPSTICK	1
2023-06-20	0	3026024	Internal	Part	VO-976068	PTO O-RING (ENGINE)	1
2023-06-20	0	3026024	Internal	Part	VO-977030	O-RING	1
2023-06-20	0	3026024	Internal	Part	VO-982508	GASKET	1
2023-06-20	0	3026024	Internal	Part	VO-983762	BOLT SOCKET M14 X 45 10.9	1
2023-06-20	0	3026024	Internal	Part	VO-984127	O-RING	1
2023-06-20	0	3026024	Internal	Part	VO-984738	FLANGE SCREW M8 X 40MM	6
2023-06-20	0	3026024	Internal	Part	VO-984740	FLANGE SCREW M8 X 60MM	1
2023-06-20	0	3026024	Internal	Part	VO-990719	O-RING	1
2023-06-20	0	3026024	Internal	Part	VO-992065	O-RING	1
2023-06-20	0	3026024	Internal	Part	VO-994447	BOLT FLANGE M8 X 25 8.8 BLACK	25
2023-06-20	0	3026024	Internal	Part	VO-995658	O-RING	1
2023-06-20	0	3026024	Internal	Other	310	BATTERY AND MOUNTING PARTS - GENERAL	
2023-06-20	0	3026024	Internal	Part	VO-22795757	LOCKING KNOB	2
2023-06-20	0	3026024	Internal	Part	VO-22791849	BATTERY COVER	1
2023-06-20	0	3026024	Internal	Other	100	Labour	
2023-06-20	0	3026024		Text		PARTS ORDERED IN JAN	
2023-06-20	0	3026024	Internal	Other	USED	Used Truck Inspection	
2023-06-20	0	3026024		Text		Carry out Mechanical Inspection.	
2023-06-20	0	3026024		Text		Carry out Brake Test.	
2023-06-20	0	3026024		Text		Complete Engine Oil Sample.	
2023-06-20	0	3026024		Text		(2hrs Labour + Sample Bottle)	
2023-06-20	0	3026024	Internal	Other	100	GR Advice	
2023-06-20	0	3026024	Internal	Part	VO-21634024	PRESSURE SENSOR	1
2023-06-20	0	3026024	Internal	Part	VO-21582423	BACK PRS WIRE KIT	1
2023-06-20	0	3026024	Internal	Part	OTH-ACX1136A	HT SHRINK 38MMP/CM	10
2023-06-20	0	3026024	Internal	Part	OTH-21849032	EARTH CABLE STARTER TO FRAME	1
2023-06-20	0	3026024	Internal	Part	VO-1592924	TEST CONNECTOR-M16	1
2023-06-20	0	3026024	Internal	Part	VO-20448956	16mm-1/4 FITTING	1
2023-06-20	0	3026024	Internal	Part	VO-993224	T NIPPLE M16XM16XM16	1
2023-06-20	0	3026024	Internal	Part	VO-21017200	VALVE	1
2023-06-20	0	3026024	Internal	Part	VO-85108352	REAR CRANKSHAFT SEAL	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-06-20	0	3026024	Internal	Part	VO-982508	GASKET	1
2023-06-20	0	3026024	Internal	Other	1000	CARRY OUT BASIC SERVICE & LUBRICATION	
2023-06-20	0	3026024	Internal	Other	100	Replace front engine mount	
2023-06-20	0	3026024	Internal	Other	100	Replace sagged aeon rubbers	
2023-06-20	0	3026024	Internal	Other	100	Air leak form gearbox air fill port	
2023-06-20	0	3026024		Text		Next to steering resivour	
2023-06-20	0	3026024	Internal	Other	100	Replace Steering Unis-Greaseless	
2023-06-20	0	3026024	Internal	Other	100	Tighten exhaust butterfly clamp	
2023-06-20	0	3026024	Internal	Other	100	Central locking inop	
2023-06-20	0	3026024	Internal	Other	100	Reset RSL to 100klm	
2023-06-20	0	3026024	Internal	Other	100	Replace Windscreen	
2023-06-20	0	3026024	Internal	Other	10	Sublet Novus	
2023-06-20	0	3026024	Internal	Other	100	Resecure Vehicle ID plate	
2023-06-20	0	3026024	Internal	Other	100	No Electric horn	
2023-06-20	0	3026024	Internal	Other	100	P/S bullbar indicator inop	
2023-06-20	0	3026024	Internal	Other	100	Repair front diff oil leak	
2023-06-20	0	3026024	Internal	Other	100	Replace engine oil filler neck oring	
2023-06-20	0	3026024	Internal	Part	VO-85114535	MP8/10 FILTER KIT	1
2023-06-20	0	3026024		Text		*** POSSIBLE POLICY CLAIM ***	
2023-06-20	0	3026024	Internal	Part	VO-20579690	SUMP PLUG O'RING	1
2023-06-20	0	3026024	Internal	Part	VO-20503550	FRONT ENGINE MOUNT	1
2023-06-20	0	3026024	Internal	Part	VO-22254125	AEON RUBBER SPRING	2
2023-06-20	0	3026024	Internal	Part	MK-2104-21221	STEERING UNI GREASELESS *notes	2
2023-06-20	0	3026024	Internal	Part	AU2-4381-2109	12V LED INDICATOR	2
2023-06-20	0	3026024	Internal	Part	VO-21780376	SEALING RING	1
2023-06-20	0	3026024	Internal	Part	VO-20770742	THROUGH SHAFT SEAL VOLVO	1
2023-06-20	0	3026024	Internal	Part	VO-995906	BOLT HEX M14	4
2023-06-20	0	3026024	Internal	Part	VO-984050	NUT HEX M14 FINE PITCH PC 10	4
2023-06-20	0	3026024	Internal	Part	VO-22203349	ELECTRIC DOOR LOCK	1
2023-06-20	0	3026024	Internal	Part	VO-20448956	16mm-1/4 FITTING	1
2023-06-20	0	3026024	Internal	Part	VO-22225326	EXHAUST PIPE CLAMP	1
2023-06-20	0	3026024	Internal	Part	VO-20375162	CABLE TERMINAL	2
2023-06-20	0	3026024	Internal	Part	VO-990053	HOUSING 2 PIN	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-06-20		0 3026024	Internal	Part	VO-992151	SEALING	2
2023-06-20		0 3026024	Internal	Part	VO-983013	CABLE TERMINAL	1
2023-06-20		0 3026024	Internal	Part	OTH-AT233005	PVC INSULATION TAPE	1
2023-06-20		0 3026024	Internal	Part	VO-984846	CABLE TERMINAL	2
2023-06-20		0 3026024	Internal	Part	VO-990053	HOUSING 2 PIN	1
2023-06-20		0 3026024	Internal	Part	VO-995906	BOLT HEX M14	8
2023-06-20		0 3026024	Internal	Part	VO-984050	NUT HEX M14 FINE PITCH PC 10	8
2023-06-20		0 3026024	Internal	Part	VO-467310	V CLAMP TURBO 16LTR *NOTES	1
2023-06-20		0 3026024	Internal	Part	VO-990950	NUT FLANGE M8 X 9.4 GR 8 BLK	1
2023-06-20		0 3026024	Internal	Part	VO-994441	BOLT FLANGE M8 X 50 8.8 BLACK	1
2023-06-20		0 3026024	Internal	Part	VO-21029030	V CLAMP	1
2023-06-20		0 3026024	Internal	Part	VO-976013	O-RING	2
2023-06-20		0 3026024	Internal	Part	VO-984751	FLANGE SCREW M10 X 16MM	1
2023-06-20		0 3026024	Internal	Part	VO-85122800	ATF DEX 3 1 LTR	3
2023-06-20		0 3026024	Internal	Part	VO-22074217	HEAT SHIELD TEMPERATURE SENSOR	1
2023-06-20		0 3026024	Internal	Part	OTH-KT3834825	370 X4.8MM CABLE TE	1
2023-06-20		0 3026024	Internal	Part	OTH-LOC56707	LOCTITE 567	1
2023-06-20		0 3026024	Internal	Part	VO-21448461	DIFF PINION SEAL	1
2023-06-20		0 3026024	Internal	Part	VO-85113736	STEERING SHAFT BOOT NEW BREED	1
2023-06-20		0 3026024	Internal	Part	VO-984734	FLANGE SCREW M8 X 20MM	1
2023-06-20		0 3026024	Internal	Part	VO-990940	FLANGE NUT M8	1
2023-06-20		0 3026024	Internal	Part	VO-995906	BOLT HEX M14	4
2023-06-20		0 3026024	Internal	Part	VO-984050	NUT HEX M14 FINE PITCH PC 10	4
2023-06-20		0 3026024	Internal	Part	VO-8171338	M DRIVE OUTPUT LOCK NUT	1
2023-06-20		0 3026024	Internal	Part	VO-1675066	TURBO INTAKE SEAL	1
2023-06-20		0 3026024	Internal	Part	VO-20592783	V-CLAMP	1
2023-06-20		0 3026024	Internal	Part	VO-21659813	INLET HOSE	1
2023-06-20		0 3026024	Internal	Part	OTH-LOC56707	LOCTITE 567	1
2023-06-20		0 3026024	Internal	Part	OTH-KTDT2	DEUTSCH PLUG 2 PIN KIT	3
2023-06-20		0 3026024	Internal	Part	AU2-AMP23068	ENGINE OIL VDS4.5 15W-40 BULK	50
2023-06-20		0 3026024	Internal	Part	AU2-AMP85147	VOLVO VCS COOLANT PER LITRE	1.1
2023-06-12	973746	3026277	Internal	Part	VO-21705662	ANTENNA	1
2023-06-12	973746	3026269	Contract	Part	VO-21705662	ANTENNA	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-06-12	973746	3026269	Contract	Operation	VO-3974600	Telematics system, GPS, test	0.2
2023-06-12	973746	3026269	Contract	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2023-06-12	973746	3026269	Contract	Operation	VO-1783000	Diagnostic Time	0.1
2023-06-12	973746	3026269	Contract	Operation	VO-1701200	Fault codes, reading	0.2
2023-06-12	973746	3026269		Text		Customer comment that vehicle is not tracking. Inspect	
2023-06-12	973746	3026269		Text		and repair.	
2023-06-12	973746	3026269	Contract	Operation	VO-3973300	Telematics system, SIM ID, calibration	0.2
2023-06-12	973746	3026269	Contract	Operation	VO-3977500	MID 141 Control unit, programming	0.7
2023-06-12	973746	3026269	Contract	Operation	VO-3950800	Antenna, replace	0.3
2023-06-12	973746	3026269	Contract	Part	VO-21385255	ANTENNA CABLE	1
2023-06-12	973746	3026269		Text		*** POSSIBLE POLICY CLAIM ***	
2023-06-12	973746	5001486		Text		Concern: Telematics not tracking	
2023-06-12	973746	5001486		Text		Cause: Open circuit in telematics arial	
2023-06-12	973746	5001486		Text		Correction: Connected tech tool. Retrieved mid141	
2023-06-12	973746	5001486		Text		psid3fmi14. Checked location of Volvo connect – found	
2023-06-12	973746	5001486		Text		location incorrect. Reprogrammed M141 & calibrated sime.	
2023-06-12	973746	5001486		Text		Checked both arials & found open circuit. Ordered new	
2023-06-12	973746	5001486		Text		arials.	
2023-06-12	973746	5001486	Contract	Part	VO-21705662	ANTENNA	2
2023-06-12	973746	5001486	Contract	Operation	VO-3974600	Telematics system, GPS, test	0.2
2023-06-12	973746	5001486	Contract	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2023-06-12	973746	5001486	Contract	Operation	VO-1783000	Diagnostic Time	0.1
2023-06-12	973746	5001486	Contract	Operation	VO-1701200	Fault codes, reading	0.2
2023-06-12	973746	5001486		Text		Customer comment that vehicle is not tracking. Inspect	
2023-06-12	973746	5001486		Text		and repair.	
2023-06-12	973746	5001486	Contract	Operation	VO-3973300	Telematics system, SIM ID, calibration	0.2
2023-06-12	973746	5001486	Contract	Operation	VO-3977500	MID 141 Control unit, programming	0.7
2023-06-12	973746	5001486	Contract	Operation	LO-395	MISCELLANEOUS - RADIO EQUIPMENT	0.4
2023-06-12	973746	5001486		Text		Remove & replace 2 antennas	
2023-06-12	973746	5001486		Text		... Note: No Impact VST for this repair and have used first	
2023-06-12	973746	5001486		Text		three digits of function group of causal part as operation	
2023-06-12	973746	5001486		Text		and claiming time taken.	
2023-06-12	973746	5001486	Contract	Part	VO-21385255	ANTENNA CABLE	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-06-12	973746	5001486	Contract	Operation	LO-395	MISCELLANEOUS - RADIO EQUIPMENT	1.2
2023-06-12	973746	5001486		Text		Remove & replace antennas cable	
2023-06-12	973746	5001486		Text		... Note: No Impact VST for this repair and have used first	
2023-06-12	973746	5001486		Text		three digits of function group of causal part as operation	
2023-06-12	973746	5001486		Text		and claiming time taken.	
2023-05-26	1002193	3023804	Internal	Other	2124000	Timing gear plate, replace	
2023-05-26	1002193	3023804	Internal	Other	2341700	Fuel tank, check	
2023-05-26	1002193	3023804		Text		LH fuel tank leaking @ bracket weld	
2023-05-26	1002193	3023804	Internal	Operation	VO-4342400	Front differential carrier, remove	1.9
2023-05-26	1002193	3023804		Text		Concern: Diff leak	
2023-05-26	1002193	3023804		Text		Cause: Leaking	
2023-05-26	1002193	3023804		Text		Correction: Inspected - rebooked	
2023-05-26	1002193	3023804		Text		Concern: Sandwich plate	
2023-05-26	1002193	3023804		Text		Cause: Leaking	
2023-05-26	1002193	3023804		Text		Correction: Inspected - rebooked	
2023-05-26	1002193	3023804		Text		Concern: LHS fuel tank leak	
2023-05-26	1002193	3023804		Text		Cause: Leaking	
2023-05-26	1002193	3023804		Text		Correction: Looking over both LHS fuel tanks & found no	
2023-05-26	1002193	3023804		Text		leaks	
2023-05-26	1002193	3023804		Text		Concern: Annual service	
2023-05-26	1002193	3023804		Text		Cause: Due	
2023-05-26	1002193	3023804		Text		Correction: Carried out 998,000 km annual service as per	
2023-05-26	1002193	3023804		Text		VOSP service sheet. Changed coolant, power steering oil &	
2023-05-26	1002193	3023804		Text		filter, engine oil & filters, tested batteries, fitted	
2023-05-26	1002193	3023804		Text		auto greaser. Plugged in tech tool.	
2023-05-26	1002193	3023804		Text		Custom air hours: 1280hrs.	
2023-05-26	1002193	3023804		Text		Faults:	
2023-05-26	1002193	3023804		Text		Exhaust manifold leak (rebooked)	
2023-05-26	1002193	3023804		Text		Sandwich plate leak (rebooked)	
2023-05-26	1002193	3023804		Text		Coolant leak under cab X 2 – done – tightened hose clamps	
2023-05-26	1002193	3023804		Text		Cab mounts & aeon rubbers (DS)	
2023-05-26	1002193	3023804		Text		Coolant leak out of compressor head fitting	
2023-05-26	1002193	3023804		Text		Cover missing off flashing light	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-05-26	1002193	3023804		Text		Diff leaking from pinion, front lower pinion cover and	
2023-05-26	1002193	3023804		Text		main gasket (rebooked)	
2023-05-26	1002193	3023804		Text		Ad blue leak on ad blue pump fitting, filler neck cracked	
2023-05-26	1002193	3023804		Text		- done	
2023-05-26	1002193	3023804		Text		Concern: Exhaust clamp broken	
2023-05-26	1002193	3023804		Text		Cause: Worn	
2023-05-26	1002193	3023804		Text		Correction: Removed nuts from D bolt exhaust clamp.	
2023-05-26	1002193	3023804		Text		Removed exhaust & removed clamp. Replace with new clamp.	
2023-05-26	1002193	3023804		Text		Put exhaust back into place, all ok.	
2023-05-26	1002193	3023804	Contract	Operation	VO-1774600	Annual service. Chassis lubrication and	2.4
2023-05-26	1002193	3023804		Text		oil changes included only in some models	
2023-05-26	1002193	3023804	Contract	Operation	VO-2562700	Filter insert, air cleaner, replace. Onl	0.2
2023-05-26	1002193	3023804		Text		Only valid for primary filter	
2023-05-26	1002193	3023804	Contract	Operation	VO-2601000	Coolant, change	0.4
2023-05-26	1002193	3023804	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2023-05-26	1002193	3023804	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2023-05-26	1002193	3023804		Text		area	
2023-05-26	1002193	3023804	Contract	Operation	VO-7714500	Wheel nuts, check tightening (all)	0.3
2023-05-26	1002193	3023804	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2023-05-26	1002193	3023804	Contract	Operation	VO-6452500	Oil filter, power steering, replace	0.2
2023-05-26	1002193	3023804	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2023-05-26	1002193	3023804	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2023-05-26	1002193	3023804		Text		*** POSSIBLE POLICY CLAIM ***	
2023-05-26	1002193	3023804	Contract	Part	VO-20579690	SUMP PLUG O'RING	1
2023-05-26	1002193	3023804	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	47
2023-05-26	1002193	3023804	Contract	Part	MK-57MD42M	***ELEMENT, AIR 'C	2
2023-05-26	1002193	3023804	Contract	Part	MK-5839-87067	FILTER P/STR GRAN	1
2023-05-26	1002193	3023804	Contract	Part	VO-85122800	ATF DEX 3 1 LTR	3
2023-05-26	1002193	3023804		Text		*** POSSIBLE POLICY CLAIM ***	
2023-05-26	1002193	3023804	Contract	Operation	VO-3116800	Battery system, test. Battery tester	0.4
2023-05-26	1002193	3023804	Contract	Operation	VO-1709700	Take charge	0.3
2023-05-26	1002193	3023804	Contract	Operation	VO-2525100	Clamp, exhaust pipe, replace	0.4
2023-05-26	1002193	3023804		Text		Exhaust clamp back of engine broken	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-05-26	1002193	3023804	Contract	Part	VO-22225326	EXHAUST PIPE CLAMP	1
2023-05-26	1002193	3023804	Contract	Operation	LO-179	Service -Pick up and delivery	1
2023-05-26	1002193	3023804	Contract	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2023-05-26	1002193	3023804	Contract	Operation	VO-1783000	Diagnostic Time	0.1
2023-05-26	1002193	3023804	Contract	Operation	VO-1701200	Fault codes, reading	0.2
2023-05-26	1002193	3023804	Contract	Operation	VO-4112600	Clutch wear, check. VCADS Pro operation	0.2
2023-05-26	1002193	3023804	Contract	Part	VO-82710488	WIPER BLADE BASIC	2
2023-05-26	1002193	3023804	Contract	Operation	VO-3630400	Windscreen wiper blade, replace	0.1
2023-05-26	1002193	3023804	Contract	Part	VO-24178893	FILLER NECK	1
2023-05-26	1002193	3023804	Contract	Part	VO-994447	BOLT FLANGE M8 X 25 8.8 BLACK	2
2023-05-26	1002193	3023804	Contract	Operation	VO-2583200	Aftertreatment diesel exhaust fluid (DEF	0.4
2023-05-26	1002193	3023804		Text		(DEF) tank, filler neck insert, replace	
2023-05-26	1002193	3023804	Contract	Part	AU2-AMP85147	VOLVO VCS COOLANT PER LITRE	7
2023-05-26	1002193	3023804	Contract	Operation	VO-1782200	Coolant, topping up. passanger seat	0.1
2023-05-26	1002193	3023804	Contract	Operation	VO-2600600	Coolant system, pressure test	0.4
2023-04-18	973746	3025327		Text		Concern: Telematics not tracking	
2023-04-18	973746	3025327		Text		Cause: Open circuit in telematics arial	
2023-04-18	973746	3025327		Text		Correction: Connected tech tool. Retrieved mid141	
2023-04-18	973746	3025327		Text		psid3fmi14. Checked location of Volvo connect – found	
2023-04-18	973746	3025327		Text		location incorrect. Reprogrammed M141 & calibrated sime.	
2023-04-18	973746	3025327		Text		Checked both arials & found open circuit. Ordered new	
2023-04-18	973746	3025327		Text		arials.	
2023-04-18	973746	3025327	Contract	Part	VO-21705662	ANTENNA	2
2023-04-18	973746	3025327	Contract	Operation	VO-3974600	Telematics system, GPS, test	0.2
2023-04-18	973746	3025327	Contract	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2023-04-18	973746	3025327	Contract	Operation	VO-1783000	Diagnostic Time	0.1
2023-04-18	973746	3025327	Contract	Operation	VO-1701200	Fault codes, reading	0.2
2023-04-18	973746	3025327		Text		Customer comment that vehicle is not tracking. Inspect	
2023-04-18	973746	3025327		Text		and repair.	
2023-04-18	973746	3025327	Contract	Operation	VO-3973300	Telematics system, SIM ID, calibration	0.2
2023-04-18	973746	3025327	Contract	Operation	VO-3977500	MID 141 Control unit, programming	0.7
2023-04-18	973746	3025327	Contract	Operation	LO-395	MISCELLANEOUS - RADIO EQUIPMENT	0.4
2023-04-18	973746	3025327		Text		Remove & replace 2 antennas	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-04-18	973746	3025327		Text		... Note: No Impact VST for this repair and have used first	
2023-04-18	973746	3025327		Text		three digits of function group of causal part as operation	
2023-04-18	973746	3025327		Text		and claiming time taken.	
2023-04-18	973746	3025327	Contract	Part	VO-21385255	ANTENNA CABLE	1
2023-04-18	973746	3025327	Contract	Operation	LO-395	MISCELLANEOUS - RADIO EQUIPMENT	1.2
2023-04-18	973746	3025327		Text		Remove & replace antennas cable	
2023-04-18	973746	3025327		Text		... Note: No Impact VST for this repair and have used first	
2023-04-18	973746	3025327		Text		three digits of function group of causal part as operation	
2023-04-18	973746	3025327		Text		and claiming time taken.	
2023-04-14	970207	3025120	Internal	Part	OTH-ACX1801	ACX1801	12
2023-04-14	970207	3025120	Internal	Part	OTH-LOC51825	LOCTITE 518 FLNGE SEALANT 25ML	1
2023-04-14	970207	3025120		Text		Truck is being traded shortly - please inspect and	
2023-04-14	970207	3025120		Text		identify any repairs or issues that need to be fixed prior	
2023-04-14	970207	3025120		Text		to contract closing. Carried out inspection during service.	
2023-04-14	970207	3025120		Text		Concern: Basic Service	
2023-04-14	970207	3025120		Text		Concern: Centre bearing	
2023-04-14	970207	3025120		Text		Cause: Excessive movement	
2023-04-14	970207	3025120		Text		Correction: Dropped tailshaft down and removed centre	
2023-04-14	970207	3025120		Text		yolk, removed & replaced centre bearing, refitted yolk	
2023-04-14	970207	3025120		Text		with new bolts.	
2023-04-14	970207	3025120		Text		Concern: Coolant leak	
2023-04-14	970207	3025120		Text		Cause: Header tank cracked & leaking	
2023-04-14	970207	3025120		Text		Correction: Found coolant on top at upper hose.	
2023-04-14	970207	3025120		Text		Pressurised system and found header tank cracked at bleed	
2023-04-14	970207	3025120		Text		fittings. Drained coolant, removed & replaced header tank	
2023-04-14	970207	3025120		Text		& bled lines and refilled coolant and all okay. Tested	
2023-04-14	970207	3025120		Text		coolant and failed, filled with new coolant.	
2023-04-14	970207	3025120		Text		Concern: Heater core fitting coolant leak	
2023-04-14	970207	3025120		Text		Cause: O-ring split	
2023-04-14	970207	3025120		Text		Correction: Removed dash panels to check blower fan &	
2023-04-14	970207	3025120		Text		heater core, fitting leaking, dropped coolant. Removed &	
2023-04-14	970207	3025120		Text		replaced o-ring on heater core fitting. Refilled coolant.	
2023-04-14	970207	3025120		Text		Started and tested all okay.	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-04-14	970207	3025120		Text		Concern: A/C fan not working	
2023-04-14	970207	3025120		Text		Cause: Blower motor internal short circuit	
2023-04-14	970207	3025120		Text		Correction: Checked fuse, okay, checked power at plug and	
2023-04-14	970207	3025120		Text		all okay. Found blower fan blown. Removed dash panels and	
2023-04-14	970207	3025120		Text		removed & replaced blower fan. Tested all okay.	
2023-04-14	970207	3025120		Text		Cause: Due	
2023-04-14	970207	3025120		Text		Correction: Carried out 967,000 km basic service as per	
2023-04-14	970207	3025120		Text		VOSP service sheets & tune up.	
2023-04-14	970207	3025120		Text		Found oil leak. Will need sandwich plate and possibly	
2023-04-14	970207	3025120		Text		head, sandwich plate has major leak at bottom passenger	
2023-04-14	970207	3025120		Text		side, head is starting to have valve recession No 6.	
2023-04-14	970207	3025120		Text		Concern: Coolant mixer tube	
2023-04-14	970207	3025120		Text		Concern Tensioner keyway rounded out	
2023-04-14	970207	3025120		Text		Concern: Water pump	
2023-04-14	970207	3025120		Text		Cause: Collapsed	
2023-04-14	970207	3025120		Text		Concern: Inspect and test water pump, found bearing	
2023-04-14	970207	3025120		Text		notchy & noisy, replace water pump. Fill with coolant,	
2023-04-14	970207	3025120		Text		test drive. Inspect after test drive,	
2023-04-14	970207	3025120		Text		all good.	
2023-04-14	970207	3025120		Text		Concern: Air drier filter	
2023-04-14	970207	3025120		Text		Cause: Blocked	
2023-04-14	970207	3025120		Text		Correction: During service, noticed that the air drier	
2023-04-14	970207	3025120		Text		filter was blocked. Remove & replace air drier filter.	
2023-04-14	970207	3025120		Text		Concern: Ad blue filter	
2023-04-14	970207	3025120		Text		Cause: Blocked	
2023-04-14	970207	3025120		Text		Correction: During service, noticed that the ad blue	
2023-04-14	970207	3025120		Text		filter was blocked. Remove & replace ad blue filter.	
2023-04-14	970207	3025120		Text		Cause: Worn	
2023-04-14	970207	3025120		Text		Correction: When replacing water pump, found tensioner	
2023-04-14	970207	3025120		Text		keyway has rounded out. Removed & replace fan belt	
2023-04-14	970207	3025120		Text		tensioner.	
2023-04-14	970207	3025120		Text		Cause: Cracked	
2023-04-14	970207	3025120		Text		Concern: Removed & replaced mixer tube.	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-04-14	970207	3025120		Text		Concern: Oil leak at rear of engine (inspection only)	
2023-04-14	970207	3025120		Text		Cause: Suspect sealant fail between sandwich plate & back	
2023-04-14	970207	3025120		Text		Correction: Inspected oil leak and found sandwich plate	
2023-04-14	970207	3025120		Text		leak at top right rear of engine and bottom left rear,	
2023-04-14	970207	3025120		Text		suspect sealant failure.	
2023-04-14	970207	3025120	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2023-04-14	970207	3025120		Text		*** POSSIBLE POLICY CLAIM ***	
2023-04-14	970207	3025120	Contract	Part	VO-20579690	SUMP PLUG O'RING	1
2023-04-14	970207	3025120	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2023-04-14	970207	3025120		Text		oil changes included only in some models	
2023-04-14	970207	3025120		Text		CHANGE OILS AFTER ANY REPAIRS	
2023-04-14	970207	3025120		Text		NEEDED ARE REPORTED - BASIC	
2023-04-14	970207	3025120		Text		SERVICE	
2023-04-14	970207	3025120	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2023-04-14	970207	3025120	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2023-04-14	970207	3025120		Text		area	
2023-04-14	970207	3025120	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2023-04-14	970207	3025120	Contract	Operation	VO-2141300	Valves and unit injectors, adjust	2.1
2023-04-14	970207	3025120		Text		Use ASA sheet.	
2023-04-14	970207	3025120		Text		Don't change rocker cover gasket on	
2023-04-14	970207	3025120		Text		Initial valve sets or if Vehicle under	
2023-04-14	970207	3025120		Text		contract maintenance, as it won't be	
2023-04-14	970207	3025120		Text		covered unless damaged or split. It is	
2023-04-14	970207	3025120		Text		mandatory to record before and after	
2023-04-14	970207	3025120		Text		clearances.	
2023-04-14	970207	3025120	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2023-04-14	970207	3025120	Contract	Operation	VO-1706800	36 Months ECU download and oil sample. O	0.9
2023-04-14	970207	3025120		Text		Only valid for Australian market	
2023-04-14	970207	3025120	Contract	Other	1784600	Trailer coupling, safety and function	
2023-04-14	970207	3025120		Text		check	
2023-04-14	970207	3025120	Contract	Part	VO-23448457	SOS VOLVO OIL SAMPLE	4
2023-04-14	970207	3025120	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	50
2023-04-14	970207	3025120	Contract	Operation	VO-1709700	Take charge	0.3

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-04-14	970207	3025120	Contract	Operation	LO-179	Service -Pick up and delivery	1
2023-04-14	970207	3025120	Contract	Operation	VO-4530200	Intermediate bearing, replace	1
2023-04-14	970207	3025120	Contract	Part	VO-23707800	CENTRE BEARING	1
2023-04-14	970207	3025120	Contract	Part	VO-984050	NUT HEX M14 FINE PITCH PC 10	4
2023-04-14	970207	3025120	Contract	Part	VO-995906	BOLT HEX M14	4
2023-04-14	970207	3025120	Contract	Operation	VO-2611800	Expansion tank, replace	0.7
2023-04-14	970207	3025120	Contract	Part	VO-23915461	EXPANSION TANK MACK NB	1
2023-04-14	970207	3025120	Contract	Part	VO-21053055	HOSE HEADER TANK BLEED LINE	1
2023-04-14	970207	3025120	Contract	Part	VO-21053033	HOSE	1
2023-04-14	970207	3025120	Contract	Part	AU2-AMP85147	VOLVO VCS COOLANT PER LITRE	45
2023-04-14	970207	3025120	Contract	Operation	VO-2600600	Coolant system, pressure test	0.4
2023-04-14	970207	3025120	Contract	Operation	VO-2602700	Coolant, draining	0.4
2023-04-14	970207	3025120	Contract	Operation	VO-2602800	Coolant, filling	0.5
2023-04-14	970207	3025120	Contract	Operation	VO-2614000	Coolant distributor pipe, replace	0.1
2023-04-14	970207	3025120	Contract	Operation	LO-874	AIR CONDITIONING	0.6
2023-04-14	970207	3025120	Contract	Part	VO-85143813	O-RING	1
2023-04-14	970207	3025120	Contract	Part	VO-20443770	O-RING	1
2023-04-14	970207	3025120		Text		... Note: No Impact VST for this repair and have used first	
2023-04-14	970207	3025120		Text		three digits of function group of causal part as operation	
2023-04-14	970207	3025120		Text		and claiming time taken.	
2023-04-14	970207	3025120	Contract	Operation	VO-8730600	Blower motor, replace	0.6
2023-04-14	970207	3025120	Contract	Part	VO-85113771	BLOWER MOTOR**	1
2023-04-14	970207	3025120	Contract	Part	VO-85151124	CAB AC FILTER NB	1
2023-04-14	970207	3025120	Contract	Operation	VO-8747400	Air filter insert, A/C unit, replace	0.3
2023-04-14	970207	3025120	Contract	Operation	VO-2442600	Coolant supply line, replace	0.9
2023-04-14	970207	3025120	Contract	Part	VO-21420336	CONNECTING PIPE	1
2023-04-14	970207	3025120	Contract	Part	VO-20799996	SEAL CONNECTION PIPE	1
2023-04-14	970207	3025120	Contract	Part	VO-21423788	SEALING RING	1
2023-04-14	970207	3025120	Contract	Part	AU2-AMP24078	VCS-2 COOLANT 5L	1
2023-04-14	970207	3025120	Contract	Part	VO-24152059	WATER PUMP MP10	1
2023-04-14	970207	3025120	Contract	Part	VO-20965822	FLANGE SCREW M8 X 55	1
2023-04-14	970207	3025120	Contract	Part	VO-984740	FLANGE SCREW M8 X 60MM	6
2023-04-14	970207	3025120	Contract	Operation	VO-2620200	Coolant pump, replace	1.1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-04-14	970207	3025120	Contract	Operation	VO-1782200	Coolant, topping up. passanger seat	0.1
2023-04-14	970207	3025120	Contract	Part	VO-85129688	AIR DRIER FILTER	1
2023-04-14	970207	3025120		Text		*** POSSIBLE POLICY CLAIM ***	
2023-04-14	970207	3025120	Contract	Operation	VO-5616600	Air drier cassette, replace	0.4
2023-04-14	970207	3025120	Contract	Part	VO-23381558	ADBLUE FILTER NB	1
2023-04-14	970207	3025120		Text		*** POSSIBLE POLICY CLAIM ***	
2023-04-14	970207	3025120	Contract	Operation	VO-2582200	Filter, AdBlue, replace	0.3
2023-04-14	970207	3025120		Text		During service, noticed that the ad blue filter was blocked	
2023-04-14	970207	3025120	Contract	Part	AU2-AMP23068:	VOLVO ENGINE OIL VDS4.5 5LT	1
2023-04-14	970207	3025120	Contract	Part	VO-22950501	BELT TENSIONER	1
2023-04-14	970207	3025120		Text		*** POSSIBLE POLICY CLAIM ***	
2023-04-14	970207	3025120	Contract	Operation	VO-2631300	Fan belt tensioner, replace	0.4
2023-03-16	948644	3024719	Internal	Operation	VO-8857300	Kitchen, water push, replace	0.2
2023-03-16	948644	3024719		Text		Customer reports that the water trap wiring plug has	
2023-03-16	948644	3024719		Text		fallen out	
2023-03-16	948644	3024719		Text		Concern: Airbag leak	
2023-03-16	948644	3024719		Text		Concern: Sump bolts	
2023-03-16	948644	3024719		Text		Cause: Missing	
2023-03-16	948644	3024719		Text		Correction: Fitted x2 new sump bolts, tensioned all sump	
2023-03-16	948644	3024719		Text		bolts.	
2023-03-16	948644	3024719		Text		Concern: Bracket	
2023-03-16	948644	3024719		Text		Cause: Missing/loose bolts	
2023-03-16	948644	3024719		Text		Correction: Tighten loose bolts on fuel line bracket near	
2023-03-16	948644	3024719		Text		fuel filters. Replaced missing bolts as well.	
2023-03-16	948644	3024719		Text		Cause: Leaking from fitting	
2023-03-16	948644	3024719		Text		Correction: Sprayed all airbags, found not leaks. Found	
2023-03-16	948644	3024719		Text		leak from fitting on 1st LH airbag. Replaced fitting,	
2023-03-16	948644	3024719		Text		leak fixed.	
2023-03-16	948644	3024719		Text		Concern: Fuel filter wiring	
2023-03-16	948644	3024719		Text		Cause: Unplugged plug	
2023-03-16	948644	3024719		Text		Correction: Plugged fuel filter plug in	
2023-03-16	948644	3024719	Contract	Operation	VO-7260300	Air bellows, driven axle, check	0.4
2023-03-16	948644	3024719	Contract	Part	MK-FT1872X6X6	FITTING 3/8 THR / 3/8 TUBE	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-03-16	948644	3024719		Text		Drive axle air bag fitting loose/broken NR	
2023-03-16	948644	3024719	Contract	Operation	VO-1709700	Take charge	0.3
2023-03-16	948644	3024719	Contract	Operation	LO-217	OIL SUMP	0.3
2023-03-16	948644	3024719		Text		Customers reports that there are 2 sump bolts missing	
2023-03-16	948644	3024719	Contract	Part	VO-22859764	SUMP ISOLATOR BOLT	2
2023-03-16	948644	3024719		Text		(workshop has 1)	
2023-03-16	948644	3024719		Text		... Note: No Impact VST for this repair and have used first	
2023-03-16	948644	3024719		Text		three digits of function group of causal part as operation	
2023-03-16	948644	3024719		Text		and claiming time taken.	
2023-03-16	948644	3024719	Contract	Operation	VO-2331300	Fuel filter, check	0.3
2023-03-16	948644	3024719		Text		Customer report that the bracket near fuel filter has a	
2023-03-16	948644	3024719		Text		loose bolt	
2023-02-28	938269	3024376	Internal	Part	OTH-KT3827525	CABLE TIE 380 X 7.5MM	1
2023-02-28	938269	3024376	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2023-02-28	938269	3024376		Text		oil changes included only in some models	
2023-02-28	938269	3024376		Text		CHANGE OILS AFTER ANY REPAIRS	
2023-02-28	938269	3024376		Text		NEEDED ARE REPORTED - BASIC	
2023-02-28	938269	3024376		Text		SERVICE	
2023-02-28	938269	3024376	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2023-02-28	938269	3024376	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2023-02-28	938269	3024376		Text		area	
2023-02-28	938269	3024376	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2023-02-28	938269	3024376	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2023-02-28	938269	3024376	Contract	Operation	VO-1706800	36 Months ECU download and oil sample. O	0.9
2023-02-28	938269	3024376		Text		Only valid for Australian market	
2023-02-28	938269	3024376		Text		FH ONLY	
2023-02-28	938269	3024376	Contract	Operation	VO-1784600	Trailer coupling, safety and function ch	0.2
2023-02-28	938269	3024376		Text		check	
2023-02-28	938269	3024376	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2023-02-28	938269	3024376		Text		*** POSSIBLE POLICY CLAIM ***	
2023-02-28	938269	3024376	Contract	Part	VO-20579690	SUMP PLUG O'RING	1
2023-02-28	938269	3024376	Contract	Part	AU2-WUR08923	CLNR-WSCRN-RAPID-3	1
2023-02-28	938269	3024376	Contract	Part	AU2-CAL851217	MACK GREASE 450G	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-02-28	938269	3024376	Contract	Part	AU2-AMP23068:	VOLVO ENGINE OIL VDS4.5 5LT	1
2023-02-28	938269	3024376	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	50
2023-02-28	938269	3024376	Contract	Part	VO-23448457	SOS VOLVO OIL SAMPLE	1
2023-02-28	938269	3024376	Contract	Part	VO-23448457	SOS VOLVO OIL SAMPLE	2
2023-02-28	938269	3024376	Contract	Part	AU2-CEN12310:	BATT N70ZZH CENTURY	4
2023-02-28	938269	3024376		Text		*** POSSIBLE POLICY CLAIM ***	
2023-02-28	938269	3024376	Contract	Operation	VO-3110200	Batteries, replace (all)	0.8
2023-02-28	938269	3024376	Contract	Part	MK-57MD42M	***ELEMENT, AIR 'C	2
2023-02-28	938269	3024376		Text		*** POSSIBLE POLICY CLAIM ***	
2023-02-28	938269	3024376	Contract	Operation	VO-2562400	Filter insert, air cleaner, replace. Onl	0.2
2023-02-28	938269	3024376		Text		Only valid for primary filter	
2023-02-28	938269	3024376	Contract	Operation	VO-2562500	Secondary air filter, replace. Air filte	0.2
2023-02-28	938269	3024376		Text		filter insert removed	
2023-02-28	938269	3024376	Contract	Operation	VO-2612000	Radiator hose, replace (Upper). ncl. dra	0.6
2023-02-28	938269	3024376	Contract	Part	VO-22891922	HOSE	1
2023-02-28	938269	3024376		Text		drain coolant	
2023-02-28	938269	3024376	Contract	Operation	VO-8185500	Air spring, replace	0.7
2023-02-28	938269	3024376	Contract	Part	VO-22058741	AIR SPRING	2
2023-02-28	938269	3024376		Text		*** POSSIBLE POLICY CLAIM ***	
2023-02-28	938269	3024376	Contract	Other	179	Service -Pick up and delivery	
2023-02-28		0 3024421		Text		Repair without detail info	
2023-02-15	928123	3023755	Internal	Part	VO-82278929	SWITCH CRUISE CONTROL *NOTES	1
2023-02-15	928123	3023755		Text		**Charging to internal rework as sensor was replaced prior	
2023-02-15	928123	3023755		Text		to being replaced again - Refer Damian + Luke**	
2023-02-15	928123	3023755		Text		Concern: Cruise control not working	
2023-02-15	928123	3023755		Text		Cause: Short circuit in set/resume switch	
2023-02-15	928123	3023755		Text		Correction: Tested switch operation, found not working.	
2023-02-15	928123	3023755		Text		Replaced switch and tested all okay. Refitted dash.	
2023-02-15	928123	3023755	Contract	Operation	VO-3658800	Steering wheel switches, replace (cruise	0.3
2023-02-15	928123	3023755	Contract	Part	VO-82278929	SWITCH CRUISE CONTROL *NOTES	1
2023-02-15	928123	3023755		Text		control)	
2023-02-15	928123	3023755	Contract	Operation	VO-1709700	Take charge	0.3
2023-02-15	928123	3023755	Contract	Operation	VO-2750300	Cruise control, test	0.5

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-01-24	910303	3023703	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2023-01-24	910303	3023703		Text		oil changes included only in some models	
2023-01-24	910303	3023703		Text		CHANGE OILS AFTER ANY REPAIRS	
2023-01-24	910303	3023703		Text		NEEDED ARE REPORTED - BASIC	
2023-01-24	910303	3023703		Text		SERVICE	
2023-01-24	910303	3023703	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2023-01-24	910303	3023703	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2023-01-24	910303	3023703		Text		area	
2023-01-24	910303	3023703	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2023-01-24	910303	3023703	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2023-01-24	910303	3023703	Contract	Operation	VO-1784600	Trailer coupling, safety and function ch	0.2
2023-01-24	910303	3023703		Text		check	
2023-01-24	910303	3023703	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2023-01-24	910303	3023703		Text		*** POSSIBLE POLICY CLAIM ***	
2023-01-24	910303	3023703	Contract	Part	VO-20579690	SUMP PLUG O'RING	1
2023-01-24	910303	3023703	Contract	Part	AU2-WUR08923	CLNR-WSCRN-RAPID-3	1
2023-01-24	910303	3023703	Contract	Part	AU2-AMP23068:	VOLVO ENGINE OIL VDS4.5 5LT	1
2023-01-24	910303	3023703	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	50
2023-01-24	910303	3023703	Contract	Operation	LO-179	Service -Pick up and delivery	1
2023-01-24	910303	3023703	Warranty	Operation	VO-2170200	Oil pan gasket, replace. Campaign only	1.6
2023-01-24	910303	3023703	Warranty	Part	VO-20734156	MP10 SUMP GASKET	1
2023-01-24	910303	3023703		Text		*** POSSIBLE POLICY CLAIM ***	
2023-01-17	903607	3023626		Text		Concern: Knocking noise under cab	
2023-01-17	903607	3023626		Text		Concern: During repair job 1 found hose clamp on airbox	
2023-01-17	903607	3023626		Text		Cause: Front RH cab mount bushes + aeon rubbers hard/worn	
2023-01-17	903607	3023626		Text		Correction: Inspected all components, found cab mount	
2023-01-17	903607	3023626		Text		bushes worn on both sides causing aeon rubbers to perish.	
2023-01-17	903607	3023626		Text		R & R with new, also found cab shocks leaking, replaced,	
2023-01-17	903607	3023626		Text		all okay.	
2023-01-17	903607	3023626		Text		loose	
2023-01-17	903607	3023626		Text		Cause: Loose/letting go	
2023-01-17	903607	3023626		Text		Correction: R & R hose clamp with new, all okay.	
2023-01-17	903607	3023626	Contract	Operation	VO-8182600	Cab shock absorber rear, replace (two)	0.5

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2023-01-17	903607	3023626	Contract	Part	VO-20975430	FRONT CAB MOUNT	2
2023-01-17	903607	3023626	Contract	Part	VO-22254125	AEON RUBBER SPRING	2
2023-01-17	903607	3023626	Contract	Part	VO-20874147	CAB SHOCK RR NB	1
2023-01-17	903607	3023626		Text		*** POSSIBLE POLICY CLAIM ***	
2023-01-17	903607	3023626	Contract	Operation	LO-81839	Cab mounting kit, front, install	0.6
2023-01-17	903607	3023626	Contract	Operation	VO-8185500	Air spring, replace	0.7
2023-01-17	903607	3023626	Contract	Part	VO-25085669	CLAMP-HOSE-NO.116	1
2023-01-17	903607	3023626	Contract	Operation	VO-2651200	Clamp or o-ring, replace	0.4
2022-12-13	808770	3023098		Text		Concern: Air bags leaking air	
2022-12-13	808770	3023098		Text		Cause: Worn bags	
2022-12-13	808770	3023098		Text		Correction: Sprayed soap water on air bags to identify	
2022-12-13	808770	3023098		Text		leaks, found rear drive front air bags perished and	
2022-12-13	808770	3023098		Text		leaking remove air lines going to air bags and replace air	
2022-12-13	808770	3023098		Text		bags, replace with new air bags and test drove vehicle	
2022-12-13	808770	3023098		Text		all okay.	
2022-12-13	808770	3023098	Contract	Operation	VO-7260200	Air bellows, drive axle, replace	0.4
2022-12-13	808770	3023098	Contract	Part	VO-22058737	AIR SPRING	2
2022-12-13	808770	3023098	Contract	Part	MK-FT1872X6X6	FITTING 3/8 THR / 3/8 TUBE	2
2022-12-13	808770	3023098	Contract	Operation	VO-5638700	Air fitting, replace	0.4
2022-12-13	808770	3023098	Contract	Operation	LO-170	road test	0.5
2022-12-13	808770	5001287		Text		Concern: Air bags leaking air	
2022-12-13	808770	5001287		Text		Cause: Worn bags	
2022-12-13	808770	5001287		Text		Correction: Sprayed soap water on air bags to identify	
2022-12-13	808770	5001287		Text		leaks, found rear drive front air bags perished and	
2022-12-13	808770	5001287		Text		leaking remove air lines going to air bags and replace air	
2022-12-13	808770	5001287		Text		bags, replace with new air bags and test drove vehicle	
2022-12-13	808770	5001287		Text		all okay.	
2022-12-13	808770	5001287	Contract	Operation	VO-7260200	Air bellows, drive axle, replace	0.4
2022-12-13	808770	5001287	Contract	Part	VO-22058737	AIR SPRING	2
2022-12-13	808770	5001287	Contract	Part	MK-FT1872X6X6	FITTING 3/8 THR / 3/8 TUBE	2
2022-12-13	808770	5001287	Contract	Operation	VO-5638700	Air fitting, replace	0.4
2022-12-13	808770	5001287	Contract	Operation	LO-170	road test	0.5
2022-12-12	878385	3023051	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-12-12	878385	3023051		Text		oil changes included only in some models	
2022-12-12	878385	3023051		Text		CHANGE OILS AFTER ANY REPAIRS	
2022-12-12	878385	3023051		Text		NEEDED ARE REPORTED - BASIC	
2022-12-12	878385	3023051		Text		SERVICE	
2022-12-12	878385	3023051	Contract	Operation	VO-3212300	Alternator belt, replace	0.3
2022-12-12	878385	3023051	Contract	Operation	VO-2630700	Drive belts fan, replace	0.5
2022-12-12	878385	3023051	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2022-12-12	878385	3023051	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2022-12-12	878385	3023051		Text		area	
2022-12-12	878385	3023051	Contract	Operation	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.4
2022-12-12	878385	3023051		Text		area	
2022-12-12	878385	3023051	Contract	Operation	VO-1752700	Final drive oil, change. Lube area	0.6
2022-12-12	878385	3023051	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2022-12-12	878385	3023051	Contract	Operation	VO-5616600	Air drier cassette, replace	0.4
2022-12-12	878385	3023051	Contract	Operation	VO-2582200	Filter, AdBlue, replace	0.3
2022-12-12	878385	3023051	Contract	Operation	VO-3210700	Belt tensioner, alternator, replace	0.3
2022-12-12	878385	3023051	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2022-12-12	878385	3023051	Contract	Operation	VO-2630800	Fan belt tensioner, replace	0.4
2022-12-12	878385	3023051	Contract	Operation	VO-2551800	Engine turbocharger, replace. Chassis mo	2.2
2022-12-12	878385	3023051		Text		mounted	
2022-12-12	878385	3023051	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2022-12-12	878385	3023051		Text		*** POSSIBLE POLICY CLAIM ***	
2022-12-12	878385	3023051	Contract	Part	VO-20579690	SUMP PLUG O'RING	1
2022-12-12	878385	3023051	Contract	Part	VO-23961777	FAN BELT	1
2022-12-12	878385	3023051	Contract	Part	VO-23961744	ALTERNATOR BELT	1
2022-12-12	878385	3023051	Contract	Part	VO-23402101	BELT TENSIONER	1
2022-12-12	878385	3023051	Contract	Part	VO-22950501	BELT TENSIONER	1
2022-12-12	878385	3023051	Contract	Part	VO-22038908	TRANSMISSION FILTER MACK	1
2022-12-12	878385	3023051	Contract	Part	VO-85129688	AIR DRIER FILTER	1
2022-12-12	878385	3023051		Text		*** POSSIBLE POLICY CLAIM ***	
2022-12-12	878385	3023051	Contract	Part	VO-23381558	ADBLUE FILTER NB	1
2022-12-12	878385	3023051		Text		*** POSSIBLE POLICY CLAIM ***	
2022-12-12	878385	3023051	Contract	Part	VO-21638569	EXCH TURBOCHARGER *NOTES	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-12-12	878385	3023051	Contract	Part	VO-1675066	TURBO INTAKE SEAL	1
2022-12-12	878385	3023051	Contract	Part	VO-20562526	SPACER SLEEVE	4
2022-12-12	878385	3023051	Contract	Part	VO-20784537	TURBO BASE GASKET	1
2022-12-12	878385	3023051	Contract	Part	VO-21940610	SEAL FEED OF HOUSING	1
2022-12-12	878385	3023051	Contract	Part	VO-21940615	TURBO DRN SEAL(BLOCK	1
2022-12-12	878385	3023051	Contract	Part	VO-22206133	TURBO FEED GASKET	1
2022-12-12	878385	3023051	Contract	Part	VO-467310	V CLAMP TURBO 16LTR *NOTES	1
2022-12-12	878385	3023051	Contract	Part	VO-470993	GASKET RETURN PIPE	1
2022-12-12	878385	3023051	Contract	Part	VO-8073055	O-RING	1
2022-12-12	878385	3023051	Contract	Part	VO-990950	NUT FLANGE M8 X 9.4 GR 8 BLK	1
2022-12-12	878385	3023051	Contract	Part	VO-993811	TURBO MOUNT BOLT	4
2022-12-12	878385	3023051	Contract	Part	VO-994441	BOLT FLANGE M8 X 50 8.8 BLACK	1
2022-12-12	878385	3023051	Contract	Part	AU2-AMP85136:	SYN TRANS OIL 20L 5108-220 *	20
2022-12-12	878385	3023051	Contract	Part	AU2-AMP85136:	VOLVO SYNTHETIC AX	40
2022-12-12	878385	3023051		Text		*** POSSIBLE POLICY CLAIM ***	
2022-12-12	878385	3023051	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	52
2022-12-12	878385	3023051	Contract	Other	179	Service -Pick up and delivery	
2022-12-12	878385	3023051	Contract	Part	VO-21352841	EXH MAN GASKET	6
2022-12-12	878385	3023051	Contract	Part	VO-21344787	MP10 EXH MAN BOLT	24
2022-12-12	878385	3023051	Contract	Part	VO-20938964	EXHAUST MANIFOLD SLIP SEAL	1
2022-12-12	878385	3023051	Contract	Part	VO-21695684	SEALING RING	2
2022-12-12	878385	3023051	Contract	Operation	VO-2510400	Gaskets, exhaust manifold, replace	2.7
2022-12-12	878385	3023051	Contract	Part	VO-21753149	IDLER PULLEY	1
2022-12-12	878385	3023051	Contract	Operation	VO-2604200	Idle pulley, replace	0.2
2022-12-12	878385	3023051	Contract	Part	VO-21743197	VENTILATION FILTER	4
2022-12-12	878385	3023051	Contract	Operation	VO-2342500	Fuel tank ventilation filter, replace	0.3
2022-12-12	878385	3023051	Contract	Part	VO-22602989	STARTER MOTOR	1
2022-12-12	878385	3023051	Contract	Operation	VO-3310600	Starter motor, replace	1.1
2022-12-12	878385	3023051	Contract	Part	VO-20874147	CAB SHOCK RR NB	1
2022-12-12	878385	3023051	Contract	Operation	VO-8182600	Cab shock absorber rear, replace (two)	0.5
2022-12-12	878385	3023051	Contract	Part	VO-23626042	AIR VALVE	1
2022-12-12	878385	3023051	Contract	Operation	VO-2533100	Air valve, replace. turbocompound unit	0.3
2022-11-30	705053	5001262	Retail	Part	OTH-CALLOUT	PARTS CALLOUT	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-11-29	870408	3307790		Text		Complaint: Noise in motor - Mack Assist case number 230519	
2022-11-29	870408	3307790		Text		Complaint: Noise in motor - Mack Assist case number 230519	
2022-11-29	870408	3307790		Text		Cause: Bearing had failed in cooling system fan hub.	
2022-11-29	870408	3307790		Text		Pressure damage, fan belt and fan blade were damaged.	
2022-11-29	870408	3307790		Text		Correction: Replace fan hub, belt and fan blade. Breakdown	
2022-11-29	870408	3307790		Text		site was 112km East of Longreach. Sub contracted job to	
2022-11-29	870408	3307790		Text		Hirst Mechanical Services from Longreach who travelled to	
2022-11-29	870408	3307790		Text		vehicle 112kms East of Longreach on Landsborough Highway	
2022-11-29	870408	3307790		Text		and completed the necessary repairs.	
2022-11-29	870408	3307790		Text		CPN: 22929437.	
2022-11-29	870408	3307790		Text		Other costs \$1,478.26 sublet Rod Bianchi invoice 31931	
2022-11-29	870408	3307790		Text		28/11/2022 \$2,050.76 split into 2 jobs. This job 1 for the	
2022-11-29	870408	3307790		Text		repair \$1,131.26 parts, \$275.00 labour and \$72.00 freight.	
2022-11-29	870408	3307790		Text		Note: Truck broke down 28/11/2022 east of Longreach and	
2022-11-29	870408	3307790		Text		neither CSC at Longreach or Emerald had technicians	
2022-11-29	870408	3307790		Text		available to attend breakdown. Rod Bianchi Motors	
2022-11-29	870408	3307790		Text		organised another mechanical shop to attend breakdown the	
2022-11-29	870408	3307790		Text		next day and parts were shipped to Hirst Mechanical	
2022-11-29	870408	3307790		Text		Services. Claiming freight as this was to transport parts	
2022-11-29	870408	3307790		Text		to a breakdown.	
2022-11-29	870408	3307790		Text		Cause: Bearing had failed in cooling system fan hub.	
2022-11-29	870408	3307790		Text		Pressure damage, fan belt and fan blade were damaged.	
2022-11-29	870408	3307790		Text		Correction: Travel to and from breakdown 112km East of	
2022-11-29	870408	3307790		Text		Longreach on the Landsborough Highway 225 kilometres @	
2022-11-29	870408	3307790		Text		\$1.20 = \$270.00 and 2.75 hours labour \$302.50. (Rod	
2022-11-29	870408	3307790		Text		Bianchi sub contracted job to Hirst Mechanical Services	
2022-11-29	870408	3307790		Text		from Longreach).	
2022-11-29	870408	3307790		Text		CPN: 22929437.	
2022-11-29	870408	3307790		Text		Other costs \$572.50 sublet Rod Bianchi invoice 31931	
2022-11-29	870408	3307790		Text		28/11/2022 \$2,050.76 split into 2 jobs. This job 2 for the	
2022-11-29	870408	3307790		Text		travel expenses \$270.00 and \$302.50 labour.	
2022-11-29	870408	3307790		Text		Note: Truck broke down 28/11/2022 east of Longreach and	
2022-11-29	870408	3307790		Text		neither CSC at Longreach or Emerald had technicians	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-11-29	870408	3307790		Text		available to attend breakdown. Rod Bianchi Motors	
2022-11-29	870408	3307790		Text		organised another mechanical shop to attend breakdown the	
2022-11-29	870408	3307790		Text		next day and parts were shipped to Hirst Mechanical	
2022-11-29	870408	3307790		Text		Services. Claiming freight as this was to transport parts	
2022-11-29	870408	3307790		Text		to a breakdown.	
2022-11-29	870408	3307790	Contract	Other	2633700	Fan hub assembly, replace	
2022-11-29	870408	3307790	Contract	Other	20	Sublet Rod Bianchi Invoice 31931 Job 1	
2022-11-29	870408	3307790	Contract	Other	20	Sublet Surcharge	
2022-11-29	870408	3307790	Contract	Other	1921200	Transfer time to breakdown site and back	
2022-11-29	870408	3307790		Text		to repairing dealer. Breakdown, call-out service	
2022-11-29	870408	3307790	Contract	Other	20	Sublet Rod Bianchi Invoice 31931 Job 2	
2022-11-21	864719	3022651	Internal	Part	OTH-LOC56707	LOCTITE 567	1
2022-11-21	864719	3022651		Text		Concern: Surging issues	
2022-11-21	864719	3022651		Text		Concern: Surging issues	
2022-11-21	864719	3022651		Text		Concern: EBS faults	
2022-11-21	864719	3022651		Text		Cause: Wastegate relay valve short circuit	
2022-11-21	864719	3022651		Text		Correction: R & R wastegate/engine brake air valve with	
2022-11-21	864719	3022651		Text		new, all okay.	
2022-11-21	864719	3022651		Text		Cause: Fan bearing seized	
2022-11-21	864719	3022651		Text		Correction: Removed fan hub, clutch and thermostat	
2022-11-21	864719	3022651		Text		housing. Found radiator was damaged from pieces of fan	
2022-11-21	864719	3022651		Text		bearing. Pressure tested radiator and found leak. Replaced	
2022-11-21	864719	3022651		Text		radiator, belt and fan hub bearing. Tested all okay.	
2022-11-21	864719	3022651		Text		Cause: Front left EBS valve bypassing air internally	
2022-11-21	864719	3022651		Text		Correction: While inspecting found EBS valve exhausting.	
2022-11-21	864719	3022651		Text		Replaced with new, tested all okay.	
2022-11-21	864719	3022651	Contract	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2022-11-21	864719	3022651	Contract	Part	VO-23992701	ENGINE BRAKE AIR VALVE FRONT	1
2022-11-21	864719	3022651	Contract	Operation	VO-1701200	Fault codes, reading	0.2
2022-11-21	864719	3022651	Contract	Operation	VO-2533600	Engine brake function, test	0.4
2022-11-21	864719	3022651	Contract	Operation	VO-2558500	Actuator by-pass valve, test	0.4
2022-11-21	864719	3022651	Contract	Operation	VO-2530400	Solenoid valve exhaust brake, replace	0.6
2022-11-21	864719	3022651	Contract	Operation	VO-2636800	Fan clutch, replace	3

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-11-21	864719	3022651	Contract	Part	VO-23508164	FAN CLUTCH *critical	1
2022-11-21	864719	3022651	Contract	Part	VO-23961777	FAN BELT	1
2022-11-21	864719	3022651	Contract	Part	VO-22876689	RADIATOR HEAVY DUTY *NOTES	1
2022-11-21	864719	3022651	Contract	Part	AU2-AMP85147	VOLVO VCS COOLANT PER LITRE	30.2
2022-11-21	864719	3022651	Contract	Part	AU2-AMP85147	VOLVO VCS COOLANT PER LITRE	4
2022-11-21	864719	3022651	Contract	Operation	VO-2610800	Radiator, replace	2.8
2022-11-21	864719	3022651	Contract	Operation	VO-2630700	Drive belts fan, replace	0.5
2022-11-21	864719	3022651	Warranty	Part	VO-21850098	RELAY VALVE (ESP) *NOTES	1
2022-11-21	864719	3022651	Warranty	Operation	VO-5633400	Control valve, replace	0.3
2022-11-21	864719	3022651	Warranty	Operation	LO-170	17097 - Take charge	0.3
2022-11-03	850408	3022094		Text		Concern: Customer states oil leak around sump	
2022-11-03	850408	3022094		Text		Cause: Leaking sump gasket	
2022-11-03	850408	3022094		Text		Correction: Removed sump and replaced gasket, all okay.	
2022-11-03	850408	3022094		Text		Concern: During service found alternator belt cracking	
2022-11-03	850408	3022094		Text		Cause: Material crack	
2022-11-03	850408	3022094		Text		Correction: Removed and replaced alternator belt, all okay.	
2022-11-03	850408	3022094		Text		Concern: During service found exhaust brake ram leaking air	
2022-11-03	850408	3022094		Text		Cause: Air leak	
2022-11-03	850408	3022094		Text		Correction: Connected tech tool and carried out 25336 -	
2022-11-03	850408	3022094		Text		engine brake function test, found failed. Removed and	
2022-11-03	850408	3022094		Text		replaced exhaust brake actuator with new and carried out	
2022-11-03	850408	3022094		Text		test again. All okay, cleared faults.	
2022-11-03	850408	3022094		Text		Concern: During exhaust brake acutator replacement found	
2022-11-03	850408	3022094		Text		air leak at gearbox test port	
2022-11-03	850408	3022094		Text		Cause: Air leak	
2022-11-03	850408	3022094		Text		Correction: Removed and replaced fitting with new, all okay.	
2022-11-03	850408	3022094		Text		Concern: During service found x4 air bags cracking	
2022-11-03	850408	3022094		Text		Cause: Material crack	
2022-11-03	850408	3022094		Text		Correction: Removed and replaced x4 air bags with new,	
2022-11-03	850408	3022094		Text		all okay.	
2022-11-03	850408	3022094	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2022-11-03	850408	3022094		Text		oil changes included only in some models	
2022-11-03	850408	3022094		Text		CHANGE OILS AFTER ANY REPAIRS	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-11-03	850408	3022094		Text		NEEDED ARE REPORTED - BASIC	
2022-11-03	850408	3022094		Text		SERVICE	
2022-11-03	850408	3022094	Contract	Operation	VO-2630700	Drive belts fan, replace	0.5
2022-11-03	850408	3022094	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2022-11-03	850408	3022094	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2022-11-03	850408	3022094		Text		area	
2022-11-03	850408	3022094	Contract	Operation	VO-7714500	Wheel nuts, check tightening (all)	0.3
2022-11-03	850408	3022094	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2022-11-03	850408	3022094	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2022-11-03	850408	3022094	Contract	Operation	VO-1706700	30 Months ECU download and oil sample. O	0.9
2022-11-03	850408	3022094		Text		Only valid for Australian market	
2022-11-03	850408	3022094		Text		FOR FH ONLY	
2022-11-03	850408	3022094	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2022-11-03	850408	3022094		Text		*** POSSIBLE POLICY CLAIM ***	
2022-11-03	850408	3022094	Contract	Part	VO-20579690	SUMP PLUG O'RING	1
2022-11-03	850408	3022094	Contract	Part	AU2-WUR08923	CLNR-WSCRN-RAPID-3	1
2022-11-03	850408	3022094	Contract	Part	VO-23961777	FAN BELT	1
2022-11-03	850408	3022094	Contract	Part	VO-23448457	SOS VOLVO OIL SAMPLE	4
2022-11-03	850408	3022094	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	52
2022-11-03	850408	3022094	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	1.5
2022-11-03	850408	3022094	Contract	Operation	VO-2170200	Oil pan gasket, replace. Campaign only	1.6
2022-11-03	850408	3022094	Contract	Part	VO-20734156	MP10 SUMP GASKET	1
2022-11-03	850408	3022094	Contract	Part	VO-21780376	SEALING RING	1
2022-11-03	850408	3022094	Contract	Operation	LO-179	Service -Pick up and delivery	1
2022-11-03	850408	3022094	Contract	Part	VO-23961744	ALTERNATOR BELT	1
2022-11-03	850408	3022094	Contract	Operation	VO-3212200	Alternator drive belt, replace	0.4
2022-11-03	850408	3022094	Contract	Part	VO-22889891	EXH BRAKE ACTUATOR	1
2022-11-03	850408	3022094	Contract	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2022-11-03	850408	3022094	Contract	Operation	VO-1701200	Fault codes, reading	0.2
2022-11-03	850408	3022094	Contract	Operation	VO-2533600	Engine brake function, test	0.4
2022-11-03	850408	3022094	Contract	Operation	VO-2531400	Control cylinder exhaust brake, replace	0.7
2022-11-03	850408	3022094	Contract	Part	VO-20448956	16mm-1/4 FITTING	1
2022-11-03	850408	3022094	Contract	Operation	VO-5638700	Air fitting, replace	0.4

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-11-03	850408	3022094	Contract	Part	VO-22058741	AIR SPRING	2
2022-11-03	850408	3022094	Contract	Part	VO-22058737	AIR SPRING	2
2022-11-03	850408	3022094		Text		*** POSSIBLE POLICY CLAIM ***	
2022-11-03	850408	3022094	Contract	Operation	VO-7260200	Air bellows, drive axle, replace	0.4
2022-10-21	840061	3021871	Internal	Other	3810600	Instrument cluster, lights	
2022-10-21	840061	3021871		Text		Complaint: Eng oil leaking	
2022-10-21	840061	3021871		Text		Complaint: Dash lights	
2022-10-21	840061	3021871		Text		Cause: Not adjusting	
2022-10-21	840061	3021871		Text		Correction: Turned on head light and played with the	
2022-10-21	840061	3021871		Text		dimmer switch and it was working - unable to fault	
2022-10-21	840061	3021871		Text		complaint.	
2022-10-21	840061	3021871		Text		Cause: PVC filter leaking	
2022-10-21	840061	3021871		Text		Correction: Inspected are of oil leak on LHS. Noticed oil	
2022-10-21	840061	3021871		Text		sump gasket has been replaced - not the cause. Found PVC	
2022-10-21	840061	3021871		Text		filter breather hose had alot of oil coming out. Removed	
2022-10-21	840061	3021871		Text		and replaced PVC filter. are was cleaned where oil was	
2022-10-21	840061	3021871		Text		present.	
2022-10-21	840061	3021871		Text		-	
2022-10-21	840061	3021871		Text		Concern report entered 23/11.	
2022-10-21	840061	3021871	Contract	Operation	VO-2573800	Gasket, oil separator crankcase breather	0.4
2022-10-21	840061	3021871	Contract	Part	VO-22767078	OIL SEPARATOR CRANKCASE VENTIL	1
2022-10-21	840061	3021871	Contract	Part	VO-20532891	ENG BREATHER GSKT	1
2022-10-21	840061	3021871	Contract	Operation	VO-1820200	Localised wash for fault tracing	0.3
2022-10-21	840061	3021871		Text		breather, replace	
2022-10-04	825432	3021543	Internal	Part	OTH-RPFAS610	RIVET	8
2022-10-04	825432	3021543	Internal	Other	510	WHEEL BRAKES-GENERAL	
2022-10-04	825432	3021543		Text		Concern: Oil leak around sump	
2022-10-04	825432	3021543		Text		Concern: LH aeon rubber peeling/cracking	
2022-10-04	825432	3021543		Text		Cause: Material crack	
2022-10-04	825432	3021543		Text		Correction: Removed and replaced LH aeon rubber with new,	
2022-10-04	825432	3021543		Text		all okay.	
2022-10-04	825432	3021543		Text		Concern: Tiger signs peeling	
2022-10-04	825432	3021543		Text		Cause: Peeling/flaking	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-10-04	825432	3021543		Text		Correction: Remove dand replaced tiger/marker signs with	
2022-10-04	825432	3021543		Text		new. All okay.	
2022-10-04	825432	3021543		Text		Concern: Front engine mount split	
2022-10-04	825432	3021543		Text		Cause: Material crack	
2022-10-04	825432	3021543		Text		Correction: Removed and replaced front engine mount, all	
2022-10-04	825432	3021543		Text		okay.	
2022-10-04	825432	3021543		Text		Cause: Gasket leaking and dipstick tube bottom cracked	
2022-10-04	825432	3021543		Text		Correction: Drained oil and removed all sump bolts.	
2022-10-04	825432	3021543		Text		Removed sump and gasket, replaced gasket and checked for	
2022-10-04	825432	3021543		Text		leaks. Washed down and found dip stick tube bottom section	
2022-10-04	825432	3021543		Text		cracked. Replaced with new, all okay.	
2022-10-04	825432	3021543	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2022-10-04	825432	3021543		Text		oil changes included only in some models	
2022-10-04	825432	3021543		Text		CHANGE OILS AFTER ANY REPAIRS	
2022-10-04	825432	3021543		Text		NEEDED ARE REPORTED - BASIC	
2022-10-04	825432	3021543		Text		SERVICE	
2022-10-04	825432	3021543	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2022-10-04	825432	3021543	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2022-10-04	825432	3021543		Text		area	
2022-10-04	825432	3021543	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2022-10-04	825432	3021543	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2022-10-04	825432	3021543	Contract	Operation	VO-8747400	Air filter insert, A/C unit, replace	0.3
2022-10-04	825432	3021543	Contract	Operation	VO-1784600	Trailer coupling, safety and function ch	0.2
2022-10-04	825432	3021543		Text		check	
2022-10-04	825432	3021543	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2022-10-04	825432	3021543		Text		*** POSSIBLE POLICY CLAIM ***	
2022-10-04	825432	3021543	Contract	Part	VO-20579690	SUMP PLUG O'RING	1
2022-10-04	825432	3021543	Contract	Part	AU2-AMP23068:	VOLVO ENGINE OIL VDS4.5 5LT	1
2022-10-04	825432	3021543	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	52
2022-10-04	825432	3021543	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	2
2022-10-04	825432	3021543	Contract	Operation	VO-2170200	Oil pan gasket, replace. Campaign only	1.6
2022-10-04	825432	3021543	Contract	Part	VO-20734156	MP10 SUMP GASKET	1
2022-10-04	825432	3021543	Contract	Part	VO-21780376	SEALING RING	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-10-04	825432	3021543	Contract	Part	VO-21523327	DIPSTICK TUBE IN SUMP *NOTES	1
2022-10-04	825432	3021543	Contract	Operation	VO-2212300	Dipstick tube, replace	0.4
2022-10-04	825432	3021543	Contract	Operation	LO-179	Service -Pick up and delivery	1
2022-10-04	825432	3021543	Contract	Part	VO-22254125	AEON RUBBER SPRING	1
2022-10-04	825432	3021543	Contract	Operation	VO-8185500	Air spring, replace	0.7
2022-10-04	825432	3021543	Contract	Part	AU2-9719-CIXTC	REAR MARKER 615A/B	1
2022-10-04	825432	3021543	Contract	Other	897	MISC-INSTRUCTION AND INFORMATION SIGNS	
2022-10-04	825432	3021543	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - rivets	
2022-10-04	825432	3021543	Warranty	Part	VO-20503550	FRONT ENGINE MOUNT	1
2022-10-04	825432	3021543		Text		*** POSSIBLE POLICY CLAIM ***	
2022-10-04	825432	3021543	Warranty	Operation	VO-2180500	Cushion mount, replace (front)	1.7
2022-09-27	710781	5400161		Text		REPLACED BROKEN BATTERY TERMINAL ON THE ICE PACK	
2022-09-27	710781	5400161		Text		ALTERNATOR.	
2022-09-27	710781	5400161	Retail	Operation	LO-170	Battery terminal on icepack broken	1
2022-09-27	710781	5400161	Retail	Other	91	Workshop Consumables	
2022-09-15	808770	3021247		Text		Concern: Air bags leaking air	
2022-09-15	808770	3021247		Text		Cause: Worn bags	
2022-09-15	808770	3021247		Text		Correction: Sprayed soap water on air bags to identify	
2022-09-15	808770	3021247		Text		leaks, found rear drive front air bags perished and	
2022-09-15	808770	3021247		Text		leaking remove air lines going to air bags and replace air	
2022-09-15	808770	3021247		Text		bags, replace with new air bags and test drove vehicle	
2022-09-15	808770	3021247		Text		all okay.	
2022-09-15	808770	3021247	Contract	Operation	VO-7260200	Air bellows, drive axle, replace	0.4
2022-09-15	808770	3021247	Contract	Part	VO-22058737	AIR SPRING	2
2022-09-15	808770	3021247	Contract	Part	MK-FT1872X6X6	FITTING 3/8 THR / 3/8 TUBE	2
2022-09-15	808770	3021247	Contract	Operation	VO-5638700	Air fitting, replace	0.4
2022-09-15	808770	3021247	Contract	Operation	LO-170	road test	0.5
2022-08-22	788697	3020665	Internal	Part	OTH-NARV4750	BULB 12V5W WEDGE	10
2022-08-22	788697	3020665	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	5
2022-08-22	788697	3020665		Text		oil changes included only in some models	
2022-08-22	788697	3020665	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2022-08-22	788697	3020665	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2022-08-22	788697	3020665		Text		area	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-08-22	788697	3020665	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2022-08-22	788697	3020665	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2022-08-22	788697	3020665	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	57
2022-08-22	788697	3020665	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2022-08-22	788697	3020665		Text		*** POSSIBLE POLICY CLAIM ***	
2022-08-22	788697	3020665	Contract	Part	VO-20579690	SUMP PLUG O'RING	1
2022-08-22	788697	3020665	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2022-08-22	788697	3020665	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts-SUBLET	
2022-08-22	788697	3020665	Contract	Other	3510400	Headlight bulb, replace (one). 1 unit,	
2022-08-22	788697	3020665		Text		excludes headlight adjustment	
2022-08-22	788697	3020665		Text		OTH-NARV47501A - BULB12V5W WEDGE	
2022-08-16	785206	3020575		Text		Concern: Clutch faults	
2022-08-16	785206	3020575		Text		Concern: Sump gasket leaking	
2022-08-16	785206	3020575		Text		Concern: Rear engine mounts cracked	
2022-08-16	785206	3020575		Text		Cause: Clutch cylinder leaking	
2022-08-16	785206	3020575		Text		Correction: Connected tech tool and found active clutch	
2022-08-16	785206	3020575		Text		codes. Carried out clutch cylinder test and found was	
2022-08-16	785206	3020575		Text		leaking. Drained coolant and removed all accessories and	
2022-08-16	785206	3020575		Text		gearbox. Removed clutch and flywheel, sent flywheel away	
2022-08-16	785206	3020575		Text		for machining. Replaced clutch, clutch cylinder and PWM	
2022-08-16	785206	3020575		Text		valve. Refitted flywheel and clutch, refitted gearbox and	
2022-08-16	785206	3020575		Text		all associated accessories. Filled with coolant and	
2022-08-16	785206	3020575		Text		calibrated gearbox.	
2022-08-16	785206	3020575		Text		Cause: Material crack	
2022-08-16	785206	3020575		Text		Correction: Whilst gearbox was out, noticed rear engine	
2022-08-16	785206	3020575		Text		mounts cracked. Removed and replaced with new, all okay.	
2022-08-16	785206	3020575		Text		Cause: Worn gasket	
2022-08-16	785206	3020575		Text		Correction: Removed sump and replaced gasket, filler tube o	
2022-08-16	785206	3020575		Text		ring and dipstick tube (cracked). Refitted sump and filled	
2022-08-16	785206	3020575		Text		with oil.	
2022-08-16	785206	3020575	Contract	Operation	VO-4110100	Clutch, replace	4.1
2022-08-16	785206	3020575	Contract	Other	10	SUBLET: ERB - FLYWHEEL HOUSING	
2022-08-16	785206	3020575	Contract	Part	VO-1652986	SPIGOT BEARING	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-08-16	785206	3020575	Contract	Part	VO-22317110	CLUTCH	1
2022-08-16	785206	3020575	Contract	Part	VO-23020399	CLUTCH DISC *notes	1
2022-08-16	785206	3020575	Contract	Part	VO-23417527	M DRIVE CLUTCH CYLINDER MACK	1
2022-08-16	785206	3020575	Contract	Part	VO-20992763	M DRIVE CLUTCH CYL AIR HOSE	1
2022-08-16	785206	3020575	Contract	Part	VO-983472	SMALL GREY CABLE TIE	6
2022-08-16	785206	3020575	Contract	Part	VO-22327069	PWM VALVE MACK *NOTES	1
2022-08-16	785206	3020575	Contract	Part	VO-984050	NUT HEX M14 FINE PITCH PC 10	8
2022-08-16	785206	3020575	Contract	Part	VO-995906	BOLT HEX M14 X 46 FINE 10.9	8
2022-08-16	785206	3020575	Contract	Operation	VO-4131300	Clutch cylinder, replace	4.2
2022-08-16	785206	3020575	Contract	Operation	VO-4137100	Supply hose, clutch cylinder, replace. G	0.1
2022-08-16	785206	3020575		Text		Gearbox removed	
2022-08-16	785206	3020575	Contract	Operation	VO-4137000	Valve assembly, clutch cylinder, replace	0.2
2022-08-16	785206	3020575		Text		replace. Gearbox removed	
2022-08-16	785206	3020575	Contract	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2022-08-16	785206	3020575	Contract	Operation	VO-1701200	Fault codes, reading	0.2
2022-08-16	785206	3020575	Contract	Operation	VO-4007000	Gearbox, clutch, engagement point, calib	0.2
2022-08-16	785206	3020575		Text		calibration	
2022-08-16	785206	3020575	Contract	Operation	VO-4118200	PWM valves clutch, activation, test	0.2
2022-08-16	785206	3020575	Contract	Operation	VO-4112600	Clutch wear, check. VCADS Pro operation	0.2
2022-08-16	785206	3020575	Contract	Operation	VO-4008300	PWM valves, clutch, test	0.2
2022-08-16	785206	3020575	Contract	Operation	VO-4001000	Clutch cylinder, test	0.2
2022-08-16	785206	3020575	Contract	Part	VO-20499470	REAR ENGINE MOUNT	2
2022-08-16	785206	3020575		Text		ALREADY GIVEN	
2022-08-16	785206	3020575	Contract	Operation	VO-2180300	Engine mounting pad rear, replace. other	0.3
2022-08-16	785206	3020575		Text		others each	
2022-08-16	785206	3020575	Contract	Part	VO-20734156	MP10 SUMP GASKET	1
2022-08-16	785206	3020575	Contract	Part	VO-21780376	SEALING RING	1
2022-08-16	785206	3020575	Contract	Part	VO-21363862	DIPSTICK AND PIPE	1
2022-08-16	785206	3020575	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	5
2022-08-16	785206	3020575	Contract	Operation	VO-2212300	Dipstick tube, replace	0.4
2022-08-16	785206	3020575	Contract	Operation	VO-2113900	Gasket, valve cover, replace	1.1
2022-07-25	768358	3020142		Text		Concern: ABS fault on dash	
2022-07-25	768358	3020142	Contract	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-07-25	768358	3020142	Contract	Operation	VO-1701200	Fault codes, reading	0.2
2022-07-25	768358	3020142	Contract	Operation	VO-5933400	Wheel speed sensor, replace (steer axle)	0.7
2022-07-25	768358	3020142	Contract	Operation	LO-170	Road test	0.5
2022-07-20	763961	3020054	Internal	Other	219	Engine Other	
2022-07-20	763961	3020054	Internal	Other	431	Transmission	
2022-07-20	763961	3020054	Internal	Part	OTH-TIE70150A	1-1/2" SILICONE HOSE PER INCH	4
2022-07-20	763961	3020054	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2022-07-20	763961	3020054		Text		oil changes included only in some models	
2022-07-20	763961	3020054	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2022-07-20	763961	3020054	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2022-07-20	763961	3020054	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2022-07-20	763961	3020054	Contract	Operation	VO-2141300	Valves and unit injectors, adjust	2.1
2022-07-20	763961	3020054	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2022-07-20	763961	3020054	Contract	Operation	VO-1784600	Trailer coupling, safety and function ch	0.2
2022-07-20	763961	3020054	Contract	Part	AU2-AMP23068:	VOLVO ENGINE OIL VDS4.5 5LT	1
2022-07-20	763961	3020054	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2022-07-20	763961	3020054	Contract	Part	VO-20579690	SUMP PLUG O'RING	1
2022-07-20	763961	3020054	Contract	Part	VO-20736230	MP10 T/COVER GASKET	1
2022-07-20	763961	3020054	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	52
2022-07-20	763961	3020054	Contract	Part	AU2-AMP22567:	VCS COOLANT 20L 2980-220	20
2022-07-20	763961	3020054	Contract	Operation	LO-258	EMISSIONS AFTER-TREATMENT	2
2022-07-20	763961	3020054	Contract	Part	AU2-WUR05492	HOSE CLAMP 35-50MM 12MM WIDE	2
2022-07-20	763961	3020054	Contract	Part	AU2-WUR05492	HOSE CLAMP 25-40MM 12MM WIDE	1
2022-07-20	763961	3020054	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - hose per inch	
2022-07-20	763961	3020054	Contract	Operation	VO-2525100	Clamp, exhaust pipe, replace	0.4
2022-07-20	763961	3020054	Contract	Operation	VO-3634400	Windshield washer hoses and nozzles, rep	0.5
2022-07-20	763961	3020054	Contract	Part	VO-85116361	WASHER NOZZLE (SQUARE) *NOTES	2
2022-07-20	763961	3020054	Contract	Part	VO-82710488	WIPER BLADE BASIC	2
2022-07-20	763961	3020054	Contract	Operation	VO-3630400	Windscreen wiper blade, replace	0.1
2022-06-17	736623	3018619	Contract	Operation	VO-8562300	Mattress, replace	0.1
2022-06-17	736623	3018619	Contract	Part	MK-9268-520SB	MATTRESS	1
2022-06-17	736623	3018619	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2022-06-17	736623	3018619		Text		oil changes included only in some models	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-06-17	736623	3018619	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2022-06-17	736623	3018619	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2022-06-17	736623	3018619	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2022-06-17	736623	3018619	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2022-06-17	736623	3018619	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2022-06-17	736623	3018619	Contract	Part	VO-20579690	GASKET	1
2022-06-17	736623	3018619	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	57
2022-06-17	736623	3018619	Contract	Operation	VO-2170200	Oil pan gasket, replace. Campaign only	1.6
2022-06-17	736623	3018619	Contract	Part	VO-21780376	SEALING RING	1
2022-06-17	736623	3018619	Contract	Part	VO-20734156	MP10 SUMP GASKET	1
2022-06-17	736623	3018619	Contract	Operation	VO-2583200	Aftertreatment diesel exhaust fluid (DEF	0.4
2022-06-17	736623	3018619	Contract	Part	VO-23121198	ADBLUE FILLER NECK	1
2022-06-17	736623	3018619	Contract	Operation	VO-2616300	Water hose, replace (hose with two clamp	0.2
2022-06-17	736623	3018619	Contract	Part	VO-949995	HOSE PER METRE	1
2022-06-17	736623	3018619	Contract	Part	VO-990215	HOSE CLAMP 20-32MM	2
2022-06-17	736623	3018619	Contract	Part	VO-85109772	H11 12V 55W LOW	1
2022-06-17	736623	3018619	Contract	Part	VO-85124906	HB3A 12V 60W BULB	1
2022-06-17	736623	3018619	Contract	Other	3510400	Headlight bulb, replace (one). 1 unit,	
2022-06-17	736623	3018619	Contract	Operation	LO-179	Service -Pick up and delivery	0.5
2022-06-15	734902	3703355	Contract	Operation	VO-4007000	Gearbox, clutch, engagement point, calib	0.2
2022-06-15	734902	3703355		Text		COMPLAINT: FAULT LIGHT ACTIVATES INTERMITTENTLY.	
2022-06-15	734902	3703355	Contract	Operation	VO-1790600	Diagnostic with Tech Tool/GD. Connect-di	0.5
2022-06-09	729977	3019253	Internal	Part	OTH-DTM06-2S-	TERMINATING RESISTOR	1
2022-06-09	729977	3019253	Contract	Operation	VO-8522300	Control, tilt adjustment, replace	0.1
2022-06-09	729977	3019253	Contract	Part	VO-85106109	CONTROL LEVER	1
2022-06-09	729977	3019253	Contract	Part	VO-20748450	ISRI SEAT VALVE KIT	1
2022-06-09	729977	3019253	Contract	Operation	VO-8530800	Control valve, replace	0.4
2022-06-09	729977	3019253	Contract	Operation	LO-386	SENDERS FOR INDICATOR/WARNING SYSTEM	0.3
2022-06-09	729977	3019253	Contract	Part	VO-22387296	M DRIVE VEHICLE SPEED SENSOR	1
2022-06-09	729977	3019253		Text		*** POSSIBLE POLICY CLAIM ***	
2022-06-09	729977	3019253	Contract	Operation	VO-3710200	Electric wires and connections, check	0.4
2022-06-09	729977	3019253	Contract	Operation	VO-2340800	Fittings, fuel line, replace	0.4
2022-06-09	729977	3019253	Contract	Part	VO-21032572	CLAMP	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-06-09	729977	3019253	Contract	Part	VO-20744599	CONNECTOR,5/16 WHITE 45DEG	1
2022-06-09	729977	3019253	Contract	Other	WTY-NONGEN	WTY-Non Genuine Part - RESISTOR	
2022-06-01	723113	3018994	Contract	Operation	LO-271	FOOT CONTROL	0.8
2022-06-01	723113	3018994	Contract	Part	VO-84739665	ACCELERATOR PEDAL MACK	1
2022-06-01	723113	3018994		Text		84739665 WSO 31/5 CS	
2022-05-23	710781	3703251		Text		REPLACED BROKEN BATTERY TERMINAL ON THE ICE PACK	
2022-05-23	710781	3703251	Retail	Operation	LO-170	Battery terminal on icepack broken	1
2022-05-23	710781	3703251	Retail	Other	91	Workshop Consumables	
2022-05-19	723264	3018865		Text		Concern: RHS indicator not working	
2022-05-19	723264	3018865	Contract	Part	VO-20996044	INDICATOR BONNET NB	1
2022-05-19	723264	3018865	Contract	Other	355	LIGHTING - SIDE LIGHTS	
2022-05-03	701756	3843675	Contract	Operation	VO-3110200	Batteries, replace (all)	0.8
2022-05-03	701756	3843675	Contract	Part	AU2-21209957	MACK BATTERY - 12V N70 N70ZZH	4
2022-05-03	701756	3843675	Contract	Operation	VO-3116800	Battery system, test. Battery tester	0.4
2022-05-03	701756	3843675	Contract	Operation	LO-190	Warranty protocol fill in 19010	0.2
2022-05-03	701756	3843675	Contract	Operation	LO-194	Travel to vehicle at	0.5
2022-05-03	701756	3843675		Text		Toll Yard in East Arm (Gate 6) & return to WTG Workshop	
2022-05-03	701756	3843675	Contract	Other	92	25 km @ 98c/km	
2022-04-29	705053	3016896	Retail	Part	OTH-BF620-00	ROTATING BEACON TWIN	1
2022-04-29	705053	3016896	Retail	Other	100	Labour	
2022-04-29	705053	3016896		Text		Supplied beacon light to Hillmans for fitting.	
2022-04-29	705053	3016896	Retail	Part	OTH-CALLOUT	PARTS CALLOUT	1
2022-04-29	705053	3016896	Internal	Other	211	CYLINDER HEAD	
2022-04-29	705053	3016896	Internal	Other	217	OIL SUMP	
2022-04-29	705053	3016896	Retail	Part	OTH-NARV4750	bulb 12v 5w	1
2022-04-29	705053	3016896	Contract	Operation	VO-8522300	Control, tilt adjustment, replace	0.1
2022-04-29	705053	3016896	Contract	Part	VO-85106108	CONTROL LEVER	1
2022-04-29	705053	3016896	Contract	Part	MK-FT1462X8	1/2" JOINER COMP	1
2022-04-29	705053	3016896	Contract	Operation	VO-1774600	Annual service. Chassis lubrication and	2.4
2022-04-29	705053	3016896	Contract	Operation	VO-2562700	Filter insert, air cleaner, replace. Onl	0.2
2022-04-29	705053	3016896	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2022-04-29	705053	3016896	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2022-04-29	705053	3016896	Contract	Operation	VO-7714500	Wheel nuts, check tightening (all)	0.3

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-04-29	705053	3016896	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2022-04-29	705053	3016896	Contract	Operation	VO-2341400	Filter for fuel tank ventilation, replac	0.3
2022-04-29	705053	3016896	Contract	Operation	VO-5616600	Air drier cassette, replace	0.4
2022-04-29	705053	3016896	Contract	Operation	VO-2582200	Filter, AdBlue, replace	0.3
2022-04-29	705053	3016896	Contract	Operation	VO-6452500	Oil filter, power steering, replace	0.2
2022-04-29	705053	3016896	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2022-04-29	705053	3016896	Contract	Operation	VO-6451400	Oil and filter, power steering, replace	0.4
2022-04-29	705053	3016896	Contract	Operation	VO-8100500	24 Months cab inspection	0.2
2022-04-29	705053	3016896	Contract	Operation	VO-1706600	24 Months ECU download and oil sample. O	0.9
2022-04-29	705053	3016896	Contract	Operation	VO-1784600	Trailer coupling, safety and function ch	0.2
2022-04-29	705053	3016896	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	57
2022-04-29	705053	3016896	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2022-04-29	705053	3016896	Contract	Part	VO-20579690	GASKET	1
2022-04-29	705053	3016896	Contract	Part	MK-57MD42M	***ELEMENT, AIR 'C	2
2022-04-29	705053	3016896	Contract	Part	VO-85129688	AIR DRIER FILTER	1
2022-04-29	705053	3016896	Contract	Part	VO-23381558	ADBLUE FILTER NB	1
2022-04-29	705053	3016896	Contract	Part	MK-5839-87067	FILTER P/STR GRAN	1
2022-04-29	705053	3016896	Contract	Part	VO-85122800	ATF DEX 3 1 LTR	4
2022-04-29	705053	3016896	Contract	Part	VO-23448457	SOS VOLVO OIL SAMPLE	4
2022-04-29	705053	3016896	Contract	Part	VO-21743197	VENTILATION FILTER	4
2022-04-29	705053	3016896	Contract	Part	VO-23251838	FILTER	1
2022-04-29	705053	3016896	Contract	Operation	VO-2584800	Strainer, replace. Pump unit	0.7
2022-04-29	705053	3016896	Contract	Part	VO-21954674	STRAINER ADBLUE PUMP	1
2022-04-29	705053	3016896	Contract	Part	MK-FT1868X6X8	3/8" X 1/2" PUSH M	1
2022-04-29	705053	3016896	Contract	Operation	VO-5638700	Air fitting, replace	0.4
2022-04-29	705053	3016896	Contract	Part	MK-FT1869X8X8	1/2" X 1/2" 90DEG PU	1
2022-04-29	705053	3016896	Contract	Part	VO-22987428	ABS MODULATOR VALVE (STEER)	1
2022-04-29	705053	3016896	Contract	Operation	VO-5640100	ABS, modulator valve, replace (front)	0.4
2022-04-29	705053	3016896	Contract	Operation	VO-5653100	Air tank fitting, replace	0.3
2022-04-29	705053	3016896	Contract	Part	VO-21816920	PRESSURE PROT VALVE	1
2022-04-29	705053	3016896	Contract	Operation	VO-5634200	Service brake relay valve, replace	0.7
2022-04-29	705053	3016896	Contract	Part	VO-25158533	WILLIAMS VALVE 118181	1
2022-04-29	705053	3016896	Contract	Operation	VO-5633400	Control valve, replace	0.3

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-04-01	674407	3017944	Internal	Other	1701000	Connect-disconnect of diagnostic tool	
2022-04-01	674407	3017944	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2022-04-01	674407	3017944		Text		oil changes included only in some models	
2022-04-01	674407	3017944	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2022-04-01	674407	3017944	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2022-04-01	674407	3017944	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2022-04-01	674407	3017944	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2022-04-01	674407	3017944	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	57
2022-04-01	674407	3017944	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2022-04-01	674407	3017944	Contract	Part	VO-20579690	GASKET	1
2022-04-01	674407	3017944	Contract	Part	AU2-AMP22567:	VOLVO VCS COOLANT 5L 2980-235	1
2022-04-01	674407	3017944	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2022-04-01	674407	3017944	Contract	Part	VO-85109772	H11 12V 55W LOW	1
2022-04-01	674407	3017944	Contract	Part	VO-85124906	HB3A 12V 60W BULB	1
2022-04-01	674407	3017944	Contract	Other	3510400	Headlight bulb, replace (one). 1 unit,	
2022-04-01	674407	3017944	Contract	Part	VO-82278971	SWITCH WINDOW LIFT	1
2022-04-01	674407	3017944	Contract	Operation	VO-3640500	Switch, window lift, replace	0.3
2022-04-01	674407	3017944	Contract	Part	VO-85151124	CAB AC FILTER NB	1
2022-04-01	674407	3017944	Contract	Operation	VO-8721000	Air filters air conditioning, replace	0.1
2022-03-24	670351	3017930		Text		Concern: Coolant leak	
2022-03-24	670351	3017930	Contract	Operation	VO-2612400	Radiator hose, replace (lower). (incl. d	0.5
2022-03-24	670351	3017930	Contract	Part	VO-21637042	HOSE	2
2022-03-24	670351	3017930	Contract	Part	VO-990215	HOSE CLAMP	4
2022-03-24	670351	3017930	Contract	Part	AU2-AMP22567:	VCS COOLANT 20L 2980-220	20
2022-03-02	654414	3017382		Text		Concern: Air drier bracket	
2022-03-02	654414	3017382	Internal	Part	OTH-NARV4750	bulb 12v 5w	2
2022-03-02	654414	3017382	Contract	Operation	LO-525	BRAKE VALVES	2
2022-03-02	654414	3017382	Contract	Other	10	SUBLET: MC - WELD BRACKET	
2022-03-02	654414	3017382	Contract	Operation	VO-3510400	Headlight bulb, replace (one). 1 unit, e	0.1
2022-03-02	654414	3017382	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts-BULB	
2022-03-02	0	3017387	Retail	Operation	LO-MMISC	WELD BRACKET AS REQUESTED	1
2022-03-02	0	3017387		Text		Prepare, weld and paint bracket as requested by workshop.	
2022-02-14	641383	3015968	Contract	Part	VO-20997037	BUG DEFLECTOR 48" CLEAR	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-02-14	641383	3015968	Contract	Other	8919700	Bug deflector, hood, replace. Gas system	
2022-02-14	641383	3015968		Text		emptied	
2022-02-14	641383	3015968	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2022-02-14	641383	3015968	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2022-02-14	641383	3015968	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2022-02-14	641383	3015968	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2022-02-14	641383	3015968	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2022-02-14	641383	3015968	Contract	Other	1784600	Trailer coupling, safety and function	
2022-02-14	641383	3015968	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2022-02-14	641383	3015968	Contract	Part	VO-20579690	GASKET	1
2022-02-14	641383	3015968	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	57
2022-02-14	641383	3015968	Contract	Part	AU2-AMP22567:	VOLVO VCS COOLANT 5L 2980-235	1
2022-02-14	641383	3015968	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2022-02-14	641383	3015968	Contract	Part	MK-57MD42M	***ELEMENT, AIR 'C	2
2022-02-14	641383	3015968	Contract	Operation	VO-2562400	Filter insert, air cleaner, replace. Onl	0.2
2022-02-14	641383	3015968	Contract	Part	VO-20448956	16mm-1/4 FITTING	1
2022-02-14	641383	3015968	Contract	Operation	VO-5638700	Air fitting, replace	0.4
2022-02-14	641383	3015968	Warranty	Operation	VO-3116800	Battery system, test. Battery tester	0.4
2022-02-14	641383	3015968	Warranty	Operation	VO-3110300	Battery, replace (one)	0.3
2022-02-14	641383	3015968	Contract	Part	VO-20503550	RUBBER CUSHION	1
2022-02-14	641383	3015968	Contract	Operation	VO-2180500	Cushion mount, replace (front)	1.7
2022-02-14	641383	3015968	Contract	Other	3510400	Headlight bulb, replace (one). 1 unit,	
2022-02-14	641383	3015968	Contract	Part	VO-85124906	HB3A 12V 60W BULB	1
2022-02-14	641383	3015968	Contract	Part	VO-85109772	H11 12V 55W LOW	1
2022-02-07	634742	3016861	Internal	Other	356	LIGHTING - EXTRA LIGHTS	
2022-02-07	634742	3016861	Contract	Operation	VO-2611800	Expansion tank, replace	0.7
2022-02-07	634742	3016861	Contract	Part	VO-21053033	HOSE	1
2022-02-07	634742	3016861	Contract	Part	VO-21053055	HOSE, COOLANT	1
2022-02-07	634742	3016861	Contract	Part	VO-23911823	EXPANSION TANK	1
2022-02-07	634742	3016861		Text		23911823 GIVEN TO BROADY 07/02/22 AT 4.44PM BY SS	
2022-02-07	634742	3016861	Contract	Operation	VO-2614000	Coolant distributor pipe, replace	0.1
2022-01-28		0 3016652		Text		Repair without detail info	
2022-01-04	609659	3016153	Internal	Part	OTH-AB3502	1/2" RUBB BRAKE HOSE	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2022-01-04	609659	3016153	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2022-01-04	609659	3016153		Text		oil changes included only in some models	
2022-01-04	609659	3016153	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2022-01-04	609659	3016153	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2022-01-04	609659	3016153	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2022-01-04	609659	3016153	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2022-01-04	609659	3016153	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2022-01-04	609659	3016153	Contract	Part	VO-20579690	GASKET	1
2022-01-04	609659	3016153	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	52
2022-01-04	609659	3016153	Contract	Operation	LO-179	Service -Pick up and delivery	0.5
2021-12-17	585130	5000911	Contract	Part	VO-20997037	BUG DEFLECTOR 48" CLEAR	1
2021-12-17	585130	5000911	Contract	Operation	VO-8919700	Bug deflector, hood, replace. Gas system	0.4
2021-12-17	585130	5000911		Text		emptied	
2021-12-10	591735	3015756		Text		Concern: Transmission cooler leaking	
2021-12-10	591735	3015756	Warranty	Operation	VO-4910800	Automatic transmission oil cooler, repla	1.1
2021-12-10	591735	3015756	Warranty	Part	VO-23653292	TRANSMISSION COOLER VOLVO	1
2021-12-10	591735	3015756	Warranty	Operation	VO-2600600	Coolant system, pressure test	0.4
2021-12-10	591735	3015756	Warranty	Operation	VO-2602600	Cooling system, drain and refill coolant	0.4
2021-12-03	585130	3015431	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2021-12-03	585130	3015431		Text		oil changes included only in some models	
2021-12-03	585130	3015431	Contract	Operation	VO-3212300	Alternator belt, replace	0.3
2021-12-03	585130	3015431	Contract	Operation	VO-2630700	Drive belts fan, replace	0.5
2021-12-03	585130	3015431	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2021-12-03	585130	3015431	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2021-12-03	585130	3015431	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2021-12-03	585130	3015431	Contract	Operation	VO-3210700	Belt tensioner, alternator, replace	0.3
2021-12-03	585130	3015431	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2021-12-03	585130	3015431	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2021-12-03	585130	3015431	Contract	Operation	VO-2630800	Fan belt tensioner, replace	0.4
2021-12-03	585130	3015431	Contract	Operation	VO-1784600	Trailer coupling, safety and function ch	0.2
2021-12-03	585130	3015431	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	57
2021-12-03	585130	3015431	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2021-12-03	585130	3015431	Contract	Part	VO-20579690	GASKET	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2021-12-03	585130	3015431	Contract	Part	VO-23961744	ALTERNATOR BELT	1
2021-12-03	585130	3015431	Contract	Part	VO-23402101	BELT TENSIONER	1
2021-12-03	585130	3015431	Contract	Part	VO-23961777	FAN BELT	1
2021-12-03	585130	3015431	Contract	Part	VO-22950501	BELT TENSIONER	1
2021-12-03	585130	3015431	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2021-12-03	585130	3015431	Contract	Part	VO-20997037	BUG DEFLECTOR 48" CLEAR	1
2021-12-03	585130	3015431	Contract	Operation	VO-8919700	Bug deflector, hood, replace. Gas system	0.4
2021-12-03	585130	3015431	Contract	Part	MK-6990-40176	STRUT L/H	1
2021-12-03	585130	3015431	Contract	Operation	VO-6413100	Gas spring, steering wheel adjustment, r	0.4
2021-11-10	564784	3015049	Internal	Other	179	Service -Pick up and delivery	
2021-11-10	564784	3015049	Contract	Operation	VO-2637500	Fan belt idler pulley, replace	0.4
2021-11-10	564784	3015049	Contract	Part	VO-23961777	V-RIBBED BELT	1
2021-11-10	564784	3015049	Contract	Part	VO-21753149	IDLER PULLEY	1
2021-11-10	564784	3015049		Text		*** POSSIBLE POLICY CLAIM ***	
2021-11-10	564784	3015049	Contract	Part	VO-22950501	BELT TENSIONER	1
2021-11-10	564784	3015049	Contract	Operation	VO-2631300	Fan belt tensioner, replace	0.4
2021-11-10	564784	3015049	Contract	Operation	VO-2630700	Drive belts fan, replace	0.5
2021-11-10	564784	3015049	Contract	Operation	VO-2141300	Valves and unit injectors, adjust	2.1
2021-11-10	564784	3015049	Contract	Operation	VO-2111400	Valve Cover, Replacement	1.3
2021-11-10	564784	3015049	Contract	Operation	VO-2140800	Rocker arm shaft, replace	4.2
2021-10-28	557405	3014587	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2021-10-28	557405	3014587		Text		oil changes included only in some models	
2021-10-28	557405	3014587	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2021-10-28	557405	3014587	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2021-10-28	557405	3014587	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2021-10-28	557405	3014587	Contract	Operation	VO-2141300	Valves and unit injectors, adjust	2.1
2021-10-28	557405	3014587	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2021-10-28	557405	3014587	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2021-10-28	557405	3014587	Contract	Operation	VO-2112600	Cylinder head, replace	13.3
2021-10-28	557405	3014587	Contract	Operation	VO-1706500	18 Months ECU download and oil sample. O	0.9
2021-10-28	557405	3014587	Contract	Other	1784600	Trailer coupling, safety and function	
2021-10-28	557405	3014587	Contract	Part	VO-85022144	CYLINDER HEAD, EXC	1
2021-10-28	557405	3014587	Contract	Part	VO-21539900	GASKET KIT MP10 / 16LTR	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2021-10-28	557405	3014587	Contract	Part	VO-24122024	VOLVO FILTER KIT	1
2021-10-28	557405	3014587	Contract	Part	AU2-AMP23068:	ENGINE OIL VDS4.5 15W-40 BULK	57
2021-10-28	557405	3014587	Contract	Part	VO-21053055	HOSE, COOLANT	1
2021-10-28	557405	3014587	Contract	Part	VO-21053033	HOSE	1
2021-10-28	557405	3014587	Contract	Part	VO-22998748	COOLANT PIPE	1
2021-10-28	557405	3014587	Contract	Part	VO-3092340	SEALANT VOLVO GREY	1
2021-10-28	557405	3014587	Contract	Part	VO-21344774	BOLT INJECTOR HOLD DOWN	1
2021-10-28	557405	3014587	Contract	Part	VO-21503575	SEAL THERMOSTAT	1
2021-10-28	557405	3014587	Contract	Part	VO-20852765	GASKET FUEL LINE	4
2021-10-28	557405	3014587	Contract	Part	VO-996457	FLANGE SCREW INLET MANIFOLD	12
2021-10-28	557405	3014587	Contract	Part	VO-21344787	MP10 EXH MAN BOLT	24
2021-10-28	557405	3014587	Contract	Part	VO-8192804	MP10 CAM BOLT	8
2021-10-28	557405	3014587	Contract	Part	VO-21015266	MP10 ADJ GEAR SCREW	6
2021-10-28	557405	3014587	Contract	Part	VO-994447	FLANGE SCREW	25
2021-10-28	557405	3014587	Contract	Part	VO-983472	SMALL GREY CABLE TIE	6
2021-10-28	557405	3014587	Contract	Part	VO-8131393	CAGE	6
2021-10-28	557405	3014587	Contract	Part	VO-1675066	TURBO INTAKE SEAL	1
2021-10-28	557405	3014587	Contract	Part	VO-8073055	O-RING	1
2021-10-28	557405	3014587	Contract	Part	VO-21345129	SCREW HEAD BOLT	38
2021-10-28	557405	3014587	Contract	Part	VO-3979639	PRE HEATER GASKET	1
2021-10-28	557405	3014587	Contract	Part	VO-1677370	SEALING RING	1
2021-10-28	557405	3014587	Contract	Part	VO-20526428	SEALING RING	1
2021-10-28	557405	3014587	Contract	Part	VO-471708	COMP INLET SEAL	2
2021-10-28	557405	3014587	Contract	Part	VO-23448457	SOS VOLVO OIL SAMPLE	4
2021-10-28	557405	3014587	Contract	Part	VO-1547252	SEAL W/PUMP 21MM ID	1
2021-10-28	557405	3014587	Contract	Part	AU2-AMP22567:	VOLVO VCS COOLANT 5L 2980-235	2
2021-10-28	557405	3014587	Contract	Operation	LO-179	Service -Pick up and delivery	0.5
2021-10-13	542284	3014364	Internal	Operation	LO-179	Service -Pick up and delivery	0.6
2021-10-13	542284	3014364	Internal	Part	OTH-KT3014825	ZIP TIE 300 X 4.8MM 25PK	1
2021-10-13	542284	3014364	Internal	Part	OTH-KTDT2	DEUTSCH PLUG 2 PIN KIT	1
2021-10-13	542284	3014364		Text		Concern: Seat belt not latching	
2021-10-13	542284	3014364	Contract	Operation	VO-8840800	Seat belt, replace (one)	0.4
2021-10-13	542284	3014364	Contract	Part	VO-23454858	SEAT BELT CATCH	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2021-10-13	542284	3014364	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - PLUG	
2021-10-13	542284	3014364	Contract	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2021-10-13	542284	3014364	Contract	Operation	VO-3700100	Wire harness, repair. repair only	0.5
2021-09-22	524607	3013915	Internal	Part	OTH-LOC56707	LOCTITE 567	1
2021-09-22	524607	3013915	Internal	Part	OTH-KT3014825	ZIP TIE 300 X 4.8MM 25PK	1
2021-09-22	524607	3013915	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	50
2021-09-22	524607	3013915	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2021-09-22	524607	3013915		Text		oil changes included only in some models	
2021-09-22	524607	3013915	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2021-09-22	524607	3013915	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2021-09-22	524607	3013915	Contract	Operation	VO-7714500	Wheel nuts, check tightening (all)	0.3
2021-09-22	524607	3013915	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2021-09-22	524607	3013915	Contract	Operation	VO-5616600	Air drier cassette, replace	0.4
2021-09-22	524607	3013915	Contract	Operation	VO-2582200	Filter, AdBlue, replace	0.3
2021-09-22	524607	3013915	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2021-09-22	524607	3013915	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2021-09-22	524607	3013915	Contract	Other	1784600	Trailer coupling, safety and function	
2021-09-22	524607	3013915	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2021-09-22	524607	3013915	Contract	Part	VO-85136742	VOLVO FILTER KIT	1
2021-09-22	524607	3013915	Contract	Part	VO-85129688	AIR DRIER FILTER	1
2021-09-22	524607	3013915	Contract	Part	VO-23381558	ADBLUE FILTER NB	1
2021-09-22	524607	3013915	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - GREASE	
2021-09-22	524607	3013915	Contract	Operation	VO-3658300	Pressure switch, park brake, replace	0.4
2021-09-22	524607	3013915	Contract	Part	VO-25165995	SWITCH PRESSURE	1
2021-09-22	524607	3013915	Contract	Part	VO-22082849	PRESSURE SWITCH	1
2021-09-22	524607	3013915	Contract	Part	MK-FT1862X6	3/8" JOINER PUSH	1
2021-09-22	524607	3013915	Contract	Part	MK-FT1469X8X8	1/2" X 1/2" 90 DEG	2
2021-09-22	524607	3013915	Contract	Operation	VO-3658200	Pressure switch, stop light, replace	0.4
2021-09-22	524607	3013915	Contract	Operation	VO-5638700	Air fitting, replace	0.4
2021-09-22	524607	3013915	Contract	Part	MK-FT1880X6X6	3/8" X 3/8" 45DEG PU	1
2021-09-22	524607	3013915	Contract	Other	179	Service -Pick up and delivery	
2021-09-22	524607	3013915	Contract	Part	VO-21850098	RELAY VALVE (ESP) *NOTES	1
2021-09-22	524607	3013915	Contract	Operation	VO-5634200	Service brake relay valve, replace	0.7

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2021-09-22	524607	3013915	Contract	Part	VO-23454856	SEAT BELT	1
2021-09-22	524607	3013915	Contract	Operation	VO-8840800	Seat belt, replace (one)	0.4
2021-09-22	524607	3013915	Contract	Part	MK-5435-SC292	STEERING DAMPER NB	1
2021-09-22	524607	3013915	Contract	Operation	VO-6460200	Steering damper, replace	0.4
2021-09-22	524607	3013915	Contract	Part	VO-21780376	SEALING RING	1
2021-09-22	524607	3013915	Contract	Operation	VO-2215300	Fitting, oil line, replace	0.2
2021-09-22	524607	3013915	Contract	Part	MK-57MD42M	***ELEMENT, AIR 'C	2
2021-09-22	524607	3013915	Contract	Operation	VO-2562400	Filter insert, air cleaner, replace. Onl	0.2
2021-08-12	493465	3013028	Internal	Other	3563600	Beacon lamp, lense	
2021-08-12	493465	3013028	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	50
2021-08-12	493465	3013028	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2021-08-12	493465	3013028		Text		oil changes included only in some models	
2021-08-12	493465	3013028	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2021-08-12	493465	3013028	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2021-08-12	493465	3013028	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2021-08-12	493465	3013028	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2021-08-12	493465	3013028	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2021-08-12	493465	3013028	Contract	Operation	VO-2601000	Coolant, change	0.4
2021-08-12	493465	3013028	Contract	Other	1784600	Trailer coupling, safety and function	
2021-08-12	493465	3013028	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2021-08-12	493465	3013028	Contract	Part	VO-85136742	VOLVO FILTER KIT	1
2021-08-12	493465	3013028	Contract	Part	AU2-CAL839486	VCS COOLANT 20L	3
2021-08-12	493465	3013028	Contract	Part	VO-984736	FLANGE SCREW	1
2021-08-12	493465	3013028	Contract	Part	VO-990950	NUT FLANGE M8 X 9.4 GR 8 BLK	1
2021-08-12	493465	3013028	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - GREASE	
2021-08-12	493465	3013028	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2021-08-12	493465	3013028	Contract	Part	VO-82710488	WIPER BLADE BASIC	2
2021-08-12	493465	3013028	Contract	Operation	VO-3630400	Windscreen wiper blade, replace	0.1
2021-08-12	493465	3013028	Contract	Part	VO-85151124	CAB AC FILTER NB	1
2021-08-12	493465	3013028	Contract	Operation	VO-8747400	Air filter insert, A/C unit, replace	0.3
2021-08-03	485433	3012911	Internal	Operation	LO-179	Service -Pick up and delivery	0.6
2021-08-03	485433	3012911		Text		Concern: AC compressor hose leaking	
2021-08-03	485433	3012911	Contract	Operation	VO-5638700	Air fitting, replace	0.4

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2021-08-03	485433	3012911	Contract	Part	MK-FT1462X4	1/4" JOINER COMP	1
2021-08-03	485433	3012911	Contract	Part	VO-20448956	16mm-1/4 FITTING	1
2021-08-03	485433	3012911	Contract	Operation	VO-2124100	Oil plug or drain valve, replace	0.2
2021-08-03	485433	3012911	Contract	Part	MK-ABCABF123	1/4" DRAIN VALVE PULL 1500 MM	1
2021-08-03	485433	3012911	Contract	Operation	LO-362	City horn, replace	0.3
2021-08-03	485433	3012911	Contract	Part	VO-20867711	HORN	1
2021-07-12	468860	3842285	Contract	Other	10	Sublet - NT Auto Air	
2021-07-12	468860	3842285		Text		CHECK AC OPERATION	
2021-07-12	468860	3842285	Contract	Other	874	Air conditioning N/W, blowing warm air	
2021-07-08	465499	3012386	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2021-07-08	465499	3012386		Text		oil changes included only in some models	
2021-07-08	465499	3012386	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2021-07-08	465499	3012386	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2021-07-08	465499	3012386	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2021-07-08	465499	3012386	Contract	Operation	VO-2141300	Valves and unit injectors, adjust	2.1
2021-07-08	465499	3012386	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2021-07-08	465499	3012386	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2021-07-08	465499	3012386	Contract	Operation	VO-6451400	Oil and filter, power steering, replace	0.4
2021-07-08	465499	3012386	Contract	Other	1784600	Trailer coupling, safety and function	
2021-07-08	465499	3012386	Contract	Part	VO-85136742	VOLVO FILTER KIT	1
2021-07-08	465499	3012386	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2021-07-08	465499	3012386	Contract	Part	MK-5839-87067	FILTER P/STR GRAN	1
2021-07-08	465499	3012386	Contract	Part	VO-85122800	ATF DEX 3 1 LTR	5
2021-07-08	465499	3012386	Contract	Part	VO-20736230	MP10 T/COVER GASKET	1
2021-07-08	465499	3012386	Contract	Operation	LO-179	Service -Pick up and delivery	0.5
2021-06-07	435829	3011768	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	50
2021-06-07	435829	3011768	Internal	Part	OTH-836-4-RL	WASTEGATE HOSE PER INCH	4
2021-06-07	435829	3011768	Internal	Part	OTH-LOC44279	LOCTITE 263	1
2021-06-07	435829	3011768	Internal	Part	OTH-LOC47131	LOCTITE 609 10ML RET COMOUND	1
2021-06-07	435829	3011768	Internal	Part	OTH-DR1342	75MM WIZZ DISC FINE BLUE	1
2021-06-07	435829	3011768	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2021-06-07	435829	3011768		Text		oil changes included only in some models	
2021-06-07	435829	3011768	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2021-06-07	435829	3011768	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2021-06-07	435829	3011768	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2021-06-07	435829	3011768	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2021-06-07	435829	3011768	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2021-06-07	435829	3011768	Contract	Operation	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.4
2021-06-07	435829	3011768	Contract	Operation	VO-1752700	Final drive oil, change. Lube area	0.6
2021-06-07	435829	3011768	Contract	Operation	VO-2551800	Engine turbocharger, replace. Chassis mo	2.2
2021-06-07	435829	3011768	Contract	Operation	VO-2620200	Coolant pump, replace	1.1
2021-06-07	435829	3011768	Contract	Operation	VO-5611100	Compressor, replace	2.3
2021-06-07	435829	3011768	Contract	Other	1784600	Trailer coupling, safety and function	
2021-06-07	435829	3011768	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2021-06-07	435829	3011768	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2021-06-07	435829	3011768	Contract	Part	VO-20579690	GASKET	1
2021-06-07	435829	3011768	Contract	Part	AU2-CAL851074	VOLVO GEAR OIL 20L	1
2021-06-07	435829	3011768	Contract	Part	AU2-CAL851362	VOLVO SYN AXLE 20L	2
2021-06-07	435829	3011768	Contract	Part	VO-20779040	M DRIVE FILTER KIT WITH O RING	1
2021-06-07	435829	3011768	Contract	Part	VO-21638569	EXCH TURBOCHARGER *NOTES	1
2021-06-07	435829	3011768	Contract	Part	VO-1675066	TURBO INTAKE SEAL	1
2021-06-07	435829	3011768	Contract	Part	VO-20562526	SPACER SLEEVE	4
2021-06-07	435829	3011768	Contract	Part	VO-20784537	TURBO BASE GASKET	1
2021-06-07	435829	3011768	Contract	Part	VO-21940610	SEAL FEED OF HOUSING	1
2021-06-07	435829	3011768	Contract	Part	VO-21940615	TURBO DRN SEAL(BLOCK	1
2021-06-07	435829	3011768	Contract	Part	VO-22206133	TURBO FEED GASKET	1
2021-06-07	435829	3011768	Contract	Part	VO-467310	V CLAMP TURBO 16LTR *NOTES	1
2021-06-07	435829	3011768	Contract	Part	VO-470993	GASKET RETURN PIPE	1
2021-06-07	435829	3011768	Contract	Part	VO-8073055	O-RING	1
2021-06-07	435829	3011768	Contract	Part	VO-990950	NUT FLANGE M8 X 9.4 GR 8 BLK	1
2021-06-07	435829	3011768	Contract	Part	VO-993811	TURBO MOUNT BOLT	4
2021-06-07	435829	3011768	Contract	Part	VO-994441	BOLT FLANGE M8 X 50 8.8 BLACK	1
2021-06-07	435829	3011768	Contract	Part	VO-85151110	EXCH MP WATER PUMP	1
2021-06-07	435829	3011768	Contract	Part	VO-85155724	EXCH MP AIR COMPRESSOR	1
2021-06-07	435829	3011768	Contract	Part	VO-21339891	COMPRESSOR RUBBER HOSE PER MET	1
2021-06-07	435829	3011768	Contract	Part	VO-471708	COMP INLET SEAL	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2021-06-07	435829	3011768	Contract	Part	VO-992065	O-RING	1
2021-06-07	435829	3011768	Contract	Part	AU2-WUR05492	HOSE CLAMP 16-27MM 12MM WIDE	4
2021-06-07	435829	3011768	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts	
2021-06-07	435829	3011768	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2021-06-07	435829	3011768	Contract	Operation	VO-2510400	Gaskets, exhaust manifold, replace	2.7
2021-06-07	435829	3011768	Contract	Part	VO-21352841	EXH MAN GASKET	6
2021-06-07	435829	3011768	Contract	Part	VO-21344787	MP10 EXH MAN BOLT	24
2021-06-07	435829	3011768	Contract	Part	VO-21695684	SEALING RING	2
2021-06-07	435829	3011768	Contract	Part	VO-20938964	EXHAUST MANIFOLD SLIP SEAL	1
2021-06-07	435829	3011768	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - wastegate hose	
2021-05-24	422475	3011547		Text		Concern: Replace front relay valve RH in chassis rail.	
2021-05-24	422475	3011547	Contract	Operation	VO-5634200	Service brake relay valve, replace	0.7
2021-05-24	422475	3011547	Contract	Part	VO-21850098	RELAY VALVE (ESP) *NOTES	1
2021-05-14	413682	3011355	Internal	Operation	LO-179	Service -Pick up and delivery	0.6
2021-05-14	413682	3011355	Internal	Part	OTH-OGX398	R134A AC GAS 100G AU45908	2
2021-05-14	413682	3011355		Text		Concern: Air con leaking green fluid	
2021-05-14	413682	3011355	Contract	Operation	VO-8740800	Condenser, replace	0.5
2021-05-14	413682	3011355	Contract	Part	VO-22386057	CONDENSER	1
2021-05-14	413682	3011355	Contract	Part	VO-82781567	RECEIVER DRIER	1
2021-05-14	413682	3011355	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - A/C GAS	
2021-05-14	413682	3011355	Contract	Operation	VO-8740500	Dryer, replace	0.2
2021-05-14	413682	3011355	Contract	Operation	LO-170	Take charge	0.3
2021-05-14	413682	3011355	Contract	Operation	LO-874	A/C System leakproofness test	0.6
2021-05-11	380768	5000670	Contract	Operation	VO-1706400	12 Months ECU download and oil sample. O	0.9
2021-05-11	380768	5000670		Text		Only valid for Australian market	
2021-05-11	380768	5000670	Contract	Operation	VO-8100300	12 Months cab inspection	0.5
2021-05-11	380768	5000670	Contract	Part	VO-23448457	SOS VOLVO OIL SAMPLE	4
2021-05-07	406941	3011138	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	50
2021-05-07	406941	3011138	Internal	Part	OTH-NARV4750	bulb 12v 5w	1
2021-05-07	406941	3011138	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2021-05-07	406941	3011138		Text		oil changes included only in some models	
2021-05-07	406941	3011138	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2021-05-07	406941	3011138	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2021-05-07	406941	3011138	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2021-05-07	406941	3011138	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2021-05-07	406941	3011138	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2021-05-07	406941	3011138	Contract	Operation	VO-1784600	Trailer coupling, safety and function ch	0.2
2021-05-07	406941	3011138	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2021-05-07	406941	3011138	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2021-05-07	406941	3011138	Contract	Part	VO-20579690	GASKET	1
2021-05-07	406941	3011138	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - GREASE	
2021-05-07	406941	3011138	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2021-05-07	406941	3011138	Contract	Operation	VO-1701200	Fault codes, reading	0.2
2021-05-07	406941	3011138	Contract	Operation	LO-364	Exhaust brake not operating	0.4
2021-05-07	406941	3011138	Contract	Part	VO-22222498	EXH BRAKE SWITCH HI/LO	1
2021-05-07	406941	3011138	Contract	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2021-05-07	406941	3011138	Contract	Operation	VO-2533600	Engine brake function, test	0.4
2021-05-07	406941	3011138	Contract	Operation	VO-3100500	Battery, replace (one or two)	0.6
2021-05-07	406941	3011138	Contract	Part	AU2-CEN12310	BATT N70ZZH CENTURY	4
2021-05-07	406941	3011138	Contract	Operation	VO-3116800	Battery system, test. Battery tester	0.4
2021-05-07	406941	3011138	Contract	Operation	VO-3510400	Headlight bulb, replace (one). 1 unit, e	0.1
2021-05-07	406941	3011138	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - BULB	
2021-04-22	391455	3010888	Internal	Operation	LO-179	Service -Pick up and delivery	0.6
2021-04-22	391455	3010888	Contract	Operation	VO-8746600	Receiver/drier, replace	1.3
2021-04-22	391455	3010888	Contract	Part	VO-82781567	RECEIVER DRIER	1
2021-04-22	391455	3010888	Contract	Part	VO-85113770	TX VALVE	1
2021-04-22	391455	3010888	Contract	Part	VO-85151124	CAB AC FILTER NB	1
2021-04-22	391455	3010888		Text		Concern: AC not cold.	
2021-04-22	391455	3010888	Contract	Operation	VO-8790500	Expansion valve, replace	0.5
2021-04-22	391455	3010888	Contract	Operation	VO-8747400	Air filter insert, A/C unit, replace	0.3
2021-04-22	391455	3010888	Contract	Operation	LO-170	TAKE CHARGE	0.3
2021-04-21	380768	3011261	Contract	Operation	VO-1706400	12 Months ECU download and oil sample. O	0.9
2021-04-21	380768	3011261		Text		Only valid for Australian market	
2021-04-21	380768	3011261	Contract	Operation	VO-8100300	12 Months cab inspection	0.5
2021-04-21	380768	3011261	Contract	Part	VO-23448457	SOS VOLVO OIL SAMPLE	4
2021-04-19	390367	3010822	Internal	Operation	LO-179	Service -Pick up and delivery	0.6

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2021-04-19	390367	3010822	Contract	Operation	VO-2180500	Cushion mount, replace (front)	1.7
2021-04-19	390367	3010822	Contract	Part	VO-20503550	RUBBER CUSHION	1
2021-04-19	390367	3010822		Text		Inspected and found front engine mount split. Removed	
2021-04-19	390367	3010822	Contract	Part	MK-ABC800155	ST4 SAFETY VALVE 1/4" 200PSI	1
2021-04-19	390367	3010822	Contract	Operation	VO-2348300	Valve, replace	0.4
2021-04-06	380768	3010594	Internal	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2021-04-06	380768	3010594	Contract	Part	VO-20579690	GASKET	1
2021-04-06	380768	3010594	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	50
2021-04-06	380768	3010594	Contract	Operation	VO-1774600	Annual service. Chassis lubrication and	2.4
2021-04-06	380768	3010594		Text		oil changes included only in some models	
2021-04-06	380768	3010594	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2021-04-06	380768	3010594	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2021-04-06	380768	3010594	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2021-04-06	380768	3010594	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2021-04-06	380768	3010594	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2021-04-06	380768	3010594	Contract	Operation	VO-2562700	Filter insert, air cleaner, replace. Onl	0.2
2021-04-06	380768	3010594	Contract	Operation	VO-2141300	Valves and unit injectors, adjust	2.1
2021-04-06	380768	3010594	Contract	Operation	VO-6452500	Oil filter, power steering, replace	0.2
2021-04-06	380768	3010594	Contract	Operation	VO-8747400	Air filter insert, A/C unit, replace	0.3
2021-04-06	380768	3010594	Contract	Other	1784600	Trailer coupling, safety and function	
2021-04-06	380768	3010594	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2021-04-06	380768	3010594	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2021-04-06	380768	3010594	Contract	Part	MK-57MD42M	***ELEMENT, AIR 'C	2
2021-04-06	380768	3010594	Contract	Part	MK-5839-87067	FILTER P/STR GRAN	1
2021-04-06	380768	3010594	Contract	Part	VO-85151124	CAB AC FILTER NB	1
2021-04-06	380768	3010594	Contract	Part	VO-85109772	H11 12V 55W LOW	1
2021-04-06	380768	3010594	Contract	Part	VO-85124906	HB3A 12V 60W BULB	1
2021-04-06	380768	3010594	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - GREASE	
2021-04-06	380768	3010594	Contract	Operation	VO-1706400	12 Months ECU download and oil sample. O	0.9
2021-04-06	380768	3010594	Contract	Operation	VO-8100300	12 Months cab inspection	0.5
2021-04-06	380768	3010594	Contract	Part	VO-23448457	SOS VOLVO OIL SAMPLE	4
2021-04-06	380768	3010594	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2021-03-29	380768	3010402	Retail	Operation	VO-5933200	EBS control unit, replace	12

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2021-03-29	380768	3010402		Text		Fit inverter and TRM system.	
2021-03-29	380768	3010402	Retail	Part	MK-745-CV2122	12V RETROFIT KIT	1
2021-03-29	380768	3010402	Retail	Part	OTH-DPS2420	24V POWER SUPPLY	1
2021-03-29	380768	3010402	Retail	Part	OTH-5806--7RD	6 B&S SINGLE CORE WIRE	1
2021-03-29	380768	3010402	Retail	Part	OTH-5808-7RD	8 B&S SINGLE CORE RED	1
2021-03-29	380768	3010402	Retail	Part	OTH-ACX0763M	6MM RED SINGLE CORE CABLE M	10
2021-03-29	380768	3010402	Retail	Part	OTH-NPN	ASSORTED ELECTRICAL SUPPLIES	1
2021-03-29	380768	3010402	Retail	Other	10	SUBLET: Fabricate brackets	
2021-03-29	380768	3010402	Retail	Part	OTH-ACX1363A	16MM CONDUIT HD	4
2021-03-29	380768	3010402	Retail	Part	OTH-ACX1106	12.6MM SPLIT TUBE	1
2021-03-29	380768	3010402	Retail	Part	MK-NARV56707	TUBING 7MM 1=10M	1
2021-03-29	380768	3010402	Retail	Part	OTH-TDR05211	THUNDER MINI FUSE HOLDER	1
2021-03-29	380768	3010402	Retail	Part	MK-NARV52720	FUSE 20 AMP MINI	1
2021-03-29	380768	3010402	Retail	Part	MK-NARV68082	RELAY BASE 4/5 PIN	1
2021-03-29	380768	3010402	Retail	Part	MK-NARV68000	RELAY N/O 12V 4 PIN 40AMP	1
2021-03-29	380768	3010402	Retail	Part	OTH-FK60	60A FUSE KIT	1
2021-03-29	380768	3010402	Retail	Part	OTH-FK40	40A FUSE KIT	1
2021-03-29	380768	3010402	Retail	Part	OTH-12X40M10	BOLT M12 X 40 PC 10.9	4
2021-03-29	380768	3010402	Retail	Part	OTH-12HTW	WASHER 1/2 GR8	8
2021-03-29	380768	3010402	Retail	Part	OTH-12MNYLN	M12 CL8 NYLOC NUT	4
2021-03-29	380768	3010402	Retail	Part	OTH-14X2.12NC	BOLT 1/4 UNC X2-1/2 GR8	3
2021-03-29	380768	3010402	Retail	Part	OTH-14HTW	WASHER 1/4 GR8	14
2021-03-29	380768	3010402	Retail	Part	OTH-14NCNYLN	NUT NYLOC 1/4 UNC GR5	7
2021-03-29	380768	3010402	Retail	Part	OTH-1/4X1UNC;	1/4X1" UNC BOLT	1
2021-03-29	380768	3010402	Retail	Part	VO-20469544	VOLVO CLOTH TAPE	1
2021-03-29	380768	3010402	Retail	Part	OTH-AT219592	MASKING TAPE 48MM 50M	1
2021-03-29	380768	3010402	Retail	Part	OTH-NARV5712	CABLE LUG 16MM X 6MM	2
2021-03-29	380768	3010402	Retail	Part	OTH-NARV5712	CABLE LUG 16MM X 10MM	2
2021-03-29	380768	3010402	Retail	Part	OTH-NARV6808	RELAY BASE 4 & 5 PIN	1
2021-03-29	380768	3010402	Retail	Part	OTH-ACX6150	SOLDER ROLL	1
2021-03-29	380768	3010402	Retail	Part	OTH-NARV5660	HEAT SHR KIT	1
2021-03-29	380768	3010402	Retail	Part	OTH-KT3827525	CABLE TIE 380 X 7.5MM	1
2021-03-29	380768	3010402	Retail	Part	OTH-KT3014825	ZIP TIE 300 X 4.8MM 25PK	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2021-03-29	380768	3010402	Retail	Part	OTH-ROADFREI	ROAD FREIGHT	10
2021-03-29	380768	3010402	Retail	Other	91	Workshop Consumables	
2021-03-29	0	3010649	Retail	Operation	LO-MBRACKE	WATERCUT ABS BRACKET	4.34
2021-03-18	367488	3010305	Internal	Operation	LO-179	Service -Pick up and delivery	0.6
2021-03-18	367488	3010305	Warranty	Operation	VO-1701200	Fault codes, reading	0.2
2021-03-18	367488	3010305		Text		Check engine light on all the time Alarm 3443. Suspect Ad	
2021-03-18	367488	3010305	Warranty	Part	VO-22406383	ADBLUE STRAINER (TEA BAG)	1
2021-03-18	367488	3010305	Warranty	Operation	VO-2584800	Strainer, replace. Pump unit	0.7
2021-03-18	367488	3010305	Warranty	Operation	VO-2580300	AdBlue tank, replace	1.1
2021-03-18	367488	3010305	Warranty	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2021-03-18	367488	3010305	Warranty	Operation	LO-170	take charge	0.3
2021-03-18	367488	3010305	Warranty	Operation	LO-210	Road test	0.5
2021-03-11	360863	3010125	Internal	Operation	LO-179	Service -Pick up and delivery	0.6
2021-03-11	360863	3010125	Warranty	Operation	VO-2605300	Fan hub, replace. Fan removed	0.4
2021-03-11	360863	3010125		Text		Concern: Testing.	
2021-03-11	360863	3010125	Warranty	Operation	VO-2630200	Fan blade, replace	2.4
2021-03-01	347626	811612	Contract	Operation	VO-9600000		1
2021-03-01	347626	811612	Contract	Operation	VO-9600000		1
2021-03-01	347626	811612	Contract	Operation	VO-9600000		1
2021-02-24	347625	3009802	Contract	Part	VO-20579690	GASKET	1
2021-02-24	347625	3009802	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	50
2021-02-24	347625	3009802	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2021-02-24	347625	3009802		Text		oil changes included only in some models	
2021-02-24	347625	3009802	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2021-02-24	347625	3009802	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2021-02-24	347625	3009802	Contract	Operation	VO-2582200	Filter, AdBlue, replace	0.3
2021-02-24	347625	3009802	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2021-02-24	347625	3009802	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2021-02-24	347625	3009802	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2021-02-24	347625	3009802	Contract	Operation	VO-5616600	Air drier cassette, replace	0.4
2021-02-24	347625	3009802	Contract	Operation	VO-7714500	Wheel nuts, check tightening (all)	0.3
2021-02-24	347625	3009802	Contract	Other	1784600	Trailer coupling, safety and function	
2021-02-24	347625	3009802	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2021-02-24	347625	3009802	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2021-02-24	347625	3009802	Contract	Part	VO-23381558	ADBLUE FILTER NB	1
2021-02-24	347625	3009802	Contract	Part	VO-85129688	AIR DRIER FILTER	1
2021-02-24	347625	3009802	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - GREASE	
2021-02-24	347625	3009802	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2021-02-24	347625	3009802	Warranty	Part	VO-85109890	REPAIR KIT CALIPER	2
2021-02-24	347625	3009802	Warranty	Operation	VO-5117200	Brake caliper, install (one side). Wheel	0.7
2021-02-17	0	3009731	Internal	Operation	LO-100	CUSTOM AIR ISSUES - SOMETIMES IT WON'T	2.84
2021-02-17	0	3009731		Text		START, SOMETIMES IT STARTS, & SOMETIMES IT WILL START &	
2021-02-16	341019	3009730	Internal	Operation	LO-179	Service -Pick up and delivery	0.6
2021-02-16	341019	3009730	Contract	Operation	VO-2611800	Expansion tank, replace	0.7
2021-02-16	341019	3009730		Text		Inspect coolant leak at header tank.	
2021-02-16	341019	3009730	Contract	Part	VO-23059017	EXPANSION TANK	1
2021-02-09	334425	3009614	Contract	Operation	LO-364	Turn signal/cruise control switch	0.4
2021-02-09	334425	3009614	Contract	Part	VO-20906004	TURN SIGNAL SWITCH	1
2021-02-09	334425	3009614		Text		assembly, replace	
2021-02-08	0	3009592		Text		Repair without detail info	
2021-02-03	328889	3009503	Contract	Other	10	SUBLET: Remove & Replace Wiper Blades	
2021-02-03	328889	3009503	Contract	Other	363	OTHER ELECTRICAL EQUIPMENT - WIPERS	
2021-01-19	320434	3009182	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	50
2021-01-19	320434	3009182	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2021-01-19	320434	3009182		Text		oil changes included only in some models	
2021-01-19	320434	3009182	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.3
2021-01-19	320434	3009182	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2021-01-19	320434	3009182	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
2021-01-19	320434	3009182	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2021-01-19	320434	3009182	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2021-01-19	320434	3009182	Contract	Other	1784600	Trailer coupling, safety and function	
2021-01-19	320434	3009182	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2021-01-19	320434	3009182	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2021-01-19	320434	3009182	Contract	Part	VO-85124906	HB3A 12V 60W BULB	1
2021-01-19	320434	3009182	Contract	Part	VO-85109772	H11 12V 55W LOW	1
2021-01-19	320434	3009182	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - GREASE	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2021-01-19	320434	3009182	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2021-01-12	313735	3009049	Warranty	Operation	VO-8533700	Cushion foam, replace	0.4
2021-01-12	313735	3009049	Warranty	Part	VO-85114453	SEAT CUSHION ISRI 6860/870	1
2021-01-12	313735	3009049		Text		*** POSSIBLE POLICY CLAIM ***	
2021-01-12	313735	3009049	Warranty	Operation	VO-8840800	Seat belt, replace (one)	0.4
2021-01-12	313735	3009049	Warranty	Part	VO-23454858	SEAT BELT CATCH	1
2021-01-12	313735	3009049	Contract	Operation	VO-3630400	Windscreen wiper blade, replace	0.1
2021-01-12	313735	3009049	Contract	Part	VO-82710488	WIPER BLADE BASIC	2
2021-01-12	313735	3009049	Warranty	Operation	VO-8182000	Cab shock absorber rear, replace (one)	0.3
2021-01-12	313735	3009049	Warranty	Part	VO-22971646	CAB SHOCK HEAVY DUTY UPGRADE	1
2020-12-17	296056	3008685	Internal	Other	561	COMPRESSOR,	
2020-12-17	296056	3008685	Contract	Part	VO-20579690	GASKET	1
2020-12-17	296056	3008685	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	50
2020-12-17	296056	3008685	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2020-12-17	296056	3008685		Text		oil changes included only in some models	
2020-12-17	296056	3008685	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2020-12-17	296056	3008685	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2020-12-17	296056	3008685	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.2
2020-12-17	296056	3008685	Contract	Operation	VO-2331100	Filter, water separator, replace	0.2
2020-12-17	296056	3008685	Contract	Operation	VO-2141300	Valves and unit injectors, adjust	2.1
2020-12-17	296056	3008685	Contract	Other	1784600	Trailer coupling, safety and function	
2020-12-17	296056	3008685	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2020-12-17	296056	3008685	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2020-12-17	296056	3008685	Contract	Part	VO-20736230	MP10 T/COVER GASKET	1
2020-12-17	296056	3008685	Contract	Part	VO-85124906	HB3A 12V 60W BULB	1
2020-12-17	296056	3008685	Contract	Part	VO-85109772	H11 12V 55W LOW	1
2020-12-17	296056	3008685	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - GREASE	
2020-12-17	296056	3008685	Contract	Operation	VO-5633400	Control valve, replace	0.3
2020-12-17	296056	3008685	Contract	Part	VO-21816920	PRESSURE PROT VALVE	1
2020-12-17	296056	3008685	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2020-12-17	296056	3008685	Contract	Operation	VO-3210700	Belt tensioner, alternator, replace	0.4
2020-12-17	296056	3008685	Contract	Operation	VO-3212300	Alternator belt, replace	0.4
2020-12-17	296056	3008685	Contract	Part	VO-23402101	BELT TENSIONER	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-12-17	296056	3008685	Contract	Part	VO-22950621	V-RIBBED BELT	1
2020-12-17	296056	3008685	Contract	Operation	VO-2630700	Drive belts fan, replace	0.4
2020-12-17	296056	3008685	Contract	Operation	VO-2630800	Fan belt tensioner, replace	0.2
2020-12-17	296056	3008685	Contract	Part	VO-21753149	IDLER PULLEY	1
2020-12-17	296056	3008685	Contract	Part	VO-22950564	V-RIBBED BELT 10PK1475	1
2020-12-17	296056	3008685	Contract	Part	VO-22950501	BELT TENSIONER	1
2020-12-17	296056	3008685	Warranty	Part	VO-20779144	SWITCH AC LOW PRESSURE	1
2020-12-17	296056	3008685	Warranty	Operation	VO-8735400	Temperature sensor, air conditioning sys	0.5
2020-12-10	262643	3008611	Contract	Part	VO-20579690	GASKET	1
2020-12-10	262643	3008611	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2020-12-10	262643	3008611		Text		oil changes included only in some models	
2020-12-10	262643	3008611	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2020-12-10	262643	3008611	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2020-12-10	262643	3008611	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2020-12-10	262643	3008611	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.2
2020-12-10	262643	3008611	Contract	Operation	VO-2331100	Filter, water separator, replace	0.2
2020-12-10	262643	3008611	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2020-12-10	262643	3008611	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2020-12-10	262643	5000555	Contract	Part	VO-20579690	GASKET	1
2020-12-10	262643	5000555	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2020-12-10	262643	5000555		Text		oil changes included only in some models	
2020-12-10	262643	5000555	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2020-12-10	262643	5000555	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2020-12-10	262643	5000555	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2020-12-10	262643	5000555	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.2
2020-12-10	262643	5000555	Contract	Operation	VO-2331100	Filter, water separator, replace	0.2
2020-12-10	262643	5000555	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2020-12-10	262643	5000555	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	52
2020-12-01	87664	811612	Contract	Operation	VO-9600000		1
2020-12-01	87664	811612	Contract	Operation	VO-9600000		1
2020-12-01	87664	811612	Contract	Operation	VO-9600000		1
2020-12-01	87664	811612	Contract	Operation	VO-9600000		1
2020-12-01	87664	811612	Contract	Operation	VO-9600000		1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-12-01	87664	811612	Contract	Operation	VO-9600000		1
2020-12-01	87664	811612	Contract	Operation	VO-9600000		1
2020-11-10	262643	3007969	Contract	Part	VO-20579690	GASKET	1
2020-11-10	262643	3007969	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2020-11-10	262643	3007969		Text		oil changes included only in some models	
2020-11-10	262643	3007969	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2020-11-10	262643	3007969	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2020-11-10	262643	3007969	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2020-11-10	262643	3007969	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.2
2020-11-10	262643	3007969	Contract	Operation	VO-2331100	Filter, water separator, replace	0.2
2020-11-10	262643	3007969	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2020-11-10	262643	3007969	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	52
2020-11-10	262643	3007969	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2020-11-10	262643	3007969	Contract	Operation	VO-2850800	Exhaust back pressure sensor, replace	0.2
2020-11-10	262643	3007969	Contract	Part	VO-85139619	BACK PRESSURE SENSOR	1
2020-11-10	262643	3007969	Contract	Part	VO-21582423	BACK PRS WIRE KIT	1
2020-11-10	262643	3007969	Contract	Operation	VO-2533600	Engine brake function, test	0.4
2020-11-10	262643	3007969	Contract	Operation	VO-1701200	Fault codes, reading	0.2
2020-11-10	262643	3007969	Contract	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2020-11-05	256007	3007916	Internal	Operation	LO-179	Service -Pick up and delivery	0.6
2020-11-05	256007	3007916	Contract	Operation	LO-372	CABLES AND FUSES-DISTR CENTRE,FUSEBOX	0.5
2020-11-05	256007	3007916	Contract	Part	VO-22640551	MANIFOLD W/O HOLE	1
2020-11-05	256007	3007916	Contract	Part	VO-25161826	1/4" PLUG AIR MANIFO	1
2020-11-05	256007	3007916		Text		Concern: Air leak at firewall.	
2020-11-05	256007	3007916	Contract	Operation	LO-170	TAKE CHARGE	0.3
2020-10-29	235395	3007824	Warranty	Part	VO-85139619	BACK PRESSURE SENSOR	1
2020-10-29	235395	3007824	Warranty	Part	VO-21582423	BACK PRS WIRE KIT	1
2020-10-29	235395	3007824	Warranty	Operation	VO-2850800	Exhaust back pressure sensor, replace	0.2
2020-10-15	235395	3007448	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	50
2020-10-15	235395	3007448	Internal	Part	OTH-OGX398	R134A AC GAS 100G AU45908	20
2020-10-15	235395	3007448	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2020-10-15	235395	3007448		Text		oil changes included only in some models	
2020-10-15	235395	3007448	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-10-15	235395	3007448	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2020-10-15	235395	3007448	Contract	Operation	VO-6451400	Oil and filter, power steering, replace	0.4
2020-10-15	235395	3007448	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2020-10-15	235395	3007448	Contract	Operation	VO-2330300	Fuel filter, replace (one)	0.3
2020-10-15	235395	3007448	Contract	Operation	VO-2331200	Filter, water separator, replace	0.3
2020-10-15	235395	3007448	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2020-10-15	235395	3007448	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2020-10-15	235395	3007448	Contract	Part	VO-85122800	ATF DEX 3 1 LTR	2
2020-10-15	235395	3007448	Contract	Part	MK-5839-87067	FILTER P/STR GRAN	1
2020-10-15	235395	3007448	Contract	Part	VO-85124906	HB3A 12V 60W BULB	1
2020-10-15	235395	3007448	Contract	Part	VO-85109772	H11 12V 55W LOW	1
2020-10-15	235395	3007448	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - GREASE	
2020-10-15	235395	3007448	Contract	Operation	VO-3510400	Headlight bulb, replace (one). 1 unit, e	0.1
2020-10-15	235395	3007448	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2020-10-15	235395	3007448	Warranty	Operation	VO-8742100	Low pressure hose, replace	0.6
2020-10-15	235395	3007448	Warranty	Part	VO-22605364	PIPE	1
2020-10-15	235395	3007448	Warranty	Other	WTY-NONGEN	WTY-Non Genuine Parts - R134A	
2020-10-15	235395	3007448	Warranty	Part	VO-82781567	RECEIVER DRIER	1
2020-10-15	235395	3007448	Warranty	Operation	VO-8746600	Receiver/drier, replace	1.3
2020-09-19	205523	3007041	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	50
2020-09-19	205523	3007041	Internal	Part	OTH-NARV4750	BULB 12V5W WEDGE	1
2020-09-19	205523	3007041	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2020-09-19	205523	3007041		Text		oil changes included only in some models	
2020-09-19	205523	3007041	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2020-09-19	205523	3007041	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2020-09-19	205523	3007041	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2020-09-19	205523	3007041	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.2
2020-09-19	205523	3007041	Contract	Operation	VO-2331100	Filter, water separator, replace	0.2
2020-09-19	205523	3007041	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2020-09-19	205523	3007041	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2020-09-19	205523	3007041	Contract	Part	VO-85124906	HB3A 12V 60W BULB	1
2020-09-19	205523	3007041	Contract	Part	VO-85109772	H11 12V 55W LOW	1
2020-09-19	205523	3007041	Contract	Part	MK-FT1469X8X8	1/2" X 1/2" 90 DEG	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-09-19	205523	3007041	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts	
2020-09-19	205523	3007041	Contract	Operation	VO-3510400	Headlight bulb, replace (one). 1 unit, e	0.1
2020-09-19	205523	3007041	Contract	Operation	VO-2141300	Valves and unit injectors, adjust	2.1
2020-09-19	205523	3007041	Contract	Part	VO-20736230	MP10 T/COVER GASKET	1
2020-09-19	205523	3007041	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2020-09-14	198823	3006957	Internal	Operation	LO-179	Service -Pick up and delivery	0.6
2020-09-14	198823	3006957	Warranty	Operation	VO-8530800	Control valve, replace	0.4
2020-09-14	198823	3006957	Warranty	Part	VO-85106107	CONTROL LEVER	1
2020-09-14	198823	3006957		Text		Concern: Replace seat adjuster for shock dampener.	
2020-09-11	192125	3006920	Warranty	Operation	VO-8530800	Control valve, replace	0.4
2020-09-11	192125	3006920	Warranty	Part	MK-ABC275707	D2 GOVERNOR VALVE	1
2020-09-11	192125	3006920		Text		Concern: Air governor.	
2020-09-11	192125	3006920	Warranty	Operation	VO-4010400	Gearbox, calibration	0.3
2020-09-11	192125	5000457	Contract	Operation	VO-8530800	Control valve, replace	0.4
2020-09-11	192125	5000457	Contract	Part	MK-ABC275707	D2 GOVERNOR VALVE	1
2020-09-11	192125	5000457		Text		Concern: Air governor.	
2020-09-11	192125	5000457	Contract	Operation	VO-4010400	Gearbox, calibration	0.3
2020-09-08	192125	3006798	Internal	Operation	LO-179	Service -Pick up and delivery	0.6
2020-09-08	192125	3006798	Contract	Operation	LO-251	INTAKE AND EXHAUST PIPES	0.5
2020-09-08	192125	3006798		Text		Concern: Inlet manifold.	
2020-09-08	192125	3006798	Contract	Operation	VO-2500300	Boost pressure, test	0.4
2020-09-08	192125	3006798	Contract	Operation	LO-170	TAKE CHARGE	0.3
2020-09-08	192125	3006798	Contract	Operation	VO-8530800	Control valve, replace	0.4
2020-09-08	192125	3006798	Contract	Part	MK-ABC275707	D2 GOVERNOR VALVE	1
2020-09-08	192125	3006798	Contract	Operation	VO-4010400	Gearbox, calibration	0.3
2020-08-24	172056	3006589	Contract	Part	VO-20579690	GASKET	1
2020-08-24	172056	3006589	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	50
2020-08-24	172056	3006589	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2020-08-24	172056	3006589		Text		oil changes included only in some models	
2020-08-24	172056	3006589	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2020-08-24	172056	3006589	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2020-08-24	172056	3006589	Contract	Operation	VO-2582200	Filter, AdBlue, replace	0.3
2020-08-24	172056	3006589	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-08-24	172056	3006589	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.2
2020-08-24	172056	3006589	Contract	Operation	VO-2331100	Filter, water separator, replace	0.2
2020-08-24	172056	3006589	Contract	Operation	VO-5616600	Air drier cassette, replace	0.4
2020-08-24	172056	3006589	Contract	Operation	VO-7714500	Wheel nuts, check tightening (all)	0.3
2020-08-24	172056	3006589	Contract	Part	VO-21516231	ADBLUE FILTER NB	1
2020-08-24	172056	3006589	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2020-08-24	172056	3006589	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2020-08-24	172056	3006589	Contract	Part	VO-85129688	AIR DRIER FILTER	1
2020-08-24	172056	3006589	Contract	Part	VO-85109772	H11 12V 55W LOW	1
2020-08-24	172056	3006589	Contract	Part	VO-85124906	HB3A 12V 60W BULB	1
2020-08-24	172056	3006589	Contract	Part	VO-85151124	CAB AC FILTER NB	1
2020-08-24	172056	3006589	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - GREASE	
2020-08-24	172056	3006589	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2020-08-24	172056	3006589	Contract	Operation	VO-1706300	6 Months ECU download and oil sample. On	0.9
2020-08-24	172056	3006589	Contract	Part	VO-23448457	SOS VOLVO OIL SAMPLE	4
2020-08-18	164304	3006522	Warranty	Operation	LO-476	DIFFERENTIAL LOCK	1.1
2020-08-18	164304	3006522		Text		Broken rear diff temp sensor wire at connector. Here now	
2020-08-18	164304	3006522	Warranty	Part	VO-25014495	TERMINAL,FEM (SOL	2
2020-08-18	164304	3006522	Warranty	Part	VO-25088933	SEAL,ELECTRICAL CA	2
2020-08-18	164304	3006522	Warranty	Part	VO-25013743	2 PIN DELPHI PLUG	1
2020-07-31	145340	3006241	Warranty	Operation	VO-8533700	Cushion foam, replace	0.4
2020-07-31	145340	3006241	Warranty	Part	VO-85114453	SEAT CUSHION	1
2020-07-31	145340	3006241		Text		Concern: Drivers seat leaning to the left.	
2020-07-31	145340	3006200	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	40
2020-07-31	145340	3006200	Internal	Part	OTH-NARV4750	BULB 12V5W WEDGE	1
2020-07-31	145340	3006200	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2020-07-31	145340	3006200		Text		oil changes included only in some models	
2020-07-31	145340	3006200	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.2
2020-07-31	145340	3006200	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2020-07-31	145340	3006200	Contract	Operation	VO-2331100	Filter, water separator, replace	0.2
2020-07-31	145340	3006200	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2020-07-31	145340	3006200	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2020-07-31	145340	3006200	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-07-31	145340	3006200	Contract	Part	VO-20579690	GASKET	1
2020-07-31	145340	3006200	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2020-07-31	145340	3006200	Contract	Part	VO-85124906	HB3A 12V 60W BULB	1
2020-07-31	145340	3006200	Contract	Part	VO-85109772	H11 12V 55W LOW	1
2020-07-31	145340	3006200	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - GREASE	
2020-07-31	145340	3006200	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2020-07-06	114731	3005751	Internal	Other	2710200	Accelerator pedal, test	
2020-07-06	114731	3005751	Contract	Part	VO-20579690	GASKET	1
2020-07-06	114731	3005751	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	50
2020-07-06	114731	3005751	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2020-07-06	114731	3005751		Text		oil changes included only in some models	
2020-07-06	114731	3005751	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2020-07-06	114731	3005751	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2020-07-06	114731	3005751	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2020-07-06	114731	3005751	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.2
2020-07-06	114731	3005751	Contract	Operation	VO-2331100	Filter, water separator, replace	0.2
2020-07-06	114731	3005751	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2020-07-06	114731	3005751	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2020-07-06	114731	3005751	Contract	Part	VO-85109772	H11 12V 55W LOW	1
2020-07-06	114731	3005751	Contract	Part	VO-85124906	HB3A 12V 60W BULB	1
2020-07-06	114731	3005751	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts - GREASE	
2020-07-06	114731	3005751	Warranty	Operation	VO-1701200	Fault codes, reading	0.2
2020-07-06	114731	3005751	Warranty	Part	VO-22387296	VEHICLE SPEED SENS	1
2020-07-06	114731	3005751	Warranty	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
2020-07-06	114731	3005751	Warranty	Operation	LO-386	SENSORS FOR INDICATOR/WARNING SYSTEM	0.3
2020-07-06	114731	3005751	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2020-06-15	87663	3005409	Contract	Part	VO-20579690	GASKET	1
2020-06-15	87663	3005409	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2020-06-15	87663	3005409		Text		oil changes included only in some models	
2020-06-15	87663	3005409	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2020-06-15	87663	3005409	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2020-06-15	87663	3005409	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2020-06-15	87663	3005409	Contract	Operation	VO-2330300	Fuel filter, replace (one)	0.3

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-06-15	87663	3005409	Contract	Operation	VO-2331100	Filter, water separator, replace	0.2
2020-06-15	87663	3005409	Contract	Operation	VO-2141300	Valves and unit injectors, adjust	2.1
2020-06-15	87663	3005409	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2020-06-15	87663	3005409	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2020-06-15	87663	3005409	Contract	Part	VO-20736230	MP10 T/COVER GASKET	1
2020-06-15	87663	3005409	Contract	Part	VO-85124906	HB3A 12V 60W BULB	1
2020-06-15	87663	3005409	Contract	Part	VO-85109772	H11 12V 55W LOW	1
2020-06-15	87663	3005409	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2020-06-15	87663	3005409	Contract	Part	VO-22725964	HOSE	1
2020-06-15	87663	3005409	Contract	Operation	LO-257	CRANKCASE VENTILATION	0.1
2020-06-05	60054	5000328	Contract	Operation	LO-234	FUEL TANK AND CONNECTION PARTS	0.5
2020-06-05	60054	5000328		Text		CONCERN: RH side front fuel tank rolled in.	
2020-06-05	60054	5000328	Contract	Operation	VO-4010400	Gearbox, calibration	0.3
2020-06-05	60054	3005300	Warranty	Operation	LO-234	FUEL TANK AND CONNECTION PARTS	0.5
2020-06-05	60054	3005300		Text		CONCERN: RH side front fuel tank rolled in.	
2020-06-05	60054	3005300	Warranty	Operation	LO-430	GEARBOX CALIBRATION	0.3
2020-06-04	13602	3005292	Contract	Part	VO-22038908	TRANSMISSION FILTER MACK	1
2020-06-04	13602	3005292	Contract	Part	AU2-CAL851074	VOLVO GEAR OIL 20L	1
2020-06-04	13602	3005292	Contract	Part	AU2-CAL851362	VOLVO SYN AXLE 20L	2
2020-06-04	13602	3005292		Text		Completed first service, changed gearbox oil and both diff	
2020-06-04	13602	3005292	Contract	Other	1772800	First service. After 4 weeks or maximum	
2020-06-04	13602	5000323	Warranty	Part	VO-22038908	TRANSMISSION FILTER MACK	1
2020-06-04	13602	5000323	Warranty	Part	AU2-CAL851074	VOLVO GEAR OIL 20L	1
2020-06-04	13602	5000323	Warranty	Part	AU2-CAL851362	VOLVO SYN AXLE 20L	2
2020-06-04	13602	5000323		Text		Completed first service, changed gearbox oil and both diff	
2020-06-04	13602	5000323	Warranty	Other	1772800	First service. After 4 weeks or maximum	
2020-05-29	30705	3005181	Warranty	Operation	LO-350	LIGHTING - GENERAL	0.2
2020-05-29	30705	3005181		Text		Lights drop in/out	
2020-05-29	30705	5000317	Contract	Operation	LO-350	LIGHTING - GENERAL	0.2
2020-05-29	30705	5000317		Text		Lights drop in/out	
2020-05-25		1 811612	Contract	Part	M-AGREEMENT (1
2020-05-25	60054	3005064	Internal	Other	9932100	Grease line, RE-ROUTE	
2020-05-25	60054	3005064	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	50

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-05-25	60054	3005064	Internal	Other	8180000	Cab mounting. Secondary operation number	
2020-05-25	60054	3005064	Contract	Operation	LO-234	FUEL TANK AND CONNECTION PARTS	0.5
2020-05-25	60054	3005064	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2020-05-25	60054	3005064	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2020-05-25	60054	3005064		Text		oil changes included only in some models	
2020-05-25	60054	3005064	Contract	Operation	VO-2330300	Fuel filter, replace (one)	0.3
2020-05-25	60054	3005064	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2020-05-25	60054	3005064	Contract	Operation	VO-2331200	Filter, water separator, replace	0.3
2020-05-25	60054	3005064	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2020-05-25	60054	3005064	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2020-05-25	60054	3005064	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2020-05-25	60054	3005064	Contract	Part	VO-20579690	GASKET	1
2020-05-25	60054	3005064	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2020-05-25	60054	3005064	Contract	Part	VO-85124906	HB3A 12V 60W BULB	1
2020-05-25	60054	3005064	Contract	Part	VO-85109772	H11 12V 55W LOW	1
2020-05-25	60054	3005064	Contract	Part	MK-TIE80088	7/8" SILICONE HOSE PER FOOT	2
2020-05-25	60054	3005064	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts-SUBLET	
2020-05-25	60054	3005064	Warranty	Other	821	BONNET AND MOUNTING PARTS	
2020-05-25	60054	3005064	Warranty	Other	10	WTG MOD-MANUFACTURE BONNET SHIMS	
2020-05-25	60054	3005064	Contract	Operation	VO-4010400	Gearbox, calibration	0.3
2020-05-25	13602	3005093	Retail	Operation	LO-MBONNET	MANUFACTURE BONNET SHIMS	1
2020-05-25	13602	3005093		Text		MANUFACTURE BONNET SHIMS AS REQUESTED	
2020-05-25	13602	3005093	Retail	Other	91	Workshop Consumables	
2020-05-18	53895	3005002	Internal	Operation	LO-179	Service -Pick up and delivery	0.6
2020-05-18	53895	3005002	Internal	Operation	VO-2544100	Filler neck, kit, replace	0.01
2020-05-18	53895	3005002		Text		filler neck completed recently - still leaking	
2020-05-18	53895	3005002	Internal	Operation	VO-6450000	Power steering equipment	0.01
2020-05-18	53895	3005002	Warranty	Operation	LO-258	EMISSIONS AFTER-TREATMENT	0.5
2020-05-18	53895	3005002	Warranty	Part	AU2-WUR05391	HOSE CLAMP 12-22MM 9MM WIDE	1
2020-05-18	53895	3005002	Warranty	Operation	VO-2500300	Boost pressure, test	0.4
2020-05-18	53895	3005002	Warranty	Part	AU2-WUR05371	JNTBLTCLMP-DIN3017	2
2020-05-18	53895	3005002	Warranty	Part	VO-8072884	T BOLT CLAMP	2
2020-05-18	53895	3005002	Warranty	Part	VO-20550690	CAC HOSE NB (REFIT)	2

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-05-18	53895	3005002	Warranty	Operation	VO-2652200	Charge air hose, replace	0.3
2020-05-18	53895	3005002	Warranty	Operation	LO-251	INTAKE AND EXHAUST PIPES	0.2
2020-04-30	30705	3004666	Internal	Other	9932100	Grease line,	
2020-04-30	30705	3004666		Text		Chassis greaser line rubbing bottom radiator bracket and	
2020-04-30	30705	3004666	Internal	Part	OTH-CAL839486	GREASE 100G NLGI 2	50
2020-04-30	30705	3004666	Warranty	Operation	VO-2583200	Aftertreatment diesel exhaust fluid (DEF	0.4
2020-04-30	30705	3004666	Warranty	Part	VO-23121198	ADBLUE FILLER NECK	1
2020-04-30	30705	3004666	Warranty	Part	VO-23251838	FILTER	1
2020-04-30	30705	3004666	Contract	Operation	LO-350	LIGHTING - GENERAL	0.2
2020-04-30	30705	3004666	Warranty	Operation	VO-8739300	Heater hose, replace	0.5
2020-04-30	30705	3004666	Warranty	Operation	VO-2600600	Coolant system, pressure test	0.4
2020-04-30	30705	3004666	Contract	Operation	LO-179	Service -Pick up and delivery	0.6
2020-04-30	30705	3004666	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
2020-04-30	30705	3004666	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.2
2020-04-30	30705	3004666	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
2020-04-30	30705	3004666	Contract	Operation	VO-2331100	Filter, water separator, replace	0.2
2020-04-30	30705	3004666	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
2020-04-30	30705	3004666	Contract	Operation	VO-1707300	Service alert system, configuration and	0.4
2020-04-30	30705	3004666	Contract	Operation	VO-2141300	Valves and unit injectors, adjust	2.1
2020-04-30	30705	3004666	Contract	Part	VO-85114535	MP8/10 FILTER KIT	1
2020-04-30	30705	3004666	Contract	Part	AU2-CAL851217	VDS4 1 LTR ENGINE OIL (BULK)	57
2020-04-30	30705	3004666	Contract	Part	VO-85124906	HB3A 12V 60W BULB	1
2020-04-30	30705	3004666	Contract	Part	VO-85109772	H11 12V 55W LOW	1
2020-04-30	30705	3004666	Contract	Other	WTY-NONGEN	WTY-Non Genuine Parts-SUBLET	
2020-04-14	13602	3004417	Internal	Operation	VO-1721000	Warranty service. After 4 weeks or maxim	3.7
2020-04-14	13602	3004417		Text		maximum 10 000 km.	
2020-04-14	13602	3004417	Internal	Operation	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.4
2020-04-14	13602	3004417	Internal	Operation	VO-1752700	Final drive oil, change. Lube area	0.6
2020-04-14	13602	3004416	Warranty	Part	VO-22038908	TRANSMISSION FILTER MACK	1
2020-04-14	13602	3004416	Warranty	Part	AU2-CAL851074	VOLVO GEAR OIL 20L	1
2020-04-14	13602	3004416	Warranty	Part	AU2-CAL851362	VOLVO SYN AXLE 20L	2
2020-04-14	13602	3004416		Text		Completed first service, changed gearbox oil and both diff	
2020-04-14	13602	3004416	Warranty	Other	1772800	First service. After 4 weeks or maximum	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-04-03	200	3004310	Internal	Operation	LO-380	Adjust speed back to 90k	1.55
2020-04-03	200	3004310		Text		Drove to yard - connected tech tool. Adjusted k-factor.	
2020-03-24	149	3004113	Retail	Part	VO-25109849	FASTENERS	1
2020-03-24	149	3004113	Retail	Operation	VO-1710400	Pre-delivery inspection	6
2020-03-24	149	3004113	Retail	Operation	LO-ENGUPRA	CARRY OUT ENGINE UPRATE	1
2020-03-24	149	3004113	Retail	Operation	VO-2830800	Idle shutdown, function check	1
2020-03-24	149	3004113		Text		TURN OFF IDLE SHUT DOWN	
2020-03-24	149	3004113	Retail	Operation	VO-2751500	Speed limiter, calibration	1
2020-03-24	149	3004113	Retail	Other	91	Workshop Consumables	
2020-03-04	130	3003831	Internal	Other	10M	CUSTOM AIR -CUSTOM AIR UNIT	
2020-03-04	130	3003831	Internal	Part	AU2-GF662129€	FW Assy G G36/185	1
2020-03-04	130	3003831	Internal	Part	OTH-X6004.A11	VIESA WATER TANK KIT	1
2020-03-04	130	3003831	Internal	Part	OTH-X6004.A34	VIESA WATER TANK SUPPORT KIT	1
2020-03-04	130	3003831	Internal	Part	AU2-9771-AE31	AERIAL	1
2020-03-04	130	3003831	Internal	Operation	LO-NMPD	PRE DELIVERY	6
2020-03-04	130	3003831	Internal	Part	AU2-9703-JOST!	WELD ON 50MM TOW EYE	2
2020-03-04	130	3003831	Internal	Part	VO-85121040	DASH MAT NEW BREED GREY	1
2020-03-04	130	3003831	Internal	Part	MK-MSC021BLM	SEAT COVER ISRI DR BB BLK	1
2020-03-04	130	3003831	Internal	Part	MK-MSC022BLM	SEAT CVR PASS BB B	1
2020-03-04	130	3003831	Internal	Part	MK-9711-9208C	CHROME HUBCAP	4
2020-03-04	130	3003831	Internal	Part	MK-9732-00113	HUB CAP 335PCD	2
2020-03-04	130	3003831	Internal	Part	MK-9732-8074B	COVER NUT 33MM PK	6
2020-03-04	130	3003831	Internal	Part	MK-3281-MSS2€	KICK PLATE / ETCHED	1
2020-03-04	130	3003831	Internal	Part	VO-85116338	FLOOR MAT SET NEW BRD	1
2020-03-04	130	3003831	Internal	Part	OTH-78EB	7/8"EYEBOLT BULLBAR	4
2020-03-04	130	3003831	Internal	Part	OTH-78EBNW	7/8 NYL E/BOLT WASHE	4
2020-03-04	130	3003831	Internal	Part	AU2-9719-CIXTC	DIAMOND BOOKS	1
2020-03-04	130	3003831	Internal	Part	AU2-9719-CIXTC	ROAD TRAIN 2 PCE	1
2020-03-04	130	3003831	Internal	Part	AU2-CEN12310!	BATT N70ZZH CENTURY	4
2020-03-04	130	3003831	Internal	Part	OTH-NARV7270!	LOAD LIGHT	2
2020-03-04	130	3003831	Internal	Part	OTH-MACKTRIO!	LIGHT COVER	2
2020-03-04	130	3003831	Internal	Part	VO-82279475	LOAD LIGHT SWITCH	1
2020-03-04	130	3003831	Internal	Part	OTH-ACX1997A	RELAY BASE WITH TERMINALS	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-03-04	130	3003831	Internal	Part	OTH-GWR10144	GW 220 RDN DRIVE LIG	2
2020-03-04	130	3003831	Internal	Part	VO-82279626	DRIVING LIGHT SWITCH	1
2020-03-04	130	3003831	Internal	Part	MK-NARV82558	ELECT SUZICOIL LOG TAIL XHD	1
2020-03-04	130	3003831	Internal	Part	MK-NARV82161	MALE 7 PIN LGE STEEL PLUG	1
2020-03-04	130	3003831	Internal	Part	MK-9752-FGT31	FLEXI-GUARD 3.1M	1
2020-03-04	130	3003831	Internal	Part	MK-47QM49402	MUDFLAP MACK SHORT	2
2020-03-04	130	3003831	Internal	Part	MK-47QM49402	MUDFLAP MACK 13X24	2
2020-03-04	130	3003831	Internal	Part	MK-44QL39403I	WIRE ROPE ANTI SAIL BRACKET	2
2020-03-04	130	3003831	Internal	Part	AU2-9719-CIXTC	CHEVRON RED AND YE	1
2020-03-04	130	3003831	Internal	Part	MK-FT1868X8X8	1/2" X 1/2" PUSH M	3
2020-03-04	130	3003831	Internal	Part	MK-FT3350X8	1/2" ELBOW 45DEG	2
2020-03-04	130	3003831	Internal	Part	MK-ABCCA9381	MALE TRAILER DUST COVER	1
2020-03-04	130	3003831	Internal	Part	MK-ABCCA9379	FEMALE TRAILER DUST COVER	1
2020-03-04	130	3003831	Internal	Part	MK-ABC285172I	1/2" MALE / FEMALE BALL TAP	2
2020-03-04	130	3003831	Internal	Part	MK-ABCABF154	FEMALE X 1/2 MALE TRAILER SEAL	1
2020-03-04	130	3003831	Internal	Part	VO-22258370	MALE X 1/2 MALE TRAILER COUP	1
2020-03-04	130	3003831	Internal	Part	OTH-12X2NF8ZF	BOLT 1/2 UNF X 2 GR8	2
2020-03-04	130	3003831	Internal	Part	OTH-38X1.12NC	BOLT 3/8 UNC X 1-1/2 GR8	20
2020-03-04	130	3003831	Internal	Part	OTH-38HTW	WASHER 3/8 GR8	40
2020-03-04	130	3003831	Internal	Part	OTH-38NCNYLN	NUT NYLOC 3/8 UNC GR5	20
2020-03-04	130	3003831	Internal	Part	OTH-5/8X5UNC;	5/8 X 5 UNC BOLT	2
2020-03-04	130	3003831	Internal	Part	OTH-58HTW	WASHER 5/8 GR8	4
2020-03-04	130	3003831	Internal	Part	OTH-58NCNYLN	NUT NYLOC 5/8 UNC GR5	2
2020-03-04	130	3003831	Internal	Part	OTH-12HTW	WASHER 1/2 GR8	16
2020-03-04	130	3003831	Internal	Part	OTH-NNM12	? M12 NYLOC NUT	16
2020-03-04	130	3003831	Internal	Part	OTH-14HTW	WASHER 1/4 GR8	50
2020-03-04	130	3003831	Internal	Part	OTH-RBOW5163	? 5/16 X 3/4 TANK SCREW	4
2020-03-04	130	3003831	Internal	Part	OTH-SSDN304C	? 5/16 DOME NUT	4
2020-03-04	130	3003831	Internal	Part	OTH-8MHTW	WASHER M8 X 16 1.6 200HV H/T	4
2020-03-04	130	3003831	Internal	Part	OTH-SW516MZ	? 5/16 SPRING WASHER	4
2020-03-04	130	3003831	Internal	Part	OTH-RPTSS66	3/16 STEEL RIVET	8
2020-03-04	130	3003831	Internal	Part	VO-992340	M14 X 60MM FLANGE BOLT	8
2020-03-04	130	3003831	Internal	Part	MK-9728-2424	MUDFLAP 605X605	1

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-03-04	130	3003831	Internal	Part	MK-47QM49402	MUDFLAP TRAILER 30 X 24	2
2020-03-04	130	3003831	Internal	Part	MK-NARV82062	FMALE 7 PIN LGE STEEL PLUG	1
2020-03-04	130	3003831	Internal	Part	AU2-9719-CIXTC	DNOT VEHICLE CAT 31L SINGLE	1
2020-03-04	130	3003831	Internal	Part	OTH-E3-13-15	KEY LOCK TRIANGLE	2
2020-03-04	130	3003831	Internal	Part	OTH-E3-5-15	KEYLOCK KEYS	2
2020-03-04	130	3003831	Internal	Part	OTH-903	CHECKER PLATE COVER	2
2020-03-04	130	3003831	Internal	Part	OTH-3275-2	ANTI RATTLE / LUCE LARGE	2
2020-03-04	130	3003831	Internal	Part	OTH-100160	CHECKER PLATE 2400 X 1200 X 5	1
2020-03-04	130	3003831	Internal	Part	OTH-TES749348	TESA TAPE 7493 50MM PER METRE	4
2020-03-04	130	3003831	Internal	Part	MK-9799-BES92	TURBO TIMER	1
2020-03-04	130	3003831	Internal	Part	MK-9732-BG12	DUST BLOWER	1
2020-03-04	130	3003831	Internal	Part	VO-21707766	685 HP MP10 LABEL	2
2020-03-04	130	3003831	Internal	Part	AU2-22606577	DISC WHEEL 22.5 X 11.75	2
2020-03-04	130	3003831	Internal	Part	MK-NARV68044	RELAY C/O 12V 5 PIN 40/30 AMP	2
2020-03-04	130	3003831	Internal	Part	OTH-SWX4001	BLOCKING DIODE BLUE 3 AMP	1
2020-03-04	130	3003831	Internal	Part	OTH-ACX1712A	MINI BLADE FUSE HOLDER	1
2020-03-04	130	3003831	Internal	Part	VO-21291263	BRACKET	1
2020-03-04	130	3003831	Internal	Part	MK-ABCABF215	FEMALE X 3/8 MALE TRAILER SEAL	1
2020-03-04	130	3003831	Internal	Part	MK-FT1868X6X6	3/8" X 3/8" PUSH M	1
2020-03-04	130	3003831	Internal	Part	VO-25159803	3/8 NYLON TUBE PER METRE	5
2020-03-04	130	3003831	Internal	Part	MK-FT1869X6X6	3/8" X 3/8" 90DEG PU	1
2020-03-04	130	3003831	Internal	Part	VO-25158533	WILLIAMS VALVE	1
2020-03-04	130	3003831	Internal	Part	MK-FT1868X6	3/8" X 1/4" PUSH M	1
2020-03-04	130	3003831	Internal	Part	MK-FT3400X4	1/4" 90DEG ELBOW	1
2020-03-04	130	3003831	Internal	Part	MK-FT3220X8X4	1/2" X 1/4" RED BSH	1
2020-03-04	130	3003831	Internal	Part	MK-FT3325X4	1/4" NIPPLE HEX	1
2020-03-04	130	3003831	Internal	Part	OTH-IFS23BFMT	3/8 M/F BALL VALVE	1
2020-03-04	130	3003831	Internal	Part	VO-23214684	LONG TAIL SUZI COIL AIR	1
2020-03-04	130	3003831	Internal	Part	VO-85114535	MP8/10 FILTER KIT	1
2020-03-04	130	3003831	Internal	Part	VO-22950621	V-RIBBED BELT	1
2020-03-04	130	3003831	Internal	Part	VO-22950564	V-RIBBED BELT 10PK1475	1
2020-03-04	130	3003831	Internal	Other	10M	STH STEEL-REAR GUARD MATERIAL	
2020-03-04	130	3003831	Internal	Operation	LO-NMTARE	NEW TRUCK TARE WEIGHT	0.65

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-03-04	130	3003831	Internal	Operation	LO-NMDASHM	S & F GREY DASH MAT	0.74
2020-03-04	130	3003831	Internal	Part	OTH-BHCSM12E	? M12 X 50 SCREW ALLEN KEY	16
2020-03-04	130	3003831	Internal	Part	MK-NARV82194	MALE 7 PIN HD STEEL PLUG	1
2020-03-04	130	3003831	Internal	Part	MK-9741-964AM	CONNECTOR	1
2020-03-04	130	3003831	Internal	Part	VO-25158202	TERMINALS-SOLDER	6
2020-03-04	130	3003831	Internal	Part	OTH-ACX1711	INLINE FUSE HOLDER	1
2020-03-04	130	3003831	Internal	Part	OTH-NARV5280	BLADE FUSE 5A ORANGE	1
2020-03-04	130	3003831	Internal	Other	NMSEATCOV	S & F MACK LAMB WOOL SEAT COVERS	
2020-03-04	130	3003831	Internal	Operation	LO-NMCHROM	S & F MACK CHROME HUB & NUT COVERS	1.98
2020-03-04	130	3003831	Internal	Operation	LO-NMKICK	S & F MACK KICK PANELS	1.65
2020-03-04	130	3003831	Internal	Operation	LO-NMMATS	S & F MACK FLOOR MATS	0.78
2020-03-04	130	3003831	Internal	Operation	LO-NMBADGE	S & F CUSTOM BUILT BADGE-BEN DARE	0.24
2020-03-04	130	3003831	Internal	Operation	LO-NMBULLB	S & F 5 POSTER BULLBAR,MESH ON HEADLIGHT	16.49
2020-03-04	130	3003831		Text		WITH ROADTRAIN SIGNS & BLUE COVERS	
2020-03-04	130	3003831	Internal	Operation	LO-NMAIR	AIR SUPPLY TO BULLBAR	1.16
2020-03-04	130	3003831	Internal	Operation	LO-NMBATTE	S & F SEALED LOW MAINTENANCE BATTERIES	4.5
2020-03-04	130	3003831	Internal	Operation	LO-NMR/LIG	S & F MIRROR MOUNTED REVERSING LIGHTS	7.04
2020-03-04	130	3003831	Internal	Operation	LO-NMD/LIG	S & F 2 X GREAT WHITE ATTACK 220 DRIVE	9.26
2020-03-04	130	3003831	Internal	Operation	LO-NMT/TAB	S & F 50MM GF TURNTABLE MOUNTED AT CENTR	10.8
2020-03-04	130	3003831	Internal	Operation	LO-NMF/GUA	S & F RUBBER FLEXI GUARDS WITH HD REAR	13.75
2020-03-04	130	3003831	Internal	Operation	LO-NMSTIFF	S & F STIFF BAR	7.68
2020-03-04	130	3003831	Internal	Operation	LO-NMW/PLA	S & F WALKPLATE	6.8
2020-03-04	130	3003831	Internal	Operation	LO-NMSPEED	CHECK SPEED WITH GPS & SET AT 90KMS P/HR	1
2020-03-04	130	3003831	Internal	Operation	LO-NMAERIA	S & F WHITE RADIO AERIAL	2.51
2020-03-04	130	3003831	Internal	Operation	LO-NMT/TIM	S & F TURBO TIMER	4.98
2020-03-04	130	3003831	Internal	Operation	LO-NMW/TIN	WINDOW TINTING	1.75
2020-03-04	130	3003831	Internal	Operation	LO-NMA/BLO	S & F AIR BLOWER OFF DRIVERS SEAT	1.2
2020-03-04	130	3003831	Internal	Other	NMW/TANK	S & F WATER TANK	
2020-03-04	130	3003831	Internal	Operation	LO-NMUPRAT	ENGINE UPRATE TO 685HP	1.3
2020-03-04	130	3003831	Internal	Operation	LO-NMT/PLU	POWER TO PIN 5 IN TRAILER PLUG	3
2020-03-04	130	3003831	Internal	Operation	LO-NMCUSTO	S & F CUSTOM AIR-REAR CHASSIS MOUNTED	36.18
2020-03-04	130	3003831	Internal	Operation	LO-NMBASH	S & F BASH PLATE FOR CUSTOM AIR	5.7
2020-03-04	130	3003831	Internal	Other	NMTYRES	S & F 2 X ALCOA DURABRITE SUPER SINGLE	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-03-04	130	3003831	Internal	Operation	LO-NMMUDFL	S & F MUDFLAPS BEHIND STEER & DRIVE	1.95
2020-03-04	130	3003831	Internal	Other	NMA/GREAS	S & F ALEMLUBE AUTO GREASER EP2 GREASE	
2020-03-04	130	3003831	Internal	Operation	LO-NMF/EXT	S & F 4.5 FIRE EXTINGUISHER (IN HEAVY	2.85
2020-03-04	130	3003831	Internal	Part	OTH-BRE90MF0	BRASS ELBOW 90DEG M&F 20MM	1
2020-03-04	130	3003831	Internal	Part	OTH-VBBTMF02	TAP M & F 20MM T HANDLE	1
2020-03-04	130	3003831	Internal	Part	OTH-WSLR20	RUBBER WASHER 20MM	1
2020-03-04	130	3003831	Internal	Part	OTH-BRBN015	BRASS BACK NUT 15MM	4
2020-03-04	130	3003831	Internal	Part	OTH-HR96000	TAP ADAPTOR UNIVERSAL 12MM	1
2020-03-04	130	3003831	Internal	Part	OTH-BRMHT020	BRASS HOSE TAIL 20MMX 12MM	1
2020-03-04	130	3003831	Internal	Part	OTH-HCSS0120	HOSE CLAMP	2
2020-03-04	130	3003831	Internal	Part	OTH-BRMHT015	BRASS TAIL 15MM X 12MM	1
2020-03-04	130	3003831	Internal	Part	OTH-S08	SOCKET 1/2" BLACK 031932	3
2020-03-04	130	3003831	Internal	Part	OTH-ACX1105M	10MM SPLIT TUBE PER METRE	3
2020-03-04	130	3003831	Internal	Part	OTH-ACX2910	DEUTSCH 2 WAY KIT	2
2020-03-04	130	3003831	Internal	Part	OTH-8X80M10.9	BOLT M8X80 PC 10.9	2
2020-03-04	130	3003831	Internal	Part	OTH-516HTW	WASHER 5/16 GR8	2
2020-03-04	130	3003831	Internal	Part	VO-22443498	SENSOR	1
2020-03-04	130	3003831	Internal	Part	OTH-SCX1321	Ä6 AC 90 DEG FITTING	2
2020-03-04	130	3003831	Internal	Part	OTH-NARV5648	P-CLAMP PS5 EACH	5
2020-03-04	130	3003831	Internal	Other	10M	CHUBB-4.5KG FIRE EXTINGUISHER	
2020-03-04	130	3003831	Internal	Other	10M	GPC-BLAST REAR GUARDS	
2020-03-04	130	3003831	Internal	Part	OTH-4381-9100	CHROME CAPS	1
2020-03-04	130	3003831	Internal	Other	10M	SEDL-BLACK KIT	
2020-03-04	130	3003831	Internal	Part	OTH-NM6RNS	6MM NUT INSERTS	4
2020-03-04	130	3003831	Internal	Part	OTH-6X20M10.9	BOLT M6 X 20 PC 10.9	4
2020-03-04	130	3003831	Internal	Part	OTH-34X3NF8ZF	BOLT 3/4 UNF X 3 GR8	12
2020-03-04	130	3003831	Internal	Part	OTH-10X30M10.	BOLT M10 X 30 PC 10.9	4
2020-03-04	130	3003831	Internal	Part	OTH-10MHTW	WASHER M10 X 20 2.0 200HV H/T	8
2020-03-04	130	3003831	Internal	Part	OTH-10MNYLN	M10 CL8 NYLOC NUT	4
2020-03-04	130	3003831	Internal	Part	OTH-MODPLATE	MOD PLATE	1
2020-03-04	130	3003831	Internal	Other	10M	WTG TOP-PD,UPRATE,IDLE SHUT DOWN,SPEED	
2020-03-04	130	3003831	Internal	Other	10M	DETAIL / DELICATE	
2020-03-04	130	3003831	Internal	Other	10M	BIG WHEELS-CHECK & ADJUST W/ALIGN	

VSR Report - 2020 Mack Superliner
Chassis Number 6FMT14H83KD811612

15Apr 2026

Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2020-03-04	130	3003831	Internal	Other	10M	HLINE-R/T COVERS BLACK	
2020-03-04	130	3003831	Internal	Other	10M	SIGNS N LINES-WHITE MACK ON BLACK COVER	
2020-03-04	130	3003831	Internal	Part	VO-20711790	JACK HANDLE	1
2020-03-04	130	3003831	Internal	Part	VO-22550236	JACK 15 TON MACK	1
2020-03-04	130	3003831	Internal	Part	OTH-716X1.12N	BOLT7/16 UNC X 1-1/2 GR8	10
2020-03-04	130	3003831	Internal	Part	OTH-58X2NC8Z	BOLT 5/8 UNC X 2 GR8	8
2020-03-04	130	3003831	Internal	Part	OTH-58X2.12NC	BOLT 5/8 UNC X 2-1/2 GR8	4
2020-03-04	130	3003831	Internal	Part	OTH-1X3NF8ZPE	BOLT 1 UNF X 3 GR8	2
2020-03-04	130	3003831	Internal	Part	OTH-716HTW	WASHER 7/16 GR8	20
2020-03-04	130	3003831	Internal	Part	OTH-1HTW	WASHER 1 GR8	4
2020-03-04	130	3003831	Internal	Part	OTH-716NCNYL	NUT NYLOC UNC 7/16 GR5	10
2020-03-04	130	3003831	Internal	Part	OTH-1SAENYLN	1 UNF NYLOC NUT	2
2020-03-04	130	3003831	Internal	Part	AU2-4381-2109	STRIP LED LAMP FRO	2
2020-03-04	130	3003831	Internal	Part	OTH-NARV5282	BLADE FUSE 25A CLEAR	1
2020-03-04	130	3003831	Internal	Part	MK-NARV56408	CABLE TIE 1=100PK	1
2020-03-04	130	3003831	Internal	Part	OTH-ACX0808M	4MM TWIN CORE PER METRE	7
2020-03-04	130	3003831	Internal	Part	OTH-ACX1102M	7MM SPLIT TUBE PER METRE	7
2020-03-04	130	3003831	Internal	Operation	LO-NMT/MOV	NEW TRUCK MOVEMENTS	1.73
2020-03-04	130	3003831	Internal	Operation	LO-NMSLEEP	FIT UP WING TO TOP OF SLEEPER	4.5
2020-03-04	130	3003831	Internal	Other	10M	K & F WINDOW TINTING	
2020-03-04	130	3003831	Internal	Part	OTH-BBM5P76	BULL BAR MACK 5 POST 76MM	1
2020-03-04	130	3003831	Internal	Operation	LO-NMS/GUA	NEW TRUCK STONEGUARD	1
2020-03-04	130	3003831	Internal	Operation	LO-NMRSA	NEW TRUCK RSA BOX	3.25