

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2	2025-04-22	1749921	8325466	Retail	Other	ACC	**PPO**PLEASE FILL IN	
3	2025-04-22	1749921	8325466	Retail	Operation	LO-460	check & report on vibration	5
4	2025-04-22	1749921	8325466		Text		Truck lifted and stands fitted under frame.	
5	2025-04-22	1749921	8325466	Retail	Operation	LO-210	sump gasket leaking	3
6	2025-04-22	1749921	8325466	Retail	Operation	LO-460	rectify diff leak	3
7	2025-04-22	1749921	8325466	Retail	Part	VO-85112668	TORQUE ROD	2
8	2025-04-22	1749921	8325466		Text		*** POSSIBLE POLICY CLAIM ***	
9	2025-04-22	1749921	8325466	Retail	Part	VO-23995578	SHOCK ABSORBER	1
10	2025-04-22	1749921	8325466	Retail	Part	VO-25164942	TORQUE ROD ASSY	1
11	2025-04-22	1749921	8325466	Retail	Part	MK-4000-97070004	BOLT M24	3
12	2025-04-22	1749921	8325466	Retail	Part	MK-4000-97071001	NUT	5
13	2025-04-22	1749921	8325466	Retail	Part	VO-FFS	FREIGHT SYDNEY - PINKENBA	1
14	2025-04-22	1749921	8325466	Retail	Part	VO-FFW	FREIGHT- WACOL TO PINKENBA	1
15	2025-04-22	1749921	8325466	Retail	Part	VO-60110468	WASHER M24	4
16	2025-04-22	1749921	8325466	Retail	Part	VO-20734156	SEALING STRIP	1
17	2025-04-22	1749921	8325466		Text		*** POSSIBLE POLICY CLAIM ***	
18	2025-04-22	1749921	8325466	Retail	Part	AU2-CHE23068346	VDS 4.5 ENGINE OIL BULK	5
19	2025-04-22	1749921	8325466		Text		Contact:JIM 0419 657 335 jim.gatt@yahoo.com.au Next Service: CREDIT	
20	2025-04-22	1749921	8325466		Text		LIMIT: BALANCE: Mileage: 1749936Hrs: 11243Defect sheet complete Y/N	
21	2025-04-22	1749921	8325466		Text			
22	2025-04-22	1749921	8325466		Text		.	
23	2025-04-22	1749921	8325466		Text		drained sump. fitted lifts under truck. lifted vehicle	
24	2025-04-22	1749921	8325466		Text		draind oil. removed cover and cleand surfaces. fitted	
25	2025-04-22	1749921	8325466		Text		cover and tentioned all bolts. refilled oil	
26	2025-04-22	1749921	8325466		Text		into the air. removed sump and cleand all surfaces. fitted	
27	2025-04-22	1749921	8325466		Text		new gasket to sump and fitted sump. tentioned all bolts	
28	2025-04-22	1749921	8325466		Text		and put vehicle on the ground. filled oil washed truck and	
29	2025-04-22	1749921	8325466		Text		carried out road test.	
30	2025-04-22	1749921	8325466		Text		Tires taken off both 1 and 2 drive Axle.	
31	2025-04-22	1749921	8325466		Text		Side rods replaced on 2drive axle.	
32	2025-04-22	1749921	8325466		Text		Shocks replaced on 2 drive axle.	
33	2025-04-22	1749921	8325466		Text		Torqued rod replaced on 2 axle.	
34	2025-04-22	1749921	8325466		Text		1 Axel side rods bolts replaced.	
35	2025-04-22	1749921	8325466		Text		1 axele shocks bolts tighten.	
36	2025-04-22	1749921	8325466		Text		Mudguards tightened.	
37	2025-04-22	1749921	8325466		Text		Tires fitted and torqued.	
38	2025-04-22	1749921	8325466	Retail	Other	91	WORKSHOP CONSUMABLES	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
39	2023-11-06	1723553	8313822	Internal	Operation	LO-210	trimming plate leaking oil.	4
40	2023-11-06	1723553	8313822	Internal	Part	VO-20469515	ELBOW NIPPLE	1
41	2023-11-06	1723553	8313822	Internal	Part	VO-982508	DOWDY WASHER	2
42	2023-11-06	1723553	8313822	Internal	Part	VO-977030	O-RING	1
43	2023-11-06	1723553	8313822	Internal	Part	VO-992065	O-RING	1
44	2023-11-06	1723553	8313822	Internal	Part	VO-953102	STUD M12*65MM	2
45	2023-11-06	1723553	8313822	Internal	Part	VO-990946	NUT M12 FL	3
46	2023-11-06	1723553	8313822	Internal	Part	VO-21185132	SEALING	2
47	2023-11-06	1723553	8313822	Internal	Part	VO-20815558	SEALING STRIP	1
48	2023-11-06	1723553	8313822	Internal	Part	VO-994447	BOLT M8*25 FL GR8.8 THREAD LOC	25
49	2023-11-06	1723553	8313822	Internal	Part	VO-943177	OIL COOLER ORIN	1
50	2023-11-06	1723553	8313822	Internal	Part	VO-21015266	BOLT M12*50MM	6
51	2023-11-06	1723553	8313822	Internal	Part	VO-471586	BOLT M8*35	6
52	2023-11-06	1723553	8313822	Internal	Part	VO-20483919	BOLT M10*45 HEX SOCKET GR10.9	6
53	2023-11-06	1723553	8313822	Internal	Part	VO-995658	O-RING	1
54	2023-11-06	1723553	8313822	Internal	Part	VO-984738	BOLT M8*40 FL	6
55	2023-11-06	1723553	8313822	Internal	Part	VO-20736230	SEALING STRIP	1
56	2023-11-06	1723553	8313822	Internal	Part	VO-20734156	SEALING STRIP	1
57	2023-11-06	1723553	8313822	Internal	Part	VO-21575727	GASKET	1
58	2023-11-06	1723553	8313822	Internal	Part	VO-22191895	CRANKSHAFT SEAL	1
59	2023-11-06	1723553	8313822	Internal	Part	VO-21352841	GASKET	6
60	2023-11-06	1723553	8313822	Internal	Part	VO-21695684	SEALING RING	2
61	2023-11-06	1723553	8313822	Internal	Part	VO-21503575	SEALING RING	1
62	2023-11-06	1723553	8313822	Internal	Part	VO-20799996	SEALING RING	1
63	2023-11-06	1723553	8313822	Internal	Part	VO-21423788	SEALING RING	1
64	2023-11-06	1723553	8313822	Internal	Part	VO-3979639	PRE-HEAT GASKET	2
65	2023-11-06	1723553	8313822	Internal	Part	VO-3092340	GREY SILASTIC	1
66	2023-11-06	1723553	8313822	Internal	Part	VO-949647	O-RING	1
67	2023-11-06	1723553	8313822	Internal	Part	MK-NARV56410	CABLE TIE 1=100PK	1
68	2023-11-06	1723553	8313822	Internal	Part	AU2-WUR089010810	BRAKE CLEAN	2
69	2023-11-06	1723553	8313822	Internal	Part	VO-994447	BOLT M8*25 FL GR8.8 THREAD LOC	9
70	2023-11-06	1723553	8313822	Internal	Part	VO-984736	BOLT M8*30 FL	5
71	2023-11-06	1723553	8313822	Internal	Part	VO-8192804	BOLT BIG END	8
72	2023-11-06	1723553	8313822	Internal	Part	VO-FFS	FREIGHT SYDNEY - PINKENBA	1
73	2023-11-06	1723553	8313822	Internal	Part	VO-21724614	SEALING	2
74	2023-11-06	1723553	8313822	Internal	Part	VO-8131850	THRUST WASHER	1
75	2023-11-06	1723553	8313822	Internal	Part	VO-995658	O-RING	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
76	2023-11-06	1723553	8313822	Internal	Part	VO-976068	O-RING	1
77	2023-11-06	1723553	8313822	Internal	Part	VO-21532261	SEALING RING	1
78	2023-11-06	1723553	8313822	Internal	Part	VO-979099	GASKET	1
79	2023-11-06	1723553	8313822	Internal	Part	VO-471708	SEAL RING	2
80	2023-11-06	1723553	8313822	Internal	Part	VO-1547252	SEALING RING	1
81	2023-11-06	1723553	8313822	Internal	Part	VO-21053055	HOSE,COOLANT	1
82	2023-11-06	1723553	8313822	Internal	Part	VO-994557	HOSE CLAMP 15mm-24mm	4
83	2023-11-06	1723553	8313822	Internal	Part	VO-994146	ELBOW NIPPLE	1
84	2023-11-06	1723553	8313822	Internal	Part	VO-993451	NIPPLE	2
85	2023-11-06	1723553	8313822	Internal	Part	VO-977237	HOSE	1
86	2023-11-06	1723553	8313822	Internal	Part	VO-990719	O-RING	1
87	2023-11-06	1723553	8313822	Internal	Part	VO-21344756	SCREW	4
88	2023-11-06	1723553	8313822	Internal	Part	VO-1545432	CLAMP P 20 MM	4
89	2023-11-06	1723553	8313822	Internal	Part	VO-20852765	DOWDY WASHER	8
90	2023-11-06	1723553	8313822	Internal	Part	VO-994451	BOLT M8*50MM FL THREAD LOC	1
91	2023-11-06	1723553	8313822	Internal	Part	VO-1677370	VEB SEALING RING	2
92	2023-11-06	1723553	8313822	Internal	Part	VO-20526428	VEB SEAL RING	1
93	2023-11-06	1723553	8313822	Internal	Part	VO-20723207	SEALING RING	1
94	2023-11-06	1723553	8313822	Internal	Part	VO-21780376	SEALING RING	1
95	2023-11-06	1723553	8313822	Internal	Part	MK-NARV56310	CABLE TIE 1=10PC	1
96	2023-11-06	1723553	8313822	Internal	Part	VO-20734156	SEALING STRIP	1
97	2023-11-06	1723553	8313822	Internal	Part	VO-20704755	WASHER.FL 7/16	1
98	2023-11-06	1723553	8313822	Internal	Part	AU2-AMP24332693	MACK VCS-2 COOLANT 5LTR	1
99	2023-11-06	1723553	8313822	Internal	Part	VO-8397715	FITTING	1
100	2023-11-06	1723553	8313822	Internal	Part	VO-25171372	SCREW	2
101	2023-11-06	1723553	8313822	Internal	Part	VO-25171471	FASTENERS	2
102	2023-11-06	1723553	8313822	Internal	Part	VO-25171459	SCREW	2
103	2023-11-06	1723553	8313822	Internal	Part	VO-85146403	CLIP	1
104	2023-11-06	1723553	8313822	Internal	Part	VO-25162665	FASTNR,PANEL SP	1
105	2023-11-06	1723553	8313822	Internal	Part	VO-60112135	SIX POINT SOCKET S	2
106	2023-10-30	1723553	8312366	Retail	Other	M	PLEASE FILL IN	
107	2023-10-30	1723553	8312366		Text		Contact:JIM 0419 657 335	
108	2023-10-30	1723553	8312366	Retail	Other	97	ENVIRONMENTAL CHARGE	
109	2023-10-30	1723553	8312366	Retail	Operation	LO-460	clutch rough changing gears	3
110	2023-10-30	1723553	8312366		Text		and hanging on to gears	
111	2023-10-30	1723553	8312366	Retail	Operation	LO-430	remove & replace trans cooler lines	1.5
112	2023-10-30	1723553	8312366	Retail	Operation	LO-460	front drive axle temp not working	1.1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
113	2023-10-30	1723553	8312366	Retail	Operation	LO-810	check both doors hard to open lock	4
114	2023-10-30	1723553	8312366		Text		check door adjustment	
115	2023-10-30	1723553	8312366	Retail	Operation	LO-170	carry out inspection of vehicle	3
116	2023-10-30	1723553	8312366		Text		MAKE SURE TO CHECK AND ADJUST BRAKES	
117	2023-10-30	1723553	8312366	Retail	Part	VO-25013743	CONNECTOR	1
118	2023-10-30	1723553	8312366	Retail	Part	VO-21331452	TERMINAL	2
119	2023-10-30	1723553	8312366	Retail	Part	VO-25084217	CONN.- ELECTRICAL	1
120	2023-10-30	1723553	8312366	Retail	Part	VO-25088933	SEAL,ELECTRICAL CA	2
121	2023-10-30	1723553	8312366	Retail	Part	VO-21331452	TERMINAL	2
122	2023-10-30	1723553	8312366	Retail	Part	VO-25088933	SEAL,ELECTRICAL CA	2
123	2023-10-30	1723553	8312366	Retail	Part	VO-23764519	DOOR STOP	2
124	2023-10-30	1723553	8312366	Retail	Part	VO-82785361	LATCH RH	1
125	2023-10-30	1723553	8312366	Retail	Part	AU2-WUR089010810	BRAKE CLEAN	2
126	2023-10-30	1723553	8312366	Retail	Part	AU2-9770-5073	HOT SHOT DEGREASER	2
127	2023-10-30	1723553	8312366	Retail	Part	VO-20997037	DEFLECTOR 48" CLEAR	1
128	2023-10-30	1723553	8312366	Retail	Part	MK-4MR29415M	DECAL MACK AIR HOR	2
129	2023-10-30	1723553	8312366	Retail	Part	VO-FFS	FREIGHT SYDNEY - PINKENBA	1
130	2023-10-30	1723553	8312366		Text		for BOBBY2 , ref James. ordered via parts and requested to have	
131	2023-10-30	1723553	8312366		Text		paied when this invoice is ready.	
132	2023-10-30	1723553	8312366		Text		for BOBBY2 , ref James. ordered via parts and requested to have	
133	2023-10-30	1723553	8312366		Text		paied when this invoice is ready.	
134	2023-10-30	1723553	8312366	Retail	Other	852	DRIVER SIDE SEAT RIDE HEIGHT	
135	2023-10-30	1723553	8312366		Text		KEEPS ADJUSTING	
136	2023-10-30	1723553	8312366	Retail	Operation	LO-843	WASHER JETS NEEDS ADJUSTMENT	0.5
137	2023-10-30	1723553	8312366	Retail	Operation	LO-560	POWER DIVIDER AIR LINE LEAKING	0.9
138	2023-10-30	1723553	8312366	Retail	Operation	LO-852	DRIVER SIDE SEAT BELT FRAYED	1.2
139	2023-10-30	1723553	8312366		Text		NOT RETRACTING	
140	2023-10-30	1723553	8312366	Retail	Operation	LO-462	FRONT DIFF THROU SHAFT SEAL	1.4
141	2023-10-30	1723553	8312366		Text		LEAKING	
142	2023-10-30	1723553	8312366	Retail	Operation	LO-560	LHS 2ND DRIVE AXLE BRAKE BACKING	0.5
143	2023-10-30	1723553	8312366		Text		PLATE MISSING	
144	2023-10-30	1723553	8312366	Retail	Operation	LO-560	AIR LEAKING AT RHS BRAKE STEER	2
145	2023-10-30	1723553	8312366		Text		BRAKE MODULATOR	
146	2023-10-30	1723553	8312366	Retail	Operation	LO-810	AIR LEAKING AT CAB RIDE	0.5
147	2023-10-30	1723553	8312366		Text		HEIGHT VALVE	
148	2023-10-30	1723553	8312366	Retail	Operation	LO-560	AIR LEAK AT WEIGHT SCALES	0.9
149	2023-10-30	1723553	8312366	Retail	Operation	LO-810	CAB BUMP STOP REAR SPLIT	4

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
150	2023-10-30	1723553	8312366	Retail	Operation	LO-360	LHS 2ND DRIVE AXLE MARKER	1
151	2023-10-30	1723553	8312366		Text		LIGHT LOOSE.	
152	2023-10-30	1723553	8312366	Retail	Operation	LO-210	DIVERTER VALVE U/S	0.4
153	2023-10-30	1723553	8312366	Retail	Part	VO-23626042	AIR VALVE	1
154	2023-10-30	1723553	8312366	Retail	Part	VO-21079507	BUMP STOP	1
155	2023-10-30	1723553	8312366	Retail	Part	VO-20975430	SUPPORT	1
156	2023-10-30	1723553	8312366	Retail	Part	VO-23270961	LEVEL VALVE,CAB SU	1
157	2023-10-30	1723553	8312366	Retail	Part	VO-22987428	MODULATOR	1
158	2023-10-30	1723553	8312366	Retail	Part	MK-8235-A13236Q21	DUST SHIELD KIT DR	1
159	2023-10-30	1723553	8312366	Retail	Part	VO-21409564	LAMP	1
160	2023-10-30	1723553	8312366	Retail	Part	VO-20748450	VALVE KIT	1
161	2023-10-30	1723553	8312366	Retail	Part	VO-8397707	ELBOW 1/2TU X 1/2TH	1
162	2023-10-30	1723553	8312366	Retail	Operation	LO-373	Replace engine harness	6
163	2023-10-30	1723553	8312366	Retail	Part	VO-21846096	CABLE HARNESS	1
164	2023-10-30	1723553	8312366		Text		Wacol	
165	2023-10-30	1723553	8312366	Retail	Part	VO-983762	BOLT M14*25 HEX SOCKET GR10.9	1
166	2023-10-30	1723553	8312366	Retail	Part	VO-20743007	IDLER GEAR	1
167	2023-10-30	1723553	8312366	Retail	Part	VO-22081685	IDLER GEAR	1
168	2023-10-30	1723553	8312366	Retail	Part	VO-3963413	LOCK RING	2
169	2023-10-30	1723553	8312366	Retail	Part	VO-8131393	CAGE	8
170	2023-10-30	1723553	8312366	Retail	Part	VO-983472	GREY CABLE TIE 145MM	10
171	2023-10-30	1723553	8312366	Retail	Part	VO-952635	P CLAMP 25MM	1
172	2023-10-30	1723553	8312366	Retail	Part	MK-8235-A11205X272	SEAL PINION INPUT FORWARD	1
173	2023-10-30	1723553	8312366	Retail	Part	MK-8235-KIT2638	NUT, PINION RT40	1
174	2023-10-30	1723553	8312366	Retail	Part	AU2-WUR089010810	BRAKE CLEAN	1
175	2023-10-30	1723553	8312366	Retail	Part	MK-2104-2507018X	KIT BRG RETAINER SPL250	3
176	2023-10-30	1723553	8312366	Retail	Part	OTH-FT1869X4X6S	SWIVEL 1/4TU 3/8 THREAD	1
177	2023-10-30	1723553	8312366	Retail	Part	VO-82710488	WIPER BLADE BASIC	2
178	2023-10-30	1723553	8312366	Retail	Part	VO-85129896	NOZZLE	2
179	2023-10-30	1723553	8312366	Retail	Part	VO-25165381	HINGE COMPL	2
180	2023-10-30	1723553	8312366	Retail	Part	VO-21030089	RUBBER DAMPER	1
181	2023-10-30	1723553	8312366	Retail	Part	VO-6781769	SPLICE RED	4
182	2023-10-30	1723553	8312366	Retail	Part	VO-21079456	RUBBER SPRING	2
183	2023-10-30	1723553	8312366	Retail	Part	OTH-ACX5158	Back Up Reverse Squawker	1
184	2023-10-30	1723553	8312366	Retail	Part	VO-20975430	SUPPORT	1
185	2023-10-30	1723553	8312366	Retail	Part	VO-984726	BOLT M6*20 FL	3
186	2023-10-30	1723553	8312366	Retail	Part	VO-990949	NUT M6 FL LOCKING	3

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
187	2023-10-30	1723553	8312366	Retail	Part	VO-21012985	HUB	1
188	2023-10-30	1723553	8312366	Retail	Part	VO-1652986	SPIGOT BRG	1
189	2023-10-30	1723553	8312366	Retail	Part	OTH-HSTM33/8	HEATSHRINK 33 MM-8MM	1
190	2023-10-30	1723553	8312366	Retail	Part	VO-994557	HOSE CLAMP 15mm-24mm	8
191	2023-10-30	1723553	8312366	Retail	Part	VO-21339891	RUBBER HOSE 1/2"	2
192	2023-10-30	1723553	8312366	Retail	Part	VO-22936956	SPACER SLEEVE	2
193	2023-10-30	1723553	8312366	Retail	Part	OTH-35-M1868-08-2	1/8 BSP MALE X 8MM PUSH IN	1
194	2023-10-30	1723553	8312366	Retail	Part	VO-20705080	ELBOW 3/8TU X 1/8TH	1
195	2023-10-30	1723553	8312366	Retail	Part	VO-20515114	ELBOW NIPPLE	1
196	2023-10-30	1723553	8312366	Retail	Part	VO-20544196	ELBOW NIPPLE	1
197	2023-10-30	1723553	8312366	Retail	Part	VO-8397699	ELBOW 1/4TU X 1/4TH	1
198	2023-10-30	1723553	8312366	Retail	Part	VO-984735	BOLT M8*25 FL	6
199	2023-10-30	1723553	8312366	Retail	Part	VO-990950	NUT M8 FL LOCKING	6
200	2023-10-30	1723553	8312366	Retail	Part	VO-25175011	ACTUATOR	1
201	2023-10-30	1723553	8312366	Retail	Part	VO-82785360	LATCH LH DOOR	1
202	2023-10-30	1723553	8312366	Retail	Other	891	Replace bug deflector	
203	2023-10-30	1723553	8312366	Retail	Other	80	sublet carry out COI inspection	
204	2023-10-30	1723553	8312366	Retail	Operation	LO-810	LHS window not going up	4
205	2023-10-30	1723553	8312366	Retail	Operation	LO-6000	R/H/S PINS & BUSHERS HAVE MOVEMENT	9
206	2023-10-30	1723553	8312366	Retail	Operation	LO-510	L/H/S S CAM TUBE HAS MOVEMENT	6
207	2023-10-30	1723553	8312366	Retail	Other	80	SUBLET REPLACE R/H/S WINDSCREEN	
208	2023-10-30	1723553	8312366	Retail	Part	VO-85113714	CAMSHAFT SEAL	2
209	2023-10-30	1723553	8312366	Retail	Part	VO-85113715	BUSHING	2
210	2023-10-30	1723553	8312366	Retail	Part	VO-85134672	BUSHING	1
211	2023-10-30	1723553	8312366	Retail	Part	VO-1076334	SHACKLE BOLT	1
212	2023-10-30	1723553	8312366	Retail	Part	VO-1075723	SHACKLE BOLT	1
213	2023-10-30	1723553	8312366	Retail	Part	VO-85134672	BUSHING	2
214	2023-10-30	1723553	8312366	Retail	Part	VO-25625833	SHACKLE, FRONT SPR	2
215	2023-10-30	1723553	8312366	Retail	Part	AU2-WUR0893033	INTERIOR CLEANER	1
216	2023-10-30	1723553	8312366	Retail	Part	VO-20852554	SEAL	1
217	2023-10-30	1723553	8312366	Retail	Part	VO-3199066	SEAL RING outer axel hat	1
218	2023-10-30	1723553	8312366	Retail	Part	MK-5396-40010180	SLACK ADJUSTER	1
219	2023-10-30	1723553	8312366	Retail	Part	MK-5554-8292001P	YOKE-BRAKE BOOSTER	1
220	2023-10-30	1723553	8312366	Retail	Part	VO-FFS	FREIGHT SYDNEY - PINKENBA	1
221	2023-10-30	1723553	8312366	Retail	Part	AU2-WUR057870504C	FLAPPY DISC 2 INCH	1
222	2023-10-30	1723553	8312366	Retail	Part	VO-1076334	SHACKLE BOLT	2
223	2023-10-30	1723553	8312366	Retail	Part	VO-25086052	FITTING	2

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
224	2023-10-30	1723553	8312366	Retail	Part	VO-984818	BOLT M12*80 FL GR10.9	6
225	2023-10-30	1723553	8312366	Retail	Part	VO-990952	NUT M12 FL LOCKING	6
226	2023-10-30	1723553	8312366	Retail	Part	VO-972081	SIX POINT SOCKE	3
227	2023-10-30	1723553	8312366		Text		was for other truck BOBBY2	
228	2023-10-30	1723553	8312366		Text		Drove vehicle over pit and inspected s-cam tubes.	
229	2023-10-30	1723553	8312366		Text		check throttle kick down	
230	2023-10-30	1723553	8312366		Text		also carry out trans/clutch cal	
231	2023-10-30	1723553	8312366		Text		Connected laptop and read fault codes. No faults for the	
232	2023-10-30	1723553	8312366		Text		transmission.	
233	2023-10-30	1723553	8312366		Text		Carried out Clutch wear check: 1.3 mm of wear.	
234	2023-10-30	1723553	8312366		Text		Carried out PWM valves clutch test: Passed.	
235	2023-10-30	1723553	8312366		Text		Carried out Clutch cylinder test: Passed.	
236	2023-10-30	1723553	8312366		Text		Carried out PWM valves activation test: No abnormal noise.	
237	2023-10-30	1723553	8312366		Text		Carried out Clutch, gearbox, pulling position	
238	2023-10-30	1723553	8312366		Text		calibration: Passed.	
239	2023-10-30	1723553	8312366		Text		Carried out Gear selector cylinder 1/Rev gear test: Passed.	
240	2023-10-30	1723553	8312366		Text		Carried out Gear selector cylinder 2/3 test: passed.	
241	2023-10-30	1723553	8312366		Text		Carried out Split cylinder test: Passed.	
242	2023-10-30	1723553	8312366		Text		Carried out Range cylinder test: Passed.	
243	2023-10-30	1723553	8312366		Text		Carried out warm hold test. Operation OK.	
244	2023-10-30	1723553	8312366		Text		Carried out actuator by-pass test. Operation OK. (Does	
245	2023-10-30	1723553	8312366		Text		have original diverter valve).	
246	2023-10-30	1723553	8312366		Text		Recomend visual inspection of clutch and servo when	
247	2023-10-30	1723553	8312366		Text		gearbox comes out for timing gear plate reseal.	
248	2023-10-30	1723553	8312366		Text		Clutch and servo OK. Replaced leaking air fittings on	
249	2023-10-30	1723553	8312366		Text		gearbox control lid. Tested operation once gearbox fitted	
250	2023-10-30	1723553	8312366		Text		all ok.	
251	2023-10-30	1723553	8312366		Text		Removed old gearbox cooler hoses and made up some new	
252	2023-10-30	1723553	8312366		Text		ones. Installed new hoses.	
253	2023-10-30	1723553	8312366		Text		Inspected front diff temp sensor, Disconnected plug and	
254	2023-10-30	1723553	8312366		Text		found wires had pulled out. Wired on new connector and	
255	2023-10-30	1723553	8312366		Text		plugged into temp sensor. Checked operation all ok.	
256	2023-10-30	1723553	8312366		Text		Inspected door hardware. Found RH latch was sticking, door	
257	2023-10-30	1723553	8312366		Text		is hanging too low and the check strap isn't holding.	
258	2023-10-30	1723553	8312366		Text		Requires new latch, hinges and check strap.	
259	2023-10-30	1723553	8312366		Text		Removed & replaced check strap + latch.	
260	2023-10-30	1723553	8312366		Text		Removed & replaced hinges and adjusted door to correct	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
261	2023-10-30	1723553	8312366		Text		alignment. Inspected LH door found strap is seizing up.	
262	2023-10-30	1723553	8312366		Text		Requires new check strap. Replaced check strap, Central	
263	2023-10-30	1723553	8312366		Text		locking is also jamming up. Found lock actuator and latch	
264	2023-10-30	1723553	8312366		Text		binding. Removed and replaced actuator and latch, greased	
265	2023-10-30	1723553	8312366		Text		internal mechanism. Checked operation all ok.	
266	2023-10-30	1723553	8312366		Text		check all locking mechanisms	
267	2023-10-30	1723553	8312366		Text		replace as required	
268	2023-10-30	1723553	8312366		Text		Carried out inspection of vehicle	
269	2023-10-30	1723553	8312366		Text		Removed and replaced wiper blades + washer jets, set	
270	2023-10-30	1723553	8312366		Text		adjustment and checked operation all ok.	
271	2023-10-30	1723553	8312366		Text		Removed rear walkplate and replaced air fitting on power	
272	2023-10-30	1723553	8312366		Text		Removed driver's side seat and found	
273	2023-10-30	1723553	8312366		Text		divider. Refit walkplate, built air system and checked for	
274	2023-10-30	1723553	8312366		Text		leaks all ok.	
275	2023-10-30	1723553	8312366		Text		Seat lumbar support not locking back in place. Removed	
276	2023-10-30	1723553	8312366		Text		seat and attempted to fix but unable to. Plastic shroud is	
277	2023-10-30	1723553	8312366		Text		all breaking apart and cracking. Stopped work and notified	
278	2023-10-30	1723553	8312366		Text		supervisor. Customer taking to seats R us. Installed new	
279	2023-10-30	1723553	8312366		Text		supplied seat.	
280	2023-10-30	1723553	8312366		Text		Removed driveshaft, input flange and seal. Cleaned all	
281	2023-10-30	1723553	8312366		Text		surfaces and pressed in new seal. Installed input flange.	
282	2023-10-30	1723553	8312366		Text		Found input flange has axial play. Suspect pinion bearing	
283	2023-10-30	1723553	8312366		Text		cup is spinning in housing. Customer will take vehicle and	
284	2023-10-30	1723553	8312366		Text		monitor for now.	
285	2023-10-30	1723553	8312366		Text		Removed broken section of LH 2nd drive brake backing	
286	2023-10-30	1723553	8312366		Text		plate. Installed new section of backing plate.	
287	2023-10-30	1723553	8312366		Text		Removed and replaced RH steer axle brake modulator valve.	
288	2023-10-30	1723553	8312366		Text		Built air system and checked operation & for leaks all ok.	
289	2023-10-30	1723553	8312366		Text		Removed and replaced cab ride height valve.	
290	2023-10-30	1723553	8312366		Text		Removed fitting from weight scales. Cut off damaged	
291	2023-10-30	1723553	8312366		Text		section of air line and installed new fitting into weight	
292	2023-10-30	1723553	8312366		Text		scales, Built up air and checked for leaks. OK.	
293	2023-10-30	1723553	8312366		Text		Replaced rear cab bump stop, found whole cab is leaning	
294	2023-10-30	1723553	8312366		Text		over	
295	2023-10-30	1723553	8312366		Text		to the left. Inspected front cab monts and bushes and	
296	2023-10-30	1723553	8312366		Text		found them all completely worn out. Removed both engine	
297	2023-10-30	1723553	8312366		Text		air filter housings and steer axle mudguards for access.	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
298	2023-10-30	1723553	8312366		Text		RH steer axle mudguard bracket was missing some mounting	
299	2023-10-30	1723553	8312366		Text		bolts, had to removed bracket from chassis and rubber	
300	2023-10-30	1723553	8312366		Text		isolator on fuel tank to replace missing bolts. Removed	
301	2023-10-30	1723553	8312366		Text		and replaced front cab mounts and bushes. Refit engine air	
302	2023-10-30	1723553	8312366		Text		cleaner housings and mudgaards.	
303	2023-10-30	1723553	8312366		Text		Replaced LH 2nd drive axle marker light, found reverse	
304	2023-10-30	1723553	8312366		Text		buzzer also damaged and several wires in lighting harness	
305	2023-10-30	1723553	8312366		Text		damaged. Replaced reverse buzzer and repaired wiring loom.	
306	2023-10-30	1723553	8312366		Text		Removed and replaced leaking diverter valve.	
307	2023-10-30	1723553	8312366		Text		Removed all components around engine harness	
308	2023-10-30	1723553	8312366		Text		Removed and installed new engine harness	
309	2023-10-30	1723553	8312366		Text		Fitted back all components and secured new harness	
310	2023-10-30	1723553	8312366		Text		Checked over after road test for any faults all ok	
311	2023-10-30	1723553	8312366		Text		Checked operation of LH window. Only works from passenger	
312	2023-10-30	1723553	8312366		Text		side switch. Swapped driver side and passenger side switch	
313	2023-10-30	1723553	8312366		Text		over and checked operation. Still n/w.	
314	2023-10-30	1723553	8312366		Text		Checked for power supply and ground at D/S passenger	
315	2023-10-30	1723553	8312366		Text		window switch OK. Removed dash/kick panels and checked for	
316	2023-10-30	1723553	8312366		Text		signal at each connector. Getting two signals when the	
317	2023-10-30	1723553	8312366		Text		clicking down on the passenger window switch. Suspect	
318	2023-10-30	1723553	8312366		Text		crushed wires.	
319	2023-10-30	1723553	8312366		Text		Checked RH door harness and found broken wire. Repaired	
320	2023-10-30	1723553	8312366		Text		wire and covered with conduit. Signal now makes it to the	
321	2023-10-30	1723553	8312366		Text		conector under the LH dash panel, Disconnected connector	
322	2023-10-30	1723553	8312366		Text		and found pin is pushed out. Pushed in pin and	
323	2023-10-30	1723553	8312366		Text		reconnected. Checked operation of window. All OK. Refit	
324	2023-10-30	1723553	8312366		Text		all trim panels.	
325	2023-10-30	1723553	8312366		Text		Put steer axle on stands and removed RH steer wheel.	
326	2023-10-30	1723553	8312366		Text		Released park brake and checked play in s-cam bushes.	
327	2023-10-30	1723553	8312366		Text		Minor play in LH 1st drive but looks more like slack	
328	2023-10-30	1723553	8312366		Text		adjuster movement in in splines rather than s-cam bushes.	
329	2023-10-30	1723553	8312366		Text		supported 1st drive axle and removed wheels, brakes, hub	
330	2023-10-30	1723553	8312366		Text		assembly and s-cam. Cleaned components and inspected for	
331	2023-10-30	1723553	8312366		Text		wear. Minor wear on s-cam. Slack adjuster has moderate	
332	2023-10-30	1723553	8312366		Text		play in splines. R/R s-cam bushings and seals. R/R hub	
333	2023-10-30	1723553	8312366		Text		seal. Installed s-cam, brake shoes as well as rest of	
334	2023-10-30	1723553	8312366		Text		components.	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
335	2023-10-30	1723553	8312366		Text		Removed grease fittings from pins and removed pins and	
336	2023-10-30	1723553	8312366		Text		shackles. Removed RH rear spring eye bushing attempted	
337	2023-10-30	1723553	8312366		Text		to remove upper bracket bushing but it was seized in	
338	2023-10-30	1723553	8312366		Text		place. Had to remove upper bracket and use press to	
339	2023-10-30	1723553	8312366		Text		extract bushing. Cleaned out housing and installed new	
340	2023-10-30	1723553	8312366		Text		bushes. Refit bracket and shackles.	
341	2023-10-30	1723553	8312366	Retail	Other	91	WORKSHOP CONSUMABLES	
342	2023-09-20	1704775	3309705	Retail	Operation	LO-920BI	Fan staying on	5
343	2023-09-20	1704775	3309705		Text		Jim: 0419 657 335.	
344	2023-09-20	1704775	3309705	Retail	Part	VO-23585940	FAN CLUTCH	1
345	2023-09-20	1704775	3309705	Retail	Part	VO-970771	CABLE SEAL	2
346	2023-09-20	1704775	3309705	Retail	Part	VO-20734499	ANTI-TAMPER SEALIN	5
347	2023-09-20	1704775	3309705	Retail	Part	VO-984945	CABLE TERMINAL	5
348	2023-09-20	1704775	3309705	Retail	Other	94	Environmental Levy	
349	2023-09-20	1704775	3309705		Text		jim.gatt@yahoo.com.au	
350	2023-09-20	1704775	3309705		Text		COMPLAINT: FAN STAYING ON	
351	2023-09-20	1704775	3309705		Text		CAUSE: INTERNAL FAULT IN FAN HUB ASSEMBLY	
352	2023-09-20	1704775	3309705		Text		CORRECTION: CONNECTED PC - NO ACTIVE FAULTS FOUND -	
353	2023-09-20	1704775	3309705		Text		CARRIED OUT ELECTRONIC CONTROLLED COOLING FAN FUNCTION	
354	2023-09-20	1704775	3309705		Text		TEST - FOUND NO RESPONSE FROM FAN ENGAGEMENT IN EITHER	
355	2023-09-20	1704775	3309705		Text		ACTIVATION OR DEACTIVATION REQUESTS FAN ENGAGEMENT	
356	2023-09-20	1704775	3309705		Text		CONSTANTLY 80% = INSPECTED FAN HUB ASSEMBLY - FOUND SEIZED	
357	2023-09-20	1704775	3309705		Text		FAN BEARING AND WORN CONNECTOR PINS - CARRIED OUT	
358	2023-09-20	1704775	3309705		Text		REPLACEMENT OF FAN HUB ASSEMBLY - CONNECTED PC - CARRIED	
359	2023-09-20	1704775	3309705		Text		OUT FUNCTION TEST FOR COOLING FAN - FOUND RESPONSE IN FAN	
360	2023-09-20	1704775	3309705		Text		ACTIVATION AND DEACTIVATION ENGAGEMENT - ADDED 1L OF	
361	2023-09-20	1704775	3309705		Text		ENGINE OIL AS PER CUSTOMER REQUEST - ALL OKAY	
362	2023-09-20	1704775	3309705	Retail	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.34
363	2023-09-20	1704775	3309705	Retail	Other	91	Workshop Consumables	
364	2023-08-25	1688624	8310943	Retail	Other	M	PLEASE FILL IN	
365	2023-08-25	1688624	8310943		Text		Contact:JIM 0419 657 335	
366	2023-08-25	1688624	8310943		Text		Mileage:	
367	2023-08-25	1688624	8310943		Text		Hrs:	
368	2023-08-25	1688624	8310943		Text		Next Service:	
369	2023-08-25	1688624	8310943		Text		Parked:	
370	2023-08-25	1688624	8310943	Retail	Operation	VO-1774400	Basic service. Chassis lubrication and o	2.7
371	2023-08-25	1688624	8310943		Text		oil changes included only in some models	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
372	2023-08-25	1688624	8310943	Retail	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
373	2023-08-25	1688624	8310943		Text		area	
374	2023-08-25	1688624	8310943	Retail	Operation	VO-2330600	Fuel filter, replace (one)	0.3
375	2023-08-25	1688624	8310943	Retail	Operation	VO-2331100	Filter, water separator, replace	0.3
376	2023-08-25	1688624	8310943	Retail	Other	97	ENVIRONMENTAL CHARGE	
377	2023-08-25	1688624	8310943	Retail	Part	AU2-AMP23068346	VDS 4.5 ENGINE OIL BULK	52
378	2023-08-25	1688624	8310943	Retail	Part	VO-85114535	FILTER KITS	1
379	2023-08-25	1688624	8310943	Retail	Part	VO-20579690	DOWDY WASHER	1
380	2023-08-25	1688624	8310943	Retail	Operation	LO-217	OIL LEAKING AT ENGINE SUMP GASKET	0.1
381	2023-08-25	1688624	8310943	Retail	Operation	LO-773	L/H 1st DRIVE HUB SEAL LEAKING	3
382	2023-08-25	1688624	8310943	Retail	Part	MK-8235-KSMA21247	BRAKE SHOE KIT	1
383	2023-08-25	1688624	8310943	Retail	Part	MK-8235-A1205R241C	OIL SEAL	1
384	2023-08-25	1688624	8310943	Retail	Part	VO-3199066	SEAL RING	1
385	2023-08-25	1688624	8310943	Retail	Part	AU2-WUR089010810	BRAKE CLEAN	2
386	2023-08-25	1688624	8310943	Retail	Operation	LO-773	REPLACE R/H 1st DRIVE HUB SEAL	3
387	2023-08-25	1688624	8310943		Text		& BRAKE LININGS	
388	2023-08-25	1688624	8310943	Retail	Part	MK-8235-KSMA21247	BRAKE SHOE KIT	1
389	2023-08-25	1688624	8310943	Retail	Part	MK-8235-A1205R241C	OIL SEAL	1
390	2023-08-25	1688624	8310943	Retail	Part	VO-3199066	SEAL RING	1
391	2023-08-25	1688624	8310943	Retail	Part	AU2-WUR089010810	BRAKE CLEAN	1
392	2023-08-25	1688624	8310943	Retail	Part	MK-9744-5526062400	SILICONE HOSE 5/8	1
393	2023-08-25	1688624	8310943		Text		Removed RH 1st drive wheels and brake drum for further	
394	2023-08-25	1688624	8310943		Text		Removed LH 1st drive wheels and brake drum for further	
395	2023-08-25	1688624	8310943		Text		this is coming from the timing plate	
396	2023-08-25	1688624	8310943		Text		inspection. Found RH 1st drive hub seal leaking, also	
397	2023-08-25	1688624	8310943		Text		brake shoes all cover with oil and grease.	
398	2023-08-25	1688624	8310943		Text		cleaned up the oil leak at the axle and the hub, R+R rh	
399	2023-08-25	1688624	8310943		Text		1st drive brake shoes	
400	2023-08-25	1688624	8310943		Text		Cleaned and inspected wheel bearings, greased then fit	
401	2023-08-25	1688624	8310943		Text		bearings and hub seal. Refit hub, brake drum and wheels.	
402	2023-08-25	1688624	8310943		Text		Adjusted bearing pre-load and adjusted brakes.	
403	2023-08-25	1688624	8310943		Text		Installed axle shaft and tensioned wheel nuts. Refit nut	
404	2023-08-25	1688624	8310943		Text		covers and hub cover. Steam cleaned vehicle and test	
405	2023-08-25	1688624	8310943		Text		drove. Checked diff oil level. OK.	
406	2023-08-25	1688624	8310943		Text		inspection. Found LH 1st drive hub seal leaking, also	
407	2023-08-25	1688624	8310943		Text		brake shoes all cover with oil and grease.	
408	2023-08-25	1688624	8310943		Text		cleaned up the oil leak at the axle and the hub, R+R LH	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
409	2023-08-25	1688624	8310943		Text		1st drive brake shoes	
410	2023-08-25	1688624	8310943		Text		Cleaned and inspected wheel bearings, greased then fit	
411	2023-08-25	1688624	8310943		Text		bearings and hub seal. Refit hub, brake drum and wheels.	
412	2023-08-25	1688624	8310943		Text		Adjusted bearing pre-load and adjusted brakes.	
413	2023-08-25	1688624	8310943		Text		Installed axle shaft and tensioned wheel nuts. Refit nut	
414	2023-08-25	1688624	8310943		Text		covers and hub cover. Steam cleaned vehicle and test	
415	2023-08-25	1688624	8310943		Text		drove. Checked diff oil level. OK.	
416	2023-08-25	1688624	8310943	Retail	Other	91	WORKSHOP CONSUMABLES	
417	2023-07-19	0	8310286	Retail	Other	M	PLEASE FILL IN	
418	2023-07-19	0	8310286		Text		Contact:JIM 0419 657 335	
419	2023-07-19	0	8310286	Retail	Operation	LO-810	cab pannard rod bolt snapped	3
420	2023-07-19	0	8310286	Retail	Other	97	ENVIRONMENTAL CHARGE	
421	2023-07-19	0	8310286	Retail	Part	VO-25162836	FLEX HOSE ASSY	1
422	2023-07-19	0	8310286	Retail	Part	VO-21609752	BUSHING	4
423	2023-07-19	0	8310286	Retail	Part	VO-60113330	WASHER	4
424	2023-07-19	0	8310286	Retail	Part	VO-21609750	TUBE	2
425	2023-07-19	0	8310286		Text		3150 19/7/2023	
426	2023-07-19	0	8310286	Retail	Other	80	Supply Bolts	
427	2023-07-19	0	8310286		Text		Brought truck into workshop, when bring it in, found there	
428	2023-07-19	0	8310286		Text		to be a large air leak when foot brake is applied, checked	
429	2023-07-19	0	8310286		Text		to see where leak was coming from, found the rhs steer	
430	2023-07-19	0	8310286		Text		axel, brake hose to be cut in half , r/r brake hose,	
431	2023-07-19	0	8310286		Text		checked for leaks, all ok, inspected cab Panhard rod,	
432	2023-07-19	0	8310286		Text		found the bolt to have already been drilled out, cut	
433	2023-07-19	0	8310286		Text		broken bolt out, removed Panhard rod, found bushes to be	
434	2023-07-19	0	8310286		Text		worn, r/r Panhard bushes, went to konnect and sourced new	
435	2023-07-19	0	8310286		Text		bolts, refitted Panhard rod, carried out road test and	
436	2023-07-19	0	8310286		Text		checked over	
437	2023-07-19	0	8310286	Retail	Other	91	WORKSHOP CONSUMABLES	
438	2023-07-14	1661082	3360794	Retail	Other	ME	Jim 0419 657 335	
439	2023-07-14	1661082	3360794	Retail	Operation	LO-210	Clamp behind the engine break	0.5
440	2023-07-14	1661082	3360794		Text		missing bolt	
441	2023-07-14	1661082	3360794	Retail	Part	VO-21029030	CLAMP	1
442	2023-07-14	1661082	3360794		Text		Popped bonnet , clamp loose on back of the EPG housing and	
443	2023-07-14	1661082	3360794		Text		missing bolt. replaced whole clamp as cannot get bolt	
444	2023-07-14	1661082	3360794		Text		seperate undone near exhaust braces to pul exhaust section	
445	2023-07-14	1661082	3360794		Text		forward to get proper seal, did clamp up properly. re did	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
446	2023-07-14	1661082	3360794		Text		braces back up . tested for leaks all good. went for a	
447	2023-07-14	1661082	3360794		Text		test drive , no leaks .	
448	2023-07-14	1661082	3360794	Retail	Other	91	Workshop Consumables	
449	2023-07-03	1642408	3845951	Retail	Operation	LO-390	VALVE SET	4
450	2023-07-03	1642408	3845951	Retail	Part	VO-20736230	SEAL/GASKET-VALVE COVER MP10	1
451	2023-07-03	1642408	3845951		Text		VEHICLE BROUGHT INTO WORKSHOP	
452	2023-07-03	1642408	3845951		Text		DISCONNECTED THE BATTERY	
453	2023-07-03	1642408	3845951		Text		CAB TILTED AND AIR INTAKE PIPES REMOVED FOR ACCESS	
454	2023-07-03	1642408	3845951		Text		LOOSEN ROCKER COVER	
455	2023-07-03	1642408	3845951		Text		COMPRESSION TEST PERFORMED - FOUND LOW COMPRESSION IN	
456	2023-07-03	1642408	3845951		Text		CYLINDER 1	
457	2023-07-03	1642408	3845951		Text		VALVE SET PERFORMED	
458	2023-07-03	1642408	3845951		Text		COMPRESSION TEST DONE AGAIN - LOW COMPRESSION STILL	
459	2023-07-03	1642408	3845951		Text		PRESENT IN CYL 1	
460	2023-07-03	1642408	3845951		Text		RECOMMEND A CYLINDER HEAD REPLACEMENT	
461	2023-07-03	1642408	3845951		Text		REPORTED FINDINGS TO CUSTOMER	
462	2023-07-03	1642408	3845951	Retail	Other	91	Workshop Consumables	
463	2023-07-03	1642408	5260336	Retail	Operation	LO-390	VALVE SET	5.5
464	2023-07-03	1642408	5260336	Retail	Part	VO-20736230	SEAL/GASKET-VALVE COVER MP10	1
465	2023-07-03	1642408	5260336		Text		VEHICLE BROUGHT INTO WORKSHOP	
466	2023-07-03	1642408	5260336		Text		DISCONNECTED THE BATTERY	
467	2023-07-03	1642408	5260336		Text		CAB TILTED AND AIR INTAKE PIPES REMOVED FOR ACCESS	
468	2023-07-03	1642408	5260336		Text		LOOSEN ROCKER COVER	
469	2023-07-03	1642408	5260336		Text		COMPRESSION TEST PERFORMED - FOUND LOW COMPRESSION IN	
470	2023-07-03	1642408	5260336		Text		CYLINDER 1	
471	2023-07-03	1642408	5260336		Text		VALVE SET PERFORMED	
472	2023-07-03	1642408	5260336		Text		COMPRESSION TEST DONE AGAIN - LOW COMPRESSION STILL	
473	2023-07-03	1642408	5260336		Text		PRESENT IN CYL 1	
474	2023-07-03	1642408	5260336		Text		RECOMMEND A CYLINDER HEAD REPLACEMENT	
475	2023-07-03	1642408	5260336		Text		REPORTED FINDINGS TO CUSTOMER	
476	2023-07-03	1642408	5260336	Retail	Other	91	Workshop Consumables	
477	2023-06-30	1642408	8309879	Internal	Other	210	sublet to wtg darwin	
478	2023-06-30	1642408	8309879		Text		vehicle presented with low power complaint after leaving	
479	2023-06-30	1642408	8309879		Text		us after a service and valve set.	
480	2023-06-30	1642408	8309879		Text		engine compression test carried out and found to have low	
481	2023-06-30	1642408	8309879		Text		compression on cylinder 1.	
482	2023-06-30	1642408	8309879		Text		valve set was carried out and compression rechecked. wtg	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
483	2023-06-30	1642408	8309879		Text		recommended cylinder head be replaced.	
484	2023-06-30	1642408	8309879		Text		vehicle than cam to us to have this repair done.	
485	2023-06-30	1642408	8309879	Internal	Other	20	sublet to wtg	
486	2023-06-14	0	4088304	Retail	Other	M	PLEASE FILL IN	
487	2023-06-14	0	4088304		Text		Contact: Jim 0419 657 335	
488	2023-06-14	0	4088304	Retail	Operation	LO-MTELEC6	4000- Workshop Parts Used	0.01
489	2023-06-13	1649336	8309298	Retail	Other	ACC	PLEASE FILL IN	
490	2023-06-13	1649336	8309298		Text		Contact:JIM 0419 657 335	
491	2023-06-13	1649336	8309298	Retail	Operation	LO-210	remove & replace cylinder head	25
492	2023-06-13	1649336	8309298	Retail	Operation	LO-210	check oil leaking at oil filter head	2
493	2023-06-13	1649336	8309298	Retail	Operation	LO-6000	check all suspension busings for movemen	3
494	2023-06-13	1649336	8309298		Text		& all suspension bolts tight	
495	2023-06-13	1649336	8309298	Retail	Part	VO-85023544	EXCH CYL HEAD 16L	1
496	2023-06-13	1649336	8309298	Retail	Part	VO-20736230	SEALING STRIP	1
497	2023-06-13	1649336	8309298	Retail	Part	VO-21575727	GASKET	1
498	2023-06-13	1649336	8309298	Retail	Part	VO-20815558	SEALING STRIP	1
499	2023-06-13	1649336	8309298	Retail	Part	VO-21352841	GASKET	6
500	2023-06-13	1649336	8309298	Retail	Part	VO-21185132	SEALING	2
501	2023-06-13	1649336	8309298	Retail	Part	VO-20799996	SEALING RING	1
502	2023-06-13	1649336	8309298	Retail	Part	VO-20852765	DOWDY WASHER	8
503	2023-06-13	1649336	8309298	Retail	Part	VO-20852764	DOWDY WASHER	12
504	2023-06-13	1649336	8309298	Retail	Part	VO-20707685	GASKET	1
505	2023-06-13	1649336	8309298	Retail	Part	VO-21940615	SEALING RING	1
506	2023-06-13	1649336	8309298	Retail	Part	VO-469601	TURBO O-RING	1
507	2023-06-13	1649336	8309298	Retail	Part	VO-21423788	SEALING RING	1
508	2023-06-13	1649336	8309298	Retail	Part	VO-21780376	SEALING RING	1
509	2023-06-13	1649336	8309298	Retail	Part	VO-1677370	VEB SEALING RING	2
510	2023-06-13	1649336	8309298	Retail	Part	VO-20526428	VEB SEAL RING	1
511	2023-06-13	1649336	8309298	Retail	Part	VO-21503575	SEALING RING	1
512	2023-06-13	1649336	8309298	Retail	Part	VO-8131154	SEALING RING	1
513	2023-06-13	1649336	8309298	Retail	Part	VO-20784537	GASKET	1
514	2023-06-13	1649336	8309298	Retail	Part	VO-22206133	GASKET	1
515	2023-06-13	1649336	8309298	Retail	Part	VO-20563945	ANTI-TAMPER SEALIN	1
516	2023-06-13	1649336	8309298	Retail	Part	VO-20578851	MAIN BEARING SHELL	6
517	2023-06-13	1649336	8309298	Retail	Part	VO-20578853	MAIN BEARING SHELL	1
518	2023-06-13	1649336	8309298	Retail	Part	VO-21948268	THRUST WASHER KIT	1
519	2023-06-13	1649336	8309298	Retail	Part	VO-8131198	SCREW	24

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
520	2023-06-13	1649336	8309298	Retail	Part	VO-20586602	BIG-END BEARING KI	6
521	2023-06-13	1649336	8309298	Retail	Part	VO-20734156	SEALING STRIP	1
522	2023-06-13	1649336	8309298	Retail	Part	MK-4000-67274530	TORQUE ROD	2
523	2023-06-13	1649336	8309298	Retail	Part	VO-85112668	TORQUE ROD	2
524	2023-06-13	1649336	8309298	Retail	Part	VO-85109233	BOLT	4
525	2023-06-13	1649336	8309298	Retail	Part	VO-85109225	WASHER	8
526	2023-06-13	1649336	8309298	Retail	Part	VO-85109234	NUT	4
527	2023-06-13	1649336	8309298		Text		Removed air intake piping, exahsut manifold and turbo,	
528	2023-06-13	1649336	8309298	Retail	Part	VO-21420336	CONNECTING PIPE	1
529	2023-06-13	1649336	8309298	Retail	Part	VO-3979639	PRE-HEAT GASKET	2
530	2023-06-13	1649336	8309298	Retail	Part	AU2-WUR089010810	BRAKE CLEAN	3
531	2023-06-13	1649336	8309298	Retail	Part	AU2-WUR0893140	INDUSTRY CLEANER	1
532	2023-06-13	1649336	8309298	Retail	Part	VO-21015266	BOLT M12*50MM	12
533	2023-06-13	1649336	8309298	Retail	Part	AU2-WUR067485024C	EMERY CLOTH 50MM G240	1
534	2023-06-13	1649336	8309298	Retail	Part	VO-1161963	RUBBER GREASE	1
535	2023-06-13	1649336	8309298	Internal	Part	VO-22742159	PIPE	1
536	2023-06-13	1649336	8309298	Internal	Operation	LO-870	REPLACE AIRCON HOSE	2
537	2023-06-13	1649336	8309298		Text		WE HAVE DAMAGED WHEN FITTING HEAD.	
538	2023-06-13	1649336	8309298	Retail	Part	VO-1675066	INT/COOL O-RING	1
539	2023-06-13	1649336	8309298	Retail	Part	VO-1542780	INT/COOL O-RING	1
540	2023-06-13	1649336	8309298	Retail	Part	VO-21497512	GASKET	1
541	2023-06-13	1649336	8309298	Retail	Part	VO-21940610	SEALING RING	1
542	2023-06-13	1649336	8309298	Retail	Part	VO-949659	PICK UP O-RING	3
543	2023-06-13	1649336	8309298	Retail	Part	AU2-WUR089010810	BRAKE CLEAN	1
544	2023-06-13	1649336	8309298	Retail	Part	VO-20938964	SEAL	1
545	2023-06-13	1649336	8309298	Retail	Part	VO-21695684	SEALING RING	2
546	2023-06-13	1649336	8309298	Retail	Part	VO-949659	PICK UP O-RING	2
547	2023-06-13	1649336	8309298		Text		Removed oil filter housing, is covered in oil and dirt,	
548	2023-06-13	1649336	8309298	Internal	Part	AU2-WUR089010810	BRAKE CLEAN	1
549	2023-06-13	1649336	8309298	Retail	Part	VO-984753	BOLT M10*25 FL	1
550	2023-06-13	1649336	8309298		Text		REFER RILEY	
551	2023-06-13	1649336	8309298	Retail	Other	97	ENVIRONMENTAL CHARGE	
552	2023-06-13	1649336	8309298	Retail	Operation	LO-210	carry out bearing roll	10
553	2023-06-13	1649336	8309298		Text		Removed sump.	
554	2023-06-13	1649336	8309298		Text		Removed oil pick up and pump, removed stiffening plate,	
555	2023-06-13	1649336	8309298		Text		installed piston liner hold down tools. Replaced all	
556	2023-06-13	1649336	8309298		Text		conrod bearings and botls, tensioned new bolts. Removed	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
557	2023-06-13	1649336	8309298		Text		Main cap bearings and replaced. Carried out main cap	
558	2023-06-13	1649336	8309298		Text		bearings replace,	
559	2023-06-13	1649336	8309298		Text		exhaust brake housing. Drained coolant and oil, removed	
560	2023-06-13	1649336	8309298		Text		inlet piping. Removed rocker cover, upper timing cover,	
561	2023-06-13	1649336	8309298		Text		timing plate bolts and adjustable idler bolts, thermostat	
562	2023-06-13	1649336	8309298		Text		front pipe and top radiator hose. Removed injector	
563	2023-06-13	1649336	8309298		Text		harness, VEB soleniod rocker shaft, injectors and cam	
564	2023-06-13	1649336	8309298		Text		gear. Removed	
565	2023-06-13	1649336	8309298		Text		cylinder head. cleaned block and installed new cylinder	
566	2023-06-13	1649336	8309298		Text		head gasket, installed new cylinder head and tensioned	
567	2023-06-13	1649336	8309298		Text		Set back lash, replaced injector o-rings and cleaned	
568	2023-06-13	1649336	8309298		Text		injectors. Installed and tensioned injectors, lubed valves	
569	2023-06-13	1649336	8309298		Text		and installed valve bridges and carried out valve and	
570	2023-06-13	1649336	8309298		Text		injector adjustment. Cleaned and sealed upper timing cover	
571	2023-06-13	1649336	8309298		Text		and rocker cover. Installed and replaced inlet manifold	
572	2023-06-13	1649336	8309298		Text		and gaskets, exhaust manifold and gaskets aswell as turbo	
573	2023-06-13	1649336	8309298		Text		base gasket and branch seals. Installed boost pipes and	
574	2023-06-13	1649336	8309298		Text		pre heater assembly, installed all brackets and air	
575	2023-06-13	1649336	8309298		Text		intake. Installed exhaust piping and exhaust brake	
576	2023-06-13	1649336	8309298		Text		housing. Installed all coolant hoses and replaced	
577	2023-06-13	1649336	8309298		Text		thermostat o-ring. Installed rear crossmember and	
578	2023-06-13	1649336	8309298		Text		compressor cooling coil, installed and sealed sump. Filled	
579	2023-06-13	1649336	8309298		Text		oil and coolant. Washed down truck and carred out long	
580	2023-06-13	1649336	8309298		Text		road test	
581	2023-06-13	1649336	8309298		Text		replaced thermostat o-rings and filter housing gasket.	
582	2023-06-13	1649336	8309298	Retail	Other	91	WORKSHOP CONSUMABLES	
583	2023-06-02	1642408	3845803	Retail	Operation	LO-390	VALVE SET	5.5
584	2023-06-02	1642408	3845803	Retail	Part	VO-20736230	SEAL/GASKET-VALVE COVER MP10	1
585	2023-06-02	1642408	3845803		Text		VEHICLE BROUGHT INTO WORKSHOP	
586	2023-06-02	1642408	3845803		Text		DISCONNECTED THE BATTERY	
587	2023-06-02	1642408	3845803		Text		CAB TILTED AND AIR INTAKE PIPES REMOVED FOR ACCESS	
588	2023-06-02	1642408	3845803		Text		LOOSEN ROCKER COVER	
589	2023-06-02	1642408	3845803		Text		COMPRESSION TEST PERFORMED - FOUND LOW COMPRESSION IN	
590	2023-06-02	1642408	3845803		Text		CYLINDER 1	
591	2023-06-02	1642408	3845803		Text		VALVE SET PERFORMED	
592	2023-06-02	1642408	3845803		Text		COMPRESSION TEST DONE AGAIN - LOW COMPRESSION STILL	
593	2023-06-02	1642408	3845803		Text		PRESENT IN CYL 1	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
594	2023-06-02	1642408	3845803		Text		RECOMMEND A CYLINDER HEAD REPLACEMENT	
595	2023-06-02	1642408	3845803		Text		REPORTED FINDINGS TO CUSTOMER	
596	2023-06-02	1642408	3845803	Retail	Other	91	Workshop Consumables	
597	2023-06-01	1642408	3845794	Retail	Operation	LO-390	OIL LEAK AT FRONT DIFF	3
598	2023-06-01	1642408	3845794	Retail	Part	MK-8235-R945008	SEAL-THRUSHAFT 160	1
599	2023-06-01	1642408	3845794	Retail	Part	AU2-CAL85121712	MACK GEAR OIL GO-J 85W140	2
600	2023-06-01	1642408	3845794		Text		BRING UNIT INTO WKSP AND INSPECT CUSTOMER COMPLAINT.	
601	2023-06-01	1642408	3845794		Text		FOUND 1st DRIVE OUTPUT SEAL HAS SEVERE LEAK.	
602	2023-06-01	1642408	3845794		Text		WASH DOWN AREA.	
603	2023-06-01	1642408	3845794		Text		REMOVE JACK SHAFT AND ANCILLARIES.	
604	2023-06-01	1642408	3845794		Text		REMOVE THRU SHAFT.	
605	2023-06-01	1642408	3845794		Text		REMOVE THRU SHAFT SEAL.	
606	2023-06-01	1642408	3845794		Text		CLEAN AND INSPECT SEALING AREA - OK.	
607	2023-06-01	1642408	3845794		Text		FIT NEW THRU SHAFT SEAL.	
608	2023-06-01	1642408	3845794		Text		REFIT THRU SHAFT.	
609	2023-06-01	1642408	3845794		Text		REFIT JACK SHAFT AND ANCILLARIES.	
610	2023-06-01	1642408	3845794		Text		TEST REPAIR - OK.	
611	2023-06-01	1642408	3845794	Retail	Other	91	Workshop Consumables	
612	2023-05-25	1638819	8308347	Retail	Other	ACC	PLEASE FILL IN	
613	2023-05-25	1638819	8308347		Text		Contact:JIM 0419 657 335	
614	2023-05-25	1638819	8308347	Retail	Operation	VO-1774600	Annual service. Chassis lubrication and	4
615	2023-05-25	1638819	8308347		Text		oil changes included only in some models	
616	2023-05-25	1638819	8308347	Retail	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
617	2023-05-25	1638819	8308347		Text		area	
618	2023-05-25	1638819	8308347	Retail	Operation	VO-2331100	Filter, water separator, replace	0.3
619	2023-05-25	1638819	8308347	Retail	Operation	VO-2330600	Fuel filter, replace (one)	0.3
620	2023-05-25	1638819	8308347	Retail	Operation	VO-2141300	Valves and unit injectors, adjust	3
621	2023-05-25	1638819	8308347	Retail	Operation	VO-2582200	Filter, AdBlue, replace	0.3
622	2023-05-25	1638819	8308347	Retail	Operation	VO-5616600	Air drier cassette, replace	0.4
623	2023-05-25	1638819	8308347	Retail	Operation	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.4
624	2023-05-25	1638819	8308347		Text		area mineral	
625	2023-05-25	1638819	8308347	Retail	Operation	VO-1752700	Final drive oil, change. Lube area	0.6
626	2023-05-25	1638819	8308347	Retail	Operation	VO-2562700	Filter insert, air cleaner, replace. Onl	0.2
627	2023-05-25	1638819	8308347		Text		Only valid for primary filter	
628	2023-05-25	1638819	8308347	Retail	Other	97	ENVIRONMENTAL CHARGE	
629	2023-05-25	1638819	8308347	Retail	Other	460	check all wheel ends for movement	
630	2023-05-25	1638819	8308347		Text		wheel bearings	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
631	2023-05-25	1638819	8308347	Retail	Other	460	check all drive line unis & centure	
632	2023-05-25	1638819	8308347		Text		bearing for movement	
633	2023-05-25	1638819	8308347	Retail	Part	AU2-AMP23068346	VDS 4.5 ENGINE OIL BULK	52
634	2023-05-25	1638819	8308347	Retail	Part	VO-85114535	FILTER KITS	1
635	2023-05-25	1638819	8308347	Retail	Part	VO-20579690	DOWDY WASHER	1
636	2023-05-25	1638819	8308347	Retail	Part	VO-85129688	AIR DRIER KIT	1
637	2023-05-25	1638819	8308347	Retail	Part	VO-21954674	STRAINER	1
638	2023-05-25	1638819	8308347	Retail	Part	VO-23381558	ADBLUE FILTER	1
639	2023-05-25	1638819	8308347	Retail	Part	AU2-CAL85121714	TRANS OIL SAE50 BULK	17
640	2023-05-25	1638819	8308347	Retail	Part	VO-20779040	AT G/BOX FILTER	1
641	2023-05-25	1638819	8308347	Retail	Operation	LO-560	CHECK AIR SYSTEM LOSSING AIR	0.8
642	2023-05-25	1638819	8308347		Text		SECONDARY SYSTEM LEAKING	
643	2023-05-25	1638819	8308347	Retail	Part	AU2-WUR089010810	BRAKE CLEAN	1
644	2023-05-25	1638819	8308347	Retail	Part	AU2-CAL85121715	DIFF OIL 85W140 BULK	34
645	2023-05-25	1638819	8308347		Text		CARRIED OUT ANNUAL SERVICE AS PER SERVICE SHEETS	
646	2023-05-25	1638819	8308347		Text		INCLUDING VALVE AND UNIT INJECTORS ADJUSTMENT	
647	2023-05-25	1638819	8308347		Text		CHECKED ALL UNI JOINTS & CENTRE BEARING FOR MOVEMENT ALL OK	
648	2023-05-25	1638819	8308347		Text		CHECKED WHEEL BEARING FOR MOVEMENT ALL OK	
649	2023-05-25	1638819	8308347		Text		CAN HEAR AIR LEAKING AT REAR OF	
650	2023-05-25	1638819	8308347		Text		VEHICLE	
651	2023-05-25	1638819	8308347		Text		CHECKED AIR LEAKS FOUND LEAKING FROM AIR FITTING AT AIR	
652	2023-05-25	1638819	8308347		Text		TANK PORT + CAB RIDE HEIGHT VALVE. REPLACED LEAKING AIR	
653	2023-05-25	1638819	8308347		Text		FITTING.	
654	2023-05-25	1638819	8308347	Retail	Other	91	WORKSHOP CONSUMABLES	
655	2023-05-18	1635914	8308525	Retail	Other	ACC	PLEASE FILL IN	
656	2023-05-18	1635914	8308525		Text		Contact:JIM 0419 657 335	
657	2023-05-18	1635914	8308525	Retail	Operation	LO-810	2.5	2.5
658	2023-05-18	1635914	8308525		Text		& rear cab shocks	
659	2023-05-18	1635914	8308525	Retail	Operation	LO-251	exhaust heat sheild under cab rubber	1
660	2023-05-18	1635914	8308525		Text		mounts broken two supplied	
661	2023-05-18	1635914	8308525	Retail	Operation	LO-210	check & repair noisy belts	2.3
662	2023-05-18	1635914	8308525		Text		& tensioners	
663	2023-05-18	1635914	8308525	Retail	Part	VO-23576479	SHOCK ABSORBER	4
664	2023-05-18	1635914	8308525	Retail	Part	VO-20593022	RUBBER CUSHION	2
665	2023-05-18	1635914	8308525	Retail	Part	VO-23961777	V-RIBBED BELT - 10PK1465	1
666	2023-05-18	1635914	8308525	Retail	Part	VO-21753149	IDLER PULLEY	1
667	2023-05-18	1635914	8308525	Retail	Part	VO-23961744	V-RIBBED BELT	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
668	2023-05-18	1635914	8308525	Retail	Part	VO-21422767	BELT TENSIONER	1
669	2023-05-18	1635914	8308525	Retail	Part	VO-21631484	BELT TENSIONER	1
670	2023-05-18	1635914	8308525		Text		put old belts & idler/tensioners in cab	
671	2023-05-18	1635914	8308525		Text		r/r both belts both tentioners along with idler pully due	
672	2023-05-18	1635914	8308525		Text		to belts been worn and idler and tentioners noisy	
673	2023-05-18	1635914	8308525		Text		need two more	
674	2023-05-18	1635914	8308525		Text		r/r all four exhaust heat sheald mount rubber three off	
675	2023-05-18	1635914	8308525		Text		them had to be cut out and had to retap all threads all	
676	2023-05-18	1635914	8308525		Text		complete	
677	2023-05-18	1635914	8308525		Text		PARTS IN TRUCK ON DRIVER SEAT!!	
678	2023-05-18	1635914	8308525		Text		removed all 4 rear cab shocks and both rear air bags and	
679	2023-05-18	1635914	8308525		Text		replace, all old	
680	2023-05-18	1635914	8308525		Text		spare parts on passager front floor	
681	2023-05-18	1635914	8308525	Retail	Other	91	WORKSHOP CONSUMABLES	
682	2023-03-15	1607482	8307091	Retail	Other	ACC	PLEASE FILL IN	
683	2023-03-15	1607482	8307091		Text		Contact:JIM 0419 657 335	
684	2023-03-15	1607482	8307091	Retail	Other	210	engine lost boost pressure	
685	2023-03-15	1607482	8307091		Text		running rough and trouble idling	
686	2023-03-15	1607482	8307091	Retail	Part	VO-23992701	AIR VALVE	1
687	2023-03-15	1607482	8307091	Internal	Part	VO-21170982	COOLANT PIPE	1
688	2023-03-15	1607482	8307091	Internal	Part	AU2-AMP24332693	MACK VCS-2 COOLANT 5LTR	2
689	2023-03-15	1607482	8307091	Internal	Operation	LO-260	cooant leak breakdown	2.18
690	2023-03-15	1607482	8307091		Text		went back out to vehicle due to loss of coolant after new	
691	2023-03-15	1607482	8307091		Text		header tank was fitted found one of the plastic clips onto	
692	2023-03-15	1607482	8307091		Text		the tank had broken and the o ring on the pipe was swollen	
693	2023-03-15	1607482	8307091		Text		replced pipe and topped up coolant	
694	2023-03-09	1607465	8306922	Retail	Other	M	PLEASE FILL IN	
695	2023-03-09	1607465	8306922		Text		Contact:JIM 0419 657 335	
696	2023-03-09	1607465	8306922	Retail	Operation	LO-250	exhaust flex after turbo leaking	0.5
697	2023-03-09	1607465	8306922	Retail	Operation	LO-250	exhaust break staying on	2.2
698	2023-03-09	1607465	8306922		Text		sounds like avu and diver valve	
699	2023-03-09	1607465	8306922	Retail	Part	MK-9711-9103M3	HUBCAP 8" MACKLOGO	2
700	2023-03-09	1607465	8306922	Retail	Part	VO-23915461	EXPANSION TANK	1
701	2023-03-09	1607465	8306922	Retail	Operation	LO-230	replace fuel tank crossover lines	1.5
702	2023-03-09	1607465	8306922	Retail	Operation	LO-260	replace headder tank	1
703	2023-03-09	1607465	8306922	Retail	Other	810	fit chrome trims	
704	2023-03-09	1607465	8306922	Retail	Part	VO-23137065	EXHAUST PIPE 360mm long	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
705	2023-03-09	1607465	8306922	Retail	Part	VO-990951	NUT M10 FL LOCKING	2
706	2023-03-09	1607465	8306922	Retail	Part	VO-994195	BOLT M10*50 FL	2
707	2023-03-09	1607465	8306922		Text		connected laptop	
708	2023-03-09	1607465	8306922		Text		removed fuel tank crossover line for repair	
709	2023-03-09	1607465	8306922	Retail	Other	20	SUBLET - HYDRAULINK	
710	2023-03-09	1607465	8306922		Text		on ppo	
711	2023-03-09	1607465	8306922	Retail	Part	VO-23278215	HOSE	1
712	2023-03-09	1607465	8306922	Retail	Operation	LO-360	replace batterys	1
713	2023-03-09	1607465	8306922	Retail	Part	VO-22823727	EXHAUST BRAKE	1
714	2023-03-09	1607465	8306922	Retail	Part	AU2-21209957	BULLDOG BATTERY N70	4
715	2023-03-09	1607465	8306922		Text		disconnected batteries, r/r all 4 batteries, reconnect	
716	2023-03-09	1607465	8306922		Text		carried exhaust brake function test	
717	2023-03-09	1607465	8306922		Text		found exhaust brake shutter sticking on, removed air	
718	2023-03-09	1607465	8306922		Text		cylinder and found shtter hosuing seized	
719	2023-03-09	1607465	8306922		Text		pulled exhaust brake housing out	
720	2023-03-09	1607465	8306922		Text		fitted new housing hooked air line up and back presure	
721	2023-03-09	1607465	8306922		Text		sensor	
722	2023-03-09	1607465	8306922		Text		fitted clamps and air intake	
723	2023-03-09	1607465	8306922		Text		sent for test drive	
724	2023-03-09	1607465	8306922		Text		batteries, extra time needed due to box built into battery	
725	2023-03-09	1607465	8306922		Text		compartment blocking access to batteries	
726	2023-03-09	1607465	8306922	Retail	Other	91	WORKSHOP CONSUMABLES	
727	2023-03-08	0	8170793	Retail	Other	M	PLEASE FILL IN	
728	2023-03-08	0	8170793		Text		Contact: Jim 0419 657 335	
729	2023-03-08	0	8170793	Retail	Operation	LO-251	Travel out to Hanson Rd Amberley and	7.5
730	2023-03-08	0	8170793		Text		rectify vehicle has low power and blowing lots of smoke.	
731	2023-03-08	0	8170793	Retail	Other	92	UTE MILEAGE 20 km's @ \$2.20/km.	
732	2023-03-08	0	8170793	Retail	Part	VO-85133578	INSTALL KIT, TURBO	1
733	2023-03-08	0	8170793	Retail	Part	VO-85000622	TURBOCHARGER, EXCH	1
734	2023-03-08	0	8170793	Retail	Part	AU2-9701-MDQ62DO18MM JOINER		1
735	2023-03-08	0	8170793	Retail	Part	VO-980832	8MM SYNDFLEX	1
736	2023-03-08	0	8170793	Retail	Part	VO-22908769	CHARGE AIR HOSE	1
737	2023-03-08	0	8170793	Retail	Part	VO-993811	FLANGE BOLT M10 x 50mm TURBO	4
738	2023-03-08	0	8170793	Retail	Part	VO-21352841	GASKET EXHAUST	6
739	2023-03-08	0	8170793	Retail	Part	OTH-CALLOUT	Callout Fee - Parts	150
740	2023-03-08	0	8170793	Retail	Part	VO-1161963	RUBBER GREASE	1
741	2023-03-08	0	8170793		Text		travel to vehicle found turbo blowen remove turbo and	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
742	2023-03-08	0	8170793		Text		mainfold clean surfaces refit mainfold with new turbo	
743	2023-03-08	0	8170793		Text		clean all engine pipe work reassemble and test ok.	
744	2023-03-08	0	8170793	Retail	Other	91	WORKSHOP CONSUMABLES	
745	2023-03-07	1606979	3024547	Retail	Operation	LO-219	Engine Other	5
746	2023-03-07	1606979	3024547		Text		Customer reports that the vehicle is losing power	
747	2023-03-07	1606979	3024547	Retail	Other	CUSTDETS	Customer Details	
748	2023-03-07	1606979	3024547		Text		Name: Jim	
749	2023-03-07	1606979	3024547		Text		Phone: 0419 657 335	
750	2023-03-07	1606979	3024547		Text		Email:	
751	2023-03-07	1606979	3024547	Retail	Part	VO-20592783	V-CLAMP	4
752	2023-03-07	1606979	3024547	Retail	Part	VO-1675066	TURBO INTAKE SEAL	2
753	2023-03-07	1606979	3024547	Retail	Part	VO-22908769	CHARGE AIR HOSE	1
754	2023-03-07	1606979	3024547	Retail	Part	VO-20550690	CAC HOSE NB (REFIT)	1
755	2023-03-07	1606979	3024547	Retail	Part	VO-8073055	O-RING	1
756	2023-03-07	1606979	3024547	Retail	Part	OTH-SC-091	CLAMP	1
757	2023-03-07	1606979	3024547	Retail	Part	VO-22073233	TEMPERATURE SENSOR	1
758	2023-03-07	1606979	3024547		Text		Concern: Losing power	
759	2023-03-07	1606979	3024547	Retail	Operation	VO-3717300	Data links, fault tracing with oscillosc	1
760	2023-03-07	1606979	3024547		Text		Clutch faults & data link faults	
761	2023-03-07	1606979	3024547		Text		Removed & refitted intercooler and replaced hose clamps.	
762	2023-03-07	1606979	3024547		Text		Test drove and all okay. Fitted new ambient air temp	
763	2023-03-07	1606979	3024547		Text		sensor.	
764	2023-03-07	1606979	3024547		Text		Cause: Boost leaks/intercooler	
765	2023-03-07	1606979	3024547		Text		Correction: Carried out boost check,found leaks at cac hose	
766	2023-03-07	1606979	3024547		Text		clamp and leaking from split in the intercooler. Replaced	
767	2023-03-07	1606979	3024547		Text		intercooler and nad replaced hose clamps. Fault codes	
768	2023-03-07	1606979	3024547		Text		present for ambient air sensor,diagnoded and replaced air	
769	2023-03-07	1606979	3024547		Text		sensor. Noted that turbo had damaged fins(small chips on	
770	2023-03-07	1606979	3024547		Text		the edge)not replacing. Noted clutch and data link faults	
771	2023-03-07	1606979	3024547		Text		to driver.	
772	2023-03-07	1606979	3024547	Retail	Other	91	Workshop Consumables	
773	2023-01-23	1585533	3023746	Retail	Operation	LO-AIRLEAK	Inspect & Rectify Air Leaks.	2
774	2023-01-23	1585533	3023746		Text		Concern: Air leaks	
775	2023-01-23	1585533	3023746		Text		Cause: Exhaust melted air lines.	
776	2023-01-23	1585533	3023746		Text		Correction: Loaded tools into van. Travelled to vehicle	
777	2023-01-23	1585533	3023746		Text		located on Greenwattle Street (Grace Removals). Inspected.	
778	2023-01-23	1585533	3023746		Text		Found exhaust had fallen off and melted air lines.	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
779	2023-01-23	1585533	3023746		Text		Repaired multiple melted air lines. Refitted exhaust pipe.	
780	2023-01-23	1585533	3023746		Text		Tightened all clamps on pipe. Started truck and checked.	
781	2023-01-23	1585533	3023746		Text		Returned to WTG workshop.	
782	2023-01-23	1585533	3023746	Retail	Other	91	Workshop Consumables	
783	2022-11-10	0	8303927	Retail	Other	M	PLEASE FILL IN	
784	2022-11-10	0	8303927		Text		Contact:	
785	2022-11-10	0	8303927		Text		Mileage:	
786	2022-11-10	0	8303927		Text		Hrs:	
787	2022-11-10	0	8303927		Text		Next Service:	
788	2022-11-10	0	8303927		Text		Parked:	
789	2022-11-10	0	8303927	Retail	Operation	LO-640	replace steering wheel	1
790	2022-11-10	0	8303927	Retail	Part	AU2-INV990005	LED HB3 Headlight	2
791	2022-11-10	0	8303927	Retail	Part	VO-85146403	CLIP	2
792	2022-11-10	0	8303927	Retail	Other	91	WORKSHOP CONSUMABLES	
793	2022-11-07	1551345	3703759	Retail	Operation	LO-511	FRONT WHEEL BRAKES	1.38
794	2022-11-07	1551345	3703759		Text		CHECK OUT AIR LEAK AT FRONT OF VEHICLE WHEN THE BRAKE	
795	2022-11-07	1551345	3703759	Retail	Part	MK-ABC229860	VALVE-QR1 QUICK RE	1
796	2022-11-07	1551345	3703759	Retail	Part	OTH-FF51/2X3/845DE	1/2X3/8 45' ELBOW	1
797	2022-11-07	1551345	3703759		Text		PEDDLE IS APPLIED.	
798	2022-11-07	1551345	3703759	Retail	Other	91	Workshop Consumables	
799	2022-09-24	1529449	3703659	Retail	Operation	LO-252	SILENCER AND EXHAUST LINE	5.25
800	2022-09-24	1529449	3703659	Retail	Part	VO-21647536	SILENCER	1
801	2022-09-24	1529449	3703659		Text		Old Part (21647536)serial # VO18647	
802	2022-09-24	1529449	3703659		Text		New Part (21647536)serial # VO44891	
803	2022-09-24	1529449	3703659		Text		COMPLAINT: NOX SENSOR FAULT ACTIVE.	
804	2022-09-24	1529449	3703659		Text		CAUSE: FAULTY MUFFLER.	
805	2022-09-24	1529449	3703659		Text		CORRECTION: CARRY OUT REPLACEMENT OF THE MUFFLER, HAD TO	
806	2022-09-24	1529449	3703659		Text		CUT THE SHIELD MOUNTING BRACKETS OFF THE OLD MUFFLER & FIT	
807	2022-09-24	1529449	3703659		Text		TO THE NEW MUFFLER, CARRY DOSING VALE TEST WHILE THE	
808	2022-09-24	1529449	3703659		Text		DOSING VALVE WAS OUT, ALL CHECKED OK, CLEAR ALL FAULT CODES.	
809	2022-09-24	1529449	3703659	Retail	Other	94	Environmental Levy	
810	2022-09-24	1529449	3703659		Text		PAID IN FULL BPOINTT REF 27244102344	
811	2022-09-24	1529449	3703659	Retail	Other	91	Workshop Consumables	
812	2022-07-21	1500181	8300726	Retail	Other	M	PLEASE FILL IN	
813	2022-07-21	1500181	8300726		Text		Contact:JIM 0419 657 335	
814	2022-07-21	1500181	8300726	Retail	Operation	VO-1774400	Basic service. Chassis lubrication and o	2.7
815	2022-07-21	1500181	8300726	Retail	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
816	2022-07-21	1500181	8300726	Retail	Operation	VO-2331100	Filter, water separator, replace	0.3
817	2022-07-21	1500181	8300726	Retail	Operation	VO-2330600	Fuel filter, replace (one)	0.3
818	2022-07-21	1500181	8300726	Retail	Operation	VO-2582200	Filter, AdBlue, replace	0.5
819	2022-07-21	1500181	8300726	Retail	Operation	VO-2584800	Strainer, replace. Pump unit	0.7
820	2022-07-21	1500181	8300726	Retail	Operation	VO-5616600	Air drier cassette, replace	0.5
821	2022-07-21	1500181	8300726	Retail	Operation	VO-1752700	Final drive oil, change. Lube area	0.6
822	2022-07-21	1500181	8300726	Retail	Operation	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.6
823	2022-07-21	1500181	8300726	Retail	Operation	VO-2141300	Valves and unit injectors, adjust	3
824	2022-07-21	1500181	8300726	Retail	Operation	VO-2562700	Filter insert, air cleaner, replace. Onl	0.2
825	2022-07-21	1500181	8300726	Retail	Operation	VO-6451400	Oil and filter, power steering, replace	0.4
826	2022-07-21	1500181	8300726	Retail	Other	97	ENVIRONMENTAL CHARGE	
827	2022-07-21	1500181	8300726	Retail	Part	AU2-AMP23068346	VOLVO VDS 4.5 BULK	52
828	2022-07-21	1500181	8300726	Retail	Part	VO-85114535	FILTER KITS	1
829	2022-07-21	1500181	8300726	Retail	Part	VO-20579690	DOWDY WASHER	1
830	2022-07-21	1500181	8300726	Retail	Part	VO-23381558	ADBLUE FILTER	1
831	2022-07-21	1500181	8300726	Retail	Part	VO-21954674	STRAINER	1
832	2022-07-21	1500181	8300726	Retail	Part	VO-85129688	AIR DRIER KIT	1
833	2022-07-21	1500181	8300726	Retail	Part	MK-57MD42M	***ELEMENT, AIR 'C	2
834	2022-07-21	1500181	8300726	Retail	Part	MK-5839-870678A	FILTER P/STR GRAN	1
835	2022-07-21	1500181	8300726	Retail	Part	VO-85122800	ATF DEX 3	3
836	2022-07-21	1500181	8300726	Retail	Operation	LO-250	check cracking of muffler	0.3
837	2022-07-21	1500181	8300726	Retail	Operation	LO-810	ds door not opening	1
838	2022-07-21	1500181	8300726	Retail	Part	VO-85131616	FILTER	1
839	2022-07-21	1500181	8300726	Retail	Part	AU2-CAL85121715	DIFF OIL 85W140 BULK	38
840	2022-07-21	1500181	8300726	Retail	Part	AU2-CAL85121714	TRANS OIL SAE50 BULK	17
841	2022-07-21	1500181	8300726	Retail	Part	VO-20779040	AT G/BOX FILTER	1
842	2022-07-21	1500181	8300726	Retail	Part	VO-82150110	PEEP WINDOW GLASS	1
843	2022-07-21	1500181	8300726	Retail	Operation	LO-430	check gearbox , rough gearshifts	0.35
844	2022-07-21	1500181	8300726	Retail	Operation	VO-3830500	K-factor, check	0.82
845	2022-07-21	1500181	8300726	Retail	Operation	LO-350	passenger bonnet indicator n/w	0.4
846	2022-07-21	1500181	8300726	Retail	Other	848	supply only missing chevron	
847	2022-07-21	1500181	8300726	Retail	Operation	LO-210	r/h /s engine welsch plugs leaking	3.25
848	2022-07-21	1500181	8300726	Retail	Part	VO-20503550	RUBBER CUSHION	1
849	2022-07-21	1500181	8300726	Retail	Part	VO-8131937	CAP PLUG	1
850	2022-07-21	1500181	8300726	Retail	Part	VO-24426721	CAP PLUG	1
851	2022-07-21	1500181	8300726	Retail	Part	VO-25162665	FASTNR,PANEL SP	1
852	2022-07-21	1500181	8300726	Retail	Part	VO-994847	WASHER M6*18	8

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
853	2022-07-21	1500181	8300726	Retail	Part	VO-984726	BOLT M6*20 FL	4
854	2022-07-21	1500181	8300726	Retail	Part	VO-990949	NUT M6 FL LOCKING	4
855	2022-07-21	1500181	8300726	Retail	Part	VO-23452020	CHEVRON L/HAND	1
856	2022-07-21	1500181	8300726	Retail	Part	VO-82717991	RUBBER MOULDING	1
857	2022-07-21	1500181	8300726	Retail	Part	AU2-AMP85112987	MACK VCS COOLANT 5LTR	1
858	2022-07-21	1500181	8300726	Retail	Other	91	WORKSHOP CONSUMABLES	
859	2022-04-30	1448022	3305946	Retail	Operation	VO-1774400	Basic service. Chassis lubrication and o	6.74
860	2022-04-30	1448022	3305946		Text		Chassis lubrication and oil changes included only in some	
861	2022-04-30	1448022	3305946	Retail	Other	1751300	Engine, oil and filter, replace. Lube	
862	2022-04-30	1448022	3305946	Retail	Other	2330600	Fuel filter, replace (one)	
863	2022-04-30	1448022	3305946	Retail	Other	2331100	Filter, water separator, replace	
864	2022-04-30	1448022	3305946	Retail	Other	5616600	Air drier cassette, replace	
865	2022-04-30	1448022	3305946	Retail	Other	1750400	Lubrication according to actual	
866	2022-04-30	1448022	3305946	Retail	Other	1751100	Lubrication of fifth wheel	
867	2022-04-30	1448022	3305946	Retail	Other	1784600	Trailer coupling, safety and function	
868	2022-04-30	1448022	3305946	Retail	Part	VO-85114535	FILTER KITS MP8/10	1
869	2022-04-30	1448022	3305946	Retail	Part	VO-85129688	AIR DRIER KIT	1
870	2022-04-30	1448022	3305946	Retail	Part	AU2-WUR0892333	WURTH BLITZ CLEANER	1
871	2022-04-30	1448022	3305946	Retail	Part	AU2-WUR089010810	BRAKE CLEANER 500ML	1
872	2022-04-30	1448022	3305946	Retail	Operation	LO-310	Rectify lights inop	0.75
873	2022-04-30	1448022	3305946	Retail	Operation	LO-211	Rectify chafed airline	0.25
874	2022-04-30	1448022	3305946	Retail	Operation	LO-212	Rectify loose shock bolts	0.25
875	2022-04-30	1448022	3305946	Retail	Other	94	Environmental Levy	
876	2022-04-30	1448022	3305946	Retail	Other	91	Workshop Consumables	
877	2022-04-11	0	8298540		Text		Repair without detail info	
878	2022-01-31	1403853	8296379	Retail	Other	M	PLEASE FILL IN	
879	2022-01-31	1403853	8296379		Text		Contact:JIM 0419 657 335	
880	2022-01-31	1403853	8296379	Retail	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
881	2022-01-31	1403853	8296379	Retail	Operation	VO-2331100	Filter, water separator, replace	0.3
882	2022-01-31	1403853	8296379	Retail	Operation	VO-2330600	Fuel filter, replace (one)	0.3
883	2022-01-31	1403853	8296379	Retail	Operation	VO-1774400	Basic service. Chassis lubrication and o	2.7
884	2022-01-31	1403853	8296379	Retail	Operation	LO-3000	rectify road speed sensor fault on dash	1
885	2022-01-31	1403853	8296379	Retail	Part	VO-24122024	SERVICE KIT	1
886	2022-01-31	1403853	8296379	Retail	Part	AU2-AMP23068346	VOLVO VDS 4.5 BULK	52
887	2022-01-31	1403853	8296379	Retail	Operation	LO-6000	CHECK ALL STEERING LINKS	3
888	2022-01-31	1403853	8296379	Retail	Operation	LO-600	SPRING PINS & BUSHERS NOT	0.25
889	2022-01-31	1403853	8296379	Retail	Part	AU2-WUR089010810	BRAKE CLEAN	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
890	2022-01-31	1403853	8296379	Retail	Part	VO-3963413	LOCK RING	1
891	2022-01-31	1403853	8296379	Retail	Part	VO-22387296	VEHICLE SPEED SENS	1
892	2022-01-31	1403853	8296379	Retail	Part	VO-23293811	TOP PLATE	1
893	2022-01-31	1403853	8296379	Retail	Operation	LO-260	REPLACE A/C HEATER HOSES ON FIREWALL	1.5
894	2022-01-31	1403853	8296379	Retail	Operation	LO-460	REPLACE BOTH DRIVE AXLE TOQUE RODS	1.75
895	2022-01-31	1403853	8296379	Retail	Operation	LO-250	HIGH COUNT OF EXHAUST BACK PRESSURE	1
896	2022-01-31	1403853	8296379	Retail	Operation	LO-640	STEERING SHAFT BOOT SPLIT	1
897	2022-01-31	1403853	8296379	Retail	Operation	LO-920	SECURE TRAILER SUZI COIL BRACKET ON	1.5
898	2022-01-31	1403853	8296379	Retail	Part	VO-21012932	HOSE SILICON 7/8"	2
899	2022-01-31	1403853	8296379	Retail	Part	VO-994559	HOSE CLAMP	4
900	2022-01-31	1403853	8296379	Retail	Part	VO-25164942	TORQUE ROD ASSY	2
901	2022-01-31	1403853	8296379	Retail	Part	VO-85139619	BACK PRESSURE SENSOR	1
902	2022-01-31	1403853	8296379	Retail	Part	VO-21582423	KIT	1
903	2022-01-31	1403853	8296379	Retail	Part	VO-85113736	GAITER	1
904	2022-01-31	1403853	8296379	Retail	Part	MK-NARV56406	CABLE TIE 1=100PK	1
905	2022-01-31	1403853	8296379	Retail	Part	AU2-AMP85112987	MACK VCS COOLANT 5LTR	1
906	2022-01-31	1403853	8296379	Retail	Part	VO-23359394	SHOCK ABSORBER	2
907	2022-01-31	1403853	8296379	Retail	Other	20	SUBLET - BOLT FOR SUMP BUNG	
908	2022-01-31	1403853	8296379	Retail	Part	VO-20734156	SEALING STRIP	1
909	2022-01-31	1403853	8296379	Retail	Part	AU2-CAL85121777	B/DOG ULTIMATE VDS4 5Ltr	1
910	2022-01-31	1403853	8296379	Retail	Other	97	ENVIRONMENTAL CHARGE	
911	2022-01-31	1403853	8296379	Retail	Other	91	WORKSHOP CONSUMABLES	
912	2021-10-11	0	8294386	Retail	Operation	LO-360	ice pack not working	0.8
913	2021-10-11	0	8294386		Text		check ice pack trace fault to blown fuse replace test ok	
914	2021-10-11	0	8294386	Retail	Operation	LO-560	air leak down on truck over night	2
915	2021-10-11	0	8294386	Internal	Operation	LO-210	engine running rough when oil is cold	1
916	2021-10-11	0	8294386	Retail	Part	VO-70301387	FUSE 150 AMP SCREW MOUNT	1
917	2021-10-11	0	8294386	Retail	Part	VO-23235129	AIR SPRING	2
918	2021-10-11	0	8294386	Retail	Part	VO-21035437	EXH FLEX 5" 200MM LONG	1
919	2021-10-11	0	8294386	Retail	Part	VO-8071883	CLAMP	2
920	2021-10-11	0	8294386	Retail	Other	91	WORKSHOP CONSUMABLES	
921	2021-09-27	0	8294704	Retail	Other	M	PLEASE FILL IN	
922	2021-09-27	0	8294704		Text		Contact:JIM 0419 657 335	
923	2021-09-27	0	8294704	Retail	Operation	LO-560	Air leak on truck	0.8
924	2021-09-27	0	8294704	Retail	Operation	LO-360	Batteries check and replace	2
925	2021-09-27	0	8294704	Retail	Operation	LO-810	bonnet spring missing	0.4
926	2021-09-27	0	8294704	Retail	Part	AU2-21209957	BULLDOG BATTERY N70	4

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
927	2021-09-27	0	8294704	Retail	Part	VO-21118098	SPRING	1
928	2021-09-27	0	8294704	Retail	Part	VO-25153781	VALVE	1
929	2021-09-27	0	8294704	Retail	Part	VO-FREIGHT	FREIGHT	45
930	2021-09-27	0	8294704	Retail	Other	91	WORKSHOP CONSUMABLES	
931	2021-09-27	1349240	8294111	Warranty	Operation	VO-2152200	Camshaft, replace	5.5
932	2021-09-27	1349240	8294111	Warranty	Part	VO-22431891	CAMSHAFT AND BEARI	1
933	2021-09-27	1349240	8294111	Warranty	Part	VO-21415409	ROCKER ARM	1
934	2021-09-27	1349240	8294111	Warranty	Part	VO-8192804	BOLT BIG END	6
935	2021-09-27	1349240	8294111	Warranty	Part	AU2-AMP23068346	VDS 4.5 ENGINE OIL BULK	52
936	2021-09-27	1349240	8294111	Warranty	Part	VO-24122024	SERVICE KIT	1
937	2021-09-27	1349240	8294111	Warranty	Part	VO-1677370	VEB SEALING RING	2
938	2021-09-27	1349240	8294111	Warranty	Part	VO-20526428	VEB SEAL RING	1
939	2021-09-27	1349240	8294111	Warranty	Part	VO-85000891	UNIT INJECTOR, EXC	1
940	2021-09-27	1349240	8294111	Warranty	Part	VO-21344774	BOLT M10*50 FL	1
941	2021-09-27	1349240	8294111	Warranty	Part	VO-21261987	GASKET	1
942	2021-09-27	1349240	8294111		Text		truck hard to start/ running rough	
943	2021-09-27	1349240	8294111	Warranty	Operation	VO-2146500	Rocker arm, replace (one)	0.4
944	2021-09-27	1349240	8294111	Warranty	Operation	VO-2378600	Engine injector and sleeve, replace (eac	0.6
945	2021-09-27	1349240	8294111	Warranty	Operation	VO-1701200	Fault codes, reading	0.2
946	2021-09-27	1349240	8294111	Warranty	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
947	2021-09-27	1349240	8294111	Warranty	Operation	VO-3710200	Electric wires and connections, check	0.4
948	2021-09-27	1349240	8294111	Warranty	Operation	VO-2301600	Cylinder balancing, check	0.2
949	2021-09-27	1349240	8294111	Warranty	Operation	VO-2840700	Sensor values, check	0.2
950	2021-09-27	1349240	8294111	Warranty	Operation	VO-2371200	Injector shut off, manual	0.2
951	2021-09-27	1349240	8294111	Warranty	Operation	LO-210	Cylinder Compression, test 21003	0.4
952	2021-09-27	1349240	8294111	Warranty	Operation	VO-1703000	Parameter, programming	0.1
953	2021-09-27	1349240	8294111	Warranty	Operation	LO-171	Road test 17105	0.5
954	2021-09-27	1349240	8294111	Warranty	Part	VO-21596644	CONTROL VALVE 12V	1
955	2021-09-27	1349240	8294111	Warranty	Operation	VO-2532000	Control valve VEB, replace	1.3
956	2021-08-04	1317856	3702390	Retail	Operation	VO-3641000	Direction indicator stalk switch, replac	0.6
957	2021-08-04	1317856	3702390		Text		replace	
958	2021-08-04	1317856	3702390	Retail	Part	VO-21793531	DIRECTION IND. SWI	1
959	2021-08-04	1317856	3702390	Retail	Part	VO-20971013	FLASHER CAN	1
960	2021-08-04	1317856	3702390	Retail	Other	91	Workshop Consumables	
961	2021-07-07	0	8292115	Retail	Other	M	PLEASE FILL IN	
962	2021-07-07	0	8292115		Text		Contact:JIM 0419 657 335	
963	2021-07-07	0	8292115	Retail	Operation	VO-1774400	Basic service. Chassis lubrication and o	2.7

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
964	2021-07-07	0	8292115	Retail	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
965	2021-07-07	0	8292115	Retail	Operation	VO-2331100	Filter, water separator, replace	0.3
966	2021-07-07	0	8292115	Retail	Operation	VO-2330600	Fuel filter, replace (one)	0.3
967	2021-07-07	0	8292115	Retail	Other	97	ENVIRONMENTAL CHARGE	
968	2021-07-07	0	8292115	Retail	Other	810	water coming through fire wall	
969	2021-07-07	0	8292115	Retail	Part	VO-85136742	FILTER KIT	1
970	2021-07-07	0	8292115	Retail	Part	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	52
971	2021-07-07	0	8292115	Retail	Other	91	WORKSHOP CONSUMABLES	
972	2021-06-28	0	8292021	Retail	Operation	LO-250	bottom elbow on exhuaast borken	2
973	2021-06-28	0	8292021	Retail	Part	VO-21827215	ELBOW	1
974	2021-06-28	0	8292021	Retail	Operation	LO-561	air system loosing air	4
975	2021-06-28	0	8292021	Retail	Part	MK-FT1869X6X6	ELBOW 3/8TU X 3/8TH	1
976	2021-06-28	0	8292021	Retail	Part	MK-FT1880X6X6	ELBOW 3/8TH X 3/8TU	1
977	2021-06-28	0	8292021	Retail	Part	VO-8071883	CLAMP	1
978	2021-06-28	0	8292021	Retail	Part	VO-20748450	VALVE KIT	1
979	2021-06-28	0	8292021		Text		29/6/21 4048 Audible air leak coming from foot brake valve	
980	2021-06-28	0	8292021	Retail	Part	VO-22646257	MANIFOLD	1
981	2021-06-28	0	8292021	Retail	Part	VO-22987428	MODULATOR	1
982	2021-06-28	0	8292021	Retail	Part	VO-20883065	OIL FILLER PIPE	1
983	2021-06-28	0	8292021	Retail	Part	VO-21780376	SEALING RING	1
984	2021-06-28	0	8292021	Retail	Other	210	ENGINE OIL FILLER PIPE CRACKED	
985	2021-06-28	0	8292021	Retail	Other	91	WORKSHOP CONSUMABLES	
986	2021-04-13	1254900	8290289	Retail	Operation	VO-1774600	Annual service. Chassis lubrication and	2.4
987	2021-04-13	1254900	8290289		Text		oil changes included only in some models	
988	2021-04-13	1254900	8290289	Retail	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
989	2021-04-13	1254900	8290289	Retail	Operation	VO-2331100	Filter, water separator, replace	0.3
990	2021-04-13	1254900	8290289	Retail	Operation	VO-2330600	Fuel filter, replace (one)	0.3
991	2021-04-13	1254900	8290289	Retail	Operation	VO-2141300	Valves and unit injectors, adjust	3
992	2021-04-13	1254900	8290289	Retail	Operation	LO-260	truck still useing coolant.	3.75
993	2021-04-13	1254900	8290289	Retail	Part	VO-85114535	FILTER KITS	1
994	2021-04-13	1254900	8290289	Retail	Part	VO-20579690	DOWDY WASHER	1
995	2021-04-13	1254900	8290289	Retail	Part	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	52
996	2021-04-13	1254900	8290289	Retail	Operation	LO-363	WIPEER BLADES REPLACE WIPER BLADES	0.25
997	2021-04-13	1254900	8290289	Retail	Other	363	WASHER JETS NOT WORKING	
998	2021-04-13	1254900	8290289	Retail	Operation	LO-561	AIR LEAKING AT TRANSMISSION AREA	0.25
999	2021-04-13	1254900	8290289	Retail	Operation	LO-251	EXHAUST LEAKING UNDER CAB	1
1000	2021-04-13	1254900	8290289	Retail	Part	VO-23017347	RADIATOR	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1001	2021-04-13	1254900	8290289	Retail	Part	VO-21637042	HOSE	2
1002	2021-04-13	1254900	8290289	Retail	Part	VO-23653292	RADIATOR	1
1003	2021-04-13	1254900	8290289	Retail	Part	MK-NARV56306	CABLE TIE 1=25PC	1
1004	2021-04-13	1254900	8290289	Retail	Part	VO-994795	SIX POINT SOCKET M6*16	1
1005	2021-04-13	1254900	8290289	Retail	Part	VO-990949	NUT M6 FL LOCKING	1
1006	2021-04-13	1254900	8290289	Retail	Part	VO-20399313	SPRING NUT	2
1007	2021-04-13	1254900	8290289	Retail	Part	VO-82710488	WIPER BLADE BASIC	2
1008	2021-04-13	1254900	8290289	Retail	Part	VO-21895024	EXHAUST PIPE	1
1009	2021-04-13	1254900	8290289	Retail	Part	VO-1629499	EXH CLAMP FH	3
1010	2021-04-13	1254900	8290289	Retail	Part	VO-990951	NUT M10 FL LOCKING	3
1011	2021-04-13	1254900	8290289	Retail	Part	VO-994195	BOLT M10*50 FL	3
1012	2021-04-13	1254900	8290289	Retail	Part	VO-994446	BOLT M8*20 FL GR8.8 THREAD LOC	4
1013	2021-04-13	1254900	8290289	Retail	Part	VO-994848	WASHER M8X22M	4
1014	2021-04-13	1254900	8290289	Retail	Part	VO-1675066	INT/COOL O-RING	1
1015	2021-04-13	1254900	8290289	Retail	Part	VO-21096684	SEALING RING	1
1016	2021-04-13	1254900	8290289	Retail	Part	VO-20544196	ELBOW NIPPLE	1
1017	2021-04-13	1254900	8290289	Retail	Part	VO-21166741	PIPE	1
1018	2021-04-13	1254900	8290289	Retail	Part	VO-1547252	SEALING RING	1
1019	2021-04-13	1254900	8290289	Retail	Part	AU2-CAL85108913	VOLVO VCS COOLANT 5 LT	1
1020	2021-04-13	1254900	8290289	Retail	Other	91	WORKSHOP CONSUMABLES	
1021	2021-04-08	0	3010679		Text		Repair without detail info	
1022	2021-04-07	0	3303057		Text		Repair without detail info	
1023	2021-03-26	1243185	3302981	Retail	Other	210	Rectify coolant leak	
1024	2021-03-26	1243185	3302981		Text		looses about 1L every 1000km's	
1025	2021-03-15	1234034	8289772	Retail	Operation	LO-561	compressor replace	4.6
1026	2021-03-15	1234034	8289772	Retail	Part	VO-85013937	EXCH COMPRESSOR	1
1027	2021-03-15	1234034	8289772	Retail	Part	VO-992065	O-RING	1
1028	2021-03-15	1234034	8289772	Retail	Part	VO-471708	SEAL RING	1
1029	2021-03-15	1234034	8289772	Retail	Part	AU2-WUR067485024C	EMRYCLTH 240	0.5
1030	2021-03-15	1234034	8289772	Retail	Part	AU2-WUR089010810	BRAKE CLEAN	1
1031	2021-03-15	1234034	8289772	Retail	Part	MK-NARV56306	CABLE TIE 1=25PC	1
1032	2021-03-15	1234034	8289772	Retail	Part	VO-20532891	GASKET	1
1033	2021-03-15	1234034	8289772	Retail	Part	VO-20723207	SEALING RING	1
1034	2021-03-15	1234034	8289772	Retail	Part	MK-NARV56310	CABLE TIE 1=10PC	1
1035	2021-03-15	1234034	8289772		Text		test compressor for passing air into	
1036	2021-03-15	1234034	8289772	Retail	Other	91	WORKSHOP CONSUMABLES	
1037	2021-03-12	1234012	8289602	Retail	Operation	LO-261	COOLING SYSTEM LOOSING COOLANT	2.5

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1038	2021-03-12	1234012	8289602	Retail	Operation	LO-170	GREASE ALL POINTS	1
1039	2021-03-12	1234012	8289602	Retail	Part	AU2-CAL85112987	BULLDOG VCS COOLANT 5LT	1
1040	2021-03-12	1234012	8289602		Text		Compressor over pressurising	
1041	2021-03-12	1234012	8289602	Retail	Other	91	WORKSHOP CONSUMABLES	
1042	2021-01-07	1192003	8288178	Retail	Other	M	JIM 0419 657 335	
1043	2021-01-07	1192003	8288178	Retail	Operation	LO-430	TRAILER DETECTION N/W, SWITCH	4
1044	2021-01-07	1192003	8288178	Retail	Operation	LO-870	replace a/c cab blower fan	0.58
1045	2021-01-07	1192003	8288178	Retail	Operation	VO-1774400	Basic service. Chassis lubrication and o	2.7
1046	2021-01-07	1192003	8288178		Text		oil changes included only in some models	
1047	2021-01-07	1192003	8288178	Retail	Operation	LO-252	exhaust stack rattle D/S if bushes worn	3.09
1048	2021-01-07	1192003	8288178	Retail	Part	VO-25625288	KEY, IGNITION BLAN	3
1049	2021-01-07	1192003	8288178	Retail	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
1050	2021-01-07	1192003	8288178	Retail	Operation	VO-2330600	Fuel filter, replace (one)	0.3
1051	2021-01-07	1192003	8288178	Retail	Operation	VO-2331100	Filter, water separator, replace	0.3
1052	2021-01-07	1192003	8288178	Retail	Part	VO-85114535	FILTER KITS	1
1053	2021-01-07	1192003	8288178	Retail	Part	VO-20579690	DOWDY WASHER	1
1054	2021-01-07	1192003	8288178	Retail	Part	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	52
1055	2021-01-07	1192003	8288178	Retail	Part	VO-85113771	BLOWER MOTOR	1
1056	2021-01-07	1192003	8288178	Retail	Part	VO-85151124	CAB FILTER	1
1057	2021-01-07	1192003	8288178	Retail	Part	VO-8397718	FITTING	1
1058	2021-01-07	1192003	8288178	Retail	Part	MK-FT3220X4X2	BRASS PIPE	1
1059	2021-01-07	1192003	8288178	Retail	Part	VO-20489118	PRESSURE SW	1
1060	2021-01-07	1192003	8288178	Retail	Part	VO-85115768	RESISTOR	1
1061	2021-01-07	1192003	8288178	Retail	Part	MK-3543-H9618	CONTROL	1
1062	2021-01-07	1192003	8288178	Retail	Part	VO-21827215	ELBOW	1
1063	2021-01-07	1192003	8288178	Retail	Part	VO-22210736	BUSHING	4
1064	2021-01-07	1192003	8288178	Retail	Part	VO-8071883	CLAMP	2
1065	2021-01-07	1192003	8288178	Retail	Part	AU2-WUR067320501C	BROWN LOC 2"	2
1066	2021-01-07	1192003	8288178	Retail	Part	VO-21687997	WASHER	1
1067	2021-01-07	1192003	8288178	Retail	Part	AU2-CAL85121777	B/DOG ULTIMATE VDS4 5Ltr	1
1068	2021-01-07	1192003	8288178	Retail	Other	97	ENVIRONMENTAL CHARGE	
1069	2021-01-07	1192003	8288178	Retail	Other	91	WORKSHOP CONSUMABLES	
1070	2020-12-01	1181861	8287463	Warranty	Operation	VO-4317500	Range gear, overhaul. Unit removed	2.4
1071	2020-12-01	1181861	8287463		Text		Check for gearbox noise, carry out road test, found	
1072	2020-12-01	1181861	8287463	Warranty	Operation	VO-4317000	Gearbox, remove	1.2
1073	2020-12-01	1181861	8287463	Warranty	Operation	VO-4317200	Gearbox, install	2.3
1074	2020-12-01	1181861	8287463	Warranty	Operation	VO-4315700	Range gear, install. Gearbox removed	0.8

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1075	2020-12-01	1181861	8287463	Warranty	Operation	VO-4010500	Gearbox, calibration. Gearbox removed	0.2
1076	2020-12-01	1181861	8287463	Warranty	Operation	VO-4010400	Gearbox, calibration	0.3
1077	2020-12-01	1181861	8287463	Warranty	Operation	VO-4001500	Range cylinder, test	0.2
1078	2020-12-01	1181861	8287463	Warranty	Operation	VO-4002000	Gears, test	0.2
1079	2020-12-01	1181861	8287463	Warranty	Operation	VO-4007000	Gearbox, clutch, engagement point, calib	0.2
1080	2020-12-01	1181861	8287463	Warranty	Operation	LO-170	Take charge, road test	0.5
1081	2020-11-24	1181861	8287200	Retail	Operation	LO-430	MALFUNCTION LIGHT ON DASH	7
1082	2020-11-24	1181861	8287200		Text		WHEN TRANS SELECT REVERSE	
1083	2020-11-24	1181861	8287200	Retail	Other	825	R/H FRONT STEER	
1084	2020-11-24	1181861	8287200	Retail	Part	VO-1161963	RUBBER GREASE	1
1085	2020-11-24	1181861	8287200	Retail	Part	MK-NARV56306	CABLE TIE 1=25PC	1
1086	2020-11-24	1181861	8287200	Retail	Part	AU2-WUR089010810	BRAKE CLEAN	2
1087	2020-11-24	1181861	8287200	Retail	Operation	LO-4333401	Replace Transmission	7
1088	2020-11-24	1181861	8287200	Retail	Part	VO-85020579	EXCH GEARBOX	1
1089	2020-11-24	1181861	8287200	Retail	Operation	LO-250	WELD SCR MUFFLER HEAT SHEILD BRACKET	3
1090	2020-11-24	1181861	8287200	Retail	Part	VO-23701845	OIL HOSE	1
1091	2020-11-24	1181861	8287200	Retail	Part	VO-23701846	OIL HOSE	1
1092	2020-11-24	1181861	8287200	Retail	Part	MK-NARV56310	CABLE TIE 1=10PC	1
1093	2020-11-24	1181861	8287200	Retail	Part	MK-2104-2507018X	KIT BRG RETAINER SPL250	1
1094	2020-11-24	1181861	8287200	Retail	Part	VO-994102	BOLT M14*48 THREAD LOC GR10.9	4
1095	2020-11-24	1181861	8287200	Retail	Part	VO-25339078	NUT M14 FINE PITCH	4
1096	2020-11-24	1181861	8287200	Retail	Other	91	WORKSHOP CONSUMABLES	
1097	2020-11-16	117807	3841146	Retail	Operation	LO-219	Low On Power	1
1098	2020-11-16	117807	3841146		Text		Fault found for back pressure and Low Adblue.	
1099	2020-11-16	117807	3841146	Retail	Part	MK-9711-00116M3	HUBCAP	1
1100	2020-11-16	117807	3841146	Retail	Other	91	Workshop Consumables	
1101	2020-10-07	1151140	7609454	Retail	Operation	VO-1774400	Basic service. Chassis lubrication and o	5
1102	2020-10-07	1151140	7609454		Text		-Carried out basic service as required	
1103	2020-10-07	1151140	7609454	Retail	Other	23306	Fuel filter, replace (one).	
1104	2020-10-07	1151140	7609454	Retail	Operation	VO-1750400	Lubrication according to actual lubricat	0.3
1105	2020-10-07	1151140	7609454	Retail	Other	1751300	Engine, oil and filter, replace. Lube	
1106	2020-10-07	1151140	7609454	Retail	Other	7714500	Wheel nuts, check tightening (all)	
1107	2020-10-07	1151140	7609454	Retail	Other	2331100	Filter, water separator, replace	
1108	2020-10-07	1151140	7609454	Retail	Operation	VO-1751100	Lubrication of fifth wheel	0.1
1109	2020-10-07	1151140	7609454	Retail	Operation	LO-560	AIR LEAK AT WALK PLATE AREA	1
1110	2020-10-07	1151140	7609454	Retail	Part	VO-85114535	FILTER KIT - NEW BREED	1
1111	2020-10-07	1151140	7609454	Retail	Part	VO-20579690	GASKET	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1112	2020-10-07	1151140	7609454	Retail	Part	VO-23448457	OIL SAMPLING KITX1	1
1113	2020-10-07	1151140	7609454	Retail	Part	VO-25152776	NYLON TUBE 1/2 BLACK	1
1114	2020-10-07	1151140	7609454	Retail	Part	MK-FT1862X8	JOINER 1/2 PUSH	1
1115	2020-10-07	1151140	7609454	Retail	Part	AU2-CAL85121715	BULK 85W140 GEAR OIL VOLVO	0
1116	2020-10-07	1151140	7609454	Retail	Part	AU2-CAL85121795	BULK VDS4 ENGINE OIL 15W-40	70
1117	2020-10-07	1151140	7609454	Retail	Operation	LO-234	SPINF FUEL CROSS OVER LINE	0.25
1118	2020-10-07	1151140	7609454	Internal	Part	VO-21780376	SEALING RING	1
1119	2020-10-07	1151140	7609454	Retail	Other	91	WORKSHOP CONSUMABLES	
1120	2020-08-10	1120820	8284804	Retail	Operation	LO-170	CARRY OUT ENGINE OIL SAMPLE	0.25
1121	2020-08-10	1120820	8284804	Retail	Part	VO-23448457	OIL SAMPLING KIT	1
1122	2020-08-10	1120820	8284804	Retail	Other	91	WORKSHOP CONSUMABLES	
1123	2020-07-20	111407	8284246	Retail	Operation	LO-6000	steer unies have movement	1.5
1124	2020-07-20	111407	8284246	Retail	Operation	LO-461	1st drive input yoke loose?	3
1125	2020-07-20	111407	8284246	Retail	Part	MK-8235-A11205X272	SEAL PINION INPUT FORWARD	1
1126	2020-07-20	111407	8284246	Retail	Part	MK-8235-KIT2638	NUT, PINION RT40	1
1127	2020-07-20	111407	8284246	Retail	Part	VO-85113737	BEARING KIT	3
1128	2020-07-20	111407	8284246	Retail	Part	VO-84727009	BEARING	1
1129	2020-07-20	111407	8284246	Retail	Part	MK-D50681261R	KIT SHOE STEER 472	2
1130	2020-07-20	111407	8284246	Retail	Part	VO-20967831	BEARING	2
1131	2020-07-20	111407	8284246	Retail	Operation	LO-810	bonnet needs adjusting hitting r/h/s	0.5
1132	2020-07-20	111407	8284246	Retail	Part	MK-2104-2507018X	KIT BRG RETAINER SPL250	1
1133	2020-07-20	111407	8284246	Retail	Part	VO-3986189	O-RING	1
1134	2020-07-20	111407	8284246	Retail	Part	MK-8235-KSMA21247	KIT SHOE STEER 6"	2
1135	2020-07-20	111407	8284246	Retail	Part	UNK-NTH626476TB	55.244 BRAKE DRUM	2
1136	2020-07-20	111407	8284246	Retail	Part	AU2-WUR089010810	BRAKE CLEAN	2
1137	2020-07-20	111407	8284246		Text		REMOVED STEERING SHAFT	
1138	2020-07-20	111407	8284246	Retail	Part	VO-82710488	WIPER BLADE BASIC	2
1139	2020-07-20	111407	8284246	Retail	Other	91	WORKSHOP CONSUMABLES	
1140	2020-07-07	1104816	8283886	Retail	Operation	VO-1774400	Basic service. Chassis lubrication and o	2.7
1141	2020-07-07	1104816	8283886		Text		oil changes included only in some models	
1142	2020-07-07	1104816	8283886	Retail	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
1143	2020-07-07	1104816	8283886	Retail	Operation	LO-23306	Fuel filter, replace (one).	0.3
1144	2020-07-07	1104816	8283886	Retail	Operation	VO-2331100	Filter, water separator, replace	0.3
1145	2020-07-07	1104816	8283886	Retail	Part	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	50
1146	2020-07-07	1104816	8283886	Retail	Part	VO-85114535	FILTER KITS	1
1147	2020-07-07	1104816	8283886	Retail	Part	VO-20579690	DOWDY WASHER	1
1148	2020-07-07	1104816	8283886	Retail	Part	VO-23448457	OIL SAMPLING KIT	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1149	2020-07-07	1104816	8283886	Retail	Part	AU2-4381-2559	LED LIC/PLATE LAMP	1
1150	2020-07-07	1104816	8283886	Retail	Other	17	Part Supplied	
1151	2020-07-07	1104816	8283886	Retail	Other	91	WORKSHOP CONSUMABLES	
1152	2020-07-01	110314	8283808	Retail	Operation	LO-210	CHECKING ALL COOLANT HOSES	3
1153	2020-07-01	110314	8283808		Text		CONDITION OF HOSES REPLACE AS REQUIRED	
1154	2020-07-01	110314	8283808	Retail	Operation	LO-170	CARRY OUT INSPECTION ON ENGINE	1
1155	2020-07-01	110314	8283808	Retail	Part	VO-21339891	RUBBER HOSE	1
1156	2020-07-01	110314	8283808	Retail	Part	VO-21380391	CONNECTOR 45 deg	1
1157	2020-07-01	110314	8283808	Retail	Part	VO-994557	HOSE CLAMP 15mm-24mm	6
1158	2020-07-01	110314	8283808	Retail	Part	VO-947281	COPPER WASHER can use 957173	1
1159	2020-07-01	110314	8283808	Retail	Part	VO-20938685	CONNECTOR 90deg	1
1160	2020-07-01	110314	8283808	Retail	Part	VO-21503575	SEALING RING	1
1161	2020-07-01	110314	8283808	Retail	Part	AU2-WUR089010810	BRAKE CLEAN	1
1162	2020-07-01	110314	8283808	Retail	Part	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	5
1163	2020-07-01	110314	8283808	Retail	Other	91	WORKSHOP CONSUMABLES	
1164	2020-06-24	1096927	214508		Text		JAQUAR TRANSPORT	
1165	2020-06-24	1096927	214508	Retail	Operation	LO-260	HOSE HAS BLOWN ON COOLING SYS	5.35
1166	2020-06-24	1096927	214508	Retail	Other	92	KM CHARGE	
1167	2020-06-24	1096927	214508	Retail	Operation	LO-100	TRAVEL	1.5
1168	2020-06-24	1096927	214508	Retail	Part	VO-21637042	HOSE	2
1169	2020-06-24	1096927	214508	Retail	Part	OTH-HCLAMP	HOSE CLAMP	4
1170	2020-06-24	1096927	214508	Retail	Part	AU2-CAL85112988	BULLDOG VCS COOLAN	2
1171	2020-06-24	1096927	214508	Retail	Other	91	Workshop Consumables & Enviromental Levy	
1172	2020-06-17	1092328	3005451	Retail	Operation	VO-2610700	Radiator hose, replace (upper). Coolant	3
1173	2020-06-17	1092328	3005451		Text		drained	
1174	2020-06-17	1092328	3005451	Retail	Other	90	CALLOUT AFTERHOURS FEE	
1175	2020-06-17	1092328	3005451	Retail	Part	VO-22891920	TOP RADIATOR HOSE	1
1176	2020-06-17	1092328	3005451	Retail	Part	VO-22891932	HOSE RADIATOR	1
1177	2020-06-17	1092328	3005451	Retail	Part	VO-22891922	HOSE	1
1178	2020-06-17	1092328	3005451	Retail	Part	AU2-CAL8394800	VCS COOLANT 20L	1
1179	2020-06-17	1092328	3005451	Retail	Other	91	Workshop Consumables	
1180	2020-06-09	1086804	8283303	Retail	Operation	LO-350	INDINCATORS NOT WORKING	1
1181	2020-06-09	1086804	8283303		Text		Removed & replaced indicator stick and relay	
1182	2020-06-09	1086804	8283303	Retail	Part	VO-21793531	DIRECTION IND. SWI	1
1183	2020-06-09	1086804	8283303	Retail	Part	VO-22526557	FLASHER RELAY	1
1184	2020-06-09	1086804	8283303	Retail	Other	91	WORKSHOP CONSUMABLES	
1185	2020-06-04	1085034	3840421	Warranty	Operation	VO-2123100	Core plug, replace	0.2

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1186	2020-06-04	1085034	3840421	Warranty	Part	AU2-CAL85112988	BULLDOG VCS 20L COOLANT	2
1187	2020-06-04	1085034	3840421	Warranty	Part	VO-1547252	SEALING RING	2
1188	2020-06-04	1085034	3840421	Warranty	Part	VO-984732	FLANGE SCREW	1
1189	2020-06-04	1085034	3840421	Warranty	Part	VO-20845995	PLUG	1
1190	2020-06-04	1085034	3840421	Warranty	Part	VO-1546531	LOCK BRACE	1
1191	2020-06-04	1085034	3840421		Text		Travel to vehicle, 170 km round trip.	
1192	2020-06-04	1085034	3840421	Warranty	Operation	VO-2601000	Coolant, change	0.4
1193	2020-06-04	1085034	3840421	Warranty	Operation	VO-2600600	Coolant system, pressure test	0.4
1194	2020-06-04	1085034	3840421	Warranty	Other	92	TRAVEL 170 km Ö Å0.98 p/km	
1195	2020-06-04	1085034	3840421	Warranty	Operation	LO-194	Travel Time to Breakdown	2
1196	2020-01-13	164325	7021588	Retail	Operation	LO-170	CARRY OUT "B" SERVICE	4
1197	2020-01-13	164325	7021588	Retail	Other	8187100	REPLACE FRONT CAB MOUNTS	
1198	2020-01-13	164325	7021588		Text		***IF TIME PERMITS***	
1199	2020-01-13	164325	7021588	Retail	Other	4000	CHANGE TRANSMISSION OIL AND FILTER	
1200	2020-01-13	164325	7021588	Retail	Operation	LO-468	CHANGE DIFF OIL AND FILTER	1
1201	2020-01-13	164325	7021588	Retail	Part	VO-85114535	FILTER KIT MP10 MP8	1
1202	2020-01-13	164325	7021588	Retail	Part	OTH-MT001	DEGREASER	1
1203	2020-01-13	164325	7021588	Retail	Part	VO-20779040	OIL FILTER I-SHIFT	1
1204	2020-01-13	164325	7021588	Retail	Part	MK-8235-A3380W168	DIFF FILTER	1
1205	2020-01-13	164325	7021588	Retail	Operation	VO-1752000	Oil filter, gearbox, change (on floor)	0.75
1206	2020-01-13	164325	7021588	Retail	Operation	VO-2450500	Oil filter, replace	0.1
1207	2020-01-13	164325	7021588	Retail	Part	AU2-CAL85121774LTF	VDS4 ENGINE OIL 15W40	52
1208	2020-01-13	164325	7021588	Retail	Part	AU2-CAL85136279	SYNTHETIC DIFF OIL 97312 20L	2
1209	2020-01-13	164325	7021588	Retail	Part	AU2-CAL85107476	97315 SYNTH GEARBOX OIL 20L	1
1210	2020-01-13	164325	7021588	Retail	Part	VO-20975430	CAB MOUNT SUPPORT 17.5mm HOLE	2
1211	2020-01-13	164325	7021588	Retail	Other	91	WORKSHOP CONSUMABLES	
1212	2020-01-06	1058403	8279314	Retail	Operation	LO-258	EMISSION FAULT ON DASH	2
1213	2020-01-06	1058403	8279314	Retail	Part	VO-22303391	SENSOR	1
1214	2020-01-06	1058403	8279314		Text		CONNECT LAP TOP READ FAULT TABLE	
1215	2020-01-06	1058403	8279314	Retail	Other	91	WORKSHOP CONSUMABLES	
1216	2020-01-03	1058275	8279297	Retail	Operation	LO-311	CARRY OUT JUMP START	0.9
1217	2020-01-03	1058275	8279297	Retail	Other	19400	TRAVEL TO VEHICLE AT	
1218	2020-01-03	1058275	8279297		Text		CULLEN AVE OUTSIDE COLONIAL WAREHOUSE	
1219	2020-01-03	1058275	8279297	Retail	Other	92	UTE MILEAGE km's Ö Å1.48/km.	
1220	2020-01-03	1058275	8279297	Retail	Other	91	WORKSHOP CONSUMABLES	
1221	2019-12-08	105728	3002507	Retail	Operation	VO-8765700	Coolant pipe auxiliary heater, replace	4
1222	2019-12-08	105728	3002507		Text		CALL OUT AFTER HOURS - HEATER HOSE SPLIT.	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1223	2019-12-08	105728	3002507	Retail	Part	OTH-CALLOUT	PARTS CALLOUT	1
1224	2019-12-08	105728	3002507	Retail	Part	MK-TIE80088	7/8" SILICONE HOSE	2
1225	2019-12-08	105728	3002507	Retail	Part	AU2-CAL8394800	VCS COOLANT 20L	1
1226	2019-12-08	105728	3002507	Retail	Other	90	CALLOUT AFTERHOURS FEE	
1227	2019-12-08	105728	3002507	Retail	Other	91	Workshop Consumables	
1228	2019-12-05	1049317	8531143	Retail	Operation	VO-2562700	Filter insert, air cleaner, replace. Ont	0.2
1229	2019-12-05	1049317	8531143	Retail	Operation	VO-2341400	Filter for fuel tank ventilation, replac	0.4
1230	2019-12-05	1049317	8531143	Retail	Operation	LO-17504	Grease chassis	0.4
1231	2019-12-05	1049317	8531143	Retail	Operation	VO-7714500	Wheel nuts, check tightening (all)	0.3
1232	2019-12-05	1049317	8531143	Retail	Operation	VO-6452500	Oil filter, power steering, replace	0.2
1233	2019-12-05	1049317	8531143		Text		-NEXT Service due at 1064000km's	
1234	2019-12-05	1049317	8531143	Retail	Other	210	Exhaust muffler cover	
1235	2019-12-05	1049317	8531143	Retail	Part	VO-984734	FLANGE SCREW-M8X20	8
1236	2019-12-05	1049317	8531143	Retail	Part	VO-22663394	HEAT SHIELD	1
1237	2019-12-05	1049317	8531143	Retail	Part	VO-22663387	HEAT SHIELD	1
1238	2019-12-05	1049317	8531143	Retail	Part	VO-22663400	ATTACHING BRACKET	2
1239	2019-12-05	1049317	8531143	Retail	Part	OTH-9727-3335281R	GREASE, BULK W/SHOP PREMIUM	2
1240	2019-12-05	1049317	8531143	Retail	Part	MK-5839-870678A	FILTER P/STR GRAN	1
1241	2019-12-05	1049317	8531143	Retail	Part	VO-995054	SIX POINT SOCKET S	8
1242	2019-12-05	1049317	8531143	Retail	Part	VO-FREIGHT	FREIGHT	4.5
1243	2019-12-05	1049317	8531143	Retail	Part	VO-21743197	AIR CLEANER	2
1244	2019-12-05	1049317	8531143	Retail	Other	91	WORKSHOP CONSUMABLES	
1245	2019-11-05	0	8277696		Text		Repair without detail info	
1246	2019-10-28	1026382	8277411	Retail	Operation	LO-5000	DEFECT NOTICE (ATTACHED)	2
1247	2019-10-28	1026382	8277411		Text		CEASE USE LIFTED WHEN BRAKES ARE REPAIRED	
1248	2019-10-28	1026382	8277411	Retail	Operation	LO-350	RECTIFY MIDDLE CAB LIGHT DULL	0.3
1249	2019-10-28	1026382	8277411	Retail	Part	VO-25109292	LAMP	1
1250	2019-10-28	1026382	8277411	Retail	Other	91	WORKSHOP CONSUMABLES	
1251	2019-10-17	1021167	8530754	Retail	Operation	LO-260	RECTIFY COOLANT LEAK	1.03
1252	2019-10-17	1021167	8530754	Retail	Part	VO-23059017	EXPANSION TANK	1
1253	2019-10-17	1021167	8530754		Text		Complaint: Rectify coolant leak.	
1254	2019-10-17	1021167	8530754	Retail	Other	91	WORKSHOP CONSUMABLES	
1255	2019-10-17	1021167	8530738	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
1256	2019-10-17	1021167	8530738	Internal	Operation	LO-210	Cab transvers rod bolts breaking	3.25
1257	2019-10-17	1021167	8530738		Text		oil changes included only in some models	
1258	2019-10-17	1021167	8530738	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
1259	2019-10-17	1021167	8530738	Contract	Operation	VO-2330600	Fuel filter, replace (one)	0.2

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1260	2019-10-17	1021167	8530738	Contract	Operation	VO-2331100	Filter, water separator, replace	0.2
1261	2019-10-17	1021167	8530738	Contract	Operation	VO-1750400	Lubrication according to actual lubricat	0.3
1262	2019-10-17	1021167	8530738	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
1263	2019-10-17	1021167	8530738	Contract	Part	AU2-CAL85121795	VDS4 BULK ENG 1LTR	52
1264	2019-10-17	1021167	8530738	Contract	Part	VO-85114535	FILTER KITS MP8/10	1
1265	2019-10-17	1021167	8530738	Internal	Part	OTH-9727-3335281R	GREASE, BULK W/SHOP PREMIUM	1
1266	2019-10-17	1021167	8530738	Contract	Part	AU2-WUR0892333	WURTH BLITZ CLEANER	1
1267	2019-10-17	1021167	8530738	Internal	Part	AU2-WUR089010810	BRAKE CLEANER 500ML	1
1268	2019-10-17	1021167	8530738	Internal	Other	50	drill out bracket.	
1269	2019-10-17	1021167	8530738	Internal	Part	OTH-MSFM16X260	m16x260 BOLT	2
1270	2019-10-17	1021167	8530738	Internal	Part	VO-FREIGHT	FREIGHT	1.5
1271	2019-10-17	1021167	8530738	Internal	Part	VO-60113330	WASHER	2
1272	2019-10-17	1021167	8530738	Contract	Other	WTY-NONGEN	Grease used during service	
1273	2019-09-02	1005128	8276013	Retail	Operation	LO-3000	MALFUNCTION LIGHT CAME UP ON DASH	1
1274	2019-09-02	1005128	8276013		Text		SPEEDO DROPE OUT	
1275	2019-09-02	1005128	8276013	Retail	Part	VO-22387296	VEHICLE SPEED SENS	1
1276	2019-09-02	1005128	8276013	Retail	Operation	LO-260	RECTIFY COOLANT LEAK FROM HEADER	0.4
1277	2019-09-02	1005128	8276013	Retail	Part	VO-21053055	HOSE,COOLANT	1
1278	2019-09-02	1005128	8276013	Retail	Other	91	WORKSHOP CONSUMABLES	
1279	2019-08-12	994942	8275472	Retail	Operation	VO-2618800	Pipe, coolant pump inlet, replace	2.95
1280	2019-08-12	994942	8275472		Text		PRESSURE TEST COOLING SYSTEM FINDING	
1281	2019-08-12	994942	8275472	Retail	Part	VO-21420336	CONNECTING PIPE	1
1282	2019-08-12	994942	8275472	Retail	Part	VO-21423788	SEALING RING	1
1283	2019-08-12	994942	8275472	Retail	Part	VO-20799996	SEALING RING	1
1284	2019-08-12	994942	8275472	Retail	Part	VO-8073055	O-RING	1
1285	2019-08-12	994942	8275472	Retail	Part	AU2-CAL85112988	BULLDOG VCS 20L	2
1286	2019-08-12	994942	8275472	Retail	Part	AU2-CAL85112987	BULLDOG VCS COOLANT 5LT	2
1287	2019-08-12	994942	8275472	Retail	Part	VO-FREIGHT	FREIGHT	80
1288	2019-08-12	994942	8275472	Retail	Other	91	WORKSHOP CONSUMABLES	
1289	2019-07-25	984812	7594889	Internal	Operation	LO-461	replace front drive shocks-supplied	0.6
1290	2019-07-25	984812	7594889	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	1.3
1291	2019-07-25	984812	7594889		Text		oil changes included only in some models	
1292	2019-07-25	984812	7594889	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
1293	2019-07-25	984812	7594889	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
1294	2019-07-25	984812	7594889	Contract	Operation	LO-23306	Fuel filter, replace (one).	0.3
1295	2019-07-25	984812	7594889	Contract	Operation	VO-1751100	Lubrication of fifth wheel	0.1
1296	2019-07-25	984812	7594889	Contract	Operation	LO-17504	O Service	0.3

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1297	2019-07-25	984812	7594889	Contract	Part	VO-85114535	FILTER KIT - NEW BREED	1
1298	2019-07-25	984812	7594889	Contract	Part	VO-20579690	GASKET	1
1299	2019-07-25	984812	7594889	Contract	Operation	VO-3212300	Alternator belt, replace	0.4
1300	2019-07-25	984812	7594889	Contract	Operation	VO-2601000	Coolant, change	0.4
1301	2019-07-25	984812	7594889	Contract	Other	2630700	Drive belts fan, replace	
1302	2019-07-25	984812	7594889	Contract	Operation	VO-1758900	Lubrication of trailer hitch	0.1
1303	2019-07-25	984812	7594889	Contract	Part	VO-22950621	V-RIBBED BELT 8PK	1
1304	2019-07-25	984812	7594889	Contract	Part	AU2-CAL85112988	COOLANT 20L VCS BULLDOG	2
1305	2019-07-25	984812	7594889	Contract	Part	VO-22950564	V-RIBBED BELT 10PK	1
1306	2019-07-25	984812	7594889	Internal	Part	MK-NARV47501	GLOBE 1=10PK 12V 5	0.1
1307	2019-07-25	984812	7594889	Contract	Part	AU2-CAL85121795	BULK VDS4 ENGINE OIL 15W-40	42
1308	2019-07-25	984812	7594889	Internal	Part	VO-990996	BOLT M16*150 FLANGE 10.9G	1
1309	2019-07-25	984812	7594889	Internal	Part	VO-994527	LOCK NUT M16 FLANGE	1
1310	2019-07-10	976010	8529918	Contract	Operation	LO-17504	Lubrication according to actual lubricat	0.3
1311	2019-07-10	976010	8529918		Text		Next service due 990 000km's	
1312	2019-07-10	976010	8529918	Internal	Part	MK-FT1868X6X6	CON	1
1313	2019-07-10	976010	8529918	Internal	Operation	LO-561	Air leak at fire wall / defect list	1
1314	2019-06-21	970852	R08017660	Warranty	Operation	VO-4510000		1.3
1315	2019-06-21	970852	R08017660	Warranty	Operation	VO-4650000	SPL250 Driveshaft, Inspection	0.2
1316	2019-06-21	970852	R08017660	Warranty	Part	MK-2104-2507018X	KIT BRG RETAINER S	1
1317	2019-06-21	970852	R08017660	Warranty	Part	MK-8235-A11205X272	SEAL PINION INPUT	1
1318	2019-06-21	970852	R08017660	Warranty	Part	MK-8235-KIT2638	NUT, PINION RT40	1
1319	2019-06-21	970852	R08017660	Warranty	Part	VO-22826772	END YOKE	1
1320	2019-05-30	957895	8529554	Retail	Operation	LO-210	Rectify cab panard bolt broken	8.25
1321	2019-05-30	957895	8529554		Text		Removed lower bracket and removed broken bolt.	
1322	2019-05-30	957895	8529554	Retail	Part	VO-60113330	WASHER	2
1323	2019-05-30	957895	8529554	Retail	Part	OTH-MSFM16X260	m16x260 BOLT	1
1324	2019-05-30	957895	8529554	Retail	Other	20	Sublet Drill cab bracket through	
1325	2019-05-30	957895	8529554	Retail	Other	91	WORKSHOP CONSUMABLES	
1326	2019-04-30	945011	8116105	Retail	Other	M	PLEASE FILL IN	
1327	2019-04-30	945011	8116105		Text		Contact:Jimmy 0419 657 335	
1328	2019-04-30	945011	8116105	Contract	Operation	VO-1774600	Annual service	2.4
1329	2019-04-30	945011	8116105	Contract	Other	23306	Fuel filter, replace (one).	
1330	2019-04-30	945011	8116105	Contract	Operation	VO-1750400	Lubrication according to actual lubricat	0.3
1331	2019-04-30	945011	8116105	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
1332	2019-04-30	945011	8116105	Contract	Operation	VO-7714500	Wheel nuts, check tightening (all)	0.3
1333	2019-04-30	945011	8116105	Contract	Other	2331100	Filter, water separator, replace	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1334	2019-04-30	945011	8116105	Contract	Operation	VO-2582200	Filter, AdBlue, replace	0.3
1335	2019-04-30	945011	8116105	Contract	Operation	VO-5612600	Air drier, drier insert, replace	0.4
1336	2019-04-30	945011	8116105	Contract	Operation	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.4
1337	2019-04-30	945011	8116105	Contract	Operation	VO-1752700	Final drive oil, change. Lube area	0.2
1338	2019-04-30	945011	8116105	Retail	Operation	LO-4000	Adjust vehilce take off gear to 2nd	0.5
1339	2019-04-30	945011	8116105	Retail	Other	170	excessive fuel burn check and report.	
1340	2019-04-30	945011	8116105	Retail	Operation	LO-350	clearance light out on roof.	0.25
1341	2019-04-30	945011	8116105	Retail	Other	270	Cruise control fault. Jimmy will talk to	
1342	2019-04-30	945011	8116105	Retail	Other	714	firth wheel inspection certificate	
1343	2019-04-30	945011	8116105	Contract	Operation	VO-2141300	Valves and unit injectors, adjust	2.5
1344	2019-04-30	945011	8116105	Contract	Part	VO-85114535	Filter Kit - MP8/MP10	1
1345	2019-04-30	945011	8116105	Contract	Part	VO-20579690	DOWTY WASHER O.D. 33mm	1
1346	2019-04-30	945011	8116105	Contract	Part	AU2-CAL85121795	ENGINE OIL BULK*	52
1347	2019-04-30	945011	8116105	Internal	Part	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
1348	2019-04-30	945011	8116105	Contract	Part	VO-21516231	Filter, Adblue Pump	1
1349	2019-04-30	945011	8116105	Contract	Part	VO-21954674	Strainer AdBlue pump	1
1350	2019-04-30	945011	8116105	Contract	Part	VO-85129688	Air Drier Kit	1
1351	2019-04-30	945011	8116105	Contract	Part	AU2-CAL85121714	OIL TRANSMISSION SAE50 BULK	16
1352	2019-04-30	945011	8116105	Contract	Part	VO-22038908	G/B FILTER KIT, Mack	1
1353	2019-04-30	945011	8116105	Contract	Part	AU2-CAL85121715	OIL GEAR 85W140 BULK	38
1354	2019-04-30	945011	8116105	Contract	Part	MK-8235-A3380W168	Diff Filter Meritor	1
1355	2019-04-30	945011	8116105	Retail	Part	VO-25109292	LAMP, ROOF AMBER	4
1356	2019-04-30	945011	8116105	Contract	Part	VO-20736230	SEAL STRIP, R/COVER GASKET	1
1357	2019-04-30	945011	8116105	Contract	Part	VO-1161277	LINER SILASTIC	1
1358	2019-04-30	945011	8116105	Retail	Part	VO-20965167	LINK	1
1359	2019-04-30	945011	8116105	Retail	Other	170	Parts Purchase - mud flaps and t shirts.	
1360	2019-04-30	945011	8116105	Retail	Part	UNK-NPN	2XL MACK T-SHIRT	2
1361	2019-04-30	945011	8116105	Retail	Part	VO-21055586	Mudflap 24 X 18 A/SP - MACK	2
1362	2019-04-30	945011	8116105	Contract	Operation	LO-25848	Strainer, replace. Pump unit	0.2
1363	2019-04-30	945011	8116105	Retail	Other	91	WORKSHOP CONSUMABLES	
1364	2019-04-23	0	7592192	Internal	Other	10	a bit more of the tow from 7582778	
1365	2019-03-22	928839	8114670	Retail	Other	M	PLEASE FILL IN	
1366	2019-03-22	928839	8114670		Text		Contact:0419 657 335	
1367	2019-03-22	928839	8114670	Retail	Operation	LO-2000	ENGINE FAULT ON DASH	8
1368	2019-03-22	928839	8114670	Retail	Part	VO-85000891	UNIT INJECTOR	1
1369	2019-03-22	928839	8114670	Retail	Part	VO-1677370	SEALING RING	2
1370	2019-03-22	928839	8114670	Retail	Part	VO-20526428	SEALING RING	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1371	2019-03-22	928839	8114670	Retail	Part	VO-20723207	SEALING RING	1
1372	2019-03-22	928839	8114670	Retail	Part	VO-20736230	SEAL STRIP, R/COVER GASKET	1
1373	2019-03-22	928839	8114670	Retail	Part	VO-85113754	Filter, Cab A/C Unit	1
1374	2019-03-22	928839	8114670	Retail	Part	VO-1161963	RUBBER GREASE	1
1375	2019-03-22	928839	8114670	Retail	Part	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
1376	2019-03-22	928839	8114670	Retail	Part	VO-21344774	FLANGE BOLT M10 x 50mm Grey	1
1377	2019-03-22	928839	8114670	Retail	Part	VO-983472	CABLE TIE, Injector Harness	1
1378	2019-03-22	928839	8114670	Retail	Other	97	ENVIRONMENTAL CHARGE	
1379	2019-03-22	928839	8114670	Retail	Other	91	WORKSHOP CONSUMABLES	
1380	2019-03-21	0	7591199	Internal	Other	10	tow sub from 7582778	
1381	2019-02-11	0	7589972		Text		Repair without detail info	
1382	2019-02-01	903634	7589637		Text		Fit Diff Oil Cooler to front Diff.	
1383	2019-02-01	903634	7589637	Internal	Operation	LO-461	Fit Diff Oil Cooler to front Diff.	3.2
1384	2019-02-01	903634	7589478	Internal	Operation	LO-230	MISS IN ENGINE	1
1385	2019-02-01	903634	7589478	Contract	Operation	VO-1774400	Basic service. Chassis lubrication and o	5.3
1386	2019-02-01	903634	7589478		Text		oil changes included only in some models	
1387	2019-02-01	903634	7589478	Contract	Operation	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
1388	2019-02-01	903634	7589478	Contract	Operation	LO-23306	Fuel filter, replace (one).	0.3
1389	2019-02-01	903634	7589478	Contract	Operation	VO-2331100	Filter, water separator, replace	0.3
1390	2019-02-01	903634	7589478	Contract	Operation	VO-2562400	Filter insert, air cleaner, replace. Ont	0.2
1391	2019-02-01	903634	7589478	Retail	Operation	VO-8700000	Air conditioning unit, general	1
1392	2019-02-01	903634	7589478	Contract	Part	VO-85114535	FILTER KIT - NEW BREED	1
1393	2019-02-01	903634	7589478	Contract	Part	VO-20579690	GASKET	1
1394	2019-02-01	903634	7589478	Internal	Part	VO-85148766	WHITE GREASE	1
1395	2019-02-01	903634	7589478	Internal	Part	AU2-9770-5073	HOT SHOT DEGREASER	1
1396	2019-02-01	903634	7589478	Retail	Part	VO-21267414	FUSE	1
1397	2019-02-01	903634	7589478	Contract	Part	MK-57MD42M	***ELEMENT, AIR 'C	2
1398	2019-02-01	903634	7589478	Contract	Part	AU2-CAL85121795	BULK 15W-40 ENGINE OIL VDS4	
1399	2019-02-01	903634	7589478	Retail	Other	91	WORKSHOP CONSUMABLES	
1400	2019-01-31	677052	7589556	Internal	Other	260	RECTIFY FAN FAILURE	
1401	2019-01-31	677052	7589556		Text		CAUSING DAMAGE TO RADIATOR VEHICLE BEING TOWED	
1402	2019-01-31	677052	7589556	Internal	Other	10	SUBLET TOW VEHICLE	
1403	2018-12-28	677052	7588659	Internal	Part	VO-22234469	REPLC BY 23017347	0.7
1404	2018-11-28	89	2383719	Internal	Operation	LO-ADR	CARRY OUT ADR/REGO INSPECTION.	0.01
1405	2018-11-05	867818	8108807	Internal	Other	M	PLEASE FILL IN	
1406	2018-11-05	867818	8108807		Text		Contact:Steve steven.kimeÖvolvo.com 0417 051 584	
1407	2018-11-05	867818	8108807	Internal	Operation	LO-170	Complete RWC	3.73

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1408	2018-11-05	867818	8108807	Internal	Other	17	Sublet -- Harrisvile	
1409	2018-11-05	867818	8108807	Internal	Other	170	Complete Turn table mod and	
1410	2018-11-05	867818	8108807	Internal	Other	17	Sublet -- Transeng.	
1411	2018-11-05	867818	8108807	Internal	Operation	LO-363	Replace wiper blades.	0.2
1412	2018-11-05	867818	8108807	Internal	Operation	LO-831	Fit missing side reflectors.	0.25
1413	2018-11-05	867818	8108807	Internal	Operation	LO-3000	move tail lights to outer edge of	3.58
1414	2018-11-05	867818	8108807	Internal	Operation	LO-251	exhaust manifold leaks.,	8.5
1415	2018-11-05	867818	8108807	Internal	Operation	LO-2000	missfire through cabin at	11.68
1416	2018-11-05	867818	8108807	Internal	Part	MK-NARV84036BL	REFLECTOR 1 = 2PK	1
1417	2018-11-05	867818	8108807	Internal	Part	MK-NARV17136BL	GLOBE 1=1 24V5W	1
1418	2018-11-05	867818	8108807	Internal	Part	MK-NARV84051BL	REFLECTOR 1 = 2PK	2
1419	2018-11-05	867818	8108807	Internal	Part	VO-82710488	WIPER BLADE BASIC	2
1420	2018-11-05	867818	8108807	Internal	Part	VO-6781769	SPLICE RED	20
1421	2018-11-05	867818	8108807	Internal	Part	MK-NARV56820BK	TAPE NITTO BLACK	1
1422	2018-11-05	867818	8108807	Internal	Part	VO-1652986	BALL BEARING	1
1423	2018-11-05	867818	8108807	Internal	Part	VO-22809246	CYLINDER	1
1424	2018-11-05	867818	8108807	Internal	Part	VO-85108352	CRANKSHAFT SEAL	1
1425	2018-11-05	867818	8108807	Internal	Part	MK-9718-BBC4	Brake Cleaner 400G	1
1426	2018-11-05	867818	8108807	Internal	Part	VO-22485772	SEALING KIT	1
1427	2018-11-05	867818	8108807	Internal	Part	VO-990073	CABLE TIE	2
1428	2018-11-05	867818	8108807	Internal	Part	VO-20483426	SEALING RING- INPUT SEAL	1
1429	2018-11-05	867818	8108807	Internal	Part	MK-2104-2507018X	STRAP KIT SPL250	2
1430	2018-11-05	867818	8108807	Internal	Part	VO-990818	STUD	2
1431	2018-11-05	867818	8108807	Internal	Part	VO-990951	FLANGE NUT CRIMP M10	2
1432	2018-11-05	867818	8108807	Internal	Part	VO-20497205	GASKET	1
1433	2018-11-05	867818	8108807	Internal	Part	VO-21352841	GASKET EXHAUST	6
1434	2018-11-05	867818	8108807	Internal	Part	VO-20938964	SEAL	1
1435	2018-11-05	867818	8108807	Internal	Part	VO-20784537	GASKET TURBO BASE	1
1436	2018-11-05	867818	8108807	Internal	Part	VO-22206133	TURBO FEED GASKET	1
1437	2018-11-05	867818	8108807	Internal	Part	VO-470993	TURBO RTN GKT	1
1438	2018-11-05	867818	8108807	Internal	Part	VO-21940615	SEALING RING	1
1439	2018-11-05	867818	8108807	Internal	Part	VO-469601	TURBO O-RING	1
1440	2018-11-05	867818	8108807	Internal	Part	OTH-MP8PAINT	MACK ENG RED PAINT	1
1441	2018-11-05	867818	8108807	Internal	Part	VO-22823727	EXHAUST BRAKE	1
1442	2018-11-05	867818	8108807	Internal	Part	VO-994441	FLANGE BOLT M8 x 50mm	1
1443	2018-11-05	867818	8108807	Internal	Part	VO-990950	FLANGE NUT CRIMP M8	1
1444	2018-11-05	867818	8108807	Internal	Part	AU2-WUR067320501C	Nylon Power LOC 2I	2

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1445	2018-11-05	867818	8108807	Internal	Part	VO-22643809	BRACKET	1
1446	2018-11-05	867818	8108807	Internal	Part	VO-22811869	PIPE SET	1
1447	2018-11-05	867818	8108807	Internal	Part	VO-21582423	4 PIN PLUG KIT	1
1448	2018-11-05	867818	8108807	Internal	Part	VO-25099438	HOSE WASTEGATE	1
1449	2018-11-05	867818	8108807	Internal	Part	VO-975269	HOSE CLAMP, MINI	2
1450	2018-11-05	867818	8108807	Internal	Part	VO-22655439	SPACER SLEEVE	1
1451	2018-11-05	867818	8108807	Internal	Part	VO-467310	EXHAUST CLAMP	1
1452	2018-11-05	867818	8108807	Internal	Part	VO-21029030	CLAMP	1
1453	2018-11-05	867818	8108807	Internal	Part	VO-25091425	CLAMP	1
1454	2018-11-05	867818	8108807	Internal	Part	VO-1675066	SEALING RING	2
1455	2018-11-05	867818	8108807	Internal	Other	MTELEC11	4000-9.9mm conduit	
1456	2018-11-05	867818	8108807	Internal	Other	20	SUBLET EXHAUST MANIFOLD	
1457	2018-11-05	867818	8108807	Internal	Part	MK-FT1880X8X8	ELBOW 45 QC 1/2 TUBE 1/2NPT	1
1458	2018-11-05	867818	8108807	Internal	Part	VO-20515114	ELBOW NIPPLE	1
1459	2018-11-05	867818	8108807	Internal	Part	MK-ABCABT8A30	SYNFLEX 1/2 BLUE	1
1460	2018-11-05	867818	8108807	Internal	Part	MK-FT1868X8	ADAPTOR QC 1/2 TUBE 3/8NPT	1
1461	2018-11-05	867818	8108807	Internal	Other	MTELEC186	RIVETS	
1462	2018-11-05	867818	8108807	Internal	Other	97	ENVIRONMENTAL CHARGE	
1463	2018-10-31	0	7586926	Internal	Part	VO-22234469	REPLC BY 23017347	0.3
1464	2018-10-30	866999	7586719	Internal	Operation	LO-510	Fit Road train electrical booster	3
1465	2018-10-30	866999	7586719	Internal	Part	VO-21422942	BRACKET	1
1466	2018-10-30	866999	7586719	Internal	Part	VO-21965574	VOLTAGE STABILIZER	1
1467	2018-10-30	866999	7586719	Internal	Part	VO-25109882	NUT-HEX-FLG-M5X0.8	3
1468	2018-10-30	866999	7586719	Internal	Part	VO-25095670	CLAMP.P-CUSH-3/4:X	1
1469	2018-10-30	866999	7586719	Internal	Part	VO-21105107	SCREW	3
1470	2018-10-30	866999	7586719	Internal	Part	VO-984728	BOLT M6*30 FLANGE	3
1471	2018-10-30	866999	7586719	Internal	Part	VO-990949	LOCK NUT M6 FLANGE	3
1472	2018-10-30	866999	7586719	Internal	Part	MK-NARV56306	CABLE TIE 1=25PK	2
1473	2018-10-30	866999	7586719	Internal	Part	VO-984726	BOLT M6*20 FLANGE	2
1474	2018-10-29	89	7586720	Internal	Operation	LO-890	DETAIL	14
1475	2018-10-29	89	7586720	Internal	Part	MK-9732-NCP33	NUT COVER 33MM	60
1476	2018-10-27	89	7586783	Internal	Operation	LO-ADR	CARRY OUT ADR/REGO INSPECTION.	3
1477	2018-10-24	89	7586721	Internal	Operation	LO-170	Check over and report	3
1478	2018-10-24	89	7586721	Internal	Operation	LO-890	DRIVERS DOOR WONT LATCH	3.59
1479	2018-10-24	89	7586721	Internal	Other	891	RH WINDSCREEN DAMAGED	
1480	2018-10-24	89	7586721	Internal	Operation	LO-891	REAR MARKER PLATES DAMAGED/MISSING	1
1481	2018-10-24	89	7586721	Internal	Other	890	WORN TYRES. RH AXLE 1 & 2	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1482	2018-10-24	89	7586721	Internal	Operation	LO-461	AXLE 2 LH SHOCK LEAKING	0.5
1483	2018-10-24	89	7586721	Internal	Other	460	AXLE 2 TRANSVERSE SLIGHT WEAR	
1484	2018-10-24	89	7586721	Internal	Operation	LO-462	AXLE 2 FRONT DIFF YOKE LOOSE	2.24
1485	2018-10-24	89	7586721	Internal	Operation	LO-350	RH BRAKE LIGHT, RH LOW BEAM N/W	3
1486	2018-10-24	89	7586721	Internal	Operation	LO-270	OIL LEAK AT FILLER PIPE	1
1487	2018-10-24	89	7586721	Internal	Other	254	EXHAUST LEAK AT SLIP JOINT IN MANIFOLD	
1488	2018-10-24	89	7586721	Internal	Operation	LO-610	STEERIMNG DAMPNER LEAKING	0.55
1489	2018-10-24	89	7586721	Internal	Other	10	RAYMOND TERRACE WINDSCREEN	
1490	2018-10-24	89	7586721	Internal	Part	VO-8039581	MUDFLAP INSERT (CIXT034A SET)	1
1491	2018-10-24	89	7586721	Internal	Part	VO-8039582	MUDFLAP INSERT (CIXT034A SET)	1
1492	2018-10-24	89	7586721	Internal	Part	VO-21341754	SHOCK ABSORBER	1
1493	2018-10-24	89	7586721	Internal	Part	VO-21780376	SEALING RING	1
1494	2018-10-24	89	7586721	Internal	Part	MK-5435-SC2920	STG STAB CYL	1
1495	2018-10-24	89	7586721	Internal	Part	VO-85109772	BULB H11 12V 55W	1
1496	2018-10-24	89	7586721	Internal	Part	MK-NARV17635BL	BULB 1=1 12V21W	1
1497	2018-10-24	89	7586721	Internal	Part	VO-85145751	LOCKING FLUID	1
1498	2018-10-24	89	7586721	Internal	Part	AU2-4381-2317	LED STOP TAIL INSE	1
1499	2018-10-24	89	7586721	Internal	Part	MK-NARV56310	CABLE TIE 1=10PK	2
1500	2018-10-24	89	7586721	Internal	Part	VO-6781769	SPLICE-RED(22-18)	2
1501	2018-10-24	89	7586721	Internal	Operation	LO-260	COOLANT LEAK	10
1502	2018-10-24	89	7586721	Internal	Part	VO-23017347	RADIATOR	1
1503	2018-10-24	89	7586721	Internal	Part	VO-21841226	FAN SHROUD	1
1504	2018-10-24	89	7586721	Internal	Part	VO-972094	SOCKET SCREW:6 PT.	4
1505	2018-10-24	89	7586721	Internal	Part	VO-992416	SIX POINT SOCKET S	3
1506	2018-10-24	89	7586721	Internal	Part	VO-994795	SIX POINT SOCKET M6X16	3
1507	2018-10-24	89	7586721	Internal	Part	VO-994945	SPRING NUT	2
1508	2018-10-24	89	7586721	Internal	Part	VO-21053033	HOSE	1
1509	2018-10-24	89	7586721	Internal	Part	AU2-CAL85112988	COOLANT 20L VCS BULLDOG	2
1510	2018-10-24	89	7586721	Internal	Part	OTH-LATE	FEE	1
1511	2018-10-24	89	7586721	Internal	Part	VO-22630453	RADIATOR	1
1512	2018-10-24	89	7586721	Internal	Part	VO-990861	BOLT M10*30 FLANGE 10.9	1
1513	2018-09-28	0	7585955	Internal	Operation	LO-260	labour from 7582778	6
1514	2018-09-21	677052	7585709	Internal	Part	VO-85111556	FAN BLADE	1
1515	2018-09-21	677052	7585709	Internal	Part	AU2-CAL85112988	COOLANT 20L VCS BULLDOG	2
1516	2018-09-21	677052	7585709	Internal	Part	VO-22723390	PIPE	1
1517	2018-09-21	677052	7585709	Internal	Part	VO-22723395	PIPE	1
1518	2018-09-21	677052	7585709	Internal	Part	VO-20443759	O-RING	2

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1519	2018-09-21	677052	7585709	Internal	Part	VO-21154500	RETAINER	2
1520	2018-09-21	677052	7585709	Internal	Part	MK-NARV56306	CABLE TIE 1=25PK	1
1521	2018-09-21	677052	7585709	Internal	Part	VO-994930	SIX POINT SOCKET S	1
1522	2018-09-21	677052	7585709	Internal	Part	VO-984723	BOLT M6*10 FLANGE	1
1523	2018-09-21	677052	7585709	Internal	Part	VO-1675066	BOOST O'RING	1
1524	2018-09-21	677052	7585709	Internal	Part	VO-6781769	SPLICE-RED(22-18)	2
1525	2018-09-21	677052	7585709	Internal	Part	VO-9130476	SPLICE-BLUE(14-16)	2
1526	2018-09-21	677052	7585709	Internal	Part	AU2-9770-5073	HOT SHOT DEGREASER	1
1527	2018-09-21	677052	7585709	Internal	Part	MK-2104-2507018X	KIT BRG RETAINER S	1
1528	2018-08-12	854226	7584225	Retail	Other	30	SUBLET-CMV WODONGA	
1529	2018-08-12	854226	7584225		Text		CALL OUT	
1530	2018-07-30	855340	7245874	Warranty	Operation	LO-381	DROPPING IN POWER	5
1531	2018-06-22	677052	7582778	Internal	Other	260	RECTIFY FAN FAILURE	
1532	2018-06-22	677052	7582778		Text		CAUSING DAMAGE TO RADIATOR VEHICLE BEING TOWED	
1533	2018-06-22	677052	7582778	Internal	Other	10	SUBLET TOW VEHICLE	
1534	2018-06-22	677052	2383534	Retail	Operation	LO-260	RECTIFY FAN FAILURE	6
1535	2018-06-22	677052	2383534		Text		CAUSING DAMAGE TO RADIATOR VEHICLE BEING TOWED	
1536	2018-06-22	677052	2383534	Retail	Part	VO-22234469	RADIATOR	1
1537	2018-06-22	677052	2383534	Retail	Part	VO-85111556	FAN BLADE	1
1538	2018-06-22	677052	2383534	Retail	Part	AU2-CAL85112988	COOLANT 20L VCS BULLDOG	2
1539	2018-06-22	677052	2383534	Retail	Part	VO-22723390	PIPE	1
1540	2018-06-22	677052	2383534	Retail	Part	VO-22723395	PIPE	1
1541	2018-06-22	677052	2383534	Retail	Part	VO-20443759	O-RING	2
1542	2018-06-22	677052	2383534	Retail	Part	VO-21154500	RETAINER	2
1543	2018-06-22	677052	2383534	Retail	Part	MK-NARV56306	CABLE TIE 1=25PK	1
1544	2018-06-22	677052	2383534	Retail	Part	VO-994930	SIX POINT SOCKET S	1
1545	2018-06-22	677052	2383534	Retail	Part	VO-984723	BOLT M6*10 FLANGE	1
1546	2018-06-22	677052	2383534	Retail	Part	VO-1675066	BOOST O'RING	1
1547	2018-06-22	677052	2383534	Retail	Part	VO-6781769	SPLICE-RED(22-18)	2
1548	2018-06-22	677052	2383534	Retail	Part	VO-9130476	SPLICE-BLUE(14-16)	2
1549	2018-06-22	677052	2383534	Retail	Part	AU2-9770-5073	HOT SHOT DEGREASER	1
1550	2018-06-22	677052	2383534	Retail	Part	MK-2104-2507018X	KIT BRG RETAINER S	1
1551	2018-06-22	677052	2383534	Retail	Other	10	SUBLET TOW VEHICLE	
1552	2018-06-22	677052	2383534	Retail	Other	91	WORKSHOP CONSUMABLES	
1553	2018-02-24	750067	7578873	Retail	Operation	LO-262	WATER PUMP LEAKING	3
1554	2018-02-24	750067	7578873	Retail	Part	VO-85151110	WATER PUMP KIT	1
1555	2018-02-24	750067	7578873	Retail	Part	MK-5166-51827	LOCTITE, 518 25ML	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1556	2018-02-24	750067	7578873		Text		P.WATER PUMP LEAKING	
1557	2018-02-24	750067	7578873	Retail	Other	91	WORKSHOP CONSUMABLES	
1558	2018-02-24	750067	7578830	Retail	Operation	LO-284	INTERMITTANT LOW POWER	1.5
1559	2018-02-24	750067	7578830	Retail	Part	VO-21634017	PRESSURE SENSOR, CRANKCASE	1
1560	2018-02-24	750067	7578830	Retail	Part	AU2-9770-2015	CO CONTACT CLEANER 150g	1
1561	2018-02-24	750067	7578830		Text		P.INTERMITTANT LOW POWER	
1562	2018-01-24	726155	7577903	Retail	Other	20	sublet Souther Truck Centre	
1563	2018-01-24	726155	7577903		Text		ROAD SIDE ASSISTANCE PHEASANTS	
1564	2018-01-20	726155	3033134	Retail	Operation	LO-19400	ROAD SIDE ASSISTANCE PHEASANTS	3.5
1565	2018-01-20	726155	3033134		Text		BOOST LEAK	
1566	2018-01-20	726155	3033134	Retail	Part	VO-20592783	CLAMP	1
1567	2018-01-20	726155	3033134	Retail	Part	OTH-CALL-OUT	CALL OUT FEE SPARE PARTS	1
1568	2018-01-20	726155	3033134	Retail	Other	92	TRAVEL 112 km Ö Å1.40 p/km.	
1569	2018-01-20	726155	3033134	Retail	Other	91	WORKSHOP MATERIALS	
1570	2017-12-13	626799	2383309	Warranty	Part	VO-21064733	V-RIBBED BELT 10PK	1
1571	2017-12-13	626799	2383309	Warranty	Part	VO-21631484	BELT TENSIONER	1
1572	2017-12-13	626799	2383309	Warranty	Part	VO-21753149	IDLER PULLEY	1
1573	2017-12-13	626799	2383309	Warranty	Part	VO-21064734	V-RIBBED BELT 8PK*	1
1574	2017-12-13	626799	2383309	Warranty	Part	VO-21422767	BELT TENSIONER	1
1575	2017-12-13	626799	2383309	Warranty	Other	2631300	Fan belt tensioner, replace	
1576	2017-12-09	699448	7576228		Text		LOW AIR PRESSURE INDICATOR LAMP, INSTALLATION	
1577	2017-12-09	699448	7576228	Warranty	Operation	LO-520	BRAKE SYSTEM - GENERAL	0.6
1578	2017-12-09	699448	7576228	Warranty	Operation	LO-170	Service and Maintenance	0.2
1579	2017-12-09	699448	7576228	Warranty	Operation	LO-384	INSTRUMENTATION-INDICATOR/WARNING SYSTEM	0.3
1580	2017-12-09	699448	7576228	Warranty	Part	VO-23007482	INDICATOR LAMP	1
1581	2017-12-09	699448	7576228	Warranty	Part	VO-23003276	BEZEL	1
1582	2017-12-09	699448	7576228	Warranty	Part	VO-23003273	WIRES	1
1583	2017-11-16	681599	7576014	Retail	Operation	LO-3000	WIRE IN DOOR ALARM OPEN WITH KEY OFF	4
1584	2017-11-16	681599	7576014	Retail	Operation	LO-363	WINDSCREEN WASHERS NOT SPRAYING	0.2
1585	2017-11-16	681599	7576014	Retail	Part	VO-85129896	NOZZLE	2
1586	2017-11-16	681599	7576014	Retail	Part	MK-X70MR2391	RELAY 12V CHANGE OVER	1
1587	2017-11-16	681599	7576014	Retail	Part	MK-NARV56044BL	TERMINAL 1=10PK BL	1
1588	2017-11-16	681599	7576014		Text		P.WINDSCREEN WASHERS NOT SPRAYING	
1589	2017-11-16	681599	7576014	Retail	Other	91	WORKSHOP CONSUMABLES	
1590	2017-11-10	677052	7575787	Retail	Operation	LO-260	RECTIFY FAN FAILURE	6
1591	2017-11-10	677052	7575787		Text		CAUSING DAMAGE TO RADIATOR VEHICLE BEING TOWED	
1592	2017-11-10	677052	7575787	Retail	Part	VO-22234469	RADIATOR	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1593	2017-11-10	677052	7575787	Retail	Part	VO-85111556	FAN BLADE	1
1594	2017-11-10	677052	7575787	Retail	Part	AU2-CAL85112988	COOLANT 20L VCS BULLDOG	2
1595	2017-11-10	677052	7575787	Retail	Part	VO-22723390	PIPE	1
1596	2017-11-10	677052	7575787	Retail	Part	VO-22723395	PIPE	1
1597	2017-11-10	677052	7575787	Internal	Part	VO-22630453	RADIATOR	1
1598	2017-11-10	677052	7575787	Internal	Part	VO-22314813	CONDENSER	1
1599	2017-11-10	677052	7575787	Retail	Part	VO-20443759	O-RING	2
1600	2017-11-10	677052	7575787	Retail	Part	VO-21154500	RETAINER	2
1601	2017-11-10	677052	7575787	Retail	Part	MK-NARV56306	CABLE TIE 1=25PK	1
1602	2017-11-10	677052	7575787	Retail	Part	VO-994930	SIX POINT SOCKET S	1
1603	2017-11-10	677052	7575787	Retail	Part	VO-984723	BOLT M6*10 FLANGE	1
1604	2017-11-10	677052	7575787	Retail	Part	VO-1675066	BOOST O'RING	1
1605	2017-11-10	677052	7575787	Retail	Part	VO-6781769	SPLICE-RED(22-18)	2
1606	2017-11-10	677052	7575787	Retail	Part	VO-9130476	SPLICE-BLUE(14-16)	2
1607	2017-11-10	677052	7575787	Retail	Part	AU2-9770-5073	HOT SHOT DEGREASER	1
1608	2017-11-10	677052	7575787	Internal	Part	OTH-ACX2910	DT 2 WAY KIT	1
1609	2017-11-10	677052	7575787	Retail	Part	MK-2104-2507018X	KIT BRG RETAINER S	1
1610	2017-11-10	677052	7575787	Retail	Other	10	SUBLET TOW VEHICLE	
1611	2017-11-10	677052	7575787	Retail	Other	91	WORKSHOP CONSUMABLES	
1612	2017-10-13	649126	2383271	Internal	Part	VO-C21638569	TURBOCHARGER EXCH	1
1613	2017-10-09	626799	7575983	Retail	Part	VO-21064733	REPLC BY 22950564	1
1614	2017-10-09	626799	7575983	Retail	Part	VO-21631484	BELT TENSIONER	1
1615	2017-10-09	626799	7575983	Retail	Part	VO-21753149	IDLER PULLEY	1
1616	2017-10-09	626799	7575983	Retail	Part	VO-21064734	REPLC BY 22950621	1
1617	2017-10-09	626799	7575983	Retail	Part	VO-21422767	BELT TENSIONER	1
1618	2017-10-09	626799	7575983	Retail	Other	263	Replace fan belts and tensioners	
1619	2017-10-09	626799	7575983		Text		credit/recharge from denied wty claim. aaron to discuss wit	
1620	2017-10-06	649126	7574680		Text		P.REPLACE TURBO	
1621	2017-10-06	649126	7574680	Retail	Operation	LO-255	REPLACE TURBO	3.5
1622	2017-10-06	649126	7574680	Warranty	Operation	LO-465	OIL LEAK AT FRONT DIFF	6
1623	2017-10-06	649126	7574680	Warranty	Operation	LO-761	CHECK ALL DRIVE SHOCKIES	1.2
1624	2017-10-06	649126	7574680	Retail	Part	VO-21638569	TURBOCHARGER HE551	1
1625	2017-10-06	649126	7574680	Retail	Part	VO-85133578	INSTALL KIT, TURBO	1
1626	2017-10-06	649126	7574680	Internal	Part	VO-C21638569	TURBOCHARGER EXCH	1
1627	2017-10-06	649126	7574680	Retail	Part	VO-21940610	SEALING RING	1
1628	2017-10-06	649126	7574680	Retail	Part	VO-993811	REPLC BY 984756	4
1629	2017-10-06	649126	7574680	Warranty	Part	VO-21341754	SHOCK ABSORBER	4

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1630	2017-10-06	649126	7574680	Retail	Part	VO-8148729	CONNECTOR	1
1631	2017-10-06	649126	7574680	Retail	Part	VO-994441	BOLT M8*50 FLANGE	1
1632	2017-10-06	649126	7574680	Retail	Part	VO-21029030	CLAMP	1
1633	2017-10-06	649126	7574680	Warranty	Part	MK-2104-2507018X	KIT BRG RETAINER S	2
1634	2017-10-06	649126	7574680	Warranty	Part	MK-8235-2208A1197	GASKET, FRONT DIFF	1
1635	2017-10-06	649126	7574680	Retail	Part	MK-8235-KIT2825	CYLINDER AIR IAD	1
1636	2017-10-06	649126	7574680	Internal	Part	AU2-WUR067320501C	NYLON POWER BUFF 2I	1
1637	2017-10-06	649126	7574680	Internal	Part	AU2-WUR067320751C	NYLON POWER BUFF 3I	1
1638	2017-10-06	649126	7574680	Retail	Part	MK-9718-BBC4	BRAKE CLEANER 400G	1
1639	2017-10-06	649126	7574680	Internal	Part	VO-3199066	SEAL	2
1640	2017-10-06	649126	7574680	Retail	Part	VO-907852	SPLIT PIN	1
1641	2017-10-06	649126	7574680	Internal	Part	AU2-9770-5073	HOT SHOT DEGREASER	1
1642	2017-08-30	626999	7573386	Warranty	Operation	LO-211	ENGINE HAS BAD VIBRATION	27.8
1643	2017-08-30	626999	7573386		Text		-DONE 2 VALVE ADJUSTMENTS AND DIAGNOSED AS CYLINDER HEAD	
1644	2017-08-30	626999	7573386	Warranty	Part	VO-984861	BOLT M14*80 FLANGED	2
1645	2017-08-30	626999	7573386	Warranty	Part	VO-984739	BOLT M8*50 FLANGE	4
1646	2017-08-30	626999	7573386	Warranty	Part	AU2-WUR0411820	WSH-FEND-TOLDIN522	4
1647	2017-08-30	626999	7573386	Warranty	Part	VO-22889891	ACTUATOR SERVICE K	1
1648	2017-08-30	626999	7573386	Warranty	Part	VO-20799996	SEALING RING	1
1649	2017-08-30	626999	7573386	Warranty	Part	VO-21423788	SEALING RING	1
1650	2017-08-30	626999	7573386	Warranty	Part	VO-3092340	SILASTIC-GREY 310ML	1
1651	2017-08-30	626999	7573386	Warranty	Part	VO-20563945	ANTI-TAMPER SEALIN	1
1652	2017-08-30	626999	7573386	Warranty	Part	VO-20736230	R/COV.GASKET D16C	1
1653	2017-08-30	626999	7573386	Warranty	Part	MK-5166-51827	LOCTITE, 518 25ML	1
1654	2017-08-30	626999	7573386	Warranty	Part	VO-21503575	SEALING RING THERMOSTAT	1
1655	2017-08-30	626999	7573386	Warranty	Part	VO-20815558	SEALING STRIP	1
1656	2017-08-30	626999	7573386	Warranty	Part	VO-21185132	SEALING	2
1657	2017-08-30	626999	7573386	Warranty	Part	VO-20852765	DOWDY WASHER	4
1658	2017-08-30	626999	7573386	Warranty	Part	VO-21352841	GASKET	6
1659	2017-08-30	626999	7573386	Internal	Part	OTH-DSF62	MACK RED SPRAY PAINT	1
1660	2017-08-30	626999	7573386	Warranty	Part	VO-21575727	GASKET	1
1661	2017-08-30	626999	7573386	Warranty	Part	VO-85000888	CYLINDER HEAD, EXC	1
1662	2017-08-30	626999	7573386	Warranty	Part	VO-22326082	VALVE BRIDGE	6
1663	2017-08-30	626999	7573386	Warranty	Part	VO-994447	FLANGE SCREW	6
1664	2017-08-30	626999	7573386	Warranty	Part	VO-471708	SEALING RING	1
1665	2017-08-30	626999	7573386	Warranty	Part	VO-1547252	SEALING RING	1
1666	2017-08-30	626999	7573386	Warranty	Part	VO-276948	O-RING KIT	6

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1667	2017-08-30	626999	7573386	Warranty	Part	VO-944126	O-RING INJECTER HARNESS	1
1668	2017-08-30	626999	7573386	Warranty	Part	VO-983472	CABLE TIE-GREY HIGH TEMP	10
1669	2017-08-30	626999	7573386	Warranty	Part	VO-3979639	GASKET	2
1670	2017-08-30	626999	7573386	Warranty	Part	VO-85148766	WHITE GREASE	1
1671	2017-08-30	626999	7573386	Warranty	Part	VO-1677370	SEALING RING-VEB	2
1672	2017-08-30	626999	7573386	Warranty	Part	VO-20526428	SEALING RING-VEB	1
1673	2017-08-30	626999	7573386	Warranty	Part	VO-22206133	GASKET	1
1674	2017-08-30	626999	7573386	Warranty	Part	VO-470993	GASKET-OIL RETURN	1
1675	2017-08-30	626999	7573386	Warranty	Part	VO-990950	NUT M8 FLANGED LOCKING	1
1676	2017-08-30	626999	7573386	Warranty	Part	AU2-CAL85112987	COOLANT 5L VCS BULLDOG	2
1677	2017-08-30	626999	7573386	Internal	Part	AU2-9770-5073	HOT SHOT DEGREASER	1
1678	2017-08-30	626999	7573386	Warranty	Part	VO-984735	BOLT M8*25 FLANGE	2
1679	2017-08-30	626999	7573386	Warranty	Part	VO-994848	WASHER M8*22	2
1680	2017-08-30	626999	7573386	Retail	Operation	VO-3630400	Windscreen wiper blade, replace	0.4
1681	2017-08-30	626999	7573386	Retail	Part	VO-82710488	WIPER BLADE BASIC	2
1682	2017-08-30	626999	7573386	Internal	Part	AU2-CAL85121714	BULK SAE50 TRANS OIL VOLVO	
1683	2017-08-30	626999	7573386	Warranty	Operation	LO-253	EXHAUST BRAKE	0.9
1684	2017-08-30	626999	7573386	Retail	Other	91	WORKSHOP CONSUMABLES	
1685	2017-08-24	626799	7573160	Warranty	Operation	LO-491	MISCELLANEOUS - OIL COOLER-TRANSMISSION	6
1686	2017-08-24	626799	7573160	Warranty	Operation	LO-222	OIL CLEANER	4.1
1687	2017-08-24	626799	7573160	Warranty	Operation	LO-263	FANS,FAN SHROUDS AND COUPLINGS	3.8
1688	2017-08-24	626799	7573160	Warranty	Operation	LO-764	LEVEL CONTROL (SEPARATE SYSTEM)	2.6
1689	2017-08-24	626799	7573160	Warranty	Operation	LO-251	INTAKE AND EXHAUST PIPES	4.9
1690	2017-08-24	626799	7573160	Warranty	Operation	LO-561	COMPRESSOR, GOVERNOR, ANTI-FREEZE DEVICE	1.3
1691	2017-08-24	626799	7573160		Text		AIR DRYER, REPLACEMENT	
1692	2017-08-24	626799	7573160	Warranty	Operation	VO-5600000	Air pressure brake, general. Secondary o	0.5
1693	2017-08-24	626799	7573160	Warranty	Operation	VO-5610000	Compressor, regulator, anti-freeze unit.	1.8
1694	2017-08-24	626799	7573160	Warranty	Operation	LO-465	FINAL DRIVES (FRONT AND REAR)	1.5
1695	2017-08-24	626799	7573160	Warranty	Operation	LO-773	REPLACE HUB SEALS WITH HIGH TEMP	5.2
1696	2017-08-24	626799	7573160	Retail	Operation	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.4
1697	2017-08-24	626799	7573160	Warranty	Operation	VO-2582700	Level sensor, tank, replace	0.6
1698	2017-08-24	626799	7573160	Warranty	Part	VO-22630453	RADIATOR	1
1699	2017-08-24	626799	7573160	Warranty	Part	VO-22713593	BRACKET	2
1700	2017-08-24	626799	7573160	Warranty	Part	VO-25309843	SEMS SCREW	4
1701	2017-08-24	626799	7573160	Warranty	Part	VO-21983562	PIPE G/BOX COOLING	1
1702	2017-08-24	626799	7573160	Warranty	Part	VO-22723390	PIPE	1
1703	2017-08-24	626799	7573160	Warranty	Part	VO-21723664	BRACKET	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1704	2017-08-24	626799	7573160	Warranty	Part	VO-20802204	CABLE CLAMP	1
1705	2017-08-24	626799	7573160	Warranty	Part	VO-21052610	NIPPLE	1
1706	2017-08-24	626799	7573160	Internal	Part	VO-948211	CABLE TIE-MEDIUM	4
1707	2017-08-24	626799	7573160	Warranty	Part	VO-984729	BOLT M6*40 FLANGE	1
1708	2017-08-24	626799	7573160	Warranty	Part	VO-984733	BOLT M8*16 FLANGE	2
1709	2017-08-24	626799	7573160	Warranty	Part	VO-85148634	KIT	1
1710	2017-08-24	626799	7573160	Warranty	Part	VO-984735	BOLT M8*25 FLANGE	2
1711	2017-08-24	626799	7573160	Warranty	Part	VO-990950	NUT M8 FLANGED LOCKING	4
1712	2017-08-24	626799	7573160	Warranty	Part	VO-993960	HOSE CLAMP	4
1713	2017-08-24	626799	7573160	Warranty	Part	VO-21052612	CONNECTOR	1
1714	2017-08-24	626799	7573160	Warranty	Part	VO-21380391	CONNECTOR 45"	1
1715	2017-08-24	626799	7573160	Warranty	Part	VO-979099	GASKET	1
1716	2017-08-24	626799	7573160	Warranty	Part	VO-952631	CLAMP	1
1717	2017-08-24	626799	7573160	Warranty	Part	VO-952630	CLAMP	2
1718	2017-08-24	626799	7573160	Warranty	Part	VO-977976	CLAMP	1
1719	2017-08-24	626799	7573160	Warranty	Part	VO-994927	SIX POINT SOCKET S	4
1720	2017-08-24	626799	7573160	Warranty	Part	VO-994792	SIX POINT SOCKET S	3
1721	2017-08-24	626799	7573160	Warranty	Part	VO-992416	SIX POINT SOCKET S	4
1722	2017-08-24	626799	7573160	Warranty	Part	VO-20399313	SPRING NUT	3
1723	2017-08-24	626799	7573160	Warranty	Part	VO-22713587	BRACKET	2
1724	2017-08-24	626799	7573160	Warranty	Part	VO-22723395	PIPE	1
1725	2017-08-24	626799	7573160	Warranty	Part	VO-1610554	RESILIENT WASHER	2
1726	2017-08-24	626799	7573160	Warranty	Part	VO-990953	LOCK NUT M14 FLANGE	1
1727	2017-08-24	626799	7573160	Warranty	Part	VO-21339891	RUBBER HOSE	0.3
1728	2017-08-24	626799	7573160	Internal	Part	MK-NARV56306	CABLE TIE 1=25PK	1
1729	2017-08-24	626799	7573160	Internal	Part	MK-NARV56310	CABLE TIE 1=10PK	1
1730	2017-08-24	626799	7573160	Warranty	Part	VO-18677	COPPER WASHER	1
1731	2017-08-24	626799	7573160	Warranty	Part	AU2-CAL85112987	COOLANT 5L VCS BULLDOG	1
1732	2017-08-24	626799	7573160	Warranty	Part	VO-3199066	SEAL	4
1733	2017-08-24	626799	7573160	Warranty	Part	MK-8235-MER0273	WHEEL SEAL DRIVE	4
1734	2017-08-24	626799	7573160	Retail	Part	VO-22038908	OIL FILTER KIT	1
1735	2017-08-24	626799	7573160	Retail	Part	AU2-CAL85107476	SYNTH GEAR OIL 20L VOLVO	1
1736	2017-08-24	626799	7573160	Retail	Part	AU2-CAL85136279	DIFF OIL SYNTHETIC 20LTR	2
1737	2017-08-24	626799	7573160	Retail	Part	MK-8235-A3380W168	DIFF FILTER	1
1738	2017-08-24	626799	7573160	Retail	Part	OTH-SYNTHETIC-TAG	SYNTHETIC OIL-TAG/STICKER	6
1739	2017-08-24	626799	7573160	Warranty	Operation	LO-253	EXHAUST BRAKE	0.8
1740	2017-08-24	626799	7573160	Warranty	Part	VO-21497512	GASKET	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1741	2017-08-24	626799	7573160	Warranty	Part	VO-21940610	SEALING RING	1
1742	2017-08-24	626799	7573160	Warranty	Part	VO-470993	GASKET-OIL RETURN	1
1743	2017-08-24	626799	7573160	Warranty	Part	VO-22206133	GASKET	1
1744	2017-08-24	626799	7573160	Warranty	Part	VO-21940615	SEALING RING	1
1745	2017-08-24	626799	7573160	Warranty	Part	VO-469601	SEALING RING TURBO OIL DRAIN	1
1746	2017-08-24	626799	7573160	Warranty	Part	VO-22114765	OIL FILTER HOUSING	1
1747	2017-08-24	626799	7573160	Warranty	Part	VO-21707136	OIL FILTER	2
1748	2017-08-24	626799	7573160	Warranty	Part	VO-21707135	OIL FILTER	1
1749	2017-08-24	626799	7573160	Internal	Part	AU2-WUR067320501C	NYLON POWER BUFF 21	2
1750	2017-08-24	626799	7573160	Internal	Part	VO-85148766	WHITE GREASE	1
1751	2017-08-24	626799	7573160	Internal	Part	MK-9718-BBC4	BRAKE CLEANER 400G	1
1752	2017-08-24	626799	7573160	Warranty	Part	VO-982508	DOWDY WASHER	2
1753	2017-08-24	626799	7573160	Warranty	Part	VO-25309934	SIX POINT SOCKET S	3
1754	2017-08-24	626799	7573160	Warranty	Part	VO-21745611	TANDEM PUMP	1
1755	2017-08-24	626799	7573160	Warranty	Part	VO-20852765	DOWDY WASHER	4
1756	2017-08-24	626799	7573160	Warranty	Part	VO-21780376	SEALING RING	1
1757	2017-08-24	626799	7573160	Warranty	Part	VO-21053055	HOSE,COOLANT	1
1758	2017-08-24	626799	7573160	Warranty	Part	VO-21070135	ADAPTER	1
1759	2017-08-24	626799	7573160	Warranty	Part	VO-992084	HOSE CLAMP	2
1760	2017-08-24	626799	7573160	Warranty	Part	VO-20784537	GASKET - TURBO BASE	1
1761	2017-08-24	626799	7573160	Warranty	Part	VO-21352841	GASKET	6
1762	2017-08-24	626799	7573160	Warranty	Part	VO-22718181	KIT	1
1763	2017-08-24	626799	7573160	Warranty	Part	VO-1161929	JOINTING PASTE	1
1764	2017-08-24	626799	7573160	Internal	Part	AU2-9770-5028	CRC 5.56 (Multi-pu	1
1765	2017-08-24	626799	7573160	Warranty	Part	VO-22580992	PIPE	1
1766	2017-08-24	626799	7573160	Warranty	Part	VO-8073055	O-RING	1
1767	2017-08-24	626799	7573160	Warranty	Part	VO-1675066	BOOST O'RING	1
1768	2017-08-24	626799	7573160	Warranty	Part	VO-21695684	SEALING RING	2
1769	2017-08-24	626799	7573160	Warranty	Part	VO-20938964	SEAL	1
1770	2017-08-24	626799	7573160	Warranty	Part	VO-20901584	EXHAUST MANIFOLD	2
1771	2017-08-24	626799	7573160	Warranty	Part	VO-20578932	EXHAUST MANIFOLD	1
1772	2017-08-24	626799	7573160	Warranty	Part	VO-21954674	STRAINER	1
1773	2017-08-24	626799	7573160	Warranty	Part	VO-21516231	FILTER, UDS	1
1774	2017-08-24	626799	7573160	Internal	Part	OTH-DSF62	MACK RED SPRAY PAINT	1
1775	2017-08-24	626799	7573160	Warranty	Part	VO-21876315	LEVEL SENSOR	1
1776	2017-08-24	626799	7573160	Warranty	Part	VO-20937176	FITTING	1
1777	2017-08-24	626799	7573160	Warranty	Part	VO-22894144	AIR DRIER	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1778	2017-08-24	626799	7573160	Warranty	Part	VO-994146	ELBOW NIPPLE	1
1779	2017-08-24	626799	7573160	Warranty	Part	VO-85147470	PIPE	1
1780	2017-08-24	626799	7573160	Warranty	Part	VO-22093827	COOLING COIL	1
1781	2017-08-24	626799	7573160	Internal	Part	MK-FT1868X4X4	QUICK CON. AIR BRA	1
1782	2017-08-24	626799	7573160	Internal	Part	MK-FT3350X4	ELBOW STRE	1
1783	2017-08-24	626799	7573160	Internal	Part	VO-8397699	FITTING	1
1784	2017-08-24	626799	7573160	Internal	Part	MK-FT1880X6X6	CON	1
1785	2017-08-24	626799	7573160	Internal	Part	OTH-F000042	STUD ELBOW (OLIVE TYPE) 5/16"	1
1786	2017-08-24	626799	7573160	Internal	Part	MK-FT3220X4X2	BRASS PIPE	1
1787	2017-08-24	626799	7573160	Warranty	Part	VO-21064733	V-RIBBED BELT 10PK	1
1788	2017-08-24	626799	7573160	Warranty	Part	VO-21631484	BELT TENSIONER	1
1789	2017-08-24	626799	7573160	Warranty	Part	VO-21753149	IDLER PULLEY	1
1790	2017-08-24	626799	7573160	Warranty	Part	VO-21064734	V-RIBBED BELT 8PK*	1
1791	2017-08-24	626799	7573160	Warranty	Part	VO-21422767	BELT TENSIONER	1
1792	2017-08-24	626799	7573160	Warranty	Part	VO-22719937	FAN HUB	1
1793	2017-08-24	626799	7573160	Warranty	Part	VO-953060	STUD	4
1794	2017-08-24	626799	7573160	Warranty	Part	VO-85115602	FAN CLUTCH	1
1795	2017-08-24	626799	7573160	Warranty	Part	VO-994441	BOLT M8*50 FLANGE	1
1796	2017-08-24	626799	7573160	Warranty	Part	VO-25106045	CLAMP HOSE -5/8:	2
1797	2017-08-24	626799	7573160	Internal	Part	MK-160AX568F	SILICON HOSE	0.1
1798	2017-08-24	626799	7573160	Warranty	Part	MK-8235-A11205X272	SEAL PINION INPUT	1
1799	2017-08-24	626799	7573160	Internal	Part	AU2-9770-5073	HOT SHOT DEGREASER	1
1800	2017-08-24	626799	7573160	Warranty	Part	MK-2104-2507018X	KIT BRG RETAINER S	1
1801	2017-08-24	626799	7573160	Warranty	Part	VO-20469515	ELBOW NIPPLE	1
1802	2017-08-24	626799	7573160	Warranty	Part	VO-977030	O-RING	1
1803	2017-08-24	626799	7573160	Warranty	Part	VO-21426909	AIR VALVE	1
1804	2017-08-24	626799	7573160	Warranty	Part	VO-85122800	ATF OIL 1LTR	4
1805	2017-08-24	626799	7573160	Warranty	Part	MK-8235-KIT2638	NUT, PINION RT40	1
1806	2017-08-24	626799	7573160	Warranty	Part	VO-85139619	BACK PRESSURE SENSOR	1
1807	2017-08-24	626799	7573160	Warranty	Part	VO-21582423	HARNES SENSOR KIT, patch	1
1808	2017-08-24	626799	7573160	Warranty	Part	AU2-CAL85121777	B/DOG ULTIMATE 15W-40 5L	1
1809	2017-08-24	626799	7573160	Warranty	Part	VO-21816920	SAFETY VALVE	1
1810	2017-08-24	626799	7573160	Internal	Part	MK-FT1868X8	CON AIR BRAKE ALSO 8397720	1
1811	2017-08-24	626799	7573160	Internal	Part	MK-FT3200X6X4	BRASS PIPE	1
1812	2017-08-24	626799	7573160	Retail	Operation	LO-430	REMOVE AND REPLACE CLUTCH	8.5
1813	2017-08-24	626799	7573160	Retail	Part	VO-22317110	CLUTCH	1
1814	2017-08-24	626799	7573160	Retail	Part	VO-22989055	DISC	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1815	2017-08-24	626799	7573160	Retail	Part	VO-22440568	CYLINDER	1
1816	2017-08-24	626799	7573160	Retail	Part	VO-20992763	AIR HOSE	1
1817	2017-08-24	626799	7573160	Retail	Part	VO-983472	CABLE TIE-GREY HIGH TEMP	5
1818	2017-08-24	626799	7573160	Retail	Part	VO-1652986	BALL BEARING SPIGOT	1
1819	2017-08-24	626799	7573160	Retail	Other	40	SUBLET - MACHINE FLYWHEEL	
1820	2017-08-24	626799	7573160	Warranty	Part	VO-21850113	BRACKET	1
1821	2017-08-24	626799	7573160	Warranty	Part	VO-22995481	PIPE	1
1822	2017-08-24	626799	7573160	Warranty	Operation	VO-2582200	Filter, AdBlue, replace	0.3
1823	2017-08-24	626799	7573160	Warranty	Operation	LO-265	INTERCOOLER WITH CONNECTIONS	0.9
1824	2017-08-24	626799	7573160	Warranty	Operation	VO-2631300	Fan belt tensioner, replace	0.4
1825	2017-08-24	626799	7573160	Warranty	Operation	VO-2630400	Drive belt, replace	0.4
1826	2017-08-24	626799	7573160	Warranty	Operation	VO-3212200	Alternator drive belt, replace	0.4
1827	2017-08-24	626799	7573160	Warranty	Operation	LO-645	STEERING - HYDRAULIC EQUIPMENT	1.4
1828	2017-08-24	626799	7573160	Warranty	Operation	LO-284	CONTROL SYSTEM FUEL SUPPLY	1.3
1829	2017-08-24	626799	7573160	Retail	Other	91	WORKSHOP CONSUMABLES	
1830	2017-05-12	552829	7569855	Retail	Operation	LO-214	VALVE ADJUSTMENT	3
1831	2017-05-12	552829	7569855		Text		P.VALVES AND UNIT INJECTOR ADJUST	
1832	2017-05-12	552829	7569855	Retail	Part	VO-20736230	R/COV.GASKET D16C	1
1833	2017-05-12	552829	7569855	Retail	Part	VO-20723207	SEALING RING	1
1834	2017-05-12	552829	7569855	Retail	Other	91	WORKSHOP CONSUMABLES	
1835	2017-02-03	453293	7565047		Text		RUSSELL 0467 668 898	
1836	2017-02-03	453293	7565047	Warranty	Other	258	muffler	
1837	2017-02-03	453293	7565047	Warranty	Part	VO-21647536	SILENCER	1
1838	2016-12-01	449175	7565087	Warranty	Operation	LO-561	OIL LEAK AT COMPRESSOR	6.2
1839	2016-12-01	449175	7565087		Text		CONTAMINATED AIR DRIER	
1840	2016-12-01	449175	7565087	Warranty	Operation	LO-1940000	Travel Time To Breakdown	1.2
1841	2016-12-01	449175	7565087	Warranty	Other	92	UTE MILEAGE 115 km's	
1842	2016-12-01	449175	7565087	Warranty	Part	VO-992065	O-RING	1
1843	2016-12-01	449175	7565087	Warranty	Part	VO-471708	SEALING RING	1
1844	2016-12-01	449175	7565087	Warranty	Part	MK-8235-S912542007	COMPRESSOR	1
1845	2016-12-01	449175	7565087	Warranty	Part	VO-22896454	AIR DRIER KIT	1
1846	2016-12-01	449175	7565087	Warranty	Part	AU2-CAL85112988	COOLANT 20L VCS BULLDOG	1
1847	2016-12-01	449175	7565087	Internal	Part	AU2-WUR067485080	EMRYCLTH-ROLL-LE-G	0.1
1848	2016-12-01	449175	7565087	Internal	Part	MK-9718-BBC4	BRAKE CLEANER 400G	1
1849	2016-12-01	449175	7565087	Internal	Part	VO-85148766	WHITE GREASE	1
1850	2016-12-01	449175	7565087	Internal	Part	AU2-WUR067320501C	NYLON POWER BUFF 2I	2
1851	2016-12-01	449175	7565087	Warranty	Part	VO-20532891	GASKET	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1852	2016-11-17	439000	7227184		Text		RUSSELL - 0467 668 898	
1853	2016-11-17	439000	7227184	Warranty	Operation	LO-253	RECTIFY BOOST FLUTUATTING	2
1854	2016-11-17	439000	7227184	Warranty	Part	VO-21369922	AIR VALVE	1
1855	2016-11-17	439000	7227184	Warranty	Part	VO-21426909	AIR VALVE	1
1856	2016-10-17	416798	R08001901	Warranty	Operation	VO-1700000	Service and maintenance, general. Secondary operation number	0.3
1857	2016-10-17	416798	R08001901	Warranty	Operation	VO-5240000	Brake control. Secondary operation number	0.4
1858	2016-10-17	416798	R08001901	Warranty	Part	VO-21400412	CLEVIS PIN	1
1859	2016-10-17	416798	R08001901	Warranty	Part	VO-25092821	COTTER PIN-1: X 3/	1
1860	2016-10-17	416798	R08001901	Warranty	Part	VO-996138	WASHER	1
1861	2016-10-17	416798	R08001901	Warranty	Operation	VO-2531400	Control cylinder exhaust brake, replace	1
1862	2016-10-17	416798	R08001901	Warranty	Part	VO-21887528	ACTUATOR SERVICE K	1
1863	2016-10-14	0	7563725		Text		CONTACT : RUSSELL 0467 668 898	
1864	2016-10-14	0	7563725	Retail	Other	251	EPG CYLINDER TO BE REPLACED	
1865	2016-10-14	0	7563725	Retail	Other	5240000	Brake control. Secondary operation	
1866	2016-10-14	0	7563725	Retail	Other	1940100	Action service fee. national	
1867	2016-10-14	0	7563725	Retail	Other	92	VAN MILEAGE ___km's Ö Å1.48/km.	
1868	2016-10-12	412208	7563583	Warranty	Other	251	INTAKE AND EXHAUST PIPES	
1869	2016-10-12	412208	7563583	Warranty	Other	20	Sublet CCTM	
1870	2016-10-12	412208	7563583		Text		EXHAUST LEAK	
1871	2016-10-12	412208	7563583	Warranty	Part	VO-21352841	GASKET	6
1872	2016-10-12	412208	7563583	Warranty	Part	VO-20938964	SEAL	1
1873	2016-10-12	412208	7563583	Warranty	Part	VO-20784537	GASKET - TURBO BASE	1
1874	2016-10-12	412208	7563583	Warranty	Part	VO-420641	GASKET - OIL FEED TURBO	1
1875	2016-10-12	412208	7563583	Warranty	Part	VO-21940610	SEALING RING	1
1876	2016-10-12	412208	7563583	Warranty	Part	VO-470993	GASKET-OIL RETURN	1
1877	2016-10-12	412208	7563583	Warranty	Part	VO-469601	SEALING RING TURBO OIL DRAIN	1
1878	2016-10-12	412208	7563583	Warranty	Part	VO-21940615	SEALING RING	1
1879	2016-09-01	425748	7562337	Warranty	Operation	LO-263	FAN NOT CUTTING IN AND OUT CORRECTLY	2.6
1880	2016-09-01	425748	7562337	Warranty	Part	VO-85115602	FAN CLUTCH	1
1881	2016-09-01	425748	7562337	Internal	Part	VO-6781769	SPLICE-RED(22-18)	7
1882	2016-09-01	425748	7562337	Internal	Part	VO-3963413	ATTACHING RING	1
1883	2016-09-01	425748	7562337	Warranty	Part	VO-21312239	CHARGE AIR HOSE	1
1884	2016-09-01	425748	7562337	Internal	Part	MK-NARV56306	CABLE TIE 1=25PK	1
1885	2016-09-01	425748	7562337	Warranty	Operation	VO-2621400	Piston thermostat, replace	0.8
1886	2016-09-01	425748	7562337		Text		VO/85115602 WAS FITTED BY BRANCH 2300	
1887	2016-09-01	425748	7562337	Warranty	Part	VO-21412639	THERMOSTAT	1
1888	2016-09-01	425748	7562337	Internal	Part	VO-82278971	SWITCH WINDOWS	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1889	2016-09-01	425748	7562337	Warranty	Operation	LO-1940000	Travel Time To Breakdown	1.2
1890	2016-09-01	425748	7562337	Warranty	Other	92	UTE MILEAGE	
1891	2016-09-01	425748	7562337	Warranty	Operation	LO-262	COOLANT PUMP AND THERMOSTAT	0.5
1892	2016-09-01	425748	7562337	Warranty	Operation	LO-260	COOLING SYSTEMS - GENERAL	0.5
1893	2016-09-01	425748	7562337	Warranty	Operation	VO-1700000	Service and maintenance, general. Second	1.2
1894	2016-09-01	425748	7562337	Warranty	Operation	VO-2652200	Charge air hose, replace	0.3
1895	2016-09-01	425748	7562337	Warranty	Operation	LO-265	INTERCOOLER WITH CONNECTIONS	0.5
1896	2016-08-31	384709	7562304		Text		Repair without detail info	
1897	2016-08-09	399800	7224147	Warranty	Operation	VO-2551800	Engine turbocharger, replace. Chassis mo	2.2
1898	2016-08-09	399800	7224147	Warranty	Other	20	SUBLET - TOW TO WORKSHOP	
1899	2016-08-09	399800	7224147	Warranty	Part	VO-21638569	TURBOCHARGER HE551	1
1900	2016-08-09	399800	7224147		Text		S/N H160334088	
1901	2016-08-09	399800	7224147	Warranty	Part	VO-C21638569	TURBOCHARGER EXCH	1
1902	2016-08-09	399800	7224147	Warranty	Part	MK-57MD42M	***ELEMENT, AIR 'C	2
1903	2016-08-09	399800	7224147	Warranty	Part	VO-21504560	CHARGE AIR COOLER	1
1904	2016-08-09	399800	7224147	Warranty	Part	MK-590GB321A	GASKET, TURBO MOUN	1
1905	2016-08-09	399800	7224147	Warranty	Part	VO-21940610	SEALING RING	1
1906	2016-08-09	399800	7224147	Warranty	Part	VO-21940615	SEALING RING	1
1907	2016-08-09	399800	7224147	Warranty	Part	VO-469601	SEAL RING	1
1908	2016-08-09	399800	7224147	Warranty	Part	VO-470993	GASKET	1
1909	2016-08-09	399800	7224147	Warranty	Part	VO-1543499	FLANGE NUT	4
1910	2016-08-09	399800	7224147	Warranty	Part	VO-21647536	SILENCER	1
1911	2016-08-09	399800	7224147	Warranty	Part	VO-420643	GASKET	1
1912	2016-08-09	399800	7224147	Warranty	Part	VO-20478809	INLET HOSE	1
1913	2016-08-09	399800	7224147	Warranty	Part	VO-990950	FLANGE LOCK NUT	1
1914	2016-08-09	399800	7224147	Warranty	Part	VO-994441	FLANGE SCREW	1
1915	2016-08-09	399800	7224147	Warranty	Part	VO-21345127	STUD	2
1916	2016-08-09	399800	7224147	Warranty	Part	VO-21312239	CHARGE AIR HOSE	1
1917	2016-08-09	399800	7224147	Warranty	Part	VO-21765997	CHARGE AIR HOSE	1
1918	2016-08-09	399800	7224147	Warranty	Part	AU2-CAL85121795	VDS4 BULK ENGINE O	7
1919	2016-08-09	399800	7224147	Warranty	Other	1940000	TOWED IN	
1920	2016-08-09	399800	7224147	Warranty	Operation	VO-2650200	Charge air cooler, replace	1.2
1921	2016-08-09	399800	7224147	Warranty	Operation	VO-2586200	SCR catalytic muffler, replace	1.5
1922	2016-08-09	399800	7224147	Warranty	Operation	LO-255	EXTRA TIME	4.6
1923	2016-05-21	316277	7559446		Text		S5102 Peep Window Hinge, CSM CMM	
1924	2016-05-21	316277	7559446	Warranty	Operation	VO-3750000	Cabin cable system. Secondary operation	0.2
1925	2016-05-21	316277	7559446	Warranty	Operation	VO-8510000	Upholstery for door, wall/side, rear she	0.3

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1926	2016-05-21	316277	7559446	Warranty	Part	VO-969550	SCREW	4
1927	2016-05-21	316277	7559446	Warranty	Part	VO-990965	HEXAGON NUT	4
1928	2016-05-21	316277	7559446	Retail	Operation	LO-1940000	Travel Time To HoyHaul	1.2
1929	2016-05-21	316277	7559446	Retail	Other	92	VAN MILEAGE 115 km's Ö Å0.80/km.	
1930	2016-05-14	310089	V359763	Warranty	Operation	VO-3710200	Electric wires and connections, check	0.4
1931	2016-05-14	310089	V359763	Warranty	Operation	VO-3732700	Engine harness, replace	4.6
1932	2016-05-14	310089	V359763	Warranty	Part	VO-21846096	CABLE HARNESS	1
1933	2016-05-10	307688	7221323		Text		RUSSELL - 0467 668 898	
1934	2016-05-10	307688	7221323	Warranty	Operation	LO-254	RECTIFY ADBLUE FAULT	1.7
1935	2016-04-25	296420	RPH888	Warranty	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
1936	2016-04-25	296420	RPH888	Warranty	Operation	VO-1701200	Fault codes, reading	0.2
1937	2016-04-25	296420	RPH888	Warranty	Operation	VO-2530000	REPAIR AIR LINE	0.6
1938	2016-04-25	296420	RPH888	Warranty	Operation	1940000	A/H MIN LABOUR CHARGE	1.56
1939	2016-04-25	296420	RPH888	Warranty	Operation	1940000	TRAVEL TO BREAKDONW	0.44
1940	2015-12-24	219300	RPF782	Warranty	Operation	VO-1820200	Localised wash for fault tracing	0.3
1941	2015-12-24	219300	RPF782	Warranty	Operation	VO-2123200	Flywheel housing sealant, replace	11.8
1942	2015-12-24	219300	RPF782	Warranty	Operation	VO-2150700	Sealant, timing gear plate, replace. Timing gears removed	0.9
1943	2015-12-24	219300	RPF782	Warranty	Operation	VO-2153100	Timing gears, replace (all). Casing and oil pan removed	1.3
1944	2015-12-24	219300	RPF782	Warranty	Operation	VO-2160700	Flywheel bearing, replace. Clutch removed	0.2
1945	2015-12-24	219300	RPF782	Warranty	Operation	VO-2162100	Flywheel, replace. Gearbox and clutch removed	0.7
1946	2015-12-24	219300	RPF782	Warranty	Operation	VO-4110100	Clutch, replace	4.1
1947	2015-12-24	219300	RPF782	Warranty	Operation	VO-4112600	Clutch wear, check. VCADS Pro operation	0.2
1948	2015-12-24	219300	RPF782	Warranty	Operation	VO-4317000	Gearbox, remove	0.8
1949	2015-12-24	219300	RPF782	Warranty	Operation	VO-4317200	Gearbox, install	1.5
1950	2015-12-24	219300	RPF782	Warranty	Part	MK-2104-2507018X	KIT BRG RETAINER S	2
1951	2015-12-24	219300	RPF782	Warranty	Part	VO-20483919	HEX. SOCKET SCREW	5
1952	2015-12-24	219300	RPF782	Warranty	Part	VO-20734156	SEALING STRIP	1
1953	2015-12-24	219300	RPF782	Warranty	Part	VO-20815558	SEALING STRIP	1
1954	2015-12-24	219300	RPF782	Warranty	Part	VO-20852765	GASKET	4
1955	2015-12-24	219300	RPF782	Warranty	Part	VO-20966752	O-RING	1
1956	2015-12-24	219300	RPF782	Warranty	Part	VO-21015266	SCREW	6
1957	2015-12-24	219300	RPF782	Warranty	Part	VO-21532261	SEALING RING	1
1958	2015-12-24	219300	RPF782	Warranty	Part	VO-21557105	TIMING GEAR COVER	1
1959	2015-12-24	219300	RPF782	Warranty	Part	VO-22206111	TIMING GEAR PLATE	1
1960	2015-12-24	219300	RPF782	Warranty	Part	VO-471708	SEALING RING	1
1961	2015-12-24	219300	RPF782	Warranty	Part	VO-8192804	SCREW	8
1962	2015-12-24	219300	RPF782	Warranty	Part	VO-85108352	CRANKSHAFT SEAL	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
1963	2015-12-24	219300	RPF782	Warranty	Part	VO-943177	O-RING	1
1964	2015-12-24	219300	RPF782	Warranty	Part	VO-975197	FLANGE SCREW	2
1965	2015-12-24	219300	RPF782	Warranty	Part	VO-976068	O-RING	1
1966	2015-12-24	219300	RPF782	Warranty	Part	VO-977030	O-RING	1
1967	2015-12-24	219300	RPF782	Warranty	Part	VO-983762	HEX. SOCKET SCREW	1
1968	2015-12-24	219300	RPF782	Warranty	Part	VO-984735	FLANGE SCREW	25
1969	2015-12-24	219300	RPF782	Warranty	Part	VO-984816	FLANGE SCREW	13
1970	2015-12-24	219300	RPF782	Warranty	Part	VO-992065	O-RING	1
1971	2015-12-24	219300	RPF782	Warranty	Part	VO-471708	SEALING RING	1
1972	2015-12-24	219300	RPF782	Warranty	Operation	VO-2510400	Gaskets, exhaust manifold, replace	2.7
1973	2015-12-24	219300	RPF782	Warranty	Part	VO-21352841	GASKET	6
1974	2015-12-24	219300	RPF782	Warranty	Part	VO-969550	SCREW	4
1975	2015-12-24	219300	RPF782	Warranty	Part	VO-990965	HEXAGON NUT	4
1976	2015-12-24	219300	RPF782	Warranty	Operation	VO-2550000	ADDITIONAL TIME	0.8
1977	2015-12-24	219300	RPF782	Warranty	Operation	VO-2551800	Engine turbocharger, replace	2.2
1978	2015-12-24	219300	RPF782	Warranty	Part	VO-1543499	FLANGE NUT	4
1979	2015-12-24	219300	RPF782	Warranty	Part	VO-20784537	GASKET	1
1980	2015-12-24	219300	RPF782	Warranty	Part	VO-21345127	STUD	4
1981	2015-12-24	219300	RPF782	Warranty	Part	VO-21940615	SEALING RING	1
1982	2015-12-24	219300	RPF782	Warranty	Part	VO-420641	GASKET	1
1983	2015-12-24	219300	RPF782	Warranty	Part	VO-469601	SEAL RING	1
1984	2015-12-24	219300	RPF782	Warranty	Part	VO-470993	GASKET	1
1985	2015-12-24	219300	RPF782	Warranty	Operation	VO-4118300	Valve assembly, clutch, replace	0.4
1986	2015-12-24	219300	RPF782	Warranty	Part	VO-22327069	SOLENOID VALVE	1
1987	2015-12-15	214140	7552254		Text		RUSSELL 0467 668 898	
1988	2015-12-15	214140	7552254	Warranty	Operation	VO-2631300	Fan belt tensioner, replace	0.4
1989	2015-12-15	214140	7552254	Warranty	Operation	LO-352	LIGHTING - FRONT LIGHTS	0.6
1990	2015-12-15	214140	7552254	Warranty	Operation	LO-762	ANTI-ROLL BAR	0.7
1991	2015-12-15	214140	7552254	Warranty	Operation	LO-725	SPRINGS-FR.SUSPENS,HYDRAULIC & GAS SPRNG	0.7
1992	2015-12-15	214140	7552254	Warranty	Part	VO-21422767	BELT TENSIONER	1
1993	2015-12-15	214140	7552254	Internal	Part	VO-21479276	BELT TENSIONER	1
1994	2015-12-15	214140	7552254	Warranty	Part	VO-21064733	V-RIBBED BELT 10PK	1
1995	2015-12-15	214140	7552254	Internal	Part	VO-21064734	V-RIBBED BELT 8PK*	1
1996	2015-12-15	214140	7552254	Warranty	Part	VO-21753149	IDLER PULLEY	1
1997	2015-12-15	214140	7552254	Warranty	Part	VO-25109292	LAMP	2
1998	2015-12-15	214140	7552254	Warranty	Part	VO-85139953	VALVE - REPLC BY 85144423	1
1999	2015-12-15	214140	7552254	Warranty	Part	VO-990996	FLANGE SCREW	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2000	2015-12-15	214140	7552254	Warranty	Part	VO-994527	FLANGE LOCK NUT	1
2001	2015-12-15	214140	7552254	Warranty	Part	VO-21341754	SHOCK ABSORBER	1
2002	2015-12-15	214140	7552254		Text		NOISE IN FAN	
2003	2015-12-15	214140	7552254	Warranty	Operation	LO-263	FANS,FAN SHROUDS AND COUPLINGS	0.3
2004	2015-12-15	214140	7552254		Text		DRIVE HEIGHT LEVEL VALVE LEAKING	
2005	2015-12-15	214140	7552254		Text		LH FIRST DRIVE SHOCK LEAKING OIL	
2006	2015-12-15	214140	2382582		Text		RUSSELL 0467 668 898	
2007	2015-12-15	214140	2382582	Internal	Part	VO-21479276	BELT TENSIONER	1
2008	2015-12-15	214140	2382582	Internal	Part	VO-21064734	V-RIBBED BELT 8PK*	1
2009	2015-12-14	213519	7551940	Warranty	Operation	LO-561	COMPRESSOR, GOVERNOR, ANTI-FREEZE DEVICE	0.6
2010	2015-12-14	213519	7551940	Warranty	Part	VO-22024367	SAFETY VALVE	1
2011	2015-12-14	213519	7551940		Text		REPAIR AIR LEAK AT COMPRESSOR DISCHARGE SAFTEY CHECK VALVE	
2012	2015-12-14	213519	7552944	Warranty	Operation	LO-641	STEERING - COLUMN, STEERING SHAFT	0.5
2013	2015-12-14	213519	7552944	Warranty	Part	VO-21006995	STEERING SHAFT	1
2014	2015-12-14	213519	7552944	Internal	Part	OTH-196498640	GREASE NIPPLES	1
2015	2015-12-14	213519	7552944	Warranty	Operation	LO-761	SHOCK ABSORBERS	0.7
2016	2015-12-14	213519	7552944	Warranty	Operation	LO-872	AIR CONDITIONING - AIR DISTRIBUTION	0.5
2017	2015-12-14	213519	7552944	Warranty	Part	VO-21341754	SHOCK ABSORBER	1
2018	2015-12-14	213519	7552944	Warranty	Part	VO-82441116	SEALING MOULDING	1
2019	2015-12-14	213519	7552944	Warranty	Operation	LO-491	gearbox oil cooler hoses leaking	2.2
2020	2015-12-14	213519	7552944	Warranty	Part	VO-22429386	OIL HOSE	1
2021	2015-12-14	213519	7552944	Warranty	Part	VO-22429384	OIL HOSE	1
2022	2015-12-14	213519	7552944		Text		TOP STEERING SHAFT RATTLING	
2023	2015-12-14	213519	7552944		Text		NEED GREASE NIPPLES FITTED TO NEW SHAFT	
2024	2015-12-14	213519	7552944		Text		LHR SHOCK LEAKING	
2025	2015-12-14	213519	7552944		Text		BONNET SEALING RUBBER ON COWL COME AWAY	
2026	2015-12-14	213519	7552944	Warranty	Operation	LO-491	MISCELLANEOUS - OIL COOLER-TRANSMISSION	0.5
2027	2015-11-23	220600	7554631		Text		RUSSELL 0467 668 898	
2028	2015-11-23	220600	7554631	Warranty	Other	261	radiator leaking coolant	
2029	2015-11-23	220600	7554631	Warranty	Part	VO-21726745	RADIATOR	1
2030	2015-11-23	220600	7554631	Warranty	Part	AU2-CAL85112988	COOLANT 20L VCS BULLDOG	3
2031	2015-11-23	220600	7554631		Text		ra	
2032	2015-11-23	220600	7554631		Text		no fitment invoice receive from hoyhaul. 15.1. ra	
2033	2015-11-23	220600	7554631		Text		need to get maddox to bill what ever coolant gets knocked	
2034	2015-11-23	220600	7554631		Text		back to hoyhaul	
2035	2015-10-30	172852	7553933	Warranty	Other	721	RHR DRIVE SHOCK LEAKING	
2036	2015-10-30	172852	7553933	Warranty	Other	451	PROPELLER SHAFT	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2037	2015-10-30	172852	7553933	Warranty	Part	VO-21341754	SHOCK ABSORBER	1
2038	2015-10-30	172852	7553933	Warranty	Part	VO-21341754	SHOCK ABSORBER	1
2039	2015-10-30	172852	7553933	Warranty	Part	MK-2104-SPL250SF3X	SPL DRIVELINE KIT	1
2040	2015-10-30	172852	7553933	Warranty	Part	MK-2104-2507018X	KIT BRG RETAINER S	1
2041	2015-10-30	172852	7553933		Text		RHR DRIVE SHOCK LEAKING	
2042	2015-10-30	172852	7553933	Warranty	Other	70	SUBLET - CCTM	
2043	2015-10-30	172852	7553933	Warranty	Other	40	SUBLET - CCTM	
2044	2015-10-30	172852	7553933		Text		LHF DRIVE SHOCK LEAKING	
2045	2015-10-30	172852	7553933		Text		UNI JOINT NEAREST TO CENTER BEARING EXCESSIVE MOVEMENT	
2046	2015-09-23	153350	7553198	Warranty	Operation	VO-2182000	Engine mounting pad, replace (left rear)	3.1
2047	2015-09-23	153350	7553198	Warranty	Part	VO-20499469	RUBBER CUSHION	2
2048	2015-09-23	153350	7553198		Text		ENGINE MOUNTS SPLIT AND RUBBER CRACKED	
2049	2015-09-23	153350	7553198	Warranty	Operation	VO-2182100	Engine mounting pad, replace (right rear	4.1
2050	2015-09-23	153350	7553198		Text		rear)	
2051	2015-09-23	153350	7553198	Warranty	Operation	VO-1900000	Miscellaneous, general. Secondary operat	0.3
2052	2015-09-23	153350	7553198		Text		operation number	
2053	2015-09-03	131967	7552693		Text		Repair without detail info	
2054	2015-08-28	132256	7552557	Warranty	Part	VO-21272103	PIPE	1
2055	2015-08-28	132256	7552557	Warranty	Other	261	RADIATOR AND CONNECTION PARTS	
2056	2015-08-28	132256	7552557	Warranty	Other	20	Sublet repairs engine	
2057	2015-08-21	131967	7552380	Warranty	Operation	LO-1940000	Travel Time To Breakdown	4.5
2058	2015-08-21	131967	7552380		Text		TRAVEL TO KEW NSW	
2059	2015-08-21	131967	7552380	Warranty	Other	92	VAN MILEAGE 404 km's Ö Å0.98/km.	
2060	2015-08-21	131967	7552380	Warranty	Operation	LO-261	RADIATOR AND CONNECTION PARTS	1.3
2061	2015-08-21	131967	7552380	Warranty	Part	AU2-CAL85112988	COOLANT 20L VCS BULLDOG	3
2062	2015-08-21	131967	7552380	Warranty	Part	VO-21052612	CONNECTOR	1
2063	2015-08-21	131967	7552380	Warranty	Part	VO-21339891	RUBBER HOSE	1
2064	2015-08-21	131967	7552380	Warranty	Part	VO-21380391	CONNECTOR	1
2065	2015-08-21	131967	7552380		Text		give to sam once arrived as its to replace the one he had in his offic	
2066	2015-08-21	131967	7552380		Text		e	
2067	2015-08-21	131967	7552380	Internal	Part	OTH-PARTS ON ORDEI	PARTS ON W/SHOP HOLD SHELF	
2068	2015-08-21	131967	7552380		Text		COOLANT LEAK - LOST ALL COOLANT	
2069	2015-08-21	131967	7552380		Text		Transferred to Order Number 7552693	
2070	2015-08-21	130918	7552346		Text		RUSSELL 0467 668 898	
2071	2015-08-21	130918	7552346	Retail	Operation	VO-2141300	Valves and unit injectors, adjust	3.6
2072	2015-08-21	130918	7552346	Retail	Operation	VO-1940100	Volvo action service fee. national	1.1
2073	2015-08-21	130918	7552346		Text		HOYHAUL YARD	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2074	2015-08-21	130918	7552346	Retail	Other	92	VAN MILEAGE 115 km's Ö Å1.38/km.	
2075	2015-08-21	130918	7552346		Text		P.VALVES AND UNIT INJECTORS ADJUSTMENT	
2076	2015-08-21	130918	7552346		Text		C.SCHEDULED/DUE	
2077	2015-08-21	130918	7552346		Text		R.-REMOVE AIR CLEANER	
2078	2015-08-21	130918	7552346		Text		-REMOVE ROCKER COVER	
2079	2015-08-21	130918	7552346		Text		-ADJUST VALVES AND UNIT INJECTORS	
2080	2015-08-21	130918	7552346		Text		-REFIT ROCKER COVER	
2081	2015-08-21	130918	7552346		Text		-REFIT AIR CLEANER	
2082	2015-08-18	104017	7552255		Text		RUSSELL 0467 668 898	
2083	2015-08-18	104017	7552255	Warranty	Operation	LO-234	FUEL TANK RUBBERS WORN/SPLIT	1.9
2084	2015-08-18	104017	7552255	Warranty	Part	VO-20730650	STRIP	9
2085	2015-05-04	57087	7549506		Text		RUSSEL 0467 668 898	
2086	2015-05-04	57087	7549506		Text		WAITING	
2087	2015-05-04	57087	7549506	Warranty	Operation	LO-371	Ad blue level wiring	2.7
2088	2015-05-04	57087	7549506	Warranty	Operation	LO-383	set K factor	1.3
2089	2015-05-04	57087	7549506	Warranty	Part	MK-NARV52700BL	FUSE 1=5PK MINI	1
2090	2015-05-04	57087	7549506	Warranty	Part	MK-NARV56310	CABLE TIE 1=10PK	1
2091	2015-05-04	57087	7549506	Warranty	Part	VO-6781769	SPLICE-RED(22-18)	2
2092	2015-05-04	57087	7549506		Text		ra	
2093	2015-05-04	54200	7549494	Warranty	Operation	LO-561	COMPRESSOR, GOVERNOR, ANTI-FREEZE DEVICE	0.6
2094	2015-05-04	54200	7549494	Warranty	Part	VO-966458	NIPPLE	1
2095	2015-05-04	54200	7549494	Warranty	Part	VO-8082135	ELBOW NIPPLE	1
2096	2015-05-04	54200	7549494	Warranty	Part	VO-21329215	DOOR STOP	1
2097	2015-05-04	54200	7549494		Text		AIR LEAK AT COMPRESSOR/ENGINE	
2098	2015-05-04	54200	7549494	Warranty	Operation	LO-565	COMPRESSED-AIR LINE & CONNECTION PARTS	0.3
2099	2015-05-04	54200	7549494		Text		AIR LEAK AT CHASSIS	
2100	2015-05-04	54200	7549494	Warranty	Operation	LO-831	SIDE DOORS,HINGES,DOOR STOPS	0.5
2101	2015-05-04	54200	7549494		Text		DOOR STOP BENT	
2102	2015-03-03	14807	7548172	Internal	Operation	VO-1721000	Warranty service. After 4 weeks or maxim	5
2103	2015-03-03	14807	7548172		Text		maximum 10 000 km.	
2104	2015-03-03	14807	7548172	Internal	Part	VO-85114535	FILTER KIT - NEW BREED	1
2105	2015-03-03	14807	7548172	Internal	Part	MK-99SX29414	KIT ANALYSIS OIL	4
2106	2015-03-03	14807	7548172	Retail	Part	AU2-CAL85121795	BULK 15W-40 ENGINE OIL VDS4	55
2107	2015-03-03	14807	7548172	Retail	Part	AU2-CAL85121714	BULK SAE50 TRANS OIL VOLVO	16
2108	2015-03-03	14807	7548172	Retail	Part	AU2-CAL85121715	BULK 85W140 GEAR OIL VOLVO	38
2109	2015-03-03	14807	7548172	Retail	Part	AU2-CAL85121715	BULK 85W140 GEAR OIL VOLVO	
2110	2015-03-03	14807	7548172	Retail	Part	AU2-CAL85121715	BULK 85W140 GEAR OIL VOLVO	

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2111	2015-03-03	14807	7548172		Text		P.MACK FIRST SERVICE	
2112	2015-03-03	14807	7548172		Text		C.SCHEDULED/DUE	
2113	2015-03-03	14807	7548172		Text		R.CARRY OUT MACK FIRST SERVICE	
2114	2015-01-06	511	7546807		Text		WORKSHOP Chrome Intake Snorkels 1000.00	
2115	2015-01-06	511	7546807		Text		PARTS Supply 35Ltr Waeco Fridge 800.00	
2116	2015-01-06	511	7546807	Internal	Operation	LO-251	Chrome Intake Snorkels	2
2117	2015-01-06	511	7546807	Internal	Operation	LO-284	Engine Upgrade to 685Hp	1
2118	2015-01-06	511	7546807	Internal	Operation	LO-922	S&F JSK37 Grless T/T Paint Red 225 heigh	5
2119	2015-01-06	511	7546807	Internal	Operation	LO-171L41P	Predelivery Mack	11.3
2120	2015-01-06	511	7546807	Internal	Operation	VO-1710200	Delivery service	2
2121	2015-01-06	511	7546807	Internal	Other	891	Supply 35Ltr Waeco Fridge	
2122	2015-01-06	511	7546807	Internal	Other	891	Supply 685Hp Badges	
2123	2015-01-06	511	7546807	Internal	Operation	LO-891	Transfers	2
2124	2015-01-06	511	7546807	Internal	Operation	LO-891	Detail	3
2125	2015-01-06	511	7546807	Internal	Operation	LO-891	Newcastle Kit Mack	4
2126	2015-01-06	511	7546807	Internal	Operation	LO-ADR	New Truck Rego Check - A136.50	1
2127	2015-01-06	511	7546807		Text		Note: Turntable Height 225mm from chassis rail.	
2128	2015-01-06	511	7546807	Internal	Part	MK-TIETR6000	AIR INTAKE T-RAM	2
2129	2015-01-06	511	7546807	Internal	Part	VO-21707766	LABEL MP10 685HP	2
2130	2015-01-06	511	7546807	Internal	Part	AU2-WAECFX35	34.5 ltr fridge fr	1
2131	2015-01-06	511	7546807	Internal	Part	MK-MSC015DGML	SEAT COVER-BB GREY	1
2132	2015-01-06	511	7546807	Internal	Part	VO-21325853	PLATE	4
2133	2015-01-06	511	7546807	Internal	Part	VO-25168181	NAMEPLATE,CUSTOM	1
2134	2015-01-06	511	7546807	Internal	Part	MK-3281-MSSV109C	DOOR KICK PLATES	1
2135	2015-01-06	511	7546807	Internal	Part	MK-34RU29406M	WEATHERSHIELDHIVIS	1
2136	2015-01-06	511	7546807	Internal	Part	MK-44QL39403M	REINFORCEMENT MUD	2
2137	2015-01-06	511	7546807	Internal	Part	MK-47QM49402M7	MUDFLAP MACK 24 X 13	4
2138	2015-01-06	511	7546807	Internal	Part	VO-85116338	FLOOR MAT SET NEW BRD	1
2139	2015-01-06	511	7546807	Internal	Part	MK-9711-00116MK	HUBCAP	2
2140	2015-01-06	511	7546807	Internal	Part	MK-9711-9103MK	HUB CAP 8" MACK LOGO	4
2141	2015-01-06	511	7546807	Internal	Part	MK-9732-8074BP	COVER NUT 33MM PK	6
2142	2015-01-06	511	7546807	Internal	Part	VO-984754	BOLT M10*35 FLANGE 10.9	16
2143	2015-01-06	511	7546807	Internal	Part	VO-990951	LOCK NUT M10 FLANGE	16
2144	2015-01-06	511	7546807	Internal	Part	OTH-7856013	TAPE REFLECTIVE RED	2
2145	2015-01-06	511	7546807	Internal	Operation	LO-5000	BRAKES	1
2146	2015-01-06	511	7546807		Text		MOVE SUZI COILS	
2147	2015-01-06	511	7546807	Internal	Part	VO-25152776	NYLON TUBE 1/2 BLACK	2

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2148	2015-01-06	511	7546807	Internal	Part	MK-NARV56306	CABLE TIE 1=25PK	2
2149	2015-01-06	511	7546807	Internal	Part	AU2-9703-JSK37CW2	JSK 37 CW/185 C/W	1
2150	2015-01-06	511	7546807	Internal	Part	AU2-9703-BOLTS	BOLT KIT	1
2151	2015-01-06	511	7546807	Internal	Part	MK-FREIGHT	FREIGHT	150
2152	2015-01-06	511	7546807		Text		FREIGHT CHARGE Å150.00	
2153	2015-01-06	511	7546807	Internal	Part	OTH-937333482	BLIND RIVET 4.8MM X 17MM	10
2154	2015-01-06	511	7546807	Internal	Part	VO-21079466	SCREW	4
2155	2015-01-06	511	7546807	Internal	Part	MK-FANSUNGLASSES	SUNGLASSES (all)	2
2156	2015-01-06	511	7546807		Text		TAKEN BY CRAIG WHITE 16/01	
2157	2015-01-06	511	7546807	Internal	Part	VO-85122956	PROTECTING COVER	1
2158	2015-01-06	511	7546807	Internal	Part	VO-21047317	HOSE GUIDE,POGO ST	1
2159	2015-01-06	511	7546807	Internal	Operation	LO-891	Final Predelivery, roadtest & check	1
2160	2015-01-06	511	7546807	Internal	Operation	LO-712L433	TURNTABLE	2
2161	2015-01-06	511	7546807		Text		The turntable has been fitted, however incorrectly, could yo	
2162	2015-01-06	511	7546807		Text		HOYHAUL PTY LTD	
2163	2015-01-06	511	7546807	Internal	Operation	LO-840	S&F LHS Weathershield	1
2164	2015-01-06	511	7546807	Internal	Part	VO-82279626	SWITCH- DRIVING LIGHTS	1
2165	2015-01-06	511	7546807	Internal	Part	MK-ABC78020	SUZI COIL	1
2166	2015-01-06	511	7546807	Internal	Part	MK-ABCABF349	ADAPTOR FEMALE	1
2167	2015-01-06	511	7546807	Internal	Part	MK-ABCABF218	COUPLING, FEMALE 1	1
2168	2015-01-06	511	7546807	Internal	Part	MK-NARV56306	CABLE TIE 1=25PK	2
2169	2015-01-06	511	7546807	Internal	Part	MK-5166-56747	LOCTITE, 567 PIPE	1
2170	2015-01-06	511	7546807		Text		Taken by Hoyhaul	
2171	2015-01-06	511	7546807		Text		Taken by Hoyhaul	
2172	2015-01-06	511	7546807		Text		Taken by Hoyhaul	
2173	2015-01-06	511	7546807		Text		Taken by Hoyhaul	
2174	2015-01-06	511	7546807		Text		Taken by Hoyhaul	
2175	2015-01-06	511	7546807		Text		Taken by Hoyhaul	
2176	2015-01-06	511	7546807	Internal	Part	VO-82100248	STORAGE BOX	3
2177	2015-01-06	511	7546807	Internal	Part	VO-21320978	CONNECTOR	3
2178	2015-01-06	511	7546807	Internal	Part	AU2-ENGMT27F	Chest Fridge / Fre	2
2179	2015-01-06	511	7546807	Warranty	Operation	LO-563	BRAKE VALVE AND OTHER VALVE	1
2180	2015-01-06	511	7546807		Text		GRADE GRIPPER TAKES LONG TIME TO RELEASE - CARRY OUT REPAIR	
2181	2015-01-06	511	7546807		Text		AS PER CAMPAIGN S5105	
2182	2015-01-06	511	7546807	Warranty	Part	VO-21169875	VALVE	1
2183	2015-01-06	511	7546807	Warranty	Part	VO-22513841	BRACKET	1
2184	2015-01-06	511	7546807	Warranty	Part	VO-3082875	PLUG	1

VSR Report - 2015 Mack Superliner
Chassis Number 6FMT14H69ED805979

15Apr 2026

	A	B	C	D	E	F	G	H
1	Repair date	Mileage	Order nr	Payment	Detail type	Code	Description (Original)	#
2185	2015-01-06	511	7546807	Warranty	Part	VO-8397703	FITTING CAN USE FT1868X6	2
2186	2015-01-06	511	7546807	Warranty	Part	VO-8397706	FITTING	1
2187	2015-01-06	511	7546807	Warranty	Part	VO-990950	NUT M8 FLANGED LOCKING	3
2188	2015-01-06	511	7546807	Warranty	Part	MK-ABCABT6	TUBE NYLON 3/8: BL	0.5
2189	2015-01-06	511	7546807	Warranty	Part	VO-984735	BOLT M8*25 FLANGE	3
2190	2015-01-06	511	7546807	Internal	Part	MK-34RU29406M2	WEATHERSHIELDHIVIS	1
2191	2015-01-06	511	7546807	Internal	Part	MK-ABCABF109	COUPLING, 1/2: FEM	1
2192	2015-01-06	511	7546807	Internal	Part	MK-ABCABF108	ADAPTOR, FEMALE 1/	1
2193	2015-01-06	511	7546807	Internal	Part	VO-8399115	MOUNTING PLUG	2
2194	2015-01-06	511	7546807	Internal	Part	VO-975197	BOLT M8*20 FLANGE	2
2195	2015-01-06	511	7546807	Warranty	Other	40	SUBLET - DRIVELINE SERVICES	
2196	2015-01-06	511	7546807	Internal	Other	40	SUBLET - ONEILS	
2197	2015-01-06	511	7546807	Internal	Part	OTH-669231001	CUTTING DISC 100X1.0X16MM	2
2198	2015-01-06	511	7546807	Warranty	Part	MK-2104-2507018X	KIT BRG RETAINER S	3
2199	2015-01-06	511	7546807	Warranty	Part	MK-2104-1707018X	KIT BRG RETAINER S	2
2200	2015-01-06	511	7546807		Text		balance twin d/shaft & nsingle jack shaft	
2201	2015-01-06	511	7546807	Internal	Part	OTH-DRPACK2014A2	DRIVERS KIT 2XL-MACK	1
2202	2015-01-06	511	7546807		Text		WORKSHOP Engine Upgrade to 685Hp 1.00	
2203	2015-01-06	511	7546807		Text		WORKSHOP S&F JSK37 Grless T/T Paint Red 225 hei 3400.00	
2204	2015-01-06	511	7546807		Text		WORKSHOP Predelivery Mack 751.00	
2205	2015-01-06	511	7546807		Text		WORKSHOP Primax Predelivery 223.00	
2206	2015-01-06	511	7546807		Text		PARTS Supply 685Hp Badges 100.00	
2207	2015-01-06	511	7546807		Text		WORKSHOP Transfers 200.00	
2208	2015-01-06	511	7546807		Text		WORKSHOP Detail 300.00	
2209	2015-01-06	511	7546807		Text		WORKSHOP Newcastle Kit Mack 1103.00	
2210	2015-01-06	511	7546807		Text		WORKSHOP New Truck Rego Check - Å136.50	
2211	2015-01-06	511	7546807		Text		Note: Turntable Height 225mm from chassis rail.	
2212	2015-01-06	511	7546807	Warranty	Other	601	GENERAL - WHEEL ALIGNMENT	
2213	2015-01-06	511	7546807		Text		VIBRATION AND WANDERING IN STEERING	
2214	2015-01-06	511	7546807	Warranty	Other	60	SUBLET - STEERING ALIGNMENT	
2215	2015-01-06	511	7546807	Warranty	Operation	LO-451	PROPELLER SHAFT	2.7
2216	2015-01-06	511	7546807		Text		u please arrange to have it moved back to 180 FOC as origina	
2217	2015-01-06	511	7546807		Text		lly requested ? no drilling required.	