



Vehicle History Summary

Fleet #	T10
Registration	10KJP
Make	MACK
Model	TRIDENT
VIN / Chassis #	6FMM12H69KD810927
Build Date	05/2019

Date	Reading / Units	Type / Repairer Notes	Repairer
		T-704	
		T-704	
		T-704	
01/12/2025	994,387 kms	Windscreen R-3404	
24/10/2025	982,113 kms	B - B Service S-1312 Service completed Ice pack kill solenoid wire resoldered. All test batteries were faulty and replaced x 4	
24/10/2025		Power Steering R-3370 Removed and Replaced Steering Box	
01/10/2025		B - B Service S-1298 R/R LH steer brake hose R/R Suzi ends, R/R trailer plug Power steering resovir was leaking, R/R seals Repair check plate bolts Transmission mounts need replacing at next service Power steering box main seal leaking	
19/07/2025	955,015 kms	NHVR Inspection Checklist I-463 Inspection Complete	
15/07/2025	952,288 kms	New T-794	Ocean Tyres
07/05/2025	939,130 kms	New T-786	Ocean Tyres
26/04/2025	936,759 kms	Engine Tune Up R-3319 Tune up complete	
03/04/2025	931,283 kms	alternator tensioner, bonnet straps, drive belt tensioner, Fan Belt R-3301 R & R fan belt and tensioner R & R bonnet strap	KJP workshop - Mitchell Breen, KJP Workshop - Scarlett Guvyner-Treanor
02/04/2025	931,283 kms	C - C Service S-1236 Conduct C service replaced alternator pulley Wheel alignment Brake test	KJP workshop - Ricky Jones, KJP workshop - Scott Laburniy
24/02/2025	920,977 kms	B - B Service S-1229	
02/10/2024	896,888 kms	New T-749	Ocean Tyres
30/09/2024	892,151 kms	Drive Tyres T-748	Ocean Tyres
02/09/2024	879,787 kms	B - B Service S-1175 brake test - PASSED	
19/08/2024	874,056 kms 13,298 hrs	exhaust elbow, exhaust rattle R-3260	

Date	Reading / Units	Type / Repairer Notes	Repairer
25/07/2024	859,995 kms	NHVR Inspection Checklist I-386 brake test - PASSED	
17/07/2024		New T-735	Ocean Tyres
09/07/2024		Parts O-249 Relacement air tank strap.	
27/06/2024		a/c fan, Check out A/C issues, Fan Belt R-3238 R & R faulty a/c blower motor repalce cabin filter remove drive	
26/06/2024		Hub Seal R-3224 R&R hub seal	
31/05/2024	829,478 kms	C - C Service S-1148 Brake test complete - PASSED Icepack service not complete due to no filters in stock	KJP workshop - Mitchell Breen
17/05/2024		Fitting T-713	Ocean Tyres
15/05/2024		exhaust, Light, Steering R-3216	
25/04/2024	810,744 kms	B - B Service S-1122 Brake test complete - PASSED identified multiple exhaust leaks - jobcard raised RH rear reverse light missing - Jobcard raised	KJP workshop - Judd Porter, KJP workshop - Mitchell Breen
11/04/2024	802,107 kms	New T-704	Ocean Tyres
12/03/2024	792,928 kms	Coolant Leak , driving lights, Water Pump R-3201 Aces found hidden fues behind dash blown R&R water pump	Aces, KJP workshop - Judd Porter
06/03/2024	789,855 kms	Drivers seat valve, Exhaust Flex, Headlight R-3189 R&R leaking exhaust flex on RHS under cab R&R seat ride height valve Fit new LED headlights	KJP Workshop - Jay Sagnol, KJP workshop - Judd Porter
16/01/2024	762,917 kms	Starter Motor, Torque Rods, Turntable R-3169 1. R&R starter motor 2. Remove , clean measure / inspect turntable, replace worn parts and refit 3. Remove damaged guard and adjust mounting arm , replace broken anti sail bracket\4. Replace worn torque rod 4. replace missing bonnet straps	KJP workshop - Scott Laburniy
14/01/2024	762,917 kms	B - B Service S-1081 Brake test complete - PASSED	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
13/12/2023	746,918 kms	Cab, Ice pack, Mud Guard R-3156 1. Repair cup holder 2. Manufacture mudguard mount 3. Retention icepack fan belt	KJP Workshop - Craig Hyde
07/12/2023		New T-666	Ocean Tyres
29/11/2023	740,119 kms	Lights R-3070 Repaired front park light screws Chris smith replaced one quick align bush	CC Smith Mechanical Repairs, KJP workshop - Scott Laburniy
05/10/2023	718,247 kms	C - C Service S-1040 Drain fuel and hyd oil from RH tank remove tank and repair pin holes/re enforce, replace rubber on tank straps and brackets, refit and fill tank.	KJP workshop - Scott Laburniy
22/09/2023	712,837 kms	B - B Service S-1037 mack oil - 36.4L mack coolant - 5L found coolant leaking at radiator outlet hose - tightened clamps looked through coeds, cleaned plugs and cleared front of torque rod bushes have movement, both drive axle pivot bushes have movement, front tie rods ends starting to show movement	KJP workshop - Scott Laburniy

Date	Reading / Units	Type / Repairer Notes	Repairer
09/09/2023	706,496 kms	Cab Mounts R-3025 R & R LHR booster and cab mounts front replace the booster we used from t8 check over fit bolt for RH stack mount	Doug Kretschmer - KJP Haulage, KJP workshop - Scott Laburniy
07/09/2023	705,714 kms	Inspect and Report, Replace T-637	Ocean Tyres
22/07/2023	675,521 kms	Wheel Alignment R-2984 preform wheel alignment	KJP workshop - Mitchell Breen
20/07/2023	675,243 kms	Cab Mounts, Cab Shockies, engine oil leak, Exhaust, Suspension R-2977 replace cab cushions and front shockies replaced worn fire extinguisher R & R exhaust flex repair air tank leak R & R front spring stops R & R spinner filter gaskets R & R exhaust rubber stacks	KJP Workshop - Craig Hyde, KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
19/07/2023	675,243 kms	Blowing Smoke, Cutting Out R-2839 1. Taken to CC smith as blowing smoke & cutting out. Rear Diverter valve has failed & requires replacement. Connect techtool check operations, all ok. Started truck, no faults on dash. 2. Driver reported problem persisted. Replaced front exhaust brake valve	CC Smith Mechanical Repairs, KJP - Internal Workshop
19/07/2023	675,243 kms 10,260 hrs	NHVR Inspection Checklist I-307	KJP workshop - Judd Porter
18/07/2023	675,243 kms	Bug Deflector , Indicators R-2927 R & R bug deflector	KJP Workshop - Craig Hyde
18/07/2023	675,243 kms	B - B Service S-986 Brake test - PASSED	KJP Workshop - Craig Hyde, KJP workshop - Mitchell Breen
18/07/2023	675,243 kms	Bonnet , Bonnet Latch, Fan Shroud, Indicators R-2963 grind out and weld up repair and adjust bonnet mount replace bonnet strap windscreen wizard replaced RH & LH screens and rubber seals - INV#9209	KJP Workshop - Craig Hyde, KJP workshop - Scott Laburniy
18/07/2023	675,243 kms	Lights, weld up cracks R-2847 manufacture bracket T & R faulty indicator	KJP Workshop - Craig Hyde
21/06/2023	647,526 kms	Windscreen Wipers, wiper arm R-2938 R & R wiper arm R & R wiper blade	KJP workshop - Scott Laburniy
19/06/2023		C-service R-2931 PLEASE REFER TO S-953	
23/05/2023	626,955 kms	C - C Service S-953 Conducted C service Replaced RH rear wheel seal	KJP workshop - Scott Laburniy
25/04/2023	612,649 kms	Check turntable R-2882 Checked turntable top for cracks. Checked for movement in pedestal bushes, checked jaws & locking mechanism for any signs of ware. Tested with our king pin tool. No fault found in anything, all good to use.	KJP workshop - Mark Johnson
19/04/2023	622,591 kms	Breakdown R-2876 Called to breakdown @ Orica. Found problem with blown air bags. Replaced 2 air bags.	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
12/04/2023	617,731 kms	Wheel Bearings R-2867 Strip hubs off, take down to CC smith. Get hub back from CC smith, Fit hubs. Tension wheel bearings / wheel nuts.	KJP workshop - Mark Johnson, KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
11/04/2023		New T-572	Ocean Tyres

Date	Reading / Units	Type / Repairer Notes	Repairer
29/03/2023	681,795 kms	Air Leaks, not charging, Park Light R-2834 1, Charge rate @ 14.1 volts 2, Load test batteries, all came up good found a couple of loose terminals that may have been the problem 3, fix park light at lh rear 4, fix minor air leak at transmission	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
14/03/2023		Flip on Rims T-556	Ocean Tyres
07/03/2023	600,820 kms	B - B Service S-912 B Service on Truck R&R header tank exhaust flex under driver side cab, R&R LHS exhaust elbow. R&R 2nd axle wheel seal, R&R RH cab bush. Clean & Wash bearings brakes drum & hub.	KJP workshop - Mitchell Breen
17/02/2023		Windscreen R-2816 Replace Laminated Windscreen	Windscreen Wizard
04/02/2023	583,308 kms	exhaust elbow R-2746 R&R exhaust elbow RHS R&R bonnet strap	KJP workshop - Mark Johnson, KJP workshop - Mitchell Breen
04/02/2023	583,302 kms	Antenna, step, Tyres R-2705 Stereo working, dash cam step has been looked at. 0026 - Drivers windscreen looked at. Clearance light has been tightened. 0031 - Boost hose clamp replaced. Fixed small air leak 0030 - No water in lens. seems to be working fine,	
06/01/2023		CTP O-216	
06/01/2023		New T-537	Ocean Tyres
28/12/2022	563,412 kms	Hub Seal R-2776 R&R RHS 1st drive hub seal. Top up coolant pressure test/ R&R hose clamp on hose bottom of header tank.	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
12/12/2022	558,026 kms	B - B Service S-879 Conducted service, Brake test Cleaned out A/C, Evaporator, and Condenser	KJP workshop - Mark Johnson
13/10/2022	532,800 kms	New T-505	Ocean Tyres
02/09/2022	506,955 kms	C - C Service S-808 Brake Test - PASSED Service Truck / Full Check over / repairs	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
01/09/2022	498,751 kms	Engine Tune Up R-2675	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
01/09/2022	506,955 kms	Exhaust manifold leak, pivot bushes, Ware pads need looking at, Wheel Alignment R-2671 R&R 1st drive axle pivot bushes Complete Wheel Alignment.	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
08/08/2022		Air bag R-2639 Remove airbags, couldn't find any in stock. Rang around and went to Maxi Parts & Keetah no luck. Rang Mack and they picked up truck, fitted new airbags on 3rd Axle & tested.	KJP workshop - Scott Laburniy, MaxiPARTS
02/08/2022	482,218 kms	leaking exhaust manifold R-2526 Remove turbo and manifold Remove and replace hub seal and wiper blade arm CQ Engine Machining: Machine Face of Exhaust Manifold	KJP workshop - Mitchell Breen
26/07/2022	487,006 kms	Hub Seal R-2628 R&R LHF drive hub seal & tidy up bay Head out near NRG to try & fault find ABS problem & charge voltage brake test passed	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
19/07/2022	483,175 kms	bonnet straps, Headlights R-2581 R&R LH bonnet strap R&R LH low beam globe R&R hose clamp on intake hose	KJP workshop - Wayne Goodlet
19/07/2022	483,175 kms	Inspect and Report T-457	

Date	Reading / Units	Type / Repairer Notes	Repairer
		monitoring	
19/07/2022	483,175 kms	NHVR Inspection Checklist I-231 brake test passed	
13/07/2022		Windscreen R-2604 Replace front Glass - Windscreen wizard 13/07/22	Windscreen Wizard
11/07/2022	478,436 kms	loose flange R-2602 Removed drive shaft, replaced yoke nut & O-Ring, reassembled. Some movement still there.	KJP workshop - Scott Laburniy
04/07/2022		Registration O-184	
24/06/2022	468,650 kms	Torque Rods R-2584 Remove & replace torque roads on 2nd & 3rd Axle	KJP Workshop - Kade Porter
18/06/2022	466,424 kms	B - B Service S-792	KJP workshop - Wayne Goodlet
18/05/2022	448,055 kms	engine oil leak R-2506 R&R Sump Put lid back on tracker box	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
12/05/2022	448,039 kms	axles, Exhaust manifold leak R-2370 Replaced air manifold in firewall Tyres replaced 26-04 T436 Fitted plug into manifold	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
26/04/2022	442,842 kms	Inspect and Report, Steer Tyres T-436	Ocean Tyres
17/04/2022	440,887 kms	Air Leaks, Fire Extinguisher R-2458 Replaced air fittings on back of cab. Replaced fire ext bracket with one from red container. Found air leak at fire wall, took photos of bulkhead & tried to re-seal. DONE SEE R2370	KJP workshop - Scott Laburniy
08/04/2022	437,592 kms	Ice pack, Oil Leak, Wheel Alignment R-2450 Fix ice pack starting issue. Check front shockies and fix boost leak	KJP workshop - Mitchell Breen
04/04/2022	435,361 kms	Battery R-2431 R&R 2 Batteries LHS	KJP workshop - Mitchell Breen
17/03/2022		Air, Guards, Tyres R-2380 R&R mudguard Rotate Steer Tyres T&R air leak, re-seal bung on air tank	KJP workshop - Wayne Goodlet
10/03/2022	422,352 kms	B - B Service S-716 Side bung on sump was weeping, tightened up. Cleaned up spots on front of cab around windshield & painted. Bonnet latch had already been repaired.	KJP workshop - Scott Laburniy
03/03/2022	415,972 kms	Bonnet Latch R-2363 Fit bonnet strap	KJP workshop - Scott Laburniy
03/03/2022	412,667 kms	Breakdown R-2374 Drive to Cracow for Breakdown R&R William's valve	KJP workshop - Judd Porter
10/02/2022	404,240 kms	batteries R-2338 Load tested all batteries Replaced 2 Batteries	KJP workshop - Mitchell Breen
24/01/2022	394,726 kms	Switch R-2298 Wire in new fridge switch Trace & repair fault for camera etc	
12/01/2022	386,117 kms	Wheel Alignment R-2272 Performed wheel alignment Dropped tyres to oceans Exhaust manifold leak - deferred till later date	
10/01/2022	382,432 kms	New T-395	Ocean Tyres

Date	Reading / Units	Type / Repairer Notes	Repairer
12/12/2021	373,840 kms	C - C Service S-636 Brake test Pass R&R interior light bulbs	
03/12/2021	369,402 kms	Bonnet Latch, Mud Flap R-2236 Replaced bonnet latch. R&R RHS front drive mudflap Fitted anti sail bracket to mudflap Air dryer missing silencer on exhaust port, not effecting operation, no repair required	KJP workshop - Mitchell Lancaster
28/10/2021	347,991 kms	Alternator R-2190 Remove Alternator from truck, found the one ordered was wrong Fitted alternator from our stock Rotated steer tyres	KJP workshop - Scott Laburniy, KJP workshop - Tre Szepanowski
25/10/2021	346,433 kms	Exhaust Flex R-2189 R & R damaged flex section	KJP workshop - Mitchell Lancaster
14/10/2021	341,141 kms	Ice pack R-2174 found faulty relay, Compressor not engaging, r & r 2 x relays Belts squealing when compressor engages, tightened Requires 2 x new fan belts, both starting to cracj	
08/10/2021	337,444 kms	Exhaust manifold leak R-2128 Replaced all manifold gaskets and studs, Found damaged turbo, Replaced Turbo	KJP workshop - Judd Porter
27/09/2021	328,611 kms	Bonnet Latch R-2135 Replaced drivers side bonnet latch Replaced passenger side wiper	KJP workshop - Tre Szepanowski
27/09/2021	332,081 kms	Exhaust Flex R-2144 Replaced leaking flex section, found at service.	KJP workshop - Scott Laburniy
27/09/2021	332,081 kms	B - B Service S-586 Conducted B service Brake test passed 36Lt Mack Ultimate Oil	KJP workshop - Scott Laburniy
27/08/2021	315,636 kms	Bonnet R-2064 Replace bonnet rest bracket on rh side	KJP workshop - Mitchell Lancaster
22/08/2021	314,301 kms	Engine Tune Up R-2113 Scheduled hours - 4083 Scheduled kms - 269740 replace RH bonnet wedge	KJP workshop - Judd Porter
15/07/2021	246,468 kms	Air leak R-1991 Fix air leak coming from left hand side under cab	KJP workshop - Mitchell Breen
10/07/2021	294,879 kms	Check Over R-1978 Brake Test - PASSED Tightened loose pivot bush bolts 2nd axle	KJP workshop - Mitchell Lancaster
04/07/2021	290,980 kms	Truck annual Inspection I-143 Brake Test - PASSED	KJP workshop - Scott Laburniy
04/07/2021	290,980 kms	B - B Service S-526 Brake Test - PASSED 36Lt Mack Oil Replaced wiper blades	KJP workshop - Judd Porter, KJP workshop - Scott Laburniy
01/07/2021		Registration O-111	
28/06/2021	286,570 kms	Bonnet, Wheel Alignment R-1908 Completed Wheel Alignment Changed rubber springs at front of cab	KJP workshop - Scott Laburniy
24/06/2021	284,561 kms	New, Steer Tyres T-330	Ocean Tyres
29/05/2021	271,635 kms	Shock Absorber, Wheel Alignment R-1874 Complete wheel alignment Move turntable back a hole Remove and replace front shockies	KJP workshop - Wayne Goodlet
27/05/2021	270,873 kms	Bonnet Latch R-1880 Replaced bonnet latch	KJP workshop - Wayne Goodlet

Date	Reading / Units	Type / Repairer Notes	Repairer
17/04/2021	249,819 kms	C - C Service S-482 Brake Test - PASSED Mack Ultimate Engine Oil - 36Lts Transmission Oil - 18Lts Diff Oil - 34Lts	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
14/04/2021	248,412 kms	Bonnet Latch, Clearance Light R-1798 Remove and replace left hand side rear side light & Deutsch plug Remove and replace right hand side top bonnet strap	KJP workshop - Mitchell Lancaster
06/04/2021	241,652 kms	boost leak R-1773 Remove and replace intercooler hose Judd: 13/4/21 Tightened boost hose clamps	KJP workshop - Wayne Goodlet
02/04/2021	241,032 kms	Battery R-1769 Replace 4 x Batteries Ben Palmer Contracting Pty Ltd: Test wiring to ice pac fan switch. Locate and replace faulty latching relay and refit earth wire to battery	KJP workshop - Scott Laburniy
18/03/2021	240,693 kms	Air bag R-1732 Adjusted all Guards	KJP workshop - Mark Johnson
15/03/2021	240,610 kms	Steering Wheel R-1731 Removed turn table and inspected. Replaced wear collar and wear pads. Adjusted turn table Degreased and washed rear deck and rear guards Remove and replace steering wheel	KJP workshop - Mitchell Lancaster, KJP workshop - Wayne Goodlet
11/03/2021	238,618 kms	boost leak, Gaurds , Ice pack R-1724 1. Started and stopped ice pack multiple times - no issues. Removed cover and removed and cleaned relays. Checked oil - was low so topped up. Blew out ice pack. 2. Tightened mudguards and cranks, Replaced missing mudflap right hand 2nd front 3. No fault found Removed wrapping and examined suzi-coil - couldn't find reason for wrap.	KJP workshop - Scott Laburniy
08/02/2021	222,173 kms	New T-262	Ocean Tyres
20/01/2021	210,803 kms	new T-250	Ocean Tyres
19/01/2021	210,793 kms	Bonnet, Wheel Alignment R-1609 R & R RH bonnet strap Remove and shorten stacks conduct wheel alignment	KJP workshop - Scott Laburniy, KJP workshop - Wayne Goodlet
19/01/2021	210,793 kms	B - B Service S-443 Spent time searching up correct suspension tension Brake Test - PASSED Re-tested Oil Sample (15/02/21)	KJP workshop - Scott Laburniy, KJP workshop - Wayne Goodlet
11/01/2021	206,259 kms	Mud Guard R-1596 R & R LHR mudguard	KJP workshop - Judd Porter, KJP workshop - Scott Laburniy
18/12/2020	194,438 kms	Rotate T-243	Ocean Tyres
26/11/2020	186,137 kms	Antenna R-1322 Antenna fixed	KJP workshop - Bill Shanahan
13/11/2020	178,597 kms	Bonnet Latch, Hub Cap R-1302 Mini Relay Part - Bill used 11/09/20 (not necessarily related to job card just recording the part against truck KS 14/9/20) Bonnet latch replaced under Warranty R & R bonnet latch Fit hubcaps Fit new bonnet shims	KJP workshop - Judd Porter, KJP workshop - Wayne Goodlet
11/11/2020	177,969 kms	Windscreen Washers, Windscreen Wipers R-1449 Remove and replaced wiper blades and washer	KJP workshop - Judd Porter
11/11/2020	177,969 kms	Coolant Leak R-1450 Breakdown near Mt Larcom - Found radiator was leaking coolant. Removed and refitted Radiator - (Part from Mack covered under Warranty Invoice: 8500509) Fitted new receiver drier, reconnected A/C system, vacuum tested re-gassed and ran A/C System. Will need thermostat. Refitted grill. Used 30Lt of Coolant	KJP workshop - Judd Porter, KJP workshop - Scott Laburniy, KJP workshop - Wayne Goodlet

Date	Reading / Units	Type / Repairer Notes	Repairer
23/10/2020	171,931 kms	B - B Service S-384 Brake Test - PASSED 36L Mack Engine Oil Topped up auto grease system Filled up windscreen washer reservoir Replaced both wiper blades and 1 x windscreen washer jet Topped up battery fluid Adjusted turn table Replaced cabin filter	KJP workshop - Mitchell Lancaster, KJP workshop - Wayne Goodlet
29/09/2020	158,627 kms	Mudflap, sign R-1323 Replaced damaged left hand mudflap Replace missing left hand chevron and damaged right hand chevron	KJP workshop - Scott Laburniy
17/09/2020		Parts O-49 ACX1211 - Insulation Tape	
07/09/2020	146,941 kms	Fridge R-1223 Installed new slide out fridge Tested - working all okay Seal up around fridge	KJP workshop - Mitchell Lancaster
18/08/2020	137,189 kms	Accessories R-1231 Inspected, cleaned and secured relays for Ice pack and tested operations	KJP workshop - Wayne Goodlet
04/08/2020	132,193 kms	Bonnet R-1196 Change broken bonnet rubber strap left hand side	KJP workshop - Wayne Goodlet
28/07/2020	129,417 kms	Air, Light R-1149 1. R&R trailer plug 2. R&R trailer tailgate air fitting 3. Inspected 12v plugs 4. Parker light working 5. Move turntable forward 1 hole	KJP workshop - Wayne Goodlet
23/07/2020	126,361 kms	New T-176	Ocean Tyres
21/07/2020	126,150 kms	C - C Service S-322 Brake Test - PASSED Mark 20/07/20	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy, KJP workshop - Wayne Goodlet
10/07/2020	121,526 kms	Truck annual Inspection I-73 Brake Test - PASSED Mark 10/07/2020	
20/05/2020	101,373 kms	Turntable R-1018 1. Took 1 turntable pad off T13 and fitted it to T10. Ordered New turntable pad kit for T10 to fit when it gets back to work.	
19/05/2020	101,372 kms	boost leak R-1017 Truck came in with a whistle. Checked over for and exhaust leak. Found no exhaust leaks and moved onto looking for a boost leak. Both hoses from turbo to intercooler were leaking. R&R hoses and clamps.	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
25/03/2020		Rotate T-145 NO INVOICE	Ocean Tyres
22/03/2020	82,847 kms	suzi coil R-878 R & R damaged suzi coil	KJP workshop - Bill Shanahan
04/03/2020	80,811 kms	Transmission R-827 Wheel alignment	CT Smith Mechanical
27/02/2020	80,782 kms	Turntable R-817 manufacture bump stop for turntable	KJP workshop - Judd Porter
27/02/2020	80,781 kms	B - B Service S-270 R & R LH&RH wiper blades Change air filter Brake test - PASSED	KJP workshop - Judd Porter
24/02/2020	77,002 kms	Brake Test, General Checkover, Lights R-788 General Check over Brake Test - PASSED	KJP workshop - Mark Johnson
18/02/2020	77,601 kms	Check Over, Rattle R-785	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy

Date	Reading / Units	Type / Repairer Notes	Repairer
		1. visually inspect diff for water 2. tighten doors	
04/02/2020	73,287 kms	Bonnet R-753	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
		Bonnet rubbing / squeaking, checked front pivots were tight and solid, greased up rubbers and catches etc.	
17/01/2020	71,170 kms	ABS R-716	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
		hooked up to computer and tested - found no codes couldn't get light to come on - suggested problem with trailer instead	
20/12/2019	65,096 kms	Auto Greaser, Power Steering R-652	KJP workshop - Mark Johnson
		1. No fault found 2. Checked out steering, no problem or noise found.	
13/12/2019	58,992 kms	Bonnet R-658	KJP workshop - Scott Laburniy
		Remove and replace bonnet latch - Part under warranty from VCV	
18/11/2019	52,760 kms	brackets R-570	KJP - Internal Workshop
		Fitted new tank cross-member brackets	
25/10/2019	44,612 kms	Wheel Alignment R-531	KJP - Internal Workshop, KJP workshop - Wayne Goodlet
		Wheel Alignment - COMPLETED	
24/10/2019	44,608 kms	New T-28	Ocean Tyres
19/10/2019	40,630 kms	Auto Greaser R-499	KJP workshop - Bill Shanahan
		Remove and replace autogreaser line (supplied by Groenveld under warranty) Degrease and hose down under body of truck to clean off excess grease, split fuel coil Wash truck and affix chevrons on rear mudflaps	
18/10/2019	40,629 kms	B - B Service S-198	KJP workshop - Judd Porter
		Brake Test - PASSED Broken grease line down right hand side - Warranty work (Repair 499)	
19/09/2019	25,875 kms	Electrical R-385	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
		Checked over tracker wiring - no issues Fill auto greaser.	
17/09/2019	25,792 kms	Signs R-277	
		Parts on hand - No Job card needed (5 minute job)	
21/08/2019		Ice pack R-316	Aces
		Service call to site to inspect the starting fault with icepack. Couldn't fault at time of test. Checked over wiring and all looked ok.	
05/08/2019	892 kms	Fit out R-213	
		Make up bracket for tracker box and fit. Fit Tracker - run all wiring to cab Fit duress button - run wiring Fit crash camera Fit eye wash and first air kit to left hand dog box Move triangles and bars to rear box Fit Stickers	
23/07/2019	891 kms	Wheel Alignment R-232	KJP workshop - Wayne Goodlet
		Complete Wheel Alignment Tension U bolts and Pivot Bolts	

Signed: _____

Name: _____

Date: _____