

A-1 Trailer & Truck Repair Ltd.

2314 B Northridge Drive
Saskatoon, Saskatchewan S7K 4R5

INVOICE



Invoice No.: 74249
Date: 15/10/2024
Ship Date:
Page: 1
Re: Order No. 33607

Sold to:
Cash

Ship to:
RMD

BRENT306-227-6454
GORD306-230-3854

Business No.:

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			07 INTERNATIONAL 7500 SER#1HTWNAZT37J405355 MILE# 209,387 LIC# 271 NDY SASK SAFETY. TRUCK OVER HEATS AT LOW SPEED UNDER LOAD. START SASK SAFETY INSPECTION, R.H REVERSE LIGHT NOT WORKING. REPLACE LIGHT AND WIRE IN PIGTAIL. TEST, GOOD. FAN HUB HAS MAJOR LEAK. REMOVE ENGINE FAN AND HUB. REPLACE AIR CARTRIDGE IN REAR HALF OF HUB., INSTALL NEW HUB AND REINSTALL FAN. RUN AND CHECK OPERATION AND CHECK FOR LEAKS, NO LEAKS, GOOD OPERATION. GREASE FRONT(STEER) CAMS AND SLACKS AND WORK THEM. THEY SEEM TO BE RELEASING WELL NOW. TRIED TO ADJUST CLUTCH AS THERE IS NO FREE PLAY @ THE PEDAL. WAS NOT ABLE TO GET ANY MORE MOVEMENT. IT IS AT END OF ADJUSTMENT. INFORMED CUSTOMER THAT IT IS NEARING THE END OF ITS LIFE. GREASED RELEASE BEARING. MAIN SUCTION HOSE IS GOING INTO PUMP IS WEARING ON ANOTHER HOSE. PROTECT BOTH LINES WITH EXTRA RUBBER AND SECURE. TIE UP AND PROTECT BRAKE LINES @ LRD BRAKE POT. DIAGNOSE AIR SYSTEM ISSUE. COMPRESSOR IS REQUIRED TO BUILD FROM 85PSI TO 100PSI IN 2 MINUTES AT IDLE. IT DOES NOT DO THAT. ALSO GOVERNOR CUTTING OFF AT 115PSI WHICH IS LOW. AIR DRYER IS SATURATED.	GP		
Comment:					Continue...	

A-1 Trailer & Truck Repair Ltd.

2314 B Northridge Drive
Saskatoon, Saskatchewan S7K 4R5

INVOICE

Invoice No.: 74249
Date: 15/10/2024
Ship Date:
Page: 2
Re: Order No. 33607

Sold to:
Cash

Ship to:
RMD

BRENT306-227-6454
GORD306-230-3854

Business No.:

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			REPLACE AIR DRYER. BRACKETS WERE ROTTED OUT, REPLACE THEM AS WELL. EXTEND AIR LINES AS NEEDED. REPLACE GOVERNOR, STILL NO IMPROVEMENT. REMOVE INTAKE AND OUTLET LINES. CHECK FOR BLOCKAGE AND LEAKS, ALL GOOD. REPLACE UNLOADER VALVES IN COMPRESSOR. REMOVE GOVERNOR AND AND ADJUST IT TO HIGHER PRESSURE. ELIMINATE ALL AIR LEAKS THAT COULD BE FOUND. RECONNECT EVERYTHING, AM NOW ABLE TO BUILD AIR IN THE TIME FRAME REQUIRED. DIAGNOSE ENGINE OVERHEATING. PRESSURE TEST COOLING SYSTEM. COOLANT LEAKING DOWN BLOCK CLOSE TO FRONT OF ENGINE. REMOVE AIR CLEANER ASSEMBLY AND BELT AND A/C COMPRESSOR + WIRING HARNESS. REDO TEST, FOUND IT LEAKING @ THERMOSTAT HOUSING. RAN ENGINE UP TO TEMPERATURE, SEEMS LIKE THERMOSTAT IS NOT OPENING WHEN IT SHOULD CAUSHING HIGHER HEAT. DRAIN COOLANT, FLUSH RADIATOR, REMOVE NECESSARY COMPONENTS AND HOSES TO ACCESS T-STAT. CLEAN RUST OFF OF THERMOSTAT HOUSING, INSTALL NEW THERMOSTAT AND HOSE @ HOUSING. REASSEMBLE AND FILL, RUN UNIT, TSTAT OPENS @ 190 AS SUPPOSED TO. NO LEAKS, EVERYTHING OPERATING WELL.			
Comment:					Continue...	

A-1 Trailer & Truck Repair Ltd.

2314 B Northridge Drive
Saskatoon, Saskatchewan S7K 4R5

INVOICE

Invoice No.: 74249
Date: 15/10/2024
Ship Date:
Page: 3
Re: Order No. 33607

Sold to:

Cash

Ship to:

RMD

BRENT306-227-6454
GORD306-230-3854

Business No.:

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			CLEANED AND GLUED CLUTCH PEDAL RUBBER TO CLUTCH PEDAL. REMOVE AND REPLACE OLD WIPER BLADES AS THE OLD ONES WERE BAD. FOUND THAT ID LIGHT ON TRUCK CAB WAS BAD, REPLACE. REPAIR WIRING FOR FRONT RIGHT MARKER LIGHT AND LEFT REAR MARKER LIGHT, AND REVERSELIGHT FOUND THAT ANGLE ON SOME BRAKE POT RODS NEEDED TO BE CORRECTED, SO TAKE REAR DRIVE WHEELS OFF, ADJUST. REMOVE AND REPLACE REAR CAM BUSHINGS AS THEY WERE WORN. WHILE DOING CAM BUSHINGS FOUND THAT A COUPLE SLACKS WERE NO GOOD, SO REPLACE THEM AS WELL. FOUND THAT TRUCK NEEDED CAGING BOL FOUND THAT THERE WAS NO BATTERY TIE DOWN, ORDERED AND INSTALLED IN TRUCK. REMOVE FRONT BUMPER, PTO PUMP AND SHAFT TO CHANGE BOTH U-JOINTS THAN REINSTALL EVERYTHING. TRUCK NEEDED DOT TAP SO HAD TO SCRAPE OLD TAPE NANO GLUE OFF, CLEAN UP SURFACE WITH WIRE WHEEL AND PAINT BOX, THAN INSTALL NEW TAPE. INSTALL BRAKE STROKE INDICATORS			
WBR22	Each	2	WIPER BLADE 22" (all season curved flexi)	GP	12.20	24.40
ASHMP056	Each	2	Howes Penetrating Oil-Spray(12 OZ.)	GP	9.00	18.00
UBSE2500R	Each	1	SEALED BEAM 2.5" ROUND RED (TRL10202R)	GP	2.70	2.70
SB194	Each	1	MINATURE BULB (1h1194)	GP	0.57	0.57
SB3157A	Each	1	BULB AMBER LGT3157A	GP	4.05	4.05
CRC05088	Each	5	Brakleen 19OZ Non-Chloro (kf313)	GP	5.45	27.25
CSK1058	Each	2	camshaft kit drive axle/Q-PLUS(E3993B)KIT8042/CK425/e1 0897	GP	22.80	45.60
Comment:					Continue...	

A-1 Trailer & Truck Repair Ltd.2314 B Northridge Drive
Saskatoon, Saskatchewan S7K 4R5**INVOICE**Invoice No.: 74249
Date: 15/10/2024
Ship Date:
Page: 4
Re: Order No. 33607Sold to:
CashShip to:
RMDBRENT306-227-6454
GORD306-230-3854

Business No.:

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
CAM199L	Each	2	CAM Q (1.5-28SPL -11-9/16")E9661/18-519/18-833	GP	42.00	84.00
CAM199R	Each	2	CAM Q (1.5-28SPL-11-9/16")E9662/18-518/18-832	GP	42.00	84.00
ST392-9131	Each	4	WHEEL SEAL REAR-392-9098*(370003a) hd809	GP	81.60	326.40
PTX58922	Each	1	FORM A GASKET PERMATEX(PTX2BR) 85GRAM	GP	10.20	10.20
UBRT2050RW	Each	1	REFLECTIVE CONSPICUITY TAPE 50FT.(bag) red/silver	GP	36.80	36.80
PNT13-22	Each	1	PAINT GLOSS WHITE 16 OZ (gdsgq1457)	GP	11.55	11.55
NS	Each	20	H8CZ12.114 1/2"X 1 1/4" BOLT	GP	0.60	12.00
TL98105	Each	4	REFLECTIVE STRIP(SILVER)2"X12"	GP	3.00	12.00
TL98105	Each	1		GP		
MTRR801074	Each	2	auto slack rockwell (1.5"-28SPL-6") rh-2291*R801074N	GP	87.14	174.28
ST330-3107	Each	4	GASKET/7-284/8HOLE=7"C.C./5"1/2-ID/E 2431	GP	4.30	17.20
NS	Each	1	HOR99A4701 DRIVE	GP	2,199.05	2,199.05
DOGF610	Each	3	Grease Fitting 1/8" Long Straight (GN610) 1/8x27	GP	0.84	2.52
MID10043	Each	1	cage release bolt ((BH800921)) 41X358((TSEK10030-15PL))	GP	9.11	9.11
MDRS-100	Each	4	BRAKE STROKE INDICATOR (S-100)	GP	3.25	13.00
MIDRT1	Each	2	RELEASE BOLT.. FS-5620LS ((longer))	GP	13.30	26.60
BRGSET403	Each	1	Bearing Set(594A 592A)	GP	42.42	42.42
NS	Each	1	1664297C4 CLAMP BATTERY HOLD	GP	170.55	170.55
NS	Each	2	3596202C1 BOLT J M8X285M	GP	25.20	50.40
NS	Each	2	2NNM10SC-08 8MM GR10 NYLOCK NUT	GP	0.25	0.50
DA51-1033	Each	1	Unimount Nut (WEP06000)NWRCM-39702/ M22X1.5	GP	3.30	3.30
DA34-1525	Each	1	Lock Ring CS3140 ...E-801	GP	0.72	0.72
ST392-9131	Each	1		GP		
NS	Each	14	3/4" GR8 NF NYLOCK NUT	GP	1.80	25.20
NS	Each	8	5/8" GR8 NC NYLOCK	GP	1.05	8.40
NS	Each	8	5/8" FLAT WASHER	GP	0.40	3.20
NS	Each	2	4999 XL EP2 GREASE	GP	6.95	13.90
BE275491	Each	1	Governor D2 New/284358(KN18530)	GP	32.10	32.10
RV65225	Each	1	AIR DRYER (AD9-12VOLT) \$200	GP	222.00	222.00
PA120-BA	Each	2	PIPE ADAPTER 1/4"X1/8"	GP	1.44	2.88

Comment:

Continue...

A-1 Trailer & Truck Repair Ltd.

2314 B Northridge Drive
Saskatoon, Saskatchewan S7K 4R5

INVOICE

Invoice No.: 74249
Date: 15/10/2024
Ship Date:
Page: 5
Re: Order No. 33607

Sold to:
Cash

Ship to:
RMD

BRENT306-227-6454
GORD306-230-3854

Business No.:

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
PA1474-6B	Each	2	45D. ELBOW TUBE TO MALE PIPE 3/8-1/4	GP	4.75	9.50
BE107695	Each	1	AD9/Bracket MTG.Kit (H107695)	GP	36.84	36.84
PA1469-10D	Each	1	ELBOW-90* 5/8-TUBE 1/2 PIPE	GP	8.50	8.50
PA1469-6B	Each	1	90D. ELBOW TUBE TO MALE PIPE 3/8-1/4	GP	4.40	4.40
PA1460-10	Each	1	SLEEVE 5/8"	GP	0.60	0.60
PA1461-10	Each	1	NUT 5/8	GP	1.15	1.15
PA1485-10	Each	1	SYNFLEX 5/8"	GP	2.50	2.50
BE107515	Each	1	Unloader Kit For 550/750 (707515)	GP	29.68	29.68
PAPC1468-4A	Each	1	PUSH TO CONNECT FITTING (1/4 TUBE-1/4 PIPE)	GP	8.50	8.50
PA121-A	Each	1	PLUG HEX HEAD 1/8	GP	0.60	0.60
PA103-A	Each	1	COUPLING 1/8	GP	1.20	1.20
S110231	Each	1	RAD CAP STANT (gat31528) 16LB	GP	8.20	8.20
NS	Each	1	1842130C3 THERMOSTAT DIAM46806B	GP	167.23	167.23
PAHC19-275	Each	1	FLEX-SEAL CLAMP (H.D.) 2.56"-2.87"	GP	13.65	13.65
NS	Each	1	G311-038 3/8 HEATER HOSE GL S7580135.001	GP	5.55	5.55
NS	Each	1	G3896-225 PREFORM 90° RAD HOSE	GP	84.90	84.90
NS	Each	2	G39-036 SPRING CLAMP GL S7579809.001	GP	6.08	12.16
NS	Each	1	4999 EP-2 GREASE DIAM 46772B	GP	6.95	6.95
UBPT9530	Each	1	PIGTAIL 3-WIRE RIGHT ANGLE	GP	1.69	1.69
UBLED2238-10C	Each	1	LITE LED CLEAR OVAL LENSE BACK UP 10-DIO(2"X6")	GP	31.26	31.26
NS	Each	2	S35.153X 1310 U-JOINT TL 452098	GP	32.28	64.56
NS	Each	3	PC4700 BUTT CONNECTORS	GP	0.70	2.10
DOGF1728	Each	1	Grease Zerk/Drive In/ 506-991	GP	0.40	0.40
NS	Each	4	1/2X2 CAPSCREW ZINC GR8	GP	1.55	6.20
NS	Each	4	1/2" STOVER/NYLOCK	GP	0.59	2.36
NS	Each	4	1/2" LOCKWASHER/ZINC	GP	0.15	0.60
NS	Each	8	1/2" FLATWASHER/ZINC GR8	GP	0.30	2.40
PA240-B	Each	1	DRAIN VALVE/1/4" WING STYLE (40c-b)	GP	2.86	2.86
EZES150/50	Each	1	ANTIFREEZE 50/50 PREMIXED/RED--PINK	GP	15.20	15.20
NS	Each	4	5/8 STOVER	GP	1.05	4.20
NS	Each	1	A131701	GP	15.00	15.00
MDRS-100	Each	2	BRAKE STROKE INDICATOR (S-100)	GP	3.25	6.50
NS	Each	1	A131701 SASK SAFETY DECAL	GP	15.00	15.00
NS	Each	1	LABOUR	GP	8,375.00	8,375.00
NS	Each	1	SHOP SUPPLIES	GP	586.25	586.25

Comment:

Continue...

A-1 Trailer & Truck Repair Ltd.

2314 B Northridge Drive
Saskatoon, Saskatchewan S7K 4R5

INVOICE

Invoice No.: 74249
Date: 15/10/2024
Ship Date:
Page: 6
Re: Order No. 33607

Sold to:

Cash

Ship to:

RMD

BRENT306-227-6454
GORD306-230-3854

Business No.:

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			GP - GST 5% PST 6% GST PST			662.58 795.00
A-1 Trailer & Truck Repair Ltd. GST: #135345916					Total Amount	14,708.12
Shipped By:			Tracking Number:		Amount Paid	0.00
Comment:					Amount Owing	14,708.12
Sold By:						