

Maintenance Log for LV.0064 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
117666	Gearbox u/s - reinstall and sell	03-Jun-26	03-Jun-26			
	1 Gearbox u/s - reinstall and sell					
116661	Replace rear tail light assy water ingress	05-Dec-25	05-Dec-25			
	1 Replace tail light assy					
115828	Replace U/S rear shock absorbers	20-Aug-25	20-Aug-25			
	1 Replace U/S rear shock absorbers					
115827	Replace Damaged rear wheel arches and mud flaps	20-Aug-25	20-Aug-25			
	1 Replace Damaged rear wheel arches and mud flaps					
115826	Remove U/S side steps	20-Aug-25	20-Aug-25			
	1 Remove U/S side steps					
115797	Replace Failed brake pipes (front Caliper)	13-Aug-25	13-Aug-25			
	1 Replace Failed brake pipes (front Caliper)					
	2 Replace Failed brake pipes (front Caliper)					
115678	Replace U/S power steering pump	24-Jul-25	24-Jul-25			
	1 Replace U/S power steering pump					
115479	Replace worn suspension and steering components	20-Jun-25	20-Jun-25	335101		
	1 Replace worn suspension and steering components					
115478	Replace U/S fan belt and pulley's	20-Jun-25	20-Jun-25	335101		
	1 Replace U/S fan belt and pulley's					

Maintenance Log for LV.0064 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
115477	Replace sagged and leaking front strut assemblies	20-Jun-25	20-Jun-25	335101		
	1 Replace sagged and leaking front strut assemblies					
115476	Replace U/S belly plate and mounts with heavy duty guard	20-Jun-25	20-Jun-25	335101		
	1 Replace U/S belly plate and mounts with heavy duty guard					
115307	Replace worn brake components	28-May-25	28-May-25	335101		
	1 Replace worn brake components					
115298	335000km Service	27-May-25	27-May-25			
	1 Complete service					
	2 Replace blown light bulbs, Repair wiring for LH bull bar lig					
115059	Rego inspection	15-Apr-25	15-Apr-25	332657		
	1 Rego inspection					
115053	Replace out of test date fire extinguisher	14-Apr-25	14-Apr-25			
	1 Replace Extinguisher					
114792	Replace Battery	11-Mar-25	11-Mar-25			
	1 Replace Battery					
114244	Replace tyres	09-Jan-25	09-Jan-25			
	1 Replace tyres					
	2 Wheel align					
113597	Install fire extinguisher	23-Sep-24	23-Sep-24			
	1 Install fire extinguisher					
113281	Jump start	26-Jul-24	26-Jul-24	322325		
	1 Jump start					

Maintenance Log for LV.0064 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
113269	320k service	25-Jul-24	25-Jul-24			
	1 320k service					
112765	Rego inspection	29-Apr-24	29-Apr-24			
	1 Rego Inspection					
111799	310k service	23-Nov-23	23-Nov-23			
	1 310,000 km service					
111798	Replace timing belt	23-Nov-23	23-Nov-23			
	1 Replace timing belt					
111748	Replace damaged rear window (Thornton Job cost)	14-Nov-23	14-Nov-23			
	1 Replace damaged rear window (Thornton Job cost)					
111072	Replace rear mudflaps	14-Aug-23	14-Aug-23			
	1 Replace rear mudflaps					
110324	Rego	02-May-23	02-May-23			
	1 rego					
109062	Tidy up bullbar wires	27-Oct-22	27-Oct-22			
	1 Tidy up bullbar wires					
108787	Repair tail lights	15-Sep-22	15-Sep-22	300546		
	1 Repair tail lights					
108784	Replace worn tyres	15-Sep-22	15-Sep-22			
	1 Replace worn tyres					
108683	Repair brakes	25-Aug-22	25-Aug-22	300528		
	1 Repair brakes					

Maintenance Log for LV.0064 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
108682	Repair worn uni joints	25-Aug-22	25-Aug-22	300528		
	1 Worn cv's					
108644	Repair fan and radiator	22-Aug-22	22-Aug-22			
	1 Repair fan and radiator					
107093	300k service	17-Feb-22	17-Feb-22			
	1 300k service					
	2 Replace rear brakes					
107069	Replace worn clutch and uni joints	15-Feb-22	15-Feb-22			
	1 Replace worn clutch					
	2 Replace worn uni joints					
106487	Carry out defect repairs at Hornsby	19-Nov-21	19-Oct-21			
	1 Replace failed power steering rack					
	2 Replace CV Shaft					
	3 Replace rear shock absorber					
	4 Regas AC system					
106125	290000km Service	13-Oct-21	13-Oct-21			
	1 Log book service					
105832	Supply ute net	16-Sep-21	16-Sep-21			
	1 Supply ute net					
105802	Mine spec	13-Sep-21	13-Sep-21			
	1 Mine spec					
104698	Rego inspection	29-Apr-21	29-Apr-21			
	1 Rego inspection					

Maintenance Log for LV.0064 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
103501	Parker lights not working	04-Jan-21	04-Jan-21	284311		
1	Parker lights not working					Found blown fuse - replaced (ok)
103357	replace battery	11-Dec-20	11-Dec-20	283573		
1	replace battery					283417 replace battery
103336	Inspection and interior clean	10-Dec-20	10-Dec-20	283097		
1	Inspection and interior clean					
102534	280000km Service	28-Sep-20	28-Sep-20	281912	281912	
1	280000km Service					
101654	Wash vehicle	24-Jul-20	24-Jul-20	276703		
1	Wash vehicle					
101555	Clean vehicle - tray & interior	17-Jul-20	17-Jul-20			
1	Clean vehicle - tray & interior					
101293	Repair rear left mud guard & RHS side step	01-Jul-20	01-Jul-20	275871		
1	Repair rear left mud flap & RHS side step					
100266	270000km Service	11-May-20	11-May-20	272564	272564	
1	270000km Service					11/5/20
20237	Rego inspection	14-Apr-20	17-Apr-20			
1	Rego inspection					
20235	Supply & fit 4 tyres	14-Apr-20	14-Apr-20			
1	Supply & fit 4 tyres					
19366	Replace fan belt & adjust brake shoes	03-Feb-20	03-Feb-20	263076		
1	Replace fan belt					
2	Adjust brake shoes					

Maintenance Log for LV.0064 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
19259	260000km Service & Brake Pads	20-Jan-20	20-Jan-20	261673	261673	
	1 Service					20/1 filters, Completed 261673km - C Thomas
	2 Brakes					21/1 service, 20/1 Brake pads 21/1 replace front brake pads
	3 Engine					20/1 Fan belt
19076	Replace no.4 injector pipe	06-Jan-20	06-Jan-20			
	1 Replace no.4 injector pipe					
18509	250000km Service	21-Oct-19	21-Oct-19	255177	255177	
	1 250000km Service					
17820	July Maintenance work order	01-Jul-19	01-Jul-19	245900		
	1 Safety work					17/7 Purchase light vehicle wheel chocks
17793	240000 Km Service	12-Jul-19	12-Jul-19	245723		
	1 240000 Km Service					Completed 12/7/19 245723 C Thomas - To be done in 5000km time to bring it back into line
17212	Prep for site	16-Apr-19	16-Apr-19	236477		
	1 Prep for site					
	2 Safety work					Fit flag. Service fire extinguisher
17090	Rego Inspection	01-Apr-19	01-Apr-19			
	1 Rego Inspection					
16358	230000 Km Service	07-Jan-19	07-Jan-19	229525		
	1 230000 Km Service					Completed 10/1/19 229525 Km B Cassin
	2 Inspect engine oil leak					
	3 Replace fire extinguisher					

Maintenance Log for LV.0064 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
16277	Inspect & check over vehicle after Mangoola	10-Dec-18	10-Dec-18	228554		
	1 Inspect & check over vehicle after Mangoola					
	2 Remove tracking device from vehicle					
15898	Inspect & prep for Mangoola	30-Oct-18	30-Oct-18	225547		
	1 Inspect & prep for Mangoola					
	2 Safety work					Fit Hi Vis unit numbers. Fit high rise light bar. Fit fire extinguisher. Fit High rise light bare & reverse alarm. Fit wheel nut indicators. Install battery isolator switch. Replace 2 way.
	3 Body work					Replace missing Tonneau Cover
	4 Replace leaking LHS axle seals					Replace leaking LHS axle seals
15757	Inspect & check over vehicle	08-Oct-18	08-Oct-18	225166		
	1 Inspect & check over vehicle					
	2 Charge battery					
	3 Engine work					Replace cracked injector pipe. Replace No4 Injector
15691	Replace missing LHS rear mudflap	08-Oct-18	08-Oct-18	225115		
	1 Replace missing LHS rear mudflap					
15090	Inspect after car accident	19-Jul-18		225115		
	1 Inspect after car accident					Inspect after car accident. Change front RH wheel over
	2 Fit new front seat covers					New covers fitted 29/8/18
	3 Fit Company signage					
	4 Fix rear number plate light					
14261	Inspect & Rego	21-Apr-18	21-Apr-18			
	1 Rego inspection					
	2 Repair rear suspension					Replace rear shackle bushes & brake pedal cover

Maintenance Log for LV.0064 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
14258	Replace 4 worn tyres	20-Apr-18	20-Apr-18	223496		
	1 Replace 4 worn tyres					Fit 4 x 225/75 R16 A/t tyres
13896	Fit fire extinguisher	14-Feb-18	14-Feb-18			
	1 Fit fire extinguisher					
	2 Fit wiper blades					
13612	Repair UHF	29-Nov-17	29-Nov-17			
	1 Repair UHF					Install new plug on UHF
13290	220000 Km Service	11-Oct-17	11-Oct-17	221164		
	1 220000 Km Service					Completed 12/10/17 220491 Km Grafton Motor Group Inv 576502
	2 Starting issue					Diagnose fuel line come away from tank. Refit , bleed & start
12996	103 Inspection & clean	21-Aug-17	21-Aug-17	219601		
	1 103 Inspection & clean					
12670	Replace AC condensor & Replace cable to horn	14-Jul-17	14-Jul-17	213578		
	1 Replace AC condensor					
	2 Replace spiral cable to horn					
12562	210000 KM Service	29-Jun-17	29-Jun-17	211556		
	1 210000 KM Service					Completed 29/6/17 211556 Km Grafton Motor Group Inv 1573693
12008	200000 Km Service	05-Apr-17	05-Apr-17	200518		
	1 200000 Km Service					Completed 5/4/17 200518 KM
10752	190000 km Service	05-Oct-16	05-Oct-16	190321		
	1 190000 km Service					Grafton Toyota Completed 5/10/16 190321
10269	Replace rear brake drums	27-Jul-16	27-Jul-16			
	1 Replace rear brake drums					Grafton Toyota remove & replace both rear brake drums.

Maintenance Log for LV.0064 - Hilux 4 x 4 Dual Cab

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
10176	Fit new seat covers	11-Jul-16	11-Jul-16			
1	Fit new seat covers					New seat covers fitted
10142	Replace fan belt	08-Jul-16	08-Jul-16			
1	Replace fan belt					Fan belt worn. Replaced with new. Checked belt tensioner
10135	Replace battery	08-Jul-16	08-Jul-16			
1	Replace battery					Car battery dead. Replaced with new