



Vehicle History Summary

Fleet #	T22
Registration	22KJP
Make	MACK
Model	Trident
VIN / Chassis #	6FMM12H83JD809413
Build Date	11/2018

Date	Reading / Units	Type / Repairer Notes	Repairer
05/01/2026	1,006,438 kms	driving lights, icepack , Seat R-3406 Repaired wiring for driving lights Replaced seat valve Rewiring icepack relay block Replaced intercooler	
24/10/2025	998,420 kms	NHVR Inspection Checklist I-485 Inspection Complete	
27/08/2025		air leak at seat, Air Leaks, Alternator R-3347	KJP Workshop - Scarlett Guvyner-Treanor, KJP workshop - Scott Laburniy
26/08/2025	992,435 kms	Brakes R-3349	
13/08/2025		batteries R-3344 R & R batteries	KJP Workshop - Scarlett Guvyner-Treanor
01/08/2025	988,115 kms	Brakes R-3338 R&R all drive brake pads	
30/07/2025	988,085 kms	B - B Service S-1283 Brake test and service completed	
24/07/2025	985,881 kms	exhaust R-3339 Replace exhaust section	
15/05/2025	969,823 kms	Rotate T-784	Ocean Tyres
27/04/2025	966,933 kms	Engine Tune Up R-3318 Tune up complete	
17/04/2025		AC R-3313 R&R blower motor	
15/04/2025		Windscreen Wipers R-3309 Replaced wiper motor	
07/04/2025		Not starting, R-3312 replace starter	
04/04/2025	964,721 kms	ice pac, Low Beam, Rear indicator, speed sensor, Steering colum, Windscreen Wipers R-3300 Replaced ice pack starter motor. low beams were insoected - all wokring steering column strut replaced speed sensor refitted fit new purge valve	KJP Workshop - Ethan Sagnol, KJP Workshop - Scarlett Guvyner-Treanor
10/11/2024	937,725 kms	C - C Service S-1185 BRAKE TEST - PASSED	
25/10/2024	940,373 kms	New T-751	Ocean Tyres

Date	Reading / Units	Type / Repairer Notes	Repairer
24/10/2024	940,359 kms 15,614 hrs	NHVR Inspection Checklist I-409	
10/10/2024	937,725 kms	B - B Service S-1184 Brake Test - PASSED	KJP workshop - Judd Porter
17/09/2024		breakdown R-3271 Mack Volvo to repair	
16/07/2024		Parts O-246 Problem- Adblu fault on dash ACES Repair -Adblu sensor had broken, R & R sensor	CC Smith Mechanical Repairs
17/06/2024		A/C, Check out A/C issues, head lights R-3215 R&R ac control unit R&R headlight bulb R & R oil fill pip o ring	KJP workshop - Mitchell Breen
27/05/2024		New T-718	Ocean Tyres
27/05/2024	885,008 kms	B - B Service S-1135 Brake test complete - PASSED Found leaking trans cooler lines - Repairs Cab mounts and exhaust flex ordered and jobcard opened	KJP workshop - Judd Porter
18/04/2024	865,319 kms	Lights, Starter Motor R-3205 R&R starter motor R&R crusic control switch ACES repaired AC and lights Coolant leak at header tank fixed	
14/03/2024	848,335 kms	Replace T-696	Ocean Tyres
22/02/2024	836,358 kms	Clutch, Clutch cylinder, Gearbox R-3187 Test clutch and clutch cylinder - Both failed R&R clutch, clutch cylinder and rear main seal	
05/02/2024	835,854 kms	Seat Belt R-3164 Pulled open seat and cleaned and lubed seat belt Checked wheel bearings / Brakes - performed brake test no fault found Check over truck	KJP workshop - Scott Laburniy
31/01/2024	834,135 kms	C - C Service S-1096 Brake test complete - PASSED	KJP workshop - Ricky Jones, KJP workshop - Scott Laburniy
31/01/2024	834,135 kms	B - B Service S-1083 Brake test complete - PASSED	KJP workshop - Ricky Jones, KJP workshop - Scott Laburniy
20/12/2023	819,886 kms	icepack R-3160 Serviced icepack Inspected oil and fuel for contamination - no fault Run for 3+ hrs Icepack run ok replaced battery in remote	KJP workshop - Judd Porter
15/12/2023	818,741 kms	radio R-3154 R&R aerial	Doug Kretschmer - KJP Haulage
12/12/2023	816,587 kms	Bonnet, icepack , Wheel Alignment, wiper blades R-3141 1. Adjust bonnet mounts - manufacture spacers and install 2. Replaced wiper blades 3. Replaced starter motor on icepack	Doug Kretschmer - KJP Haulage, KJP Workshop - Craig Hyde
06/12/2023	816,591 kms	Wheel Alignment R-3144 Complete wheel alignment Ocean tyres flipped steers	KJP workshop - Scott Laburniy
06/12/2023		New T-664	Ocean Tyres
22/11/2023	813,558 kms	Brakes R-3120 Remove and rebuild LH and RH front brake calipers	Doug Kretschmer - KJP Haulage
20/11/2023	812,299 kms	Gearbox, icepack , Pulleys R-3117	Doug Kretschmer - KJP Haulage

Date	Reading / Units	Type / Repairer Notes	Repairer
		1. No fault found at gearbox for shifting complaint 2. Remove tensioners and Alternator - all bearings noisy and close to failure - replace all and fit new fan belt 3. Aces diagnosed failed AC compressor at icepak, we removed and replaced, aces regassed and inspected	
20/11/2023	812,299 kms	inspection R-3118 Completed inspection Found steer caliper slides on steer had wear, jobcard opened - R3120	KJP workshop - Scott Laburniy
20/11/2023	812,299 kms	Fuel Leak R-3114 Drain fuel from tank, remove drivers side fuel tank, repair split in tank and add wear strips to tank, refit.	KJP Workshop - Craig Hyde, KJP workshop - Scott Laburniy
02/11/2023	808,224 kms	coolant leak, inspection, Suspension R-3102 Fit bonnet bushes top up with coolant and check for leaks R & R wiper blades	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
25/10/2023	808,224 kms 13,074 hrs	NHVR Inspection Checklist I-330	
17/10/2023	805,251 kms	Windscreen Wipers R-3086 R & R wiper blade and arm	KJP workshop - Judd Porter
22/08/2023	787,162 kms	Air bag R-3020 R & R all 8 air bags	KJP Workshop - Craig Hyde
21/08/2023	787,162 kms	B - B Service S-1002 Brake Test - PASSED repair exhaust system replace bonnet mount T & R turbo oil leak	KJP Workshop - Craig Hyde
10/08/2023	57,410 kms	B - B Service S-998 R & R rocker box bush repair air tank mount brake test -PASSED	KJP Workshop - Craig Hyde
01/08/2023	766,252 kms	batteries R-3000 Replace all 4 batteries, load test and charge up old batteries.	KJP workshop - Judd Porter
31/07/2023	766,252 kms	bonnet straps, Power steering leak R-2928 1. Replaced LHS bonnet latch 17/07/23 2. Replaced PWR steer res gasket	KJP workshop - Judd Porter
03/07/2023	764,509 kms	Replace T-614	Ocean Tyres
28/06/2023		Fitting T-604	Ocean Tyres
26/06/2023		Wheel Alignment R-2894 wobble/ bounce was repaired by replacing engine mount wheel alignment preformed	KJP workshop - Scott Laburniy
19/06/2023		Headlight, Interior lights R-2911 Scotty - patched wiring for head light Craig - Glued in light	KJP workshop - Scott Laburniy
19/06/2023	755,337 kms	Fuel Leak, fuel tank R-2914	KJP Workshop - Craig Hyde
16/06/2023	755,537 kms	Engine Mount, gearbox mount R-2878 R & R front engine mount	
16/06/2023	755,337 kms	Air bag, Auto Greaser, Call out, miscellaneous R-2890 Mack Callout - Failed Williams valve, travelled to truck, diagnose problem, remove & install new valve. RHC air fitting into Williams valve R & R road train sign clips	KJP Workshop - Craig Hyde
16/06/2023	755,357 kms	Exhaust Brake R-2871 Parts from Mack Inv 4037267 - Flange Screw, Spacer Sleeve, Gaskets, seal rings etc. 1. Check for leaks Hooked up computer to run tests. found leaks at manifold joins, turbo/manifold gasket and exhaust flex after turbo dump pin. Get manifold machines to do external work fit manifold, new gaskets boost hoses and clamps. C.Q Eng Machining external work Inv#18432	KJP - Internal Workshop
30/05/2023	747,750 kms	Rotate T-589	Ocean Tyres

Date	Reading / Units	Type / Repairer Notes	Repairer
		Rotate each tire	
08/05/2023	738,272 kms	C - C Service S-939 service and check over on truck catch can, manifold and rear air bags starting to crack around bottom have part numbers off air bags drivers side exhaust elbow cracked.	KJP workshop - Mitchell Breen
03/05/2023		Air leak, Call out R-2887 Failed williams valve, travelled to truck, diagnose problem, remove & install new valve.	Mack / Volvo
23/04/2023	732,760 kms	B - B Service S-931 Brake test passed. LHS fuel tank had lots of dirt & diesel on it, may be leaking. Cleaned tank with Gernie. Catch can leaking. Front engine mount & both gear box mounts to be replaced. Bonnet mounts need replacing. Conducted Wheel Alignment on truck, keep an eye on drive tyres.	KJP workshop - Mitchell Breen
21/04/2023		Steer Tyres T-580 Replace As required	Ocean Tyres
19/04/2023		Registration O-243	
11/04/2023	724,245 kms	arial am/fm, Electrical, Ice pack, Indicators, Trailer Plug, Windscreen R-2853 1. replace plug and test 2. Diagnosis Icepack 3. Inspect windscreens and organize replacements 4. replace or fit ! Diagnose ice pack issue, alternator on ice pac needs replacing. Ordered from Aces. R&R reverse beeper. R&R ice pack alternator and fan belts. Indicator flashing different because of different jumbo / resistance still acceptable.	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
03/04/2023	724,245 kms	Exhaust manifold leak R-2844 Front cab shockies, cab sway bar, exhaust flex, exhaust elbow & reverse beeper replaced. Weld up & fit auto greaser bracket. Exhaust elbow to be done on R2853	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
27/03/2023		Balance T-560	Ocean Tyres
06/02/2023		Check turntable R-2807 Inspect & repair turntable	KJP workshop - Scott Laburniy
23/01/2023	685,724 kms	Drag Link, tie rod, Wheel Alignment R-2791 R&R tie rod ends & drag link. Tighten LH steer bearings, seal was clogeed. Strip steer hubs. Take down to GFL and press new bearings. Tension bearing nut hub caps & wheel nuts. Replace auto greaser fittings.	KJP workshop - Mitchell Breen
16/01/2023	685,724 kms	Air Leaks, bonnet straps R-2789 Replace broken compressor fitting that was causing air system to over pressure Replace both RH bonnet laches.	KJP workshop - Judd Porter
16/01/2023	685,724 kms	B - B Service S-893 Service & check over Leaking out of catch can Tightened hydraulic hose to filter Replaced wipers R&R tie rod ends & drag link Fixed air box RHS LHS steer loose	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
03/01/2023	677,031 kms	New, Steer Tyres T-536	Ocean Tyres
02/11/2022	650,434 kms	Air Dryer R-2739 R&R air leak & Air Dryer	KJP workshop - Mark Johnson, KJP workshop - Mitchell Breen
29/10/2022	648,483 kms	Air Leak R-2730 Tested System Replaced air pressure safety valve Signed off defect	KJP workshop - Mark Johnson
27/10/2022	645,657 kms	B - B Service S-858 Conducted service Brake test passed	KJP workshop - Mark Johnson
26/10/2022	645,657 kms	Air Fitting, Engine Tune Up, Exhaust Flex, Ice pack R-2708 Ice-pack Clean out relay holders and blow out radiator, topped up oil Replace 2 flex sections and LH elbow Replaced fitting on rear of truck Conducted Engine tune	KJP workshop - Mark Johnson, KJP workshop - Mitchell Breen

Date	Reading / Units	Type / Repairer Notes	Repairer
26/10/2022	645,657 kms	Bonnet , Signs R-2605 Fit road train signs to bumper Adjust bonnet	KJP workshop - Mark Johnson, KJP workshop - Mitchell Breen
26/10/2022	645,657 kms	NHVR Inspection Checklist I-255 Brake test passed	
18/10/2022		CTP O-203	
18/10/2022	638,581 kms	Derating R-2722 Mack Callout - Travelled to trucks location 15kms west of Duinga. Drained coolant & swapped replaced header tank. Filled with coolant and checked over for leaks. Travelled home.	Mack / Volvo
26/08/2022	615,154 kms	Air Leaks R-2661 Repairing air leaks 4 leaks found and repaired	KJP Workshop - Kade Porter, KJP workshop - Mark Johnson
31/07/2022	601,522 kms	C - C Service S-806 Brake Test - PASSED	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
20/07/2022	594,819 kms	beacon, Signs R-2616 Removed snorkel head off T19 & fit onto T22 - Fix road train sign clip.	KJP workshop - Mitchell Breen
14/07/2022	590,932 kms	Drive Tyres, Steer Tyres T-465	Ocean Tyres
01/07/2022	582,074 kms	Drivers seat valve R-2557 Replaced seat valve	KJP workshop - Mark Johnson
01/07/2022	582,074 kms	ABS/TC, Tail light R-2594 Checked with tech tool for ABS issue. Found and cleaned up plugs-electrical on front & rear ABS relay valves. Repaired small air leaks. Straightened LH rear light bar, replaced side light bracket. CC Smith Mechanical 15/07/22 ATC ABS Dash Fault: ATC control solenoid on relay valve leaking into air service line. R&R top of relay valve with repair kit at rear. Check front relay & found same leaking air R&R aswell. Safety valve at compressor letting off, inspect & found safety valve was worn R&R. CC Smith Mechanical 12/08/22 Connect diagnostic computer & read DTC & event history on ABS system. No faults recorded or events, inspect front ATC valve & had found an air fitting blew out. R&R 2 air fittings at ATC valve, now functioning correctly.	KJP workshop - Mark Johnson
17/06/2022	571,657 kms	driving lights R-2568 Repair wiring for spotlight relay	KJP workshop - Wayne Goodlet
14/06/2022	509,637 kms	Puncture Repair T-451	Ocean Tyres
12/06/2022	567,691 kms	Air leak R-2559 Found to be ABS Valve. Used one from KJP019	KJP workshop - Scott Laburniy
05/06/2022	908,525 kms	Check turntable, Seat Belt R-2525 Remove and replace seat belt Inspect work and lube turntable	KJP workshop - Scott Laburniy
28/05/2022	560,387 kms	B - B Service S-776 brake test passed R&R Jaw Kit / Locking Bar	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
23/05/2022	553,086 kms	Breakdown R-2512 Received call to go to Dingo as T22 wouldn't start. Found it was the starter motor, had to go to Stanwell & meet Mack gentleman with part & take back to Dingo to fit. Tested & was all good, stayed the night in Dingo.	KJP workshop - Mark Johnson
20/05/2022	555,307 kms	Air Leak , Bonnet, Fire Extinguisher R-2508	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
27/04/2022	542,851 kms	Clearance Light R-2481 R&R clearance light	KJP workshop - Mark Johnson

Date	Reading / Units	Type / Repairer Notes	Repairer
26/04/2022		Registration O-167	
22/04/2022	539,998 kms	Bonnet Latch R-2469 Replaced bonnet strap Repaired 3 air leaks, good look over.	KJP workshop - Mark Johnson
24/03/2022	519,280 kms	B - B Service S-726	KJP workshop - Wayne Goodlet
18/03/2022	520,602 kms	Coolant Leak , Indicators R-2401 T&R Coolant leak & Indicator fault. Inspected comp for coolant leak, ok. Pressure tested cooling system. Inspected coolant lines. R&R radiator & header tank. Bleed lines & flushed cooling system. Re-filled with coolant & fit auto greaser.	KJP workshop - Judd Porter, KJP workshop - Wayne Goodlet
23/02/2022	507,543 kms	Auto Greaser R-2102 Auto greaser still full Repaired light in cab - Took parts from T14 Fitted new lights to T14 R&R auto greaser pot - 18.02.22 Check over - front engine mount cracking rubber Groeneveld - Cleaned and inspected pump, found no damage to pump housing or internal parts Replaced all O-rings and seals. Replaced Canister, follower plate and guide rod. Bench tested, pump was reaching and holding.	KJP workshop - Mitchell Lancaster, KJP workshop - Tre Szepanowski
17/02/2022	506,995 kms	Turntable R-2349 R&R turntable wear pads	KJP workshop - Mitchell Lancaster
24/01/2022	496,395 kms	New T-402	Ocean Tyres
20/01/2022	490,611 kms	Ice pack R-2280 Aces repaired	
20/01/2022	491,714 kms	ariel , Lights R-2271 T&R faulty wiring for LH front parker	
07/12/2021	476,788 kms	C - C Service S-625 Brake test passed Slight weep on PTO - Monitor	KJP workshop - Mitchell Breen
25/11/2021	471,365 kms	Indicators R-2217 R&R flasher relay, fault fixed. Going to wire up resistors to front indicators at service Brake Test Passed	
03/11/2021	465,743 kms	NHVR Inspection Checklist I-170 Conducted Inspection, No faults found	
21/10/2021	460,043 kms	Coolant Leak R-2178 Found header tank was leaking R & R header tank, Pressure tested system and all ok	KJP workshop - Tre Szepanowski
20/10/2021	460,844 kms	driving lights, Mudflaps R-2181 Fitted 2 new mud flaps to rear of truck Find issue with driving lights, replaced burnt fuse holder, Tested ok	
20/10/2021		Registration O-137	
11/10/2021	455,969 kms	Air Conditioner, Bonnet, Clearance Light R-2151 Cleaned out cab filter, clean temp sensors in heater box. Replaced front cab mounts, Adjusted bonnet replaced GPS aerial replace exhaust flex section. Repair indicator, fitted resistor	KJP workshop - Judd Porter, KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy, KJP workshop - Tre Szepanowski
02/10/2021	453,219 kms	ROTC Pre Check R-2153 Conduct ROTC Inspection Brake Test - PASSED Fit A/C Sensors Remove and replace cab filters / clearance light and bonnet strap	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
28/09/2021	449,539 kms	Power Socket, windsceen wipers R-2145 Replaced LH wiper blade Change out lighter plug	KJP workshop - Scott Laburniy
31/08/2021	437,082 kms	Clearance Light, Headlight, Indicators R-2077	KJP workshop - Mitchell Lancaster

Date	Reading / Units	Type / Repairer Notes	Repairer
		inspected for faults as listed on fault repair, no faults found straightened up metal ring inside LHS headlight	
19/08/2021	435,610 kms	indicator stalk R-2055 T & R air leak under cab @ rear R & R indicator stalk	KJP workshop - Mitchell Lancaster
12/08/2021	433,140 kms	Exhaust Brake R-1961 (82161BLNA Used 6/07/21 to Replace trailer plug Mitch B) Replaced both air diverter valves Replaced exh back pressure valve & wiring	KJP workshop - Luke Schmidt
30/07/2021	433,135 kms	Hoses R-2027 R & R hose	KJP workshop - Judd Porter, KJP workshop - Scott Laburniy
30/07/2021	433,135 kms	B - B Service S-543 vehicle info test trip info test and reset service trip clutch wear checked brake test - PASSED	KJP workshop - Wayne Goodlet
30/07/2021	433,135 kms	Engine Tune Up R-2120	KJP workshop - Scott Laburniy, KJP workshop - Wayne Goodlet
27/07/2021	433,135 kms	Ice pack R-2019 pressure tested and topped up cooloant, read DTC fault - findings icepack	KJP workshop - Judd Porter
19/07/2021	429,294 kms	Steering R-1996 Remove steering strut out of T08 - Fit into T22 (part ordered to put into T08)	KJP workshop - Mitchell Breen
02/07/2021	420,921 kms	Exhaust R-1956 Remove and replace exhaust brake air valve on left hand side of motor	KJP workshop - Judd Porter
29/06/2021	420,076 kms	Headlight, windsceen wipers R-1950 Replace wiper blades, adjust headlights, check through defect book	KJP workshop - Scott Laburniy
24/06/2021	417,707 kms	Vibration R-1930 Diagnose vibration in Steering - Worn gearbox mount Remove and replace both gear box mounts and road test. Inspected engine mount and cab mounts Vibration gone	KJP workshop - Mitchell Breen, KJP workshop - Mitchell Lancaster, KJP workshop - Wayne Goodlet
24/06/2021	417,770 kms	Windscreen R-1648 Cracks are small bullseye / star fractures that do NOT exceed 16mm in diameter. Has been monitored for 4 months and has not worsened - Job Cancelled	KJP workshop - Mark Johnson
18/06/2021	415,953 kms	Drive Tyres, New T-326	Ocean Tyres
18/06/2021	415,960 kms	Tyres, Wheel Alignment R-1898 1. No repair required. 2. Inspected suspension for vibration by Jack. Drag link forward seemed worn. Check drag link - all okay Vibration problem differed to R-1930 Wheel Alignment completed.	KJP workshop - Scott Laburniy
14/06/2021	416,379 kms	Smoke R-1911 Connect tech tool and inspect for related fault codes. Inactive data link - fault codes found Cleared inactive fault codes	KJP workshop - Wayne Goodlet
11/06/2021	411,571 kms	Dash cam, Excess Noise R-1854 1. Cleaned windscreen 2. Was the adjustment on dash dimmer lights switch. Fixed	KJP workshop - Mark Johnson
01/06/2021	407,858 kms	Body R-1882 Remove broken tail light, straighten up taillight bar, fit new taillight using duets plug	KJP workshop - Mark Johnson
09/05/2021	397,673 kms	B - B Service S-495 Brake Test - PASSED Mack Oil - 36Lts	KJP workshop - Scott Laburniy
09/05/2021	397,673 kms	diff oil sample R-1708 Took rear diff oil sample during service	KJP workshop - Scott Laburniy
27/04/2021	393,088 kms	leaking Radiator R-1863	KJP workshop - Mark Johnson

Date	Reading / Units	Type / Repairer Notes	Repairer
		Radiator replaced under warranty from Mack Radiator yet to be installed (waiting for it to worsen)	
09/04/2021	383,639 kms	Idler pulley R-1785	KJP workshop - Judd Porter, KJP workshop - Scott Laburniy
		Remove and replace idler pulley and fan and compressor belts	
26/03/2021	376,984 kms	Brakes, Breakdown R-1791	Rod Bianchi Motors Pty Ltd
		Found air was being supplied to service side of spring brake chamber when park brakes were released. Found relay valve at fault. Replace valve, replace brake chamber air hose fittings with reusable type.	
16/03/2021	374,367 kms	Auto Greaser R-1735	KJP workshop - Mitchell Breen, KJP workshop - Scott Laburniy
		Swap auto greaser out with one from 13KJP	
12/03/2021	372,967 kms	New T-289	Ocean Tyres
10/03/2021	370,904 kms	Fridge R-1608	Aces, gladstone refridgeration
		ACES: Inspect ice pack air conditioner - found no power to compressor - found thermostat had come unplugged. Plugged back in. GRA: Fridge replaced under warranty Remove Fridge - sent to aces to fix - refitted new fridge	
09/03/2021	370,232 kms	Air Compressor, Air Conditioner, Ice pack R-1712	KJP workshop - Judd Porter, KJP workshop - Scott Laburniy, KJP workshop - Wayne Goodlet
		Remove and replace A/C Compressor, inspect for leaks and regas Remove and replace fan belts ACES: Service call to inspect fault with A/C system. Carry out tests and suspect compressor is faulty. ACES: Service call to carry out tested with ice pack. Found oil temp switch is faulty. Fitted temp sender, tested ice pack and cleaned	
03/03/2021	366,867 kms	Battery, Breakdown R-1707	Mack / Volvo
		Replaced 4 x Batteries (AU2 21209957 - Bulldog battery)	
18/02/2021	363,694 kms	Engine Light R-1683	KJP workshop - Scott Laburniy
		Hooked computer up. Ad blue related codes level sensor / pump failure. Pressure sensor checked over hoses and wiring found tank outlet line not hooked up properly. Hooked it back up cycled key to run pump a few times. Removed ad blue pressure code and pump failure code. Pulled apart plugs and cleaned and changed level sensor wiring once back together - couldn't fault.	
15/02/2021	362,824 kms	Alternator, batteries R-1672	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
		Removed all battery terminals and check load on batteries Checked charge rate @ alternator was 13.9 v Checked with lap top and charging at 12.4 volts Found broken earth terminal under cab, Replaced broken earth lead	
10/02/2021	359,805 kms	Booster, Turbo, Vibration R-1668	KJP workshop - Wayne Goodlet
		1. Connected computer to check any codes - contacted Mack and run tests. Remove Waste gates diverter valve from T11 to fit to T22 - tested operation - all good 2. No Fault fount	
09/02/2021	358,964 kms	C - C Service S-447	KJP workshop - Judd Porter, KJP workshop - Scott Laburniy
		Brake Test - PASSED Remove and replace drag link Engine Oil - 36L Trans Oil - 18L Front Diff Oil - 20L Rear Diff Oil - 15L	
03/02/2021	354,539 kms	Air Conditioner, Ride Height R-1599	Aces, KJP workshop - Mitchell Lancaster, KJP workshop - Scott Laburniy, KJP workshop - Wayne Goodlet
		Replaced cabin A/C Filter. put gauges on and let it run a couple of cycles - cycled low. Pulled out thermostat contact cleaned plugs and refitted, consistently cycled off at 6.8 degrees while in workshop. Scott 27/01/21 - Replaced ride height control valve 31/1/21 - R&R thermostat and cycled A/C. Wayne 02/02/21 - R & R TX Valve, regas A/C, check for leaks 3/2/21 Inspected Ice pack - replaced faulty relay ACES: Found system cycling on temp. Remove compressor dust cover and inspected clutch gap. All looked okay. Customer to replace intermittent thermistors.	
27/01/2021	354,539 kms	Oil R-1619	KJP workshop - Scott Laburniy
		Checked oil level still alright almost due for service and to be sampled then preformed wheel alignment adjusted turntable R & R damaged windscreen wiper	
24/01/2021	351,861 kms	Coolant Leak , Fault Code R-1626	KJP workshop - Scott Laburniy

Date	Reading / Units	Type / Repairer Notes	Repairer
		fault code was due to the adblu level disconnected - cleaned plugs and cleared code Pressure test held steady for coolant leak just topped up coolant and tidied up	
23/01/2021	351,860 kms	light R-1627 2 & 3 LED lights were dead so replaced them	KJP workshop - Scott Laburniy
19/01/2021	348,985 kms	exhaust R-1604 Remove stacks and fitted stacks from T19 fitted 5"stacks to T19	KJP workshop - Wayne Goodlet
04/01/2021	339,293 kms	Ice pack R-1588 icepack throttle full of dirt - cleaned out	KJP workshop - Judd Porter
04/01/2021	339,293 kms	Gauge R-1567 R & R air cleaner indicator gauge	KJP workshop - Mitchell Lancaster
23/12/2020	334,473 kms	turntable R-1576 Remove and replace turntable pads	KJP workshop - Judd Porter
30/11/2020	325,716 kms	Leaks, Transmission R-1503 R & R lid and bolt seals on pwr steering cleaned out top of auto greaser	KJP workshop - Judd Porter
18/11/2020	319,998 kms	B - B Service S-408 Brake Test - PASSED	KJP workshop - Judd Porter
18/11/2020	319,998 kms	Windscreen R-1463 Crack in windshield is very minor - no repair required.	KJP workshop - Judd Porter
05/11/2020	312,870 kms	Truck annual Inspection I-94 Brake test - PASSED	
30/10/2020	308,609 kms	Bonnet Latch R-1427 Remove and replace right hand side lower bonnet strap Fitted new hub caps to steers	KJP workshop - Mitchell Lancaster
28/10/2020	305,420 kms	Air Conditioner, Wheel Alignment R-1409 Inspected A/C - Remove and replace Cab filter Completed Wheel Alignment ACES - Service call to site to inspect air conditioning system blowing hot air. Check all A/c components and pressures. Test drove truck and count not fault system. Changed wiper blades and changed out A/C Thermostat Fitted new relay holder for spotlight	Aces, KJP workshop - Wayne Goodlet
27/10/2020		Registration O-60	
19/10/2020	301,242 kms	Chassis Plate, Mud Guard R-1385 Cleaned up bent plate, nothing else can be done	KJP workshop - Mark Johnson
28/09/2020	297,635 kms	batteries R-1345 Remove and replace 4 x batteries	KJP workshop - Mitchell Lancaster
04/09/2020	286,974 kms	Bug Deflector R-1287	
03/09/2020	286,974 kms	Air Conditioner, Bonnet, Fridge, Power Steering, Sign, Spot Lights R-1213 1. leaked gas at TX Valve waiting on replacement R & R suction- line and trace A/C leak 2. CT SMITH - Stiff steering caused by a power steering oil bypass failure. Replace power steering box. (50% of parts under warranty) 3. T & R problem 4. replaced bonnet strap 5. Fit all new clips for road train covers (Parts from Hendens invoice 2007120) Help with A/C	KJP workshop - Mark Johnson, KJP workshop - Wayne Goodlet
26/08/2020	282,583 kms	Shock Absorber R-1244 R & R front shockies Degrease and wash under truck while its on hoist	KJP workshop - Mark Johnson
25/08/2020	242,861 kms	Bug Deflector , Turntable R-1162 R & R bug deflector Remove and replace turntable pad	KJP workshop - Mark Johnson
24/08/2020	282,583 kms	B - B Service S-350	KJP workshop - Mark Johnson

Date	Reading / Units	Type / Repairer Notes	Repairer
		Brake test - PASSED	
24/07/2020	267,071 kms	Coolant Leak R-1183 Had pressure tester on for 30min, no leak detected.	KJP workshop - Mark Johnson
30/06/2020	255,277 kms	Seat R-1125 R & R new valve for seat	KJP workshop - Mark Johnson
19/06/2020	250,553 kms	Brake problems R-1111 Inspect cab mounting points. Loose pedestal on right hand side. Tighten loose bolt and cab support bar. Change waste gate driver valve exhaust silencer. Unbolted air valve from engine, unbolted fittings from air valve. bolted new air valve on and connected fittings onto new air valve.	CT Smith Mechanical
02/06/2020	243,815 kms	Air Leak R-1355 Undo 4 air fittings and the plug for the valve. Remove 2 bolts holding valve into place. Place new air valve in and secure top air fittings on then the bottom air fittings. Then secure the plug. Tighten bolts back up.	CT Smith Mechanical
28/05/2020	242,928 kms	C - C Service S-306 Brake test - PASSED	
19/05/2020	237,589 kms	General Checkover, Wheel Alignment R-1014 1. Completed Wheel Alignment 2. Completed General Checkover	KJP workshop - Wayne Goodlet
11/05/2020	233,551 kms	Lights R-984 fixed driving lights, was a dirty relay checked gearbox, oil level, OK checked suspension on shaker pads, no play found fixed plastic guards that were loose needs to go to mack, oil leak at rear of engine to get bracket replaced and exhaust leak when engine brake on.	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
23/04/2020	228,501 kms	brackets, Dash cam R-967 R & R dashcam with one in kirks office - JP R & R cab fire extinguisher bracket - JP Fix road train cover - W.G Tighten LH step and smear greaser on hinges - JP	KJP workshop - Judd Porter, KJP workshop - Wayne Goodlet
13/04/2020	225,418 kms	Lights R-944	KJP workshop - Mark Johnson
26/03/2020	221,474 kms	Mud Guard R-879 Adjust RHF mudguard as mush as possible thin layer of vaso applied to top bonnet seal R & R RHR cab shockie checked for oil leaks - no leaks found	KJP workshop - Bill Shanahan, KJP workshop - Judd Porter
23/03/2020	221,470 kms	Replace T-144	Ocean Tyres
13/01/2020	204,142 kms	Wheel Alignment R-688	
13/01/2020	204,146 kms	new T-116	Ocean Tyres
16/12/2019	196,107 kms	B - B Service S-235 Degreased and wash engine/truck Brake test - PASSED	
19/11/2019	179,520 kms	Truck annual Inspection I-25 Brake test - PASSED	
25/10/2019	164,421 kms	Cab Mounts R-414 Realigned exhaust guard.	KJP workshop - Jason Amos
20/10/2019	162,775 kms	Air R-501 Remove all brackets and Guards from rear of cab to gain access. Tighten fitting nut. Repair previously damaged threads in guard mounts. Find and fit correct size bolts to secure guards. Refit guards and test.	KJP workshop - Bill Shanahan
16/10/2019		Registration O-9	

Date	Reading / Units	Type / Repairer Notes	Repairer
07/10/2019	154,071 kms	B - B Service S-185 Brake Test - PASSED	KJP workshop - Mark Johnson, KJP workshop - Scott Laburniy
03/10/2019	150,466 kms	batteries, General, Lights R-459 1 - Replaced cable and topped up batteries 2 - Remove and replace LED parklight 3 - Completed inspection	KJP workshop - Judd Porter
10/09/2019	138,831 kms	Air Leak R-355 Replace small section of hose	KJP workshop - Mark Johnson
15/08/2019	116,491 kms	Starting Problem R-293 Chris Smith - repaired under warranty	CT Smith Mechanical
06/08/2019	116,485 kms	Air Leak , Excess Noise R-272 1 - Trace and repair excessive noise 2 - Trimmed air hose and swapped fitting	KJP workshop - Wayne Goodlet
01/08/2019	113,847 kms	New T-8	Ocean Tyres
31/07/2019	113,843 kms	C - C Service S-150 Brake Test - PASSED Parts Used: 4 x Oil Sample Kits 23448457 1 x Filter Kit 85114535 1 x Air Dryer filter KO39454 1 x AD Blue Filter 21516231 1 x Power Steering Fluid HF35486 1 x Lube Filter P559128 1 x Air Filter P822686 1 x Air Filter P1533551 2 x Wiper Blades TNB24-20	
17/07/2019	102,873 kms	Indicators R-206 Remove and Replace Trailer light plug on suzi coil	KJP workshop - Wayne Goodlet
08/07/2019	94,658 kms	Exhaust Flex R-166 Replaced split exhaust flex under cab	CT Smith Mechanical
04/07/2019	98,212 kms	Junction Block R-196 Remove and Replace electrical junction block	KJP workshop - Bill Shanahan
25/06/2019	93,002 kms	Chocks, Junction Block, Lights, Wheel Alignment R-153 1 - Traced spotlight fault to blown fuse - Replace fuse 2 - Fit LED healights 3 - Fit crank for chock holder 4 - Complete wheel Alignment	KJP workshop - Wayne Goodlet
05/06/2019	80,932 kms	Latch R-201 Remove and Replace bonnet straps	
27/05/2019	73,916 kms	B - B Service S-103 1. Rear of tappet cover leaking- Check next service	KJP workshop - Judd Porter
12/02/2019	32,343 kms	B - B Service S-66	

Signed: _____
Name: _____
Date: _____