



Vehicle History Detail



Fleet #	1CL7SA
Registration	1CL7SA
Make	Kenworth
Model	T409
VIN / Chassis #	6F5000000FA453800

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
01/07/2025	1,116,484 kms 19,909 hrs	BROKEN BOLT, Exhaust, weld R-12500 REMOVE BROKEN BOLTS FROM EXHAUST MANIFOLD, WELD CRACKS IN BRACKET	VIC Workshop		\$0.00
16/06/2025	1,115,168 kms 19,867 hrs	ABS, ADBLUE FAULT, CHECK ENGINE LIGHT, Engine Tune Up, SPEED LIMITER, WARNING LIGHT R-12360 KENWORTH DAF MELBOURNE INVOICE 1341684 90NFTU Hours 02/06/2025. Carryout Engine Tune IP. Completed Engine tune up 98PITADBLUE Hours AdBlue Shows empty than speed limiter stops Working. Warning Lights - Check Engine - ABS Fault . A diagnosis was conducted using the Davie tool, identifying multiple error codes. Upon inspection, an open circuit was discovered within the fuel sender, and the EAS harness was found to be filled with water and showing signs of partial corrosion. An investigation into the ABS warning light did not reveal any faults; the warning was determined to be a result of a breakdown in the CAN wiring due to the corrosion of the EAS wiring harness. Additionally, the Bendix system had an inactive code related to wheel speed sensor issues. While it faulted during the road test, no issues were present upon further testing. A new fuel sender and harness were installed. Parts have been ordered. Although preparations for repinning and reconnecting were made, the harness was found to be damaged further up, where the conduit had been cut back. One snapped wire was repaired, and several others showed signs of wear. These were taped up for now but will need to be replaced once the new harness arrives. The vehicle was road tested and ok for now. . Removed old harness from truck - ran new harness and cable tied as I progressed - got everything plugged in - adjusted to make sure everything was fitting nicely - finished cable tied off - heat shields refit - refit deck plate - refit side panel - truck went for road test - all working correctly	KENWORTH	1341684	\$6,685.35
20/05/2025		BATTERY R-12166 S & F 1 x NEW BATTERY TO VEHICLE.	VIC Workshop		\$323.14
17/02/2025	1,114,521 kms 19,848 hrs	C - C Service S-20410 CARRY OUT C + A-SERVICE AS PER SERVICE SHEET, CHECK ALL TYRES, REPAIR BROKEN EARTH WIRE ON LHF INDICATOR, REPLACE MIDDLE ROOF LIGHT & MIRROR LIGHT GLOBE RH, REPLACE WINDSCREEN LH DEFROST VENT, DRAIN & CHANGE TRANSMISSION OIL & FILTER, REPLACE ADBLUE FILTERS, REPLACE REAR TRACK ROD BUSHES, REPLACE EXHAUST BRAKE AIR LINE, RE-SEAL FRONT & REAR DIFFS - REASSEMBLE WITH NEW OILS & FILTER, REPLACE CLUTCH PEDAL RUBBER, REPLACE RH DOOR HANDLE TRIM, REPLACE 2 x TELL TAIL GLOBES FOR CRUISE & ENG BRAKE, REFIT ALL DRIVE HUB CAPS, FIT NEW RH STEER HUB CAP, ADJUST BONNET MOUNTS - DOWN INSTALL A/C CONDENSOR & MESH COVER, REFIT TWISTED BOOST HOSES, TOP COOLANT, CLEAR AFTER TREATMENT LIGHT, STRAIGHTEN STEERING WHEEL,, REPAIR AIR LEAK NEAR TO ENGINE BLOCK,	VIC Workshop		\$8,028.44

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
16/12/2024	10,286 kms 19,759 hrs	Brakes, Slack Adjusters R-11267 THACKERS INVOICE 67476 16.12.24 -Removed wheels, drums and replaced brake shoes on front drive axle. -Fitted wheels and tensioned wheel nuts -Removed all 4 drive slack adjusters, fitted new slack adjusters and set up following instructions. Concerns:- -S cam bushes are worn but serviceable, Monitor	Thackers Trucks and Engineering	67476	\$1,826.00
30/11/2024	6,777 kms 19,702 hrs	B - Oils & Filters S-19668 CARRY OUT B-SERVICE AS PER SERVICE SHEET FOR SATURDAY NOVEMBER 30th AS PER JASON / JUSTIN PHONE DISCUSSION. THACKERS INVOICE 67271 30.11.24 -Carry out B Service as per attached service sheet. - Plugged in techtool, found lots of fault codes for Adblue, diagnosed that adblue sender could be causing engine shut down light to come on, recommend replacing sender in tank. -Replaced one wiper blade. Concerns:- -Auto adjusters not working. -Fuel primer leaking when priming. -Spring keepers are worn. -Front drive axle brakes worn. -Front axle shockers are loose, unable to tighten. -ABS light flashes on dash - will need more investigation.	Thackers Trucks and Engineering	67271	\$1,708.25
12/11/2024	19,597 hrs	REPAIRS R-10975 THACKERS INVOICE 67075 2.11.24 -Removed dash, fitted new speedo and calibrated, couldn't change kms. - Speedo is out by 4 kms says 64kph when truck is doing 60kph. -Removed and replaced hydraulic coupling at back of truck, tested, all ok. -Drained coolant, removed hose off back of water pump, removed fitting and replaced dowty washer. -Cut new lenth of hose and replaced hose clamps. -Refilled with drained coolant. -Replaced mudguard bracket on LH front drive. -Adjusted brakes. 9.11.24 Invoice Notes. Truck was back for A/C work (billed on another invoice) Truck had 2413km. We adjusted speedo and now was working correctly.	Thackers Trucks and Engineering	67075	\$2,555.90
12/11/2024	2,413 kms	Air Conditioning R-10974 THACKERS INVOICE 67164, 9.11.24 Diagnose leaking hose. Fit new hose and regas air conditioning	Thackers Trucks and Engineering	67164	\$957.00
06/11/2024	1,182 kms 19,605 hrs	Dash Lights, SIDE LIGHTS R-10944 REPLACE RHS & LHS SIDE LIGHTS & REPAIR DASH LIGHT.	VIC Workshop		\$30.49
04/11/2024		New Drive Tyres T-4750 TYREPOWER BENDIGO INVOICE 153455 S & F 8 x NEW DRIVE TYRES re attached pdf	Tyrepower Bendigo	153455	\$3,550.00
23/10/2024		S/H TYRE T-4730 TYREPOWER BENDIGO INVOICE 153221 Truck Tyre Strip & Fit 5 Truck Strip & Fit as Required RUN OUT TRUCK TYRE 3 USED 3 SUPPLIED TYRES AND 2 OWNER SUPPLIED TYRES 4 ACROSS REAR AXLE AND 1 RHF INNER REPLACED AFTER HOURS SERVICE CALL Travel Fee Per Klm TWO TRIPS TO STORE FOR TYRES AND RETURN SUNDAY 20TH TYRES REPLACED WERE ALL UNROADWORTHY TRUCK TO BE TRADED IN NEXT COUPLE OF WEEKS	Tyrepower Bendigo	153221	\$795.00
19/10/2024	1,088,618 kms 195,017 hrs	A - Grease & Brake Adj S-19219 CARRY OUT A2 SERVICE AS PER SERVICE SHEET FOR SATURDAY OCTOBER 19th PER JASON / JUSTIN PHONE DISCUSSION. THACKERS INVOICE 66869, 19.10.24 Carry out A Service as per attached service sheet. Topped up engine oil. Need to order new step light for LHS of tank. Tightened mudguards. Tightened hose behind water pump. Tightened hydraulic hose - monitor Checked connections on speedo, all ok, will need more time to diagnose why speedo is not working. Concerns:- Front drive axle brakes need to be done next service. Spring keepers are worn. reminder R-3894 added	Thackers Trucks and Engineering	66869	\$490.82
26/09/2024	905,017 kms	WIPER ARM & BLADE R-10698 GRAHAM THOMSON MOTORS INVOICE 531536 P; RH WIPER ARM TO BE REPLACED C: BROKEN R: REMOVED BROKEN WIPER ARM AND FIT NEW, FIT NEW WIPER BLADE TO LHS	Graham Thomson Motors	531536	\$335.84

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
24/08/2024	77,728 kms 19,311 hrs	A - Grease & Brake Adj S-18660 CARRY OUT A1 service as per service sheet FOR SATURDAY 24th per Jason / Justin phone discussion. THACKERS INVOICE 66401. 24.8.24 Carry out A Service as per attached service sheet. Concerns:- Front light on LH step not working. Coolant leak a hose behind water pump. Oil just above minimum on dipstick reminder R-3816 added	Thackers Trucks and Engineering	66401	\$286.00
27/07/2024	1,066,395 kms 19,119 hrs	B - Oils & Filters S-18378 CARRY OUT B-SERVICE AS PER SERVICE SHEET, FOR JULY 27th PER JASON / JUSTIN THACKERS INVOICE 66153 27.7.24 Carried out B service as per attached service sheet. Repaired wiring in step light. Changed globe in left hand mirror light. Replaced hose clamp on coolant pipe. Removed shocker and space out to tighten bushes.. Invoice Notes Faults Found: Fuel tank needs replacing Centre roof light not working Cab shocker leaking RH bonnet rest broken oil pressure gauge not working REMINDER R-3741 ADDED.	Thackers Trucks and Engineering	66153	\$1,922.57
16/07/2024		New Steer Tyres T-4527 TYRE POWER BENDIGO INVOICE 151243 S & F 2 x NEW STEER TYRES re attached PDF	Tyrepower Bendigo	151243	\$1,486.00
22/06/2024	1,053,593 kms 18,895 hrs	A - Grease & Brake Adj S-18086 CARRY OUT A2-SERVICE AS PER SERVICE SHEET AS DISCUSSED per JASON & JUSTIN. THACKERS INVOICE 65820 22/06/24 A service. Carry out A Service as per attached service sheet. Concerns:- Repositioned top boost hose RH side and tightened clamp. R/H steer tyre low. Replaced mirror light globes L/H & R/H.	Thackers Trucks and Engineering	65820	\$319.93
13/05/2024		MT Data, Upgrades R-10050 ELITE TRACKING SOLUTIONS INVOICE 1338 4G Upgrade Supplied & fitted new triband antenna Kenworth T409 1CL7SA Old Sim 1: 8500 0488 3359 5N New Sim: 8000 4548 1611 9N S/N: 464007881	ELITE TRACKING SOLUTIONS	1338	\$308.00
10/05/2024	1,038,167 kms 18,632 hrs	A - Grease & Brake Adj S-17671 CARRY OUT A2-SERVICE AS PER SERVICE SHEET THACKERS INVOICE 65426 10.5.24 -Carry out A Service as per attached service sheet. -Topped up oil. -R/H front fuel tank leaking - repaired (Removed fuel tank, weld crack refit fuel tank R/H front). -Cab sway bar bushes cracked but ok. -Bottom backing plate on RH rear axle missing	Thackers Trucks and Engineering	65426	\$1,184.21
09/04/2024	1,027,877 kms 18,458 hrs	A - Grease & Brake Adj S-17463 CARRY OUT A- SERVICE AS PER SERVICE SHEET as per Justin & Jason phone discussion 05/04/24 THACKERS INVOICE 65157 9.4.24 -Carry out A Service. -Fixed cigarette lighter output, chased wiring and found blown fuse and replaced fuse. -Topped up coolant and tightened hose clamps. -Tightened cross member under back of gearbox. - Delivered truck to Bendigo yard. Concerns:- -Front marker lights on each mirror not working, 2 on drivers side 1 on passenger side. -Middle roof light not working. -Front steer springs have movement REMINDER R-3628 ADDED.	Thackers Trucks and Engineering	65157	\$668.31
28/03/2024		NEW TYRE, S/H TYRE T-4341 SOLAR CITY TYRE SERVICE INVOICE 509168 S & F 1 x NEW TYRE & 1 x SECOND HAND TYRE TO POSITION 11/12. re attached pdf	Solar City Tyre Service	509168	\$839.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
28/03/2024	1,015,425 kms	Air Dryer, BREAKDOWN, Hydraulic Hose R-9716 THACKERS INVOICE 64900 -Called out to truck not building up air at Ridley's Bendigo, found the air dryer bypassing. Plugged and and had the truck return to the workshop. Fitted anew air dryer assembly and checked operation. OK. -Had the truck brought into the workshop, hydraulic hose had not been dis connected from the trailer. Removed damaged hose and rear bracket, fitted a temporary hose so the truck could be unloaded. Travelled to the Bendigo yard and removed the damaged hose's from the trailer. Had 3 hose's made and fabricated a new bracket for the truck and trailer. brought the truck back in and fitted the bracket and hose and tied up. Returned to the yard and picked up the trailer and brought it back to workshop and fitted the new bracket and 2 hoses to the trailer and topped up the hydraulic oil and cleaned and tested operation. OK. Delivered the truck back to the yard	Thackers Trucks and Engineering	64900	\$4,820.10
01/03/2024	1,014,135 kms 18,195 hrs	B - Oils & Filters S-17112 THACKERS invoice 64811 CARRY OUT B-SERVICE AS PER SERVICE SHEET, 1.3.24 Carry out B Service as per attached service sheet. Concerns:- Coolant weeping from hose at back of water pump. LF front hub cap weeping. Clutch pedal has no free travel. Nylon Pads on turntable damaged. Oil pressure gauge in cab not working. Bottom backing plate on RH rear axle broken. reminder r-3591 ADDED.	Thackers Trucks and Engineering	64811	\$1,813.12
15/02/2024		FRIDGE REPAIRS R-9479 FRIDGE REPAIRS TEST POWER / LIGHTER SOCKET & REPLACE FUSE, REPLACE FRIDGE CORD PLUG-TEST SOCKET VOLTAGE 9.6v AT BOTH PLUGS (FURTHER WORK REQUIRED).	VIC Workshop		\$6.33
30/12/2023	993,313 kms 17,853 hrs	A - Grease & Brake Adj S-16553 THACKERS INVOICE 64253 CARRY OUT A2-SERVICE AS PER SERVICE SHEET 30.12.23 Carried out A service as per service sheet attached.. Fitted E clip to wiper arm Tightened hose clamps on heater hose.	Thackers Trucks and Engineering	64253	\$324.50
05/12/2023	984,947 kms	flasher can replaced R-9092 Replaced flasher counter and adjust timing switches to truck New phone cradle installed check all working well	VIC Workshop		\$264.59
02/12/2023	983,856 kms 17,689 hrs	A - Grease & Brake Adj S-16291 THACKERS INVOICE 63976 2.12.23 -Carried out an A service as per service sheet.	Thackers Trucks and Engineering	63976	\$253.00
22/11/2023	979,755 kms	Electrical Fault R-9010 INDICACATOR + WIRING + TANK-LIGHT/S REPAIRS. repair truck for no Rh flasher on rear-find rubbed wiring at Lh steer spring & fire wall + repair rh step lights.	VIC Workshop		\$30.49
19/10/2023	970,631 kms	Annual Primemover Inspection I-729			\$0.00
17/10/2023		FIRST AID KIT, SUPPLY TO VEHICLE R-8860 SUPPLY FIRST AID KIT TO DRIVERS CAB.	VIC Workshop		\$26.40

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
17/10/2023	970,631 kms	C - C Service S-15928 CARRY OUT C & B SERVICE AS PER SERVICE SHEET, REPLACE OIL,FUEL,WATER,ADBLUE,CAB AIR & POWER STEERING FILTERS, REPLACE EXHAUST MANIFOLD GASKETS + COMPONENTS, S & F NEW TORQUE ROD BUSHES TO FRONT AND REAR ASSEMBLIES, S & F NEW FRONT CAB BUSHES & FRONT ENGINE MOUNT BUSHES, REPLACE COMPRESSOR COOLANT HOSES, S & F NEW A/C BELT AND TENSIONER, FIT NEW DRIVERS SEAT - SEAT COVER. S & F NEW RH STEP LIGHT & LH TAIL LIGHT, REPLACE LEAKING LH S-CAM SEAL, SUPPLY NEW CAB BLOWER NOZZLE & HOSE, CAC CLEAN, LHR TOP SHOCKER BUSH REPLACED, FIT NEW 7 PIN PLUG-FRONT HOOK UP, REPLACE CAB SHOCKERS & AIT BAGS, REPLACE REQUIRED REFLECTORS, AIR CON ISSUE REPAIRED PER COOL ZONE, HUB OIL & GASKETS REPLACED, REPLACE 3 X DASH GLOBES, REPAIRED CLOCK SPRING, ROTATE DRIVE TYRES, ADJUST STEER AXLE BEARINGS !!COOL ZONE A/C REPAIR!!	Cool Zone Ballarat, VIC Workshop		\$5,012.73
13/10/2023		Annual Primemover Inspection I-724			\$0.00
10/10/2023		New Steer Tyres T-3895 TYRE POWER BENDIGO INVOICE 145546 S & F NEW STEER TYRES	Tyrepower Bendigo	145546	\$1,496.00
30/08/2023	970,631 kms	Annual Trailer Inspection I-848 Annual inspection			\$0.00
23/08/2023	954,437 kms	EXHAUST FLEX R-8622 REPLACE BROKEN EXHAUST FLEX, REPLACE BROKEN HEADLIGHT BUCKET RETAINING RING	VIC Workshop		\$1,659.07
19/08/2023	952,885 kms 17,153 hrs	A - Grease & Brake Adj S-15338 THACKERS INVOICE 62981 19.8.23 Carry out A Service as per attached service sheet. - Replace globe in mirror - Adjust clutch - Replace wiper blade bracket - Replace air line fittings on weight gauge. - Take truck back to yard. Concerns:- - King pin have 1mm up and down, monitor next service	Thackers Trucks and Engineering	62981	\$515.03
15/08/2023	950,948 kms	Batteries R-8599 Remove and replace batteries as required	VIC Workshop		\$612.57
22/07/2023	942,355 kms 16,975 hrs	A - Grease & Brake Adj S-15091 THACKERS INVOICE 62760 22.7.23 Carry out A Service as per attached service sheet. - Change globe in mirror light. - Check over grease system, couldn't find screen to adjust settings. Deliver truck back to yard. Faults found: RH top mirror light not working. Exhaust manifold leaking LH steer brake over greasing	Thackers Trucks and Engineering	62760	\$320.35
12/07/2023	936,892 kms	FUEL LEAK R-8560 KENWORTH DAF MELBOURNE INVOICE 1185446, CHECK TRUCK FOR FUEL LEAK,FOUND LEAKING FUEL RAIL - REPAIR AND TEST. re attached pdf	Kenworth	1185446	\$380.33
10/07/2023		bonnet latch R-8474 S & F NEW LATCH-HOOD , HOLD DOWN.	VIC Workshop		\$229.17
17/06/2023	937,824 kms 16,782 hrs	B - Oils & Filters S-14729 Thackers invoice 62469 CARRY OUT B-SERVICE AS PER SERVICE SHEET, REMINDER R-3012 ADDED RE MULTIPLE CONCERNS per THACKERS. re attached pdf	Thackers Trucks and Engineering	62469	\$1,719.67
16/06/2023	931,677 kms	light R-8390 S & F NEW LH CAB ROOF LIGHT per REMEINDER R-2970, WASH FUEL RAIL TO INSPECT FOR SUSPECTED LEAK -thackers advised to investigate at service S-14729 17/06/23, REPLACED UHF HAND PIECE.	VIC Workshop		\$116.42

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
25/05/2023	923,307 kms	Ride Height valve R-8322 Driver complaint of erratic ride height and loosing air, inspected found LHS valve was sloppy and worn out, Fit 2 x new ride height valves and re-adjust to 10.5"	VIC Workshop		\$654.69
08/05/2023	915,787 kms	A - Grease & Brake Adj S-14404 CARRY OUT A-SERVICE AS PER SERVICE SHEET, RH TANK LIGHT REPLACED, REPLACE 3 X MIRROR LIGHTS, REPLACE LHR & RHR TAIL LIGHTS, REPAIR AUTO GREASER, **REMINDER R-2879 ADDED**	VIC Workshop		\$431.47
11/04/2023	906,336 kms	NEW TYRE T-3575 S & FIT 8 X NEW DRIVE & 2 X STEER TYRES per DOCKET #1211 DONE @ S-14183	VIC Workshop		\$5,286.38
11/04/2023	906,336 kms	B - Oils & Filters S-14183 carry out b-service as per service sheet, s & f new drive & steer tyres per DOCKER #1211 re Reminder R-2639	VIC Workshop		\$313.82
04/04/2023	905,017 kms	FAILED NoX SENSOR R-8200 SHEPPARTON TRUCK CENTRE INV-525417. Nox SENSOR FAULT re attached pdf invoice	Shepparton Truck Centre	525417	\$947.55
28/03/2023		A - Grease & Brake Adj S-14072			\$0.00
06/03/2023	895,616 kms	A - Grease & Brake Adj S-13803 CARRY OUT A-SERVICE AS PER SERVICE SHEET, REPLACE CAB AND ENGINE AIR FILTERS, REPLACE RIDE HEIGHT ROSE JOINTS. REMINDERS R-2638 + 39 + 40 + 41 ADDED.	VIC Workshop		\$181.85
28/02/2023		CONDENSER FAN R-8022 FRESCO REPAIR CHECK FAULT, FOUND FAULTY CONDENSER FAN. REPLACE CONDENSER FAN AND TEST OK.	TRANS AIR & ELECTRICS BENDIGO		\$324.50
27/02/2023	891,970 kms	Valve Stem T-3468 REMOVE AND REPLACE LEAKING VALVE STEM IN RHR-O TYRE.	VIC Workshop		\$0.00
17/02/2023	891,202 kms	Clutch Adjust R-7973 Adjust clutch as required, adjust linkage to obtain correct clutch brake.	VIC Workshop		\$0.00
13/02/2023	888,558 kms	FRIDGE PLUG R-7946 S & F 12v FRIDGE PLUG LEAD	VIC Workshop		\$29.54
31/01/2023	887,798 kms	Hydraulic leak R-7904 S & F NEW TEMA HYDRAULIC COUPLER FEMALE, FIT NEW BATTERY BOX CLIP / FASTENER.	VIC Workshop		\$203.13
24/01/2023	887,085 kms	B - Oils & Filters S-13433 b-service completed, RH UHF BASE & COAX REPLACED, REAR LOWER SHOCKER BUSHES REPLACED, RHM BRAKE STONE GUARD REPLACED. **ADDED REMINDERS R-2550 & 51**	VIC Workshop		\$579.59
04/01/2023		BANNER, LED BEACON, Nut Cover R-7772 S & F NEW NUT COVERS per JASON	VIC Workshop		\$367.83

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
28/11/2022	880,290 kms	A - Grease & Brake Adj S-12902 carry out a-service as per service sheet, FIT NEW FUEL TANK J BRACKETS + RUBBERS AND COMPONENTS (per reminder R-2409), ROTATE LH FUEL TANK , FIT NEW FUEL TANK STEP LHS, FIT NUMBER PLATE TO BUMPER, ADJUST BONNET, FIT ORING KIT TO HYD COUPLER, FIT SECOND HAND TYRE TO LHRI, FIT FEMALE PVR, ADJUST AIR GAP OR RHR WHEEL SENSOR AND CLEAR FAULT CODE, FIT NEW CABIN FILTER, FIT NEW LHS TAIL LIGHT. ***ALSO NOTE R-7564 REPAIR no costings***	VIC Workshop		\$1,385.95
25/11/2022	880,290 kms	FUEL TANK SUPPORTS R-7564 REMOVE AND REPLACE DAMAGED FUEL TANK J-BRACKETS AND COMPONENTS -per Reminder R2409. ****for all labour and parts re service S-12902 job card 13871 **** REPAIR CARRIED OUT WITH A-SERVICE.	VIC Workshop		\$0.00
08/11/2022	878,436 kms	bonnet latch R-7460 S & F NEW LHS BONNET LATCH	VIC Workshop		\$114.59
26/10/2022	877,039 kms	PVR Fitting R-7381 Replace PVR fitting-FEMALE	VIC Workshop		\$0.00
28/09/2022	875,329 kms	CLOCK SPRING, lights R-7227 S & F 1 NEW LH & RH TANK LIGHTS S & F NEW STEERING WHEEL CLOCK SPRING ADJUST AND SET (per reminder R-2324)	VIC Workshop	1119638	\$501.74
27/09/2022		Engine Tune Up, Fault Codes R-7260 WARNING LIGHTS - CHECK ENGINE, AFTERTREAT/MIL, ENGINE BRAKE ISSUE, ENGINE FAN ISSUE. - PLUGGED IN AND CHECKED FOR FAULTS, NO POWER TO E-FAN AND EXHAUST BRAKE. - CHECKED FUSES, FOUND 10A FUSE AT ECM PLUG BLOWN. - REPLACED FUSE, ALL FAULTS INACTIVE. ROAD TESTED VEHICLE, NO FURTHER FAULTS FOUND. CARRIED OUT KENWORTH MX ENGINE TUNE-UP AS PER KENWORTH SPECIFICATIONS.	KW/DAF Melbourne		\$1,237.73
21/09/2022	874,522 kms	puncture repair T-3139 PUNCTURE RHR INSIDE TYRE RAN OFF BEAD REPLACED WITH S/H JINYU TYRE	VIC Workshop		\$0.00
06/09/2022		Annual Primemover Inspection I-348	VIC Workshop		\$0.00
12/08/2022		parts R-7027 PER GEOFF BURGESS PICK UP FOR VEHICLE	Scobies Ballarat		\$0.00
10/08/2022	872,540 kms	B - Oils & Filters S-11865 B-SERVICE AS PER SERVICE SHEET	VIC Workshop		\$642.62
31/05/2022		CAPEX INSURANCE R-6820 28/12/22 (JOB CARD 14037) -NED -FIT BUG SCREEN.(884591 KM'S). COOL ZONE INVOICE 5283663 DETAILS, ONSITE SERVICE CALL TO BALLARAT WORKSHOP , LABOUR TO INSTALL COMPONENETS RUN AND CHECK OPERATION.	VIC Workshop		\$28,982.97
16/05/2022	869,761 kms	B - Oils & Filters S-11077 B service as per service sheet Mirror globes replaced x4 Dash globes x2 replaced x3 nut covers replaced (2nd hand stock) Air filter replaced Cab filter replaced Rebook: Cab mounts	VIC Workshop	1460030412	\$557.70

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
14/04/2022		STEERING BOX REPAIR R-6609 PARTS FITTED BY HYDROSTEER @ STEERING BOX REPAIR HYDROSTEER COMMENTS: check steering reseal steering gear replaced sector shaft and pitman arm (supplied) change uni joints and rephase coloumn	Hydrosteer	029256	\$3,076.93
07/04/2022	856,530 kms	A - Grease & Brake Adj S-10747 Complete A service as per service sheet Fit hubcap to LHR drive Replace UHF aerial Fit nut covers to LHF steer Cross rotate drive tyres and spin insides on rims Replace rear axle brakes and drums	VIC Workshop	1080006	\$974.15
11/03/2022	846,511 kms	Coolant Change R-6500 Drain coolant into tubs, remove 5/8 coolant hose from LHR of engine as hose was wrong size and leaking. Cut new 1/2" hose and refit to truck Fill up coolant then top up remaining 6 litres Pressure test system Replace steer tyres as RHS had wire hanging out x2 second hand of shelf fitted	VIC Workshop		\$28.79
24/02/2022	842,014 kms	B - Oils & Filters S-10228 Complete B service as per service sheet tighten tacho nut on back of guage complete annual inspection fit 4 steer nut covers to RHS fit 1 light surround to step lights	VIC Workshop	1081089	\$318.36
24/02/2022	842,014 kms	Annual Primemover Inspection I-132	VIC Workshop		
15/02/2022	838,591 kms	Coolant Change R-6397 Drain coolant from radiator, refill with green coolant (50L), run truck with rad cap off and heaters going to bleed system then top up coolant.	VIC Workshop		\$239.92
31/01/2022	831,551 kms	A - Grease & Brake Adj S-9903 LABOUR TO LOCATE FAULTS TO ELECTRICAL FAULT TO PRESSURE SWITCH WIRING & HEATER BLOWER MOTOR. REPAIR PRESSURE SWITCH WIRING & INSTALL NEW BLOWER FAN MOTOR (SUPPLIED) RUN & CHECK OPERATION Clutch Adjusted LHM Roof Light Replaced Globes In Mirror Light Replaced RHS Engine Light Was On, Cleared Codes With Scan Tool, Test Drive To Brown Hill, Codes Didn't Come Back So Sent Truck To Work	VIC Workshop	1063747	\$1,134.23
13/01/2022	818,246 kms	Fault R-6262 plugged in lap top but could not comunicate with dmci. checked power & earths at can & eas all good. disconnected batteries & reconnected was able to read dmci & can. had can faults for everything. removed murphy guage to isolate & road tested vehicle did not fault. adblue & oil pressure guages working o.k. Sub	Kenworth	1061426	\$176.00
22/12/2021	819,697 kms	B - Oils & Filters S-9763 Replaced Blown Fuse For Cig Socket Refit Broken Grease Lines Onto Auto Greaser Blow Out Radiator and Charge Cooler Fill Auto Greaser Wash Engine	VIC Workshop		\$291.70
17/12/2021	816,000 kms	New Steer Tyres T-2718 Replace Steer Tyres	VIC Workshop		\$861.30
03/12/2021	809,467 kms	A - Grease & Brake Adj S-9064 Replaced Middle Roof Light Replaced RHS Mirror Globes Air Filters Replaced Cabin Filter Replaced Fire Ext Replaced Exhaust Flex Between Ad blue Muffler and Stacks replaced Dash Globe Replaced In Diff Temp Gauge Telltale Globes Replaced For Cruise Missing Wheel Nut On RHF Drive Replaced and Retorqued Replace Wiper Blades	VIC Workshop	1054795	\$602.63
01/11/2021	801,046 kms	JUMPSTART R-5943 Travel To Ballarat Site Jump Start Truck With Another Truck	VIC Workshop		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
07/10/2021	798,152 kms	General Repair R-5827 Removed Drive Tyres and Brake Drums. Cleaned Out Mud From Rear Of Truck Lift Truck In Air Wash All Underneath Refit Brakes and Tyres Clean Engine Bay	VIC Workshop		\$3.52
06/10/2021	798,075 kms	General Repair R-5840 Travel To Mamnbodar Inspected Truck For Damage Due To truck Running Off Road. Assist With Tow Operator To Remove Truck From Bog Clean Debris and Returned To Workshop	VIC Workshop		\$0.00
01/10/2021	797,216 kms	B - Oils & Filters S-9045 B service completed RHS LED number plate light replaced Hose clamp on compressor coolant feed line tightened Steer nut covers x5 replaced	VIC Workshop		\$360.92
17/09/2021		coolant leak R-5756 Travle to near Michael uwins wines Inspect coolant leak Remove LH panel under cabin Found split hose for air compressor and replaced hose Refilled coolant, run to get hot and pressure test Drove back to Ballarat site to wash and refit panel under cab	VIC Workshop		\$242.04
23/08/2021	783,180 kms	A - Grease & Brake Adj S-7612 Engine oil temp gauge replaced Steer tyres replaced and balanced New drive tyres Tank light wiring repair LHS 3 wedge globes in mirrors replaced A service as per service sheet	VIC Workshop	1027450	\$348.09
23/08/2021	783,150 kms	New Steer Tyres T-2508 Replace steer tyres	VIC Workshop		\$811.80
23/08/2021	783,150 kms	New Drive Tyres T-2509 Replace Drive Tyres	VIC Workshop	0964	\$2,000.00
19/07/2021	772,324 kms	B - Oils & Filters S-8319 Fit 2 Dash Globes Fit 3 Globes To Mirror Lights Fit S/C Drive Tyres To Rear Of Rear Axle Inside	VIC Workshop	10854	\$278.66
04/06/2021	760,972 kms	Engine Tune Up R-5405 Carry Out Engine Tune	KW/DAF Melbourne	1015108	\$683.44
02/06/2021	760,859 kms	Annual Primemover Inspection I-131	VIC Workshop		
02/06/2021	760,859 kms	C - C Service S-4013 Replaced Pressure Valve In Chassis Washed Chassis Resealed Front Diff Replaced Cab and Air Filters Replaced Wiper Blades Replaced Front and Rear Engine Mounts Replaced Fan Belts and Fan Tensioner Replaced Rubber On RHS Fuel Tank Replaced Upper Shocker Rubbers On LHF and RHF Replaced Rear Cab Shockers Rekitted Air Drier Remove CAC and Blow Out Radiator and CAC	VIC Workshop	1014596	\$4,989.16
30/04/2021	751,189 kms	B - Oils & Filters S-7432 Black Button Valve	VIC Workshop	1006326	\$303.28
09/04/2021	742,299 kms	A - Grease & Brake Adj S-7228 Replace Electric Heater Tap Fix Air Leak On Foot Brake Valve Replaced Front Cab mounts Replaced 8 Nut Covers Replaced RH Mirror Globe Replaced Front Axle Drive Tyres With 2nd Hand	VIC Workshop	998636	\$931.29
16/03/2021	732,178 kms	Electrical R-5105 Replaced LH Steer Nut Covers Replaced LHF Side Bonnet Indicator Replaced LH Tank Lights	VIC Workshop	998140	\$86.08

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
12/03/2021	730,529 kms	B - Oils & Filters S-6943 Replaced Rear Cab Bumper Stop Removed P/S Hose and Have New Part Made Refit New Hose Replaced Globe In RHS Mirror	VIC Workshop	BT-T00018728	\$550.03
24/02/2021	715,567 kms	General Repair R-5043 Replace D/S Bonnet Latch Supplied 2L Of Coolant	VIC Workshop	994377	\$55.56
22/02/2021	724,388 kms	Airbag, Mudguards R-5033 Travel Between Lake Bolac and Westmere. Jack Up and Replace Blown Drive Tyre On LHRI, Jack Up Chassis and Replace LHR Airbags Refit Good Second Hand Tyre To LHRI and Fit New Guard	VIC Workshop	993901	\$767.95
16/02/2021	721,734 kms	New Steer Tyres T-2184 Remove and Replace Steer Tyres Balance Up	VIC Workshop		\$957.11
08/02/2021	718,080 kms	A - Grease & Brake Adj S-6574 Repair 2x Mirror Parker Globes Replaced RHM Roof Light Fit New LH Light Cover Replaced LHS Rear Tank Light Fit New Bolt To Bottom Of air Dryer, Tighten All Bolts Rotated Drive Tyres	VIC Workshop	990853	\$54.33
05/02/2021	715,429 kms	Cruise Control R-4963 CHECK AND RECTIFY THE CRUISE CONTROL IS ENGAGING IT SELF AND TRYING TO TAKE OFF. DIAGNOSED FAULTY CRUISE CONTROLLER. ADVISED CUSTOMER WHO ADVISED TO REPLACE. CARRIED OUT REPLACEMENT AS REQ. ROAD TESTED VEHICLE ALL GOOD.	KW, KW/DAF Melbourne	990378	\$700.81
07/01/2021	707,360 kms	B - Oils & Filters S-6278 Replaced Bottom LH Mirror Globe Tightened Hose Clamp On heater Tap Replaced 1 Dash globe Give Clutch A Bit More Free Travel	VIC Workshop		\$327.98
10/12/2020	700,292 kms	A - Grease & Brake Adj S-6040 Make Bracket and Mount Weight Guage Fit New Microphone Replace Air Filter Replace Cabin Filter Blow Out Radiator and Charge Cooler	VIC Workshop	289023	\$848.05
12/11/2020	687,594 kms	B - Oils & Filters S-5791 Remove charge cooler and clean Clean out Radiator Replace Turbo Timer Replace 2 Dash Globes	VIC Workshop	974530	\$583.85
30/10/2020	680,583 kms	Fault R-4429 PLUGGED IN LAP TOP & FOUND IT HAD LOGGED A NOX SENSOR FAULT. CHECKED WIRING WAS O.K. REMOVED & REPLACED NOX SENSOR WITH NEW. ROAD TESTED VEHICLE ALL GOOD.	KW/DAF Melbourne	971639	\$1,092.30
28/10/2020	681,590 kms	Valve R-4450 Replace Air Valve For Exhaust Brakes	VIC Workshop		\$143.35
21/10/2020	678,894 kms	Electrical R-4360 Repair Wiring To 12v Socket at Front	VIC Workshop		\$0.00
15/10/2020	676,625 kms	Mirror R-4312 Fitted New Mirror Light Lense Fitted 2x Mirror Globes	VIC Workshop		\$0.00
14/10/2020	676,244 kms	A - Grease & Brake Adj S-5421 Fit New Steer Tyre Nut Covers Replaced Steer Tyres Re stick LH Horn Sticker Back On Replaced Engine Brake Solenoid	VIC Workshop		\$208.39

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
14/10/2020	676,244 kms	New Steer Tyres, Tyre Balanced T-1924 Remove and Replace Steer Tyres	VIC Workshop	0602+5495	\$1,320.00
21/09/2020	669,580 kms	Exhaust R-4235 Replace Exhaust Flex Under Cab, Brackets and Gaskets Tighten Sway Bar Behind Sump	VIC Workshop	963669	\$423.28
07/09/2020	664,980 kms	B - Oils & Filters S-5238	VIC Workshop		\$311.72
12/08/2020	656,226 kms	A - Grease & Brake Adj S-4928 Replaced RH Steer Tyre With Second Hand One Replace Fire Extinguisher With Change Over	VIC Workshop		\$9.48
21/07/2020	649,343 kms	Batteries R-3946 Replace Batteries	VIC Workshop	55401	\$614.42
13/07/2020	646,798 kms	General Repair R-3938 Lengthen and Refit Grease Line To Turn Table, Supply Bungee Cord For Air Lines	VIC Workshop		\$0.00
08/07/2020	645,509 kms	B - Oils & Filters S-4621 Replaced Dash globe In Tacho P Clap On Power Steering Lines adjusted Driving Lights Replace LHB Boost Hose Shift Turntable Back	VIC Workshop		\$322.72
29/06/2020		JUMPSTART R-3828 Jump Start truck	VIC Workshop		\$0.00
02/06/2020	638,064 kms	A - Grease & Brake Adj S-4373	VIC Workshop		\$0.00
02/06/2020	638,064 kms	Air Filter, Electrical R-3721 Replace Air Filter LH Headlight Fault, Repaired Wiring Replaced Mirror Light Globes	VIC Workshop		\$60.00
29/04/2020	624,949 kms	B - Oils & Filters S-4014	VIC Workshop		\$320.91
29/04/2020	624,949 kms	Brake Valve, Cabin Filter, Electrical, General Repair, Wash Bay R-3490	VIC Workshop		\$42.81
11/04/2020	618,571 kms	Lights R-3395	VIC Workshop		\$1,374.85
18/03/2020	615,000 kms	Coolant Change, General Repair R-3268 Replace Coolant Bug Deflector Step Light Coolant Bleed Line Sign Write Truck	Lister Signs, VIC Workshop		\$1,829.33
13/03/2020	613,236 kms	C - C Service S-4015	VIC Workshop		\$0.00
11/03/2020	613,216 kms	New Drive Tyres T-1377 Replace Drive Tyres	VIC Workshop		\$3,080.00
10/03/2020	613,236 kms	A - Grease & Brake Adj S-3689	VIC Workshop		\$0.00
10/03/2020	613,236 kms	Brake Drums, Brakes, Differential Oil and Filter Change, Drive Wheel Bearing Replacement, S Cam Bushes, steer wheel bearing replacement, Transmission Oil Change, Wash Bay R-3191 Replace Steer and Drive Wheel Bearings Replace Power Steering Oil and Filter Change Diff Oils and Filter Replace G Box Oil and Filter Replace Drive Brakes Degrease and Wash, Wash Whole Truck Replace Rear Axle S Cam bushes Replace LHR S Cam	VIC Workshop		\$3,559.23

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
27/02/2020	609,784 kms	Engine Tune Up R-3183 Complete Engine Tune Up	KW/DAF Melbourne	916547	\$2,887.43
05/02/2020	605,661 kms	General Repair, Valve R-2881	VIC Workshop		\$364.90
05/02/2020	605,661 kms	B - Oils & Filters S-3420	VIC Workshop		\$358.30
10/01/2020	596,682 kms	A - Grease & Brake Adj S-3152	VIC Workshop		\$0.00
28/12/2019	591,297 kms	Coolant Top Up, Electrical, Wash Bay R-2682	VIC Workshop		
16/12/2019	586,984 kms	inspection R-2613	VIC Workshop		
09/12/2019	584,338 kms	Universal Joint, Wash Bay R-2511	VIC Workshop		\$0.00
09/12/2019	584,338 kms	B - Oils & Filters S-3153	VIC Workshop		\$485.85
13/11/2019	573,859 kms	A - Grease & Brake Adj S-2706 Complete A Service	VIC Workshop		\$181.64
13/11/2019	573,859 kms	Bonnet, Dash cam R-2291 Replace LH Bonnet Latch and Adjust Bonnet Fit Dash Cam	VIC Workshop		
17/10/2019	562,781 kms	New Steer Tyres T-965 Replace Steer Tyres	VIC Workshop	0266	
17/10/2019	562,781 kms	Air Filter, CAC Clean, Centre Bearing, Drag Link, Electrical, General Repair, Radiator Clean R-2114 Remove Charge Cooler, Clean Radiator and Cooler, Reassemble, replace LH and RH Boost Hoses. R+R Centre Bearing R+R Drag Link End Replace RH Step Light R+R Air Filters Replace Tea Bag Filter	VIC Workshop		
17/10/2019		Air Conditioning R-2184 Labour To locate fault to leaking Hose and Seized compressor. Install New Components Run an Check Operation	Cool Zone Ballarat	00091400	\$1,306.80
17/10/2019	562,781 kms	B - Oils & Filters S-2705 Complete B Service	VIC Workshop		\$1,961.51
17/10/2019	562,781 kms	New Steer Tyres T-967 Replace Steer Tyres and RH Nut Covers	VIC Workshop		
17/10/2019	557,977 kms	General Repair R-2107 Remove Stickers From Door	VIC Workshop		
04/10/2019	557,977 kms	A - Grease & Brake Adj S-2607 Complete A Service	VIC Workshop		
04/10/2019	557,977 kms	Clutch, Electrical, General Repair, Oil Top Up, Shock Absorbers R-2053 Repair Wiring On front Bumper Lights Add 2L Oil Replace Bottom Clutch Linkage Rose Joints Replace LHR and Front Drive Axle, Bottom Shocker Bushes Replace Cab Filter Fit Fire Extinguisher In Locker Box Tighten Cross member Behind Sump Fill Auto Greaser	VIC Workshop		
144 Records				Total:	\$142,490.95