

# Cummins South Pacific Pty. Ltd.

## WORKSHOP TAX INVOICE

ABN NO. 42006332949



Cummins Mount Isa  
23-35 Northridge Road  
Mount Isa QLD 4825  
Ph 07 4749 8600  
Fax 07 4743 0777

INVOICE NUMBER

1614986

INVOICE DATE

21/05/25

PAGE

1

### Invoice To

Account Number 1301065  
WAGNER INVESTMENTS P/L  
WAGNER INVESTMENTS P/L  
PO BOX 151  
DRAYTON NORTH  
QLD 4350

### Customer

WAGNERS INVESTMENTS  
ALDERLEY STREET  
TOOWOOOMBA

QLD 4350

| Engine Model:    | SIGNATURE/ISX/QSX | Eng No:     | 80334854 | Equip Make:  | KENWORTH   |
|------------------|-------------------|-------------|----------|--------------|------------|
| FleetNo:         | 761               | Reg No:     | XQ67BK   | Cust Ord NO: | AU00030427 |
| Date in Service: | 05/09/21          | KLMS:       | 830695   | HRS:         | 39163      |
| Repair Date:     | 13/05/25          | Chassis NO: | 463038   | Currency:    | AUD        |
| C.O.No.          | 6783547           | Work ordNo. | 2958914  | Facility     | 139        |

### Complaint:

Engine locked up @39,163 hrs  
Remove and replace with new engine.

### Cause:

Customer request

### Correction:

Hrs/Klms:830,695 km / 39,163hrs  
Fuel Burn:261,159 litres

Remove and replace engine as per quote 6783547.

- New ISX-E5 Engine
- Capped price R + R
- Up-rate 550hp @1850ftlb.
- Warranty Plus coverage -  
5 years/1.2m km/18,000hrs/600,000 litres

Agreed Quoted price [REDACTED]

Please note: Additional labour for replacing input shaft, cross shaft bushes, clutch kit, hoses and clean radiator assembly.

Originally quoted 6.3 hours extra labour.

- plus 9 additional hours for overtime and OEM harness install.

\*\*\*\*\*

\*\*\*Banking Details\*\*\*

[REDACTED]

Include Account and Invoice Numbers in Payment Reference

# Cummins South Pacific Pty. Ltd.

# WORKSHOP TAX INVOICE



Cummins Mount Isa  
23-35 Northridge Road  
Mount Isa QLD 4825  
Ph 07 4749 8600  
Fax 07 4743 0777

Invoice To  
Account Number 1301065

INVOICE NUMBER

1614986

INVOICE DATE

21/05/25

PAGE

2

Customer WAGNERS INVESTMENTS

| Description | Operation | Unit price | Qty | Extension |
|-------------|-----------|------------|-----|-----------|
|             |           |            |     |           |
|             |           |            |     |           |

## Material

|                 |                           |     |
|-----------------|---------------------------|-----|
| 1324.01         | PREMIUM BLUE 8600 OIL (W/ | 50  |
| 185848          | GASKET AIR COMPRESSOR     | 1   |
| 4988280         | GASKET HYDRAULIC PUMP     | 1   |
| 2866337         | GASKET AFM DEVICE         | 3   |
| DCT110          | CABLE TIE, DUAL CLAMP 485 | 10  |
| 80264GL-CM      | HOSE, HEATER (CM)         | 200 |
| 80261GL-CM      | HOSE DAYCO SILICONE       | 300 |
| 78250GL         | SILICONE HOSE 915MM LE    | 1   |
| 78300GL-CM      | HOSE DAYCO SILICONE       | 30  |
| 4918022         | CONNECTION OIL SUCTION    | 1   |
| FS19764         | PLUS SIZE ELEMAX          | 1   |
| 3316591S        | LUBE SERVICE PART         | 1   |
| 52377.03        | ENGINE, ISXE5 500 / 1850  | 1   |
| 6306-2RS2/C5GJB | BEARING, SPIGOT           | 1   |
| HE8761XL        | HOSE                      | 1   |

## Miscellaneous

|                    |      |
|--------------------|------|
| Environmental Levy | 1.00 |
| Uprate 550 / 1850  | 1.00 |
| Warranty Plus      | 1.00 |
| Engine trade-in    | 1.00 |
| Overtime adjust    | 1.00 |

MISC TOTAL