

MAINTANENCE MANAGEMENT RECORD			
BODY TYPE:		PRIME MOVER	
MAKE:		MACK	
YEAR OF MANUFACTURE:		2008	
VEHICLE ID No. (VIN)		6FMT13F028D800217	
ENGINE NUMBER:		79287939	
LICENSE NUMBER:		SB93CX	
CONFIGURATION CODE:		3 AXLE PRIME MOVER HAULS 1 SEMI-TRAILER	
MASS:		8800	
LAST SERVICE:		26/3/2026 - 344,497KM	
NEXT SERVICE DUE:		01/10/2026 - (WHICHEVER IS SOONER)	
NHVAS LABEL NUMBER:		A045836 (AS OF 05/12/2016 MASS/MAINTENANCE)	
DATE	COMPANY	DESCRIPTION	KM'S
25/08/2014	SCOTT CHRISTENSEN	SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS CHECK ALL LEVELS REPLACE TOOLBOX DOOR LATCHES, REPLACE QUARTER GUARD LOW SPRAY MUDFLAPS	
29/12/2014	SCOTT CHRISTENSEN	SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, GREASE ALL POINTS, ADJUST BRAKES, REPAIR INDICATOR STALK, REPAIR ELECTRIC HORN	
6/05/2015	SCOTT CHRISTENSEN	SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHECK ALL LEVELS, CHANGE ALL FILTERS, CHECK AND ADJUST BRAKES, GREASE ALL POINTS	
15/08/2015	KILLMORE PLANT SERVICES	RECTIFY BROKEN AIR FITTINGS AT LOWER FIREWALL. INSTALL CLUTCH CABLE AND ADJUST	
18/08/2015	SOUTHERN TRUCK CENTRE	CARRY OUT SERVICE	139,761
17/09/2015	KILLMORE PLANT SERVICES	BREAKDOWN CALL FOR HYDRAULIC TANK ISSUES. REMOVE LEAKING FUEL TANK, TRANSPORT TO REPAIRER, FIT REPAIRED FUEL TANK AND RECONNECT ALL LINES REPLACE ALL REQUIRED FITTINGS REPLENISH HYDRAULIC FLUID. TEST AND CHECK ALL OPERATIONS	
8/02/2016	KILLMORE PLANT SERVICES	BREAKDOWN CALL TO FIX DAMAGED LH FUEL TANK	
12/02/2016	SOUTHERN TRUCK CENTRE	CARRY OUT A & B SERVICE	150,998
9/03/2016	SOUTHERN TRUCK CENTRE	RECTIFY RADIATOR LEAKING AT THE TOP WHERE THE HOSE GOES IN BEHIND THE PANEL, REPLACE LEAKING AC HOSE	153,250
21/03/2016	KILLMORE PLANT SERVICES	REPLACE FUEL FILTER DUE TO BLOCKAGE BLEED SYSTEM AND TEST	
28/04/2016	KILLMORE PLANT SERVICES	BREAKDOWN CALL - SLUGGISH START, LOAD TEST BATTERIES, CLEAN TERMINALS AND CHECK CHARGE RATE, SUPPLY AND FIT NEW FUEL FILTER	156,660

6/09/2016	KILLMORE PLANT SERVICES	BREAKDOWN CALL - ENGINE CUT OUT - NO RESTART, BATTERIES LOW SUPPLY AND FIT NEW 4X BATTERIES LOW FUEL ADD 110L FUEL, ENGINE NO START, RUN AIR LINE FROM SERVICE TRUCK TO MACK TO RELEASE BRAKES, ESCORT TRUCK 300M TO SAFE PARKING AREA, SUPPLY AND FIT NEW STARTER MOTOR ASSEMBLY AND NEW FUEL FILTERS- BLEED SYSTEM - NO START SUBLET AUTO ELECTRICIAN TO SCAN ECU NO FAULT CODES LOGGED INTO SYSTEM CHECK ECU OK - NO START - CALL TOW TRUCK	
22/08/2016	ILLAWARRA TRUCK REPAIRS AND SPARES	BREAKDOWN AT GERRINGONG TRUCK WON'T START - BAD FUEL GONE THROUGH IT AND DAMAGED GEAR PUMP AND 1 AND 3 INJECTOR REMOVE AND REPLACE GEAR PUMP, REMOVE AND REPLACE 1 & 3 INJECTOR, REMOVE AND REPLACE STOPPER SOLONOID DUE TO SUNKEN BASE, REMOVE AND REPLACE TURBO AND ACTUATOR CARRY OUT FULL ENGINE TUNE UP	164,084
12/09/2016	KILLMORE PLANT SERVICES	BREAKDOWN CALL - NO CLUTCH - TRAVEL TO SITE REMOVE AND FIT NEW CLUTCH CABLE CHARGE AIR SYSTEM	164,769
25/10/2016	SCOTT CHRISTENSEN	DRAIN AND REMOVE LH FUEL TANK AND STEPS FROM TRUCK, REMOVE LIGHT BARS, REMOVE RUBBER REAR GUARDS, REMOVE DAMAGED LH FRONT QUARTER GUARD, REFIT FUEL TANK TO TRUCK, FILL UP HYDRAULIC OIL, TEST HYDRAULICS REFIT LIGHT BARS AND REAR GUARDS TO TRUCK WIRE UP ALL LIGHTS TEST OPERATION FIT AND ADJUST STEPS AND QUARTER GUARD REMOVE BATTERY BOXES FOR BLASTING AND PAINTING REFIT BATTERY BOXES AND BATTERIES FIT TOOL BOXES TO BATTERY BOXES REMOVE AND REPLACE RH DOOR HINGE REMOVE AND REPLACE ELECTRIC WINDOW SWITCH REMOVE AND REPLACE REAR TORQUE RODS FIT NEW HOLD DOWN HANDLES TO BATTERY BOXES	
17/11/2016	SOUTH CENTRAL TRUCKS	CARRY OUT SPEED LIMIT CERTIFICATE, CHECK BRAKE PEDAL FOUND TO BE ALL OK, ADJUST CLUTCH	170,543
21/11/2016	SCOTT CHRISTENSEN	SERVICE TRUCK DRAIN AND REFILL ENGINE OIL, CHANGE FILTERS, CHECK LEVELS, CHECK LIGHTS AND BATTERIES, GREASE ALL POINTS, DRAIN AND REFILL DIFF OIL, REMOVE AND REPLACE WIPER BLADES, REMOVE AND REPLACE CAB SHOCKERS	
30/11/2016	SCOTT CHRISTENSEN	ADJUST TURNTABLE JAWS, REMOVE AND REPLACE TURNTABLE BUSHES AND PINS	
21/12/2016	COOPER AUTO ELECTRICS	CHECK A/C SYSTEM, FIND SYSTEM WORKING OK ADD 250G TO SYSTEM AS REQUIRED CLEAN CABIN FILTERS	
28/01/2017	SCOTT CHRISTENSEN	SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, GREASE ALL POINTS, CHECK LIGHTS AND BATTERIES	180,403
28/02/2017	SCOTT CHRISTENSEN	REMOVE AND REPLACE LHR AIR BAG	185,614
6/03/2017	SCOTT CHRISTENSEN	REPAIR AIR LEAKS, DIAGNOSE TRUCK AIR PRESSURE FAULT, REMOVE AND REPLACE AIR DRYER, ROAD TEST TRUCK	186,927
12/04/2017	SCOTT CHRISTENSEN	REMOVE AND REPLACE ENGINE AIR COMPRESSOR	188,694

25/05/2017	SCOTT CHRISTENSEN	SERVICE TRUCK DRAIN AND REFILL ENGINE OIL, CHECK ALL LEVELS CHANGE ALL FILTERS CHECK LIGHTS AND BATTERIES, GREASE ALL POINTS CHECK AND ADJUST BRAKES REMOVE AND REPLACE RH REAR AIR BAG REMOVE AND REPLACE INDICATOR STALK REFIT AIR COND FILTER AND PANELS	197,369
1/08/2017	SCOTT CHRISTENSEN	MAKE AND FIT FESTO AIR LINE TO OPERATE TAIL GATE ON TIPPER	
14/09/2017	SCOTT CHRISTENSEN	SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHECK ALL LEVELS, CHANGE ALL FILTERS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL POINTS, RECTIFY AIR LEAKS ON FIRE WALL, REMOVE KICK PANELS IN DRIVERS FOOT WELL REMOVE AND REPLACE AIR MANIFOLD NEAR CLUTCH PEDAL	206894
28/02/2018	SCOTT CHRISTENSEN	REMOVE AND REPLACE WIRING HARNESS, REMOVE AND REPLACE X/Y SHIFTER ON TOP OF GEARBOX	213818
19/03/2018	TRUCK POWER AUTO ELEC	REPAIR NO PARK/TAIL LIGHTS ON TRAILER AND REPAIR UHF	
8/03/2018	SCOTT CHRISTENSEN	MAKE UP AND FIT CHECKER PLATE BATTERY LIDS X 2 REPAIR AIR LINE AND ELECTRICAL RACK AT REAR OF CAB	
28/04/2018	SCOTT CHRISTENSEN	SERVICE TRUCK DRAIN AND REFILL ENGINE OIL, CHECK ALL LEVELS, CHANGE ALL FILTERS, GREASE ALL POINTS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, REPAIRED BROKEN WIRES FOR FAN CLUTCH, REPAIRED AIR LEAK ON CLUTCH ASSIST CYLINDER	217933
28/05/2018	SCOTT CHRISTENSEN	REMOVE AND REPLACE RD SIDE STEP, REPAIR FRONT QUARTER GUARD	
3/09/2018	SCOTT CHRISTENSEN	MAKE UP FESTO AIRLINE TO SUIT END TIPPING TRAILER FOR TAILGATE AND HYDRAULIC RAM RELEASE	
7/12/2018	SCOTT CHRISTENSEN	REMOVE, REPAIR AND REFIT HYDRAULIC TANK, REPLACE FUEL TANK BRACKET AND STRAP RUBBERS, REFILL TANK WITH FUEL AND HYDRAULIC OIL, TEST OPERATION	
14/01/2019	SCOTT CHRISTENSEN	REPLACED WORN UNI JOINT AT FRONT OF FRONT DIFF	227040
31/05/2019	SCOTT CHRISTENSEN	SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, REPLACE 1 BATTERY BOX HOLD DOWN STRAP, CHECK LIGHTS AND BATTERIES, GREASE ALL POINTS	229028
7/03/2020	SCOTT CHRISTENSEN	drained and refilled engine oil. Changed all filters. Checked all levels. Checked lights and batteries. Checked and adjusted brakes. Greased all grease nipples. B double side tippers. Removed old grease and dirt from lead trailer. Then applied fresh grease. connected trailer up and tested hydraulics to open up side tipper door. removed link hose from rear trailer and fitted to front trailer. replaced faulty o ring on festo air lines on front of rear trailer. strapped up hydraulic hoses. brake hoses and side tipper air lines between trailers. checked brake pads thickness and for flat tyres. removed and replaced fuel filter and water filter on engine removed fuel pro filter, cleaned out filter assembly and fitted new filter.	
		installed x2 ball valve taps on fuel pro and then bled air out of fuel system. Fitted stand off bracket and p clip to stop hydraulic hose from rubbing on fuel pro housing. Removed repaired and refitted bonnet springs mounts. Straighten exhaust bracket rod. tightened up headache rack. made up plate for rack to stop it from moving.	

13/03/2020	CMV Truck and Trailer Parts	Parts. Fuel filter x1. es water filter (non chem) (cu x1. lube filter x1.	
13/03/2020	SOUTH CENTRAL TRUCKS	parts - element air 'c x2. spring x1.	
16/03/2020	SOUTH CENTRAL TRUCKS	parts - insulator x1.	
12/06/2020	Adelaide Independent Bandag	RH rear inner : puncture repair - 11r22.5 x1. rad 120 tl patch x1. remove and replace wheels/tyres x1.	
2/10/2020	TRUCK POWER AUTO ELEC	Service and repair AC compressor	
29/10/2020	TRUCK POWER AUTO ELEC	Check fault with A/C blower fan not working, check power to fan motor assembly. Refit new blower fan motor, test	
28/01/2021	TRUCK POWER AUTO ELEC	Check fault with truck cranking but not firing. Connect cummins Insite and check fault codes, find active fault code present for fuel pressure low. Advise possible fault with fuel lift pump (pump running but noisy) or main high pressure pump or blockage.	
22/02/2021	Cummins South Pacific	Carry out JSA and live testing LOTTO. Diagnose transfer pump not operating. Remove and replace pump. Find pump priming correctly now, start & run to find engine fuel filter had a brown seal. Remove and replace fuel filter and prime fuel system. Start and run up all ok.	245796
28/04/2021	SCOTT CHRISTENSEN	REPLACED MUFFLER BOX, ELBOW AND CLAMPS ON RH SIDE OF TRUCK, ADJUSTED TURN TABLE, SERVICED TRUCK, DRAINED AND REFILLED ENGINE OIL, CHECKED ALL LEVELS, CHANGED ALL FILTERS, CHECKED LIGHTS AND BATTERIESREPLACED MISSING BOLT ON HEADERTANK REPLACED AIR FILTER DRYER	249297
3/06/2021	ADELAIDE INDEPENDENT BANDAG	SUPPLY & FIT STEER & DRIVER X 2-WHEEL BALANCE X 2-BALANCE WEIGHT X 1-11R22 ATT307 HAULMAX X 8	249,813
4/05/2021	SCOTT CHRISTENSEN	AS PER LINK	249,301
7/06/2021	SCOTT CHRISTENSEN	CONNECT UP ROAD TRAIN, TESTED LIGHTS, NO POWER TO REAR TRAILER OR DOLLY, REPLACED ELECTRICAL SOCKET, TESTED HYDRAULICS, FAULTY, REMOVED AND REPLACED HYDRAULIC HOSES, MADE UP NEW AIRLINES TO CONNECT FRONT TRAILER TO REAR TRAILER, REPLACED ROAD TRAIN SIGNS TO FRONT OF TRUCK AND TO REAR TRAILER	
10/06/2021	TRUCKPOWER	LABOUR X 3 HRS-FIT LED GLOBE KIT-STEDI 18INCH LED LIGHT BAR-INLINE FUSE HOLDER-W/PROOF-SUNDRIES	
30/08/2021	SCOTT CHRISTENSEN	MECHANICS REPORT: CHECK HYPER LINK	263,656
2/09/2021	TRUCK POWER AUTO ELEC	CHECK HYPER LINK FOR DETAILS	
24/09/2022	SCOTT CHRISTENSEN	MADE NEW AIRLINES FOR TIPPER. REM AND REP HYDRAULIC HOIST CONTROL SWITCH	N/A

5/11/2021	SCOTT CHRISTENSEN	DRAINED AND REFILLED ENGINE OIL, CHANGED ALL FILTERS, CHECKED ALL LEVELS, CHECKED LIGHTS AND BATTERIES, CHECKED AND ADJUSTED BRAKES, GREASED ALL GREASE NIPPLES, REMOVED AND REPLACED BALL JOINT ENDS OF CLUTCH AIR CYLINDER, FITTED AIR CYLINDER, CHECKED OPERATION OF CLUTCH CYLINDER, CHECKED GEAR BOX, CHECKED DIFFS AND POWER STEERING OIL LEVELS	280,153
28/01/2022	SCOTT CHRISTENSEN	CHANGED GEARBOX OIL , REPAIRED RH FRONT MUDGUARD	281,055
1/04/2022	SCOTT CHRISTENSEN	FIXED 3 AIR LEAKS, STRAIGHTENED RACK BEHIND CAB, REMOVED EXHAUST STAY ROD TO BE FIXED AND RE-FITTED EXHAUST STAY ROD, FITTED NEW TEMA HYDRAULIC FITTING, REPAIRED EXHAUST STABILIZER BAR, WELDED HYDRAULIC FITTING	282,828
10/11/2022	SCOTT CHRISTENSEN	REPLACED OIL, CHANGED FILTERS, CHECKED ALL LEVELS, CHECKED LIGHT SAND BATTERIES, CHECKED A ADJUSTED BRAKES	291,210
21/11/2022	Adelaide Independent Bandag	SUPPLY & FIT 8 X 11R22.5 ATT307 HAILMAX/RUNOUT TYRE	291,359
14/12/2022	SCOTT CHRISTENSEN	CHECK HYPERLINK FOR DETAILS	
12/01/2023	TRUCK POWER AUTO ELEC	REMOVE AND REPLACE AMBER FLASHING LIGHTS X2. REMOVE AND REPLACE FAULTY MIRROR LIGHT. REPLACE PASSANGER SIDE MIRROR. CHECK INDICATOR OPERATION. REPLACE FAULTY STALK. CHECK WIPER FAULT. FIND POOR CONNECTION IN FUSE BOX FOR CIRCUIT BREAKER. FIT AND WIRE LOCKABLE BATTERY ISOLATOR SWITCH. MAKE NEW EARTH CABLES AS REQUIRED. TEST OK. REMOVE AND REPLACE FAULTY UHF RADIO WITH NEW 80 CHANNEL UNIT. TEST ANTENNA. OK. SERVICE A/C SYSTEM. RECOVERED REFRIGERANT. REPLACE RECIEVER DRIER. REPLACE CABIN FILTER. REPLACE REAR WORK LIGHT BEHIND CAB. REPLACE INCORRECT FLASHER RELAY. CHECK LIGHTING. FIND BLOWN FRONT GLOBES. FIND NO REVERSE LIGHT OR BUZZER. REPLACE FULLY REVERSE LIGHT AND BUZZER. TEST OK	N/A
9/02/2023	DOUBLE R EQUIPMENT REPAIRS	SB-93-CX : SUPER LINER: REMOVED AND REPLACED YOKE SEAL ON TAILSHAFT (PINION SEAL)	301,245
6/01/2023	SCOTT CHRISTENSEN	CONNECTED HYDRAULIC HOSES AND AIR LINES, FITTED NEW DRYER FILTER, CHANGED 2X BATTERIES ON LH SIDE TRUCK, REMOVED AND FITTED NEW CLUTCH CABLE, P CLIPPED AND ZIP TIED, REMOVED AND FITTED NEW EVERSE, SWITCH ON GEARBOX	295895
20/06/2023	NT DIESEL	REPAIRS AND MAINTANCE DONE TO TRUCK SB93CX OVER THE DAYS OF 5/6/2023 TO TTHE 18/6/2023/ SEE HYPERLINK	N/A
21/06/2023	NT DIESEL	REPAIRS AND MAINTANCE DONE TO TRUCK SB93CX SEE HYPERLINK	
16/10/2023	OTR TYRES	REPLACE 2X STEER TYRES	
14/12/2023	SCOTT CHRISTENSEN	REPAIRS AS PER HYPERLINK	

19/12/2023	TRUCK POWER AUTO ELEC	REPAIR DAMAGED WIRING IN BONNET FOR LIGHTING, CHECK FAULT WITH PASSENGER SIDE POWER WINDOW NOT WORKING, FIND FAULTY/SEIZED WINDOW MOTOR/REGULATOR ASSEMBLY, REPAIR WIRING CONNECTOR TO SIDE TANK MARKER LIGHTS, REPAIR WIRING TO REAR DIFF TEMPERATURE SENDER, CHECK FAULT WITH WINDSCREEN WASHER ONLY WORKING ON HIGH SPEED, REPLACE MISSING WIPER RELAY IN DASH, FIND FUSE BOX IN DASH HAS SEVERAL LOOSE FUSE/RELAY CONNECTIONS, ADVISE FUSE BOX REPLACEMENT	
11/01/2024	TRUCK POWER AUTO ELEC	REMOVE AND REPLACE OEM FUSE BOX IN CENTRE DASH	
22/01/2024	SCOTT CHRISTENSEN	DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL NIPPLES, REFIT SEAT, REMOVED AND REPLACED STEERING BOX, FIT NEW UNIJOINTS IN STEERING SHAFT, REMOVED AND REPLACED POWER STEERING RESERVOIR, FIT STEERING SHAFT BACK INTO TRUCK, REMOVED FRONT BONNET MOUNT, FIT NEW BOLTS IN INTERCOOLER BRACKETS TO REPLACE ONES THAT WERE MISSING, BOLTED RH REAR MUDGUARD BACK TOGETHER, FIT NEW FRONT BONNET MOUNT, TIGHTENED UP SIDE STEPS, FIT NEW PARK BRAKE AND TRAILER AIR VALVES DUT TO LEAKING AIR, REFIT LH DOOR TRIM, INSTALLED NEW HEIGHT CONTROL VALVE, REMOVE AND REPLACE RUBBER ON FUEL TANK ON DRIVERS SIDE, REFIT DRIVERS DOOR CARD, FABRICATE ANTI SAIL BRACKETS FOR MUD FLAPS, WELDED UP WORN SPRING MOUNTS IN BONNET	334731
7/02/2024	TRUCK POWER AUTO ELEC	CHECK FAULT WITH PRIMARY AIR PRESSURE GAUGE NOT WORKING, TEST AIR PRESSURE SENSOR OK, REMOVE INSTRUMENT CLUSTER AND SEND FOR REPAIR, CHECK OPERATION OF REPAIRED INSTRUMENT CLUSTER OK.	
4/03/2024	TRUCK POWER AUTO ELEC	CHECK AC OPERATION, FIND AC SYSTEM LOW ON REFRIGERANT, PRESSURE TEST SYSTEM WITH NITROGEN, SYSTEM HELP 200PSI, REPLACE SERVICE VALVE CORES, VAC DOWN SYSTEM, CHARGE SYSTEM WITH OIL/DYE, CHARGE SYSTEM WITH REFRIGERANT, TEST OPERATION FIND POOR VENT AIR FLOW, REPLACE BLOCKED CABIN FILTER	
8/02/2024	SCOTT CHRISTENSEN	FIT BONNET BACK ON TRUCK, FIT QUARTER GUARDS, CONNECTED AND TESTED ALL LIGHTS IN BONNET, FIT FIXED DASH CLUSTER INTO TRUCK, FIT TRIM PANELS, FIT NEW SIDE STEPS, FIX BENT BEACON BRACKET, FIXED AIR TO DRIVERS SEAT	334,731
19/08/2024	TRUCK POWER AUTO ELEC	CHECK TRUCK FOR FAULTS WITH ENGINE RUNNING ROUGH, EXCESSIVE BLOW BY, CONNECT DIAGNOSTIC LAPTOP AND CHECK FOR FAULTS, NO ACTIVE CODES PRESENT, CONDUCT CYLINDER PERFORMANCE TEST, ALL CYLINDERS PASSED, ADVISE POTENTIAL INTERNAL ENGINE ISSUE CAUSING BREATHING ISSUE	
6/12/2024	SOUTHWELL DIESEL SERVICES	DISMANTLED ENGINE TO FIND OUT WHY EXCESSIVE BLOW-BY, FOUND CRACK IN CYLINDER 3 PISTON, ALL OTHER PISTONS AND LINERS INSPECTED ALL OK, REPLACED PISTON AND LINER IN CYLINDER 3, FITTED RECON INJECTOR TO CYLINDER 3&4 FITTED NEW CYLINDER HEAD, REASSEMBLED ENGINE, FOUND CRACKED SUMP AND FITTED SECOND HAND SUMP, REPLACED OIL FILTER AND FILLED ENGINE WITH NEW OIL, FILLED ENGINE WITH NEW COOLANT TEST DRIVE ALL OK	338029

