

Rocks Farming Company

Asset History Report

Wednesday
, 5
November
2025

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type
FL-03	JCB Tele						
686	Remove old fork set with one badly bent.Fit new set that came as spares with machine.	20/01/2021	.00	2.00	2.00		Damage
956	Remove boom lift assist ram, reseal ram with genuine seal kit, refit and test.	29/06/2021	.00	3.00	3.00		Break
1064	Forklift 500 hr Service	17/09/2021	.00	###	3.00	19	PM
1081	Cut and fit cutting edges to bucket.	3/08/2021	.00	###	###		Mod
1454	Hydraulic sway valve replaced.Front stabilizer arm pivot pins Gouged out and replaced with new ones made by Nu-Tek.	10/03/2022	.00	###	8.00		Break
1726	Fit new latch to rear access door.Disassemble lock valve on sway ram, inspect, clean and reassemble.Remove RH stabilizer leg, Hayward Hydraulics make a new ram shaft, reassemble and fit.Repair oil leak on transmission bung.Fit new LH leg stabilizer sensor and repair wiring.Replaced final stage boom ran solenoid.	1/11/2022	.00	1.00	2.00		Break
1859	RH Stabilizer Lift ram, remove reseal, refit and test.Repair wiring on LH stabilizer ram.	28/10/2022	.00	8.50	8.50		Break
1898	Fit uhf radio	26/10/2022	.00	4.00	4.00		Mod
1918	Remove tilt ram, disassemble, clean, inspect, reseal and reassemble to machine.Top up hydraulic oil.	27/10/2022	.00	8.00	8.00		Break

2749	Self leveling of fork system not responding. Found system ok operator not putting safety support legs down first. Bleed brake due to spongy pedal.	16/11/2023	.00	4.00	3.00		Break
2782	Repair wiring on fuel tank sender. (fuel gauge still not fixed) Replace bottom door hinge.	7/12/2023	.00	3.50	2.00		Break
2913	Diagnose issue with sender unit in fuel tank. Remove fuel tank, fit new sender unit and refit tank. Repair latch on toolbox at front of machine. Replace battery.	22/02/2024	.00	9.50	2.50		Break
3047	Forklift 250hr Service	8/06/2024	.00	5.00	2.00	20	PM
3104	Tighten loose brake bleeder and bleed brakes.	20/06/2024	.00	1.00	1.00		Break
3584	Reseal all four steering rams. Repair puncture on rear left tyre.	10/01/2025	.00	###	###		Break
15		Total	.00	###			###

